UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK)/ CONTAMINATION SITE REPORT						
EMERGENCY HAS STATE OFFICE OF EMERGENCY SERVICES □ Yes ☑ No □ Yes ☑ No			FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PERSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.			
REPORT DATE CASE # 11/04/2008						
ВΥ	NAME OF INDIVIDUAL FILING REPORT PHONE Jim Gribi (7			SIGNATURE 07)748-7743		
REPORTED B	REPRESENTING □ LOCAL AGENCY □ REGIONAL BOARD 凶 OWNER/OPERATOR □ OTHER ADDRESS			COMPANY OR AGENCY NAME Gribi Associates		
3LE	1090 Adams Street, Suite K, Benicia, CA 94510 NAME Willbett Company			спу st. Sue Rosenberg		ATE ZIP PHONE (925)838-2408
RESPONSIBLE PARTY	Willbett Company Unknown Sue Rosenberg (925)838-2408 ADDRESS 109 Hartford Road, Danville, CA 94526					
	STREET FACILITY NAME (IF APPLICABLE)			CITY ST. OPERATOR		ATE ZIP PHONE
SITE LOCATION	ADDRESS 925 Stanford Avenue, Oakland, CA 94608 STREET CITY COUNTY ZIP					
N	CROSS STREET Lowell Street LOCAL AGENCY AGENCY NAME PHONE PHONE					
IMPLEMENTING AGENCIES	LOCAL AGENCY Alameda County Depar	onmental He	alth		PHONE 510-567-6700	
						PHONE 510-622-2300
SUBSTANCES INVOLVED	(1) NAME QUANTITY LOST (GALLONS) Fuel hydrocarbons (gasoline, diesel, motor oil)					
	© Unknown					
DISCOVERY/ABATEMENT	DATE DISCOVERED 04/21/2008			☑ Tank Removal □ Nuisance Conditions ontrol □ Subsurface Monitoring □ Other		
	DATE DISCHARGE BEGAN			METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) Remove Contents I Close Tank Repair Tank Change Procedure Replace Tank Other Repair Piping		
	HAS DISCHARGE BEEN STOPPED? Yes No IF YES, DATE					
SOURCE/ CAUSE	CAUSE(S) Tank Leak Piping Leak Unknown Other Overfill Corrosion Rupture/Failure Unknown Other					
CASE TYPE	CHECK ONE ONLY					
CURRENT STATUS	CHECK ONE ONLY Case Closed (Cleanup Completed or Unnecessary) Action Taken Case Closed (Cleanup Completed or Unnecessary) Leak Being Confirmed Pollution Characterization Remediation Plan Post Cleanup Monitoring in Progress Preliminary Site Assessment Workplan Submitted Cleanup Underway					
REMEDIAL ACTION	CHECK APPROPRIATE ACTION(S) Cap Site (CD) Excavate & Treat (ET) Treatment at Hookup (HU) Other Contamination Barrier (CB) No Action Required (NA) Enhanced Bio Degradation (IT) Vacuum Extract (VE) Remove Free Product (FP) Replace Supply (RS) Excavate & Dispose (ED) Pump & Treat Groundwater (GT) Vent Soil (VS)					
COMMENTS						