UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT						
☐ Yes ☑ No REPORT BEEN FILED? ☐ Yes ☑ No				FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.		
September 24, 2008				with the	6 /0/17/08 DATE	
	NAME OF INDIVIDUAL FILING REPORT	PHONE (016) P		SIGNATURE	26	
REPORTED BY	Charles O'Neill (916) 853-8927 Company or agency name					
	☐ LOCAL AGENCY ☐ REGIONAL BOARD ☐ OWNER/OPERATOR ☐ OTHER ADDRESS		Shell Oil Products US			
	20945 S. Wilmington Ave.		Carson		CA 90810 STATE ZIP	
RESPONSIBLE PARTY		Unknown	Denis Brow		(707) 865-0251	
	ADDRESS 20945 S. Wilmington Ave		Carson		CA 90810 STATE ZIP	
SITE LOCATION	FACILITY NAME (IF APPLICABLE) Shell 135682		OPERATOR		PHONE ()	
	ADDRESS 3750 E 14 th Street		Oakland	Alameda	94601 zip	
	CROSS STREET Villa Avenue and 14 th Street (International Blvd)					
MPLEMENTING AGENCIES	LOCAL AGENCY AGENCY NAME				PHONE	
	Alameda County Health Agency				(510) 567-6721	
	San Francisco Regional Water Board PHONE ()					
SUBSTANCES	(1) NAME QUANTITY LOST (GALLONS) TPPH (gasoline; 1.5 ppm soil; 3900 ppb groundwater)					
	MTBE (3600 ppb groundwater) benzene(17 ppb groundwater)					
DISCOVERY/ABATEMENT	9/23/08 HOW DISCOVERED	Tank T	ory Control	Tank Removal Subsurface Monitoring	Nuisance Conditions Other	
	DATE DISCHARGE BEGAN METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) Remove Contents Close Tank					
	UNKNOWN Repair Tank Change Procedu			dure		
	has discharge been stopped? ⊠ yes □ no if yes, date Unknown		Replace Tank	Other		
_	SOURCE OF DISCHARGE	CAUSE(S)				
SOURCE/ CAUSE	☐ Tank Leak ☐ Piping Leak ☐ Unknown ☒ Other	☐ Overfi	ll Corrosion (Rupture/Failure 🔲 Unk	nown 🗌 Spill 🛛 Other	
-	CHECK ONE ONLY					
CASE	☐ Undetermined ☐ Soil Only ☐ Groundwater ☐ Drinking Water — (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)					
CURRENT	CHECK ONE ONLY No Action Taken Leak Being Confirmed Remediation Plan Preliminary Site Assessment Workplan Submitted Preliminary Site Assessment Underway □ Preliminary Site Assessment Underway					
REMEDIAL ACTION	CHECK APPROPRIATE ACTION(S) Cap Site (CD) Contamination Barrier (CB) Vacuum Extract (VE) Excavate & Dispose (ED) Pump & Treat Groundwater (GT) Treatment At Hookup (HU) Enhanced Bio Degradation (IT) Replace Supply (RS) Vent Soil (VS)					
COMMENTS	During review of laboratory analytical results from soil and groundwater sampling, concentrations of MTBE (3600 ppb); benzene (17 ppb); and TPPH (gasoline, 3900 ppb groundwater and 1.5 ppm soil) were noted in groundwater and/or soil samples collected from the site by Delta Consultants (Delta). Delta notified Alameda County Environmental Health on 9/23/2008 by emailing Donna Drogos at 3:16pm PST. A report documenting the findings will be submitted to the agency within 60 days					

www.unidocs.org