

ALAMEDA COUNTY HEALTH CARE SERVICES
HAZARDOUS MATERIALS PROGRAM/ENVIRONMENTAL HEALTH SERVICES

SERVICE REQUESTED: REMEDIATION
 NAME OF SITE : SUNOL COMMUNICATIONS CENTER
 ADDRESS : 3700 PALOMARES Rd
SUNOL (Watson Comm. Svcs.)
 CONTRACTOR : Uriah INC
 ADDRESS : 464 Lindbergh Ave
LIVERMORE 94550 PHONE # 455-4991
 CONTACT PERSON : _____ PHONE # _____
 DATE OF DEPOSIT : 10-2-90 AMOUNT OF DEPOSIT \$375.00

DATE	ACTION TAKEN	IN	OUT	HRS.	X ⁶⁰ ₅₆	SUB/TOT	BALANCE
10-4-90	review of 6-29-90	9:30	11:00	1.5	90	375	285
<u>11-16-90</u>							
12-6-90	call to Uriah	3:20	3:25	0.25	15	285	270
3-26-91	call to Gene Pinter/FAX info			0.5			235-
<u>4/12/91</u>							
7-9-92	calls w/Ron Sadler			0.5			
7-9-92	review of 7/21 report; letter; conference w/BC			2.0			48-
12/2/92	wrote a letter			2.0			
12/2/92	meeting			1.5			
<u>7-14-93</u>							
<u>to Billings (with assessment) deposit</u>							

PROJECT COMPLETED BY : _____
 DATE OF COMPLETION : _____ DATE SENT TO BILLING: _____
 TOTAL COST OF PROJECT: _____ REFUND AMOUNT : _____

TO BE REPORTED WEEKLY TO THE ACCOUNTING DEPARTMENT FOR CASHFLOW ADJUSTMENT

Amir -

2/9/92

Here's a case for you. It began with a
leak of diesel from an above ground tank
serving an emergency power generator. I
don't think it qualifies as an LOP case.

Let's talk about it. I just sent some
correspondence today.

Scott

ALAMEDA COUNTY
HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director



RAFAT A. SHAHID, Assistant Agency Director

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

July 9, 1992

Mr. Ron Sadler
Watson Communications
1333 Willow Pass Road
Concord, CA 94520

Re: SUNOL COMMUNICATIONS SITE, 3700 PALOMARES ROAD, SUNOL

Dear Mr. Sadler:

Following our telephone conversation today, I had the opportunity to review the July 17, 1991 Uriah Inc. report documenting the results of the bioremediation of diesel-contaminated soil previously excavated and stockpiled at the referenced site. Review of the cited report revealed that the subject soil had not been remediated to nondetectable (ND) levels of diesel-range compounds. During our earlier conversation, you had communicated to me that ND results had been achieved. My verbal approval for reintroduction of the treated soil into the site was based upon this statement.

The subject soil is not appropriate for reintroduction into the site as a result of detectable concentrations of diesel-range compounds being present. This soil, however, may likely be disposed of at a local Class III landfill capable of accepting soil with low concentrations (<100 parts per million) of hydrocarbon compounds. Clean import may then be used to backfill the site.

Please call me, or Amir Gholami, at 510/271-4320 should you have any further questions regarding this case.

Sincerely,


Scott O. Seery, CHMM
Senior Hazardous Materials Specialist

cc: Rafat A. Shahid, Assistant Agency Director, Env. Health
Gil Jensen, Alameda County District Attorney's Office
Eddie So, RWQCB
Ed Howell/files

REF./
A/C NO. Remediation

COUNTY OF ALAMEDA
OFFICE OF THE AUDITOR-CONTROLLER

DATE: 10 / 3 / 90

MISCELLANEOUS RECEIPT

No 577069

\$ 375.00
DOLLARS

RECEIVED FROM: WATSON COMMUNICATION SYSTEM 1233 WILLOW PASS
 FOR: Urich, INC. Rd # 201 Concord
 464 LINDBERGH AVE Livermore 94550
 RECEIVED BY: *[Signature]* DEPT. NO.: 430-453

CASH PERSONAL/CASHIER'S CHECK/M. O. # 4464

OTHER: _____

110-1 (Rev 10/85) [0134E (08)] 3-Part

Distribution: White - Payor Yellow & Pink - Depart.

REF./

FILE OR **Remediation** ENVELOPE
 PER NO. No. _____ of _____

OWNER **SUNOL Comm. Center**

Address **37000 PALOMARES Rd**

SUNOL Phone _____

Contractor **URIAH, INC.**

Address **464 LINDBERGH AVE**
LIVERMORE 94550

Phone _____

OTHER (Specify) _____

Address _____

Phone _____

CONTACT FOR INVESTIGATION

PLAN REVIEW		By	Date
\$	Rec'd.		
No.	Plans Rec'd.		
	Plans Approved		
	Layout Made		
	Rejected		
	Applicant Notified		
	Plans Returned		
	Permit Issued		
CONSTRUCTION PROGRESS ACCEPTANCE			
DOOR	Pre-Plaster/drywall		
	Pre-Final		
	Final		

	By	Date	
	POOL		
Pre-Concrete/Gunite			
Pre-Plaster			
Final			
EXCAVATION			
	Septic Tank		
	Absorption Field		
FINAL			
	Absorption Bed		
	House Sewer		
OTHER			
	Septic Tank		
	Absorption Field		
Absorption Bed			

	By	Date
	U.G. TANKS	
Pre-Covering		
Final		

XR	REMARKS		
	Date	By	REMARKS

LOCATION _____

Vicinity Map

\$375.00
 10-2-90
 577069

*2069



WATSON COMMUNICATION SYSTEMS, INC.
1333 WILLOW PASS ROAD, SUITE 201
CONCORD, CALIFORNIA 94520
TELEPHONE: (415) 676-7642

April 19, 1990

Scott Seery
Alameda County, Department of
Environmental Health
80 Swan Way, #200
Oakland, CA 94621

Dear Mr. Seery:

Concerning the diesel spill that occurred at our Sunol Ridge communication site. We have secured the spill area by covering the soil that was removed with plastic and covered the trenched out area with plastic.

I met today with Helen Mawhinney of Uriah Inc. to look at the site. Helen will be at the site again on Tuesday, April 24, to take soil samples for evaluation.

I was informed by Uriah that the lab test will take about five days to get back. So, I will be calling you in about two weeks with the information I have at that time.

Sincerely,

Ron Sadler

Ron Sadler
Director, Site Maintenance

RS:hdk

90 MAR 20 9 41:06 AM '90

ALAMEDA COUNTY
HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director



Certified Mailer #P 062 127 924

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Program
80 Swan Way, Rm. 200
Oakland, CA 94621
(415)

February 2, 1990

Mr. Ron Sadler
Telecommunications Properties, Inc.
1333 Willow Pass Road, Suite 201
Concord, CA 94520

RE: FUEL LEAK; TELECOMMUNICATIONS PROPERTIES, INC. (TPI)
TRANSMITTING FACILITY, 3700 PALOMARES ROAD, SUNOL

Dear Mr. Sadler:

This letter is in response to this agency's inspection of the referenced facility on January 30, 1990. This inspection was prompted by a report from Mr. Jerry Siegel of MCI Telecommunications on January 26, 1990 which indicated diesel fuel had leaked from an auxiliary generator day tank during its repair. This day tank is associated with an underground storage tank (UST) of unknown size.

The January 30 inspection confirmed that product had impacted the backfill and native soil in proximity to the referenced UST. Before this inspection, several yards of material had already been excavated from around the top of the UST and adjacent areas, and is presently stockpiled on-site upon, and covered by, plastic. However, further assessment and excavation appear necessary to satisfactorily characterize and remediate the site.

Please be advised that the unauthorized release of product to the surface and subsurface strictly constitutes unlawful disposal of hazardous waste, a violation of Section 25189.5 of the California Health and Safety Code. Therefore, pursuant to Section 66328 (d) of Title 22, California Code of Regulations (CCR), you are directed to submit a Plan of Correction which addresses our concerns for the remediation of the area impacted by the noted diesel fuel release.

Your Plan of Correction should be in the form of a proposal to investigate and assess the impact this release of product may have had upon the environment. Once implemented, this work will help define the vertical and lateral impact upon soils and groundwater which resulted from the noted spill, and will steer an appropriate course of action to remediate the site.

Mr. Ron Sadler
RE: 3700 Palomares Road
February 2, 1990
Page 2 of 3

In order to submit a viable Plan of Correction and proceed with a site investigation, you will need to solicit the services of a reputable environmental consulting firm. Your responsibility will be to ensure that your consultant draft and submit for review a proposal outlining planned activities pertinent to meeting the requirements outlined in this letter, and to submit a final technical report summarizing site related activities once remediation of the noted site is complete.

Please submit your Plan of Correction within 30 days of receipt of this letter. Accompanying this plan should be a check, payable to Alameda County, ~~totaling \$23,100~~ as deposit to cover costs incurred by the county during oversight of this project. Any balance remaining after the close of this case will be refunded.

Until such time as additional work is performed, please securely cover the UST excavation with plastic to reduce the quantity of rainwater infiltrating through the contaminated backfill material. If applicable, it may also be prudent to provide a temporary berm at the edge of the asphalt to prevent runoff from flowing beneath this cover.

Additionally, Mr. Dave Sadler of TPI was provided California Underground Storage Tank Permit Application forms (Forms A and B) so that you may register your UST with the State of California. You must complete all areas of these forms where information is requested. Particular attention should be given to the section entitled "Leak Detection System" which requests that you indicate both primary and secondary methods of leak detection.


Further, as a facility which handles, stores, and/or uses hazardous material, pursuant to Chapter 6.95, Section 25500 et seq. of the California Health and Safety Code, you are required to submit a Business Plan. A Business Plan application packet was also provided Mr. Sadler during the January 30 inspection.

Please complete and submit both the California Underground Storage Tank Permit Application (Forms A and B) and Business Plan application within 30 days of the date of this letter.

Mr. Ron Sadler
 RE: 3700 Palomares Road
 February 2, 1990
 Page 3 of 3

Should you have any questions, please call me at 415/271-4320.

Sincerely,


 Scott O. Seery
 Hazardous Materials Specialist

SOS: tln

cc: Rafat A. Shahid, Assistant Agency Director, Alameda County
 Department of Environmental Health
 Gil Jensen, Alameda County District Attorney, Consumer and
 Environmental Protection Division
 Lester Feldman, RWQCB
 Howard Hatayama, DHS
 Jay Watson, TPI
 Jerry Siegel, MCI
 Jody Roman, MCI
 Files

P 062 127 924


RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED
 NOT FOR INTERNATIONAL MAIL
 (See Reverse)

Sent to	
Street and No	
P.O., State and ZIP Code	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt by Registered Mail (if applicable)	
Return Receipt by Registered Mail (if applicable)	
Other Postage and Fees	
Postmark or Date	

S.S.

Instructions: Complete Items 1 and 2 when additional services are desired, and attach to card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check boxes for additional service(s) requested.

1. <input checked="" type="checkbox"/> Show to whom delivered, date, and addressee's address. (Extra charge)	2. <input type="checkbox"/> Restricted Delivery (Extra charge)
3. Article Addressed to: MR. RON SADLER 1333 WILLOW PASS RD CONCORD, CA 94520	4. Article Number P 062 127 924
5. Signature - Address X	Type of Service: <input type="checkbox"/> Registered <input type="checkbox"/> Insured <input checked="" type="checkbox"/> Certified <input type="checkbox"/> COD <input type="checkbox"/> Express Mail <input type="checkbox"/> Return Receipt for Merchandise
6. Signature - Agent 	Always obtain signature of addressee on receipt and DATE DELIVERED.
7. Date of Delivery 2/6/90	8. Addressee's Address (ONLY if requested and fee paid)

January 30, 1990

scott seery
Alameda County Health Dept.
Division of Environmental Health
80 Swan Way, Room 200
Oakland, Ca 94621

90 FEB - 1 PM 3:31

Dear Mr. Seery:

The purpose of this letter is to follow-up on the oral report made by Gerald Siegel of MCI on Friday, 1/26/90, concerning an environmental incident which impacted MCI's site at 3700 Palomares Road, Alameda County, Sunol, California. The coordinates are latitude 37-37-12 and longitude 121-55-16.

On 1/26/90, an MCI employee noticed what appeared to be a diesel oil spill on the surface of MCI's leased property. MCI was not engaged in any activity which could have resulted in a release of diesel fuel.

The property is jointly used; the other occupant of the property is Telecommunications Properties, Incorporated (TPI). TPI has an above ground diesel tank which had been recently serviced and maintained. The oil which migrated onto MCI's property appeared to originate from an area close to TPI's tank.

After detecting the spill, MCI contacted TPI's representative, Steve Clark at (415) 676-7642 and inquired whether TPI had notified the appropriate governmental agency concerning the spill. Based on his discussion with TPI, Gerald Siegel contacted you.

Since the time of the oral report, clean-up of the spill has begun. MCI, however, has no direct knowledge of the identity of the people doing the work. Clean-up actions include: covering some of the contaminated soil with an absorbent material and surficial soil removal.

This is all the information MCI has concerning this incident. If you have further questions, please contact me at (415) 732-3035.

Sincerely,

Jody Roman
Senior Manager

90 JAN 32 PM 3:28

Jody C. Roman
MCIT Pacific Region
101 Howard Street
3rd Floor
9301/606
San Francisco CA 94105

90 JAN 32 PM 2: 20

scott seery
Alameda County Health Dept.
Division of Environmental Health
80 Swan Way, Room 200
Oakland, Ca 94621

*This letter was electronically transmitted and distributed by **MCI Mail***

*Call 800-444-6245 for information about sending **MCI Mail***

ZRH2

000192244490030211810000001*

white -env.health
 yellow -facility
 pink -files

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

80 Swan Way, #200
 Oakland, CA 94621
 (415) 271-4320

Hazardous Materials Inspection Form

(TPI)

II, III

II.A BUSINESS PLANS (Title 19)

- 1. Immediate Reporting 2703
- 2. Bus. Plan Stds. 25503(b)
- 3. RR Cars > 30 days 25503.7
- 4. Inventory Information 25504(a)
- 5. Inventory Complete 2730
- 6. Emergency Response 25504(b)
- 7. Training 25504(c)
- 8. Deficiency 25505(a)
- 9. Modification 25505(b)

II.B ACUTELY HAZ. MATLS

- 10. Registration Form Filed 25533(a)
- 11. Form Complete 25533(b)
- 12. RMPP Contents 25534(c)
- 13. Implement Sch. Req'd? (Y/N)
- 14. OffSite Conseq. Assess. 25524(c)
- 15. Probable Risk Assessment 25534(d)
- 16. Persons Responsible 25534(g)
- 17. Certification 25534(i)
- 18. Exemption Request? (Y/N) 25536(b)
- 19. Trade Secret Requested? 25538

III. UNDERGROUND TANKS (Title 23)

- | | |
|---|---|
| General | <input checked="" type="checkbox"/> 1. Permit Application 25284 (H&S) |
| | <input type="checkbox"/> 2. Pipeline Leak Detection 25292 (H&S) |
| | <input type="checkbox"/> 3. Records Maintenance 2712 |
| | <input type="checkbox"/> 4. Release Report 2651 |
| | <input type="checkbox"/> 5. Closure Plans 2670 |
| Monitoring for Existing Tanks | <input type="checkbox"/> 6. Method |
| | 1) Monthly Test |
| | 2) Daily Vadose
Semi-annual groundwater
One time soils |
| | 3) Daily Vadose
One time soils
Annual tank test |
| | 4) Monthly Gndwater
One time soils |
| | 5) Daily Inventory
Annual tank testing
Cont pipe leak det
Vadose/gndwater mon. |
| | 6) Daily Inventory
Annual tank testing
Cont pipe leak det |
| | 7) Weekly Tank Gauge
Annual tank testing |
| | 8) Annual Tank Testing
Daily Inventory |
| | 9) Other |
| New Tanks | <input type="checkbox"/> 7. Precls Tank Test 2643
Date: _____ |
| | <input type="checkbox"/> 8. Inventory Rec. 2644 |
| | <input type="checkbox"/> 9. Soil Testing 2646 |
| | <input type="checkbox"/> 10. Ground Water. 2647 |
| <input type="checkbox"/> 11. Monitor Plan 2632 | |
| <input type="checkbox"/> 12. Access. Secure 2634 | |
| <input type="checkbox"/> 13. Plans Submit 2711
Date: _____ | |
| <input type="checkbox"/> 14. As Built 2635
Date: _____ | |

Site ID # _____ Site Name Telecommunication Prop., Inc Today's Date 9/130/90

Site Address 3700 Palameras Rd.

City Sunol Zip 94 Phone 676-7642

MAX AMT stored > 500 lbs, 55 gal., 200 cft.?

Inspection Categories:

- I. Haz. Mat/Waste GENERATOR/TRANSPORTER
- II. Business Plans, Acute Hazardous Materials
- III. Underground Tanks

* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

Comments:

* Pictures taken.
 In response to a call from mecl (who leases transmitting space from TPI) which described a spill of diesel from a day tank assoc. with a generator on-site, I inspected the site to determine what additional measures will be necessary to remove the soils impacted by the spilled diesel. Several cu.yds. of soil has been removed from above a UST assoc. with the day tank. The backfill material appears to be saturated. The UST/day tank are situated adjacent to a fairly steep slope. This slope is comprised of native material which has also been impacted by the diesel leak, although appears to be of a lesser degree. The impact has yet to be fully assessed; further work is required to remove contaminated material from around the UST (which has no concrete slab over its top) and the native soil adjacent to it. Request that a 3rd party consultant be contracted to assess and clean up the site. Also, the UST is not on record as being registered. This, too, must be done; no business plan is on file. Letter is forthcoming.

II, III

Contact: Dave Sadler

Title: Site Maintenance, TPI

Signature: Dave Sadler

Inspector: S. Seery

Signature: [Signature]

RECEIPT OF THE BUSINESS PLAN FORM
UNDER H & SC, CHAPTER 6.95

I hereby acknowledge receipt of a business plan form^{*} which is to be completed by the below named business or facility. I understand that this plan is to be submitted to the Alameda County Department of Health within 30 days of the receipt of this plan.

** and Underground Storage Tank registration form*

Name of Business: Telecommunications Properties, Inc
Site Address: 3700 Palamares Road, Sunol Ridge
~~Street~~ Sunol (Niles)
City, Zip Code 945

Person receiving this plan:

Printed Name: Dave Sadler
Title: Site Maintenance
Signature: David Sadler
Date: 1-30-90



ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY
DEPARTMENT OF ENVIRONMENTAL HEALTH
HAZARDOUS MATERIALS DIVISION
80 SWAN WAY, ROOM 200-
OAKLAND, CA 94621
415/271-4320

HAZARDOUS MATERIALS RELEASE AND NOTIFICATION REPORT (H&SC 25180.7)
 EMERGENCY RESPONSE

1. INFORMATION RECEIVED BY: Scott Siny

DATE: 1-26-90 TIME: _____

2. INCIDENT LOCATION: 3700 Tolman Rd
CITY: Sunnyvale ZIP CODE: 94086

3. DATE OF INCIDENT: UNK TIME OF INCIDENT: UNK

4. REPORTED BY: Jerry Siegel AGENCY: AT&T Telecommunications
ADDRESS: 21350 Cabrillo Blvd. CITY, ZIP: Hayward 94545
TELEPHONE: 415-732-2079 CONTACT: same
PHONE: _____

5. TYPE OF DISCHARGE:
 Discharge from vehicle License Plate No. _____
Manifest/Shipping Information: _____
 Abandoned Material Fixed Facility
Name: Telecommunications Institute Inc Address: 3700 Tolman Rd
City: Sunnyvale Zip Code: _____
 Other (specify) _____

6. ESTIMATED QUANTITY DISCHARGED: approx. 25-40 gallons
QUANTITY THREATENED TO BE RELEASED: none

7. NATURE OF MATERIAL:
 Solid Liquid Gas Powder Granular
 Radioactive Other

Chemical Name: diesel fuel Common Name: diesel fuel

8. HAZARDOUS PROPERTIES: Corrosive Ignitable Toxic
 Reactive Other

9. HAZARDOUS MATERIAL WAS RELEASED TO:
 Air Storm Drain San Francisco Bay Sanitary Sewer
 Other Natural Waterway (creek, lake, reservoir) Groundwater
 Groundsurface (soil, road, etc.) Other (specify) _____

10. WEATHER CONDITIONS: clear

11. NUMBER OF INJURED PERSONS REQUIRING HOSPITALIZATION: none
NAMES AND ADDRESSES OF HOSPITALS UTILIZED: _____

12. PERSONS PRESENT AT SCENE:

NAME: Dave Seiler AFFILIATION: TPI PHONE NO. 415-676-7442

13. RESPONSIBLE PARTY:

NAME: Environmental Properties Inc PHONE NO. 415-676-7442
ADDRESS: 1333 Willow Pass Road, Concord, CA 94520

14. EVIDENCE COLLECTED (SAMPLES, PHOTOGRAPHS, ETC.)

15. CLEAN-UP ACTIONS: excavation; more work pending

NAMES AND ADDRESSES OF PERSONS DOING CLEAN-UP:

TPI personnel currently; others pending approval of work plan

DESCRIPTION OF CLEAN-UP ACTIONS:

excavation of impacted material;

16. TIME INCIDENT CLOSED: open

17. ELAPSED TIME: N/A

18. DISCHARGE NOT TO BE NOTIFIED:

- Unlikely to Cause Substantial Injury to Public Health & Safety
- Public knowledge Ongoing criminal investigations
- Permitted Discharge Other

19. DISCHARGE TO BE NOTIFIED:

FACTORS DETERMINING THAT THIS HAZARDOUS WASTE DISCHARGE OR POTENTIAL DISCHARGE IS LIKELY TO CAUSE SUBSTANTIAL INJURY TO THE PUBLIC HEALTH OR SAFETY:

20. NOTIFICATION:

- Board of Supervisors
- Health Officer
- Alameda County Press Room
- California Department of Health Services
- Reporting Agency or Individual

By copy of this report to the above listed agencies and officials, we are hereby submitting this information on behalf of all designated employees of the Department of Environmental Health, according to Section 25180.7, Health & Safety Code. The information submitted in this report is based upon the best available information at the time the report was completed.

Inspector's Name: Scott Seiler
Inspector's Signature: [Signature]

Date: 1-31-90

EH/mam/88



ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY
DEPARTMENT OF ENVIRONMENTAL HEALTH
HAZARDOUS MATERIALS DIVISION
80 SWAN WAY, ROOM 200-
OAKLAND, CA 94621
415/271-4320

- HAZARDOUS MATERIALS RELEASE AND NOTIFICATION REPORT (H&SC 25180.7)
 EMERGENCY RESPONSE

1. INFORMATION RECEIVED BY: Scott Searcy

DATE: 1-28-90 TIME: _____

2. INCIDENT LOCATION: 3700 Tolman Rd
CITY: San ZIP CODE: 94536

3. DATE OF INCIDENT: UNK TIME OF INCIDENT: UNK

4. REPORTED BY: Jerry Siegel AGENCY: AT&T Telecommunications
ADDRESS: 21350 Cabot Blvd. CITY, ZIP: Hayward 94525
TELEPHONE: 415-732-2079 CONTACT: same
PHONE: _____

5. TYPE OF DISCHARGE:
 Discharge from vehicle License Plate No. _____
Manifest/Shipping Information: _____
 Abandoned Material Fixed Facility
Name: Telecommunications International Address: 3700 Tolman Rd
City: San Zip Code: _____
 Other (specify) _____

6. ESTIMATED QUANTITY DISCHARGED: approx. 25-40 gallons
QUANTITY THREATENED TO BE RELEASED: none

7. NATURE OF MATERIAL:
 Solid Liquid Gas Powder Granular
 Radioactive Other

Chemical Name: diesel fuel Common Name: diesel fuel

8. HAZARDOUS PROPERTIES: Corrosive Ignitable Toxic
 Reactive Other

9. HAZARDOUS MATERIAL WAS RELEASED TO:
 Air Storm Drain San Francisco Bay Sanitary Sewer
 Other Natural Waterway (creek, lake, reservoir) Groundwater
 Groundsurface (soil, road, etc.) Other (specify) _____

10. WEATHER CONDITIONS: clear

11. NUMBER OF INJURED PERSONS REQUIRING HOSPITALIZATION: none
NAMES AND ADDRESSES OF HOSPITALS UTILIZED:

Report of fuel leak

1-26-90

Properties

Jerry Siegel 732-2079
MCI Telecommunications - 2080

- Sunol Mtn. -
- diesel fuel "seepage"
- 1-26-90 detected

Thinks came from here →

Telecommunications, Inc.

TPI

Steve Clark -

above-ground clay

415-676-7642

UST ? above ground

~~732-2298~~

facility #

732-2298
- 2291

- need to arrange a time to inspect

Address of site

3700 Palomares Rd
Alameda Co.

owned by TPI

Tuesday?


37° 37' 12" lat
121° 55' 16" long

541-1980
541-1495
mark Reason
449-1766
916-1767

1707 Wood St
Oakland 94607

Telecommunications Properties, Inc (TPI)

- own site (structures, antenna, space)



TPI

Two (2) tanks on-site

1) MCI

2) TPI

MCI Telecommunications
21350 Cabot Blvd
Hayward, Ca 94545

Attn: Jody Roman, Senior Mgr. Encumbrance

cc: Jerry Siegel