

Facility Name Frank Sanchez Trucking Address 2100 Carden Date 8/27/90  
 Inspector M. Bakaldin Arrival Time 1550 Departure Time 1830  
 Contact at Site Dino Gonis Company Tank Protect Engineering

|                 | Tank 1     | Tank 2 | Tank 3 | Tank 4 |
|-----------------|------------|--------|--------|--------|
| Tank Content    | Diesel     |        |        |        |
| Tank Size       | 10,000 gal |        |        |        |
| % LEL / % O2    | <5% / <5%  |        |        |        |
| Lbs Dry Ice     | 400        |        |        |        |
| Corrosion/Holes | Yes/No     |        |        |        |
| No. of Samples  | 3          |        |        |        |
| Soil odor/color | No/No      |        |        |        |

Piping: Supply  Vapor Return  Vent  Piping Removed: Yes  
 Piping Sampled: No No. of samples:      Sample odor/color:     

| Site Map        | Sample Description                       |
|-----------------|--|
|                 | #1 <u>Soil - South end - sidewalk</u>    |
|                 | #2 <u>Soil - North end - sidewalk</u>    |
|                 | #3 <u><del>So</del> Water - tank pit</u> |
|                 | #4 <u>    </u>                           |
|                 | #5 <u>    </u>                           |
|                 | #6 <u>    </u>                           |
|                 | #7 <u>    </u>                           |
|                 | #8 <u>    </u>                           |
|                 | #6 <u>    </u>                           |
|                 | #7 <u>    </u>                           |
|                 | #8 <u>    </u>                           |
|                 | #9 <u>    </u>                           |
|                 | #10 <u>    </u>                          |
|                 | #11 <u>    </u>                          |
| #12 <u>    </u> |  |
| #13 <u>    </u> |  |
| #14 <u>    </u> |  |

Comments: Water sample collected 8/31/90