Drogos, Donna, Env. Health

From: Sent: To: Subject: Attachments:	Vibeke Norgaard [vnorgaard@hotmail.com] Thursday, August 12, 2010 8:46 AM Drogos, Donna, Env. Health FW: 6501 Shattuck Ave. demolition activity IMG_4121.JPG; IMG_4114.JPG; IMG_4115.JPG; IMG_4116.JPG; IMG_4117.JPG; IMG_ 4118.JPG; IMG_4119.JPG; IMG_4120.JPG
Categories:	Mail_Cases

Hi Donna,

More photos re the demolition and an email sent around the time from a concerned neighbor describing activity.

Vibeke

Date: Wed, 11 Aug 2010 16:53:24 -0700 From: <u>jbfaust@pacbell.net</u> Subject: Fw: 6501 Shattuck Ave. demolition activity To: <u>vnorgaard@hotmail.com</u>

Thanks, Vibeke, for your investigation into the various permit activities at 6501. Below is an e-mail and photos I sent March 19 to John Lawton of the BAAQMD regarding the demolition I was observing at the site. I called him in the morning and he advised that I take pictures with a time/date stamp and submit them. I also sent a note to the neighborhood listserv at the time, but didn't attach the photos. Hope this is helpful for the timeline.

John Faust 721 65th St.

----- Forwarded Message ---From: John Faust <jbfaust@pacbell.net>
To: jlawton@baaqmd.gov
Sent: Fri, March 19, 2010 10:13:14 AM
Subject: 6501 Shattuck Ave. demolition activity

Mr. Lawton,

Attached are my photos of the activity that's going on at 6501 Shattuck Ave. right now. It appears that demolition is continuing. A man named George approached me and asked my interest in what was going on. I told him I was a concerned neighbor. He told me he thought the permits were "in the works", but they just wanted to get things moving while the weather was nice. I observed 4 people at the site, one operating the bucket loader, one hosing for dust, one preparing the truck, and another monitoring from a truck on the steet (George).

Hope this is helpful.

John Faust 721 65th St.