

COUNTY OF ALAMEDA UNDERGROUND TANK SYSTEM CLOSURE INSPECTION REPORT

For Use By the County of Alameda, Environmental Health

SR0016 790

Facility Name: LESLIE MULHOLLAND Contractor's name: GOLDEN GATE TANK REMOVAL
 Address: 132 GUILFORD ROAD City: PIEDMONT Zip: _____

Project Contact: JOSHUA ALEXANDER Phone No.: _____

Tank ID No.	/				
Size	GALLONS				
Construction Material	STEEL				
Single/Double Wall	SW				
Backfill Type	SAND				
Oxygen <10%	/				
LEL <20%	/				
Tank Condition	HOLES				
Soil/Groundwater Condition	PENETRATED ROCK SUBSTRATE				
Soil Sample Depth	VARIOUS				
Number and Description of Soil/Groundwater Samples (Indicate Sample Locations on Site Plan.)	SMALL EXCAVATION	SEE PHOTOS			

Disposition of Tank Contents: CLEAN WATER ENV Piping: Rinsed/Tested/Capped. Rinsate: Shipped on Manifest.
 Tank & Piping Transport: Shipped on Manifest; Transporter Name Same as on Application.
 Sampling: Evidence Tape; Chain of Custody; Samples Refrigerated; Pipeline Samples Taken Yes, No (If no, explain why in Comments.)
 Soil: Soil Stored on Bermed Plastic & Covered; Soil Returned to Excavation. Site Plan: Attached.
 Comments/Special Conditions: IN ROLL OFF BOX VERY ROCKY SOIL, SMALL TANK W/ HOLES, SPILLAGE ON WATER IN PIT. RAINY DAY TANIC IN LAWN AREA

Inspector: [Signature] Agency: _____ Date: 4-2-10 Start Time: _____ Stop Time: _____

Signature of Contractor/Authorized Agent: _____ Date: _____ Page _____ of _____