## UST Removal; 1342 Stanford Avenue; "Emeryville Parkside" September 11, 2012; 1:00 – 3:30 inclusive of travel and notes

- Leave ACEH @ 1:00pm for site with Chris Tougeron for 1:30 UST removal; Treadwell & Rollo (Peter Cusack) and Rob onsite for soil sampling.
- Arrive 1:30ish; UST ready for removal; held down by Deadmen, perhaps poured / installed after UST install per contractor supposition (Ron Rinehart, Complete Environmental Solutions, Inc.); soil / gravel exposed at base of UST; UST reported buried 2 ft, 8 ft diameter; groundwater not encountered.
- Fill end at east end; tank age estimated at 60 plus years; bottom samples collected for CUPA, no water in soil sample 2 ft below base of UST but was very moist; LOP requested sidewall samples at upper level of concrete Deadmen on all four walls. Suspect staining along N and E ends of UST, at top level of concrete

LOP photos on Chris's camera.