Drogos, Donna, Env. Health

| From: | Brent Wheeler [b.wheeler@ggtr.com] |
|-------------|--------------------------------------------------------------|
| Sent: | Monday, May 06, 2013 9:32 AM |
| To: | Annette Chen; Drogos, Donna, Env. Health; 'Skillern, Sheryl' |
| Cc: | link@linkcorkery.com; jvjung98@gmail.com; Tim Hallen |
| Subject: | Re: 640 Brooklyn Ave, Oakland_LUST Investigation |
| Categories: | Mail_Cases |

Donna,

On behalf of RP for subject property, we have made several attempts to contact you regarding review status of UST Removal Closure Report and further corrective action work regarding the LUST investigation, if warranted. If this project was transferred to a specific ACDEH case manager, please provide us with contact information so that we may follow up with any further directive. Thank you for your assistance on this project.

Regards,

Brent Wheeler Golden Gate Environmental, Inc. Golden Gate Tank Removal, Inc. 1455 Yosemite Avenue San Francisco, CA 94124

Direct GGE: 415-970-9088 Direct GGTR: 415-512-1555 Cellular: 415-686-8846 Email: b.wheeler@ggtr.com wheelerbrent@ymail.com

From: Annette Chen <<u>annettechen@ggtr.com</u>> To: <u>donna.drogos@acgov.org;</u> "'Skillern, Sheryl'" <<u>SSkillern@oaklandnet.com</u>> Cc: <u>b.wheeler@ggtr.com; link@linkcorkery.com; jvjung98@gmail.com</u> Sent: Wednesday, April 17, 2013 10:44 AM Subject: RE: 640 Brooklyn Ave

Good Morning Donna,

Attached please find the tank closure report for your review.

Should you have any questions or need further information, please feel free to contact us.

Thank you, Annette Chen Golden Gate Tank Removal, Inc. 1455 Yosemite Avenue San Francisco, CA 94124 Tel: 415-512-1555 Fax: 415-512-0964 From: Skillern, Sheryl [mailto:SSkillern@oaklandnet.com] Sent: Tuesday, April 9, 2013 3:59 PM To: donnadrogas@acgov.org Cc: Annette Chen Subject: 640 Brooklyn Ave

Donna,

As we discussed yesterday, the above site is being referred to you for follow-up. The analyses reports were mailed to you yesterday. You advised that a water sample needs to be taken and specific fill material needs to be used to temporarily close the pit.

This pit is a 17' foot hole in the sidewalk in front of an apartment building. It is barricaded and covered with wood however it is a potential hazard and we would like the pit filled in as quickly as possible. Can you please provide Golden Gate and the property owner with instructions for taking the water sample and materials they need to use to temporarily closing the hole.

Sincerely, Sheryl Skillern Senior Hazardous Materials Inspector City of Oakland Fire Prevention Bureau 250 Frank H Ogawa Plaza, Suite 3341 Oakland, Ca 94612 Tel: 510 238-7253 Fax: 510 238-6739