

12/13/2017 Phone Log- RO3148 EMBL LLC Tank, 1501 Martin Luther King Jr. Way, Oakland

Duration: Approximately 10 minutes

Exchanged voice mails before received a phone call from Frank Hamedi of Enviro Soil Tech Consultants (ESTC) regarding our request for a work plan. Mr. Hamedi pointed out that our letter stated the depth to water was less than 10 feet- it is 25-30 feet. I apparently used the groundwater elevation.

Mr. Hamedi asked questions regarding soil sample collection in the 0- to 5 and 5- to 10-foot zones. I indicated only one sample from each of these intervals from each soil bore was needed, he interpreted this as sampling at every foot. For soil vapor sampling I indicated the sample should be collected 5 feet below the base of the foundation.

Interior soil bore- Mr. Hamedi thought the location proposed at our on-site meeting, the employee lunch room, may not be accessible to the drill rig. He proposed on the other side of the wall in the main commercial space. I told him this may be too close to the down gradient well. At the on-site meeting we had discussed the well location to be about mid-distance from the former tank pit and the down gradient well. He will propose the location with the work plan submittal.

Keith Nowell