

Detterman, Karel, Env. Health

From: Detterman, Karel, Env. Health
Sent: Friday, October 27, 2017 2:37 PM
To: 'Robert Kitay'
Cc: coachelliott@me.com; Roe, Dilan, Env. Health; JDHAULING@hotmail.com
Subject: RE: Excavation schedule for Fuel leak Case RO3159 and GeoTracker Global ID Number T10000006491 - Roofing Facility, 745 Kevin Court, Oakland, CA 94621
Attachments: Attachment_1_and_ftpUploadInstructions_2016-12-15.pdf

Hello Robert:

During our meeting, the decision not to collect confirmation samples was based on the site conceptual model that water would fill the excavation. Because the site conceptual model was not accurate and water did not fill the excavation, we are now requesting confirmation samples, which will provide another line of evidence.

Rain is not forecast for next week, so please perform the confirmation sampling next week and as requested in the October 6, 2017 Directive Letter include the analytical results, photos, trench logs, and backfill documentation with the Remedial Action Report. I have provided a report extension below:

REVISED TECHNICAL REPORT REQUEST

Please upload technical reports to the ACDEH ftp site (Attention: Karel Detterman), and to the State Water Resources Control Board's GeoTracker website, in accordance with the following schedule and file naming convention:

- **December 29, 2017 ~~December 8, 2017~~ Remedial Action Report**
File to be named: RO3159_RA_R_YYYY-MM-DD

This report is being requested pursuant to California Health and Safety Code Section 25296.10. 23 CCR Sections 2652 through 2654, and 2721 through 2728 outline the responsibilities of a responsible party in response to an unauthorized release from a petroleum UST system, and require your compliance with this request.

Should you have any questions, please contact me at (510) 567-6708 or send me an electronic mail message at karel.detterman@acgov.org

Thank you,

Karel Detterman, PG
Hazardous Materials Specialist
Alameda County Environmental Health
1131 Harbor Bay Parkway
Alameda, CA 94502
Direct: 510.567.6708
Fax: 510.337.9335
Email: karel.detterman@acgov.org

PDF copies of case files can be downloaded at:

<http://www.acgov.org/aceh/lop/ust.htm>

From: Robert Kitay [mailto:cleaneearthgeo@gmail.com]
Sent: Friday, October 27, 2017 11:31 AM
To: Detterman, Karel, Env. Health <Karel.Detterman@acgov.org>
Cc: coachelliott@me.com; Roe, Dilan, Env. Health <Dilan.Roe@acgov.org>; JDHAULING@hotmail.com
Subject: Re: Excavation schedule for Fuel leak Case RO3159 and GeoTracker Global ID Number T10000006491 - Roofing Facility, 745 Kevin Court, Oakland, CA 94621

Hi Karel -

There isn't very much water (or at least there wasn't yesterday). At the meeting we were specifically told NOT to collect confirmation soil samples from the sidewalls and our workplan states that we are not to collect confirmation sidewall samples. The only soil sample to be collected is from the stockpiled soil for landfill profiling purposes. This has already been completed and the sample analyzed on a rush basis. Attached is the analytical report. During the stockpile sampling I collected the sample from the darkest black material I could find.

Robert Kitay
Clean Earth Geologic, LLC
[\(925\) 413-8604](tel:(925)413-8604)

On Fri, Oct 27, 2017 at 10:59 AM, Detterman, Karel, Env. Health <Karel.Detterman@acgov.org> wrote:

Hello Robert:

If there is not much water in the trench , please collect confirmation samples for laboratory analysis (one sample per 20 linear feet) from fresh surfaces of the floor and sidewalls. After confirmation sample collection, please backfill the trench with documented clean

backfill as per the October 6, 2017 Directive Letter.

Thank you for the update,

Karel Detterman, PG
Hazardous Materials Specialist
Alameda County Environmental Health
[1131 Harbor Bay Parkway](#)
[Alameda, CA 94502](#)
Direct: [510.567.6708](tel:510.567.6708)
Fax: [510.337.9335](tel:510.337.9335)
Email: karel.detterman@acgov.org

PDF copies of case files can be downloaded at:

<http://www.acgov.org/aceh/lop/ust.htm>

From: Robert Kitay [mailto:[cleanearthgeo@gmail.com](mailto:cleaneearthgeo@gmail.com)]

Sent: Wednesday, October 25, 2017 11:59 AM

To: Detterman, Karel, Env. Health <Karel.Detterman@acgov.org>

Subject: RE: Excavation schedule for Fuel leak Case RO3159 and GeoTracker Global ID Number T10000006491 - Roofing Facility, [745 Kevin Court, Oakland, CA 94621](#)

No, they put caution tape and cones around it.

Sent via the Samsung GALAXY S® 5, an AT&T 4G LTE smartphone

----- Original message -----

From: "Detterman, Karel, Env. Health" <Karel.Detterman@acgov.org>

Date: 10/25/17 11:12 AM (GMT-08:00)

To: 'Robert Kitay' <cleanearthgeo@gmail.com>

Subject: RE: Excavation schedule for Fuel leak Case RO3159 and GeoTracker Global ID Number T10000006491 - Roofing Facility, [745 Kevin Court, Oakland, CA 94621](#)

Hello Robert:

Thank you for the update; Dilan is out today but I'll catch her up about the trench tomorrow. Will trench plates be used to cover the trench until it's back filled?

Karel Detterman, PG

Hazardous Materials Specialist

Alameda County Environmental Health

[1131 Harbor Bay Parkway](#)

[Alameda, CA 94502](#)

Direct: [510.567.6708](tel:510.567.6708)

Fax: [510.337.9335](tel:510.337.9335)

Email: karel.detterman@acgov.org

PDF copies of case files can be downloaded at:

<http://www.acgov.org/aceh/lop/ust.htm>

From: Robert Kitay [<mailto:cleanearthgeo@gmail.com>]

Sent: Wednesday, October 25, 2017 10:51 AM

To: Detterman, Karel, Env. Health <Karel.Detterman@acgov.org>

Subject: RE: Excavation schedule for Fuel leak Case RO3159 and GeoTracker Global ID Number T10000006491 - Roofing Facility, [745 Kevin Court, Oakland, CA 94621](#)

Hi Karel -

We completed the excavation this morning. There wasn't a whole lot of black material, mostly surrounding some buried metal debris that we removed. The sidewalls look brown/dark brown and there was never really any odor anywhere nor PID readings above zero. I've collected a sample for the lab and will be heading there shortly. The final dimensions of the excavation were 5 foot wide by 21 long by 5 to 6 feet deep. Only a small amount of water seeped into the bottom of the excavation on the western side.

I told them to hold off on backfilling for a day or two in the event you want to come out to take a look at the excavation. I've taken pictures that I will include in my report, and I've attached a couple here.

Feel free to call me if you have any questions.

Robert Kitay

Clean Earth Geologic, LLC

----- Original message -----

From: "Detterman, Karel, Env. Health" <Karel.Detterman@acgov.org>

Date: 10/19/17 2:58 PM (GMT-08:00)