



ALAMEDA COUNTY
ENVIRONMENTAL HEALTH DEPARTMENT
Certified Unified Program Agency (CUPA)
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577

Photo Log

Case: RO3181

Name: GIG Soil Cleanup

Address: 8467 Patterson Pass Road, Livermore, CA


Date: November 6, 2015

Photo Taken by: Jerry Wickham



Description: Excavation of southwest stained soil in SW corner

Photo # 1 of



Description: Stained soil in SW corner of excavation

Photo # 2 of



ALAMEDA COUNTY
ENVIRONMENTAL HEALTH DEPARTMENT
Certified Unified Program Agency (CUPA)
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577

Photo Log

Case: RO3181

Name: GIG Soil Cleanup

Address: 8467 Patterson Pass Road, Livermore, CA

Date: November 6, 2015

Photo Taken by: Jerry Wickham



Description: Bottom of excavation eastern end

Photo # 3 of



Description: Northern sidewall

Photo # 4 of



ALAMEDA COUNTY
ENVIRONMENTAL HEALTH DEPARTMENT
Certified Unified Program Agency (CUPA)
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577

Photo Log

Case: RO3181

Name: GIG Soil Cleanup

Address: 8467 Patterson Pass Road, Livermore, CA

Date: November 6, 2015

Photo Taken by: Jerry Wickham



Description: Sampling southern wall of excavation

Photo # 5 of

