Name: E&B NATURAL RESOURCES - NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



ALAMEDA COUNTY
ENVIRONMENTAL HEALTH DEPARTMENT
Certified Unified Program Agency (CUPA)
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577
(510) 567-6700
FAX (510) 337-9335



DESCRIPTION: FACILITY

Photo # 1 of 26



DESCRIPTION: PILE OF SOIL FROM SITE'S EXCAVATION

Photo # 2 of 26

Name: E&B NATURAL RESOURCES - NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



ALAMEDA COUNTY ENVIRONMENTAL HEALTH DEPARTMENT Certified Unified Program Agency (CUPA) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



DESCRIPTION: TRASH DUMPSTER WITH CLOSED LID

Photo # 3 of 26



DESCRIPTION: VIEW OF ENTRANCE AND PARKING AREA – PERMEABLE GRAVEL

Photo # 4 of 26

Name: E&B NATURAL RESOURCES - NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



ALAMEDA COUNTY ENVIRONMENTAL HEALTH DEPARTMENT Certified Unified Program Agency (CUPA) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



DESCRIPTION: EXCAVATION AREA WHERE 4 TANKS WERE REMOVED

Photo # 5 of 26



DESCRIPTION: EXCAVATION AREA WHERE 4 TANKS WERE REMOVED

Photo # 6 of 26

Name: E&B NATURAL RESOURCES - NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



ALAMEDA COUNTY ENVIRONMENTAL HEALTH DEPARTMENT Certified Unified Program Agency (CUPA) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



DESCRIPTION: FUEL LOADING AREA WITH SPILL CAPTURE BASIN THAT RUNS BACK INTO THE SYSTEM

Photo # 7 of 26



DESCRIPTION: BALL TRAP OIL AND WATER SEPARATOR SYSTEM

Photo # 8 of 26

Name: E&B NATURAL RESOURCES – NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



ALAMEDA COUNTY ENVIRONMENTAL HEALTH DEPARTMENT Certified Unified Program Agency (CUPA) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



DESCRIPTION: BALL TRAP OIL AND WATER SEPARATOR SYSTEM

Photo # 9 of 26



DESCRIPTION: VIEW OF INSIDE OF FUELING SPILL CATCHING BASIN

Photo # 10 of 26

Name: E&B NATURAL RESOURCES - NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



ALAMEDA COUNTY ENVIRONMENTAL HEALTH DEPARTMENT Certified Unified Program Agency (CUPA) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



DESCRIPTION: PIPE AND VALVE

Photo # 11 of 26



DESCRIPTION: VIEW OF OIL SPILL STAIN ON THE GRAVEL AND PIPING

Photo # 12 of 26

Name: E&B NATURAL RESOURCES - NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



ALAMEDA COUNTY ENVIRONMENTAL HEALTH DEPARTMENT Certified Unified Program Agency (CUPA) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700

FAX (510) 337-9335



DESCRIPTION: VAREC LEVEL GAUGE OF STOCK TANK

Photo # 13 of 26



DESCRIPTION: SCORTRON MATERIALS NOT IN HAZARDOUS MATERIAL INVENTORY

Photo # 14 of 26

Name: E&B NATURAL RESOURCES - NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



ALAMEDA COUNTY ENVIRONMENTAL HEALTH DEPARTMENT Certified Unified Program Agency (CUPA) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



DESCRIPTION: SCORTRON MATERIALS WITH ELECTRICAL CORDS

Photo # 15 of 26



DESCRIPTION: SCORTRON MATERIALS WITH ELECTRICAL CORDS

Photo # 16 of 26

Name: E&B NATURAL RESOURCES - NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



**ALAMEDA COUNTY ENVIRONMENTAL HEALTH DEPARTMENT Certified Unified Program Agency (CUPA)** 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700

FAX (510) 337-9335



Photo # 17 of 26 06/11/2015 11:20 Photo # 18 of 26

DESCRIPTION: STOCK TANK #1 – VALVES WIL MINOR WEEPING.

Name: E&B NATURAL RESOURCES - NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



ALAMEDA COUNTY ENVIRONMENTAL HEALTH DEPARTMENT Certified Unified Program Agency (CUPA) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



DESCRIPTION: POLISHER WATER TANK

Photo # 19 of 26



DESCRIPTION: CURRENTLY CLOSED SYSTEM, LEVEL GAUGE IS BROKEN

Photo # 20 of 26

Name: E&B NATURAL RESOURCES - NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



ALAMEDA COUNTY ENVIRONMENTAL HEALTH DEPARTMENT Certified Unified Program Agency (CUPA) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



DESCRIPTION: CURRENTLY CLOSED SYSTEM, LEVEL GAUGE IS BROKEN

Photo # 21 of 26



DESCRIPTION: GAS SYSTEM THAT SENDS GAS TO ENCLOSED COMBUSTION

Photo # 22 of 26

Name: E&B NATURAL RESOURCES - NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



ALAMEDA COUNTY ENVIRONMENTAL HEALTH DEPARTMENT Certified Unified Program Agency (CUPA) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



DESCRIPTION: ENCLOSED COMBUSTION SYSTEM

Photo # 23 of 26



DESCRIPTION: SOIL BERM OUTSIDE THE FENCE BETWEEN FACILITY AND CREEK

Photo # 24 of 26

Name: E&B NATURAL RESOURCES - NISSEN TANK FARM

Address: 8617PATTERSON PASS ROAD

LIVERMORE, CA 94551

Date: 06/11/2015

Photo Taken by: KEVIN HOM



ALAMEDA COUNTY ENVIRONMENTAL HEALTH DEPARTMENT Certified Unified Program Agency (CUPA) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



DESCRIPTION: SOIL BERM WITH OIL CONTAMINATED SOIL – POTENTIAL FOR OIL RUNOFF ON OUTSIDE OF BERM

Photo # 25 of 26



DESCRIPTION: SOIL BERM WITH OIL CONTAMINATED SOIL – POTENTIAL FOR OIL RUNOFF ON OUTSIDE OF BERM

Photo # 26 of 26