UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK)/ CONTAMINATION SITE REPORT						
EMERGENCY HAS STATE OFFICE OF EMERGENCY SERVICES Presservices REPORT BEEN FILED? Yes No				FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PERSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.		
REPORT DATE CASE # 1/26/16				SIGNED DATE		
REPORTED BY	NAME OF INDIVIDUAL FILING REPORT		^{РНОМЕ} (415) 512-1555	SIGNATURE	
	REPRESENTING C LOCAL AGENCY REGIONAL BOARD OWNER/OPERATOR C OTHER C Contractor			Golden Gate Tank Removal, Inc.		
	ADDRESS 1480 Carroll Avenue			San Francisco	CA	94124 _{ZIP}
RESPONSIBLE PARTY	378 Grand Avenue, LLC					^{рноле} 510-540-5982
	ADDRESS 2295 San Pablo Avenue	ΈT		Berkeley	CA	94702 Tate zip
SITE LOCATION	FACILITY NAME (IF APPLICABLE)			OPERATOR		PHONE
	ADDRESS 378 Grand Avenue CROSS STREET CROSS STREET CROSS STREET CROSS STREET					
	Staten Avenue					
IMPLEMENTING AGENCIES	In Coal AGENCY AGENCY NAME PHONE Image: State of the state of th					^{рноле} 5 <mark>10-567-6737</mark>
	REGIONAL BOARD PHONE					
SUBSTANCES INVOLVED	Diesel	QUANTITY LOST (GALLONS)				
SUBST INVO	(2)					
TEMENT	DATE DISCOVERED 1/26/16	HOW DISCOVERED □ Tank Test □ Tank Removal □ Nuisance Conditions □ Inventory Control □ Subsurface Monitoring ☑ Other Tank Cleaning				
DISCOVERY/ABATEMENT	DATE DISCHARGE BEGAN METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)					
	HAS DISCHARGE BEEN STOPPED? The set of the			Repair Tank Change Procedure Replace Tank Other Repair Piping		
					_	
E SOURCE/ E CAUSE	Tank Leak Piping Leak 🖾 Unknown 🗋 Other					
CASE TYPE	Undetermined 🕅 Soil Only 🔲 Groundwater 🗋 Drinking Water - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)					
CURRENT STATUS	CHECK ONE ONLY No Action Taken Case Closed (Cleanup Completed or Unnecessary) Leak Being Confirmed Pollution Characterization Remediation Plan Post Cleanup Monitoring in Progress Preliminary Site Assessment Workplan Submitted Cleanup Underway					
REMEDIAL ACTION	CHECK APPROPRIATE ACTION(S) Cap Site (CD) Excavate & Treat (ET) Contamination Barrier (CB) No Action Required (NA) Contamination Barrier (CB) No Action Required (NA) Enhanced Bio Degradation (IT) Vacuum Extract (VE) Remove Free Product (FP) Excavate & Dispose (ED) Pump & Treat Groundwater (GT)					
COMMENTS	Holes found in the tank					