UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK)/ CONTAMINATION SITE REPORT						
EMERGENCY HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED?			ES	FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE		
□ Yes ☑ No □ Yes □ No				THE HEALTH A RECEIVED		
	26/16 CAS	= #	By Alameda Coun		alth 8:45 am, Feb 28, 2017	
	NAME OF INDIVIDUAL FILING REPORT		PHONE	SIGNED		DATE
REPORTED BY	Gina Wee (415)			) 512-1555		
	REPRESENTING  LOCAL AGENCY REGIONAL BOARD  OWNER/OPERATOR OTHER  contractor			COMPANY OR AGENCY NAME Golden Gate Tank Removal, Inc.		
	ADDRESS 1480 Carroll Avenue			San Francisco CA		94124 STATE ZIP
RESPONSIBLE PARTY	<sup>NAME</sup> 378 Grand Avenue, LLC □ <sup>Unknown</sup>					PHONE 510-540-5982
	ADDRESS 2295 San Pablo Avenue	ET		Berkeley	CA	94702 State zip
Z	FACILITY NAME (IF APPLICABLE)			OPERATOR		PHONE
SITE LOCATION	ADDRESS 378 Grand Avenue Oakland Alameda 94610 STREET CITY COUNTY ZIP					
	CROSS STREET Staten Avenue					
IMPLEMENTING AGENCIES	LOCAL AGENCY AGENCY NAME PHONE					
	Alameda County Environmental Health -Barbara Jakub 510-567-6737					
	REGIONAL BOARD PHONE					
SUBSTANCES INVOLVED	Image: Diesel     NAME     QUANTITY LOST (GALLONS)					
SUBST	(2)					
TEMENT	DATE DISCOVERED 1/26/16	HOW DISCOVERED Tank Test Tank Removal Nuisance Conditions				
DISCOVERY/ABATEN	DATE DISCHARGE BEGAN METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)					
OVER		Remove Contents     Close Tank & Removed     Repair Tank     Change Procedure				
DISC	As DISCHARGE BEEN STOPPED? As Ves No 01/26/16 IF YES, DATE BEEN STOPPED? Characterization of the content of t					
RCE/	SOURCE OF DISCHARGE	`	CAUSE(S)			
SOURCE/ CAUSE	Tank Leak Diping Leak 🖸 Unknown Dother					
CASE TYPE	CHECK ONE ONLY					
CURRENT STATUS	CHECK ONE ONLY       Case Closed (Cleanup Completed or Unnecessary)         No Action Taken       Case Closed (Cleanup Completed or Unnecessary)         Leak Being Confirmed       Pollution Characterization         Remediation Plan       Post Cleanup Monitoring in Progress         Preliminary Site Assessment Workplan Submitted       Cleanup Underway					
REMEDIAL ACTION	CHECK APPROPRIATE ACTION(S)         Cap Site (CD)       Excavate & Treat (ET)         Contamination Barrier (CB)       No Action Required (NA)         Contamination Barrier (CB)       No Action Required (NA)         Enhanced Bio Degradation (IT)       Dispose         Excavate & Dispose (ED)       Pump & Treat Groundwater (GT)					
COMMENTS	Holes found in the tank					