UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK)/ CONTAMINATION SITE REPORT						
EMERGENCY HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED? Yes ☑ No Yes ☑ No				FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PERSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.		
REPORT DATE CASE #				THE HEALTH WAR ON ETT GODE.		
11/06/15				SIGNED		DATE
REPORTED BY	NAME OF INDIVIDUAL FILING REPORT PHON		PHONE	SIGNED	SIGNATURE ()	DATE
	Gina Wee (415) 512-1555			
	REPRESENTING		1,	COMPANY OR AGENCY NAME		
	☐ LOCAL AGENCY ☐ REGIONAL BOARD ☐ OWNER/OPERATOR XOTHER Contractor			Golden Gate Tank Removal, Inc.		
	1480 Carroll Avenue	STREET		San Francisco	CA	94124 STATE ZIP
RESPONSIBLE PARTY	Kuen C. Lau & Sar P Kwan					510-834-4747 c/o Iris
	3701 Lakeshore Avenue	STREET		Oakland	CA	94610
SITE LOCATION	FACILITY NAME (IF APPLICABLE)			OPERATOR		PHONE
	ADDRESS 3820 Penniman Avenue Oakland Oakland Alameda Oounty ZIP					
	38th Avenue					
IMPLEMENTING AGENCIES	LOCAL AGENCY AGENCY NAME					PHONE
	Alameda County Environmental Health -Steven Plunkett					510-383-1767
	REGIONAL BOARD PHONE					PHONE
SUBSTANCES	Gasoline				_	QUANTITY LOST (GALLONS)
	(2)				_	☐ Unknown
TEMENT	DATE DISCOVERED 11/06/15 HOW DISCOVERED Tank Test Inventory Control Subsurface Monitoring Other					
//AB/	DATE DISCHARGE BEGAN			METHOD USED TO STOP DISCHAR	RGE (CHECK ALL THAT APPLY	Y)
DISCOVERY/ABATE	∑ Unknown			Remove Contents Close Tank & Removed		
	HAS DISCHARGE BEEN STOPPED? ☐ Yes ☐ No 11/06/15 IF YES, DA	.TE		☐ Repair Tank ☐ Change Procedure ☐ Replace Tank ☐ Other ☐ Repair Piping		
SE/SE/						
SOURCE/ CAUSE	☐ Tank Leak ☐ Piping Leak ☑ Unknown ☐ Other ☐ Overfill ☐ Corrosion ☐ Rupture/Failure ☐ Unknown ☐ Spill ☐ Other					
CASE TYPE	CHECK ONE ONLY ☐ Undetermined ☐ Soil Only ☐ Groundwater ☐ Drinking Water - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)					
CURRENT STATUS	CHECK ONE ONLY No Action Taken Case Closed (Cleanup Completed or Unnecessary) Case Being Confirmed Pollution Characterization Post Cleanup Monitoring in Progress Preliminary Site Assessment Workplan Submitted Preliminary Site Assessment Underway					
REMEDIAL ACTION	CHECK APPROPRIATE ACTION(S) Cap Site (CD)					
COMMENTS						