


1110 Jackson St., Oakland
B Jakub, April 15, 2016

04/15/2016 14



1110 Jackson St., Oakland
B Jakub, April 15, 2016
Excavation for tanks 1 and 2

04/15/2016 14




1110 Jackson St., Oakland
B Jakub, April 15, 2016
Prep for tank removal

04/15/2016 14



04/15/2016 15

1110 Jackson St., Oakland
B Jakub, April 15, 2016
Tank 3 with utility line above



1110 Jackson St., Oakland
B Jakub, April 15, 2016
Pulling Tank 1








1110 Jackson St., Oakland
B Jakub, April 15, 2016
Tank one being placed on plastic



1110 Jackson St., Oakland
B Jakub, April 15, 2016
Tank 2 being removed

04/15/2016 15





04/15/2016 15



1110 Jackson St., Oakland
B Jakub, April 15, 2016
Tank 2 where tank was hit while boring for utilities.

04/15/2016 15






1110 Jackson St., Oakland
B Jakub, April 15, 2016
Tank 2 hole near top of tank

04/15/2016 15




1110 Jackson St., Oakland
B Jakub, April 15, 2016
Tank 3 being removed

04/15/2016 15



1110 Jackson St., Oakland
B Jakub, April 15, 2016
Holes in Tank 3

04/15/2016 15




1110 Jackson St., Oakland
B Jakub, April 15, 2016
More holes in tank 3

04/15/2016 15



1110 Jackson St., Oakland
B Jakub, April 15, 2016
Tank 3 with multiple holes observed

04/15/2016 15



1110 Jackson St., Oakland
B Jakub, April 15, 2016
Loading tanks onto flatbed



1110 Jackson St., Oakland
B Jakub, April 15, 2016
Utility line in tank pit after tank removal





1110 Jackson St., Oakland
B Jakub, April 15, 2016
Possible secondary piping from tanks



1110 Jackson St., Oakland
B Jakub, April 15, 2016
Excavating below tanks

04/15/2016 16




04/15/2016 16





1110 Jackson St., Oakland
B Jakub, April 15, 2016
Collecting soil sample with slide hammer



1110 Jackson St., Oakland
B Jakub, April 15, 2016
Hand augering soil sample