

THRIFTY OIL CO.

Ro 4

0.456301

April 14, 2004

Mr. Barney Chan
Alameda County Health Care Services
Department of Environmental Health
1131 Harbor Bay Parkway, 2nd Floor
Alameda, CA 94502

Local #4057
RWQCB #01-1478
Alameda County Global ID #T0600101365

APR 26 2004

RE: **Former Thrifty Oil Co. Station #049 Environmental Health**
3400 San Pablo Avenue
Oakland, CA 94612
1st Quarter 2004, Status Report

Dear Mr. Chan:

Presented herein is the 1st Quarter 2004, Status Report prepared for former Thrifty Oil Co. (Thrifty) Station #049 located at 3400 San Pablo Avenue, Oakland, California (**Figure 1**). This report presents the results of the site monitoring and remedial activities conducted during the first quarter of 2004. Thrifty has retained the services of Earth Management Company (EMC) to conduct quarterly monitoring and sampling, and remediation system monitoring activities at this site.

Groundwater Monitoring

Depth to groundwater is measured in each monitoring well on a quarterly basis. In general, groundwater occurs beneath the station at depths ranging from 3.03 feet below top of casing (btc) in monitoring well MW-5 to 4.38 feet btc in monitoring well MW-3 (**Appendix A**). A groundwater elevation contour map based on the January 14, 2004, monitoring data is presented in **Figure 2**. Groundwater elevation data indicates that groundwater flow to the southwest under at an approximate gradient of 0.0372 feet/foot.

Quarterly Groundwater Sampling

As part of the ongoing groundwater-monitoring program, EMC obtained groundwater samples from monitoring wells MW-1, MW-3, MW-5, MW-6 and MW-7 on January 14, 2004. Groundwater wells MW-2 and MW-4 and recovery well RW-1 were abandoned by Advanced GeoEnvironmental in January 2004, as part of an upgrade to the groundwater recovery system. Groundwater samples were delivered by EMC in a chilled state following strict Chain-of-Custody procedures to a state-certified laboratory and analyzed for total petroleum hydrocarbons as gasoline (TPHg) by EPA Method 8015M. Volatile organic compounds of benzene, toluene, ethylbenzene, xylenes (BTEX), methyl tert butyl ether (MTBE), and other oxygenates were analyzed by EPA Method 8260B. A summary of historical analytical sampling results for TPHg, BTEX, and MTBE is provided in **Table 1** and other oxygenates data is provided on **Table 2**. Copies of the EMC Field Data Groundwater Sampling Forms are provided in **Appendix A**, and copies of the laboratory analytical reports are contained in **Appendix B**.

TPHg, benzene, and MTBE isoconcentration maps in micrograms per liter (ug/L) were prepared using data from the January 14, 2004, sampling event and are presented in **Figures 3, 4, and 5**, respectively. Laboratory results indicate the highest concentrations of TPHg, benzene, and MTBE were detected in well MW-3 (1,160 ug/L, 2 ug/L, and 767 ug/L, respectively).



13116 Imperial Highway, Santa Fe Springs, CA 90670 • (562) 921-3581

Mr. Barney Chan
Thrifty #049
1st Quarter 2004
Page 2

Although TPHg, benzene, and MTBE concentrations all decreased in well MW_3 from the sample collected on October 20, 2003, the concentrations are still elevated above data from previous sampling events as shown on **Table 1**. The groundwater flow direction and TPHg, benzene, and MTBE contour maps suggest that an upgradient source is likely. Since a Shell Oil station is located adjacent and upgradient, dissolved hydrocarbons may be migrating onsite and commingling with a Thrifty plume.

Remediation Status

Site remedial activities were initiated in April 1991. The remediation system consists of a Groundwater Treatment System using activated carbon, with groundwater extraction from recovery well RW-1. System operational data is included in **Table 3**. On February 14, 2003, the groundwater system was shut down initially for carbon replacement, and on April 4, 2003, the system was left off for system upgrade activities. As of April 4, 2003, the system has treated approximately 1,445,088 gallons of groundwater since start up (April 1991).

Other Activities

Thrifty selected Advanced GeoEnvironmental (AGE) to conduct remedial system upgrade activities including installation of a new treatment compound, installation of new piping, connection of piping to the replacement well network, and the operation and maintenance of the upgraded groundwater pump and treat system. In January 2004, AGE abandoned wells MW-2, MW-4, and RW-1 and replaced them with wells MW-2R, MW-4R, and RW-1R. AGE also completed four (4) offsite soil borings (B-1 through B-4). In a transmittal letter dated March 11, 2004, Thrifty submitted preliminary soil and groundwater data from the offsite soil borings and onsite well replacement activities. On March 18, 2004, Thrifty, AGE, and the Alameda Health Care Agency (ACHCA) met at the site to discuss the location of offsite well MW-8 and the soil and groundwater data provided by Thrifty. In a letter dated March 19, 2004, the ACHCA requested that Thrifty prepare a workplan to address the offsite contamination detected in the data from the January 2004 site assessment conducted by AGE. Thrifty is in the process of preparing the workplan to complete temporary borings so that additional groundwater monitoring wells may be more accurately located to intercept the offsite dissolved hydrocarbon plume.

The existing treatment compound has been removed from the site; the installation of the replacement compound and trenching activities were conducted in January 2004. AGE anticipates system start-up in mid to late April 2004. Thrifty will notify the ACHCA of any significant changes to the above tentative schedule and will continue to keep the ACHCA updated of future system upgrade activities.

The groundwater monitoring wells will be monitored and sampled during the next quarter. All site monitoring/sampling data generated during the next quarter will be reported in the Second Quarter 2004 monitoring report.


Mr. Barney Chan
Thrifty #049
1st Quarter 2004
Page 3

All interpretations expressed in this report are based solely upon data collected by EMC and laboratory analyses conducted by Associated Laboratories.

Sincerely,



Michael H. Bowery, R. G.
Project Manager



Chris Panaitescu
General Manager
Environmental Affairs

cc: BP West Coast Products LLP; Ms. Kateri Luka
File

TABLES

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #049, OAKLAND, CA.

DATE SAMPLED	ANALYTICAL PARAMETERS					DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)					
MONITORING WELL #MW-1										
01/09/92	-	-	-	-	-	-	5.54	NP	0.00	98.03
04/13/92	-	-	-	-	-	-	5.86	NP	0.00	98.03
10/05/92	-	-	-	-	-	-	9.39	NP	0.00	98.03
01/06/93	-	-	-	-	-	-	4.76	NP	0.00	98.03
04/26/93	-	-	-	-	-	-	4.96	NP	0.00	98.03
01/04/94	-	-	-	-	-	-	7.00	NP	0.00	98.03
04/05/94	-	-	-	-	-	-	6.44	NP	0.00	98.03
10/09/95	44,000	4,500	4,300	1,700	10,000	-	-	-	-	98.03
01/08/96	21,000	1,200	150	34	4,800	-	6.15	NP	0.00	98.03
04/08/96	4,700	80	110	10	910	-	5.40	NP	0.00	98.03
07/22/96	7,000	280	130	<3	2,100	440	5.50	NP	0.00	98.03
10/16/96	120	<0.3	<0.3	<0.3	<0.5	180	6.02	NP	0.00	98.03
01/22/97	160	<0.3	<0.3	<0.3	<0.5	360	4.40	NP	0.00	98.03
04/21/97	20,000	420	140	5.8	840	55,000	6.30	NP	0.00	98.03
07/14/97	13,000	<0.3	<0.3	<0.3	<0.55	30,000	5.92	NP	0.00	98.03
10/07/97	-	-	-	-	-	-	7.71	7.70	0.01	98.03
01/15/98	<50	0.3	<0.3	<0.3	<0.5	-	4.40	NP	0.00	98.03
04/23/98	540	<0.3	<0.3	<0.3	<0.5	<20	8.10	NP	0.00	98.03
07/20/98	<50	<0.3	<0.3	<0.3	<0.5	<5	5.55	NP	0.00	98.03
10/14/98	50	1.4	0.56	<0.3	11	22	7.05	NP	0.00	98.03
01/21/99	<50	0.59	<0.3	<0.3	<0.5	<5	4.10	NP	0.00	98.03
04/15/99	<50	<0.3	<0.3	<0.3	<0.5	<5	4.30	NP	0.00	98.03
07/26/99	<50	<0.3	<0.3	<0.3	<0.5	<5	5.54	NP	0.00	98.03
10/13/99	<50	<0.3	<0.3	<0.3	<0.5	<5	6.13	NP	0.00	98.03
01/20/00	<50	<0.3	<0.3	<0.3	<0.5	<5	6.04	NP	0.00	98.03
04/05/00	<50	<0.25	<0.25	<0.25	<0.5	<5	4.03	NP	0.00	98.03
07/19/00	<50	<0.3	<0.3	<0.3	<0.6	<5	4.00	NP	0.00	98.03
10/18/00	<50	<0.18	<0.14	<0.18	<0.26	<0.24	5.53	NP	0.00	98.03
01/17/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	3.97	NP	0.00	98.03
04/19/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	3.98	NP	0.00	98.03
07/18/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	5.51	NP	0.00	98.03
10/10/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	3.97	NP	0.00	98.03
01/30/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	3.95	NP	0.00	98.03
04/17/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	2.42	NP	0.00	98.03
07/31/02	<50	<0.18	1.3	<0.18	<0.26	<0.24	5.49	NP	0.00	92.54

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #049, OAKLAND, CA.

DATE SAMPLED	ANALYTICAL PARAMETERS					DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH ($\mu\text{g/L}$)	BENZENE ($\mu\text{g/L}$)	TOLUENE ($\mu\text{g/L}$)	EthylBenzene ($\mu\text{g/L}$)	XYLENE ($\mu\text{g/L}$)					
11/14/02	<50	<0.08	<0.18	<0.17	<0.4	16	6.13	NP	0.00	98.03
01/29/03	<15	<0.04	<0.02	<0.02	<0.06	<0.03	2.45	NP	0.00	98.03
04/23/03	<15	<0.04	<0.02	<0.02	<0.06	<0.03	7.02	NP	0.00	98.03
07/10/03	<15	<0.22	<0.32	<0.31	<0.4	<0.18	5.15	NP	0.00	98.03
10/20/03	<15	<0.04	<0.02	<0.02	<0.06	<0.03	5.13	NP	0.00	98.03
01/14/04	<15	<0.04	<0.02	<0.02	<0.06	<0.03	3.92	NP	0.00	98.03
										94.11
MONITORING WELL #MW-2										
<i>Screen Interval = 5 to 15 feet</i>										
01/09/92	-	-	-	-	-	-	5.35	NP	0.00	97.44
04/13/92	-	-	-	-	-	-	7.42	NP	0.00	97.44
10/05/92	-	-	-	-	-	-	12.15	NP	0.00	97.44
01/06/93	-	-	-	-	-	-	5.46	NP	0.00	97.44
04/26/93	-	-	-	-	-	-	5.15	NP	0.00	97.44
01/04/94	-	-	-	-	-	-	9.45	NP	0.00	97.44
04/05/94	-	-	-	-	-	-	8.23	NP	0.00	97.44
10/09/95	33,000	6,000	390	1,700	4,900	-	-	-	-	97.44
01/08/96	<50	0.32	<0.3	0.41	2.1	-	5.60	NP	0.00	97.44
04/08/96	10,000	490	210	210	830	-	5.43	NP	0.00	97.44
07/22/96	60,000	6,500	1,000	1,500	10,000	8,500	5.65	NP	0.00	97.44
10/16/96	6,500	12	0.34	0.72	110	4,700	5.82	NP	0.00	97.44
01/22/97	3,200	<0.3	0.46	0.37	<0.5	8,000	4.30	NP	0.00	97.44
04/21/97	66,000	5,300	1,000	2,300	14,000	30,000	5.80	NP	0.00	97.44
07/14/97	17,000	1.8	4.6	4.6	350	24,000	8.92	NP	0.00	97.44
10/07/97	220,000	5,200	1,700	3,800	15,000	-	6.80	NP	0.00	97.44
01/19/98	25,000	5.4	2.2	2.1	240	-	8.50	NP	0.00	97.44
04/23/98	7,700	<0.3	0.55	0.38	4.9	28,000	7.60	NP	0.00	97.44
07/20/98	430,000	4,200	10,000	5,400	28,000	77,000	6.94	NP	0.00	97.44
10/14/98	27,000	<0.3	4.5	4.1	4.6	65,000	8.45	NP	0.00	97.44
01/21/99	16,000	7.6	9.8	4.2	310	* 49,000 / 42,000	6.95	NP	0.00	97.44
04/15/99	20,000	<0.3	<0.3	<0.3	<0.5	* 31,000 / 30,000	8.45	NP	0.00	97.44
07/26/99	6,700	<6	<6	<6	<10	*11,000 / 15,000	6.94	NP	0.00	97.44
10/13/99	7,600	<3	3.7	<3	11	11,000	5.48	NP	0.00	97.44
01/20/00	7,500	<6	<6	<6	<10	*14,000 / 16,000	5.84	NP	0.00	97.44
04/05/00	10,400	<0.25	<0.25	<0.25	<0.5	*10,000 / 14,400	5.41	NP	0.00	97.44
07/19/00	130	<0.3	<0.3	<0.3	<0.6	*9,620 / 6,520	5.40	NP	0.00	97.44
										92.04

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #049, OAKLAND, CA.

DATE SAMPLED	ANALYTICAL PARAMETERS						DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)	MTBE (ug/L)					
10/18/00	150	<0.18	<0.14	<0.18	<0.26	*9,090 / 6,560	6.91	NP	0.00	97.44	90.53
01/17/01	75	<0.18	2.0	2.0	3.0	*8,650 / 9,710	5.41	NP	0.00	97.44	92.03
04/19/01	4,380	<0.18	<0.14	<0.18	<0.26	8,890	5.40	NP	0.00	97.44	92.04
07/18/01	3,260	<0.18	<0.14	<0.18	2.0	*7960 / 1,710	6.92	NP	0.00	97.44	90.52
10/10/01	1,760	<0.18	<0.14	<0.18	<0.26	*2,980 / 2,600	3.87	NP	0.00	97.44	93.57
01/30/02	1,770	<0.18	1.0	1.0	2.0	*2,560 / 1,590	8.45	NP	0.00	97.44	88.99
04/17/02	1,470	1.0	<0.14	<0.18	<0.26	*2,460 / 2,080	8.45	NP	0.00	97.44	88.99
07/31/02	3,910	<0.18	1.2	<0.18	2.1	*2,090 / 1,740	9.98	NP	0.00	97.44	87.46
11/14/02	39,400	1,680	728	173	5,120	8,270	5.40	NP	0.00	97.44	92.04
01/29/03	22,100	746	76	<1.0	2,840	8,220	8.43	NP	0.00	97.44	89.01
04/23/03	19,500	<0.8	<0.4	<0.4	<1.2	9,580	5.38	NP	0.00	97.44	92.06
07/10/03	29,900	<2.2	<3.2	<3.1	<4.0	6,690	5.10	NP	0.00	97.44	92.34
10/20/03	13,000	4.79	<0.02	<0.02	<0.06	*6,330 / 5,980	5.10	NP	0.00	97.44	92.34
01/14/04	WELL ABANDONED 01/2004										

MONITORING WELL #MW-3		Screen Interval = 5 to 25 feet									
01/09/92	-	-	-	-	-	-	17.60	NP	0.00	97.69	80.09
04/13/92	-	-	-	-	-	-	17.40	NP	0.00	97.69	80.29
10/05/92	-	-	-	-	-	-	17.35	NP	0.00	97.69	80.34
01/06/93	-	-	-	-	-	-	17.40	NP	0.00	97.69	80.29
04/26/93	-	-	-	-	-	-	17.90	NP	0.00	97.69	79.79
01/04/94	-	-	-	-	-	-	17.60	NP	0.00	97.69	80.09
04/05/94	-	-	-	-	-	-	16.25	NP	0.00	97.69	81.44
01/08/96	-	-	-	-	-	-	7.11	NP	0.00	97.69	90.58
04/08/96	8,800	610	31	530	900	-	7.20	NP	0.00	97.69	90.49
07/22/96	38,000	4,100	1,500	1,600	5,400	2,600	6.82	NP	0.00	97.69	90.87
10/16/96	2,400	<0.3	<0.3	<0.3	<0.5	3,800	6.84	NP	0.00	97.69	90.85
01/22/97	2,200	<0.3	<0.3	<0.3	<0.5	5,500	4.80	NP	0.00	97.69	92.89
04/21/97	15,000	1,500	36	260	710	11,000	9.40	NP	0.00	97.69	88.29
07/14/97	5,400	0.45	<0.3	<0.3	<0.5	14,000	10.92	NP	0.00	97.69	86.77
10/07/97	8,800	0.39	<0.3	<0.3	0.88	-	11.95	NP	0.00	97.69	85.74
01/19/98	22,000	1,300	15	20	310	-	7.85	NP	0.00	97.69	89.84
04/23/98	9,200	3.9	3.1	5.7	9.8	16,000	11.20	NP	0.00	97.69	86.49
07/20/98	750	0.41	1.4	0.47	1.8	2,800	7.36	NP	0.00	97.69	90.33
10/14/98	750	<0.3	<0.3	<0.3	<0.5	15,000	11.95	NP	0.00	97.69	85.74
01/21/99	4,700	0.32	<0.3	<0.3	<0.5	* 12,000 / 16,000	10.45	NP	0.00	97.69	87.24

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #049, OAKLAND, CA.

DATE SAMPLED	ANALYTICAL PARAMETERS						DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)	MTBE (ug/L)					
04/15/99	7,900	0.59	0.69	<0.3	0.94	* 11,000 / 14,000	7.86	NP	0.00	97.69	89.83
07/26/99	5,200	<3	<3	<3	<5	*9,600 / 11,000	10.40	NP	0.00	97.69	87.29
10/13/99	<50	<0.3	<0.3	<0.3	<0.5	<5	7.09	NP	0.00	97.69	90.60
01/20/00	<50	<0.3	<0.3	<0.3	<0.5	<5	6.86	NP	0.00	97.69	90.83
04/05/00	<50	0.8	<0.25	<0.25	<0.5	*5.6 / <5	8.85	NP	0.00	97.69	88.84
07/19/00	<50	<0.3	<0.3	<0.3	<0.6	<5	8.86	NP	0.00	97.69	88.83
10/18/00	<50	<0.18	<0.14	<0.18	<0.26	<0.24	7.32	NP	0.00	97.69	90.37
01/17/01	<50	<0.18	2.0	<0.18	1.0	*39 / 39	5.40	NP	0.00	97.69	92.29
04/19/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	8.87	NP	0.00	97.69	88.82
07/18/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	7.32	NP	0.00	97.69	90.37
10/10/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	8.87	NP	0.00	97.69	88.82
01/30/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	5.78	NP	0.00	97.69	91.91
04/17/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	7.31	NP	0.00	97.69	90.38
07/31/02	138	1.1	1.2	<0.18	<0.26	<0.24	5.76	NP	0.00	97.69	91.93
11/14/02	<50	<0.08	<0.18	<0.17	<0.4	21	5.73	NP	0.00	97.69	91.96
01/29/03	<15	<0.04	<0.02	<0.02	<0.06	16	7.30	NP	0.00	97.69	90.39
04/23/03	<15	<0.04	<0.02	<0.02	<0.06	16	5.76	NP	0.00	97.69	91.93
07/10/03	<15	<0.22	<0.32	<0.31	<0.4	11	5.63	NP	0.00	97.69	92.06
10/20/03	13,700	4.13	<0.02	<0.02	<0.06	*6,570 / 4,920	5.61	NP	0.00	97.69	92.08
01/14/04	1,160	2.0	2.2	6.1	7.8	*1,510 / 767	4.23	NP	0.00	97.69	93.46

MONITORING WELL #MW-4											
Screen Interval = 4 to 14 feet											
01/09/92	-	-	-	-	-	-	5.25	NP	0.00	97.33	92.08
04/13/92	-	-	-	-	-	-	6.40	NP	0.00	97.33	90.93
10/05/92	-	-	-	-	-	-	9.95	NP	0.00	97.33	87.38
01/06/93	-	-	-	-	-	-	4.10	NP	0.00	97.33	93.23
04/26/93	-	-	-	-	-	-	4.84	NP	0.00	97.33	92.49
01/04/94	-	-	-	-	-	-	9.05	NP	0.00	97.33	88.28
04/05/94	-	-	-	-	-	-	8.10	NP	0.00	97.33	89.23
10/09/95	63,000	9,000	2,100	2,500	9,600	-	-	-	-	97.33	-
01/08/96	23,000	2,200	830	880	3,600	-	5.57	NP	0.00	97.33	91.76
04/08/96	56,000	5,000	2,500	2,600	11,000	-	5.36	NP	0.00	97.33	91.97
07/22/96	33,000	3,700	1,600	1,400	6,000	2,400	4.80	NP	0.00	97.33	92.53
10/16/96	2,800	7.8	0.60	0.41	52	2,000	5.47	NP	0.00	97.33	91.86
01/22/97	1,400	<0.3	<0.3	<0.3	<0.5	3,100	5.15	NP	0.00	97.33	92.18

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #049, OAKLAND, CA.

DATE SAMPLED	ANALYTICAL PARAMETERS						DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)	MTBE (ug/L)					
04/21/97	-	-	-	-	-	-	6.36	5.30	1.06	97.33	91.77
07/14/97	-	-	-	-	-	-	5.24	5.21	0.03	97.33	92.11
10/07/97	-	-	-	-	-	-	7.82	7.80	0.02	97.33	89.53
01/15/98	-	-	-	-	-	-	6.68	6.60	0.08	97.33	90.71
04/23/98	-	-	-	-	-	-	6.36	5.30	1.06	97.33	91.77
07/20/98	<50	<0.3	<0.3	<0.3	<0.5	<5	6.05	NP	0.00	97.33	91.28
10/14/98	3,100	86	23	2.0	520	1,100	6.85	NP	0.00	97.33	90.48
01/21/99	9,100	3.2	5.6	1.8	130	* 24,000 / 17,000	6.10	NP	0.00	97.33	91.23
04/15/99	14,000	<0.3	0.71	<0.3	<0.5	* 20,000 / 22,000	6.05	NP	0.00	97.33	91.28
07/26/99	4,500	<6	<6	<6	<10	* 8,700 / 9,800	6.07	NP	0.00	97.33	91.26
10/13/99	410	<0.3	0.63	<0.3	<0.5	660	5.54	NP	0.00	97.33	91.79
01/20/00	770	<0.3	<0.3	<0.3	<0.5	* 2,400 / 1,900	5.49	NP	0.00	97.33	91.84
04/05/00	61,200	0.9	<0.25	<0.25	<0.5	* 18,500 / 21,900	5.30	NP	0.00	97.33	92.03
07/19/00	96,600	1,770	1,760	2,690	8,730	21,900 / 9,740 J	5.29	NP	0.00	97.33	92.04
10/18/00	34,900	698	1,010	607	4,130	* 27,800 / 15,900	6.02	NP	0.00	97.33	91.31
01/17/01	29,100	799	930	614	3,400	* 24,300 / 31,400	4.88	NP	0.00	97.33	92.45
04/19/01	103,000	4,880	3,980	3,260	11,800	66,900	4.89	NP	0.00	97.33	92.44
07/18/01	52,200	3,320	2,090	440	5,520	* 55,500 / 16,800	6.04	NP	0.00	97.33	91.29
10/10/01	8,580	6.1	14	5.3	70	* 40,100 / 30,000	4.51	NP	0.00	97.33	92.82
01/30/02	36,500	<0.18	3.0	1.0	3.0	* 43,000 / 24,900	4.51	NP	0.00	97.33	92.82
04/17/02	12,900	8.0	1.0	<0.18	1.0	16,000 / 13,600	4.51	NP	0.00	97.33	92.82
07/31/02	19,300	<0.18	1.2	1.5	2.6	* 13,200 / 10,100	5.26	NP	0.00	97.33	92.07
11/14/02	36,200	1,720	940	235	6,190	8,280	5.27	NP	0.00	97.33	92.06
01/29/03	13,000	444	39	<0.4	1,200	8,160	4.50	NP	0.00	97.33	92.83
04/23/03	7,430	130	5.7	<0.2	387	5,830	4.80	NP	0.00	97.33	92.53
07/10/03	16,200	<2.2	<3.2	<3.1	<4.0	3,930	4.55	NP	0.00	97.33	92.78
10/20/03	6,040	672	384	3.4	444	* 3,780 / 3,220	4.56	NP	0.00	97.33	92.77
01/14/04	WELL ABANDONED 01/2004										

MONITORING WELL #MWS	Screen Interval = 4 to 14 feet										
01/09/92	-	-	-	-	-	-	5.32	NP	0.00	98.85	93.53
04/13/92	-	-	-	-	-	-	4.82	NP	0.00	98.85	94.03
10/07/92	-	-	-	-	-	-	8.78	NP	0.00	98.85	90.07
01/06/93	-	-	-	-	-	-	3.46	NP	0.00	98.85	95.39
04/26/93	-	-	-	-	-	-	4.66	NP	0.00	98.85	94.19
01/04/94	-	-	-	-	-	-	6.36	NP	0.00	98.85	92.49

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #049, OAKLAND, CA.

DATE SAMPLED	ANALYTICAL PARAMETERS					DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)					
04/05/94	-	-	-	-	-	5.94	NP	0.00	98.85	92.91
07/12/95	< 100	< 0.5	< 0.5	< 0.5	< 1	-	-	-	98.85	-
10/09/95	440	31	11	19	84	-	-	-	98.85	-
01/08/96	< 50	< 0.3	< 0.3	< 0.3	< 0.5	-	6.63	NP	0.00	98.85
04/08/96	< 50	< 0.3	< 0.3	< 0.3	< 0.5	-	5.22	NP	0.00	98.85
07/22/96	< 50	< 0.3	< 0.3	< 0.3	< 0.5	< 20	6.62	NP	0.00	98.85
10/16/96	< 50	< 0.3	< 0.3	< 0.3	< 0.5	< 20	6.12	NP	0.00	98.85
01/22/97	< 50	< 0.3	< 0.3	< 0.3	< 0.5	< 20	5.17	NP	0.00	98.85
04/21/97	73	2.5	0.34	0.74	3.8	21	6.64	NP	0.00	98.85
07/14/97	< 50	< 0.3	< 0.3	< 0.3	< 0.5	< 20	6.67	NP	0.00	98.85
10/07/97	130	< 0.3	< 0.3	< 0.3	< 0.5	-	8.20	NP	0.00	98.85
01/19/98	85	< 0.3	< 0.3	< 0.3	< 0.5	-	1.55	NP	0.00	98.85
04/23/98	220	0.39	< 0.3	< 0.3	< 0.5	350	8.10	NP	0.00	98.85
07/20/98	< 50	< 0.3	< 0.3	< 0.3	< 0.5	< 5	6.30	NP	0.00	98.85
10/14/98	< 50	< 0.3	< 0.3	< 0.3	< 0.5	< 5	7.65	NP	0.00	98.85
01/21/99	< 50	< 0.3	< 0.3	< 0.3	< 0.5	*6.7 / < 5	6.15	NP	0.00	98.85
04/15/99	< 50	< 0.3	< 0.3	< 0.3	< 0.5	< 5	1.60	NP	0.00	98.85
07/26/99	< 50	< 0.3	< 0.3	< 0.3	< 0.5	< 5	6.13	NP	0.00	98.85
10/13/99	< 50	< 0.3	< 0.3	< 0.3	< 0.5	< 5	6.61	NP	0.00	98.85
01/20/00	< 50	< 0.3	< 0.3	< 0.3	< 0.5	< 5	6.14	NP	0.00	98.85
04/05/00	< 50	0.5	< 0.25	< 0.25	< 0.5	*5.4 / < 5	4.58	NP	0.00	98.85
07/19/00	< 50	< 0.3	< 0.3	< 0.3	< 0.6	< 5	4.59	NP	0.00	98.85
10/18/00	< 50	< 0.18	< 0.14	< 0.18	< 0.26	< 0.24	6.28	NP	0.00	98.85
01/17/01	< 50	< 0.18	< 0.14	< 0.18	1.0	*5 / 4.8	4.58	NP	0.00	98.85
04/19/01	< 50	< 0.18	< 0.14	< 0.18	< 0.26	< 0.24	4.58	NP	0.00	98.85
07/18/01	< 50	< 0.18	< 0.14	< 0.18	< 0.26	< 0.24	6.12	NP	0.00	98.85
10/10/01	< 50	< 0.18	< 0.14	< 0.18	< 0.26	< 0.24	4.58	NP	0.00	98.85
01/30/02	< 50	< 0.18	< 0.14	< 0.18	< 0.26	< 0.24	4.48	NP	0.00	98.85
04/17/02	< 50	< 0.18	< 0.14	< 0.18	< 0.26	< 0.24	4.58	NP	0.00	98.85
07/31/02	< 50	< 0.18	< 0.14	< 0.18	< 0.26	< 0.24	6.10	NP	0.00	98.85
11/14/02	< 50	< 0.08	< 0.18	< 0.17	< 0.4	9	6.11	NP	0.00	98.85
01/29/03	< 15	< 0.04	< 0.02	< 0.02	< 0.06	7.1	4.55	NP	0.00	98.85
04/23/03	< 15	< 0.04	< 0.02	< 0.02	< 0.06	7.9	3.03	NP	0.00	98.85
07/10/03	< 15	< 0.22	< 0.32	< 0.31	< 0.4	7.4	5.25	NP	0.00	98.85
10/20/03	< 15	< 0.04	< 0.02	< 0.02	< 0.06	*9.11 / 9.2	5.25	NP	0.00	98.85
01/14/04	< 15	< 0.04	< 0.02	< 0.02	< 0.06	*8.2 / 4.1	3.03	NP	0.00	98.85
										95.82

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #049, OAKLAND, CA.

DATE SAMPLED	ANALYTICAL PARAMETERS					DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthyBenzene (ug/L)	XYLENE (ug/L)					
MONITORING WELL #MW-6										
01/09/92	-	-	-	-	-	6.30	NP	0.00	99.67	93.37
04/13/92	-	-	-	-	-	5.47	NP	0.00	99.67	94.20
10/05/92	-	-	-	-	-	9.85	NP	0.00	99.67	89.82
01/06/93	-	-	-	-	-	4.16	NP	0.00	99.67	95.51
04/26/93	-	-	-	-	-	5.75	NP	0.00	99.67	93.92
01/14/94	-	-	-	-	-	7.20	NP	0.00	99.67	92.47
04/05/94	-	-	-	-	-	6.76	NP	0.00	99.67	92.91
07/10/95	<100	<0.5	0.9	<0.5	1.1	-	-	-	99.67	-
10/09/95	250	4.8	5.6	11	58	-	-	-	99.67	-
01/08/96	<50	<0.3	<0.3	<0.3	<0.5	-	6.16	NP	0.00	99.67
04/08/96	230	4.6	4.7	3.2	33	-	4.60	NP	0.00	99.67
07/22/96	<50	<0.3	<0.3	<0.3	<0.5	<20	7.30	NP	0.00	99.67
10/16/96	<50	<0.3	<0.3	<0.3	<0.5	<20	5.82	NP	0.00	99.67
01/22/97	<50	<0.3	<0.3	<0.3	<0.5	<20	4.40	NP	0.00	99.67
04/21/97	130	<0.3	<0.3	<0.3	<0.5	<20	7.10	NP	0.00	99.67
07/14/97	<50	<0.3	<0.3	<0.3	0.70	<20	7.35	NP	0.00	99.67
10/07/97	<50	0.78	0.3	<0.3	<0.5	-	6.98	NP	0.00	99.67
01/23/98	<50	<0.3	<0.3	<0.3	<0.5	-	2.35	NP	0.00	99.67
04/23/98	<50	<0.3	<0.3	<0.3	<0.5	<20	6.90	NP	0.00	99.67
07/20/98	<50	<0.3	1.1	<0.3	1.4	<5	5.45	NP	0.00	99.67
10/14/98	<50	<0.3	<0.3	<0.3	<0.5	<5	4.95	NP	0.00	99.67
01/21/99	<50	0.35	0.62	<0.3	<0.5	<5	3.90	NP	0.00	99.67
04/15/99	<50	<0.3	<0.3	<0.3	<0.5	<5	2.35	NP	0.00	97.32
07/26/99	1,000	<0.3	<0.3	<0.3	<0.5	*2,300 / 3,900	3.93	NP	0.00	95.74
10/13/99	<50	<0.3	<0.3	<0.3	<0.5	<5	6.15	NP	0.00	93.52
01/20/00	<50	<0.3	<0.3	<0.3	<0.5	*42 / 41	5.84	NP	0.00	93.83
04/05/00	4,600	338	2.8	1.2	55.2	*282 / 230	3.89	NP	0.00	95.78
07/19/00	60	1.0	2.0	<0.3	<0.6	*87 / 76	3.07	NP	0.00	99.67
10/18/00	-	-	-	-	-	-	-	-	99.67	-
01/17/01	103	<0.18	2.0	<0.18	3.0	*78 / 106	3.87	NP	0.00	99.67
04/19/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	3.86	NP	0.00	99.67
07/18/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	5.40	NP	0.00	94.27
10/10/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	3.86	NP	0.00	95.81
01/30/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	3.86	NP	0.00	99.67
04/17/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	3.86	NP	0.00	95.81

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #049, OAKLAND, CA.

DATE SAMPLED	ANALYTICAL PARAMETERS					DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)					
07/31/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	5.40	NP	0.00	99.67
11/14/02	140	3.2	<0.18	5.2	<0.4	111	5.42	NP	0.00	99.67
01/29/03	694 J	<0.04	<0.02	<0.02	<0.06	630	3.88	NP	0.00	99.67
04/23/03	1,550	<0.04	<0.02	<0.02	<0.06	578	3.86	NP	0.00	99.67
07/10/03	1,670	<0.22	<0.32	<0.31	<0.4	509	5.31	NP	0.00	99.67
10/20/03	1,320	<0.04	<0.02	<0.02	<0.06	*656 / 662	5.30	NP	0.00	99.67
01/14/04	272	<0.04	<0.02	<0.02	<0.06	*304 / 180	3.82	NP	0.00	99.67
MONITORING WELL #MW-7										
	<i>Screen Interval = 4 to 14 feet</i>									
01/09/92	-	-	-	-	-	6.30	NP	0.00	99.02	92.72
04/13/92	-	-	-	-	-	6.68	NP	0.00	99.02	92.34
10/05/92	-	-	-	-	-	9.60	NP	0.00	99.02	89.42
01/06/93	-	-	-	-	-	13.90	NP	0.00	99.02	85.12
04/26/93	-	-	-	-	-	5.55	NP	0.00	99.02	93.47
01/04/94	-	-	-	-	-	7.58	NP	0.00	99.02	91.44
04/05/94	-	-	-	-	-	6.66	NP	0.00	99.02	92.36
10/09/95	27,000	2,400	140	1,700	2,700	-	-	-	99.02	-
01/08/96	13,000	800	42	540	860	-	6.94	NP	0.00	99.02
04/08/94	9,100	840	31	690	1,200	-	5.48	NP	0.00	99.02
07/22/96	11,000	1,700	22	660	700	840	6.60	NP	0.00	99.02
10/16/96	180	<0.3	<0.3	<0.3	<0.5	270	6.42	NP	0.00	99.02
01/22/97	130	<0.3	<0.3	<0.3	<0.5	470	5.70	NP	0.00	99.02
04/21/97	10,000	1,400	27	820	490	1,100	5.30	NP	0.00	99.02
07/14/97	8,200	660	15	230	270	560	7.90	NP	0.00	91.12
10/07/97	7,700	480	15	8.4	350	-	7.70	NP	0.00	99.02
01/19/98	1,400	20	0.74	0.46	4.4	-	6.05	NP	0.00	99.02
04/23/98	590	<0.3	<0.3	<0.3	<0.5	1,700	7.60	NP	0.00	99.02
07/20/98	4,900	570	150	300	500	1,500	5.30	NP	0.00	91.42
10/14/98	1,100	1.0	<0.3	<0.3	5.3	2,000	8.60	NP	0.00	99.02
01/21/99	570	0.32	<0.3	<0.3	<0.5	* 1,500 / 1,700	6.70	NP	0.00	92.32
04/15/99	770	<0.3	<0.3	<0.3	<0.5	* 1,400 / 1,200	6.07	NP	0.00	92.95
07/26/99	500	<0.3	<0.3	<0.3	<0.5	*710 / 950	7.86	NP	0.00	91.16
10/13/99	<50	<0.3	0.44	<0.3	0.62	<5	6.93	NP	0.00	99.02
01/20/00	<50	<0.3	<0.3	<0.3	<0.5	*5 / <5	6.44	NP	0.00	92.09
04/05/00	5,670	415	19	1.7	60.1	*329 / 194	7.86	NP	0.00	91.16

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #049, OAKLAND, CA.

DATE SAMPLED	ANALYTICAL PARAMETERS					DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)					
07/19/00	1,350	14	<3	<3	10	*237 / 120	7.10	NP	0.00	99.02
10/18/00	<50	<0.18	<0.14	<0.18	<0.26	*63 / 41.1	5.28	NP	0.00	99.02
01/17/01	<50	<0.18	<0.14	<0.18	3.0	*57 / 81	5.27	NP	0.00	99.02
04/19/01	<50	<0.18	<0.14	<0.18	<0.26	66	7.86	NP	0.00	99.02
07/18/01	<50	<0.18	<0.14	<0.18	<0.26	*9 / 3.5	6.30	NP	0.00	99.02
10/10/01	<50	<0.18	<0.14	<0.18	<0.26	*9.4 / 7.9	8.23	NP	0.00	99.02
01/30/02	2,590	40	9.0	8.0	6.0	*45 / 22	5.14	NP	0.00	99.02
04/17/02	51	<0.18	<0.14	<0.18	<0.26	*58 / 45	5.53	NP	0.00	99.02
07/31/02	<50	<0.18	<0.14	<0.18	<0.26	*39 / 33	5.93	NP	0.00	99.02
11/14/02	<50	<0.08	<0.18	<0.17	<0.4	6.8	5.92	NP	0.00	99.02
01/29/03	<15	<0.04	<0.02	<0.02	<0.06	<0.03	5.51	NP	0.00	99.02
04/23/03	<15	<0.04	<0.02	<0.02	<0.06	<0.03	5.14	NP	0.00	99.02
07/10/03	<15	<0.22	<0.32	<0.31	<0.4	<0.18	5.03	NP	0.00	99.02
10/20/03	<15	<0.04	<0.02	<0.02	<0.06	<0.03	5.01	NP	0.00	99.02
01/14/04	<15	<0.04	<0.02	<0.02	<0.06	<0.03	4.38	NP	0.00	99.02
										94.64

MONITORING WELL #RW-1

01/09/92	-	-	-	-	-	-	14.00	NP	0.00	-	-
04/13/92	-	-	-	-	-	-	14.00	NP	0.00	-	-
10/05/92	-	-	-	-	-	-	15.05	NP	0.00	-	-
01/06/93	-	-	-	-	-	-	5.43	NP	0.00	-	-
04/26/93	-	-	-	-	-	-	13.20	NP	0.00	-	-
01/04/94	-	-	-	-	-	-	14.30	NP	0.00	-	-
04/05/94	-	-	-	-	-	-	14.13	NP	0.00	-	-
01/08/96	-	-	-	-	-	-	14.22	NP	0.00	-	-
04/08/96	-	-	-	-	-	-	14.33	NP	0.00	-	-
07/22/96	8,100	530	84	120	860	-	14.27	NP	0.00	-	-
10/16/96	-	-	-	-	-	-	13.10	NP	0.00	-	-
01/22/97	-	-	-	-	-	-	16.97	NP	0.00	-	-
10/07/97	-	-	-	-	-	-	14.20	NP	0.00	-	-
01/15/98	-	-	-	-	-	-	15.60	NP	0.00	-	-
04/23/98	81,000	0.72	1.4	3.2	5.7	270,000	14.20	NP	0.00	-	-
07/20/98	-	-	-	-	-	-	14.30	NP	0.00	-	-
10/14/98	-	-	-	-	-	-	11.20	NP	0.00	-	-
01/21/99	-	-	-	-	-	-	-	-	-	-	-

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #049, OAKLAND, CA.

DATE SAMPLED	ANALYTICAL PARAMETERS						DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)	MTBE (ug/L)					
04/15/99	-	-	-	-	-	-	13.10	NP	0.00	-	-
07/26/99	4,400	<3	<3	<3	<5	*6,800 / 9,000	13.83	NP	0.00	-	-
10/13/99	-	-	-	-	-	-	-	-	-	-	-
01/20/00	-	-	-	-	-	-	13.22	NP	0.00	-	-
04/05/00	-	-	-	-	-	-	-	-	-	-	-
07/19/00	-	-	-	-	-	-	13.25	NP	0.00	-	-
10/18/00	-	-	-	-	-	-	11.14	NP	0.00	-	-
01/17/01	-	-	-	-	-	-	11.12	NP	0.00	-	-
04/19/01	-	-	-	-	-	-	-	-	-	-	-
07/18/01	-	-	-	-	-	-	11.20	NP	0.00	-	-
10/10/01	-	-	-	-	-	-	11.20	NP	0.00	-	-
01/30/02	-	-	-	-	-	-	12.30	NP	0.00	-	-
04/17/02	-	-	-	-	-	-	14.30	NP	0.00	-	-
07/31/02	-	-	-	-	-	-	14.21	NP	0.00	-	-
11/14/02	-	-	-	-	-	-	14.13	NP	0.00	-	-
01/29/03	-	-	-	-	-	-	13.12	NP	0.00	-	-
04/23/03	-	-	-	-	-	-	No Access	-	-	-	-
07/10/03	-	-	-	-	-	-	No Access	-	-	-	-
10/20/03	-	-	-	-	-	-	No Access	-	-	-	-
01/14/04	WELL ABANDONED 01/2004										

NOTE: * MTBE 8020 / 8260

ND = Nondetectable

NP = No free hydrocarbon product

" - " = Not analyzed / Not available

Benzene, toluene, ethlybenzene, and xylene analyzed by EPA method 8020.

Total petroleum hydrocarbons (TPH) analyzed by EPA method 8015 modified for gasoline

Methyl-tert Butyl Ether (MTBE) analyzed by EPA method 8020 or 8260

On 7/10/03 & 11/14/02, BTEX and MTBE done by 8260B

TABLE 2
ADDITIONAL GROUNDWATER DATA
THRIFTY OIL STATION # 049, OAKLAND, CA.

DATE SAMPLED	OXYGENATES					
	Di-isopropyl Ether (DIPEN) ($\mu\text{g/L}$)	Ethyl-Tert-Butyl Ether (ETBE) ($\mu\text{g/L}$)	Tert-Amyl-Methyl Ether (TAME) ($\mu\text{g/L}$)	Tert-Butyl Alcohol (TBA) ($\mu\text{g/L}$)	1,2-Dichloroethane ($\mu\text{g/L}$)	
MONITORING WELL # MW-1						
11/14/02	<0.2	<0.12	<0.16	<10	<0.13	
01/29/03	-	-	-	-	-	
04/23/03	-	-	-	-	-	
07/10/03	<0.29	<0.17	<0.28	<10	-	
10/20/03	-	-	-	-	-	
01/14/04	-	-	-	-	-	
MONITORING WELL # MW-2						
11/14/02	<2.0	<1.2	111	341	<1.3	
01/29/03	-	-	-	-	-	
04/23/03	-	-	-	-	-	
07/10/03	<2.9	<1.7	59	449	-	
10/20/03	-	-	-	-	-	
01/14/04			WELL ABANDONED 01/2004			
MONITORING WELL # MW-3						
11/14/02	<0.2	<0.12	<0.16	<10	<0.13	
01/29/03	-	-	-	-	-	
04/23/03	-	-	-	-	-	
07/10/03	<0.29	<0.17	<0.28	<10	-	
10/20/03	-	-	-	-	-	
01/14/04	-	-	-	-	-	
MONITORING WELL # MW-4						
11/14/02	<2.0	<1.2	106	281	<1.3	
01/29/03	-	-	-	-	-	
04/23/03	-	-	-	-	-	
07/10/03	<2.9	<1.7	35	<100	-	
10/20/03	-	-	-	-	-	
01/14/04			WELL ABANDONED 01/2004			
MONITORING WELL # MW-5						
11/14/02	<0.2	<0.12	<0.16	<10	<0.13	
01/29/03	-	-	-	-	-	
04/23/03	-	-	-	-	-	
07/10/03	<0.29	<0.17	<0.28	<10	-	
10/20/03	-	-	-	-	-	
01/14/04	-	-	-	-	-	
MONITORING WELL # MW-6						
11/14/02	<0.2	<0.12	<0.16	<10	<0.13	
01/29/03	-	-	-	-	-	
04/23/03	-	-	-	-	-	
07/10/03	<0.29	<0.17	2.1	38	-	
10/20/03	-	-	-	-	-	
01/14/04	-	-	-	-	-	

TABLE 2
ADDITIONAL GROUNDWATER DATA
THRIFTY OIL STATION # 049, OAKLAND, CA.

DATE SAMPLED	OXYGENATES					1,2-Dichloroethane (ug/L)
	Di-isopropyl Ether (DIPE) (ug/L)	Ethyl Tert-Butyl Ether (ETBE) (ug/L)	Tert-Amyl Methyl Ether (TAME) (ug/L)	Tert Butyl Alcohol (TBA) (ug/L)		
MONITORING WELL # MW-7						
11/14/02	<0.2	<0.12	<0.16	<10	<0.13	
01/29/03	-	-	-	-	-	
04/23/03	-	-	-	-	-	
07/10/03	<0.29	<0.17	<0.28	<10	-	
10/20/03	-	-	-	-	-	
01/14/04	-	-	-	-	-	

NOTE: DIPE, ETBE, TAME, TBA analyzed by EPA Method 8260B

TABLE 3
GROUNDWATER REMEDIATION SYSTEM MONITORING PROGRAM
 Thrifty Oil Co. Station No 049, OAKLAND, CA

Date	Totalizer (gallons)	Total/Cum. Discharge (gallons)	Flow (gal/day)	Total H-C Removed (lbs)	EFFLUENT (ug/L)						INFLUENT (ug/L)					
					TPH-g	B	T	E	X	MTBE	TPH-g	B	T	E	X	MTBE
4/8/91	1,310	0	-	0 000	-	<0.3	<0.3	<0.3	<0.3	-	-	910	2000	160	2000	-
4/15/91	1,434	124	18	0 049	-	<0.3	<0.3	<0.3	<0.3	-	-	2800	4600	310	5000	-
4/22/91	1,510	200	11	0 078	-	<15	<15	<15	<45	-	-	3100	3300	<15	2800	-
4/29/91	1,660	350	21	0 137	-	<0.3	<0.3	<0.3	<0.9	-	-	3600	4500	300	5000	-
5/6/91	1,740	430	11	0 168	-	<0.3	<0.3	<0.3	<0.9	-	-	3600	3500	300	3800	-
5/13/91	1,880	570	20	0 223	-	<0.3	<0.3	<0.3	<0.9	-	-	3300	3200	230	3900	-
5/20/91	2,010	700	19	0 274	-	<0.3	<0.3	<0.3	<0.9	-	-	3300	3400	260	5100	-
5/28/91	2,050	740	5	0 290	-	<0.3	<0.3	<0.3	<0.9	-	-	2900	3000	230	4200	-
6/3/91	2,110	800	10	0 313	-	<0.3	<0.3	<0.3	<0.9	-	-	2500	2100	110	2800	-
6/10/91	2,160	850	7	0 333	-	<0.3	<0.3	<0.3	<0.9	-	-	1800	1700	120	2100	-
6/17/91	2,219	909	8	0 356	-	<0.3	<0.3	<0.3	<0.9	-	-	2100	1900	170	2700	-
6/24/91	2,263	953	6	0 373	-	<0.3	<0.3	<0.3	<0.9	-	-	2100	1800	150	2700	-
07/01/91	2,313	1,003	7	0 393	-	<0.5	<0.5	<1	<1	-	-	2,700	2,000	150	2,900	-
07/08/91	2,700	1,390	55	0 544	-	<0.5	<0.5	<1	<1	-	-	4,000	2,500	130	4,400	-
07/15/91	2,872	1,562	25	0 611	-	<0.5	<0.5	<1	<1	-	-	3,100	1,900	140	3,200	-
07/22/91	3,144	1,834	39	0 718	-	<0.5	<0.5	<1	<1	-	-	3,400	2,100	110	2,800	-
07/29/91	3,220	1,910	11	0 748	-	<0.5	<0.5	<1	<1	-	-	5,100	2,200	180	2,700	-
08/05/91	3,348	2,038	18	0 798	-	<0.5	<0.5	<1	<1	-	-	5,100	3,900	400	4,200	-
08/12/91	3,472	2,162	18	0 846	-	<0.5	<0.5	<1	<1	-	-	11,000	6,200	440	8,400	-
08/19/91	3,548	2,238	11	0 876	-	<0.5	<0.5	<1	<1	-	-	4,500	2,400	130	2,600	-
08/26/91	3,655	2,345	15	0 918	-	<0.5	<0.5	<1	<1	-	-	4,400	2,500	260	3,600	-
09/09/91	3,822	2,512	12	0 983	-	<0.5	<0.5	<1	<1	-	-	5,200	3,000	390	3,700	-
09/16/91	3,884	2,574	9	1 007	-	<0.5	<0.5	<1	<1	-	-	4,100	2,000	460	4,900	-
09/23/91	4,013	2,703	18	1 058	-	<0.5	<0.5	<1	<1	-	-	4,600	1,600	710	6,400	-
09/30/91	4,092	2,782	11	1 089	-	<0.5	<0.5	<1	<1	-	-	5,700	2,000	380	6,200	-
10/07/91	4,131	2,821	6	1 104	System shut down	-	-	-	-	-	-	-	-	-	-	-
10/14/91	4,195	2,885	9	1 129	-	<0.5	<0.5	<1	<1	-	-	4,400	2,000	370	8,100	-
10/21/91	4,406	3,096	30	1 212	-	<0.5	<0.5	<1	<1	-	-	2,300	1,100	190	4,200	-
10/28/91	4,474	3,164	10	1 238	-	<0.5	<0.5	<1	<1	-	-	6,400	4,100	620	6,100	-
11/03/91	4,613	3,303	23	1 293	-	<0.5	<0.5	<1	<1	-	-	6,100	2,800	200	5,600	-
11/11/91	4,700	3,390	11	1 327	-	<0.5	<0.5	<1	<1	-	-	6,500	2,300	<30	4,900	-
11/18/91	4,887	3,577	27	1 400	-	<0.5	<0.5	<1	<1	-	-	5,600	2,500	300	4,600	-
11/25/91	5,042	3,732	22	1 461	-	<0.5	<0.5	<1	<1	-	-	5,400	2,800	230	5,700	-
12/03/91	5,263	3,953	28	1 547	-	<0.5	<0.5	<1	<1	-	-	7,200	3,300	490	5,500	-
12/09/91	5,362	4,052	17	1 586	-	<0.5	<0.5	<1	<1	-	-	4,400	1,700	140	3,900	-
12/16/91	5,486	4,176	18	1 635	-	<0.5	<0.5	<0.5	<0.5	-	-	4,700	2,300	310	4,600	-
12/23/91	5,516	4,206	4	1 646	-	<0.5	<0.5	<0.5	<0.5	-	-	4,000	2,200	290	5,900	-
12/30/91	5,575	4,265	8	1 669	-	<0.5	<0.5	<0.5	<0.5	-	-	5,200	2,500	350	5,800	-
01/15/92	5,720	4,410	9	1 726	-	<0.5	<0.5	<0.5	<0.5	-	-	3,400	1,900	300	6,300	-

TABLE 3
GROUNDWATER REMEDIATION SYSTEM MONITORING PROGRAM
 Thrifty Oil Co. Station No 049, OAKLAND, CA

Date	Totalizer (gallons)	Total/Cum. Discharge (gallons)	Flow (gal/day)	Total H-C Removed (lbs.)	EFFLUENT (ug/L)						INFLUENT (ug/L)					
					TPH-g	B	T	E	X	MTBE	TPH-g	B	T	E	X	MTBE
02/10/92	6,264	4,954	21	1 939	-	<0.5	<0.5	<0.5	<0.5	-	-	5,800	2,800	320	7,200	-
03/09/92	8,520	7,210	81	2 822	<200	<0.5	16	<0.5	<0.5	-	47,000	7,100	4,800	630	10,300	-
04/13/92	22,888	21,578	411	7 369	<200	<0.5	<0.5	<0.5	<0.5	-	29,000	4,500	2,200	160	4,800	-
05/11/92	24,920	23,610	73	7 800	<200	<0.5	<0.5	<0.5	<0.5	-	22,000	4,300	1,500	130	3,800	-
06/01/92	28,330	27,020	162	8 368	<200	<0.5	<0.5	<0.5	<0.5	-	18,000	3,400	1,500	660	4,200	-
07/13/92	72,675	27,020		8,368	-	<0.5	<0.5	<0.5	<0.5	-	-	1,800	750	150	5,600	-
07/13/92	72,675	27,020		8,368	The system pumped air and flowmeter jumped from 30,000 gallons to 70,000 gallons.						-	-	-	-	-	-
08/17/92	75,046	29,391	68	8 724	-	<0.5	<0.5	<0.5	<0.5	-	-	1,100	350	200	1,100	-
09/14/92	75,582	29,927	19	8 804	-	<0.5	<0.5	<0.5	<1	-	-	2,100	520	<25	3,500	-
10/05/92	75,680	30,025	5	8 819	<200	<0.5	<0.5	<0.5	<1	-	19,000	1,700	270	<25	4,000	-
11/09/92	77,280	31,625	46	9 072	-	<0.5	<0.5	<0.5	<0.5	-	-	4,000	1,400	120	5,900	-
12/14/92	79,420	33,765	61	9 411	-	<0.5	<0.5	<0.5	<1	-	-	7,300	4,900	1,800	16,000	-
01/04/93	84,720	39,065	252	10 250	-	<0.5	<0.5	<0.5	<1	-	-	5,400	2,100	450	7,800	-
02/15/93	102,689	57,034	428	14 739	<200	<0.5	<0.5	<0.5	<1	-	41,000	6,600	3,200	260	9,600	-
02/22/93	146,430	57,034		14 739	The system pumped air and flowmeter jumped from 102,689 gallons to 146,430 gallons						-	-	-	-	-	-
03/08/93	147,500	58,104	76	15 104	-	<0.5	<0.5	<0.5	<1	-	-	7,400	3,400	56	11,000	-
04/26/93	151,200	61,804	76	16 291	<100	<0.5	<0.5	<0.5	<1	-	36,000	4,300	2,200	420	8,300	-
04/26/93	151,200	61,804		16 291	Shut down system for repair						-	-	-	-	-	-
07/21/93	151,240	61,844	0	16 303	Restart the system						-	-	-	-	-	-
08/11/93	151,650	62,254	20	16 426	-	<0.5	<0.5	<0.5	<1	-	-	6,500	2,300	390	6,200	-
09/16/93	154,005	64,609	65	17 200	<60	<0.3	<0.3	<0.3	<0.6	-	43,000	2,300	320	<4.4	2,900	-
10/04/93	154,896	65,500	50	17 482	<60	<0.3	<0.3	<0.3	<0.6	-	33,000	2,900	470	6.9	3,500	-
11/05/93	157,431	68,035	79	17 989	<50	<0.3	<0.3	<0.3	<0.5	-	15,000	1,100	27	<0.3	920	-
12/03/93	159,324	69,928	68	18 233	<50	<0.3	<0.3	<0.3	<0.5	-	16,000	1,100	88	<6.6	2,300	-
01/06/94	166,440	77,044	209	19 181	-	<0.3	<0.3	<0.3	<0.5	-	-	3,800	730	<13	1,200	-
02/03/94	170,720	81,324	153	19 752	-	<0.3	<0.3	<0.3	<0.5	-	-	3,600	610	<4.4	4,800	-
03/03/94	178,168	88,772	266	20 744	-	<0.3	<0.3	<0.3	<0.5	-	-	2,800	2,000	270	3,400	-
04/07/94	185,670	96,274	214	22 056	<50	<0.3	<0.3	<0.3	<0.5	-	26,000	2,200	550	<6.6	1,900	-
05/12/94	188,840	99,444	91	22 460	<50	<0.3	<0.3	<0.3	<0.5	-	4,600	100	10	8.4	280	-
06/16/94	194,680	105,284	167	22 684	<50	<0.3	<0.3	<0.3	<0.5	-	<50	<0.3	<0.3	<0.3	<0.5	-
07/11/94	199,135	109,739	178	22 832	<50	<0.3	<0.3	<0.3	<0.5	-	4,000	220	<2.6	<2.6	320	-
08/04/94	200,910	111,514	74	22 919	<50	<0.3	<0.3	<0.3	<0.5	-	7,800	480	62	<0.3	630	-
09/15/94	203,450	114,054	60	23 036	<50	<0.3	<0.3	<0.3	<0.5	-	3,200	150	24	2.6	170	-
10/10/94	205,210	115,814	70	23 069	<50	<0.3	<0.3	<0.3	<0.5	-	1,300	86	15	11	15	-
11/07/94	206,060	116,664	30	23 074	<50	<0.3	<0.3	<0.3	<0.5	-	170	15	<0.3	<0.5	0.5	-
12/05/94	207,093	117,697	37	23 075	<50	<0.3	<0.3	<0.3	<0.5	-	75	1.3	<0.3	<0.5	<0.5	-
01/09/95	207,293	117,897	6	23 075	<50	<0.3	<0.3	<0.3	<0.5	-	<50	<0.3	<0.3	<0.5	<0.5	-
02/01/95	207,650	118,254	16	23 075	<50	<0.3	<0.3	<0.3	<0.5	-	<50	<0.3	<0.3	<0.5	<0.5	-
02/06/95	207,810	118,414	32	23 075	<50	<0.3	<0.3	<0.3	<0.5	-	<50	27	<0.3	<0.5	<0.5	-

TABLE 3
GROUNDWATER REMEDIATION SYSTEM MONITORING PROGRAM
 Thrifty Oil Co. Station No 049, OAKLAND, CA

Date	Totalizer (gallons)	Total/Cum. Discharge (gallons)	Flow (gal/day)	Total H-C Removed (lbs)	EFFLUENT (ug/L)						INFLUENT (ug/L)					
					TPH-g	B	T	E	X	MTBE	TPH-g	B	T	E	X	MTBE
03/10/95	208,430	119,034	19	23,076	<100	<0.5	<0.5	<0.5	<1	-	<100	<0.5	<0.5	<0.5	<1	-
04/10/95	208,564	119,168	4	23,079	<100	<0.5	<0.5	<0.5	<1	-	3,300	180	7.6	2.1	150	-
05/08/95	208,608	119,212	2	23,082	<100	<0.5	<0.5	<0.5	<1	-	11,000	640	9.2	<5	1,100	-
06/05/95	208,926	119,530	11	23,103	<100	<0.5	<0.5	<0.5	<1	-	5,100	270	2.2	<0.5	49	-
07/10/95	214,182	124,786	150	23,500	<100	<0.5	<0.5	<0.5	<1	-	13,000	1,600	120	24	1,300	-
08/07/95	221,876	132,480	275	24,332	Shut down system for repair						-	-	-	-	-	-
08/28/95	221,997	132,601	6	24,346	Restart the system						-	-	-	-	-	-
09/06/95	222,003	132,607	1	24,346	<100	<0.5	<0.5	<0.5	<1	-	2,300	<0.5	<0.5	<0.5	<1	-
10/03/95	222,343	132,947	10	24,352	<100	<0.5	<0.5	<0.5	<1	-	2,000	5.6	0.77	0.66	3.8	-
11/06/95	222,704	133,308	13	24,360	<50	0.3	0.31	<0.3	0.68	-	3,000	27	1.7	3.7	48	-
12/11/95	223,792	134,396	31	24,387	<50	<0.3	<0.3	<0.3	<0.5	-	<50	<0.3	<0.3	<0.3	0.96	-
01/08/96	224,661	135,265	31	24,400	970	<0.3	<0.3	<0.3	0.67	-	1,800	39	<0.3	<0.3	<0.5	-
02/12/96	227,812	138,416	90	24,467	<50	10	0.37	<0.3	0.53	-	3,300	190	<7.5	<7.5	20	-
03/12/96	229,301	139,905	51	24,504	<50	<0.3	<0.3	<0.3	<0.5	-	2,700	250	2.3	<1.5	<2.5	-
04/08/96	242,320	152,924	482	24,704	<50	<0.3	<0.3	<0.3	<0.5	-	1,000	90	5	<0.3	67	-
05/06/96	247,840	158,444	197	25,072	100	<0.3	<0.3	<0.3	<0.5	-	15,000	2,200	600	32	2,400	-
06/03/96	248,423	159,027	21	25,145	Shut down system for carbon change						-	-	-	-	-	-
08/08/96	248,423	159,027	-	25,145	Start-up system						-	-	-	-	-	-
08/20/96	248,630	159,234	17	25,149	<50	<0.3	<0.3	<0.3	<0.5	-	2,100	24	<0.3	<0.3	49	-
09/23/96	259,030	169,634	306	25,417	<50	<0.3	<0.3	<0.3	<0.5	-	4,100	260	<3	<3	34	-
10/16/96	263,610	174,214	199	25,547	<50	<0.3	<0.3	<0.3	<0.5	-	2,700	220	3.8	<0.6	44	-
11/19/96	263,986	174,590	11	25,553	<50	<0.3	<0.3	<0.3	<0.5	-	1,200	<0.3	<0.3	<0.3	<0.5	-
12/16/96	264,210	174,814	8	25,581	<50	<0.3	<0.3	<0.3	1.5	-	29,000	410	2,300	120	1,100	-
01/22/97	266,220	176,824	54	26,393	<50	<0.3	<0.3	<0.3	<0.5	-	68,000	<0.3	<0.3	<0.3	<0.5	-
02/24/97	267,030	177,634	25	26,794	<50	<0.3	<0.3	<0.3	<0.5	-	51,000	3,500	3,200	390	2,200	-
03/17/97	267,230	177,834	10	26,911	<50	<0.3	<0.3	<0.3	<0.5	-	89,000	<6	11	<6	14	-
04/21/97	267,415	178,019	5	27,026	<50	<0.3	<0.3	<0.3	<0.5	-	61,000	730	18	130	360	-
05/22/97	276,535	187,139	294	29,375	<50	<0.3	<0.3	<0.3	<0.5	-	850	1.3	<0.3	0.4	46	-
06/23/97	281,214	191,818	146	29,408	-	-	-	-	-	-	-	-	-	-	-	-
07/14/97	284,210	194,814	143	29,501	<50	<0.3	<0.3	<0.3	<0.5	-	6,600	<0.3	0.59	<0.3	9	-
08/18/97	298,610	209,214	411	30,293	-	-	-	-	-	-	-	-	-	-	-	-
09/15/97	301,043	211,647	87	30,427	-	-	-	-	-	-	-	-	-	-	-	-
10/07/97	333,480	244,084	1,474	44,014	<50	<0.3	<0.3	<0.3	<0.5	-	94,000	<0.3	<0.3	<0.3	<0.5	-
11/17/97	334,286	244,890	20	44,645	-	-	-	-	-	-	-	-	-	-	-	-
12/08/97	334,382	244,986	5	44,720	-	-	-	-	-	-	-	-	-	-	-	-
12/12/97	334,382	244,986	-	44,720	Shut down system due to stolen equipment						-	-	-	-	-	-
04/08/98	334,382	244,986	-	44,720	<50	<0.3	<0.3	<0.3	<0.5	<20	3,100	12	1	<0.3	490	2,600
05/11/98	334,382	244,986	-	44,720	-	-	-	-	-	-	-	-	-	-	-	-
06/22/98	334,382	244,986	-	44,720	-	-	-	-	-	-	-	-	-	-	-	-

TABLE 3
GROUNDWATER REMEDIATION SYSTEM MONITORING PROGRAM
 Thrifty Oil Co Station No 049, OAKLAND, CA

Date	Totalizer (gallons)	Total/Cum. Discharge (gallons)	Flow (gal/day)	Total H-C Removed (lbs)	EFFLUENT (ug/L)						INFLUENT (ug/L)					
					TPH-g	B	T	E	X	MTBE	TPH-g	B	T	E	X	MTBE
07/20/98	334,382	244,986	-	44,720	<50	<0.3	<0.3	<0.3	<0.5	-	52,000	8	0.52	0.83	1.5	-
08/03/98	346,521	257,125	867	49,977	Shut down system for carbon canisters replacement						-	-	-	-	-	-
09/17/98	354,985	265,589	188	53,642	-	-	-	-	-	-	-	-	-	-	-	-
10/14/98	358,015	268,619	112	54,336	<50	<0.3	<0.3	<0.3	1.6	-	3,100	45	13	3.5	350	-
11/05/98	359,600	270,204	72	54,378	System shut down due to vandalism and stolen equipment						-	-	-	-	-	-
11/20/98	359,600	270,204	-	54,378	Restart						-	-	-	-	-	-
12/11/98	369,452	280,056	469	54,633	-	-	-	-	-	-	-	-	-	-	-	-
12/24/98	-	280,056	-	54,633	No reading, meter broken						-	-	-	-	-	-
01/15/99	0	280,056	-	54,633	Replaced Flowmeter started at 0						-	-	-	-	-	-
01/21/99	985.5	281,042	164	54,636	57	<0.3	<0.3	<0.3	0.76	-	380	6.2	1	<0.3	9.1	-
02/12/99	1,971.0	282,027	45	54,639	-	-	-	-	-	-	-	-	-	-	-	-
03/12/99	4,390.0	284,446	86	54,647	-	-	-	-	-	-	-	-	-	-	-	-
04/15/99	8,595.0	288,651	124	54,661	<50	<0.3	<0.3	<0.3	<0.5	<5	410	1.6	0.78	<0.3	5	*580 / 330
05/04/99	9,410.0	289,466	43	54,663	-	-	-	-	-	-	-	-	-	-	-	-
05/18/99	9,410.0	289,466	-	54,663	Shut down system for pump controller repair by manufacturer						-	-	-	-	-	-
09/20/99	9,411.0	289,467	0	54,663	Restart the system						-	-	-	-	-	-
09/24/99	9,412.4	289,468	0	54,663	-	-	-	-	-	-	-	-	-	-	-	-
10/13/99	9,509.8	289,566	5	54,666	<50	<0.3	<0.3	<0.3	<0.5	<5	6,000	<0.3	<0.3	<0.3	<0.5	13,000
11/12/99	9,701.9	289,758	6	54,676	-	-	-	-	-	-	-	-	-	-	-	-
12/17/99	9,893.7	289,950	5	54,685	-	-	-	-	-	-	-	-	-	-	-	-
01/20/00	10,052.1	290,108	5	54,693	<50	<0.3	<0.3	<0.3	<0.5	<5	<50	<0.3	<0.3	<0.3	<0.5	-
02/17/00	10,156.6	290,213	4	54,698	-	-	-	-	-	-	-	-	-	-	-	-
03/13/00	10,354.7	290,411	8	54,708	-	-	-	-	-	-	-	-	-	-	-	-
04/05/00	10,545.7	290,602	8	54,897	72.7	1.8	4.1	0.7	6.7	-	119,000	2,360	6,440	6,240	25,200	*30,800 / 21,800
05/19/00	11,071.7	291,128	12	55,419	Shut down system for carbon drum replacement						-	-	-	-	-	-
06/05/00	11,075.4	291,131	0	55,419	Restart the system						-	-	-	-	-	-
06/14/00	11,131.6	291,188	6	55,474	<50	<0.3	<0.3	<0.3	<0.6	<5	<1,000	<6	<6	<6	14	24,500
07/06/00	11,362.0	291,418	10	55,703	Shut down system for carbon replacement						-	-	-	-	-	-
07/17/00	0.0	291,418	-	55,703	Restart the system after carbon change, repipe and flowmeter change (starting at 0.0)						-	-	-	-	-	-
07/24/00	411.0	291,829	59	55,907	<50	<0.3	<0.3	<0.3	<0.6	<5	205	<0.3	1	<0.3	<0.6	*99 / 104
08/21/00	8,193.0	299,611	278	55,920	-	-	-	-	-	-	-	-	-	-	-	-
09/18/00	27,251.0	318,669	681	55,953	-	-	-	-	-	-	-	-	-	-	-	-
10/18/00	54,280.0	345,698	901	96,155	<50	<0.18	<0.14	<0.18	<0.26	<0.24	357,000	2,380	2,960	1,290	6,850	9,630
10/30/00	64,610.0	356,028	861	126,867	-	-	-	-	-	-	-	-	-	-	-	-
11/27/00	79,870.0	371,288	545	172,235	-	-	-	-	-	-	-	-	-	-	-	-
12/22/00	99,240.0	390,658	775	229,623	-	-	-	-	-	-	-	-	-	-	-	-
01/17/01	101,250.0	392,668	77	233,018	<50	<0.18	<0.14	<0.18	<0.26	<0.24	24,700	783	373	2	3,480	15,000
02/23/01	144,120.0	435,538	1,159	241,836	-	-	-	-	-	-	-	-	-	-	-	-
03/30/01	195,400.0	486,818	1,465	252,385	-	-	-	-	-	-	-	-	-	-	-	-

TABLE 3
GROUNDWATER REMEDIATION SYSTEM MONITORING PROGRAM
 Thrifty Oil Co. Station No 049, OAKLAND, CA

Date	Totalizer (gallons)	Total/Cum. Discharge (gallons)	Flow (gal/day)	Total H-C Removed (lbs)	EFFLUENT (ug/L)						INFLUENT (ug/L)					
					TPH-g	B	T	E	X	MTBE	TPH-g	B	T	E	X	MTBE
04/06/01	199,090.0	490,508	527	253,144	System shut down for carbon replacement. Replaced on 4/11/01, restart on 4/13/01											
04/20/01	207,050.0	498,468	569	255,172	88	<0.18	<0.14	<0.18	<0.26	93	36,500	855	716	659	1,570	11,400
04/27/01	210,640.0	502,058	513	256,263	System shut down for repair/replacement of compressor's pressure switch and exhaust valve											
04/30/01	210,640.0	502,058	-	256,263	320	<0.18	<0.14	<0.18	<0.26	*337 / 60	7,620	268	22	10	124	*13,600 / 9,130
05/11/01	210,640.0	502,058	-	256,263	Replaced pressure switch on 5/7/01, system still off for carbon replacement											
05/21/01	210,640.0	502,058	-	256,263	Restart the system											
05/30/01	226,830.0	518,248	1,799	263,289	<50	<0.18	<0.14	<0.18	<0.26	<0.24	96,600	4,980	1,660	2,770	11,300	*53,600 / 41,600
06/29/01	267,230.0	558,648	1,347	295,790	-	-	-	-	-	-	-	-	-	-	-	-
07/11/01	310,010.0	601,428	3,565	341,855	<50	<0.18	<0.14	<0.18	<0.26	<0.24	162,000	<0.18	4,140	4,760	24,000	<0.24
08/17/01	441,270.0	732,688	3,548	518,940	-	-	-	-	-	-	-	-	-	-	-	-
09/28/01	498,310.0	789,728	1,358	595,894	-	-	-	-	-	-	-	-	-	-	-	-
10/03/01	503,930.0	795,348	1,124	600,424	<50	<0.18	<0.14	<0.18	<0.26	<0.24	31,600	<1.8	150	294	5,280	<2.4
11/12/01	664,700.0	956,118	4,019	642,733	-	-	-	-	-	-	-	-	-	-	-	-
12/28/01	706,300.0	997,718	904	653,680	-	-	-	-	-	-	-	-	-	-	-	-
01/11/02	721,050.0	1,012,468	1,054	657,562	System shut down for carbon replacement											
01/21/02	721,050.0	1,012,468	-	657,562	Restart the system											
02/01/02	731,320.0	1,022,738	934	658,963	<100	<0.3	<0.3	<0.3	<0.6	<5	1,172	1	1	1	6	<5
02/22/02	751,340.0	1,042,758	953	659,159	-	-	-	-	-	-	-	-	-	-	-	-
03/27/02	813,240.0	1,104,658	1,876	659,763	-	-	-	-	-	-	-	-	-	-	-	-
04/12/02	835,170.0	1,126,588	1,371	660,975	<50	<0.18	<0.14	<0.18	<0.26	<0.24	12,100	5	1	<0.18	<0.26	18,400
04/26/02	918,670.0	1,210,088	5,964	669,389	System shut down											
05/10/02	918,680.0	1,210,098	1	669,390	Restart											
05/17/02	928,670.0	1,220,088	1,427	670,397	-	-	-	-	-	-	-	-	-	-	-	-
06/03/02	-	-	-	-	-	<0.5	<0.7	<0.8	<3.3	-	-	-	-	-	-	Outlet sampling results from EBMUD (sample collected by EBMUD inspector)
06/03/02	-	-	-	-	-	<50	<0.18	<0.14	<0.18	<0.26	<0.24	-	-	-	-	Split-sample results (sample collected by us)
06/07/02	971,240.0	1,262,658	2,027	674,686	-	-	-	-	-	-	-	-	-	-	-	-
06/28/02	1,012,150.0	1,303,568	1,948	678,809	-	-	-	-	-	-	-	-	-	-	-	-
07/15/02	1,045,670.0	1,337,088	1,972	681,977	<50	<0.18	<0.14	<0.18	<0.26	3.3 J	10,600	<0.18	<0.14	<0.18	<0.26	10,000
07/31/02	1,052,380.0	1,343,798	419	682,569	System shut down for carbon replacement											
08/16/02	1,052,390.0	1,343,808	1	682,569	Restart											
08/30/02	1,057,310.0	1,348,728	351	683,004	-	-	-	-	-	-	-	-	-	-	-	-
09/20/02	-	-	-	-	Sample results from EBMUD nor received yet											Outlet sampling results from EBMUD (sample collected by EBMUD inspector)
09/20/02	1,061,730.0	1,363,148	210	683,394	<50	<0.1	<0.15	<0.06	-	-	-	-	-	-	-	Split-sample results (sample collected by us, analysis by EPA 624 & 8015M)
09/27/02	1,064,020.0	1,365,438	327	683,596	-	-	-	-	-	-	-	-	-	-	-	-
10/04/02	1,069,139.0	1,366,548	730	683,787	<50	<0.18	<0.14	<0.18	<0.26	<0.24	4,500 J	<0.18	<0.14	<0.18	<0.26	2,570
10/25/02	1,082,500.0	1,373,918	637	684,289	-	-	-	-	-	-	-	-	-	-	-	-
11/29/02	1,108,680.0	1,400,098	748	685,270	-	-	-	-	-	-	-	-	-	-	-	-
12/27/02	1,123,890.0	1,415,308	543	685,840	-	-	-	-	-	-	-	-	-	-	-	-
01/03/03	1,128,910.0	1,420,328	717	686,028	System shut down for carbon replacement											

TABLE 3
GROUNDWATER REMEDIATION SYSTEM MONITORING PROGRAM
 Thrifty Oil Co. Station No 049, OAKLAND, CA

Date	Totalizer (gallons)	Total/Cum. Discharge (gallons)	Flow (gal/day)	Total H-C Removed (lbs)	EFFLUENT (ug/L)						INFLUENT (ug/L)					
					TPH-g	B	T	E	X	MTBE	TPH-g	B	T	E	X	MTBE
01/10/03	1,128,970.0	1,420,388	9	686,030	Restart											
01/17/03	1,132,560.0	1,423,978	513	686,999	<50	<0.14	<0.07	<0.08	1.1	<2.0	32,400	11	64	<0.8	6,050	706
01/31/03	1,143,290.0	1,434,708	766	689,460	<15	<0.04	0.58	<0.02	1.1	<0.03	22,700	14	34	18	5,160	550
02/14/03	1,153,670.0	1,445,088	741	691,423	System shut down for carbon replacement											
04/04/03	1,153,670.0	1,445,088	-	691,423	System kept off and dismantled for upgrade											

WD PERMIT LIMITS:	NE	5.0	5.0	5.0	5.0	NE
-------------------	----	-----	-----	-----	-----	----


Note:

< = less than laboratory detection level indicated
 - = no sample / not analyzed

TPH is analyzed by EPA Method 8015 M
 BTEX is analyzed by EPA Method 602 or 8020
 *MTBE 8020/8260

In February 2000, the total cumulative discharge amount was corrected to reflect all system maintenance and flowmeter changeouts since the startup of the system. The total number may be different from previous versions of this table
 Total Hydrocarbons Removed = From 4/8/91 to 2/10/92, the influent TPHg is assumed to be 47,000 (3/9/92)

FIGURES



SITE PLAN AND RECOVERY SYSTEM LOCATION
THRIFTY SERVICE STATION NO. 49
3400 SAN PABLO AVE.
OAKLAND, CA

LEGEND

- OMW1 - GT MONITORING WELLS
- MW4 - WCC MONITORING WELLS
- RW1 - PROPOSED RECOVERY WELL





FIGURE 1



GROUNDWATER CONTOUR MAP
THRIFTY SERVICE STATION NO. 49
3400 SAN PABLO AVE.
OAKLAND, CA


Data Collected 1/14/2004
Datum is Mean Sea Level

LEGEND

OWW1 - GT MONITORING WELLS
MW-4 - WCC MONITORING WELLS



FIGURE 2



Samples Collected 1/14/2004
Results in ug/L


LEGEND

OMW1 - GT MONITORING WELLS
@ MW-4 - WCC MONITORING WELLS

TPH ISOCONCENTRATION MAP ug/L
THRIFTY SERVICE STATION NO. 49
3400 SAN PABLO AVE.
OAKLAND, CA



FIGURE 3



Samples Collected 1/14/2004
 Results in ug/L

BENZENE ISOCONCENTRATION MAP ug/L
 THRIFTY SERVICE STATION NO. 49
 3400 SAN PABLO AVE.
 OAKLAND, CA

LEGEND

OMW1 - GT MONITORING WELLS
 MW-4 - WCC MONITORING WELLS





FIGURE 4



Samples Collected 1/14/2004
Results in ug/L

MTBE ISOCONCENTRATION MAP ug/L
THRIFTY SERVICE STATION NO. 49
3400 SAN PABLO AVE.
OAKLAND, CA

LEGEND

○ MW1 - GT MONITORING WELLS
◐ MW-4 - WCC MONITORING WELLS




FIGURE 5

APPENDIX A



PROJECT STATUS REPORT

SITE
ADDRESS:

THRIFTY OIL CO. #049
3400 SAN PABLO AVE.
OAKLAND, CA 94612

DATE.

01-14-04

PERSONNEL:

SERBAN,

WELL ID	DTP (FT)	DTW (FT)	DTB (FT)	PT (FT)	WC (FT)	DIA (IN)	PURGE (GAL) EST.	COMMENT	PURGE (GAL) ACT.					
MONTHLY/QUARTERLY														
1 MW-1		3.92	17.72			2"	9	10						
2 MW-2	A.					2"								
3 MW-3		4.23	24.16			2"	13	13						
4 MW-4	A-					4"								
5 MW-5		3.03	13.76			2"	7	10						
6 MW-6		3.82	13.02			2"	6	10						
7 MW-7		4.38	13.56			4"	24	24						
8 RW-1	A.					6"								
FREE PRODUCT REMOVED: APPROX. <input checked="" type="checkbox"/> GALLONS					PURGE-WATER REMOVED: APPROX. <input checked="" type="checkbox"/> GALLONS									
REMARKS: MW-2, MW-4, RW-1 ARE ABANDONED WELLS -														
EXPLANATION:														

DTP=DEPTH TO PRODUCT, DTW=DEPTH TO WATER, DTB=DEPTH TO BOTTOM; ALL MEASURED FROM TOP OF CASING
 PT=PRODUCT THICKNESS, WC=WATER COLUMN, DIA=DIAMETER, EST=ESTIMATE, ACT=ACTUAL, FT=FEET, GAL=GALLONS

REV: 8/28/02

FIELD DATA - GROUNDWATER SAMPLING PROGRAM

Site:	# 049	Date:	01-14-04
Address:			
Personnel:	SERBON	Weather:	Rainy
Well No:	MW - 1	Equip:	BAILER

Before Purging:			
Total Well Depth: (ft)	17.72	Well Diameter	24
Depth to Water (ft)	3.92	Est. Purge Volume:	9

Sampling Data:							
Initial Turbidity:				Final Turbidity:			
Time	12:04	12:06	12:08	12:10	12:11	12:13	12:15
EC	1670	1710	1690	1670	1640	1650	1620
pH	6.03	6.19	6.40	6.32	6.36	6.32	6.30
Temp	73.4	73.2	73.1	72.1	72.2	72.3	72.1
Gal.	1	2	3	5	6	7	9
Time							
EC							
pH							
Temp							
Gal.							

After Purging/Before Sample Collection	
Depth to Water (ft.)	7.11
Total Well Depth(ft.)	17.72

FIELD DATA - GROUNDWATER SAMPLING PROGRAM

Site:	# 064	Date:	01-14-04
Address:			
Personnel:	SERBAN	Weather:	Rainy
Well No:	MW-3	Equip:	BARRIER

Before Purging:			
Total Well Depth: (ft)	24.16	Well Diameter	24
Depth to Water (ft)	3.92	Est. Purge Volume:	9

Sampling Data:								
Initial Turbidity:	Final Turbidity:							
Time	9:00	9:12	9:13	9:14	9:15	9:17	9:20	
EC	1380	1340	1370	1360	1370	1380	1370	
pH	6.11	6.04	6.11	6.07	6.04	6.03	6.01	
Temp	73.4	73.2	72.9	72.7	72.7	72.6	72.7	
Gal.	1	2	3	5	6	7	9	

Time								
EC								
pH								
Temp								
Gal.								

After Purging/Before Sample Collection			
Depth to Water (ft.)	8.42	Total Well Depth(ft.)	24.16

FIELD DATA - GROUNDWATER SAMPLING PROGRAM

Site:	# 049	Date:	01-14-04
Address:			
Personnel:	SERBAN	Weather:	RAIN
Well No:	MW-5	Equip:	BAILER

Before Purging:			
Total Well Depth: (ft)	13.76	Well Diameter	24
Depth to Water (ft)	3.03	Est. Pure Volume:	7

Sampling Data:							
Initial Turbidity:				Final Turbidity:			
Time	11:48	11:50	11:52	11:54	11:56	11:58	12:00
EC	1430	1420	1420	1430	1420	1410	1430
pH	6.03	6.04	6.03	6.09	5.92	5.96	5.96
Temp	72.4	72.2	72.2	71.9	71.6	71.4	71.3
Gal.	1	2	3	4	5	6	7
Time							
EC							
pH							
Temp							
Gal.							

After Purging/Before Sample Collection			
Depth to Water (ft.)	8.10	Total Well Depth(ft.)	13.76

FIELD DATA - GROUNDWATER SAMPLING PROGRAM

Site:	4069	Date:	01-14-04
Address:			
Personnel:	SERBAN,	Weather:	RAIN
Well No:	MW-C	Equip:	BARRIER

Before Purging:			
Total Well Depth: (ft)	13.02	Well Diameter	2"
Depth to Water (ft)	3.82	Est. Purge Volume:	6

Sampling Data:							
Initial Turbidity:				Final Turbidity:			
Time	12:49	12:50	12:51	12:52	12:53	12:54	12:55
EC	1370	1390	1370	1380	1370	1370	1380
pH	6.30	6.38	6.36	5.42	5.46	5.42	5.46
Temp	73.3	73.1	73.1	72.9	72.8	72.7	72.6
Gal.	0.5	1	2	3	4	5	6
Time							
EC							
pH							
Temp							
Gal.							

After Purging/Before Sample Collection			
Depth to Water (ft.)	6.42	Total Well Depth(ft.)	13.02

FIELD DATA - GROUNDWATER SAMPLING PROGRAM

Site:	4049	Date:	01-14-04
Address:			
Personnel:	SERRAN	Weather:	RAIN
Well No:	MW-7	Equip:	BAILER

Before Purging:			
Total Well Depth: (ft)	13.56	Well Diameter	
Depth to Water (ft)	4.88	Est. Purge Volume:	

Sampling Data:								
Initial Turbidity:	Final Turbidity:							
Time	12:24	12:27	12:31	12:34	12:38	12:41	12:45	
EC	1420	1470	1420	1430	1420	1420	1430	
pH	6.40	6.32	6.20	6.18	6.11	6.06	6.06	
Temp	72.4	72.2	72.2	71.9	71.7	71.6	71.4	
Gal.	3	6	10	13	17	20	24	
Time								
EC								
pH								
Temp								
Gal.								

After Purging/Before Sample Collection			
Depth to Water (ft.)	3.14	Total Well Depth(ft.)	13.56

APPENDIX B



ASSOCIATED LABORATORIES
806 North Batavia - Orange, California 92868 - 714/771-6900

FAX 714/538-1209

CLIENT	Thrifty Oil Company ATTN: Jeff Suryakusuma 13116 Imperial Hwy. P.O. Box 2128 Santa Fe Springs, CA 90670	(8871)	LAB REQUEST	123007
			REPORTED	01/26/2004
			RECEIVED	01/16/2004

PROJECT Station #049
3400 San Pablo Ave., Oakland

SUBMITTER Client

COMMENTS Global ID: T0600101366

This laboratory request covers the following listed samples which were analyzed for the parameters indicated on the attached Analytical Result Report. All analyses were conducted using the appropriate methods as indicated on the report. This cover letter is an integral part of the final report.

<u>Order No.</u>	<u>Client Sample Identification</u>
491448	TOC #049 MW-3
491449	TOC #049 MW-5
491450	TOC #049 MW-1
491451	TOC #049 MW-7
491452	TOC #049 MW-6
491453	Trip Blank
491454	Laboratory Method Blank

Thank you for the opportunity to be of service to your company. Please feel free to call if there are any questions regarding this report or if we can be of further service.

ASSOCIATED LABORATORIES by,

Edward S. Behare, Ph.D.
Vice President

NOTE: Unless notified in writing, all samples will be discarded by appropriate disposal protocol 30 days from date reported.

The reports of the Associated Laboratories are confidential property of our clients and may not be reproduced or used for publication in part or in full without our written permission. This is for the mutual protection of the public, our clients, and ourselves.

TESTING & CONSULTING
Chemical
Microbiological
Environmental

Order #: 491448

Matrix: WATER

Client Sample ID: TOC #049 MW-3

Date Sampled: 01/14/2004 Time Sampled: 11:30

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX + MTBE						
Benzene	2.0	1	0.3	0.04	ug/L	01/19/04 LZ
Ethyl benzene	6.1	1	0.3	0.02	ug/L	01/19/04 LZ
Methyl t - butyl ether	1510	50	250.0	0.03	ug/L	01/19/04 LZ
Toluene	2.2	1	0.3	0.02	ug/L	01/19/04 LZ
Xylene (total)	7.8	1	0.6	0.06	ug/L	01/19/04 LZ
Surrogates						Units
a,a,a-Trifluorotoluene	96				%	70 - 130
8260B BTEX/MTBE Only						
Methyl-tert-butylether (MTBE)	767	1	1	0.18	ug/L	01/24/04 LB
8015M - Gasoline						
Gasoline	1160	1	50	15	ug/L	01/19/04 LZ
Surrogates						Units
a,a,a-Trifluorotoluene	96				%	55 - 200

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
 ND = Not detected below indicated MDL, J=Trace



Order #: 491449
Matrix: WATER

Client Sample ID: TOC #049 MW-5
Date Sampled: 01/14/2004 Time Sampled: 15:00

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX + MTBE						
Benzene	ND	1	0.3	0.04	ug/L	01/19/04 LZ
Ethyl benzene	ND	1	0.3	0.02	ug/L	01/19/04 LZ
Methyl t - butyl ether	8.2	1	5	0.03	ug/L	01/19/04 LZ
Toluene	ND	1	0.3	0.02	ug/L	01/19/04 LZ
Xylene (total)	ND	1	0.6	0.06	ug/L	01/19/04 LZ
Surrogates						Units
a,a,a-Trifluorotoluene	91				%	70 - 130
8260B BTEX/MTBE Only						
Methyl-tert-butylether (MTBE)	4.1	1	1	0.18	ug/L	01/24/04 LB
8015M - Gasoline						
Gasoline	ND	1	50	15	ug/L	01/19/04 LZ
Surrogates						Units
a,a,a-Trifluorotoluene	91				%	55 - 200

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 491450

Matrix: WATER

Client Sample ID: TOC #049 MW-1

Date Sampled: 01/14/2004 Time Sampled: 15:05

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX + MTBE						
Benzene	ND	1	0.3	0.04	ug/L	01/19/04 LZ
Ethyl benzene	ND	1	0.3	0.02	ug/L	01/19/04 LZ
Methyl t - butyl ether	ND	1	5	0.03	ug/L	01/19/04 LZ
Toluene	ND	1	0.3	0.02	ug/L	01/19/04 LZ
Xylene (total)	ND	1	0.6	0.06	ug/L	01/19/04 LZ
Surrogates						Units
a,a,a-Trifluorotoluene	89				%	70 - 130
8015M - Gasoline						
Gasoline	ND	1	50	15	ug/L	01/19/04 LZ
Surrogates						Units
a,a,a-Trifluorotoluene	89				%	55 - 200

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
 ND = Not detected below indicated MDL, J=Trace



Order #: 491451
Matrix: WATER

Client Sample ID: TOC #049 MW-7
Date Sampled: 01/14/2004 Time Sampled: 15:15

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX + MTBE						
Benzene	ND	1	0.3	0.04	ug/L	01/19/04 LZ
Ethyl benzene	ND	1	0.3	0.02	ug/L	01/19/04 LZ
Methyl t - butyl ether	ND	1	5	0.03	ug/L	01/19/04 LZ
Toluene	ND	1	0.3	0.02	ug/L	01/19/04 LZ
Xylene (total)	ND	1	0.6	0.06	ug/L	01/19/04 LZ
Surrogates						Units
a,a,a-Trifluorotoluene	88				%	70 - 130
8015M - Gasoline						
Gasoline	ND	1	50	15	ug/L	01/19/04 LZ
Surrogates						Units
a,a,a-Trifluorotoluene	88				%	55 - 200

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 491452
Matrix: WATER

Client Sample ID: TOC #049 MW-6
Date Sampled: 01/14/2004 Time Sampled: 15:25

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX + MTBE						
Benzene	ND	1	0.3	0.04	ug/L	01/19/04 LZ
Ethyl benzene	ND	1	0.3	0.02	ug/L	01/19/04 LZ
Methyl t - butyl ether	304	10	50.0	0.03	ug/L	01/19/04 LZ
Toluene	ND	1	0.3	0.02	ug/L	01/19/04 LZ
Xylene (total)	ND	1	0.6	0.06	ug/L	01/19/04 LZ
Surrogates						Units
a,a,a-Trifluorotoluene	95				%	70 - 130
8260B BTEX/MTBE Only						
Methyl-tert-butylether (MTBE)	180	1	1	0.18	ug/L	01/24/04 LB
8015M - Gasoline						
Gasoline	272	1	50	15	ug/L	01/19/04 LZ
Surrogates						Units
a,a,a-Trifluorotoluene	95				%	55 - 200

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 491453
Matrix: WATER

Client Sample ID: Trip Blank
Date Sampled: 01/14/2004 Time Sampled: 15:00

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX + MTBE						
Benzene	ND	1	0.3	0.04	ug/L	01/19/04 LZ
Ethyl benzene	ND	1	0.3	0.02	ug/L	01/19/04 LZ
Toluene	ND	1	0.3	0.02	ug/L	01/19/04 LZ
Xylene (total)	ND	1	0.6	0.06	ug/L	01/19/04 LZ
Surrogates					Units	Control Limits
a,a,a-Trifluorotoluene	90				%	70 - 130
8015M - Gasoline						
Gasoline	ND	1	50	15	ug/L	01/19/04 LZ
Surrogates					Units	Control Limits
a,a,a-Trifluorotoluene	90				%	55 - 200

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 491454

Client Sample ID: Laboratory Method Blank

Matrix: WATER

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX + MTBE						
Benzene	ND	1	0.3	0.04	ug/L	01/19/04 LZ
Ethyl benzene	ND	1	0.3	0.02	ug/L	01/19/04 LZ
Methyl t - butyl ether	ND	1	5	0.03	ug/L	01/19/04 LZ
Toluene	ND	1	0.3	0.02	ug/L	01/19/04 LZ
Xylene (total)	ND	1	0.6	0.06	ug/L	01/19/04 LZ
Surrogates						Units
a,a,a-Trifluorotoluene	90				%	70 - 130
8260B BTEX/MTBE Only						
Methyl-tert-butylether (MTBE)	ND	1	1	0.18	ug/L	01/23/04 LB
8015M - Gasoline						
Gasoline	ND	1	50	15	ug/L	01/19/04 LZ
Surrogates						Units
a,a,a-Trifluorotoluene	90				%	55 - 200

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
 ND = Not detected below indicated MDL, J=Trace



ASSOCIATED LABORATORIES LAB REQUEST RESULTS SUMMARY

Client: Thrifty Oil Company
 Jeff Suryakusuma
 13116 Imperial Hwy.
 P.O. Box 2128
 Santa Fe Springs, CA 90670

Lab Request: 123007
 Date Received: 1/16/2004
 Print Date: 01/26/2004

Project: Station #049
 3400 San Pablo Ave., Oakland

Sample ID.	Gasoline	Benzene	Toluene	Ethyl benzene	Xylene (total)	MTBE	MTBE by EPA8260
Laboratory	ND	ND	ND	ND	ND	ND	ND
TOC #049 MW-1	ND	ND	ND	ND	ND	ND	
TOC #049 MW-3	1160 ug/L	2.0 ug/L	2.2 ug/L	6.1 ug/L	7.8 ug/L	1510 ug/L	767 ug/L
TOC #049 MW-5	ND	ND	ND	ND	ND	8.2 ug/L	4.1 ug/L
TOC #049 MW-6	272 ug/L	ND	ND	ND	ND	304 ug/L	180 ug/L
TOC #049 MW-7	ND	ND	ND	ND	ND	ND	
Trip Blank	ND	ND	ND	ND	ND		

ND = Not Detected
 Blank Field = Component not analyzed by this method.

ASSOCIATED LABORATORIES
LCS REPORT FORM

QC Sample: LCS / LCSD

Matrix: WATER

Prep. Date: 01/19/04

Analysis Date: 01/19/04-01/20/04

LAB ID#'s in Batch: LR 123007, 123006, 123009

REPORTING UNITS = mg/L

PREPARATION BLANK / LAB CONTROL SAMPLE RESULTS

Test	Method	PREP. BLK	LCS	LCSD			
		Value	Result	TRUE	%Rec	Result	%Rec
Benzene	8021	ND	23.4	20	117	23.9	120
Toluene	8021	ND	22.9	20	115	23.0	115
Ethylbenzene	8021	ND	22.4	20	112	22.5	113
Xylenes	8021	ND	65.4	60	109	65.3	109

I.CS = Lab Control Sample Result

TRUE = True Value of LCS

L.LIMIT / H LIMIT = LCS Control Limits

L.Limit	H.Limit
80%	120%

SURROGATE RECOVERY

Sample No.	AAA-TFT
QC Limit	55-200
Method Blank	90
LCS	93
LCSD	97

AAA-TFT = *a,a,a*-Trifluorotoluene

ASSOCIATED LABORATORIES
LCS REPORT FORM

QC Sample: LCS / LCSD
 Matrix: WATER
 Prep. Date: 01/19/04
 Analysis Date: 01/19/04-01/20/04
 ID#'s in Batch: LR 123007, 123006, 123009
 Reporting Units = mg/L

PREPARATION BLANK / LAB CONTROL SAMPLE RESULTS

Test	Method		PREP BLK					
			Value	Result	True	%Rec	L.Limit	H.Limit
		LCS	ND	522	500	104	80%	120%
TPH	8015M-G	LCSD	ND	507	500	101	80%	120%

LCS Result = Lab Control Sample Result

True = True Value of LCS

L.Limit / H.Limit = LCS Control Limits

SURROGATE RECOVERY

Sample No.	AAA-TFT
QC Limit	55-200
Method Blank	90
LCS	146
LCSD	143

AAA-TFT = a,a,a-Trifluorotoluene

ASSOCIATED LABORATORIES
LCS REPORT FORM - METHOD 8260 / 624 / 524.2

QC Sample: LCS/LCSD - Water Samples

Analysis Date: 01/24/04

Applies to: LR 123007, 123009, 123049

Reporting Units = ug/L

Lab Controlled Spike / Lab Controlled Spike Duplicate

Test	Sample Result	Spike Added	LCS Spike	LCS Spk. Dup	%Rec LCS	%Rec LCS D	RPD	QC Limits	
								RPD	%REC
1,1-Dichloroethene	ND	50	44.12	43.40	88	87	2	22	59-172
MTBE	ND	50	40.57	40.49	81	81	0	24	62-137
Benzene	ND	50	48.67	45.38	97	91	7	24	62-137
Trichloroethene	ND	50	47.84	46.99	96	94	2	21	66-142
Toluene	ND	50	45.70	45.49	91	91	0	21	59-139
Chlorobenzene	ND	50	46.74	45.85	93	92	2	21	60-133

Method Blank = All ND

SURROGATE (QC Limits : 70-135)

Compounds	DBFM	1,2-DCA	Tol-d8	p-BFB
LCS	91	100	99	110
LCSD	92	97	100	112
BLANK # 3	99	115	99	120

ASSOCIATED LABORATORIES
LCS REPORT FORM - METHOD 8260 / 624 / 524.2

QC Sample: LCS/LCSD - Water Samples

Analysis Date: 01/23/04

Applies to: LR 123070, 122597, 123178, 123179, 123172, 123259, 123007

Reporting Units = ug/L


Lab Controlled Spike / Lab Controlled Spike Duplicate

Test	Sample Result	Spike Added	LCS Spike	LCS Spk. Dup	%Rec LCS	%Rec LCS D	RPD	QC Limits	
								RPD	%REC
1,1-Dichloroethene	ND	50	45.86	49.12	92	98	7	22	59-172
MTBE	ND	50	44.38	46.56	89	93	5	24	62-137
Benzene	ND	50	48.43	51.23	97	102	6	24	62-137
Trichloroethene	ND	50	46.15	47.97	92	96	4	21	66-142
Toluene	ND	50	46.45	48.86	93	98	5	21	59-139
Chlorobenzene	ND	50	46.16	48.91	92	98	6	21	60-133

Method Blank = All ND

SURROGATE (QC Limits : 70-135)

Compounds	DBFM	1,2-DCA	Tol-d8	p-BFB
LCS	93	97	97	114
LCSD	95	100	99	115
BLANK # 1	96	106	97	114
BLANK # 2	100	115	101	111



ASSOCIATED LABORATORIES

806 North Batavia - Orange, California 92868-1225 - 714/771-6900 FAX 714/538-1209

Cooler Receipt Form

Client: Thrifty oil Project: 049

Date Cooler Received: 1/16 Date Cooler Opened: 1/16

Was cooler scanned for presence of radioactivity ? Yes/No
If yes was radioactivity results above 25 cpm ? Yes/No

Was a shipper's packing slip attached to the cooler ? Yes/No

If the cooler had custody seal(s), were they signed and intact ? Yes/No/Na

Was the cooler packed with: Ice Ice Packs Bubble wrap
Styrofoam Paper None Other

Cooler Temperature: 2.3°C *

*cooler needs to be received @ 4°C with an acceptable range of 2°- 6 °C

If samples were hand delivered do they meet the temp. criteria, which should be @ 4°C with
an acceptable range of 2°- 6 °C ? Yes/No

If no explain: _____

Were all samples sealed in plastic bags ? Yes/No

Did all samples arrive intact ? If no, indicate below. Yes/No

Were all samples labeled correctly ? (ID's Dates, Times) If no, indicate below. Yes/No

Can the tests required be ran with the provided containers, If no indicate below. Yes/No

Was sufficient sample volume sent for all containers ? Yes/No

Were any VOA vials received with head space ? Yes/No/Na

Was the correct preservatives used ?
If no, see the pH log for a list of samples containers regarding pH Yes/No/Na

Any other important information: _____

Receiving Department: DNV Date: 1/16

Chain of Custody Record

123007

ASSOCIATED LABORATORIES

806 North Batavia • Orange, CA 92868
Phone: (714) 771-6900 • Fax: (714) 538-1209



Company	THIRTY OIC CO.		Phone	(662) 921-3581		A.L. Job No.	Page _____ of _____
Project Manager	JEFF JURY ARNUSUMA		Fax	(662) 921-7510			
Project Name	Q. W. S -		Project #	049			
Site Name and Address	3400 SAN PABLO AVE OAKLAND, CA. 94612						T0600101366
Sample ID	Lab ID	Date	Time	Matrix	Container Number/Size	Pres.	
1 MW-3		01-16-04	11:30	H ₂ O	3 VOA	1CL	X X X
2 MW-5		1	15:00	1	1	1	XX X
3 MW-1			15:05				XX X
4 MW-7			15:15				XX X
5 MW-6			15:25				XX X
6 TRIP BLANK			15:00		2 VOA		X X
7							
8							
9							
10							
11							
12							
13							
14							
15							

Sample Receipt - To Be Filled By Laboratory

Total Number of Containers	17	Property Cooled	Y / N / NA	Relinquished by Sampler:	THIRTY	1.	Relinquished by	GOLDFELD STATE ²	Relinquished by	3.
Custody Seals	Y / N / NA	Samples Intact	Y / N / NA	Signature:	<i>Elton</i>		Signature:	OVERNIGHT	Signature:	
Received in Good Condition	Y / N	Samples Accepted	Y / N	Printed Name:	<i>Elton</i>		Printed Name:		Printed Name:	
Turn Around Time				Date:	01-16-04	Time:	Date:	Time:	Date:	Time:
<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Rush				Received By:	GOLDFELD STATE ¹	Received By:	<i>M</i>	Received By:	<i>Z</i>	
<input type="checkbox"/> Same Day				Signature:	OVERNIGHT	Signature:	<i>M</i>	Signature:		
<input type="checkbox"/> 24 hrs.				Printed Name:		Printed Name:	<i>M</i>	Printed Name:		
<input type="checkbox"/> 48 hrs.				Date:	11/16	Time:	11:20	Date:	1-19-04	
<input type="checkbox"/> 72 hrs.				Time:				Time:	9:20	