

THRIFTY OIL CO.

Alameda County

JAN 17 2003

Environmental Health

Local #3871

RWQCB #01-1479

Global ID #T0600101366

Confirmation #2844481110

January 13, 2003

Ms. Susan Hugo
Alameda County Health Care Services
Department of Environmental Health
1131 Harbor Bay parkway, 2nd Floor
Alameda, CA 94502

RE: **Former Thrifty Oil Co. Station #063**
ARCO Products Company Station 39542
6125 Telegraph Avenue
Oakland, CA 94609
4th Quarter 2002, Status Report

Dear Ms. Hugo:

Presented herewith is the Fourth Quarter 2002, Status Report for former Thrifty Oil Co. Station #063 located at 6125 Telegraph Avenue, Oakland, California.

Thrifty proposes to connect well MW-4 to the existing remediation system to enhance the reduction of petroleum hydrocarbons in the groundwater. Once approval is received from the ACHCS, Thrifty will complete the work.

If you have any questions or comments, please contact the undersigned in this report or myself at (562) 921-3581.

Sincerely,



Chris Panaitescu
General Manager
Environmental Affairs

c: BP West Coast Products LLP; Ms. Kateri Luka
File



THRIFTY OIL CO.

January 13, 2003

Ms. Susan Hugo
Alameda County Health Care Services
Department of Environmental Health
1131 Harbor Bay Parkway, 2nd Floor
Alameda, CA 94502

Local #3871
RWQCB #01-1479
Global ID #T0600101366
Confirmation #2844481110

RE: **Former Thrifty Oil Co. Station #063**
ARCO Products Company Station #9542
6125 Telegraph Avenue
Oakland, CA
4th Quarter 2002, Status Report

Dear Ms. Hugo:

Presented herein is the Fourth Quarter 2002, Status Report prepared for former Thrifty Oil Co. (Thrifty) Station #063 located at 6125 Telegraph Avenue, Oakland, California (**Figure 1**). This report presents the results of the site monitoring and remedial activities in the fourth quarter of 2002. Thrifty has retained the services of Earth Management Company (EMC) to conduct quarterly monitoring and sampling, and remedial system monitoring activities at this site.

Groundwater Monitoring

Depth to groundwater is measured in each monitoring well on a quarterly basis. In general, groundwater occurred beneath the station at depths ranging from 14.20 feet below surface grade (bsg) in monitoring well MW-6 to 17.00 feet bsg in monitoring well MW-4 on October 30, 2002. A groundwater elevation contour map based on the October 30, 2002 data is presented in **Figure 2**. The groundwater flow is generally towards the west with a gradient of approximately 0.04 feet/foot.

Quarterly Groundwater Sampling

As part of the ongoing groundwater-monitoring program, groundwater samples were obtained from monitoring wells MW-1, MW-4, MW-5, and MW-6 on October 30, 2002. Recovery well MW-3 was sampled on October 7, 2002 as an influent stream into the groundwater remediation system. Groundwater samples were obtained by EMC and delivered in a chilled state following strict Chain-of-Custody procedures to a state-certified laboratory. The samples were analyzed for total petroleum hydrocarbons as gasoline (TPH-g), benzene, toluene, ethylbenzene, xylenes (BTEX) and methyl tert-butyl ether (MTBE) by EPA methods 8015M and 8021B. Laboratory analytical sampling results are provided in **Table 1**. Copies of the EMC Field Status Reports are presented in **Appendix A**, and copies of the laboratory analytical reports are contained in **Appendix B**.

TPH-g, BTEX, and MTBE concentrations appear in **Table 1**, and **Appendix B**. TPH-g, benzene, and MTBE isoconcentration maps results are presented in **Figures 3, 4, and 5**, respectively. Laboratory results indicate the highest concentrations of TPH-g, benzene, and MTBE were in monitoring well MW-4, with



concentrations of 17,300 ug/L, 400 ug/L, and 12,300 ug/L, respectively. The isoconcentration maps did not incorporate data from the treatment system influent well (MW-3), because it was sampled on a different day (October 7, 2002), than the other site wells.

Remediation Status

Site remedial activities were initiated in April 1991. Presently, the remediation system consists of a Groundwater Treatment System that extracts groundwater from monitoring well MW-3 with treatment utilizing activated carbon. System operational data is included in **Table 2** and **Appendix C**. During this reporting period, the groundwater treatment system processed approximately 63,240 gallons of groundwater from September 30, through December 30, 2002, and has treated approximately 2,019,319 gallons of groundwater since start up (April 1991) through December 2002. The system was operational throughout the quarter.

Inlet, intermediate 3, intermediate 2, intermediate 1, and outlet water samples were collected on October 7, 2002. The system water samples collected by EMC were sent to a state certified laboratory for analysis. The samples were analyzed for TPH-g, BTEX, and MTBE by EPA methods 8015 and 8021B. All outlet sample constituents were below the laboratory detection limit. Copies of the laboratory analytical reports are included in **Appendix D**.

Other Activities

With the high concentration of petroleum hydrocarbons in well MW-4, Thrifty proposes to connect well MW-4 to the existing remediation system in the 2nd and 3rd quarters 2002 reports to enhance the reduction of the petroleum hydrocarbons in the groundwater. Once approval is received from the ACHCS, Thrifty will complete this work.

The groundwater monitoring wells and the treatment unit will be monitored and sampled during the next quarter. All site monitoring/sampling data generated during the next quarter will be reported in the First Quarter 2003 monitoring report.


All interpretations expressed in this report are based solely upon the review of data collected by EMC, and Associated Laboratories.

Written by:

Reviewed by:


Raymond C. Friedrichsen, REA II
Project Manager, MBA
Senior Hydrogeologist


Larry Higinbotham
Registered Geologist #2407



FIGURES






FIGURE 1


SITE PLAN AND RECOVERY SYSTEM
 THRIFTY SERVICE STATION NO. 63
 6125 TELEGRAPH AVE.
 OAKLAND, CA




Groundwater Contour Map
 THRIFTY SERVICE STATION NO. 63
 6125 TELEGRAPH AVE.
 OAKLAND, CA



10/30/02 FIGURE 3
 TPH-g Isoconcentration Map ug/L
 THRIFTY SERVICE STATION NO. 63
 6125 TELEGRAPH AVE.
 OAKLAND, CA



Benzene Isoconcentration Map ug/L
 THRIFTY SERVICE STATION NO. 63
 6125 TELEGRAPH AVE.
 OAKLAND, CA



10/30/02
 FIGURE 5
 MTBE Isoconcentration Map ug/L
 THRIFTY SERVICE STATION NO. 63
 6125 TELEGRAPH AVE.
 OAKLAND, CA

TABLES

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #063, OAKLAND, CA

DATE SAMPLED	ANALYTICAL PARAMETERS						DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)	MTBE (ug/L)					
MONITORING WELL #MW-1											
11/21/86	-	-	-	-	-	-	15.42	NP	0.00	99.34	83.92
07/22/91	-	-	-	-	-	-	20.41	FILM	0.00	99.34	78.93
10/24/91	-	-	-	-	-	-	19.06	SHEEN	0.00	99.34	80.28
01/22/92	-	-	-	-	-	-	18.78	SHEEN	0.00	99.34	80.56
03/24/92	-	-	-	-	-	-	13.55	SHEEN	0.00	99.34	85.79
07/15/92	-	-	-	-	-	-	18.90	FILM	0.00	99.34	80.44
10/05/92	-	-	-	-	-	-	20.50	FILM	0.00	99.34	78.84
01/06/93	-	-	-	-	-	-	14.93	FILM	0.00	99.34	84.41
07/13/93	-	-	-	-	-	-	15.44	FILM	0.00	99.34	83.90
10/11/93	-	-	-	-	-	-	20.36	FILM	0.00	99.34	78.98
01/11/94	-	-	-	-	-	-	19.50	FILM	0.00	99.34	79.84
04/12/94	-	-	-	-	-	-	18.10	FILM	0.00	99.34	81.24
07/14/94	-	-	-	-	-	-	20.03	FILM	0.00	99.34	79.31
01/15/96	11,000	2,800	150	780	770	-	19.02	NP	0.00	99.34	80.32
04/15/96	17,000	3,600	330	1,500	3,400	-	18.82	NP	0.00	99.34	80.52
07/15/96	12,000	1,300	200	1,200	4,600	250	-	NP	-	-	-
10/09/96	-	-	-	-	-	-	14.87	NP	0.00	99.34	84.47
01/13/97	27,000	810	6,000	570	4,100	2,700	10.20	NP	0.00	99.34	89.14
04/14/97	2,900	3.0	2.9	<0.3	1.7	9,900	-	NP	-	-	-
07/07/97	5,200	0.57	0.57	<0.3	0.71	16,000	18.75	NP	0.00	99.34	80.59
10/16/97	680	<0.3	0.55	<0.3	<0.5	-	17.92	NP	0.00	99.34	81.42
01/07/98	42,000	980	2,800	1,200	5,200	1.3	9.80	NP	0.00	99.34	89.54
04/06/98	7,100	700	340	170	2,600	1,000	9.60	NP	0.00	99.34	89.74
07/14/98	19,000	2,100	400	890	5,800	1,600	13.70	NP	0.00	99.34	85.64
10/15/98	490	<0.3	<0.3	<0.3	<0.5	1,300	15.25	NP	0.00	99.34	84.09
01/20/99	350	<0.3	<0.3	<0.3	<0.5	* 670 / 820	12.20	NP	0.00	99.34	87.14
04/16/99	320	<0.3	<0.3	<0.3	<0.5	* 540 / 630	12.20	NP	0.00	99.34	87.14
07/14/99	290	<0.3	<0.3	<0.3	<0.5	*590 / 580	13.75	NP	0.00	99.34	85.59
10/07/99	130	<0.3	<0.3	<0.3	<0.5	270	12.15	NP	0.00	99.34	87.19
01/26/00	13,000	460	54	290	3,700	940	13.14	NP	0.00	99.34	86.20
04/19/00	546	<0.25	<0.25	<0.25	<0.5	*430 / 606	10.63	NP	0.00	99.34	88.71
05/26/00	<50	<0.3	<0.3	<0.3	<0.6	<5	9.11	NP	0.00	99.34	90.23
07/26/00	<50	<0.3	<0.3	<0.3	<0.6	<5	9.10	NP	0.00	99.34	90.24
10/25/00	<50	<0.18	<0.14	<0.18	<0.26	<0.24	9.08	NP	0.00	99.34	90.26
01/10/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	12.16	NP	0.00	99.34	87.18

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #063, OAKLAND, CA

DATE SAMPLED	ANALYTICAL PARAMETERS						DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)	MTBE (ug/L)					
04/23/01	18,100	740	55	650	4,000	*1,850 / 842	10.60	NP	0.00	99.34	88.74
07/16/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	9.07	NP	0.00	99.34	90.27
10/17/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	12.16	NP	0.00	99.34	87.18
01/23/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	15.23	NP	0.00	99.34	84.11
04/10/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	15.17	NP	0.00	99.34	84.17
07/24/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	16.71	NP	0.00	99.34	82.63
10/30/02	<50	2.2	<0.14	<0.18	<0.26	13	15.16	NP	0.00	99.34	84.18
MONITORING WELL #MW-2											
11/21/86	-	-	-	-	-	-	14.90	0.11	14.79	100.01	96.28
07/22/91	-	-	-	-	-	-	17.84	0.38	17.46	100.01	95.35
10/24/91	-	-	-	-	-	-	17.00	16.97	0.03	100.01	83.03
01/22/92	-	-	-	-	-	-	16.72	FILM	0.00	100.01	83.29
03/24/92	-	-	-	-	-	-	15.81	11.98	3.83	100.01	87.09
07/15/92	-	-	-	-	-	-	16.37	FILM	0.00	100.01	83.64
10/05/92	-	-	-	-	-	-	18.41	18.09	0.32	100.01	81.84
01/06/93	-	-	-	-	-	-	12.37	FILM	0.00	100.01	87.64
07/13/93	-	-	-	-	-	-	15.19	FILM	0.00	100.01	84.82
10/11/93	-	-	-	-	-	-	18.05	0.10	17.95	100.01	95.51
01/11/94	-	-	-	-	-	-	16.98	0.03	16.95	100.01	95.83
04/12/94	-	-	-	-	-	-	15.54	FILM	0.00	100.01	84.47
07/14/94	-	-	-	-	-	-	17.93	FILM	0.00	100.01	82.08
01/15/96	7,100	720	280	48	660	-	17.20	NP	0.00	100.01	82.81
04/15/96	11,000	600	59	420	870	-	17.26	NP	0.00	100.01	82.75
07/15/96	19,000	360	51	610	1,600	<250	-	-	-	-	-
10/09/96	-	-	-	-	-	-	14.42	NP	0.00	100.01	85.59
01/13/97	11,000	230	30	91	700	56	10.25	NP	0.00	100.01	89.76
04/14/97	141	1.2	0.33	0.44	<0.5	20	-	-	-	-	-
07/07/97	<50	<0.3	<0.3	<0.3	<0.5	<20	17.20	NP	0.00	100.01	82.81
10/16/97	<50	<0.3	<0.3	<0.3	<0.5	-	16.20	NP	0.00	100.01	83.81
01/07/98	-	-	-	-	-	-	16.26	16.18	0.08	100.01	83.81
Well Abandoned 1/30/98											

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #063, OAKLAND, CA

DATE SAMPLED	ANALYTICAL PARAMETERS						DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)	MTBE (ug/L)					
MONITORING WELL #MW-3											
11/21/86	-	100	5.1	<1.0	25	-	16.25	0.10	16.15	99.76	95.70
07/22/91	-	-	-	-	-	-	24.00	NP	0.00	99.76	75.76
10/24/91	-	-	-	-	-	-	18.10	NP	0.00	99.76	81.66
01/22/92	-	-	-	-	-	-	25.80	SHEEN	0.00	99.76	73.96
03/24/92	-	-	-	-	-	-	15.60	NP	0.00	99.76	84.16
07/15/92	-	-	-	-	-	-	25.10	FILM	0.00	99.76	74.66
10/05/92	-	-	-	-	-	-	25.20	NP	0.00	99.76	74.56
01/06/93	-	-	-	-	-	-	25.45	NP	0.00	99.76	74.31
07/13/93	-	-	-	-	-	-	14.24	NP	0.00	99.76	85.52
10/11/93	-	-	-	-	-	-	25.60	NP	0.00	99.76	74.16
01/11/94	-	-	-	-	-	-	25.90	NP	0.00	99.76	73.86
04/12/94	-	-	-	-	-	-	25.70	NP	0.00	99.76	74.06
07/14/94	-	-	-	-	-	-	25.10	NP	0.00	99.76	74.66
01/15/96	-	-	-	-	-	-	26.04	NP	0.00	99.76	73.72
04/15/96	-	-	-	-	-	-	21.03	NP	0.00	99.76	78.73
07/15/96	5,900	240	30	270	730	780	-	-	-	-	-
10/09/96	-	-	-	-	-	-	21.43	NP	0.00	99.76	78.33
01/13/97	-	-	-	-	-	-	11.20	NP	0.00	99.76	88.56
07/07/97	-	-	-	-	-	-	23.40	NP	0.00	99.76	76.36
10/16/97	-	-	-	-	-	-	22.30	NP	0.00	99.76	77.46
01/07/98	-	-	-	-	-	-	20.10	NP	0.00	99.76	79.66
07/14/98	-	-	-	-	-	-	14.40	NP	0.00	99.76	85.36
10/15/98	-	-	-	-	-	-	-	-	-	-	-
01/20/99	-	-	-	-	-	-	-	-	-	-	-
04/16/99	-	-	-	-	-	-	11.20	NP	0.00	99.76	88.56
07/14/99	5,600	9.6	1.3	3.5	8.1	*14,000 / 14,000	25.87	NP	0.00	99.76	73.89
10/07/99	-	-	-	-	-	-	15.40	NP	0.00	99.76	84.36
01/26/00	-	-	-	-	-	-	14.25	NP	0.00	99.76	85.51
04/19/00	-	-	-	-	-	-	14.20	NP	0.00	99.76	85.56
05/26/00	-	-	-	-	-	-	15.12	NP	0.00	99.76	84.64
07/26/00	-	-	-	-	-	-	14.30	NP	0.00	99.76	85.46
10/25/00	-	-	-	-	-	-	14.32	NP	0.00	99.76	85.44
01/10/01	-	-	-	-	-	-	13.46	NP	0.00	99.76	86.30
04/23/01	-	-	-	-	-	-	-	-	-	-	-
07/16/01	-	-	-	-	-	-	12.80	NP	0.00	99.76	86.96

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #063, OAKLAND, CA

DATE SAMPLED	ANALYTICAL PARAMETERS						DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)	MTBE (ug/L)					
10/17/01	-	-	-	-	-	-	15.30	NP	0.00	99.76	84.46
01/23/02	-	-	-	-	-	-	-	-	-	-	-
04/10/02	-	-	-	-	-	-	13.22	NP	0.00	99.76	86.54
07/24/02	-	-	-	-	-	-	14.32	NP	0.00	99.76	85.44
10/30/02	-	-	-	-	-	-	16.20	NP	0.00	99.76	83.56
MONITORING WELL #MW-4											
11/21/86	100,000	3,200	2,700	2,400	14,000	-	16.22	FILM	0.00	99.48	83.26
07/22/91	-	-	-	-	-	-	21.80	21.35	0.45	99.48	78.02
10/24/91	-	-	-	-	-	-	20.02	SHEEN	0.00	99.48	79.46
01/22/92	-	-	-	-	-	-	19.78	SHEEN	0.00	99.48	79.70
03/24/92	-	-	-	-	-	-	13.94	FILM	0.00	99.48	85.54
07/15/92	-	-	-	-	-	-	19.27	FILM	0.00	99.48	80.21
10/05/92	-	-	-	-	-	-	21.44	FILM	0.00	99.48	78.04
01/06/93	-	-	-	-	-	-	14.08	FILM	0.00	99.48	85.40
07/13/93	-	-	-	-	-	-	16.09	FILM	0.00	99.48	83.39
10/11/93	-	-	-	-	-	-	21.33	FILM	0.00	99.48	78.15
01/11/94	-	-	-	-	-	-	20.45	FILM	0.00	99.48	79.03
04/12/94	-	-	-	-	-	-	19.05	FILM	0.00	99.48	80.43
07/14/94	-	-	-	-	-	-	20.41	FILM	0.00	99.48	79.07
01/15/96	5,000	370	38	300	390	-	19.89	NP	0.00	99.48	79.59
04/15/96	38,000	300	78	540	470	-	19.62	NP	0.00	99.48	79.86
07/15/96	13,000	880	69	820	1,100	3,600	-	-	-	-	-
10/09/96	-	-	-	-	-	-	15.32	NP	0.00	99.48	84.16
01/13/97	47,000	2,500	2,500	1,100	2,800	70,000	10.80	NP	0.00	99.48	88.68
04/14/97	8,700	<0.3	0.45	<0.3	0.64	29,000	-	-	-	-	-
07/07/97	12,000	<0.3	<0.3	<0.3	<0.5	-	18.80	NP	0.00	99.48	80.68
10/16/97	770	<0.3	<0.3	<0.3	<0.5	-	17.76	NP	0.00	99.48	81.72
01/07/98	75,000	3,000	900	1,400	2,500	110	11.60	NP	0.00	99.48	87.88
04/08/98	18,000	1,200	130	710	1,400	22,000	10.10	NP	0.00	99.48	89.38
07/14/98	21,000	1,300	58	1,200	1,100	23,000	16.30	NP	0.00	99.48	83.18
10/15/98	9,100	1.1	0.62	<0.3	<0.5	30,000	16.90	NP	0.00	99.48	82.58
01/20/99	16,000	<0.3	0.91	0.72	1.4	* 43,000 / 42,000	15.35	NP	0.00	100.48	85.13
04/16/99	17,000	0.48	0.92	0.54	1.4	* 28,000 / 26,000	15.30	NP	0.00	100.48	85.18
07/14/99	8,500	<6	<6	<6	<10	*21,000 / 16,000	18.40	NP	0.00	100.48	82.08

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #063, OAKLAND, CA

DATE SAMPLED	ANALYTICAL PARAMETERS						DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)	MIBB (ug/L)					
10/07/99	2,500	<1.5	3.1	<1.5	<2.5	4,800	16.89	NP	0.00	100.48	83.59
01/26/00	9,900	350	9	460	460	2,800	12.62	NP	0.00	100.48	87.86
04/19/00	8,990	0.7	<0.25	<0.25	<0.5	*3,240 / 5,450	12.28	NP	0.00	100.48	88.20
05/26/00	94	<0.3	<0.3	<0.3	<0.6	*746 / 419	13.81	NP	0.00	100.48	86.67
07/26/00	<50	<0.3	<0.3	<0.3	<0.6	3,110 / 2,060	12.29	NP	0.00	100.48	88.19
10/25/00	2,480	<0.18	<0.14	<0.18	<0.26	*3,690 / 3,040	12.26	NP	0.00	100.48	88.22
01/10/01	<50	<0.18	2	<0.18	1	962	10.75	NP	0.00	100.48	89.73
04/23/01	482	<0.18	<0.14	<0.18	<0.26	*875 / 453	12.26	NP	0.00	100.48	88.22
07/16/01	71,700	9,440	12,600	514	8,980	*1,330 / 389	13.80	NP	0.00	100.48	86.68
10/17/01	13,500	1,950	425	<5.94	1,110	*829 / 329	16.87	NP	0.00	100.48	83.61
01/23/02	12,100	196	57	68	2,090	*688/738	12.28	NP	0.00	100.48	88.20
04/10/02	655	7	8	1	1	587	13.80	NP	0.00	100.48	86.68
07/24/02	17,400	<0.18	1.9	1.4	2.2	12,800	15.33	NP	0.00	100.48	85.15
10/30/02	17,300	400	47	748	131	12,300	17.00	NP	0.00	100.48	83.48
MONITORING WELL #MW-5											
11/21/86	<1,000	4.8	2.1	<0.5	7.4	-	16.10	NP	0.00	100.98	84.88
07/22/91	-	<0.5	1.6	<1.0	2.0	-	18.20	NP	0.00	100.98	82.78
10/24/91	-	-	-	-	-	-	17.67	NP	0.00	100.98	83.31
01/22/92	600	21.0	8.0	2.0	17.0	-	-	-	-	-	-
03/24/92	-	-	-	-	-	-	12.98	NP	0.00	100.98	88.00
07/15/92	<200	<0.5	<0.5	<0.5	<0.5	-	17.29	NP	0.00	100.98	83.69
10/05/92	-	-	-	-	-	-	18.92	NP	0.00	100.98	82.06
01/06/93	300	2.7	<0.5	1.3	26.0	-	13.12	NP	0.00	100.98	87.86
07/13/93	<100	1.1	0.5	1.0	1.5	-	16.15	NP	0.00	100.98	84.83
10/11/93	130	1.2	<0.3	<0.3	<0.6	-	18.75	NP	0.00	100.98	82.23
01/11/94	<50	1.5	<0.3	<0.3	<0.5	-	17.80	NP	0.00	100.98	83.18
04/12/94	<50	<0.3	<0.3	<0.3	<0.5	-	13.59	NP	0.00	100.98	87.39
07/14/94	<50	0.42	<0.3	<0.3	<0.5	-	18.26	NP	0.00	100.98	82.72
07/15/95	100	1.2	<0.5	0.8	<1	-	-	-	-	-	-
01/15/96	1,900	21	13	6.2	6.8	-	13.09	NP	0.00	100.98	87.89
04/15/96	250	5.1	2.7	1.7	1.1	-	13.16	NP	0.00	100.98	87.82
07/15/96	270	6.5	1.4	1.8	1.4	230	-	NP	-	-	-
10/09/96	-	-	-	-	-	-	15.37	NP	0.00	100.98	85.61
01/13/97	25,000	780	5,700	560	4,000	24,000	10.90	NP	0.00	100.98	90.08

TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #063, OAKLAND, CA

DATE SAMPLED	ANALYTICAL PARAMETERS						DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)	MIBE (ug/L)					
04/14/97	6,300	260	1,600	28	550	9,000	-	-	-	-	-
07/07/97	7,500	300	1,500	12	110	16,000	14.70	NP	0.00	100.98	86.28
10/16/97	4,600	<0.3	0.65	<0.3	<0.5	-	13.60	NP	0.00	100.98	87.38
01/07/98	2,700	33	11	37	580	7.3	10.97	NP	0.00	100.98	90.01
04/08/98	300	9.1	<0.3	<0.3	<0.5	650	10.90	NP	0.00	100.98	90.08
07/14/98	670	5.9	<0.3	<0.3	0.53	2,300	15.20	NP	0.00	100.98	85.78
10/15/98	<50	<0.3	<0.3	<0.3	<0.5	19	15.90	NP	0.00	100.98	85.08
01/20/99	<50	<0.3	<0.3	<0.3	<0.5	<5	15.20	NP	0.00	101.98	86.78
04/16/99	<50	<0.3	<0.3	<0.3	<0.5	<5	15.25	NP	0.00	101.98	86.73
07/14/99	<50	<0.3	<0.3	<0.3	<0.5	<5	15.96	NP	0.00	101.98	86.02
10/07/99	<50	<0.3	<0.3	<0.3	<0.5	<5	16.33	NP	0.00	101.98	85.65
01/26/00	<50	<0.3	<0.3	<0.3	<0.5	<5	14.80	NP	0.00	101.98	87.18
04/19/00	965	<0.25	<0.25	<0.25	<0.5	<5	10.97	NP	0.00	101.98	91.01
05/26/00	<50	<0.3	<0.3	<0.3	<0.6	<5	14.43	NP	0.00	101.98	87.55
07/26/00	<50	<0.3	<0.3	<0.3	<0.6	<5	14.02	NP	0.00	101.98	87.96
10/25/00	<50	<0.18	<0.14	<0.18	<0.26	<0.24	14.04	NP	0.00	101.98	87.94
01/10/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	14.80	NP	0.00	101.98	87.18
04/23/01	<50	<0.18	<0.14	<0.18	<0.26	*10 / 4.2	10.97	NP	0.00	101.98	91.01
07/16/01	3,360	430	603	53	429	*41 / 4.2	14.80	NP	0.00	101.98	87.18
10/17/01	<50	<0.18	<0.14	<0.18	<0.26	*16 / 5.2	16.71	NP	0.00	101.98	85.27
01/23/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	14.80	NP	0.00	101.98	87.18
04/10/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	14.42	NP	0.00	101.98	87.56
07/24/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	14.78	NP	0.00	101.98	87.20
10/30/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	15.93	NP	0.00	101.98	86.05
MONITORING WELL #MW-6											
11/21/86	<1,000	<2.0	<2.0	<2.0	<2.0	-	12.64	NP	0.00	99.44	86.80
07/22/91	-	-	-	-	-	-	-	-	-	-	-
01/22/92	<200	<0.5	<0.5	<0.5	1.5	-	-	-	-	-	-
03/24/92	-	-	-	-	-	-	10.04	NP	0.00	99.44	89.40
07/15/92	<200	<0.5	<0.5	<0.5	<0.5	-	13.29	NP	0.00	99.44	86.15
10/05/92	-	-	-	-	-	-	14.69	NP	0.00	99.44	84.75
01/06/93	<200	<0.5	<0.5	<0.5	<1.0	-	10.87	NP	0.00	99.44	88.57
07/13/93	<100	<0.5	<0.5	<0.5	<1.0	-	13.10	NP	0.00	99.44	86.34
10/11/93	<60	<0.3	<0.3	<0.3	<0.6	-	14.43	NP	0.00	99.44	85.01

**TABLE 1
GROUNDWATER DATA
THRIFTY OIL STATION #063, OAKLAND, CA**

DATE SAMPLED	ANALYTICAL PARAMETERS						DEPTH TO GROUNDWATER (feet)	DEPTH TO PRODUCT (feet)	PRODUCT THICKNESS (feet)	CASING ELEVATION (feet)	GROUNDWATER ELEVATION (feet)
	TPH (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	EthylBenzene (ug/L)	XYLENE (ug/L)	MTBE (ug/L)					
01/11/94	<50	<0.3	<0.3	<0.3	<0.5	-	13.56	NP	0.00	99.44	85.88
04/12/94	<50	<0.3	<0.3	<0.3	<0.3	-	12.10	NP	0.00	99.44	87.34
07/14/94	<50	<0.3	<0.3	<0.3	<0.3	-	14.16	NP	0.00	99.44	85.28
07/15/95	140	<0.5	<0.5	<0.5	<1	-	-	-	-	-	-
01/15/96	56	0.38	0.33	<0.3	<0.5	-	14.29	NP	0.00	99.44	85.15
04/15/96	96	4.5	<0.3	<0.3	0.53	-	14.32	NP	0.00	99.44	85.12
07/15/96	140	2.4	0.44	<0.3	0.70	110	-	-	-	-	-
10/09/96	-	-	-	-	-	-	12.09	NP	0.00	99.44	87.35
01/13/97	210	<0.3	1.2	<0.3	0.68	270	9.85	NP	0.00	99.44	89.59
04/14/97	<50	<0.3	<0.3	<0.3	<0.5	<20	-	-	-	-	-
07/07/97	<50	<0.3	<0.3	<0.3	<0.5	<20	14.20	NP	0.00	99.44	85.24
10/16/97	<50	<0.3	<0.3	<0.3	<0.5	-	13.10	NP	0.00	99.44	86.34
01/07/98	<50	<0.3	<0.3	<0.3	<0.5	0.10	9.80	NP	0.00	99.44	89.64
07/14/98	330	<0.3	<0.3	<0.3	<0.5	380	12.30	NP	0.00	99.44	87.14
10/15/98	<50	<0.3	<0.3	<0.3	<0.5	<5	14.30	NP	0.00	99.44	85.14
01/20/99	<50	0.47	<0.3	<0.3	<0.5	<5	13.60	NP	0.00	100.44	86.84
04/16/99	<50	<0.3	<0.3	<0.3	<0.5	<5	13.50	NP	0.00	100.44	86.94
07/14/99	<50	<0.3	<0.3	<0.3	<0.5	*5.4 / <5	14.65	NP	0.00	100.44	85.79
10/07/99	<50	<0.3	0.96	0.35	1.8	<5	15.39	NP	0.00	100.44	85.05
01/26/00	<50	<0.3	<0.3	<0.3	0.63	<5	13.85	NP	0.00	100.44	86.59
04/19/00	83.1	<0.25	<0.25	<0.25	<0.5	*11 / <5	9.65	NP	0.00	100.44	90.79
05/26/00	<50	<0.3	<0.3	<0.3	<0.6	<5	13.10	NP	0.00	100.44	87.34
07/26/00	<50	<0.3	<0.3	<0.3	<0.6	<5	12.35	NP	0.00	100.44	88.09
10/25/00	<50	<0.18	<0.14	<0.18	<0.26	*7 / 10	12.30	NP	0.00	100.44	88.14
01/10/01	<50	<0.18	<0.14	<0.18	<0.26	78	13.45	NP	0.00	100.44	86.99
04/23/01	<50	<0.18	<0.14	<0.18	<0.26	*9 / 4	9.65	NP	0.00	100.44	90.79
07/16/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	13.09	NP	0.00	100.44	87.35
10/17/01	<50	<0.18	<0.14	<0.18	<0.26	<0.24	15.37	NP	0.00	100.44	85.07
01/23/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	13.27	NP	0.00	100.44	87.17
04/10/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	13.07	NP	0.00	100.44	87.37
07/24/02	<50	<0.18	<0.14	<0.18	<0.26	<0.24	13.86	NP	0.00	100.44	86.58
10/30/02	<50	1.6	<0.14	<0.18	<0.26	6.4	14.20	NP	0.00	100.44	86.24

NOTE: NP = No free hydrocarbon product
 " - " = Not analyzed / Not available
 * MTBE 8020 / 8260

Benzene, toluene, ethylbenzene, and xylene analyzed by EPA method 8020
 Total petroleum hydrocarbons (TPH) analyzed by EPA method 8015 modified for gasoline
 Methyl-tert Butyl Ether (MTBE) analyzed by EPA method 8020 or 8260

TABLE 2
GROUNDWATER REMEDIATION SYSTEM MONITORING PROGRAM
 Thrifty Oil Co. Station No 063, OAKLAND, CA

Date	Totalizer (gallons)	Total/Cum. Discharge (gallons)	Flow (gal/day)	EFFLUENT (ug/L)						INFLUENT (ug/L)					
				TPH-g	B	T	E	X	MTBE	TPH-g	B	T	E	X	MTBE
4/8/91	1,669	0	-	-	<0.3	<0.3	<0.3	<0.9	-	-	1300	120	<7.5	1300	-
4/15/91	5,742	4,073	582	-	<0.3	<0.3	<0.3	<0.3	-	-	700	140	<15	500	-
4/22/91	10,240	8,571	643	-	<0.3	<0.3	<0.3	<0.9	-	-	850	100	34	860	-
4/29/91	15,510	13,841	753	-	<0.3	<0.3	<0.3	<0.9	-	-	220	8.4	<0.3	42	-
5/6/91	20,200	18,531	670	-	<0.3	<0.3	<0.3	<0.9	-	-	280	0.8	<0.3	56	-
5/13/91	24,430	22,761	604	-	<0.3	<0.3	<0.3	<0.9	-	-	190	5.6	<0.3	37	-
5/20/91	28,480	26,811	579	-	<0.3	<0.3	<0.3	<0.9	-	-	150	0.83	1.4	29	-
5/28/91	29,310	27,641	104	-	<0.3	<0.3	<0.3	<0.9	-	-	<0.3	<0.3	<0.3	<0.9	-
6/3/91	33,090	31,411	628	-	<0.3	<0.3	<0.3	<0.9	-	-	58	4	<0.3	33	-
6/10/91	36,939	35,270	551	-	<0.3	<0.3	<0.3	<0.9	-	-	45	<0.3	<0.3	16	-
6/17/91	40,673	39,004	533	-	<0.3	<0.3	<0.3	<0.9	-	-	69	4.9	0.9	21	-
6/24/91	44,453	42,784	540	-	<0.3	<0.3	<0.3	<0.9	-	-	5.4	2	<0.3	6.6	-
7/1/91	48,173	46,504	531	-	<0.5	<0.5	<1	<1	-	-	14	15	<1	9.1	-
7/8/91	51,681	50,012	501	-	<0.5	<0.5	<1	<1	-	-	<0.5	<0.5	<1	6.9	-
7/15/91	55,186	53,517	501	-	<0.5	<0.5	<1	<1	-	-	<0.5	0.6	<1	6.3	-
7/22/91	62,150	60,481	995	-	<0.5	<0.5	<1	<1	-	-	<0.5	<0.5	<1	2.6	-
7/29/91	62,150	60,481	-	-	<0.5	<0.5	<1	<1	-	-	<0.5	<0.5	1.2	1.9	-
8/5/91	63,241	61,572	156	-	<0.5	<0.5	<1	<1	-	-	<0.5	<0.5	<1	<1	-
8/12/91	66,091	64,422	407	-	<0.5	<0.5	<1	<1	-	-	2.6	<0.5	<1	1.2	-
8/19/91	67,649	65,980	223	-	<0.5	<0.5	<1	<1	-	-	20	3.3	2.8	70	-
8/26/91	70,514	68,845	409	-	<0.5	<0.5	<1	<1	-	-	<0.5	<0.5	1.2	1.9	-
9/9/91	70,564	68,895	4	-	<0.5	<0.5	<1	<1	-	-	270	10	1.3	6.9	-
9/16/91	73,526	71,857	423	System shut down due to damaged compressor pump						-	-	-	-	-	-
10/7/91	73,526	71,857	-	-	<0.5	<0.5	<1	<1	-	-	<0.5	<0.5	<1	3.8	-
10/14/91	74,516	72,847	141	-	<0.5	<0.5	<1	<1	-	-	60	1.1	<1	2.3	-
10/21/91	76,091	74,422	225	-	<0.5	<0.5	<1	<1	-	-	<0.5	<0.5	<1	<1	-
10/28/91	83,242	81,573	1,022	-	<0.5	<0.5	<1	<1	-	-	<0.5	<0.5	<1	1.4	-
11/3/91	83,242	81,573	-	-	<0.5	<0.5	<1	<1	-	-	<0.5	<0.5	<1	3.1	-
11/11/91	84,351	82,682	139	-	<0.5	<0.5	<1	<1	-	-	99	1.9	<1	1.4	-
11/18/91	85,647	83,978	185	-	<0.5	<0.5	<1	<1	-	-	42	1	1	10	-
11/25/91	89,512	87,843	552	-	<0.5	<0.5	<1	<1	-	-	<0.5	<0.5	<1	3.9	-
12/3/91	93,407	91,738	487	-	<0.5	<0.5	<1	<1	-	-	<0.5	<0.5	<1	3.8	-
12/9/91	96,210	94,541	467	-	<0.5	<0.5	<1	<1	-	-	<0.5	<0.5	<1	3.2	-
12/16/91	99,045	97,376	405	-	<0.5	<0.5	<0.5	<0.5	-	-	1.3	<0.5	<0.5	1.5	-
12/23/91	102,334	100,665	470	-	<0.5	<0.5	<0.5	<0.5	-	-	1.7	<0.5	<0.5	2.4	-
12/30/91	105,124	103,455	399	-	<0.5	<0.5	<0.5	<0.5	-	-	22.6	1.2	0.7	4.9	-
1/15/92	115,691	114,022	660	-	<0.5	<0.5	<0.5	<0.5	-	-	130	11	<0.5	50	-
2/10/92	124,846	123,177	352	-	<0.5	<0.5	<0.5	<0.5	-	-	20	0.51	<0.5	3.6	-
3/9/92	149,965	148,296	897	<200	<0.5	<0.5	<0.5	<0.5	-	12,000	2,100	400	170	2,100	-
4/13/92	168,567	166,898	531	<200	<0.5	<0.5	<0.5	<0.5	-	2,100	280	3.9	<2.5	98	-
5/11/92	187,170	185,501	664	<200	<0.5	0.7	<0.5	<0.5	-	<200	<0.5	<0.5	<0.5	<0.5	-
6/8/92	190,490	188,821	119	-	<0.5	<0.5	<0.5	<0.5	-	-	44	3.7	0.7	64	-
7/6/92	197,080	195,411	235	-	-	-	-	-	-	-	-	-	-	-	-
7/13/92	197,890	196,221	116	-	<0.5	<0.5	<0.5	<0.5	-	-	<0.5	<0.5	<0.5	<0.5	-

TABLE 2
GROUNDWATER REMEDIATION SYSTEM MONITORING PROGRAM
 Thrifty Oil Co. Station No 063, OAKLAND, CA

Date	Totalizer (gallons)	Total/Cum. Discharge (gallons)	Flow (gal/day)	EFFLUENT (ug/L)						INFLUENT (ug/L)					
				TPH-g	B	T	E	X	MTBE	TPH-g	B	T	E	X	MTBE
7/13/92	197,890	196,221	-	System shut down for repair of electrical motor											
8/10/92	197,890	196,221	-	Restart the system											
8/17/92	201,300	199,631	487	-	<0.5	<0.5	<0.5	<0.5	-	-	<0.5	<0.5	<0.5	<0.5	-
9/14/92	209,647	207,978	298	-	<0.5	<0.5	<0.5	<1	-	-	<0.5	<0.5	<0.5	<1	-
10/5/92	217,360	215,691	367	<200	<0.5	<0.5	<0.5	<1	-	<200	<0.5	<0.5	<0.5	<1	-
11/09/92	225,780	224,111	241	-	<0.5	<0.5	<0.5	<1	-	-	1.1	0.5	<0.5	10	-
12/14/92	243,048	241,379	493	-	<0.5	<0.5	<0.5	<1	-	-	720	46	<10	1,700	-
01/04/93	252,510	250,841	451	-	<0.5	<0.5	<0.5	<1	-	-	400	32	<25	520	-
02/15/93	266,210	264,541	326	<200	<0.5	<0.5	<0.5	<1	-	9,000	1,400	330	260	1,200	-
03/08/93	269,330	267,661	149	-	<0.5	<0.5	<0.5	<1	-	-	1,100	150	7.5	1,000	-
04/26/93	271,290	269,621	40	<100	<0.5	<0.5	<0.5	<1	-	7,200	1,100	100	25	780	-
04/26/93	271,290	269,621	-	System shut down to repair											
07/15/93	272,577	270,908	16	Restart the system											
08/11/93	284,230	282,561	432	-	<0.5	<0.5	<0.5	<1	-	-	1.3	<0.5	<0.5	1.6	-
09/16/93	298,832	297,163	406	<60	<0.3	<0.3	<0.3	<0.6	-	<60	<0.3	<0.3	<0.3	<0.6	-
10/08/93	305,641	303,972	310	-	-	-	-	-	-	-	-	-	-	-	-
10/11/93	307,068	305,399	476	<60	<0.3	<0.3	<0.3	<0.6	-	<60	<0.3	<0.3	<0.3	<0.6	-
10/15/93	308,495	306,826	357	-	-	-	-	-	-	-	-	-	-	-	-
11/12/93	318,203	316,534	347	<50	<0.3	<0.3	<0.3	<0.5	-	<50	<0.3	<0.3	<0.3	<0.5	-
12/10/93	329,947	328,278	419	<50	<0.3	<0.3	<0.3	<0.5	-	<50	<0.3	<0.3	<0.3	<0.5	-
01/13/94	345,860	344,191	468	-	<0.3	<0.3	<0.3	<0.5	-	-	<0.3	<0.3	<0.3	<0.5	-
02/10/94	359,662	357,993	493	-	<0.3	<0.3	<0.3	<0.5	-	-	430	41	36	480	-
02/18/94	618,620	-	-	Changed air filters The water flowmeter jumped from 359,662 to 618,620											
03/10/94	627,540	366,913	446	-	<0.3	<0.3	<0.3	<0.5	-	-	<0.3	<0.3	<0.3	7.7	-
04/14/94	645,330	384,703	508	<50	<0.3	<0.3	<0.3	<0.5	-	170	1.5	<0.3	0.38	0.73	-
05/19/94	653,520	392,893	234	<50	<0.3	<0.3	<0.3	<0.5	-	1,500	46	4.1	0.5	84	-
06/16/94	664,015	403,388	375	<50	<0.3	<0.3	<0.3	<0.5	-	12,000	860	37	<13	1,800	-
07/14/94	672,760	412,123	312	<50	<0.3	<0.3	<0.3	<0.5	-	<50	<0.3	<0.3	<0.3	<0.5	-
08/11/94	681,920	421,293	328	<50	<0.3	<0.3	<0.3	<0.5	-	<50	<0.3	<0.3	<0.3	<0.5	-
09/15/94	692,083	431,456	290	<50	<0.3	<0.3	<0.3	<0.5	-	<50	<0.3	<0.3	<0.3	<0.5	-
10/17/94	699,979	439,352	247	<50	<0.3	<0.3	<0.5	<0.5	-	<50	<0.3	<0.3	<0.5	<0.5	-
11/14/94	712,539	451,912	449	<50	<0.3	<0.3	<0.5	<0.5	-	<50	<0.3	<0.3	<0.5	<0.5	-
12/19/94	734,620	473,993	631	<50	<0.3	<0.3	<0.5	<0.5	-	<50	<0.3	<0.3	<0.5	<0.5	-
01/10/95	742,072	481,445	339	-	-	-	-	-	-	-	-	-	-	-	-
01/16/95	742,074	481,447	0	System shut down for repair of compressor pump											
02/06/95	742,074	481,447	-	Restart the system											
02/13/95	744,063	483,436	284	<50	<0.3	<0.3	<0.5	<0.5	-	<50	<0.3	<0.3	<0.5	<0.5	-
03/13/95	758,930	498,303	531	<100	<0.5	<0.5	<0.5	<1	-	1,300	<0.5	<0.5	<0.5	<1	-
04/17/95	768,276	507,649	267	<100	<0.5	<0.5	<0.5	<1	-	6,200	410	73	97	280	-
05/15/95	780,716	520,089	444	<100	<0.5	<0.5	<0.5	<1	-	1,300	0.6	<0.5	<0.5	<1	-
06/12/95	784,514	523,887	136	<100	<0.5	<0.5	<0.5	<1	-	<100	<0.5	<0.5	<0.5	<1	-
07/18/95	794,158	533,531	268	<100	<0.5	<0.5	<0.5	<1	-	1,100	<0.5	<0.5	<0.5	<1	-
08/14/95	795,216	534,589	39	<100	<0.5	<0.5	<0.5	<1	-	170	<0.5	<0.5	<0.5	<1	-
09/06/95	797,631	537,004	105	<100	<0.5	<0.5	<0.5	<1	-	1,320	<0.5	<0.5	<0.5	<1	-

TABLE 2
GROUNDWATER REMEDIATION SYSTEM MONITORING PROGRAM
 Thrifty Oil Co. Station No 063, OAKLAND, CA

Date	Totalizer (gallons)	Total/Cum. Discharge (gallons)	Flow (gal/day)	EFFLUENT (ug/L)						INFLUENT (ug/L)					
				TPH-g	B	T	E	X	MTBE	TPH-g	B	T	E	X	MTBE
10/17/95	800,316	539,689	65	<100	<0.5	<0.5	<0.5	<1	-	2,400	26	2.7	3.9	46	-
11/20/95	806,264	545,637	175	150	<0.3	<0.3	<0.3	<0.5	-	450	0.31	<0.3	<0.3	<0.5	-
12/11/95	809,236	548,609	142	300	<0.3	<0.3	<0.3	0.59	-	470	<0.3	<0.3	<0.3	<0.5	-
01/15/96	822,734	562,107	386	510	<0.3	<0.3	<0.3	<0.5	-	900	0.39	<0.3	<0.3	<0.5	-
02/19/96	848,213	587,586	728	800	<0.3	0.57	<0.3	0.83	-	1700	23	3.7	<0.3	80	-
03/19/96	849,587	588,960	47	930	<0.3	<0.3	<0.3	<0.5	-	1,600	5.5	1.4	<0.3	94	-
04/15/96	852,042	591,415	91	990	<0.3	<0.3	<0.3	<0.5	-	1,100	0.43	<0.3	<0.3	<0.5	-
05/13/96	890,214	629,587	1,363	840	<0.3	<0.3	<0.3	<0.5	-	910	<0.3	<0.3	<0.3	<0.5	-
05/13/96	890,214	629,587	-	System shut down for carbon change											
06/14/96	890,214	629,587	-	Restart the system											
06/18/96	890,818	630,191	151	<50	<0.3	<0.3	<0.3	<0.5	-	1,000	92	8.7	3.4	55	-
07/01/96	892,781	632,154	151	-	-	-	-	-	-	-	-	-	-	-	-
07/08/96	894,210	633,583	204	System shut down due to burglary and damaged air compressor											
08/05/96	894,210	633,583	-	Restart the system											
08/13/96	896,220	635,593	251	<50	<0.3	<0.3	<0.3	<0.5	-	3,500	160	110	220	650	-
09/23/96	899,410	638,783	78	<50	<0.3	<0.3	<0.3	<0.5	-	<50	0.49	<0.3	<0.3	<0.5	-
10/09/96	899,845	639,218	27	<50	<0.3	<0.3	<0.3	<0.5	-	730	1.7	0.42	2.1	2.5	-
11/11/96	901,348	640,721	46	<50	<0.3	<0.3	<0.3	<0.5	-	81	<0.3	<0.3	<0.3	<0.5	-
12/09/96	901,576	640,949	8	<50	<0.3	<0.3	<0.3	<0.5	-	<50	<0.3	<0.3	<0.3	<0.5	-
01/13/97	904,630	644,003	87	<50	<0.3	<0.3	<0.3	<0.5	-	13,000	590	250	180	850	-
02/10/97	912,610	651,983	285	82	<0.3	0.38	<0.3	<0.5	-	700	0.92	0.75	<0.3	4.1	-
03/10/97	921,020	660,393	300	<50	<0.3	<0.3	<0.3	<0.5	-	600	<0.3	<0.3	<0.3	<0.5	-
04/14/97	932,410	671,783	325	<50	<0.3	<0.3	<0.3	<0.5	-	4,400	<0.3	<0.3	<0.3	<0.5	-
05/12/97	941,028	680,401	308	<50	<0.3	<0.3	<0.3	<0.5	-	5,600	7.3	0.32	<0.3	17	-
06/23/97	943,183	682,556	51	-	-	-	-	-	-	-	-	-	-	-	-
07/07/97	945,821	685,194	188	<50	<0.3	<0.3	<0.3	<0.5	-	1,500	3.4	<0.3	<0.3	26	-
08/04/97	951,020	690,393	186	-	-	-	-	-	-	-	-	-	-	-	-
09/02/97	957,933	697,306	238	System shut down due to stolen air compressor											
10/06/97	961,030	700,403	91	-	-	-	-	-	-	-	-	-	-	-	-
10/16/97	961,077	700,450	5	<50	<0.3	<0.3	<0.3	<0.5	-	550	<0.3	<0.3	<0.3	<0.5	-
11/17/97	970,920	710,293	308	-	-	-	-	-	-	-	-	-	-	-	-
12/23/97	986,016	725,389	419	-	-	-	-	-	-	-	-	-	-	-	-
01/05/98	991,520	730,893	423	-	-	-	-	-	-	-	-	-	-	-	-
01/07/98	992,365	731,738	423	<50	<0.3	<0.3	<0.3	<0.5	-	65,000	690	8,400	3,100	20,000	-
02/02/98	996,874	736,247	173	-	-	-	-	-	-	-	-	-	-	-	-
02/09/98	-	-	-	System shut down due to the UST replacement and station remodeling											
02/17/98	-	-	-	<50	<0.3	<0.3	<0.3	<0.5	-	35,000	150	<15	<15	8,900	-
04/13/98	53,000	736,247	-	Replaced carbons and restarted system with new meter (53,000)											
4/13 - 6/1/98	-	-	-	System was undergoing several maintenance / piping / hose replacement											
06/01/98	53,780	737,027	16	-	-	-	-	-	-	-	-	-	-	-	-
07/14/98	56,905	740,152	73	<50	<0.3	<0.3	<0.3	<0.5	-	3,500	14	0.56	<0.3	26	-
08/13/98	59,426	742,673	84	-	-	-	-	-	-	-	-	-	-	-	-
09/11/98	62,356	745,603	101	-	-	-	-	-	-	-	-	-	-	-	-
10/15/98	62,714	745,961	11	<50	<0.3	<0.3	<0.3	<0.5	-	2,200	21	4	<0.3	100	-

TABLE 2
GROUNDWATER REMEDIATION SYSTEM MONITORING PROGRAM
 Thrifty Oil Co. Station No 063, OAKLAND, CA

Date	Totalizer (gallons)	Total/Cum. Discharge (gallons)	Flow (gal/day)	EFFLUENT (ug/L)						INFLUENT (ug/L)						
				TPH-g	B	T	E	X	MTBE	TPH-g	B	T	E	X	MTBE	
11/06/98	62,952	746,199	11	-	-	-	-	-	-	-	-	-	-	-	-	
11/20/98	-	-	-	System shut down for flowmeter replacement						-	-	-	-	-	-	-
12/01/98	0.0	746,199	-	Restart the system with flowmeter at 000						-	-	-	-	-	-	-
12/31/98	5,340.0	751,539	178	-	-	-	-	-	-	-	-	-	-	-	-	
01/11/99	15,020.0	761,219	880	System shut down						-	-	-	-	-	-	-
1/11 - 2/1/99	-	-	-	System was undergoing maintenance for the compressor						-	-	-	-	-	-	-
01/20/99	-	-	-	<50	<0.3	<0.3	<0.3	<0.5	-	110	0.43	0.42	<0.3	<0.5	260	
02/01/99	15,600.0	761,799	28	Restart system						-	-	-	-	-	-	-
02/12/99	22,840.0	769,039	658	-	-	-	-	-	-	-	-	-	-	-	-	
02/22/99	22,840.0	769,039	-	System shut down for carbon canister replacement						-	-	-	-	-	-	-
03/26/99	22,840.0	769,039	-	Restart the system						-	-	-	-	-	-	-
03/31/99	24,620.0	770,819	356	-	-	-	-	-	-	-	-	-	-	-	-	
04/16/99	29,605.0	775,804	312	<50	<0.3	<0.3	<0.3	<0.5	<5	<50	<0.3	<0.3	<0.3	<0.5	<5	
05/11/99	36,010.0	782,209	256	-	-	-	-	-	-	-	-	-	-	-	-	
05/25/99	46,000.0	792,199	714	System shut down due to carbon canister leaking						-	-	-	-	-	-	-
09/02/99	46,000.0	792,199	-	Restart system						-	-	-	-	-	-	-
09/17/99	46,217.0	792,416	14	-	-	-	-	-	-	-	-	-	-	-	-	
10/07/99	46,809.0	793,008	30	<50	<0.3	<0.3	<0.3	<0.5	11	65	<0.3	<0.3	<0.3	<0.5	120	
10/21/99	47,278.0	793,477	34	System shut down for carbon change						-	-	-	-	-	-	-
11/24/99	47,283.0	793,482	0	Restart system						-	-	-	-	-	-	-
12/30/99	49,386.0	795,585	58	-	-	-	-	-	-	-	-	-	-	-	-	
01/26/00	50,569.0	796,768	44	<50	<0.3	<0.3	<0.3	<0.5	-	<50	<0.3	<0.3	<0.3	<0.5	-	
02/25/00	51,983.0	798,182	47	-	-	-	-	-	-	-	-	-	-	-	-	
03/24/00	54,603.0	800,802	94	-	-	-	-	-	-	-	-	-	-	-	-	
04/19/00	56,754.0	802,953	83	<5	<0.25	<0.25	<0.25	<0.5	-	<50	1.3	<0.25	<0.25	<0.5	<5	
04/30/00	58,022.0	804,221	115	-	-	-	-	-	-	-	-	-	-	-	-	
05/26/00	60,086.0	806,285	79	-	-	-	-	-	-	923	<0.6	2	85	80	8,350/4,810	
06/16/00	61,889.0	808,088	86	<50	<0.3	<0.3	<0.3	<0.6	<5	3,820	<0.3	<0.3	<0.3	<0.6	3,740	
07/26/00	65,987.0	812,186	102	<50	<0.3	<0.3	<0.3	<0.6	<5	<50	<0.3	<0.3	<0.3	<0.6	<5	
08/25/00	68,630.0	814,829	88	-	-	-	-	-	-	-	-	-	-	-	-	
09/29/00	85,661.0	831,860	487	-	-	-	-	-	-	-	-	-	-	-	-	
10/13/00	96,212.0	842,411	754	-	-	-	-	-	-	-	-	-	-	-	-	
10/20/00	99,700.0	845,899	498	Shut down system for QWS and replaced flowmeter starting at 000 (old meter estimated at 99,700) System restarted on 10/25/00 after QWS												
10/25/00	0.0	845,899	-	<50	<0.18	<0.14	<0.18	<0.26	<0.24	17,100	111	121	141	972	998	
10/27/00	2,160	848,059	1,080	-	-	-	-	-	-	-	-	-	-	-	-	
11/03/00	7,420	853,319	751	-	-	-	-	-	-	-	-	-	-	-	-	
11/24/00	16,560	862,459	435	-	-	-	-	-	-	-	-	-	-	-	-	
12/22/00	51,530	897,429	1,249	-	-	-	-	-	-	-	-	-	-	-	-	
01/10/01	54,520	900,419	157	<50	<0.18	<0.14	<0.18	<0.26	<0.24	10,000	384	223	<0.18	1,330	11,600	
02/19/01	99,640	945,539	1,128	-	-	-	-	-	-	-	-	-	-	-	-	
03/19/01	144,170	990,069	1,590	-	-	-	-	-	-	-	-	-	-	-	-	
04/09/01	167,050	1,012,949	1,090	378	<0.18	<0.14	<0.18	<0.26	475	4,040	191	4	42	38	4,990	
04/13/01	169,210	1,015,109	540	Shut down system for replacement of carbon drums						-	-	-	-	-	-	-
04/18/01	169,210	1,015,109	-	Restart system						-	-	-	-	-	-	-

TABLE 2
GROUNDWATER REMEDIATION SYSTEM MONITORING PROGRAM
 Thrifty Oil Co. Station No 063, OAKLAND, CA

Date	Totalizer (gallons)	Total/Cum. Discharge (gallons)	Flow (gal/day)	EFFLUENT (ug/L)						INFLUENT (ug/L)					
				TPH-g	B	T	E	X	MTBE	TPH-g	B	T	E	X	MTBE
04/23/01	177,140	1,023,039	1,586	93	<0.18	<0.14	<0.18	<0.26	132	1,400	<0.18	<0.14	<0.18	<0.26	3,240
05/02/01	186,800	1,032,699	1,073	Shut down system for carbon change											
05/18/01	186,900	1,032,799	6	Restart system											
05/30/01	200,850	1,046,749	1,163	<50	<0.18	<0.14	<0.18	<0.26	<0.24	3,100	15	<0.14	1	2	*8,510 / 5,780
06/25/01	266,720	1,112,619	2,533	-	-	-	-	-	-	-	-	-	-	-	-
07/09/01	278,760	1,124,659	860	<50	<0.18	<0.14	<0.18	<0.26	<0.24	748	15	<0.14	2	2.7	1,440
08/13/01	399,700	1,245,599	3,455	-	-	-	-	-	-	-	-	-	-	-	-
09/24/01	451,240	1,297,139	1,227	-	-	-	-	-	-	-	-	-	-	-	-
10/01/01	488,310	1,334,209	5,296	<50	<0.18	<0.14	<0.18	<0.26	<0.24	956	1.2	<0.14	<0.18	<0.26	878
11/12/01	636,260	1,482,159	3,523	-	-	-	-	-	-	-	-	-	-	-	-
12/31/01	674,080	1,519,979	772	-	-	-	-	-	-	-	-	-	-	-	-
01/14/02	688,450	1,534,349	1,026	<50	<0.18	<0.14	<0.18	<0.26	<0.24	232	1	1	<0.18	<0.26	363
02/18/02	738,420	1,584,319	1,428	-	-	-	-	-	-	-	-	-	-	-	-
03/25/02	814,570	1,660,469	2,176	-	-	-	-	-	-	-	-	-	-	-	-
04/08/02	828,510	1,674,409	996	<50	<0.18	<0.14	<0.18	<0.26	<0.24	105	<0.18	<0.14	<0.18	<0.26	157
04/22/02	895,910	1,741,809	4,814	-	-	-	-	-	-	-	-	-	-	-	-
05/06/02	895,920	1,741,819	1	System off, Restart											
05/13/02	929,130	1,775,029	4,744	-	-	-	-	-	-	-	-	-	-	-	-
06/03/02	-	-	-	-	<0.5	<0.7	<0.8	<3.3	-	Outlet sampling results from EBMUD (sample collected by EBMUD inspector)					
06/03/02	593,740	1,839,539	3,077	<50	<0.18	<0.14	<0.18	<0.26	<0.24	Split-sample results (sample collected by us)					
06/24/02	1,001,590	1,847,489	374	-	-	-	-	-	-	-	-	-	-	-	-
07/08/02	-	-	-	<50	<0.18	<0.14	<0.18	<0.26	<0.24	4,710	1	1.2	<0.18	2	6,980
07/12/02	1,051,430	1,897,329	2,769	-	-	-	-	-	-	-	-	-	-	-	-
07/29/02	1,052,820	1,898,719	82	System shut down for carbon change											
08/16/02	1,052,820	1,898,719	-	Restart											
08/30/02	1,069,050	1,914,949	1,159	-	-	-	-	-	-	-	-	-	-	-	-
09/20/02	-	-	-	Sample results from EBMUD nor received yet						Outlet sampling results from EBMUD (sample collected by EBMUD inspector)					
09/20/02	1,106,410	1,952,309	1,779	<50	<0.1	<0.15	<0.06	-	-	Split-sample results (sample collected by us, analysis by EPA 624 & 8015M)					
09/30/02	1,110,180	1,956,079	377	-	-	-	-	-	-	-	-	-	-	-	-
10/07/02	1,114,720	1,960,619	649	<50	<0.18	<0.14	<0.18	<0.26	<0.24	128	<0.18	<0.14	<0.18	<0.26	95
10/28/02	1,127,540	1,973,439	610	-	-	-	-	-	-	-	-	-	-	-	-
11/25/02	1,149,730	1,995,629	793	-	-	-	-	-	-	-	-	-	-	-	-
12/20/02	1,166,840	2,012,739	684	-	-	-	-	-	-	-	-	-	-	-	-
12/30/02	1,173,420	2,019,319	658	-	-	-	-	-	-	-	-	-	-	-	-

WD PERMIT LIMITS:	NE	5.0	5.0	5.0	5.0	NE
--------------------------	----	-----	-----	-----	-----	----

Note: < = less than laboratory detection level indicated
 - = no sample / not analyzed
 NE = Permit Limit not established
 In February 2000, the total cumulative discharge amount was corrected to reflect all system maintenance and flowmeter changeouts since the startup of the system. The total number may be different from previous versions of this table

TPH is analyzed by EPA Method 8015 M
 BTEX is analyzed by EPA Method 602 or 8020
 *MTBE 8020/8260

APPENDIX A



PROJECT STATUS REPORT
 THRIFTY OIL CO., S.S. #063
 6125 TELEGRAPH AVENUE
 OAKLAND, CA 94609
 DATE: 10.30.02

OBSERVATION WELLS

NO.	DTW	DTP	PT	DTB	DIA.	ODORS			F/P	
						YES	NO	S	YES	NO
MONTHLY										
MW-1	15.16			28.96	2"		X			X
MW3	16.20			28.23	6"		X			X
MW-4	17.00			29.10	2"		X			X
MW-5	15.93			26.26	4"		X			X
MW-6	14.20			26.83	4"		X			X

EXPLANATION

DTW - DEPTH TO WATER FROM SURFACE	DTP - DEPTH TO PRODUCT FROM SURFACE
PT - PRODUCT THICKNESS	S - SLIGHT
MEASUREMENTS IN FEET	
REMARKS: <u>Q. W. S.</u>	
FREE PRODUCT REMOVED: APPROX. <u> </u> GALLONS	WATER REMOVED: APPROX. <u>77</u> GALLONS
DATA RECORDED BY: <u>[Signature]</u>	INPUT BY: Carrie

FIELD DATA - GROUNDWATER SAMPLING PROGRAM

Site:	#063	Date:	10.30.02
Address:			
Personnel:	SERBAA	Weather:	SUNNY DAY
Well No:	MV-1	Equip:	BAPLAR

Before Purging:			
Total Well Depth: (ft.)	28.96	Well Diameter	27
Depth to Water (ft)	15.16	Est. Purge Volume:	9

Sampling Data:							
Initial Turbidity:				Final Turbidity:			
Time	10:32	10:33	10:34	10:36	10:37	10:38	10:40
EC	1890	1960	1930	1970	1920	1940	1920
pH	5.36	5.33	5.36	5.35	5.34	5.33	5.36
Temp	71.4	71.6	71.7	71.8	71.6	71.9	71.9
Gal.	1	2	3	5	6	7	9
Time							
EC							
pH							
Temp							
Gal.							

After Purging/Before Sample Collection	
Depth to Water (ft.)	18.03
Total Well Depth (ft.)	28.96

FIELD DATA -GROUNDWATER SAMPLING PROGRAM

Site:	<u># 063</u>	Date:	<u>10.30.02</u>
Address:			
Personnel:	<u>SERBAN</u>	Weather:	<u>SUNNY DAY</u>
Well No:	<u>MW-4</u>	Equip:	<u>BATLER</u>

Before Purging:			
Total Well Depth: (ft.)	<u>29.10</u>	Well Diameter	<u>2'</u>
Depth to Water (ft)	<u>17.00</u>	Est. Purge Volume:	<u>8</u>

Sampling Data:							
Initial Turbidity:				Final Turbidity:			
Time	<u>10:43</u>	<u>10:44</u>	<u>10:45</u>	<u>10:46</u>	<u>10:47</u>	<u>10:48</u>	<u>10:50</u>
EC	<u>1380</u>	<u>1390</u>	<u>1410</u>	<u>1420</u>	<u>1460</u>	<u>1410</u>	<u>1410</u>
pH	<u>5.09</u>	<u>5.06</u>	<u>5.16</u>	<u>5.12</u>	<u>5.16</u>	<u>5.12</u>	<u>5.12</u>
Temp	<u>73.1</u>	<u>73.4</u>	<u>73.4</u>	<u>73.6</u>	<u>73.9</u>	<u>73.6</u>	<u>73.9</u>
Gal.	<u>1</u>	<u>2</u>	<u>3</u>	<u>4</u>	<u>5</u>	<u>6</u>	<u>8</u>
Time							
EC							
pH							
Temp							
Gal.							

After Purging/Before Sample Collection			
Depth to Water (ft.)	<u>20.05</u>	Total Well Depth(ft.)	<u>29.10</u>

FIELD DATA - GROUNDWATER SAMPLING PROGRAM

Site:	# 063	Date:	10.30.02
Address:			
Personnel:	SERBADA	Weather:	SUNNY DAY
Well No:	MW-5	Equip:	BAPLER

Before Purging:			
Total Well Depth: (ft.)	26.26	Well Diameter	4"
Depth to Water (ft)	15.93	Est. Purge Volume:	27

Sampling Data:							
Initial Turbidity:				Final Turbidity:			
Time	10:06	10:10	10:14	10:18	10:22	10:26	10:30
EC	1560	1540	1530	1540	1560	1580	1520
pH	5.27	5.23	5.20	5.23	5.28	5.28	5.26
Temp	21.3	21.1	20.9	20.8	20.5	20.3	20.2
Gal.	3	7	11	15	19	23	27
Time							
EC							
pH							
Temp							
Gal.							

After Purging/Before Sample Collection			
Depth to Water (ft.)	18.10	Total Well Depth(ft).	26.26

FIELD DATA -GROUNDWATER SAMPLING PROGRAM


Site:	063	Date:	10.30.02
Address:			
Personnel:	SERBANT	Weather:	SUNNY DAY
Well No:	MW-6	Equip:	BAYLER

Before Purging:			
Total Well Depth: (ft.)	26.83	Well Diameter	4"
Depth to Water (ft)	14.20	Est. Purge Volume:	33

Sampling Data:							
Initial Turbidity:				Final Turbidity:			
Time	9:31	9:36	9:41	9:45	9:50	9:55	10:00
EC	1560	1560	1540	1530	1520	1530	1530
pH	5.16	5.13	5.17	5.16	5.13	5.14	5.13
Temp	71.3	71.2	71.2	70.9	70.4	70.7	70.6
Gal.	4	9	14	18	23	28	33
Time							
EC							
pH							
Temp							
Gal.							

After Purging/Before Sample Collection	
Depth to Water (ft.)	12.03
Total Well Depth(ft.)	26.83

APPENDIX B



ASSOCIATED LABORATORIES

806 North Batavia - Orange, California 92868 - 714/771-6900

133451
RECEIVED
NOV 26 2002
ENVIRONMENTAL
FAX 714/538-1209

CLIENT Thrifty Oil Co. (8871)
ATTN: Jack Kosztowny
13116 Imperial Hwy.
P.O. Box 2128
Santa Fe Springs, CA 90670

LAB REQUEST 101634

REPORTED 11/11/2002

RECEIVED 11/01/2002

PROJECT Station #063
6125 Telegraph Ave., Oakland

SUBMITTER Client

COMMENTS Global ID: T0600101366

This laboratory request covers the following listed samples which were analyzed for the parameters indicated on the attached Analytical Result Report. All analyses were conducted using the appropriate methods as indicated on the report. This cover letter is an integral part of the final report.

<u>Order No.</u>	<u>Client Sample Identification</u>
389298	TOC #063, MW-6
389299	TOC #063, MW-5
389300	TOC #063, MW-1
389301	TOC #063, MW-4
389302	TOC #063, Trip Blank
389303	Laboratory Method Blank

Thank you for the opportunity to be of service to your company. Please feel free to call if there are any questions regarding this report or if we can be of further service.

ASSOCIATED LABORATORIES by,

Edward S. Behare, Ph.D.
Vice President

NOTE: Unless notified in writing, all samples will be discarded by appropriate disposal protocol 30 days from date reported.

The reports of the Associated Laboratories are confidential property of our clients and may not be reproduced or used for publication in part or in full without our written permission. This is for the mutual protection of the public, our clients, and ourselves.

TESTING & CONSULTING
Chemical
Microbiological
Environmental

Order #: 389298

Client Sample ID: TOC #063, MW-6

Matrix: WATER

Date Sampled: 10/30/2002

Time Sampled: 13:00

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX						
Benzene	1.6	1	0.3	0.18	ug/L	11/04/02 LZ
Ethyl benzene	ND	1	0.3	0.18	ug/L	11/04/02 LZ
Methyl t - butyl ether	6.4	1	5	0.24	ug/L	11/04/02 LZ
Toluene	ND	1	0.3	0.14	ug/L	11/04/02 LZ
Xylene (total)	ND	1	0.6	0.26	ug/L	11/04/02 LZ
8015M - Total Petroleum Hydrocarbons						
Gasoline	ND	1	50	50	ug/L	11/04/02 LZ

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 389299

Client Sample ID: TOC #063, MW-5

Matrix: WATER

Date Sampled: 10/30/2002

Time Sampled: 13:10

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX						
Benzene	ND	1	0.3	0.18	ug/L	11/04/02 LZ
Ethyl benzene	ND	1	0.3	0.18	ug/L	11/04/02 LZ
Methyl t - butyl ether	ND	1	5	0.24	ug/L	11/04/02 LZ
Toluene	ND	1	0.3	0.14	ug/L	11/04/02 LZ
Xylene (total)	ND	1	0.6	0.26	ug/L	11/04/02 LZ
8015M - Total Petroleum Hydrocarbons						
Gasoline	ND	1	50	50	ug/L	11/04/02 LZ

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 389300

Client Sample ID: TOC #063, MW-1

Matrix: WATER

Date Sampled: 10/30/2002

Time Sampled: 13:20

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX						
Benzene	2.2	1	0.3	0.18	ug/L	11/04/02 LZ
Ethyl benzene	ND	1	0.3	0.18	ug/L	11/04/02 LZ
Methyl t - butyl ether	13	1	5	0.24	ug/L	11/04/02 LZ
Toluene	ND	1	0.3	0.14	ug/L	11/04/02 LZ
Xylene (total)	ND	1	0.6	0.26	ug/L	11/04/02 LZ
8015M - Total Petroleum Hydrocarbons						
Gasoline	ND	1	50	50	ug/L	11/04/02 LZ

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 389301

Client Sample ID: TOC #063, MW-4

Matrix: WATER

Date Sampled: 10/30/2002

Time Sampled: 13:30

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX						
Benzene	400	20	6.0	0.18	ug/L	11/04/02 LZ
Ethyl benzene	748	20	6.0	0.18	ug/L	11/04/02 LZ
Methyl t - butyl ether	12300	500	2500.0	0.24	ug/L	11/04/02 LZ
Toluene	47	20	6.0	0.14	ug/L	11/04/02 LZ
Xylene (total)	131	20	12.0	0.26	ug/L	11/04/02 LZ
8015M - Total Petroleum Hydrocarbons						
Gasoline	17300	20	1000.0	50	ug/L	11/04/02 LZ

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 389302

Client Sample ID: TOC #063, Trip Blank

Matrix: WATER

Date Sampled: 10/30/2002

Time Sampled: 13:00

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX						
Benzene	ND	1	0.3	0.18	ug/L	11/04/02 LZ
Ethyl benzene	ND	1	0.3	0.18	ug/L	11/04/02 LZ
Toluene	ND	1	0.3	0.14	ug/L	11/04/02 LZ
Xylene (total)	ND	1	0.6	0.26	ug/L	11/04/02 LZ
8015M - Total Petroleum Hydrocarbons						
Gasoline	ND	1	50	50	ug/L	11/04/02 LZ

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 389303

Client Sample ID: Laboratory Method Blank

Matrix: WATER

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX						
Benzene	ND	1	0.3	0.18	ug/L	11/04/02 LZ
Ethyl benzene	ND	1	0.3	0.18	ug/L	11/04/02 LZ
Methyl t - butyl ether	ND	1	5	0.24	ug/L	11/04/02 LZ
Toluene	ND	1	0.3	0.14	ug/L	11/04/02 LZ
Xylene (total)	ND	1	0.6	0.26	ug/L	11/04/02 LZ
8015M - Total Petroleum Hydrocarbons						
Gasoline	ND	1	50	50	ug/L	11/04/02 LZ

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



APPENDIX C



THRIFTY OIL CO. SERVICE STATION #063

GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: SERBATA POPESCU

DATE OF INSPECTION: 12.30.02

OBSERVATIONS AND COMMENTS: ADD OIL, CHECK BELT, HOSES,
DRUMS CONNECTIONS, DRAIN COMPRESSOR TANK,
CLEAN WATER FILTER BAG, REPLACE CARTRIDGE
WATER FILTER,

FLOW METER READING: - 1173420 -

SAMPLES OBTAINED: N/A

PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: 13

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: 11

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: 1.0

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: 0.8

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: 0.6

INSPECTOR'S SIGNATURE: Serbaty

063

THRIFTY OIL CO. SERVICE STATION # 063

GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: SERBOPOPEDU

DATE OF INSPECTION: 12.20.02

OBSERVATIONS AND COMMENTS: CHECK OIL, BELT, HOSES,

[Empty lines for additional observations and comments]

FLOW METER READING: -116.6840-

SAMPLES OBTAINED: N/A

PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: 13

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: 11

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: 117

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: 0.8

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: 0.6

INSPECTOR'S SIGNATURE: [Signature]

063

THRIFTY OIL CO. SERVICE STATION # 063

GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: SERB MOORE JR

DATE OF INSPECTION: 12-16-02

OBSERVATIONS AND COMMENTS: ADD OIL, CLEAN WATER FILTER BAG

REPLACE CARTRIDGE WATER FILTER, CHECK

BELT, HOSES, DRAIN COMPRESSOR TANK,

FLOW METER READING: 1162320

SAMPLES OBTAINED: N/A

PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: 13

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: 11

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: 1.1

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: 0.9

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: 0.6

INSPECTOR'S SIGNATURE: [Signature]

THRIFTY OIL CO. SERVICE STATION # 063

GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: SERBAN POPESCU

DATE OF INSPECTION: 12.10.02

OBSERVATIONS AND COMMENTS: CHANGE OIL, CLEAN WATER FILTER BAG
REPLACE CARTRIDGE WATER FILTER, DRAIN COMPRESSOR
TANK,

FLOW METER READING: 1156750

SAMPLES OBTAINED: N/A


PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: 13

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: M

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: 1.1

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: 0.9

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: 0.6

INSPECTOR'S SIGNATURE: 

063

THRIFTY OIL CO. SERVICE STATION # 063

GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: SERBATOPOPEBA

DATE OF INSPECTION: 12-02-02

OBSERVATIONS AND COMMENTS: ADD OIL, CLEAN WATER FILTER BAG, REPLACE CARTRIDGE WATER FILTER

FLOW METER READING: -1152310-

SAMPLES OBTAINED: N/A

PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: 13

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: 11

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: 1.1

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: 0.8

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: 0.6

INSPECTOR'S SIGNATURE: [Signature]

063

THRIFTY OIL CO. SERVICE STATION #063

GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: SERBAPPOFFIN

DATE OF INSPECTION: 11.25.02

OBSERVATIONS AND COMMENTS: CHANGE OIL, CHECK BELT, HOSES,
CLEAN WATER FILTER BAG, REPLACE CARTRIDGE
WATER FILTER,

FLOW METER READING: 1149730

SAMPLES OBTAINED: N/A

PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: 13

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: 11

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: 1.1

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: 0.9

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: 0.7

INSPECTOR'S SIGNATURE: [Signature]

063

THRIFTY OIL CO. SERVICE STATION #063

GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: SEBASTIAN

DATE OF INSPECTION: 11.18.02

OBSERVATIONS AND COMMENTS: CHECK OIL, BELT, DRUMS, HOSES, DRAIN COMPRESSOR TANK, CHECK AIR FILTER AND FILTER BOWL DRAINS ON THE THREE STAGE FILTER REGULATOR,

FLOW METER READING: 1145310

SAMPLES OBTAINED: N/A

PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: 11

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: 11

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: 1.1

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: 0.9

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: 0.7

INSPECTOR'S SIGNATURE: [Signature]

063

THRIFTY OIL CO. SERVICE STATION # 063
GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: TERESA POPP

DATE OF INSPECTION: 11.11.02

OBSERVATIONS AND COMMENTS: ADD OIL, CHECK BELT, HOSES, CLEAN
WATER FILTER BAG, REPLACE CARTRIDGE WATER
FILTER, DRAIN COMPRESSOR TANK.

FLOW METER READING: 1139620

SAMPLES OBTAINED: N/A

PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: 12

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: 10

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: 0.8

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: 0.6

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: 0.4

INSPECTOR'S SIGNATURE: [Signature]

THRIFTY OIL CO. SERVICE STATION #

063

GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: SERBAPOPEBU

DATE OF INSPECTION: 11.04.02

OBSERVATIONS AND COMMENTS: ADD OIL, CHECK BELT, DRUMS, WOPPS

DRAIN COMPRESSOR TANK, CLEAN WATER FILTER BAG,

REPLACE CARTRIDGE WATER FILTER

FLOW METER READING: 1134130

SAMPLES OBTAINED: N/A

PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: _____

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: _____

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: _____

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: _____

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: _____

INSPECTOR'S SIGNATURE: _____

063

THRIFTY OIL CO. SERVICE STATION # 063

GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: SERENA POPPER

DATE OF INSPECTION: 10.28.02

OBSERVATIONS AND COMMENTS: CHECK BELT, DRUMS, HOSES, CLEAN WATER FILTER BAG, DRAIN COMPRESSOR TANK, REPLACE CARTRIDGE WATER FILTER, CHANGE OIL

FLOW METER READING: -1127540

SAMPLES OBTAINED: N/A

PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER:

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER:

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT:

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT:

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT:

INSPECTOR'S SIGNATURE:

THRIFTY OIL CO. SERVICE STATION # 063
GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: SERBAN POPESCU

DATE OF INSPECTION: 10.21.02

OBSERVATIONS AND COMMENTS: ADD OIL, CHECK BELT (LOOSE), CHECK

WATER FILTER BAG, REPLACE CARTRIDGE WATER

FILTER, DRAIN COMPRESSOR TANK,

FLOW METER READING: - 1123420

SAMPLES OBTAINED: N/A

PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: 13

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: 11

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: 1.0

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: 0.8

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: 0.6

INSPECTOR'S SIGNATURE: [Signature]

063

THRIFTY OIL CO. SERVICE STATION # 063

GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: SERBAPOPESCU

DATE OF INSPECTION: 10.19.02

OBSERVATIONS AND COMMENTS: ADD OIL, CLEAN WATER FILTER BAG, REPLACE CARTRIDGE WATER FILTER, DRAIN COMPRESSOR TANK, DRAIN BOWL FROM TERTER SPACE FILTER, CHECK BELT, HOSES

FLOW METER READING: 1118940

SAMPLES OBTAINED: N/A

PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: 13

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: 11

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: 1.8

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: 0.9

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: 0.7

INSPECTOR'S SIGNATURE: [Signature]

THRIFTY OIL CO. SERVICE STATION #063

GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: BERNARD DEDU

DATE OF INSPECTION: 10.07.02

OBSERVATIONS AND COMMENTS: ADD OIL, REPLACE CARTRIDGE WATER

FILTER, DRAIN COMPRESSOR TANK, CLEAN WATER

FILTER BAG, CHECK BELT, HOSES,

FLOW METER READING: -1114720-

SAMPLES OBTAINED: System water sampling

PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: 13

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: 11

PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: 1.0

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: 0.8

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: 0.6

INSPECTOR'S SIGNATURE: [Signature]

THRIFTY OIL CO. SERVICE STATION #063

GROUNDWATER EXTRACTION/TREATMENT SYSTEM INSPECTION FORM

NAME OF INSPECTOR: SERBIA POPESCU

DATE OF INSPECTION: 09.30.02

OBSERVATIONS AND COMMENTS: ADD OIL, CHECK BELT, CLEAN WATER

FILTER BAG, DRAIN COMPRESSOR TANK, REPLACE

CARTRIDGE WATER FILTER

FLOW METER READING: 1110180

SAMPLES OBTAINED: N/A


PRESSURE GAUGE READING UP STREAM OF THE BAG FILTER: 14

PRESSURE GAUGE READING DOWN STREAM OF THE CARTRIDGE FILTER: 12


PRESSURE GAUGE READING DOWN STREAM OF THE PRIMARY GAC UNIT: 1.2

PRESSURE GAUGE READING DOWN STREAM OF THE SECONDARY GAC UNIT: 0.9

PRESSURE GAUGE READING DOWN STREAM OF THE THIRD GAC UNIT: 0.6

INSPECTOR'S SIGNATURE: 

APPENDIX D



ASSOCIATED LABORATORIES

806 North Batavia - Orange, California 92868 - 714/771-6900

1-32700
RECEIVED

OCT 30 2002

ENVIRONMENTAL

FAX 714/538-1209

CLIENT Thrifty Oil (8871)

ATTN: Jeff Suryakusuma

13116 Imperial Hwy.

P.O. Box 2128

Santa Fe Springs, CA 90670

LAB REQUEST 100545 ✓

REPORTED 10/17/2002

RECEIVED 10/09/2002

PROJECT Station #063 ✓

SUBMITTER Client

COMMENTS

This laboratory request covers the following listed samples which were analyzed for the parameters indicated on the attached Analytical Result Report. All analyses were conducted using the appropriate methods as indicated on the report. This cover letter is an integral part of the final report. ✓

<u>Order No.</u>	<u>Client Sample Identification</u>
384635	TOC #063, Outlet
384636	TOC #063, Int-3
384637	TOC #063, Int-2
384638	TOC #063, Inlet
384639	TOC #063, Int-1
384640	Laboratory Method Blank

Thank you for the opportunity to be of service to your company. Please feel free to call if there are any questions regarding this report or if we can be of further service.

ASSOCIATED LABORATORIES by,

Edward S. Behare, Ph.D.
Vice President

NOTE: Unless notified in writing, all samples will be discarded by appropriate disposal protocol 30 days from date reported.

The reports of the Associated Laboratories are confidential property of our clients and may not be reproduced or used for publication in part or in full without our written permission. This is for the mutual protection of the public, our clients, and ourselves.

*TESTING & CONSULTING
Chemical
Microbiological
Environmental*

Order #: 384635

Client Sample ID: TOC #063, Outlet

Matrix: WATER

Date Sampled: 10/07/2002 Time Sampled: 09:30

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
8021B BTEX + MTBE						
Benzene	ND	1	0.3	0.18	ug/L	10/14/02 LZ
Ethyl benzene	ND	1	0.3	0.18	ug/L	10/14/02 LZ
Methyl t - butyl ether	ND	1	5	0.24	ug/L	10/14/02 LZ
Toluene	ND	1	0.3	0.14	ug/L	10/14/02 LZ
Xylene (total)	ND	1	0.6	0.26	ug/L	10/14/02 LZ

8015M - Total Petroleum Hydrocarbons

Gasoline	ND	1	50	50	ug/L	10/14/02 LZ
Surrogates					Units	Control Limits
a,a,a-Trifluorotoluene	100				%	55 - 156

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
 ND = Not detected below indicated MDL, J=Trace



Order #: 384636

Client Sample ID: TOC #063, Int-3

Matrix: WATER

Date Sampled: 10/07/2002 Time Sampled: 09:10

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
---------	--------	----	-----	-----	-------	--------------

8021B BTEX + MTBE

Benzene	ND	1	0.3	0.18	ug/L	10/14/02 LZ
Ethyl benzene	ND	1	0.3	0.18	ug/L	10/14/02 LZ
Methyl t - butyl ether	63	1	5	0.24	ug/L	10/14/02 LZ
Toluene	ND	1	0.3	0.14	ug/L	10/14/02 LZ
Xylene (total)	ND	1	0.6	0.26	ug/L	10/14/02 LZ

8015M - Total Petroleum Hydrocarbons

Gasoline	ND	1	50	50	ug/L	10/14/02 LZ
----------	----	---	----	----	------	-------------

Surrogates

				Units	Control Limits
a,a,a-Trifluorotoluene	101			%	55 - 156

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 384637

Client Sample ID: TOC #063, Int-2

Matrix: WATER

Date Sampled: 10/07/2002 Time Sampled: 09:50

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
---------	--------	----	-----	-----	-------	--------------

8021B BTEX + MTBE

Benzene	ND	1	0.3	0.18 ug/L	10/14/02 LZ
Ethyl benzene	ND	1	0.3	0.18 ug/L	10/14/02 LZ
Methyl t - butyl ether	60	2	10.0	0.24 ug/L	10/14/02 LZ
Toluene	ND	1	0.3	0.14 ug/L	10/14/02 LZ
Xylene (total)	ND	1	0.6	0.26 ug/L	10/14/02 LZ

8015M - Total Petroleum Hydrocarbons

Gasoline	ND	1	50	50 ug/L	10/14/02 LZ
Surrogates				Units	Control Limits
a,a,a-Trifluorotoluene	101			%	55 - 156

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 384638

Client Sample ID: TOC #063, Inlet

Matrix: WATER

Date Sampled: 10/07/2002 Time Sampled: 10:00

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
---------	--------	----	-----	-----	-------	--------------

8021B BTEX + MTBE

Benzene	ND	1	0.3	0.18	ug/L	10/14/02 LZ
Ethyl benzene	ND	1	0.3	0.18	ug/L	10/14/02 LZ
Methyl t - butyl ether	95	5	25.0	0.24	ug/L	10/14/02 LZ
Toluene	ND	1	0.3	0.14	ug/L	10/14/02 LZ
Xylene (total)	ND	1	0.6	0.26	ug/L	10/14/02 LZ

8015M - Total Petroleum Hydrocarbons

Gasoline	128	1	50	50	ug/L	10/14/02 LZ
----------	-----	---	----	----	------	-------------

Surrogates

				Units	Control Limits
a,a,a-Trifluorotoluene	100			%	55 - 156

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 384639

Client Sample ID: TOC #063, Int-1

Matrix: WATER

Date Sampled: 10/07/2002 Time Sampled: 10:10

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
---------	--------	----	-----	-----	-------	--------------

8021B BTEX + MTBE

Benzene	ND	1	0.3	0.18 ug/L	10/14/02 LZ
Ethyl benzene	ND	1	0.3	0.18 ug/L	10/14/02 LZ
Methyl t - butyl ether	ND	1	5	0.24 ug/L	10/14/02 LZ
Toluene	ND	1	0.3	0.14 ug/L	10/14/02 LZ
Xylene (total)	1.1	1	0.6	0.26 ug/L	10/14/02 LZ

8015M - Total Petroleum Hydrocarbons

Gasoline	ND	1	50	50 ug/L	10/14/02 LZ
----------	----	---	----	---------	-------------

Surrogates		Units	Control Limits
a,a,a-Trifluorotoluene	117	%	55 - 156

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



Order #: 384640

Client Sample ID: Laboratory Method Blank

Matrix: WATER

Analyte	Result	DF	PQL	MDL	Units	Date/Analyst
---------	--------	----	-----	-----	-------	--------------

8021B BTEX + MTBE

Benzene	ND	1	0.3	0.18 ug/L	10/14/02 LZ
Ethyl benzene	ND	1	0.3	0.18 ug/L	10/14/02 LZ
Methyl t - butyl ether	ND	1	5	0.24 ug/L	10/14/02 LZ
Toluene	ND	1	0.3	0.14 ug/L	10/14/02 LZ
Xylene (total)	ND	1	0.6	0.26 ug/L	10/14/02 LZ

8015M - Total Petroleum Hydrocarbons

Gasoline	ND	1	50	50 ug/L	10/14/02 LZ
Surrogates				Units	Control Limits
a,a,a-Trifluorotoluene	99			%	55 - 156

PQL = Practical Quantitation Limit, MDL = Method detection limit, DF = Dilution Factor
ND = Not detected below indicated MDL, J=Trace



ASSOCIATED LABORATORIES
LCS REPORT FORM

QC Sample: LCS 101402
 Matrix: WATER
 Prep. Date: 10/14/02
 Analysis Date: 10/14/02
 ID#'s in Batch: LR 100428, 100545, 100543

LAB CONTROLLED SPIKE / LAB CONTROLLED DUPLICATE RESULT

Reporting Units = ug/L

Test	Method	Method Blank	Spike Added	LCS Spike	LCSD Spk. Dup	%Rec LCS	%Rec LCSD	RPD
TPH	8015M-G	ND	500	442	476	88	95	7

ND = Not Detected

LCS Result = Lab Control Sample Result

%REC-LCS & LCSD = Percent Recovery of LCS Spike & LCS Spike Duplicate

RPD = Relative Percent Difference of LCS Spike and LCS Spike Duplicate

%REC LIMITS = 70 - 130
RPD LIMITS = 30

SURROGATE RECOVERY

Sample No.	AAA-TFT
QC Limit	55-156
Method Blank	99
LCS	176 *
LCSD	180 *

AAA-TFT = a,a,a-Trifluorotoluene

* Outside QC Limits

ASSOCIATED LABORATORIES

LCS REPORT FORM

QC Sample: LCS 101402
 Matrix: WATER
 Prep. Date: 10/14/02
 Analysis Date: 10/15/02
 LAB ID#'s in Batch: LR 100428, 100545, 100543

REPORTING UNITS = ug/L

PREPARATION BLANK / LAB CONTROL SAMPLE RESULTS

Test	Method	PREP. BLK	LCS			LCSD	
		Value	Result	TRUE	%Rec	Result	%Rec
Benzene	8021	ND	16	20	80	16	80
Toluene	8021	ND	18	20	90	17	85
Ethylbenzene	8021	ND	21	20	105	21	105
Xylenes	8021	ND	42	40	105	41	103

LCS = Lab Control Sample Result
 TRUE = True Value of LCS
 L.LIMIT / H.LIMIT = LCS Control Limits

L Limit	H.Limit
80%	120%

SURROGATE RECOVERY

Sample No.	AAA-TFT
QC Limit	55-156
Method Blank	99
LCSD	104
LCSD	96

AAA-TFT = a,a,a-Trifluorotoluene

Cooler Receipt Form

Client: Thurifty Oro Co Project: TOC#0103
Date Cooler Received: 10/9/02 Date Cooler Opened: 10/9/02

Was cooler scanned for presence of radioactivity? Yes / No
a: Was radioactivity results above 25cpm? Yes / No

If cooler had custody seal(s), were they signed and intact? NA / Yes / No

Was a shipper's packing slip attached to the cooler? Yes / No

Cooler was packed with: Ice Ice Packs Bubble Wrap Styrofoam
Paper None Other

Temperature of cooler: 10.4°

*Cooler needs to be received @ 4°C with an acceptable range of 2°-6°C

Were all samples sealed in plastic bags? Yes / No

Did all samples arrive intact? If no, see below Yes / No

Were all samples labeled correctly? (ID, Dates, Times) If no, see below Yes / No

Can the tests required be run with provided containers? If no, see below Yes / No

Was sufficient volume of sample sent in all containers? Yes / No

Were any VOA vials received with headspace? NA / Yes / No

Were correct preservatives used? NA / Yes / No

*If no, see pH Log for a list of samples and container pH.

Any other important information: _____

Signed: [Signature] Date: 10/9/02



ASSOCIATED LABORATORIES

806 North Batavia - Orange, California 92868 - 714/771-6900

1.32452
RECEIVED
OCT 21 2002
ENVIRONMENTAL

JS
RF

FAX 714/538-1209

CLIENT Thrifty Oil (8871)
ATTN: Jeff Suryakusuma
13116 Imperial Hwy.
P.O. Box 2128
Santa Fe Springs, CA 90670

LAB REQUEST 100545

REPORTED 10/17/2002

RECEIVED 10/09/2002

PROJECT Station #063

SUBMITTER Client

COMMENTS

This laboratory request covers the following listed samples which were analyzed for the parameters indicated on the attached Analytical Result Report. All analyses were conducted using the appropriate methods as indicated on the report. This cover letter is an integral part of the final report.

<u>Order No.</u>	<u>Client Sample Identification</u>
384635	TOC #063, Outlet PSP1 OUTLET
384636	TOC #063, Lat 1 INT - 3
384637	TOC #063, Lat 2 INT - 2
384638	TOC #063, Lat 3 INLET
384639	TOC #063, Inlet INT - 1
384640	Laboratory Method Blank

Thank you for the opportunity to be of service to your company. Please feel free to call if there are any questions regarding this report or if we can be of further service.

ASSOCIATED LABORATORIES by:

Edward S. Behere, Ph.D.
Vice President

NOTE: Unless notified in writing, all samples will be discarded by appropriate disposal protocol 30 days from date reported.

The reports of the Associated Laboratories are confidential property of our clients and may not be reproduced or used for publication in part or in full without our written permission. This is for the mutual protection of the public, our clients, and ourselves.

TESTING & CONSULTING
Chemical
Microbiological
Environmental

ASSOCIATED LABORATORIES

806 North Batavia • Orange, CA 92868
 Phone: (714) 771-6900 • Fax: (714) 538-1209



Chain of Custody Record

OCT-21-2002 15:03 FROM-

Company THRIFTY OIL CO.		Phone (562) 921-3581		A.L. Job No. 100545		Page _____ of _____					
Project Manager JEFF DUBAYAN		Fax (562) 921-7540		Analysis Requested				Test Instructions & Comments			
Project Name System water sampling		Project # 063									
Site Name and Address # 063											
Sample ID	Lab ID	Date	Time	Matrix	Container Number/Size	Pres.	T	B	M		
1		10.07.02	9:30	H ₂ O	3V0H	HCL	X	X	X		
4		↑	9:40	↑	↑	↑	X	X	X	GRAB SAMPLE	
3		↑	9:50	↑	↑	↑	X	X	X		
5		↑	10:00	↑	↑	↑	X	X	X		
2		↑	10:10	↑	↑	↑	X	X	X		
6											
7											
8											
9											
10											
11											
12											
13											
14											
15											

Sample Receipt - To Be Filled By Laboratory				Relinquished by Sampler	Relinquished by	Relinquished by
Total Number of Containers	15	Property Cooled	Y/N/NA	Signature: <i>[Signature]</i>	Signature: <i>[Signature]</i>	Signature:
Custody Seals	Y/N/NA	Samples Intact	Y/N/NA	Printed Name: <i>[Signature]</i>	Printed Name:	Printed Name:
Received in Good Condition	Y/N	Samples Accepted	Y/N	Date: 10.07.02 Time: 11:30	Date: Time:	Date: Time:
Turn Around Time				Received By:	Received By:	Received By:
<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Rush	<input type="checkbox"/> Same Day	<input type="checkbox"/> 48 hrs.	Signature: <i>[Signature]</i>	Signature: <i>[Signature]</i>	Signature:
		<input type="checkbox"/> 24 hrs.	<input type="checkbox"/> 72 hrs.	Printed Name: <i>[Signature]</i>	Printed Name: <i>[Signature]</i>	Printed Name:
				Date: 10/9/02 Time: 18:30	Date: 10/9/02 Time: 18:30	Date: 10/9/02 Time: 2:55

T-688 P. 008/008 F-578