
Regional Offices Arizona California Hawaii Virginia



Mr. Charles W. Wren, Project Manager UNITED STATES POSTAL SERVICE San Bruno Facilities Service Center 850 Cherry Avenue San Bruno, California 94099-0310

CONSTRUCTION OBSERVATION OF UST ACTIVITIES Oakland Main Postal Office 1675 7th Street Oakland, California

Dear Mr. Wren:

Geo/Resource Consultants, Inc. (GRC) is pleased to submit to the UNITED STATES POSTAL SERVICE (USPS) the enclosed report regarding the observations and findings for the underground storage tank (UST) installations program at the aforementioned site.

In fulfillment of the Alameda County Health Agency request, GRC respectfully requests that the USPS submit a copy of the Report to:

> Mr. Dennis Byrnes Senior Hazardous Materials Specialist Division of Hazardous Materials Department of Environmental Health

We appreciate the opportunity to work with you on this project and look forward to working with you again in the future. If you have any questions or comments regarding this project, please feel free to contact us.

Sincerely,

GEO/RESOURCE CONSULTANTS, INC.

Hor

Gary A. Floyd, R.E.A.

Senior Environmental Scientist

T. Carbullido, R.E.A. Vice Rresident & Principal

GTC/GAF: kbc

GRC Project File, 1708-001-00 cc:

GRC Chron

Keith B Crain

3EPD4: 1708-L

CONSTRUCTION OBSERVATION OF UST ACTIVITIES UNITED STATES POSTAL SERVICE OAKLAND MAIN POST OFFICE 1675 7th STREET OAKLAND, CALIFORNIA

PREPARED FOR:

UNITED STATES POSTAL SERVICE

850 CHERRY AVENUE

SAN BRUNO, CALIFORNIA

PREPARED BY:

GEO/RESOURCE CONSULTANTS, INC.

505 BEACH STREET

BAN FRANCISCO, CALIFORNIA 94133

APRIL 23, 1992

JOB NUMBER: 1708-001-00

TABLE OF CONTENTS

				PAGE
1.0	INTR	ODUCTIO	N	1
	1.1	Purpos	e	3
	1.2	Projec	t Personnel	3
2.0	UST	ACTIVIT	TES	5
	2.1	Pre-Co	nstruction Conference	5
	2.2	Constr	uction Observation	6
		2.2.1	Removal of Two 10,000-gallon Diesel USTs and One 5,000-gallon Gasoline UST	7
		2.2.2	Removal of the Fuel Dispensing Island and Associated Piping	9
		2.2.3	Removal of One 750-gallon Waste Oil UST Removal	9
		2.2.4	Installation of the Three 12,000-gallon USTs	1.0
		2.2.5	Installation of the 1,000- gallon Above Ground Waste Oil Tank	12
		2.2.6	Stock Pile Disposal	13
3.0	SAMP ANAL		THODOLOGY AND LABORATORY	14
	3.1	Soil S Protoc	ampling and Laboratory Analyses	14
4.0	CONC	LUSIONS		19
5.0	REFE	RENCES		21

LIST OF FIGURES

Figure 1 Vicinity Map

Figure 2 "As-Built" Drawing, Facility Plan, and Equipment Lists

LIST OF TABLES

Table 1 Soil Analytical Results - USTs

Table 2 Soil Analytical Results - Stock Pile

LIST OF APPENDICES

Appendix A GRC Project Update Chronologies

Appendix B Alameda County Health Permits

Appendix C Rinsate Manifest

Appendix D Subsurface Consultants, Inc. Backfill Report

Appendix E Plumbing Inspection Field Reports, and UST Tank Integrity Test

Appendix F Equipment List for Fuel Dispensing Island and Waste Oil Tank

Appendix G Non-Hazardous Waste Manifests


Appendix H Soil Sample Location Maps, Laboratory Analyses Results, and Chain-of-Custody Records

Appendix I Photographs

1.0 INTRODUCTION

Geo/Resource Consultants, Inc. (GRC) was retained by the UNITED STATES POSTAL SERVICE (USPS) to perform construction observations for the underground storage tank (UST) program at the Oakland Main Post Office (OMPO) and distribution center located at 1675 in Oakland. California (See Figure 1). The Street UST excavation activities, including and construction installation, were performed by R. S. Eagan Company (EAGAN) of This report fulfills the requirements Hayward, California. outlined in the Scope of Work under "Task 4 - Report of Findings" of GRC's proposal dated November 1, 1991, in accordance with the USPS Master Contract Number 059984-89-J-0053.

This Report will include the following items: chronology of summary of laboratory data from the soil sampling field events; general description of the field construction a activities completed, and; the quantity of soil transported off-Additionally, GRC was retained by the USPS to complete "As-Built Drawings" of the three newly installed 12,000-gallon diesel and gasoline USTs and the newly installed 1,000-gallon above ground storage tank (AGST). These drawings are nonspecification "as-built" drawings and are presented for general information purposes only.



1.1 Purpose

The purpose of this report is to present a compilation of the field data and methodology observed during the demolition and construction phases of the project. EAGAN's Scope of Work for the UST removals and installations included the following activities:

- o Removal of two 10,000-gallon diesel USTs; V
- o Removal of one 5,000-gallon gasoline UST; V
- o Removal of one 750-gallon Waste Oil UST;
- o Demolition of all of the fuel product lines and the fuel dispensing islands;
- o Installation of one new 12,000-gallon unleaded gasoline UST;
- o Installation of two new 12,000-gallon diesel USTs;
- o Installation of one 1,000-gallon waste oil AGST
- o Installation of two new fuel dispensing islands; and
- o Installation of a leak detection system for all of the three installed USTs.

1.2 Project Personnel

During the UST construction activities, beginning November 4, 1991, Mr. Keith B. Craig of GRC was present on-site to observe and record the work performed by EAGAN. However, during the period between January 11, 1992 and March 19, 1992, GRC personnel were not required to be on-site to observe the construction activities. Observations noted by Mr. Craig were recorded in a GRC field logbook (GRC Logbook Number EPD 9022). Mr. Jim Nichols

April 23 1992 1708-001-00 Page 4 of 22

of EAGAN was the on-site project manager for the UST demolition and construction activities. As project manager, Mr. Nichols supervised and directed field operations, as well as maintained Health and Safety Standards.

The excavation portion of the UST removal program was completed by personnel from Tank Excavators, Inc. (TEI) of Santa Cruz, California, a subcontractor retained by EAGAN. Other EAGAN subcontracted companies included Trace Analysis Laboratories (TALL) of Hayward, California; Dillard Trucking (DILLARD) of Byron, California; H & H Ship Service Company (H & H) of San Francisco, California; and, Subsurface Consultants, Inc. (SUBSURFACE) of Oakland, California.

UST ACTIVITIES

will discuss the sections Pre-Construction following The Conference and the demolition and construction observation phases The construction phase includes the removal of the project. activities of the three USTs and the product lines associated with the USTs; the demolition of the fuel dispensing islands; the initial abatement of the contaminated soil from the UST removal excavations and associated product line excavation areas; the installation methodology of the three 12,000-gallon USTs; the installation methodology of the 1,000-gallon waste oil AGST; the re-construction of the fuel dispensing islands; and the installation of the TLS-350 leak detection system. The two diesel 10,000-qallon USTs that were removed, UST-1/UST-2, were located in the same excavation. The 5,000-gallon gasoline UST and the 750-gallon waste oil UST were removed from separate excavations.

2.1 Pre-Construction Conference

On September 18, 1991, a Pre-Construction Conference was held at The purpose of the Pre-Construction Conference was to outline the proposed schedule for the removal of the USTs, the fuel dispensing pump islands and associated product lines, the installation of the three new 12,000-gallon fuel containing USTs fuel dispensing two associated pump islands, installation of the 1,000-gallon waste oil AGST, the installation of the leak detection system for the new USTs. addition, contingency plans were discussed in the event that contaminated soil was discovered during the tank removal program.

Mr. Eagan of EAGAN stated that all regulatory permits required to remove and install the USTs for this project would be processed by EAGAN personnel. Mr. Eagan also outlined the proposed dates for the removal of the old tanks and the installation of the new tanks during the Conference.



April 23 1992 1708-001-00 Page 6 of 22

following personnel, representing their respective The agency/company, were present at the September 18, 1991 Pre-Construction Conference:

USPS

Mr. Van Hester, Manager of Vehicle Maintenance Programs

EAGAN

Mr. Robert S. Eagan, President

GRC

Mr. Gary A. Floyd, Senior Environmental Scientist

2.2 Construction Observation

During the UST removal, Initial Abatement Program (IA), and UST installation, Mr. Craig of GRC was present on-site to observe and record the work performed by EAGAN and their subcontractors. Additionally, GRC submitted weekly "Project Up-dates" to Mr. Charles Wren of USPS from November 8, 1991 to January 10, 1992 The Project Up-dates reported the weekly (See Appendix A). chronological job progress in detail. Agency construction permits were obtained by EAGAN prior to construction activities (See Appendix B).

The USTs and fuel pump island removal activities were initiated on November 4, 1991. TEI used a Kimatsu PL 280 LG excavator for the concrete removal and soil excavation prior to removal of the four USTs and the excavation for the new USTs (See Appendix I Two of the four USTs were 10,000-gallon tanks Photograph A). containing diesel, one UST was a 5,000-gallon tank containing gasoline, and the fourth UST was a 750-gallon tank used for storing waste oil.

The two diesel 10,000-gallon USTs (UST-1 and UST-2) were located adjacent to the south end of the Vehicle Maintenance Building (VMB) and east of the existing fuel dispensing islands (See The 5,000-gallon gasoline UST (UST-3) was located Figure 2).





approximately 15-feet south of the two 10,000-gallon USTs (See Figure 2). The 750-gallon waste oil UST (UST-4) was located on the western side of the VMB adjacent to the tire storage area and in front of the one of main vehicle entrances (See Figure 2).

2.2.1 Removal of Two 10,000-Gallon Diesel USTs and One 5,000-gallon Gasoline UST

TEI and EAGAN personnel demolished the asphalt and concrete slabs exposing the underlying soils above UST-1, UST-2, and UST-3. and associated piping were then exposed the The soils surrounding and overlying the three USTs excavator. consisted of brown clayey silty sand. The soil was moist to wet and moderately dense. Once the product, fill, and vent lines were disconnected from each of the USTs, the excavation Soil staining was noted in the soil excavated from approximately 4.0-feet below ground surface (bgs) covering the entire area of each of the two excavations (UST-1/UST-2 and UST-3) to the bottom of the excavations (See Appendix I, Photographs B and C).

Due to the extent of the soil removal, sheet piles were used to strengthen the walls of the excavation to insure against collapse and to minimize impact to the adjacent foundations of the VMB and the fuel dispensing island canopy. The sheet piles were placed between 1.0-feet to 5-feet from UST-1 and UST-2 forming a rectangular-shaped excavation area (See Appendix I Photograph D). No sheet piles were needed to shore the UST-3 excavation.

The removal of the USTs was completed using the aforementioned excavator (See Appendix I Photograph F). Upon removal of the adjacent soils, all three USTs were noted to be bedded on approximately 2-feet of sand. An estimated 12-inch-thick concrete slab covered the entire floor of the excavation below The concrete pad was left in place at the bottom of the excavations. No ground water was initially encountered at or above the lowest point of the excavation which was approximately 16-feet below ground surface (bgs). After heavy rains, rain water partially filled the UST-3 excavation before backfilling had been completed.



Prior to removal, each UST was vacuum-vented by H & H, purged with several hundred pounds of dry ice, and removed on November 8, 1991 (See Appendix I Photograph E). The rinsate product from each of the banks were transported to the H & H facility for disposed (see Appendix D). TAL and EAGAN personnel collected soil samples immediately following the UST removal (See Section 3.1, Figure 2 and Appendix I Photograph G). Inspection of the USTs revealed one small hole the size of a quarter in the 5,000gallon UST (See Appendix I Photograph H). The tanks were transported by DILLARD to Erikson Environmental of Richmond, California.

original UST-1/UST-2 excavation comprised an area of. The The approximately 30-feet by 28-feet and a depth of 16-feet. UST-3 excavation comprised an area of approximately 18-feet by depth of 14-feet. Visible contamination and a (discoloration of the soil) and strong hydrocarbon odors, was noted on the south and north wall of the UST-1/UST-2 and UST-3 In addition, five of the six soil excavations, respectively. samples collected from the ends of the USTs, confirmed that elevated levels of Total Petroleum Hydrocarbons as diesel and gasoline (TPH-Diesel and TPH-Gasoline), Benzene, Toluene, Ethyl Benzene, and Total Xylenes (BTXE) were present (See Section 3.2). Soil from the excavations was stockpiled on plastic sheeting, and covered, and stored on-site until the determination of final > Initial Abatement pesx ist disposal (See Appendix E). عزه هر

On November 8, 1991, TEI personnel initiated the IA Program, for the UST-3(9°excavation, by /excavating soil that was visibly Soil was excavated to approximately 5-feet in all directions and stockpiled for later disposal. The IA Program soil samples were collected and submitted to the laboratory for analyses (See Section 3.2). Due to the shoring of the UST-1/UST-2 excavation, the IA program was not instigated. The remaining soil was excavated to the face of the sheet piling.

Backfilling of the excavations commenced on November 11 through November 15, 1991. Imported fill consisting of "Tidewater" sand, aggregate base and "Pea" gravel was used to back-fill excavation to approximately 3.0 feet bgs. The fill material was compacted with a vibratory plate attached on to the end of the



excavator (See Appendix I Photograph I). Personnel from SUBSURFACE performed numerous density tests on the back-fill. Results were reportedly at or above 95 percent Final surfacing with concrete and compaction (See Appendix E). asphalt paving was completed in January, 1992 by EAGAN personnel (See Appendix I Photograph J).

2.2.2 Removal of the Fuel Dispensing Island and Associated Piping

Prior to the removal of the three USTs, the gasoline fuel dispensing island was completely demolished and excavated to remove the associated product lines. The diesel fuel dispenser and associated product lines were partially demolished leaving the TRAK and the island itself intact. Soil was removed from grade to approximately 3.0-feet below ground surface from each The soil was stockpiled on-site.

The excavated soil from below the pump islands and the product lines showed visible signs of petroleum staining throughout the excavation area. Soil samples analyzed from below the fuel pump island confirmed that contamination did exist below the island (See Section 3.1).

Removal of One 750-Gallon Waste Oil UST

TEI personnel removed the surface asphalt and concrete slabs The tank and exposing the soils above the waste oil UST (UST-4). associated piping were then exposed using an excavator. The soils surrounding and overlying the UST consisted of brown sandy The soil was moist to wet. silty clay.

UST-4 was embedded in at least 2 feet of soil above a concrete The UST was vacuum-vented by H & H, purged with several hundred pounds of dry ice, and removed on November 8, 1991. DILLARD transported the UST to Erikson Environmental. concrete slab at the bottom of the excavation was left in-place. No petroleum odors nor soil discolorations were evident in the



April 23 1992 1708-001-00 Page 10 of 22

excavation. Soil samples were collected in the bottom of the excavation with trace detections of five metals, Dichloromethane, and Benzene (See Section 3.1). No ground water was encountered in the excavation at the time of the UST removal.

The excavation comprised an area of approximately 12-feet-long by 10-feet-wide and a depth of 6-feet. All soil from the excavation was stockpiled for disposal. Upon review of the laboratory data, further excavation was deemed unnecessary by Mr. Dennis Byrnes of the Alameda County Environmental Health, Hazardous Materials Division (ACEHHMD) for the UST-4 excavation (Personal Conversation with Mr. Byrnes, on November 13, 1991).

Backfilling of the excavation commenced soon after the laboratory results of the samples collected from the bottom of the excavation were known. Pea gravel was placed in the excavation to approximately 1.0-feet below grade. Final grading with concrete and asphalt paving was completed in January 1991.

2.2.4 Installation of the Three 12,000-Gallon USTs

TEI personnel excavated the soil and the overlying asphalt to an approximate depth of 18-feet bgs in order to install the three 12,000-gallon USTs. The excavation was located on the south west corner of the USPS vehicle parking lot and adjacent to the main truck entrance (See Figure 2). The lateral dimensions of the excavation were approximately 44-feet by 40-feet. The soil was stockpiled on-site for later disposal at a Class III landfill. Ground water was encountered at the 18-foot bgs elevation during excavation.

A 2-feet-thick layer of 3/8-inch pea gravel was placed across the bottom of the excavation to provide bedding for the new 12,000-gallon USTs (See Appendix I Photograph K). A total of six (two each for each of the three USTs), 36-feet-long by 18-inch-diameter, octogonal-shaped reinforced concrete piers (deadman) were placed parallel, to be situated between each of the new USTs, on top of the pea gravel bedding (See Figure 2).

Prior to installation, the 12,000-gallon Double Wall Glasteel Underground tanks, manufactured by Shields, Harper & Company (SH&C), were soap-tested for possible leaks, with Mr. Byrnes of the ACEHHMD overseeing the test procedures (See Appendix I Photograph L). All three new tanks tested tight when pressurized to 5 pounds per square inch (psi) of air. After the USTs and associated piping were installed into the new excavation, Mr. inspectors from the City of Oakland Fire and two Inspection Bureau observed the primary and secondary pressure testing of the product lines and sumps (See Appendix Photographs M, N, and P, and Appendix E). Western America Tank Testing, Inc. of Bakersfield, California, performed the tank the VPLT Tank Testing System utilizing test (manufactured by NDE Technology, Inc.), prior to the The test results indicated that the tank backfilling operation. passed the California Administrative Code Title 23, Subchapter 16 Underground Storage Regulations, allowable pressure loss standard of (+/-) 0.05 gallons per hour (See Appendix E).

The new 12,000-gallon USTs were each lowered into the new excavation using a large crane provided by Allied Crane and Rigging (AC&R) of Richmond, California. AC&R personnel placed each UST between the two deadman in the common excavation (See Figure 2). A 0.5-inch-diameter steel cable was wrapped over and across the UST and attached to the other deadman, anchoring the UST into the ground. Pea gravel was then placed around and over the UST to fill the remainder of the excavation after all piping had been constructed and tested for tightness.

The new fuel dispensing islands were constructed in the original The new double-walled locations of the demolished islands. fiberglass product and vapor recovery lines were connected into the appropriate pump island (See Figure 2, and Appendix I, Photograph Q). No vapor recovery line was needed for the diesel The vent outlet pipes for each of the three dispensing system. USTs were connected to the guard rail adjacent to the southwest The TLS-350 and corner of the UST installations (See Figure 2). power conduits collected from the three USTs were connected into the VMB to the computer room or main power breaker Approximately 140-feet of conduit respectively (See Figure 2). was used to connect the Annular Space Monitoring Probe to the April 23 1992 1708-001-00 Page 12 of 22

TLS-350 Veeder Root monitoring computer and printer located in the computer room in the VMB. Appendix F contains the equipment list submitted by EAGAN for the installation of the dispensing island electrical and plumbing systems.


Electrical power supply lines for the pump island were housed in a separate conduit leading from the power source in the VMB (See Figure 2). The air and water supply lines were reconnected to the overhead roller (See Figure 2). New conduit for the TRAK system was connected up in the area outside of the VMB (See Figure 2).

Final filling and compacting to grade of pea gravel above the USTs were completed prior to the final UST integrity tests. Following the final tank and pipe integrity tests, the two dispensing islands were concrete poured on top of the existing compacted soil. Number 5 steel bar reinforcing on 12-inch centers was placed in the concrete slabs over the USTs and the removed UST excavations to conform with the existing concrete slabs. Baserock and asphalt were placed in those areas needed to conform with the existing asphalt.

All of the new leak detection monitors and probes were installed during the course of this project. Final calibration of the leak detection system and tank monitoring devices was completed by March 1992, after fuel had been placed in the new USTs. However, GRC personnel were not present for these activities.

2.2.5 <u>Installation of the 1,000-gallon Above Ground Waste Oil</u> Tank

A 1,000-gallon waste oil storage tank, manufactured by Enviro-Vault of Huntington Beach, California, was set on the prepared 6-inch thick concrete pad (See Appendix I, Photograph R). Connections of the power to run the pump and to the TLS-350 system for control of the overfilling system were all above ground. The power lines were connected into the main breaker box and the TLS-350 overfill system was connected to the main computer in the computer room. The accessories to the tank are



April 23 1992 1708-001-00 Page 13 of 22

drawn from a brochure provided by EAGAN (See Figure 2). The waste oil evacuation system consists of the Grover 1-inch diameter double diaphragm pump and the accessories (See Appendix F). The installation of the electrical and plumbing systems for the waste oil AGST were not observed by GRC personnel due to the late date of installation (after January 10, 1992).

2.2.6 Stock Pile Disposal

After the soil stock pile laboratory results were received, the stock pile was approved to be transported to two facilities, Liquid Waste Management and McKittrick Waste Disposal Site (at the Highway 58 and 33 junction and at 56533 West Highway 58, respectively) both in McKittrick, California. On November 11, 1991, twenty two (22) end dump trucks from DILLARD were loaded with the stock piled soil and sent to the respective sites. Nine trucks (approximately 168 yards of soil) went to the Liquid Waste Management site (See Appendix G). A total of approximately 396 cubic yards of soil were hauled to the two disposal sites.

doc ! G Jee App. G

3.0 SAMPLING METHODOLOGY AND LABORATORY

ANALYSES

Soil sampling occurred on November 8, 1991, for each of the USTs and the fuel dispensing islands and the associated product lines. Due to the extent of the excavations, IA Program sampling was run concurrently with the sampling on November 8, 1991. TALL collected the soil samples under the guidance of Mr. Byrnes of the ACEHHMD.

The results of the soil sample analyses are found in Tables 1 and 2. No ground-water samples were collected for this phase of construction.

3.1 Soil Sampling and Laboratory Analyses Protocol

Soil samples were collected by TAL and EAGAN personnel by hand sampling the UST excavations sidewalls and beneath the product and dispensing islands. The soil stockpiles were sampled in a random order, with the number of samples collected depending upon the volume of the particular stockpile. Either three or four soil samples were composited prior to running the analyses for the stockpile samples.

EAGAN personnel collected the soil samples by scraping the loose soil to a fresh surface and driving a 6-inch long brass liner into the soil. Each soil sample was capped with aluminum foil and plastic caps, sealed with duct tape, properly labeled, placed on ice to preserve sample integrity, and transported to TALL, a State certified analytical laboratory under Chain-of-Custody Protocol.

Soil sampling locations were determined by Mr. Byrnes to be at approximately 2.0-feet below the bottom of the USTs on each end (See Appendix H). The fuel dispensing island excavation was sampled approximately every 20-linear feet along the path of the product lines.



TABLE 1

SOIL ANALYTICAL RESULTS - USTs

OAKLAND MAIN POST OFFICE OAKLAND, CALIFORNIA

chain not signed

TPH-G BENZENE TOLUENE TOTAL ETHYL HALOGENATED -SEMEVOLATILE WIL & CADMIUM CHROMIUM LEAD WHICKEL! ZINC PC8s TPH-D SAMPLE XYLENES BENZENE VOLATILE ORGANICS .. GREASE OLDY! ORGANICS: 8015m. EPA 8010 EPA-7130 EPA 7190 EPA 7420 | EPA 7520 EPA 8080 6015m EPA 8023 EPA BOZO EPA 8020 EPA 8020 EPA 8270 5570F EPA 7050 depth (mg/kg) (ma/ka) (mg/kg) (mp/km) (ma/ka) « (ma/ka) (ma/kg) (ma/kg) (ma/kg) (ma/ka) (ma/ka) (mg/kg) (mp/kg) (mp/kg) (ma/ka) 5,000-Gallon UST: Of Co 9,4 = 260 🗸 0.80 = 0.12 0.015 0.0068 (3.0)(0.50)(0.0050)(0.0050)(0.015)(0.0050)2 76 L 3.5 1,200 = 0.59 -0.23 52 (15) (0.50)(0.013)(0.011)(0.030)(0.012)10,000-Gallon USTs: diase 2.000 59 0.27 0.79 5.3 1.4 (0.12)(15)(1.5)(0.13)(0.11)(0.30)3B ND ND ND ND ND ND (1.0)(0.50)(0.0050) (0.0050)(0.015)(0.0050)4A 220 150 7.5 19 32 8.9 $\{0.026\}$ (0.060)(0.024)(3.0)(0.50)(0.022)4B 620 z 37 L 130 53 ع: 2,500 **د** 1.6 (7.0)(3.0)(1.0)(2.0)(1.0)(0.82)7.24 Composite (2.5)of 3 & 4 11).0 750-Gallon UST: ND -90 ND & ND ND c 0.0068 ---ND ND ND ND 1.0 4 24 68 ^ 18 (0.0050)(0.33 - 3.3)(50) (0.25)(1.2)(2.5)(7.5)(1.2)(0.080 - 0.16)(1.0)(0.50)(0.0050)(0.0050)(0.015)Product Line/Fuel Dispensing Islands 1.4 36 4 11 % -0.36 8.1 0.82 (1.0)(0.50)(0.013)(0.011)(0.030)(0.012)14 7 7,900 210 4 ND 0.45 1.4 (15) (0.50)(0.026)(0.022)(0.060)(0.024)170 27 8 2,900 4 610 Z 3.4 60 (2.0)(1.0)(15) (3.0)(1.0)(0.82)

Notes: TPH-D = Total Petroleum Hydrocarbons as diesel

TPH-G = Total Petroleum Hydrocarbons as gasoline

11-8-91

ND = Not detected at or above the Laboratory Reporting Limit

() = Laboratory Reporting Limit

= Dichloromethane at 0.0024 (0.00050); Tetrachloroethene at 0.0099 (0.00050);

all other Halogenated Volatile Organics were not detected.

- = Not analyzed

EPD4: 1708-001/T1

E

6

6

TABLE 2

SOIL ANALYTICAL RESULTS - STOCKPILES

OAKLAND MAIN POST OFFICE OAKLAND, CALIFORNIA

	TPH-D	TPH-G	BENZENE	TOLUENE	TOTAL XYLENES	ETHYL BENZENE
SAMPLE LD.	8015m (mg/kg)	8015m (mg/kg)	EPA 8020 (mg/kg)	EPA 8020 (mg/kg)	EPA 8020 (mg/kg)	EPA 8020 (mg/kg)
Composite of Alternate 1, 2, & 3	ND V (1.0)	ND V (0.50)	ND (0.0050)	ND /	ND (0.015)	, ND (0.0050)
Composite of	1,500 /	590 / (4.2)	2,5 V (0.26)	46 (0.22)	160 (0.62)	12 (0.26)
Composite of 5, 6, 7 & 8	1,600	770 V (4.2)	1.3	13 (0.22)	180 (0.62)	12 (0.26)
Composite of 9, 10, 11 & 12	1,600 √ (9.8)	240 (4.2)	3.1 (0.26)	0.61 (0.22)	77 (0.62)	4.3 (0.26)
Composite of 13, 14, 15, &16	1,600 1	280 🗸	ND (0.26)	2.8 (0.22)	100 (0.62)	3.2 (0.26)
Composite of 17, 18, 19 & 20	660 (9.8)	190 V (4.2)	ND (0.26)	1.3 (0.22)	18 (0.62)	0.93 (0.26)
Composite of 21, 22, 23 & 24	2,600	210 ·/ (4.2)	ND (0.26)	1.8 (0.22)	63 (0.62)	2.8 (0.26)

Notes: TPH-D = Total Petroleum Hydrocarbons as diesel

TPH-G = Total Petroleum Hydrocarbons as gasoline

ND = Not detected at or above the Laboratory Reporting Limit

() = Laboratory Reporting Limit

April 23 1992 1708-001-00 Page 17 of 22

The initial suite of analyses selected for the two 10,000-gallon USTs and the 5,000-gallon UST excavation samples included:

Total Petroleum Hydrocarbons (TPH as Diesel and Gasoline)	EPA Method 8015 modified
Volatile Organic Compounds (Benzene, Toluene, Total Xylenes, and Ethylbenzene (BTXE))	EPA Method 8020
Lead	EPA Method 7420

The suite of analyses selected for the 750-gallon UST excavation samples included:

Total Petroleum Hydrocarbons (TPH as Diesel and Gasoline)	EPA Method 8015 modified
Volatile Organic Compounds (Benzene, Toluene, Total Xylenes, and Ethylbenzene (BTXE))	EPA Method 8020
Halogenated Volatile Organics	EPA Method 8010
Semi-Volatile Organics	EPA Method 8270
Oil And Grease	EPA Method 5520F
Cadmium (Cd)	EPA Method 7130
Chromium (Cr)	EPA Method 7190
Lead (Pb)	EPA Method 7420
Nickle (Ni)	EPA Method 7520
Zinc (Zn)	EPA Method 7950
PCBs	EPA Method 8080

The initial suite of analyses selected for the Product Lines and Fuel Dispenser Islands excavation samples included:

Total Petroleum Hydrocarbons (TPH as Diesel and Gasoline)	EPA Method 8015 modified
Volatile Organic Compounds (Benzene, Toluene, Total Xylenes, and Ethylbenzene (BTXE))	EPA Method 8020



April 23 1992 1708-001-00 Page 18 of 22

The suite of analyses selected for the soil stock piles from the three UST excavations included:

Total Petroleum Hydrocarbons (TPH as Diesel and Gasoline)

EPA Method 8015 modified

Volatile Organic Compounds (Benzene, Toluene, Total Xylenes, and Ethylbenzene (BTXE))

EPA Method 8020

The results of the analyses are presented in Tables 1 and 2. Copies of all laboratory reports, Quality Assurance and Quality Control (QA/QC), Chain-of-Custody Records and sample location maps are presented in Appendix H.

Upon review of the laboratory data, Mr. Byrnes of the ACEHHMD, requested a soil and ground-water investigation in the area of the UST-1/UST-2, UST-3 excavations, and the associated product GRC submitted to the USPS a proposal lines/dispensing islands. February 1992 to address the soil and/or ground water contamination.

4.0 CONCLUSIONS

Between November 4, 1991, and January 10, 1992, GRC personnel provided construction observation support during the following operation at the Oakland Main Post Office:

- Excavation of an area for the removal of two 10,000-gallon, diesel, single-walled steel tanks and associated piping;
- Excavation of an area for the removal of one 5,000-gallon, gasoline, single-walled steel tank and associated piping;
- o Excavation of an area for the removal of one 750-gallon, waste oil, single-walled steel tank and associated piping;
- Removal and transportation of each aforementioned USTs from the site to a designated recycling facility;
- o Back-fill of the removed tank area with pea gravel;
- Excavation of soils around each of the removed USTs including initial abatement of contaminated soils;
- Demolition of the existing fuel dispensing islands including two pump dispenser units;
- o Transportation of contaminated soils to the two separate designated landfills;
- o Installation of three new 12,000-gallon double-walled, Glasteel USTs;
- o Installation of electrical and plumbing piping associated with the UST;
- o Construction of two new fuel dispensing pump island structures with one double hose pump dispenser;
- o Trenching and conduit placement for the TLS-350 control line;
- A system integrity test on the three newly installed 12,000gallon USTs and associated plumbing;
- o Installation of a leak detection system (TLS-350); and
- o Refinishing of the surface overlying and surrounding the new UST and utility trench with concrete and asphalt paving.



April 23 1992 1708-001-00 Page 20 of 22

Following January 10, 1992, GRC was not authorized to continue the observation phase of the project. However, GRC personnel contacted EAGAN personnel at regular intervals throughout the remainder of the construction activities with regards to the construction progress.

The three new double-walled Glasteel USTs, associated plumbing, and electric conduits were installed in a new location at the VMB. However, the fuel dispensing island structures were constructed at the locations they previously occupied. All associated appurtenances were installed at the OMPO at the time of this report submittal.

April 23 1992 1708-001-00 Page 21 of 22

5.0 REFERENCES

- American Chemical Society, 1988, "Principles of Environmental Sampling," ACS Professional Reference Book, pp. 73-83.
- California State Water Resources Control Board, 1987, "Leaking Underground Fuel Tank Field Manual: Guidelines for Site Assessment, Cleanup, and Underground Storage Tank Closure," Sacramento, CA, 118 pages.
- San Francisco Bay Regional Water Quality Control Board, June 1988, "Regional Board Staff Recommendations For Initial Evaluation and Investigation of Underground Tanks, Regional Recommendations." Tri-Regional Board Staff.
- San Francisco Bay Regional Water Quality Control Board, August 1990, "Recommendations for Preliminary Evaluation and Investigation of Underground Tank Sites." Tri-Regional Board Staff.
- United States Environmental Protection Agency, 1986, "Test Methods for Evaluating Solid Wastes, Physical/Chemical Methods," U.S. EPA Office of Solid Waste and Emergency Response, Washington D.C., Document Number SW-846.

APPENDIX A

GRC Project Update Chronologies

Summary of Laboratory Results November 8,1991

A total of eight soil samples were collected by Trace Analysis Laboratory from each of the excavations. The four excavations were for the removal of the following USTs and their associated product lines: one 5,000-gallon fuel storage UST (Samples 1 and 2); two 10,000-gallon fuel storage USTs (Samples 3A, 3B, 4A, and 4B); one 750-gallon waste oil UST (Sample 5); and the product lines from each of the fuel storage tanks (Samples 6, 7, and 8).

5,000-gallon UST Soil Sample 1 and 2:

TPH-Diesel - 260 mg/kg and 1,200 mg/kg

TPH-Gasoline - 3.4 mg/kg and 76 mg/kg

Benzene - 0.80 mg/kg and 0.59 mg/kg

Toluene - 0.0068 mg/kg and 0.23 mg/kg

Ethylbenzene - 0.015 mg/kg and 3.5 mg/kg

Xylenes - 0.12 mg/kg and 52 mg/kg

Two 10,000-gallon USTs, Soil Samples 3A, 3B, 4A, and 4B:

TPH-Diesel - 2,000 mg/kg, ND, 220 mg/kg, and 2,500 mg/kg

TPH-Gasoline - 59 mg/kg, ND, 150 mg/kg, and 620 mg/kg

Benzene - 0.27 mg/kg, ND, 7.5 mg/kg, and 37 mg/kg

Toluene - 0.79 mg/kg, ND, 19 mg/kg, and 1.6 mg/kg

Ethylbenzene - 1.4 mg/kg, ND, 8.9 mg/kg, and 53 mg/kg

Xylenes - 5.3 mg/kg, ND, 32 mg/kg, and 130 mg/kg

Lead (composite) - 7.2 mg/kg

750-gallon UST, Soil Sample 5:

TPH-Diesel - ND

TPH-Gasoline - ND

Benzene - 0.0068 mg/kg

Toluene - ND

Ethylbenzene - ND

Xylenes - ND

Oil and Grease - ND

Cadmium - 1.0 mg/kg

Chromium - 24 mg/kg

Lead - 68 mg/kg

Nickel - 18 mg/kg

Zinc - 90 mg/kg

Methylene Chloride - 2.5 ppb

Tetrachlorethene - 9.8 ppb

All other EPA Method 8010 analytes - ND

All EPA Method 8080 analytes - ND

All EPA Method 8270 analytes - ND

Fuel Product Lines, Soil Samples 6, 7, and 8:

TPH-Diesel - 1.4 mg/kg, 7,900 mg/kg, and 2,900 mg/kg

TPH-Gasoline - 36 mg/kg, 210 mg/kg, and 610 mg/kg

Benzene - 11 mg/kg, ND, 3.4 mg/kg

Toluene - 0.36 mg/kg, 0.45 mg/kg, and 60 mg/kg

Ethylbenzene - 0.82 mg/kg, 1.4 mg/kg, and 27 mg/kg

Xylenes - 8.1 mg/kg, 14 mg/kg, and 170 mg/kg

Summary of Project Status

USPS, Oakland GMF

November 14, 1991

<u>Date</u> <u>Summary</u>

- November 4, 1991 Start-up of the job and saw cutting of concrete slabs over the Underground Storage Tanks (UST).
- November 5, 1991 Demolition of the pump island and the concrete slabs; begin the placement of several sheet piles in the 10,000-gallon UST excavation.
- November 6, 1991 Continued to drive the sheet piles for shoring the excavation; excavated several test pits to identify the potential extent of the visible contamination.
- November 7, 1991 Sheet pile driving is finished; the 2 10,000-gallon USTs and the 5,000-gallon UST were uncovered.
- November 8, 1991 Steam clean each UST and ready USTs for removal; removal of all four USTs from the ground; collected soil samples from each UST and pump island excavation.
- November 11, 1991 Began backfilling of the excavations; collected a soil sample from the new UST excavation location.
- November 12, 1991 Continued the backfilling of the excavations; Excavated soil for the new UST location.

- November 13, 1991 Placed the three new USTs into the excavation and began the backfilling operation to the top of the tanks; installed one above ground storage tank (waste oil) on top of prepared concrete pad.
- November 14, 1991 Continued backfilling the old UST excavations; filled new USTs with water.

Summary of Project Status

USPS, Oakland VMF

December 4, 1991

Summary

<u>Date</u>

- November 15, 1991 Eagan & Company continued backfilling all three of the UST excavations to 95% relative compaction, finishing at baserock grade. Eagan will complete all backfilling and refinishing after all underground work is completed.
- November 18, 1991 Eagan & Company began to excavate the utility trench, avoiding all existing underground services.
- November 19, 1991 Eagan & Company finished the utility trench and found potentially contaminated soil (had noticeable hydrocarbon odor) to approximately 22-feet from the north east corner of the maintenance building.
- November 20, 1991 The removal of the contaminated soil to McKittrick disposal facility in Southern Californians completed. Approximately 300 yards of material was hauled by 19 trucks for disposal of the soil.
- November 21, 1991 Several truck loads sent the remaining contaminated soil to McKittrick in the AM. Placed steel and poured concrete over the waste oil UST site to close the facility.
- November 22, 1991 No work performed at the site.
- November 25, 1991 Mobilization and set-up of the electrical and the plumbing crew was accomplished.
- November 26-27, 1991 Began installation of the new plumbing and electrical lines

EBC116: 1708UDT2

- November 28-29, 1991 No work performed during the holidays.
- December 2, 1991 No plumbing work was completed. The electrician set-up conduit for the power and signal wires.
- <u>December 3, 1991</u> Eagan's crew continued progressing towards finishing more plumbing and electrical.
- December 4, 1991 Plumber began connecting the USTs to their respective destination at the pump island. Eagan will begin to clean-up all remaining unnecessary materials and give back to USPS numerous car stall. Eagan cut the trench to the main building for the product line.

BC116: 1708UDT2

Summary of Project Status USPS, Oakland VMF December 18, 1991

Date <u>Summary</u>


December 5-6, 1991 Eagan & Company continued the installation of the main product lines from each UST. The product, vent and vapor return lines were connected to each of the USTs (only the gasoline UST has a vapor return line connection). The manhole covers on the three USTs were set in-place to house the vent, product, vapor return lines.

The electrician has begun to install the electrical conduits from the interstitial space of each UST which connects to the main inventory computer and alarm system. Plastic electrical conduit was connected in the utility trench adjacent to the VMF building.

<u>December 9-10, 1991</u> Eagan connected into the existing electrical conduits in the sidewalk adjacent to the VMF building. Majority of the conduit system for the alarm and power system has been completed.

The majority of the product line had been placed in the utility trench and will be glued at a later date prior to testing of the system for tightness.

December 11, 1991 Eagan installed the over-head water and air lines to the existing outlets in the canopy. The Trac system was electrically connected to the conduits from the three USTs and fuel dispensing pumps. The two fuel dispensing pump island structures were set in-place. All product lines were connected into the pump islands. The product lines will be final tested with the County inspector sometime during the week of December 27.



- The pump island is continued to be December 12-13, 1991 constructed and is ready for the connection to the pump itself after the concrete is poured for the pad. The pad will be poured after the final inspection and testing passes.
- December 16-17, 1991 The two-inch diameter diesel product line is connected to the middle diesel UST and will go to the small emergency tank inside the main processing building for usage during black-outs.

Summary of Project Status USPS, Oakland VMF January 2, 1992

Date

Summary

- December 18-20, 1991 The County inspector inspected the primary joints for all product and the vapor recovery line from the USTs to the pump islands. All joints were not leaking under primary pressure. The secondary plumbing inspection also was conducted without incident. The electrician continued to set-up all the electrical conduit for the sensor and power system.
- <u>December 23, 1991</u> Eagan & Company began backfilling the UST excavation to top of the USTs, the utility trench, and the two 10,000-gallon UST excavation to grade.
- <u>December 24-25, 1991</u> No work was completed due to the holidays.
- December 26-27, 1991 Finished backfilling of the excavations and graded the pea gravel to grade. Began placement of the steel for concrete pad in the two 10,000-gallon UST excavation. Poured concrete in the utility trench in the area of the truck access lane. A backhoe excavated the utility trench for the 100-gallon generator day tank. The 1-inch product and over-spill line was installed to the day tank.
- <u>December 30-31, 1991</u> Eagan & Co. finished the concrete forms and tying of the steel for the pad. Poured concrete in the utility trench, old UST pad, and the pump islands. The primary inspection of the day tank product and over-spill was conducted and passed.
- January 1, 1992 No work was completed due the holiday.

<u>January 2, 1992</u> Eagan will continue to install the day tank system and the secondary pressure test will conducted for the day tank system.

Further work to be completed by Eagan & Co. is as follows: Finish all concrete pouring work for the newly installed USTs; 2) Pressure test each of the new USTs for leaks; 3) Install day 4) After installation of the day tank, remove the tank system; UST that supplies the diesel to the generator presently; Set-up pump islands; 6) Other miscellaneous tasks. Eagan completion informed GRC that the estimated time of is approximately two weeks.

KBC116: 1708UDT4

Summary of Project Status USPS, Oakland VMF January 13, 1992

Date

Summary

- January 2-3, 1992 The secondary containment diesel day tank product line was tested for integrity and was passed by the County representative. Concrete was poured to re-open the truck access area for the northern loading docks. Additional concrete was poured in the area of the 10,000-gallon UST excavation to finish the concrete work in this area. At a later date Eagan will place asphalt over the 5,000-gallon UST excavation.
- January 6, 1992 The UST integrity test for each of the three 12-gallon USTs was delayed until Eagan could pump out all the rain water in the new tank excavation. The test was canceled until January 6, 1992. Installation of the plumbing for the 1,000-gallon waste oil above ground storage tank (AGST) was mostly completed by the days end.
- January 7, 1992 Mr. Frank Miller of the Western America Tank Testing, Inc. company performed the tank integrity test for all three 12,000-gallon USTs. Apparently the test passed for all three tanks.
- January 8, 1992 No work was performed on this day.
- January 9, 1992 The installation of the two fuel dispensers was begun. Eagan's plumber connected the product lines and the one vapor return line to the gasoline dispenser. The 1,000-gallon waste oil AGST plumbing was completed. The AGST plumbing was tested by Eagan and apparently was operational. Only the electrical connections into the TLS 350 computer system has to be completed before the AGST can be fully operational.

1708-001-00 January 13,1992

January 10, 1992 Both fuel dispenser plumbing systems was connected by the end of the day. The electrician began connecting the over-head conduits for the TLS 350 computer system.

Note: As of January 10, 1992, all field hours per the contract agreement, dated November 15, 1991, have been used up. Eagan has at least two to three weeks of work to be completed before they are finished. At this time no system has been completed.

There is no hours in the budget to go to site. Our contract with the USPS, the field portion, was ended as of 1-10-Charles Wren has been notified in the project 92. update notes faxed to him by me. The remaining work is Install 100-gallon diesel day as follows: 1) Remove the old 1,000-gallon tank for generator; 2) diesel UST for the generator; 3) Install the TLS 350 electrical system for the USTs; 4) Finish concrete pads over the USTs; 5) Install electrical to the waste oil AGST, and 6) any punch list items. (+10.0)Hours per/week)

Summary of Project Status USPS, Oakland VMF March 19, 1992

<u>Date</u>

Summary

January to March 1992 To date the project as outlined in the original Scope of Work has been completed. Additional work (IE: installation of generator and boiler day tank system and the removal of the associated diesel supply UST) has not been completed. Robert Eagan of EAGAN has informed GRC personnel that he is going to meet with Charles Wren on March 26, 1992 for the final inspection and sign-off for the primary and original Scope of Work. Mr. Eagan also stated that a letter would be forth coming in regards to this meeting.

The systems completed since the last GRC site inspection on January 10, 1992, includes the set-up and running of the TLS-350 leak detection system; the set-up and running of the fuel dispensing island and pump system of the three new UST; installation of the waste oil AGST and system; the closing of all excavations, and; the general clean-up of the site.

3KBC116: 1708UDT6

APPENDIX B Alameda County Health Permits

ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY DEPARTMENT OF ENVIRONMENTAL HEALTH HAZARDOUS MATERIALS DIVISION 80 SWAN WAY, ROOM 200 OAKLAND, CA 94621 PHONE NO. 415/271-4320

distance of a potent to optice is dependent on counte with eccipted pens and all applicable laws rendiations Department are to assure compliance with State and able and essentially meet the requirements of Stath These plans have been reviewed end found to be otal health laws. Changes to your plans indicated t s had been a command herein is now released to the state of the second of the second by the fell of any or increased than purmits for construction DEPARTMENT OF ENVIRONMENTAL HEALTH THERE IS A FILLARICIAL PERIALTY FOR NOT OBTAILM A TUSSE INSPLOTIONS. Telephone: (415) 874-7237

have been reviewed and found to be accept seantishy meet the requirements of Stath Accept seantishy meet the requirements of Stath Accept seantishy meet the requirements of Stath Accept seasons to your plans indicated by Children to Assure compliance with State and Relative to Assure to Assure the partition of the least to Assure that the least the least to Assure that the least the least the least to Assure that the least the l Procure Test

—Procure Test
—Procure Test
—Procure Test
—In Covering of Tenk and Piping D

—In the operate is dependent on CRITICAL PENALTY FOR NOT DEED INSECTIONS.

UNITED BERNALTY FOR NOT DEED INSECTIONS. -Final Inspection Oakland, CA 94612 -Prousure Test -firs-Covering of \$ 60

1.	Business Name	Main Post	Office		
	Business Owne	u. S. Pos	tal Service		
2.	Site Address	1675 - 7t	h Street		<u> </u>
	city	Oakland	Zip 94615	Phone 540/874-8476	<u>) </u>
3.	•	ss same			
	City	/ · · ·	Zip	Phone	
4.		Ţi		Service Center	
	· · · · · · · · · · · · · · · · · · ·	•		Bruno, CA zip 9409	
5.					
6.	Contractor	R. S. Eagan &	Co.		
	Address	1992 National	Avenue	······································	
	city	Hayward		Phone 510/732-730)0_
	License Type	A,B,C-8,C-10,C	-61/D40 _{ID#} 476428	}	
7.	Consultant G	eo/Resource Con			
	Address8	51 Harrison St			********
	City San Fr	ancisco 9410	7 Phone 415/	771-3177	

A C CEPTED

A CEPTED

A C CEPT

1.	Business Name	Main Post UII	ice			
		U. S. Postal				
2.	Site Address _	1675 - 7th St	reet	J.,,		
		Dakland				
3.	Mailing Addres	ss <u>same</u>				
	city		Zip	Phone		
4.	Land Owner	U. S. Postal Servi	ice, Facilities	Service	Center	
	Address85	O Cherry Avenue	City, State Sa	n Bruno	, CA zip 94099-0	0310
	EPA I.D. No.	CAC 000 643 69	16			
6.	Contractor	R. S. Eagan & Co.				
	Address	1992 National Aver	nue			
	city	Hayward		_ Phone	510/732-7300	
	License Type	A,B,C-8,C-10,C-61,	/D40ID# <u>4764</u> 2	28		
7.	Consultant G	eo/Resource Consult 51 Harrison St	tants, Inc.			
	Address City _San Fr	ancisco 94107	Phone 41	5/771-31	77	

ACKNOWLEDGMENT Bay Area Air Quality Management District acknowledges receipt of your Tank Removal/Contaminated Soil Excavation Notification Form received on 10.17.91	Aeration of Contaminanted Soil and Removal of Underground Storage Tanks NOTIFICATION FORM Removal or Replacement of Tanks. Excavation of Contaminated Soil NFORMATION REGULATION 8, RULE 40 Aeration of Contaminated Soil
OWNER NAME U. S. Postal Service	
SPECIFIC LOCATION OF PROJECT Main Post Of	fice .
TANK REMOVAL	CONTAMINATED SOIL EXCAVATION
SCHEDULED STARTUP DATE 1/4/91	SCHEDULED STARTUP DATE
VAPORS REMOVED BY:	STOCKPILES WILL BE COVERED? YES NO
[X] WATER WASH	ALTERNATIVE METHOD OF AERATION (DESCRIBE BELOW):
[] VAPOR FREEING (CO ²) [] VENTILATION	(MAY REQUIRE PERMIT)
CONTRA	ACTOR INFORMATION
NAME R. S. Eagan & Co.	CONTACTBob Eagan
ADDRESS 1992 National Avenue	PHONE (510)732-7300
CITY, STATE, ZIP Hayward, CA 94545	-1787
	LTANT INFORMATION (IF APPLICABLE)
NAME	टिम्मुन्दि विविधान
ADDRESS	PHONE (TIE !! V E)
CITY, STATE, ZIP	OCT 2 S 1991
	EAGAN & COMPANY
FOR OFFICE USE ONLY	0
DATE RECEIVED . 10.17.9/	BY C
CC: INSPECTOR NO. 556 DATE	10.22-91 BY (INIT.)
TELEPHONE UPDATE: CALLER	1 1
BAAQMD N #	

House No. 1675 - 7th Street Avanue Owner U. S. Postal Service Address 850 Cherry Avanue San Bruno 9009 Mene 415-742-4526 Applicant R. S. Eagan & Company Address 1992 National Avenue Hayward 9454 Mene 732-7300 Dimensions of street (sidewalk) surface to be disturbed X Number of Tanki 3 Capacity 12.000 Eallown and 1,000 above ground Remarks: This Permit is granted in accordance with existing City Ordinances. Owner hereby agrees to ramove tanks on discontinuance of use or when notified by the City Authorities. When installing, removing or repairing tanks, no open flams to be on or near premises. Approved Fire Marshal Approved Drainage Division Engineering Dept. EXCAVATING PERMIT Issued in accordance with Ord. No. 278 CMS, Sec. 4-2.04 tquare feet of digging or removal granted. CERTIFICATE OF TANK AND EQUIPMENT INSPECTION Inspection Fee Paid - \$200.00 CM / MST MARSHALL STARS Fire Marshal Inspection Fee Paid - \$200.00 CM / MST MARSHALL STARS NOTICE				Eventual Per	_is_Ci		N.	
Permit to Excavate and Install, Repair, or Remove Inflammable Liquid Tanks. No. 9500 Ostland, California. October 15, 19. 91 PERMISSION IS HEREBY GRANTED.TO Install MANAGONXXXXANA Gesciline tank and excavate commencing feet instide. Jin on the side of Street Avenue On the Side of Street October 15, 19. 91 On the Side of Street October 15, 19. 91 On the Side of Street October 15, 19. 91 On the Side of Street October 15, 19. 91 Install National Avenue Sain Entropy Regulates: Service Center Avenue San Entropy Regulates: Service Center Service Center Avenue San Entropy Regulates: Service Center Avenue San Entropy Regulates: Service Center Service Service Center Service Servi		CIT		• •		?		
PERMISSION IS HEREBY GRANTED TO install. MANGESTAXXASPIBLE On the	Permit to		٠,		. st. []	أخارسنا أخاط		
PERMISSION IS HEREBY GRANTED. TO Install. XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	i cimii to	Excurdit dila ilisi					* *	
on the	BEDWISSION IS HEDE	RY CRANTED TO Total			٠.		•	
Avenue House No. 1675 - 7th Street House No. 1675 - 7th Street House No. 1675 - 7th Street Avenue Owner, U. S. Postal Service Address 80 Cherry Avenue San Bruno 94094 hone 415-742-4526 Applicant R. S. Eagan & Company Address 1992 National Avenue Hayward 9454 hone, 732-7300 Dimensions of street (tidewalk) surface to be disturbed X. Number of Tenks 3 Capacity 12,000 above 8100nd ascl. Remarks: This Permit is granted in accordance with existing City Ordinances. Owner hereby agrees to remove tanks on discontinuance of use or when notified by the City Authorities. When installing, removing or repairing tanks, no open flame to be on or near premises. Approved Approved Fire Marshal Approved Fre Marshal The receipt of \$ speciel deposit is hereby acknowledged. GENERAL DEPOSIT. BUREAU OF PERMITS AND LICENSES. By Fire Marshal Inspection Fee Paid \$ 200.00 (A*HAST NA** MATCHES**) NOTICE NOTICE	TERMISSION IS HERE	DI GRANIED, IO INITAL	_	STREET GESON	ine rank and exca	vare commencing		
House No. 1675 - 7th Street Owner U. S. Postal Service Address San Bruno Facilitries: Service Center A15-742-4526 Applicant R. S. Eagan & Company Address 1992 National Avenue Hayward 9454 hose 732-7300 Dimensions of street (sidewalk) surface to be disturbed X Number of Tanks 3 Capacity 1,000 above ground accordance with existing City Ordinances. Owner hereby agrees to remove tanks on discontinuance of use or when notified by the City Authorities. When installing, removing or repairing fanks, no open flame to be on or near primites. Approved Fire Marshal Approved Drainage Division Engineering Dept. EXCAVATING PERMIT Issued in accordance with Ord. No. 278 CMS, Sec. 4-2.04 square feet of digging or removal granted. CERTIFICATE OF TANK AND EQUIPMENT INSPECTION Inspected and passed on 19 BUREAU OF PERMITS AND LICENSES. By Fire Marshal NOTICE	on theside of		Ayenue		eetof			Street Avenue
Approved Direction Fee Paid				Pres				
Dimensions of street (sidewalk) surface to be disturbed X Number of Tenks 3 Capacity 12,000 Gallons seed Remarks: This Permit is granted in accordance with assisting City Ordinances. Owner hereby agrees to remove tanks on discontinuence of use or when notified by the City Authorities. When installing, removing or repairing tanks, no open flame to be on or near premises. Approved Approved Drainage Division Engineering Dept. EXCAVATING PERMIT Issued in accordance with Ord. No. 278 CMS, Sec. 4-2.04 square feet of digging or removal granted. CERTIFICATE OF TANK AND EQUIPMENT INSPECTION Inspected and passed on 19 BUREAU OF PERMITS AND LICENSES. By Fire Marshal Inspection Fee Paid - \$200.00 CM 4/4957 MM 4657285 NOTICE	Owner U. S. Postal Servic	e	Addres	San Bru 850 Che	no Facilit rry Avenue	les Service San Bruno	Center	15-742-4526
This Permit is granted in accordance with axisting City Ordinances. Owner hereby agrees to remove tanks on discontinuence of use or when notified by the City Authorities. When installing, removing or repairing tanks, no open flame to be on or near premises. Approved Fire Marshal Approved Drainage Division Engineering Dept. EXCAVATING PERMIT Issued in accordance with Ord. No. 278 CMS, Sec. 6-2.04	Applicant R. S. Eagan & Com	pany	Addres	1992 Na	ational Ave	nue Hayward	1 94545 7	32-7300
This Permit is granted in accordance with axisting City Ordinances. Owner hereby agrees to remove tanks on discontinuence of use or when notified by the City Authorities. When installing, removing or repairing tanks, no open flame to be on or near premises. Approved Fire Marshal Approved Drainage Division Engineering Dept. EXCAVATING PERMIT Issued in accordance with Ord. No. 278 CMS, Sec. 6-2.04	Dimensions of street (sidewalk) surface	to be disturbed	_x	Number	of Tenke 3	Capacity	12,000	Gallons, Jeach
Owner hereby agrees to remove tanks on discontinuance of use or when notified by the City Authorities. When installing, removing or repairing tanks, no open flame to be on or near premises. Approved Fire Marshal Approved Drainage Division Engineering Dept. EXCAVATING PERMIT Issued in accordance with Ord. No. 278 CMS, Sec. 4-2.04 square feet of digging or removal granted. The receipt of \$ special deposit is hereby acknowledged. GENERAL DEPOSIT. BUREAU OF PERMITS AND LICENSES. EXCAVATING PERMIT Inspected and pessed on 19 Fire Marshal Inspection Fee Paid . \$200.00 CM */4557 Mc*/157285* NOTICE	Remarks:			·			1,000 abo	ve ground
EXCAVATING PERMIT 1sseed in accordance with Ord. No. 278 CMS, Sec. 6-2.04 square feet of digging or removel granted. State of the receipt of \$,,	F	ire Marshal			To the M		•
Issued in accordance with Ord. No. 278 CMS, Sec. 6-2.04			neering Dept.		W .		E	* / - /
The receipt of \$special deposit is hereby acknowledged. GENERAL DEPOSIT. BUREAU OF PERMITS AND LICENSES. Inspection Fee Paid								
Special deposit is hereby acknowledged. GENERAL DEPOSIT. BUREAU OF PERMITS AND LICENSES. By Fire Marshal Inspection Fee Paid				 Etntli		S	,	
Inspection Foe Paid \$ 200.00 Ch 4/4957 NC 4658285 NOTICE	The receipt of \$	special deposit is hereby a	icknowledged.	.'	and the state of t	ANK AND E	QUIPMENT	INSPECTION
Inspection Fee Paid : 200.00 Ch 4/4957 No 4658285 NOTICE	GENERAL DEPOSIT.	BUREAU OF PERMITS AN	D LICENSES.	By	and passed on			
							•	Fire Marshal
	Inspection Fee Paid	- \$ 200.00 Ch #14	957 rec 46.	58285		NOTIO	E .	
Received by G. M. Johnson Detoile Covering tanks, Above Cartificate must be Signed.			.,	Befor	e Covering Tai	nks, Above Ce	rtificate Mus	t Be Signed.
Received by G. M. Johnson FIRE PREVENTION BUREAU When ready for Inspection notify Fire Prevention Sureau, 273-3851	FIRE PREVEN	TION BUREAU	· · · · · · · · · · · · · · · · · · ·	When read	y for inspection in	ofify Fire Preven	rion Bureau, 27	3-3851

THIS PERMIT MUST BE LEFT ON THE WORK AS AUTHORITY THEREFOR.

7 13 10	The state of the s		Excavati	on Permit Gran	ded	-		No	
0 [3 (P) [3] W [3 [] 1 8 1991	CITY to Excavate and Insta	•	OA	KLAN	D ~	able Liqui	d Tani	Tank ?	
IN COMP	"W								19 91
PERMISSION IS	HEREBY GRANTED TO XXXXXXX		. :	-					
on the south side of	7th Street	Street Avenu	200	foot_eas	sto	f	Wood_S	treet_	. Street Avenue
House No. 1675 - 7th	• .		•	Present Stor	•	<u> </u>			
Owner U.S. Postal Serv		•							
Applicant R. S. Eagan &			199	2 nationa	1 Ave	. Hayward	94545	_ Phone_7 3	32-7300
Dimensions of street (sidewalk) su	rface to be disturbed	_x		umber of Ten	ks f	Capacit	<u>- 3,8</u>	XX 00 abov	Gallons, each. e ground was
Remarks:			<u> </u>						6
Approved	When installing, removing o	e Marshal	ks, no op	n tiality to by		N			
,	Drainage Division Engin	eering Dept.	*		W			E	
	ATING FERMIT	-	- '.'		لب				
	itk Ord. No. 278 CMS, Sec. 6-2.0				70.00	S	· ,],		•
	square feet of digging or remo	oval granted.	C	ERTIFICATI	E OF T	ANK AND	EQUIF	MENT I	NSPECTION
The receipt of \$	special deposit is hereby a	cknowledged.	(Insp	ected and pass	sed on				
GEHERAL DEPOSIT.	BUREAU OF PERMITS AND	LICENSES.	Ву		· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·	<u> </u>	Fire Marshal
		arl.	۱۹. در دستاند	ه را ایک در ایک در ایک در ایک در					
Inspection Fee Paid	200.00 Ch 3/4	7-16 rect	65128	Before Cove	%	NOT	CALIF	-i- Mo-i	Re Signed
Received by G. M. John:	SON		Wh	n ready for in	, -			. /	=
71115	· Neglit list be set	T ÅN TU	= W <i>o</i> \		المالية المعارض	OITV THE			-


538-68 (5.67)

APPENDIX C Rinsate Manifest

A	nnt or type. Form designed for use on eilte (12-pitch typewrite	B1).					Socramento, California
	I GIVIFORIVI FIAZARDOGS	rs US EPA ID No. D : 0 : 0 : 6 : 4 : 3 : 6 : 9 : 6 0	nfest Documer	0 1	2. Poge 1	k not req	on in the shaded areas ulred by Federal law,
	U. S. POSTAL SERVICE - SAN BRUI 850 Cherry Avenue, San Bruno,	NO FACILITY SVC. CEN		A State	Manfest Document		31507249
	4 Generator's Phone (415) 550-5236/5235	ATTN: CHARLES WRI	เท	B.31010		gardengs La East a	
	5. Transporter 1 Company Name	6, US EPA ID Number	411	C. State	Transporter's ID	×2005:	36 umsterführigen 36
	H & H Ship Service Company	C:A:D:0:0:4:7:7:	1:1:6:8	cD _e . Iron	aboutette Epotre (1997)	(415)	543-4835
	7. Transporter 2 Company Name	8. US EPA ID Number					2 - 4 .2 12.33333.334.
	Designated Excitity Name and Site Address	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1	F. Trans	porter's Phone ************************************	લીકલેઇ હાલ્ટ જારા સુરક્ષિત્રમાર	r (m. 1900), i ma karasan kalabasa. Kalendaran Maria Wali (m. 1900), ika
	9. Designated Eccity Name and Side Address H. & H. Ship Service Company 220 China Basin Street San Francisco, CA 94107				A, D, O, O, &	$\mathbf{l}_1 \mathcal{I}_1 \mathcal{I}_1$	1,1,6,8
1	San Francisco, CA 94107	CIA:D:0:0:4:7:7:	1:1:6:8	H'Foeli	hys Phone 115) 543-41	135	
	11. US DOT Description (including Proper Shipping Name, Hazara		12. Conto		13. Total Quantity	14. Unit	I. Woste Number
1	a						State
Ģ	OIL AND WATER	.				Ì	133,241 EPA/Other
E N	NON-RCRA HAZARDOUS WASTE LIQUI	LD	0,0 1	$T \mid T$	012151010	G	7.000
E	D .						Sicre
R A							EPA/Otner
Î	С.	······································		<u> </u>	- L - L - 1	 	State State
O R							EPA/Other
ì			1 1	1	<u> </u>		EPA/ORBH
	d.						Sicile
							EPA/Other
	J. Additional Descriptions for Materials Listed Above	Television (m. 1901)	· J J		I I I I I I I I I I I I I I I I I I I	Listed Ab	ove . 1 7 1 25% 1.3
	FUEL, OIL AND WATER			Q.	<mark>C</mark> SUSTICE **	b.	
	DDARTY B. 444270			C.	grand to a	d	A Comment of the comm
	PROFILE #A1379 15. Special Handling Instructions and Additional Information		ing the milities		SAP (3 4 2 1 2 1 2 1 2 1 2 1 2 2 2 2 2 2 2 2 2	<u> </u>	
	JOB #9608		JOB STT	TE · MI	AIN POST OF	שרדשה	ሚህ ሮ ወሞአ
	24 Hr. Emergency Contact: # H	& H (415) 543-4835	i		675 7th & V		
	APPROPRIATE PROTECTIVE CLOTHIN				akland, Cal		
	16. GENERATOR'S CERTIFICATION: It hereby declare that the co- packed, marked, and labeled, and are in all respects in pro-	ontents of this consignment are fully ar	nd accurately o	described applicable	l above by proper st	nipping no	ame and are classified,
1	If I am a large quantity generator, I certify that I have a	program in place to reduce the volum					vernment regulations,
1			ne and toxicity	of waste	generated to the o	dearee i h	cve determined to be
	threat to human health and the environment; OR, if I am a	acticable method of treatment, storage	, or disposal cu	o Vitnenu	vailable to me which	d l eerget seximinim	cove determined to be
	threat to human health and the environment; OR, if I am a management method that Is available to me and that I ca	octicable method of treatment, storage small quantity generator, 1 have mode o	, or disposal cu	o Vitnenu	vailable to me which	d l eerget seximinim	cove determined to be
	threat to human health and the environment; OR, if I am a management method that is available to me and that I ca Printed/Typed Name	octicable method of treatment, storage small quantity generator, I have made a n afford. Signature	, or disposal cu	o Vitnenu	vailable to me which	d l eerget seximinim	ove determined to be the present and future as select the best waste
	threat to human health and the environment; OR, if I am a management method that is available to me and that I ca Printed/Typed Name	octicable method of treatment, storage small quantity generator, I have made a n afford. Signature	, or disposal cu	o Vitnenu	vailable to me which	degree the minimizes eration an Monte	the present and future to be the present and future to select the best waste. The Day Year
*	threat to human health and the environment; OR, if I am a management method that is available to me and that I co Printed/Typed Nome STEVEN K - WAKE 1 SV	octicable method of treatment, storage small quantity generator, I have made a n afford. Signature	, or disposal cu	o Vitnenu	vailable to me which	degree t h minimizes eration an	the present and future to be the present and future to select the best waste
T R	threat to human health and the environment; OR, if I am a management method that is available to me and that I ca Printed/Typed Name	octicable method of treatment, storage small quantity generator, I have made a n afford. Signature	, or disposal cu	o Vitnenu	vailable to me which	degree the minimizes eration an	the present and future to select the best waste to the Day Year 1 0 8 9 1
TRAN	threat to human health and the environment; OR, if I am a management method that is available to me and that I co Printed/Typed Name STEVEN K - WAKE SV = 17. Transporter I Acknowledgement of Receipt of Materials	octicable method of treatment, storage small quantity generator, I have made an afford. Signature	, or disposal cu	o Vitnenu	vailable to me which	degree the minimizes eration and Mont	the present and future to select the best waste to the Day Year 1 0 8 9 1
TRANSP	threat to human health and the environment; OR, if I am a management method that is available to me and that I co Printed/Typed Name TEVEN K - WAKE SV S 17. Transporter I Acknowledgement of Receipt of Materials Printed/Typed Name EDWARD G MILANO	octicable method of treatment, storage small quantity generator, I have made an afford. Signature	, or disposal cu	o Vitnenu	vailable to me which	degree the minimizes eration and Mont	th Day Year th Day Year 1 10 8 9 1
S P O	threat to human health and the environment; OR, if I am a management method that is available to me and that I co Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name EDWARD G. MILANO 18. Transporter 2 Acknowledgement of Receipt of Materials	Signature Signature Signature	, or disposal cu	o Vitnenu	vailable to me which	Moni	the present and future to be the present and future to select the best waste to the Day Year 1 10 8 9 1 to 8 9 1
S P O R T	threat to human health and the environment; OR, if I am a management method that is available to me and that I co Printed/Typed Name TEVEN K - WAKE SV S 17. Transporter I Acknowledgement of Receipt of Materials Printed/Typed Name EDWARD G MILANO	octicable method of treatment, storage small quantity generator, I have made an afford. Signature	, or disposal cu	o Vitnenu	vailable to me which	Moni	the present and future to be the present and future to select the best waste to be the Day Year 1 10 8 9 1 the Day Year 1 10 8 9 1
S P O R	threat to human health and the environment; OR, if I am a management method that is available to me and that I co Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name EDWARD G. MILANO 18. Transporter 2 Acknowledgement of Receipt of Materials	Signature Signature Signature	, or disposal cu	o Vitnenu	vailable to me which	Moni	the present and future to be the present and future to select the best waste to the Day Year 1 10 8 9 1 to 8 9 1
SPORTE	threat to human health and the environment; OR, if I am a management method that is available to me and that I co Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name EDWARD G. MILANO 18. Transporter 2 Acknowledgement of Receipt of Materials	Signature Signature Signature	, or disposal cu	o Vitnenu	vailable to me which	Moni	the present and future to be the present and future to select the best waste the Day Year 1 10 8 9 1 the Day Year 1 10 8 9 1
SPORTER	threat to human health and the environment; OR, if I am a management method that is available to me and that I co Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name EDWARD G. MILANO 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	Signature Signature Signature	, or disposal cu	o Vitnenu	vailable to me which	Moni	the present and future to be the present and future to select the best waste the Day Year 1 10 8 9 1 the Day Year 1 10 8 9 1
S P O R T E R	threat to human health and the environment; OR, if I am a management method that is available to me and that I co Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name EDWARD G. MILANO 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	Signature Signature Signature	, or disposal cu	o Vitnenu	vailable to me which	Moni	the present and future to be the present and future to select the best waste to the Day Year 1 10 8 9 1 to 8 9 1
SPORTER	threat to human health and the environment; OR, if I am a management method that is available to me and that I co Printed/Typed Name TEVEN K. WAKE SVS 17. Transporter I Acknowledgement of Receipt of Materials Printed/Typed Name EDWARD G. MILANO 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	Signature Signature Signature	o good forth ef	urently or fort to mir	vailable to me which nimee my waste gen	Moni	the present and future to be the present and future to select the best waste the Day Year 1 10 8 9 1 the Day Year 1 10 8 9 1
SPORTER FACILIT	threat to human health and the environment; OR, if I am a management method that is available to me and that I co Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name EDWARD G. MILANO 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	Signature Signature Signature	o good forth ef	urently or fort to mir	vailable to me which nimee my waste gen	Moni	the present and future to be the present and future to select the best waste the Day Year 1 0 8 9 1 1 1 1 1 1 1 1 1
SPORTER FACILI	threat to human health and the environment; OR, if I am a management method that is available to me and that I co Printed/Typed Name TEVEN K. WAKE SVS 17. Transporter I Acknowledgement of Receipt of Materials Printed/Typed Name EDWARD G. MILANO 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name 19. Discrepancy Indication Space	Signature Signature Signature Signature Signature Signature Signature Signature	o good forth ef	urently or fort to mir	vailable to me which nimee my waste gen	Moni	the present and future to be the present and future to select the best waste the Day Year 1

APPENDIX D

Subsurface Consults, Inc. Back-fill Report



January 7, 1992 SCI 364.022

Mr. Robert S. Eagan R. S. Eagan & Company 1992 National Avenue Hayward, California 94545

Soil Engineering Services During Backfill Oakland Main Post Office 1675 7th Street Oakland, California

Dear Mr. Eagan:

This letter summarizes the results of soil engineering services we performed during excavation backfill at the subject project. We understand that the site formerly contained underground fuel and waste oil storage tanks in two separate locations. The tanks were removed, and soil and groundwater samples were obtained and analytically tested by others.

Excavation Backfill

Excavation backfill took place on November 11 through 15, 1991. During backfilling, our field engineer visited the site on an intermittent basis.

Prior to our becoming involved with the project, we understand that a few feet of soil was placed and compacted in the former fuel tank excavations. Prior to backfill placement, the exposed surface at the former waste oil tank excavation was compacted. The concrete slabs beneath the former fuel tanks were reportedly left in place. Fill materials were then placed above the compacted native soil or concrete slabs. The fill materials consisted of "Tidewater" sand, aggregate base and "Pea" gravel. Laboratory compaction tests and field checkpoints of the sand and baserock were conducted in accordance with the ASTM D1557-78 test method to evaluate the optimum moisture content and maximum dry density of the material to be compacted.

Field density tests were performed using nuclear methods in accordance with the ASTM D2922-71 test method. Based upon the test results, we conclude that the fill we observed being placed was

Subsurface Consultants, Inc.

Mr. Robert S. Eagan R. S. Eagan & Company SCI 364.022 January 7, 1992 Page 2

compacted to at least 90 percent relative compaction greater than 2 feet below grade and at least 95 percent relative compaciton in the upper 2 feet.

Conclusions

Based upon our observations and test results, we conclude that the geotechnical engineering aspects of the project performed under our observation were completed in accordance with standard practices.

Field and laboratory data will be retained in our files for future reference, if necessary. A summary of the field density test data is attached.

If you have questions regarding our conclusions or services, please call.

Yours very truly,

Subsurface Consultants, Inc.

William K. Wikander

Geotechnical Engineer 892 (expires 12/31/92)

WKW: RWR: ddh

Attachment: Summary of Field Density Test Data

Copies: Addressee (2)

Mr. Keith B. Craig (1)

Geo/Resource Consultants, Inc.

505 Beach Street

San Francisco, CA 94133

SUBSURFACE CONSULTANTS, INC. OAKLAND MAIN POST OFFICE 1675 7TH STREET SCI 364.022 SUMMARY OF FIELD DENSITY TEST DATA

Test No.	(1) Location	(2) Depth (ft.)	Moisture Content	Dry Density (pcf)	Maximum Dry Density (pcf)	(3) Relative Compaction	Remarks
1	E21-S6	92.0	6.1	103	112	92	Pass
2	E26-N1	92.0	6.7	103	112	92	Pass
3	E25-S9	90.0	7.5	102	112	91	Pass
4	E20-S1	94.0	6.7	101	112	90	Pass
5	E22-S10	94.0	6.2	101	112	90	Pass
6	E20-S20	92.0	8.0	102	112	91	Pass
7	E31-S20	92.0	8.7	101	112	90	Pass
8	E26-S10	95.0	6.9	101	112	. 90	Pass
9	E25-S1	97.0	10.4	104	112	93	Pass
10	E24-S8	97.0	11.7	105	112	94	Pass
11	E28-S18	96.0	11.3	104	112	93	Pass
12	E15-N1	98.0	13.0	102	106	96	Pass
13	E30-S23	98.0	14.0	101	106	96	Pass
14	E15-S13	98.0	11.5	100	106	95	Pass
15	E32-NO	99.0	10.4	102	106	96	Pass
16	E30-S13	99.0	9.6	101	106	95	Pass
17	E12-S26	99.0	10.5	103	106	97	Pass
18	E19-S20	99.5	10.7	137	145	95	Pass
19	E30-S10	99.5	8.6	135	145	93	Pass w/re pack
20	E20-S10	99.5	6.8	139	145	96	Pass
21	E22-N5	100.0	6.0	138	145	95	Pass

Test	(1) Location	(2) Depth (ft.)	Moisture Content	Dry Density (pcf)	Maximum Dry Density (pcf)	(3) Relative Compaction	Remarks
22	E32-S20	100.0	6.5	137	145	95	Pass
23	E22-S26	100.0	7.1	136	145	94	Pass w/re pack
24	Waste Oil Tank Exc.	97.0	7.3	130	145	90	Pass
25	E50-S10	95.0	8.2	130	145	90	Pass
26	E55-S20	95.0	8.3	131	145	90	Pass
27	E60-S10	96.5	7.3	136	145	94	Pass
28	E50-S25	96.5	8.3	133	145	92	Pass
29	E50-S10	98.0	6.3	129	145	89	See #30
30	E60-S15	98.0	8.6	138	145	95	Pass Retest of #29
31	E55-S20	98.0	9.1	136	145	94	Pass w/re pack
32	E50-S15	100.0	8.3	141	145	97	Pass
33	E60-S20	100.0	8.7	139	145	96	Pass
34	Waste Oil Tank Exc.	100.0	7.9	139	145	96	Pass

Origin of location coordinates: Northeast corner of vehicle maintenance building.

² Assume slab subgrade is at elevation 100.00 feet.

Relative compaction refers to the in-place dry density of soil expressed as a percentage of the maximum dry density of the same soil, as determined by the ASTM D1557-78 compaction test method. Optimum moisture is the water content (percentage by dry weight) corresponding to the maximum dry density.

APPENDIX E

Plumbing Inspection Field Reports, and UST Tank Integrity Test

		CITY OF O		ENGI	NE CO.
=	ADDRESS / 76	V /	1.S. Post Office		- P.B.
•	GENERAL (7)	Egan 91-7 PERMIT OTHER	HAZARD NOTED	HAZA ABAT	1" 1
	NOTICE LEFT	1st NOTICE	2nd NOTICE	FINAL	
	DATE	VIOLATION		O.F.C.	CONTACTED
	12/13/41 Yiess	ine lest or pipin	of 3 Anural	5. Frac	
1					
j	Soat Test	o test on all g	oints & fitt	50	
	A REINSPECTION WIL	L BE MADE WITHIN	_payé'	$\frac{1}{m}$	
_	338-5 (Rev. 5-77)	FIRE PREVENTION	ON BUREAU PHONE 27	3.3851/1	NO

CITY OF C		ENGINE CO
ADDRESS 4 WOOD	·	1,000
NAME U.S. TOSTOFIC	<u>e</u> 91-7	96
GENERAL PERMIT INSPECTION OTHER	HAZARD NOTED	HAZARD ABATED
NOTICE LEFT 1st NOTICE LETTER	2nd NOTICE	FINAL
DATE VIOLATION		O.F.C. CONTACTED
12319 TWO I'' COPPER LING	• .	
50 Ms. PRESSURE.	FOR 2 is	, 29 +
NO CANKS DEL	ECTED.	×4-
UNDEREMOU	wh (co	NO SHOW
DAY TANK PIPEII	~	
A REINSPECTION WILL BE MADE WITHIN	DAYS.	
	NEUREAU - PHONE	

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

80 Swan Way, #200 Oakland, CA 94621 (415) 271-4320

Hazardous Materials Division Inspection Form

Slte	ID#	Site Name		1646		Today's	Date _	1/2/14
Slte	Address	-	· ,			EPA	1D#	
City		C 316 1 200 Ch		ZIF	94 in 7	Phone		
Hazard	nt. Stored > 5001b ous Waste generat	ed per month?	N	II. Business F III. Undergro	/Waste GENER Plans, Acute Ho und Tanks	RATOR/TRANSPI azardous Mate	riais	
The ma	rked Items represe	ent violations of th	ie Callf. Adm	inistration Code	(CAC) or the	Health & Salet	у Соде (н	5&C)
3 4	ATOR (Title 22) 1. Waste ID 2. EPA ID 3. YO days Label dates Blennial	* 66471 66472 66508 66508 66493	mments: (ilyanuce piping	for be, L	38 55 1 11	and the	1 14 C - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	.,, Y
Tonife - 8	o. Records 7. Correct . Copy sent . Exception . Coples Rec'd	66492 66484 66492 66484 66492	Fuery	100 t - 1		to 5. P.	8 / - 2000 /	7
¥ — 12	. Treatment . On-site Disp. (H.S.&C.) . Ex Haz. Waste	66371 26189,5 66570	10.401		ved Sin	wideno		
15 - 15 - 16	I. Communications Alsie Space D. Local Authority J. Maintenance D. Training	67121 67124 67126 67120 67105	Mattee	observed	Na voi	<u> </u>	d. 100	6
· · · · · · · · · · · · · · · · · · ·	P. Prepared J. Name List J. Coples , Erng, Coord, Ting,	67140 67141 67141 67144	Ad line 1	7	letion .	t the		Howa Occiling
24 — 25 — 26 — 27 — 28 — 29 — 30	Concilion Compatibility Maintenance Inspection Butter Zone Tank Inspection Containment Safe Storage Freeboard	67241 67242 67243 67244 67246 67259 67245 67251	···	PSI The	1200 3556	e gau	ges general	
3:	ORTER (Title 22) 2. Applic./Insurance 3. Comp. Cert./CHP Insp. 34. Containers	66428 66448 66465	-	e d'				
Manken!	35, Vehicles 16, EPA ID ≠s 37, Correct 18, HW Delivery 39, Records	66465 66531 66541 66543 66544		(UNDE	DUGICOUND	DAY TANK		
Con .	Nome/ Covers 11, Recyclobles	66545 66800						
Rev 6/88	Contact:							t
	Title:			 Insp	pector:			
	Signature:	نه شد چن هد شد سا سبا جه س <u>ب چن شد</u> شد شه _{وس}		_ Sign	ature:		17/42, 17/42, 18/2000	<u> </u>

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

Hazardous Materials Division Inspection Form

80 \$wan Way, #200 Oakland, CA 94621 (415) 271-4320

SIte	ID#	Site Nan	me 17, 12, 12, 44, 12 Today's Date 12/25/9
SIte	Address _	· · · · · · · · · · · · · · · · · · ·	フたった EPA ID#
City		01.6	Zip 94 60 7 Phone 4 5
Hazard	nt. Stored > 500 ous Waste gener:	ated per mon	nth? II. Business Plans, Acute Hazardous Materials III. Underground Tanks
The ma	rked Items repre	sent vlolatio	ons of the Callf. Administration Code (CAC) or the Health & Safety Code (HS&C) 🍇
= 2 = 3.	ATOR (Title 22) Waste ID EPA ID 9 0 days Labet dates Blennial	66471 66472 66508 66508 66693	Comments: Observed containment text for over \$111.
7 — 8. — 9.	Records Correct Copy sent Exception Coples Recid	66492 66484 66492 66484 66492	1446 three resurriers but her filled
<u> </u>	Treatment On-site Disp. (H.S.&C.) Ex:Haz_Waste	66371 26189.5 66570	report that the property and before
15. 16. 17.	Communications Able Space Local Authority Mathlenarice Training	67121 67124 67126 67120 67105	the meter the high water works the high water works the most of he sport in painterents the water works of the water and
20. 21. 22.	Prepared Name List Copies Emg. Coord, Ting.	67140 67141 67141 67144	place to day 12/20/9
24. — 25. — 26. — 27.	Condition Compatibility Maintenance Inspection Buffer Zone Tank Inspection	67241 67242 67243 67244 67246 67259	The morning the reproductive with
5 30.	Containment Safe Storage Freeboard	67245 67261 67257	remarked life the part mantred
33.	RTER (Title 22) Applic //nauronce comp. Cert./CHP frep. Conteners	66428 66448 66465	Marialton the mariory feel for
35. 36. 37. 38.	Vehicles EPA ID ≠s Correct HW Delivery Records	66465 66531 66541 66543 66544	The over 2/1/ 11-1 tainne ent wastely digit
	Name/ Covers Recyclobles	66545 66800	There were to a one and full a relation
~ 6/88 C	ontact:	······································	(SUMPS-FILL CONTAINMENT)
Ti	tle:		Inspector:
Si	gnature: _		Signature:

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

80 Swan Way, #200 Oakland, CA 94621 (415) 271-4320

Hazardous Materials Division Inspection Form

SIte ID#	Site Name Oskia	01 12 0 P	<u>,,, ,4,</u>	Today's D	ate <u>17/20/</u>
SIte Address	7+6 stre				D#
City	Oaklad	Zip _	94 60 7	Phone	
MAX Amt. Stored > 500lb Hazardous Waste generat	ed per month?	pection Categori I. Haz. Mat/W II. Business Plar ☑ III. Underground	aste GENERAT ns. Acute Hazo d Tanks	ardous Materia	s
THE MOREOUTER'S TEPTESE	ent violations of the Calif. Adm	nInistration Code (C	AC) or the He	aith & Safety C	ode (HS&C)
I.A GENERATOR (Title 22) 1. Waste ID 2. EPA ID 3. > 90 days 4. Lobel dates	66471 055-700 66472 66508	to the	of more	and and	orpra
5. Blennia () () () () () () () () () (66508				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
8. Copy sent	66492 66492 66492	coints Espe	. /	16	
10. Copiex Rec'd	66371 water	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	erved 1	or evide.	
12. On-site Disp. (H.S.&C.)	20189.5 /ea fe				
5 14. Communications	67121 67124 67126	3 low trave	126 serve	1/4 1387	The second second
16 Local Authority 17, Maintenance 18 Training	67106 67106	und the te			
20. Name List	67141 67141	dost fi	P linet	Mayores (a)	A VEST
22 Emg. Coord Ting.	67144			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
24. Compatibility 25. Maintenance 26. Inspection	67243 67243	demple + i de	34.361	er de sep	
27. Butter Zone 28. Tonk inspection 129. Containment 30. Sofe Storage	67246 67259 67745	Thomas Co	13 4/4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	AVESTURE 2	Jane San
31.) Freeboard	67261				
B TRANSPORTER (TITLE 22)	love	KAK TELLING	Anon to	bojen ich	Litte I
32. Applic./insurance 33. Comp. Cert./CHP insp.	66428 66448	eather 34h	four 1 pot	which a	
	60465 May 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ho They bee	14/4 F	<u> </u>	from 19 hours
5 37. Correct 300 38. HW Delivery 30.	66541 66543 12/23	3/9/2/ 20		Hon du.	10
F40. Name/ Covers	66544	*(FIRE NO	SHOW)	-	
41. Recyclobles	sss00	SECONDA	W CONTA	EINMENT) .
Contact:	•	(Sumi	bs - FILL	L5]	<u> </u>
Title:		Inspect	or:	,	
Signature:		Signatur		Men	
•				/	

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

80 Swan Way, #200 Oakland, CA 94621 (415) 271-4320

Hazardous Materials Division Inspection Form

SIte ID#	SIte Name	Pos	1746	· <u>··a</u>	т	oday's i	Date _	<u></u> //
Site Address		17 H	5-/-	<u> </u>		EPA	ID# _	
City				ZIp <u>94</u>	Pho	ne _		
MAX Amt. Stored > 500 Hazardous Waste genera		Y N	I. H II. Bi	Categories: az. Mat/Waste usiness Plans, A nderground Ta	cute Hazardo			
The marked Items repre	sent violations of	the Calif. A	Administratio	n Code (CAC)	or the Health	& Safety (Code (H	S&C)
1.A GENERATOR (Title 22) 1. Waste ID 2. EPA ID 3. > 90 days: 4. Label -dates 5. Blennial	* 66471 66472 66508 66508 66508	comments		ist of	orienacy.			
6. Records 7. Correct 8. Copy sent 9. Exception 10. Copies Recid	66492 66484 66492 66492		· de live	und the	foressur		-	Spr.
11. Treatment 12. On-site Disp. (H.S.&C.) 13. Ex Hoz. Waste	66371 26189.5 66570	press	wized	to 5057				
14, Communications 15, Alste Space 16, Local Authority 17, Maintenance 18, Training	67121 67124 67126 67120 67105	A11	myorate	wiere o	ocked!	* * * * * * * * * * * * * * * * * * *	506/	
19. Prepared 20. Name Ust 21. Coptes 22. Erng. Coord. Trng.	67140 67141 67141	W. Spart			Raye ob	sales of	, v	The second second
23. Condition 24. Compatibility 5 .25. Maintenance 26. Inspection 27. Butter Zone 28. Tank Inspection	67241 67242 67243 67244 67246	BAF .	L' SEE	ion intit		Preso.	1.2 11.2	
29, Containment 5 30, Safe Storage 5 31, Freeboard	67245 () 67261 67257	spai	* * * * *	piction coud 0	pst.	La plant	F 3 4	27/200
LB TRANSPORTER (Title 22) 32/App8c /Insuronce 33, Comp. Cert./CHP Insp.	66428 66448 66465				1			
35, Vehicles 36, EPA ID #s 37, Correct 38, HW Delivery 39, Records	66465 66531 66541 66543 66544			PRIMA	siy)	. ,		
40. Nome/ Covers 41. Recyclobles	60545 60800	,						
₩ 6/88 Contact:								ľ
Title:				Inspector	•			
Signature:				Signature:		1.27		

WESTERN AMERICA TANK TESTING, INC.

**** CERTIFICATE OF UNDERGROUND STORAGE TANK INTEGRITY ****

PRECISION VOLUMETRIC QUANTITATIVE VOLUMETRIC LEAK TEST

WESTERN AMERICA TANK TESTING, INC. has tested the following underground storage tank systems, and certifies them tight at the product height equal to the grade level.

List of Tank Systems Tested:

TANK CONTENTS	TANK CAPACITY	TANK NUMBER	STATION NUMBER
Water	12,000 gal.	Water #1	N/A
Water	12,000 gal.	Water #2	N/A
Water	12,000 gal.	Water #3	N/A

TANK LOCATION: U.S. POSTAL SERVICE

1679 7th Street

Oakland, California 94607

WESTERN AMERICA TANK TESTING, INC. is authorized to test and certify these tanks using the VPLT Tank Testing System by the manufacturer, NDE Technology, Inc.

This certification meets or exceeds certification standards set by the State of California, Federal and the Local jurisdictional agency: County of Alameda.

western america tank testing, Inc. certification meets the requirements of California Administrative Code Title 23 Water

Resources Control Board, Subchapter 16 Underground Storage

Regulations, Part 2643. The leak test certifies the leak resolution of instrumentation or allowable change is no more than 0.05 gallons per hour as cited in Part 2643(b) on Page 4.14.

Date : 01/07/1992

Certification No. : 891764

Certified Tester : Mike Levesque

License Number : 92-1405 Recertification Date recommended: 01/07/1993

NDE'S VPLT COMPUTERIZED TANK TESTING SYSTEM Patent Pending PRECISION UNDERGROUND TANK TESTING RESULTS AND CERTIFICATION PAGE 1, GENERAL REPORT FORM - Copyright 1985 NDE TECHNOLOGY, INC. PROPRIETARY

TEST DATE: 01/07/92

U. S. POST OFFICE 1. Owner of storage tanks Company Representative

Title

1679 7th Street 2. Mailing address of owner Oakland, CA. 94607

3. Phone of owner N/A N/A STATION NUMBER 1679 7th Street Location and address of Oakland, CA. 94607 the tanks Phone number N/A

County of Alameda Regulatory Agency

TANK DESIGNATION OR ID # Water #1 5. 6. Date each tank was tested 01/07/92

7. The name of the test method VPLT COMPUTERIZED TANK TESTING SYSTEM

Business name of tank 8.

testing company

Mailing address of tank testing company

10. Person conducting test and completing report License Number

WESTERN AMERICA TANK TESTING, INC. 3131 FAIRHAVEN DRIVE

BAKERSFIELD, CA 93308

(TECHNICIAN) Mike Levesque

92-1405

Jim Nicles 11. Station Operator or manager

12. Phone number

U. S. POST OFFICE Owner name and 13.

title

14. Capacity of the tank 12,000 gallons

N/A

15. Present or past contents Water

16. Tank construction material Fiberglass

Testing fluid 17. Water

THE UNDERGROUND STORAGE TANK SYSTEM CERTIFIED TIGHT AT PRODUCT 18. (a) HEIGHT EQUAL TO THE GRADE LEVEL. Yes.

(b) Allowable leak resolution of instrumentation or allowable change per California Administrative Code Title 23 Waters, Chapter 3 Water Resources Control Board Subchapter 16 Underground Storage Regulations, Part 2643 (b), Page 4.14; 0.05 gallons per hour.

MEASURED HOURLY CHANGE: LOSS (+) OR GAIN (-) GALLONS OR *** NUMERICAL LEAK RATE IS: -0.019 Gal/Hr.

This measurement is within the legal limits as defined in (b).

TANK # Water

PAGE 2

STAT # N/A GENERAL REPORT FORM TEST DATE: 01/07/92 Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

1. Capacity of the tank 12,000 Gallons

2. Present or past contents Water

3. Tank construction material Fiberglass

4. Tank end deflection 0"

5. Internal diameter of tank 95"

6. Fill pipe internal diameter 4"

7. Fill pipe length 44"

8. Air vents

9. Type of fill pipe cap Camlock

10. Type of pumps associated with the appurtenant piping R. J. Turbine

ll. Coefficient of thermal expansion .000115 volumetric coefficient of expansion/deg

12. Specific gravity 1.0

13. Bulk modulus 312,000

14. Type of phase II vapor recovery system None

15. Depth of groundwater from grade level BELOW BOTTOM OF TANK

16. Date and Time storage
tank system was 01/05/92
filled for testing Unknown

17. Testing fluid Water

Pumped all water out of monitoring well from rain. Tanks are double wall.

Actual job schedule was 01/06/92. Water completely filled hole from rain storm.

Gusty winds to 25 mph.

On site inspection by Keith B. Craig at

On site inspection by Keith B. Craig at 3:15 pm (Geo Resource Consult.).

NDE TECHNOLOGY, INC. PROPRIETARY WATT INC. 3131 FAIRHAVEN DRIVE, BAKERSFIELD, CA 93308 (805) 322-9827

TANK #

PAGE 3

STAT # N/A TEST PROCEDURES

TEST DATE: 01/07/92

Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY Individual steps taken as part of the test but not limited to:

Topping of the tanks 1.

01/05/92

Tank inclination 0, 90, 180, 270 degrees

(see reduced data plots & raw data part III) Temperature calibration (see reduced data plots & raw data part III) Pressure calibration Level readings (see reduced data plots & raw data part III)

3. Log entries:

Due to heavy traffic caused temperature to fluctuate.

Other measurement or readings not included in the computer 4. printout:

None

other than NDE Computerized VPLT Tank 5. Any special procedures Testing Procedures:

None

Description of any repairs made to the storage tank prior to or 6. during the test:

None

Were tanks subject to sludge deposits during normal use properly cleaned prior to testing:

Yes, to the best of our knowledge.

TANK # Water

PAGE 4

STAT # N/A

TEST PROCEDURES

TEST DATE: 01/07/92

Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

1. (a) THE UNDERGROUND STORAGE TANK SYSTEM CERTIFIED TIGHT AT PRODUCT

HEIGHT EQUAL TO THE GRADE LEVEL. Yes.

(b) Allowable leak resolution of instrumentation or allowable change per California Administrative Code Title 23 Waters, Chapter 3 Water Resources Control Board Subchapter 16 Underground Storage Regulations, Part 2643 (b), Page 4.14; 0.05 gallons per hour.

*** (c) MEASURED HOURLY CHANGE: LOSS (+) OR GAIN (-) GALLONS OR NUMERICAL LEAK RATE IS: -0.019 Gal/Hr.

This measurement is within the legal limits as defined in (b). (See also computer plots or reduced data of leakage rate, Part III)

Product level of the storage system at the time of testing:

2. Total product level 138"

3. Fill pipe height

from bottom of tank 139"

4. Test pipe height

from bottom of tank 169"

5. Grade level

from bottom of tank 136"

6. Tank top height from bottom of tank

excluding piping, or tank diameter 95"

7. Test conduction -

total time

Time leak rate calculated 2:11 Hours

8. Start 11:45

9. End 13:56

(See also computer plots or reduced data of leakage rate, Part III)

(Calculated leak rate shall be based on data generated during the second hour of testing)

Distance from grade level and/or location at which the test was conducted (tank top level, distance below grade level, distance above grade, etc.)

- 10. Distance from grade level to location test conducted: +2"
- 11. Fluid level where the test was conducted. Fill Pipe
- 12. Does the tank show the presence of vapor pockets?

If yes, was the owner informed of steps that must be taken to release all vapor pockets in order to complete testing?

Owners of storage tanks are under a legal obligation to report any leaking tanks to the agency having jurisdiction of the tank test.

TANK # Water

PAGE 5

STAT # N/A

TEST PROCEDURES
Copyright 1985

TEST DATE: 01/07/92

NDE TECHNOLOGY, INC. PROPRIETARY

COMPUTERIZED PRINTOUT OF DIGITAL LEAKAGE RATE DATA

```
Tank Owner ..... = OAKLAND MAIN POST OFFICE
Tank Number ..... = 12k #1
Measurement #
                   26
Date of measurement
                                       01/07/1992
Time of measurement ..... = 13:56:45
Tank Temperature ,,..... = '
                                    55.7289 degrees F.
Tank Pressure ..... =
                                    -.0005 psi.
Basic Tank Volume ********* ==
                                 12079.000
                                            Gallons.
Temperature Correction ******* =
                                    -5.933
                                            Gallons.
Pressure Correction ******** =
                                     -.000
                                            Gallons.
Corrected Volume ********* =
                                 12073.067
                                            Gallons.
Stratified Corrected Volume *** =
                                 12073.038
                                            Gallons.
Total Fluid Level ...... ==
                                  136.99702 inches.
Fluid Pressure on Tank Boltom =
                                     4.9497 psi
Total Temperature Change ..... =
                                     -.00915 degrees F.
Total Level Change ......
                                     -.00398 inches.
Leak Rate Calculation Time.... = 01:01:27
Geometry Band ..... =
                                    Rate of Temperature Change .... =
                                     .00534 degrees F/Hour.
Volume Change ..... ==
                                     .008
                                            Gallens.
Expected Level Change ..... =
                                     .01562 inches.
Measured Level Change ******* =
                                     .01211 inches.
Primary Apparent Leak ******** =
                                     .0019 Gallons.
Primary Apparent Leak Rate **** ==
                                     .002 Gallons/Hour.
Strat Volume Change * ** * * * * * * * *
                                    -.0211 Gallons.
Strat Expected Level Change *** =
                                    -.04188 inches.
Strat Apparent Leak ******** ==
                                    -.0272 Gallons.
Strat Apparent Leak Rate ***** =
                                    -.027
                                            Gallons Hour.
Avg Measured Level Change .... =
                                     .00176 inches.
Avp Volume Change ..... =
                                    -.0094 Gallons.
Avg Expected Level Change .... =
                                    -.01867 inches.
Avg Apparent Leak ...... 😑
                                    -.0103 Gallons.
ń∨g Apparent Leak Rate ..... =
                                    -.009
                                            Gallons/Hour.
Avg Strat Volume Change ****** =
                                    -.0206 Gallons.
Avg Strat Expected Level Change =
                                    -.04094 inches.
Avg Strat Apparent Leak ****** =
                                    -.0215 Gallons.
Avg Strat Apparent Leak Rate ** =
                                    -.019 Gallons/Hour.
```

Total Elapsed Test Time = 02:11:03

TANK # Water


PAGE 6

STAT # N/A
TEST DATE: 01/07/92


TEST PROCEDURES Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

COMPUTERIZED PLOTS OF LEAKAGE RATE DATA



COMPUTERIZED PRINTOUT OF AVERAGE TEMPERATURE



Water TANK #


STAT # N/A TEST PROCEDURES

TEST DATE: 01/07/92

Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

LEVEL DATA



NDE'S VPLT COMPUTERIZED TANK TESTING SYSTEM Patent Pending PRECISION UNDERGROUND TANK TESTING RESULTS AND CERTIFICATION PAGE 1. GENERAL REPORT FORM - Copyright 1985 NDE TECHNOLOGY, INC. PROPRIETARY

TEST DATE: 01/07/92

U. S. POST OFFICE Owner of storage tanks Company Representative Title

1679 7th Street 2. Mailing address of owner Oakland, CA. 94607 Phone of owner N/A STATION NUMBER N/A Location and address of 1679 7th Street Oakland, CA. 94607 the tanks Phone number N/A County of Alameda

TANK DESIGNATION OR ID # Water #2 5. Date each tank was tested 01/07/92 6.

VPLT COMPUTERIZED TANK TESTING SYSTEM The name of the test method

Business name of tank 8. testing company

Mailing address of tank testing company

Regulatory Agency

10. Person conducting test and completing report License Number

WESTERN AMERICA TANK TESTING, INC. 3131 FAIRHAVEN DRIVE BAKERSFIELD, CA 93308 (TECHNICIAN) Mike Levesque

92 - 1405

Jim Nicles 11. Station Operator or manager

12. Phone number

13. Owner name and U. S. POST OFFICE

title

gallons Capacity of the tank 12,000 14.

15. Present or past contents Water

Tank construction material Fiberglass 16.

17. Testing fluid Water

THE UNDERGROUND STORAGE TANK SYSTEM CERTIFIED TIGHT AT PRODUCT 18. (a) HEIGHT EQUAL TO THE GRADE LEVEL. Yes.

Allowable leak resolution of instrumentation or allowable change California Administrative Code Title 23 Waters, Chapter 3 Water Resources Control Board Subchapter 16 Underground Storage Regulations, Part 2643 (b), Page 4.14; 0.05 gallons per hour.

MEASURED HOURLY CHANGE: LOSS (+) OR GAIN (-) GALLONS OR *** (c) NUMERICAL LEAK RATE IS: +0.003 Gal/Hr.

This measurement is within the legal limits as defined in (b).

TANK # Water STAT # N/A

PAGE 2

GENERAL REPORT FORM

TEST DATE: 01/07/92

Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

Capacity of the tank 12,000 Gallons l.

Water 2. Present or past contents

3. Tank construction material Fiberglass

0 11 Tank end deflection 4,

95" 5. Internal diameter of tank

Fill pipe internal diameter 4 11

47" 7. Fill pipe length

1 Air vents

Type of fill pipe cap Camlock 9.

10. Type of pumps associated with the appurtenant piping R. J. Turbine

11. Coefficient of thermal expansion .000115

volumetric coefficient of expansion/deg

12. Specific gravity 1.0

13. Bulk modulus 312,000

14. Type of phase II vapor

recovery system

15. Depth of groundwater from

grade level

16. Date and Time storage tank system was filled for testing

17. Testing fluid Water

01/05/92

Unknown

None

BELOW BOTTOM OF TANK

18. NOTES: Pumped all water out of monitoring well from rain. Tanks are double wall. Actual job schedule was 01/06/92. Water completely filled hole from rain storm. Gusty winds to 25 mph.

On site inspection by Keith B. Craig at 3:15 pm (Geo Resource Consult.).

NDE TECHNOLOGY, INC. PROPRIETARY WATT INC. 3131 FAIRHAVEN DRIVE, BAKERSFIELD, CA 93308 (805) 322-9827

TANK # Water

PAGE 3

STAT # N/A

TEST PROCEDURES

TEST DATE: 01/07/92

Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY Individual steps taken as part of the test but not limited to:

1. Topping of the tanks

01/05/92

2. Tank inclination 0, 90, 180, 270 degrees 0

Temperature calibration (see reduced data plots & raw data part III)
Pressure calibration (see reduced data plots & raw data part III)
Level readings (see reduced data plots & raw data part III)

3. Log entries:

Due to heavy traffic caused temperature to fluctuate.

4. Other measurement or readings not included in the computer printout:

None

5. Any special procedures other than NDE Computerized VPLT Tank Testing Procedures:

None

6. Description of any repairs made to the storage tank prior to or during the test:

None

7. Were tanks subject to sludge deposits during normal use properly cleaned prior to testing:

Yes, to the best of our knowledge.

PAGE 4 Water TANK # STAT # N/A TEST PROCEDURES

TEST DATE: 01/07/92 Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY THE UNDERGROUND STORAGE TANK SYSTEM CERTIFIED TIGHT AT PRODUCT (a)

HEIGHT EQUAL TO THE GRADE LEVEL. Yes.

Allowable leak resolution of instrumentation or allowable change (b) per California Administrative Code Title 23 Waters, Chapter 3 Water Resources Control Board Subchapter 16 Underground Storage Regulations, Part 2643 (b), Page 4.14; 0.05 gallons per hour.

MEASURED HOURLY CHANGE: LOSS (+) OR GAIN (-) GALLONS OR *** (c)

NUMERICAL LEAK RATE IS: +0.003 Gal/Hr.

This measurement is within the legal limits as defined in (b). (See also computer plots or reduced data of leakage rate, Fart III)

Product level of the storage system at the time of testing:

140" 2. Total product level

Fill pipe height 3.

> 142" from bottom of tank

4. Test pipe height

> from bottom of tank 172"

Grade level

136" from bottom of tank

Tank top height from bottom of tank 6.

excluding piping, or tank diameter 95"

Test conduction -

total time

Time leak rate calculated 2:00 Hours

8. 11:15 Start

9. End 13:15

(See also computer plots or reduced data of leakage rate, Part III)

(Calculated leak rate shall be based on data generated during the second hour of testing)

Distance from grade level and/or location at which the test was conducted (tank top level, distance below grade level, distance above grade, etc.)

- Distance from grade level to location 10. test conducted:
- Fluid level where the test was conducted. Fill Pipe 11.
- 12. Does the tank show the presence of vapor pockets? No

If yes, was the owner informed of steps that must be taken to release all vapor pockets in order to complete testing?

Owners of storage tanks are under a legal obligation to report any leaking tanks to the agency having jurisdiction of the tank test.

TANK # Water

PAGE 5

STAT # N/A

TEST PROCEDURES

TEST DATE:

01/07/92 Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

COMPUTERIZED PRINTOUT OF DIGITAL LEAKAGE RATE DATA

```
Tank Owner ......... # OAKLAND HAIN POST OFFICE
Tank Number ..... - 12K #2
Measurement # 24
Date of measurement
                                       01/07/1992
Time of measurement ...... = 13:15:45
Tank Temperature ..... =
                                   54.8064
                                            degrees f.
Tank Pressure ...... =
                                    .1725 psi.
Basic Tank Volume ********* = 12080.645 Gallons.
Temperature Correction ****** ==
                                -7.215
                                            Gallons.
Pressure Correction ******** =
                                      . 607
                                            Gallons.
Corrected Volume ********** ==
                                12073.437
                                            Gailons.
Stratified Corrected Volume *** =
                                12073.432
                                           Gallons.
Total Fluid Level ..... =
                                 140.01360 inches.
Fluid Pressure on Tank Bottom ==
                                    5.0587 psi
Total Temperature Change ..... =
                                     -.01165 dearess F.
Total Level Change .....
                                     .01360 inches.
Lear Rate Calculation Time.... = 01:04:02
Geometry Band .....
                                - .0001
                                            Gallons/Hour.
Rate of Temperature Change .... =
                                     -.00476 degrees F/Hour.
Volume Change ..... =
                                    -.005
                                            Gallons.
Expected Level Change . .... =
                                     -.01353 inches.
Measured Level Change ****** =
                                     -.01260 inches.
Primary Apparent Leak ******** *
                                     -.0004 Gallons.
Primary Apparent Leak Rate **** =
                                     -.000 Gallons/Hour.
Strat Volume Change ********* =
                                    .0018 Galiona.
Strat Expected Level Change (** =
                                    .00402 inches.
Strat Apparent Lear ********* =
                                    .0073 Gallons.
Strat Apparent Leat Rate ***** =
                                     .007
                                            Gallons/Hour.
Avg Measured Level Change .... =
                                   -.01338 inches.
avg Volume Change .....
                                    -.0059 Gallons.
                               ..000 0allons.
-.01347 inches.
-.0000 5allons.
-.000 0---
Avg Expected Level Change .... =
Avg Apparent Leak ......... =
Avg Apparent Leal.Rate ..... = -
                                            Gallons/Hour.
Avg Etrat Volume Change ****** = -
                                     .v027 Gallons.
Avg Strat Expected Level Change =
                                    -,00612 inches.
Avg Strat Apparent Leak ****** = -
                                    .0032 Gallons.
Avg Strat Apparent Leak Rate ** ≈
                                    .003 Gallons/Hour.
```

Total Plapsed Test Time = 02:00:03

TANK # Water

PAGE 6


STAT # N/A

TEST PROCEDURES Copyright 1985


TEST DATE: 01/07/92

NDE TECHNOLOGY, INC. PROPRIETARY

COMPUTERIZED PLOTS OF LEAKAGE RATE DATA



COMPUTERIZED PRINTOUT OF AVERAGE TEMPERATURE



TANK # Water

PAGE 7

STAT # N/A


TEST PROCEDURES

TEST DATE: 01/07/92

Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

LEVEL DATA



NDE'S VPLT COMPUTERIZED TANK TESTING SYSTEM Patent Pending PRECISION UNDERGROUND TANK TESTING RESULTS AND CERTIFICATION PAGE 1, GENERAL REPORT FORM - Copyright 1985 NDE TECHNOLOGY, INC. PROPRIETARY

01/07/92 TEST DATE:

Owner of storage tanks U. S. POST OFFICE 1. Company Representative

Title

1679 7th Street 2. Mailing address of owner Oakland, CA. 94607

3. Phone of owner N/A STATION NUMBER N/A 1679 7th Street Location and address of

Oakland, CA. 94607 the tanks Phone number N/A

County of Alameda Regulatory Agency

5. TANK DESIGNATION OR ID # Water #3 Date each tank was tested 01/07/92 6.

7. The name of the test method VPLT COMPUTERIZED TANK TESTING SYSTEM

BAKERSFIELD, CA

Mike Levesque

93308

(TECHNICIAN)

Business name of tank 8.

WESTERN AMERICA TANK TESTING, INC. testing company 3131 FAIRHAVEN DRIVE

Mailing address of tank testing company

10. Person conducting test and completing report

92-1405 License Number

11. Jim Nicles Station Operator or manager

12. Phone number

N/A U. S. POST OFFICE 13. Owner name and

title

14. Capacity of the tank 12,000 gallons

15. Present or past contents Water

16. Tank construction material Fiberglass

17. Testing fluid Water

THE UNDERGROUND STORAGE TANK SYSTEM CERTIFIED TIGHT AT PRODUCT 18. (a) HEIGHT EQUAL TO THE GRADE LEVEL. Yes.

Allowable leak resolution of instrumentation or allowable change (b) per California Administrative Code Title 23 Waters, Chapter 3 Water Resources Control Board Subchapter 16 Underground Storage Regulations, Part 2643 (b), Page 4.14; 0.05 gallons per hour.

MEASURED HOURLY CHANGE: LOSS (+) OR GAIN (-) GALLONS OR *** (c) NUMERICAL LEAK RATE IS: -0.018 Gal/Hr.

This measurement is within the legal limits as defined in (b).

TANK # Water

PAGE 2

STAT # N/A

GENERAL REPORT FORM

TEST DATE: 01/07/92

Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

1. Capacity of the tank 12,000 Gallons

2. Present or past contents Water

3. Tank construction material Fiberglass

4. Tank end deflection 0'

5. Internal diameter of tank 95"

6. Fill pipe internal diameter 4"

7. Fill pipe length 47"

8. Air vents 1

9. Type of fill pipe cap Camlock

10. Type of pumps associated with the appurtenant piping R. J. Turbine

11. Coefficient of thermal expansion .000115 volumetric coefficient of expansion/deg

12. Specific gravity 1.0

13. Bulk modulus 312,000

14. Type of phase II vapor recovery system None

15. Depth of groundwater from grade level BELOW BOTTOM OF TANK

16. Date and Time storage
tank system was
filled for testing
Unknown

17. Testing fluid Water

18. NOTES:

Pumped all water out of monitoring well from rain. Tanks are double wall.

Actual job schedule was 01/06/92. Water completely filled hole from rain storm.

Gusty winds to 25 mph.

On site inspection by Keith B. Craig at

3:15 pm (Geo Resource Consult.).

ANK # Water

PAGE 3

STAT # N/A

TEST PROCEDURES

TEST DATE: 01/07/92

Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY Individual steps taken as part of the test but not limited to:

1. Topping of the tanks 01/05/92

2. Tank inclination 0, 90, 180, 270 degrees 0

Temperature calibration (see reduced data plots & raw data part III)
Pressure calibration (see reduced data plots & raw data part III)
Level readings (see reduced data plots & raw data part III)

Log entries:

Due to heavy traffic caused temperature to fluctuate.

4. Other measurement or readings not included in the computer printout:

None

5. Any special procedures other than NDE Computerized VPLT Tank Testing Procedures:

None

6. Description of any repairs made to the storage tank prior to or during the test:

None

7. Were tanks subject to sludge deposits during normal use properly cleaned prior to testing:

Yes, to the best of our knowledge.

TANK # Water PAGE 4

STAT # N/A TEST PROCEDURES TEST DATE: 01/07/92 Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

1. (a) THE UNDERGROUND STORAGE TANK SYSTEM CERTIFIED TIGHT AT PRODUCT

HRIGHT EQUAL TO THE GRADE LEVEL. Yes.

(b) Allowable leak resolution of instrumentation or allowable change per California Administrative Code Title 23 Waters, Chapter 3 Water Resources Control Board Subchapter 16 Underground Storage Regulations, Part 2643 (b), Page 4.14; 0.05 gallons per hour.

*** (c) MEASURED HOURLY CHANGE: LOSS (+) OR GAIN (-) GALLONS OR NUMERICAL LEAK RATE IS: -0.018 Gal/Hr.

This measurement is within the legal limits as defined in (b). (See also computer plots or reduced data of leakage rate, Part III)

Product level of the storage system at the time of testing:

2. Total product level 137"

3. Fill pipe height

from bottom of tank 139"

4. Test pipe height from bottom of tank 169"

5. Grade level from bottom of tank 136"

S. Tank top height from bottom of tank excluding piping, or tank diameter 95"

excluding piping, or tank diameter 5:

7. Test conduction -

total time

Time leak rate calculated 2:03 Hours

8. Start 13:53 9. End 15:56

(See also computer plots or reduced data of leakage rate, Part III)

(Calculated leak rate shall be based on data generated during the second hour of testing)

Distance from grade level and/or location at which the test was conducted (tank top level, distance below grade level, distance above grade, etc.)

- 10. Distance from grade level to location test conducted: +1"
- 11. Fluid level where the test was conducted. Fill Pipe
- 12. Does the tank show the presence of vapor pockets?

If yes, was the owner informed of steps that must be taken to release all vapor pockets in order to complete testing?

Owners of storage tanks are under a legal obligation to report any leaking tanks to the agency having jurisdiction of the tank test.

Water TANK #

PAGE 5

STAT # N/A TEST PROCEDURES

01/07/92 TEST DATE:

Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

COMPUTERIZED PRINTOUT OF DIGITAL LEAKAGE RATE DATA

```
Tank Duner ..... = OAKLAND HAIN POST OFFICE
Tank Number ..... = 12K #3
Measurement # 05
                                       01/07/1992
Date of measurement
Time of measurement ..... = 15:58:45
Tank Temperature ...... = . 55.7206 degrees f.
Tank Pressure ......
                                    -.0012 msi.
Busic Tank Volume ++******* =
                                12080.493
                                            Gallons.
Temperature Correction ****** =
                                    -5.945
                                            Gallons.
Pressure Correction ******** ==
                                     -.000 Galions.
Corrected Volume ********** =
                                 12074.548 Gallons.
Stratified Corrected Volume *** =
                                 12074.550
                                            Gallons,
Total Fluid Level ..... =
                                  136,99654 inches.
Fluid Pressure on Tank Bottom -
                                     4.9497 psi
Total Temperature Change ..... =
                                     -.01423 degrees F.
Total Level Change ...... #
                                     -.00346 inches.
Leak Rate Calculation Time.... = 01:03:27
Geometry Band ..... =
                                     -.0002 Gailons/Hour.
Rate of Tamperature Change .... =
                                     -100564 deanees F/Hour.
Volume Change ..... =
                                     -.008 Gailons.
Expected Level Change ..... =
                                     -.01851 inches.
Measured Level Change ******* ==
                                     .01164 inches.
Primary Apparent Leak ******** =
                                     -.0129 Gatlons.
Primary Apparent Leak Rate **** =
                                     -.012 Gallons/Hour.
Strat Volume Change ******** =
                                     -,0009 Gallons.
Strat Expected Level Change *** =
                                     -.00212 Inches.
Strat Apparent Leak ********* =
                                     -.0059 Gallons.
Strat Apparent Leak Rale ****** =
                                     -.006
                                            Gallons/Hour.
                                      .01208 inches.
Avg Measured Level Change .... =
                                     -.0187 Gallons.
Avg Volume Change ...... #
                                     -,04375 inches.
Avg Expected Level Change .... =
                                     -.0238 Gallons.
Avg Apparent Leak ...... ≈
Avg Apparent Leak Rate ..... =
                                     -.022
                                            Gallons/Hour.
                                     ~.0145 Gallons.
Avg Strat Volume Change <****** =
                                     -.03392 inches.
Avg Strat Expected Level Change =
Avg Strat Apparent Leak ****** =
                                     -.0196 Gallons.
                                     -.018 Gallons/Hour.
Avg Strat Apparent Leak Rate ** =
```

Total Elapsed Test Time = 02:02:00

TANK # Water

PAGE 6


STAT # N/A

TEST PROCEDURES Copyright 1985


TEST DATE: 01/07/92

NDE TECHNOLOGY, INC. PROPRIETARY

COMPUTERIZED PLOTS OF LEAKAGE RATE DATA



COMPUTERIZED PRINTOUT OF AVERAGE TEMPERATURE



TANK # Water PAGE 7

N/A STAT #


TEST PROCEDURES

TEST DATE: 01/07/92

Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

LEVEL DATA



NDE'S VPLT COMPUTERIZED TANK TESTING SYSTEM Patent Pending PRECISION UNDERGROUND TANK TESTING RESULTS AND CERTIFICATION PAGE 1, SHORT REPORT FORM + Copyright 1985 NDE TECHNOLOGY, INC. PROPRIETARY

TEST DATE: 01/07/92

1.	Owner of storage tanks	U.	s.	POST	OFFICE
	Company Representative				
	Title				

Mailing address of owner 1679 7th Street 0akland, CA. 94607

3. Phone of owner N/A
4. STATION NUMBER N/A
Location and address of 1679 7th Street
the tanks Oakland, CA. 94607
Fhone number N/A
Regulatory Agency County of Alameda

5. TANK DESIGNATION OR ID # Water #1
6. Date each tank was tested 01/07/92
7. The name of the test method VPLT COM

7. The name of the test method VPLT COMPUTERIZED TANK TESTING SYSTEM

8. Business name of tank
testing company WESTERN AMERICA TANK TESTING, INC.
9. Mailing address of tank
testing company BAKERSFIELD, CA 93308

10. Person conducting test Mike Levesque (TECHNICIAN)

and completing report
License Number 92-1405

11. Station Operator or Jim Nicles

manager

12. Phone number N/A
13. Owner name and U. S. POST OFFICE

title
14. Capacity of the tank 12,000 gallons

15. Present or past contents Water

16. Tank construction material Fiberglass

17. Testing fluid Water

18. (a) THE UNDERGROUND STORAGE TANK SYSTEM CERTIFIED TIGHT AT PRODUCT HEIGHT EQUAL TO THE GRADE LEVEL. Yes.

(b) Allowable leak resolution of instrumentation or allowable change per California Administrative Code Title 23 Waters, Chapter 3 Water Resources Control Board Subchapter 16 Underground Storage Regulations, Part 2643 (b), Page 4.14; 0.05 gallons per hour.

*** (c) MEASURED HOURLY CHANGE: LOSS (+) OR GAIN (+) GALLONS OR NUMERICAL LEAK RATE IS: -0.019 Gal/Hr.

This measurement is within the legal limits as defined in (b).

TANK # Water STAT #

PAGE 2 SHORT REPORT FORM N/A

Copyright 1985

TEST DATE: 01/07/92 NDE TECHNOLOGY, INC. PROPRIETARY

COMPUTERIZED PRINTOUT OF DIGITAL LEAKAGE RATE DATA

```
Tank Owner ..... # OAKLAND MAIN POST OFFICE
Tank Number ..... # 12k #1
Measurement # 26
Date of measurement
                                      01/07/1992
Time of measurement ..... # 13:56:45
                                   55.7289 degrees F.
Tank Temperature ...... #
                                    -.0005 ps).
Tank Pressure ..... =
                                 12079.000
                                           Gallans.
Basic Tank Volume ********* =
Temperature Correction ******* =
                                   -5.933
                                           Gallons.
Pressure Correction ******** =
                                    -.000
                                           Gallons.
Corrected Volume >***********
                                 12073.067 Gallons.
Stratified Corrected Volume *** =
                                12073.038
                                           Gallons.
                                 136.99702 inches.
Total Fluid Level ..... =
                                    4.9497 psi
Fluid Pressure on Tank Bottom =
Total Temperature Change ..... =
                                    -.00915 degraes F.
                                    -.00298 inches.
Total Level Change ..... =
Leak Rate Calculation Time.... = 01:01:27
                                    .0001 Gallons/Hour.
Geometry Band ..... =
                                    .00534 degrees F/Hour.
Rate of Temperature Change .... =
                                    .008
                                            Gallons.
Volume Change ..... =
                                    .01592 inches.
Expected Level Change ......
Neasured Level Change ******* *
                                    .01211 inches.
Primary Apparent Leaf ******* =
                                    .0019 Gallons.
Primary Apparent Leak Rate *** **
                                     .002 Gallons/Hour.
Strat Volume Change ******** ==
                                    -.0211 Gallens.
Strat Expected Level Change *** =
                                    -.04168 inches.
                                    -.0272 Gallons.
Strat Apparent Leak ******** =
Strat Apparent Leak Rate ***** ==
                                    - .027
                                            Gallons/Hour.
Avg Measured Level Change .... =
                                    .00176 inches.
Avg Volume Change ..... ≔
                                    -.0094 Gallons.
Avg Expected Level Change .... =
                                    -.01867 inches.
                                    -.0103 Gallons.
Avg Apparent Leak ..... =
Avg Apparent Lear Rate ..... =
                                    -.009
                                            Gallons/Hour.
Avg Strat Volume Change ***** ==
                                    -.0206 Gallons.
Avg Strat Expected Level Change =
                                    ~.04094 inches.
Avg Strat Apparent Leaf ****** =
                                    -.0215 Gallons.
Avg Strat Apparent Leak Rate ** =
                                    -.019
                                            Gallons/Hour.
```

Total Elapsed Test Time = 02:11:03

TANK # Water

PAGE 3 SHORT REPORT FORM


STAT # N/A

Copyright 1985

TEST DATE: 01/07/92

NDE TECHNOLOGY, INC. PROPRIETARY

COMPUTERIZED PLOTS OF LEAKAGE RATE DATA



NDE'S VPLT COMPUTERIZED TANK TESTING SYSTEM Patent Pending PRECISION UNDERGROUND TANK TESTING RESULTS AND CERTIFICATION PAGE 1, SHORT REPORT FORM + Copyright 1985 NDE TECHNOLOGY, INC. PROPRIETARY

01/07/92 TEST DATE:

U. S. POST OFFICE Owner of storage tanks Company Representative Title

1679 7th Street 2. Mailing address of owner Oakland, CA. 94607

3. N/A Phone of owner N/A STATION NUMBER 4. 1679 7th Street Location and address of Oakland, CA. 94607 the tanks N/A Phone number County of Alameda Regulatory Agency

TANK DESIGNATION OR ID # Water #2 5.

Date each tank was tested 01/07/92 6. VPLT COMPUTERIZED TANK TESTING SYSTEM

7. The name of the test method

8. Business name of tank

testing company Mailing address of tank testing company

10. Person conducting test and completing report License Number

WESTERN AMERICA TANK TESTING, INC.

3131 FAIRHAVEN DRIVE 93308 BAKERSFIELD, CA

(TECHNICIAN) Mike Levesque

92-1405

11. Station Operator or manager

Jim Nicles

12. Phone number

13. Owner name and title

U. S. POST OFFICE

Capacity of the tank 14.

12,000

gallons

15. Present or past contents Water

16. Tank construction material Fiberglass

Water 17. Testing fluid

THE UNDERGROUND STORAGE TANK SYSTEM CERTIFIED TIGHT AT PRODUCT 18. (a) HEIGHT EQUAL TO THE GRADE LEVEL. Yes.

Allowable leak resolution of instrumentation or allowable change (b) per California Administrative Code Title 23 Waters, Chapter 3 Water Resources Control Board Subchapter 16 Underground Storage Regulations, Fart 2643 (b), Page 4.14; 0.05 gallons per hour.

(c) MEASURED HOURLY CHANGE: LOSS (+) OR GAIN (+) GALLONS OR *** NUMERICAL LEAK RATE IS: +0.003 Gal/Hr.

This measurement is within the legal limits as defined in (b).

TANK # Water

PAGE 2 SHORT REPORT FORM

STAT # N/A TEST DATE: 01/07/92

Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

COMPUTERIZED PRINTOUT OF DIGITAL LEAKAGE RATE DATA

```
Taid Owner ..... # OAKLAND HAIN POST OFFICE
Tank Number ...... = 12K #2
Measurement # .24
Date of measurement
                                       01/07/1992
Time of measurement ..... = 13:15:45
Tank Temperature ...... =
                                    54.8064 degrees F.
Tank Pressure ...... =
                                     .1723 psi.
Basic Pank Volume ********* *
                                 12000.045
                                            Gallons.
Temperature Correction ******* =
                                    -7.215
                                            Sallons.
Pressure Correction ******** *
                                      . 007
                                           Gallons.
Corrected Volume *********** =
                                 12073.437
                                            Sallons.
Etratified Convected Uplane *** =
                                 12073.132
                                             ballons.
Total Fluid Level ...... =
                                   140,01360 inches.
Fluid Pressure on Yank Bostom - -
                                     -5 0587 psi
Total Temperature Change ..... :
                                     m.01165 degrees f.
Total Level Change ..... =
                                     U1360 inches.
teak hate Calculation lime.... = 01:04:07
Geometry Band ..... =
                                     -.0001 Galtons/hour.
Rate of Temperature Change .... =
                                     -.00476 degrees fyHour.
Volume Change ..... ==
                                     -.006 6allons.
Expected Level Change ..... =
                                     -.01353 inches.
Measured Level Change ******* =
                                     -.01260 inches.
Primary Apparent Lesk ****** **
                                     -.0004 Gallons.
Primary Apparent Leak Rate **** =
                                     -.000 Gallons/Hour.
Strat Volume Change ******** =
                                     .0018 Gallons.
Strat Expected Level Change *** =
                                      .00402 inches.
Stral Apparent Leal ******** ==
                                      .0073 Gallons.
Strat Apparent Leak Rate ***** ==
                                     .007
                                           - 6allona Hour.
Avg Measured Level Change .... =
                                     -.01338 inches.
mivg Volume Change ...... ≃
                                     -.0059 Gallons.
hvg Expected Level Change .... =
                                     -.01347 inches.
Avg Apparent Leak ...... =
                                     ~.0000 Gallons.
Avg Apparent Leak Rate ..... =
                                     -.000
                                            Gallons Hour.
Avg Strat Volume Change ****** =
                                     -.0027 Gallons.
Avg Strat Expected Lavel Change =
                                     -.00612 inches.
Avg Strat Apparent Leak ****** =
                                      .0031 Gailans.
Avg Strat Apparent Lear Rate ** =
                                      .003
                                            Gallons/hour.
```

Total Elapsed Test Time = 02:00:33

TANK # Water

PAGE 3


STAT # N/A

SHORT REPORT FORM Copyright 1985

TEST DATE: 01/07/92

NDE TECHNOLOGY, INC. PROPRIETARY

COMPUTERIZED PLOTS OF LEAKAGE RATE DATA



NDE'S VPLT COMPUTERIZED TANK TESTING SYSTEM Patent Pending PRECISION UNDERGROUND TANK TESTING RESULTS AND CERTIFICATION PAGE 1, SHORT REPORT FORM + Copyright 1985 NDE TECHNOLOGY, INC. PROPRIETARY

TEST DATE: 01/07/92

Owner of storage tanks Company Representative Title

U. S. POST OFFICE

Mailing address of owner

1679 7th Street Oakland, CA. 94607

Phone of owner 3.

STATION NUMBER 4. Location and address of the tanks Phone number Regulatory Agency

N/A N/A 1679 7th Street Oakland, CA. 94607 N/A County of Alameda

5. TANK DESIGNATION OR ID #

Date each tank was tested 6.

The name of the test method 7.

8. Business name of tank testing company

Mailing address of tank testing company

Person conducting test 10. and completing report License Number

Water #3 01/07/92

VPLT COMPUTERIZED TANK TESTING SYSTEM

WESTERN AMERICA TANK TESTING, INC.

3131 FAIRHAVEN DRIVE BAKERSFIELD, CA 93308

(TECHNICIAN) Mike Levesque

92 - 1405

11. Station Operator or manager

12. Phone number 13. Owner name and

title

Capacity of the tank 14.

Jim Nicles

N/A

U. S. POST OFFICE

12,000

gallons

15. Present or past contents

Water

16. Tank construction material

Fiberglass Water

Testing fluid 17.

- THE UNDERGROUND STORAGE TANK SYSTEM CERTIFIED TIGHT AT PRODUCT 18. (a) HEIGHT EQUAL TO THE GRADE LEVEL. Yes.
 - Allowable leak resolution of instrumentation or allowable change (b) per California Administrative Code Title 23 Waters, Chapter 3 Water Resources Control Board Subchapter 16 Underground Storage Regulations, Part 2643 (b), Page 4.14; 0.05 gallons per hour.

MEASURED HOURLY CHANGE: LOSS (+) OR GAIN (+) GALLONS OR *** (c) NUMERICAL LEAK RATE IS: -0.018 Gal/Hr.

This measurement is within the legal limits as defined in (b).

TANK # Water

PAGE 2

STAT # N/A TEST DATE: 01/07/92 SHORT REPORT FORM Copyright 1985

NDE TECHNOLOGY, INC. PROPRIETARY

COMPUTERIZED PRINTOUT OF DIGITAL LEAKAGE RATE DATA

. .

```
Tank Owner ..... OAKLAND MAIN POST OFFICE
Tank Number ..... #3
Measurement #
               25
Date of measurement
                                      01/07/1992
Time of measurement ..... = 15:58:45
Tank Temperature .....
                                   55.7208 degrees F.
Tank Pressure ......
                                    -,0012 psi.
Basic Tani Volume ******** ==
                                 12080.493 Gallons.
Temperature Correction ****** ==
                                   -5.945 Gallons.
Pressure Correction ******** ==
                                    -.000 Gallons.
Corrected Volume ********* =
                                 12074.548 Gallons.
Stratified Corrected Volume *** =
                                 12074.550 Gallons.
Total Fluid Level ..... =
                                  136.99654 inches.
Fluid Pressure on Tank Bottom ==
                                    4.9497 psi
Total Temperature Change ..... =
                                    -.01423 degrees F.
Total Level Change ...... =..
                                   -.00345 inches.
Lear Rate Calculation Time.... = 01:03:27
Geometry Band ..... =
                                    -.0002 Gallons/Hour.
Rate of Temperature Change .... =
                                    .00564 degrees F/Hour.
Volume Change .....
                                    -.008 Gallons.
Expected Level Change ..... =
                                    -.01851 inches.
Neasured Level Change ****** =
                                    .01164 inches.
Primar, Apparent Leal ********
                                    -.0129 Gallons.
Primary Apparent Leaf Rate *** =
                                    .012 Gallons/Hour,
Strat Volume (namge ********* ==
                                    +.0009 Galtons
Strat Expected Level Change *** =
                                    -.00212 inches.
Strat Apparent Leak ******** =
                                    -.0059 Gallons.
Etrat Apparent Leal Rate ***** =
                                    - . 006
                                           Gallons/Hour.
Avg Measured Level Change .... =
                                     .01208 inches.
Avg Volume Change .....
                                    -.0187 Gallons.
Avg Expected Level Change .... =
                                   -.04375 inches.
Avg Apparent Leah ..... =
                                   -.0238 Gallons.
h∨g πpparent Leak Rate ..... ≕
                                   -.022
                                           Gallons/Hour.
Avg Strat Volume Change ****** =
                                   ~.0145 Gallons.
Avg Strat Expected Level Change =
                                   -.03392 inches.
Avg Strai Apparent Leal ****** =
                                   -.0196 Gallons.
Avg Strat Apparent Leal Rate ** =
                                    -.018 Galions/Hour.
```

Total Elapsed Test Time = 02:02:00

TANK # Water

PAGE 3

STAT # N/A


SHORT REPORT FORM

TEST DATE: 01/07/92

Copyright 1985


NDE TECHNOLOGY, INC. PROPRIETARY

COMPUTERIZED PLOTS OF LEAKAGE RATE DATA



APPENDIX F

Equipment List For Fuel Dispensing Island and Waste Oil Tank



GARLAND MAIN POST OFFICE 1675 - 7TH STREET OAKLAND, CA 94615

1992 NATIONAL AVENUE HAYWARD, CA 94545-1787 (415) 732-7300 FAX (415) 732-7304

SUBMITTAL INDEX

TANKS

Two (2) Modern Welding Glasteel Model 16 12,000-gallon diesel

16 12;000-gallon Modern Welding Glasteel Model One (1) unleaded

Three (3) Modern Welding-turbine enclosures with lid

TANK TRIM

Three (3) EBW 705-435-01 15-gallon till containment box Three Emco Wheaton 97-005 4" locking fill caps

Two (2) Emco Wheaton A30-014 4" fill adapter (b/e_{24})

One (1) OPW 61SOP (4002) 4" coaxial overfill valve adapter (Gasolice)

Two (2) Emco Wheaton Alloo-001 Guardian overfill valve

Two (2) Emco Wheaton A20-004 4" x 12' drop tube

Three (3) Universal 65-1212 12" round monitoring manhole

Three (3) Universal 78-3610 36" round manhole

One (1) Emco Wheaton A563-004 2" angle check valve

One (1) Emco Wheaton A677-003 1-1/2" foot valve extractor

One (1) Emco Wheaton A560-001 extractor wrench

One (1) Emco Wheaton A439-005 1-1/2" double poppet foot valve

Five (5) Universal 412-40 4" extractor pipe cap

Three (3) Universal V421-2020 float cage extractor 2"x2"

Three (3) Universal 37 float cage

Three Emco Wheaton 493016 (A4103) 2" up-flow vent

Three CNL-216R-125G 16" round manhole with gasket and screwed lid

PUMPS, DISPENSERS

One (1) Tokheim 785-1-TW-APCG single twin commercial dispenser pump for gasoline

Two (2) Red Jacket P75S1 3/4 hp submersible pump

Two (2) Red Jacket 880-029 control box

Two (2) Red Jacket 116-036 XLD leak detector

(1) Tokheim 785-1-RC-TW-APCG diesel twin commercial dispenser

Two (2) Diesel Nozzle and Breakaway Hose Assemblies:

One (1) Husky 1+VIII 1" high flow diesel nozzle

One (1) Husky 1+VI-T 1" x1" swivel

One (1) CNI 9911-1 high hose retractor arm

Two (2) Dayco 1'x7' hose, male x male

One (1) Husky 2276 super safe-t-break

Two (2) Unleaded Carb Stage II Vapor Recovery Set-Ups:

- One (1) Emco Wheaton A4005-002 vapor coaxial nozzle
- One (1) Emco Wheaton A4040-001 coax splitter
- One (1) Dayco 7280 3/4" x24" jumper hose
- One (1) CNI 9915-2D high hose retractor hose
- One (1) Dayco 7658-0017 coax hose clamp
- One (1) Husky 3030 coax super safe-t-break with scuff guard
- One (1) Dayco 7575BTN-78 6 x6" coax hose
- One (1) Dayco 75758TN-60 5'x0" coax hose

ISLAND EQUIPMENT

- Three (3) Total Containment DS-2316 dispenser sumps
- Three (3) Emco Wheaton A60-002 1-1/2" shear valve
- Three (3) Titeflex 110165-24-0120 male x male swivel stainless steel flex connector

MISCELLANEOUS

- Two (2) Cimco 805 single aluminum adapter
- Six (6) Cimco 800HS-30 hydrosorb spin-on filter/element

TANK GUAGE WITH LEAK DETECTION

- One (1) Veeder Root TLS-350 847090-022 monitor and printer
- One (1) Veeder Root 329356-001 four-input in-tank probe module
- One (1) Veeder Root 329358-001 eight-input interstitial/sump liquid sensor module
- One (1) Veeder Root 329360 two-input two-out pump I/O model
- Three (3) Veeder Root 847390-007 eight-foot tank probes, magnetostrictive
- four-foot tank probe, (1) Veeder Root 847390-001 magnetostrictive
- One Veeder Root 329394-001 ballast ring G2
- Two (2) Veeder Root 329394-003 ballast ring D2
- One (1) Veeder Root 794390-420 aboveground tank interstitial liquid sensor
- Three (3) Shaw Aero 55854 cap and ring kit
- Three (3) Veeder Rsoot 794390-205 piping sump sensor
- One (1) Veeder Root 312020-952 Evertite cap and ring kit

WASTE OIL TANK AND ACCESSORIES

- One (1) Envirovault 1,000-gallon double steel concrete filled above-ground waste oil tank
- One (1) Clay & Bailey 368 6" emergency vent
- One (1) Galz 6" short nipple for #368
- One (1) Emco Wheaton A785-005 2" mushroom vent
- One (1) Emco Wheaton A30-014 4" fill adapter One (1) Emco Wheaton A97-005 4" cap
- One (1) Veeder Root 790091-001 overfill alarm
- One (1) Veeder Root 709905-001 alarm acknowledgement switch

WASTE OIL PUMP SYSTEM

One (1) Grover 10310 evacuation system, 1"

One (1) Grover 4698 3/4" vall valve wand control

One (1) Grover 6504B no air line solenoid valve

PIPING

Ameron Dualoy 3000/L fiberglas pipe and fittings Ameron Dualoy 3000/L secondary containment fiberglas pipe and fittings

OAKMAIN.IND

APPENDIX G Non-Hazardous Waste Manifests

Precise print or type.

CALL THE NATIONAL RESPONSE CENTER 1-800 424-8802: WITHIN CALIFORNIA, CALL 1-800-852-7550

IN CASE OF EMERGENCY OR SPILL.

Form designed for use on elite (12-pitch typewriter).

	UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US	0641316196	Manifest Documen	0.4	2. Page 1 1 _{of} 1	is not req	on in the shaded areas urred by Federal law.
Ī	3. Generator's Name and Mailing Address U. 1675 744 ST. OAK	SPACT	AL SERVICE		A State	Manifest Documen	1 Number	1488902
						B. State Generator's ID		
-	5. Transporter 1 Company Name		6. US EPA ID Number	"-11	C State	Transporter's ID	コロイ	33
	TRIDNKT TRUCK LINE, INC	•	C A D 9 8 2 4	184 1317	D. Iron	sporters Phone (10) 7	83-2881
	7, Transporter 2 Company Name		8. US EPA ID Number			Ironsporter's ID 🐼	e - 3 877 37 17	
-	° ERTCKSON "INCORPORATED"		10. US EPA ID Number		G. Stote	porter's Phone (1997) Facility's ID (1997)	2 13 22	
	255 PARR BLVD.					IAID IOIO	714161	6 13 19 12
ļ	RICHMOND, CA. 94801		OADOO9		2	(5)		5-1393
	11, US DOT Description (including Proper Shipping	Name, Hazard Cla	ss, and ID Number)	No.	Type	13, Total Quantity	14 Unit Wi/Vol	- I Woste Number
	O STATE OF THE STA	1000000		,			'	State 512
	EMERY TANK NONPRORA HAZ	AKDOOS			dı ib	05500	• P.	EPA/Other, NONE
!	b.							Stote
.					ł			EPA/Other
					<u> </u>	1 1 1 1	<u> </u>	State
5	c.					,		Sicile
۲								EPA/Other
Ì	ď			· ····	 		<u> </u>	State
1								EPA/Oliver
					1		1	
	J. Ardinocod D-spotoso (ox Materials Listed Abo	Yn STORAG	E TANK(S) 75	<u> 26</u> ,	a .	ing Codes for Waste	p	ove .
	HAME BEEN INERTED WITH	TK TOC TO	ממו משל זמן עם	n 247	<u></u>		a	
	CAPACITY		NA THE THE TOO	O URMS		<u> </u>] ~	
	15. Special Handling Instructions and Additional Information KEEP AWAY FROM SOURCESK OF IGNITION. ALWAYS WEAR HARDHATS AND GLASSES WHELY WORKING							
	AROUND UNDERGROUND, STOR			CT NAME:XC	1/2	UEN K	WK	Re
AND PHOKE: \$ 510/- 814. 8962								
	16 GENERATOR'S CERTIFICATION: I hereby deci- pocked, marked, and labeled, and are in all							
İ	If I am a large quantity generator, I certify	that I have a prog	ram in place to reduce the	volume and toxicity	of waste	penerated to the	degree I h	cave determined to be
economically procticable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste								
	management method that is available to me	and that I can aff	ord.			A A	1010:10:1	0 1000CLIVE D67! #77!8
Ì	Printed/Typed Name	10	Signature	1 11	/ 1		Mon	th Day Yoar
	STEVEN K. WAKI, ST	√ >	1 / /		// \		,	1,000,01
,	7. Transporter 1 Acknowledgement of Receipt of	/ Materials	X/M	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	$U \cup$	mic C	11	11981911
2	Printed/Typod Name	, more man	Signoture	11-1			Mon	n Day Year
ì	SOUTT //21		20-	H Ma				
3	Jeon Cox		- COI	1 / 92			· // [110/8/9//
2	 Transporter 2 Acknowledgement of Receipt of Printed/Typed Name 	1 Materias	Signature	/			Mon	th Day Year
				,				
₹							1	11081911
F	19 Decrepancy Indication Space							
1								
i	20. Facility Owner or Operator Certification of rec	eipt of hozardous r		ndest except as note	o in item 1	9		
Ţ	Printed/typed Name		Signature				Моп	th Day Year
,								, ,
ل							1 1	`~\

State of California—Health and Welfare Agency Department of Health Services See Instructions on back of page 6. form designed for use on eitle (12-pitch typewriter). ease pant of type. Sacramento, California 1. Generator's US EPA ID No. Manifest Document No. 2. Page 1 Information in the shaded areas UNIFORM HAZARDOUS C.A. C.00,06,43696 0,0,0,0,0 is not required by Federal law. WASTE MANIFEST 1 of 1 3. Generator's Name and Mailing Address U.S. POSTAL SERVICE A State Manifest Document Number 1675 7th ST, OAKLAND, CA. and the special states of the second B, State Generators ID 4. Generator's Phone (510 8748462 하는 많은데 싫었다. 6. US EPA ID Number 5, Transporter 1 Company Name C. State Transporter's ID TRIDENT TRUCK LINE, INC. C, A, D, 9, 8, 2, 4, 8, 4, 3, 7, D. Tronsporter's Phone 8, US EPA ID Number 7. Iransporter 2 Company Name E. State Transporter's ID F. Transporter's Phone 9. Designated Facility Name and Site Address ERICKSON INCORPORATED 10. US EPA ID Number G. State Facility's ID. CLACD: 0101 9141 616131912 H. Focility's Phone (510) 255 PARR BLVD. Ci Ai Di Oi Oi 9i 4i 6i 6i 3i 9i RICHMOND, CA. 94801 12 Containers 13. Total 11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) Wt/VbI : I. Woste Number Type Quantity Stafe Çali (1) ... EMPTYM TANK NON-RCRA HAZARDOUS G EPA/Other WASTE SOLID E 002 Ti PQOOQ NONE N ь. E R Α Ţ State C. 0 EPA/Other NATIONAL RESPONSE CENTER 1-800-424-8802 ACCURATE TAY TO MOTOR LEADING STORAGE TANK(S) 7524 HAVE BEEN INERWED WITH 15 LES. DRY ICE PER 1000 GAL. or May 13 CAPACITY. 15. Special Handling Instructions and Additional Information KEEP AWAY FROM SOURCES OF IGNITION. ALWAYS WEAR HARDHATS AND GAASSES WHRE WORKING AROUND UNDERGROUND STRRAGE TANKS. 24RR. CONTACT NAME: X STEVEN AND PHONE: X 51 .- 8748462 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and inchonal government regulations, If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste 175 management method that is available to me and that I can afford CALL Pinted/lyped Name Signature STEUEN KILL 1,110,819,1 17. Transporter 1 Acknowledgement of Receipt of Materials õ Pnnted/Typed Name Signature Month Ä MIKE VERNAZZA SPORT 0 81 18. Transporter 2 Acknowledgement of Receipt of Materials Pnnted/Typed Name Skinature Yoca ö E R 19, Discrepancy Indication Space A C 20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in them 19, Ī Printed/Typed Name Signature Month Doy Ĭ

☐ M.P. VACUUM TRUCK SERVICE INC.	☐ M.P. ENVIRONMENTAL SERVICES INC.
To Be Used For: NON-HAZAR	DOUS WASTES ONLY Nº 002946
GENERATOR (GENERATOR MUST COMPLETE) NAME R.S. EAGAN CO. FIELD ADDRESS 1675 7th STREET CITY,STATE,ZIP OAKLAND, CALIF. 94601 PHONE (415) 132-7300 SIGNATURE OF AUTHORIZED AGENT X THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED	WASTE TO BE DISPOSED TYPE SOIL GENERATING LOCATION 1675 7th STREET OAKLAND, CA. 94601 SPECIAL HANDLING INSTRUCTIONS X GLOVES X GOGGLES OTHER QUANTITY BBLS./ GLS. YARDS TONS DESIGNATED FACILITY NAME LIQUID WASTE MANAGEMENT ADDRESS HWY 58 AND HWY 33 CITY, STATE, ZIP McKITTRICK, CA
IS 100% NON-HAZARDOUS TRANSPORTER (HAULER MUST COMPLETE) M.P. VACUUM TRUCK SERVICE INC. 3400 MANOR STREET MP JOB #EC5225 BAKERSFIELD, CA 93308 (805) 393-1151	TICKET # 22063 UNIT NO. 471 3086 PICKUP DATE 1429 TIME AM SIGNATURE DATE 11-28-91 NOTE: THIS FORM TO BE IN LIEU OF THE CALIFORNIA DEPARTMENT OF HEALTH SERVICES HAZARDOUS WASTE MANIFEST FOR NON-HAZARDOUS WASTES ONLY.
DISPOSAL FACILITY RELEASE #1191-1039 PB NAMELIQUID_WASTE_MANAGEMENT ADDRESSHWY_58 AND HWY_33 CITY,STATE,ZIP_Mc KITTRICK, CA. PHONE(805) 762-7607 DISP. TICKET # SIGNATURE DATE	QUANTITY RECEIVED BBLS./GLS. YARDS TONS TIMEAMPM DISPOSAL METHOD: SURFACE IMPOUNDMENT LANDFILL INJECTION OTHER_ RETURN COPY TO: GENERATOR UNLESS OTHERWISE SPECIFIED NOTE: IT IS NOT NECESSARY TO SEND COPY TO DOHS REMARKS

☐ M.P. VACUUM TRUCK SERVICE INC.	☐ M.P. ENVIRONMENTAL SERVICES INC.
To Be Used For: NON-HAZAR	RDOUS WASTES ONLY No 002945
GENERATOR (GENERATOR MUST COMPLETE) NAME R.S. EAGAN CO. FIELD ADDRESS 1675 7th STREET CITY, STATE, ZIP OAKLAND, CALIF. 94601 PHONE (415) 732-7300 SIGNATURE OF AUTHORIZED AGENT X DATE: 1//2 o/9/ THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED	WASTE TO BE DISPOSED TYPE SOIL GENERATING LOCATION 1675 7th STREET OAKLAND, CA. 94601 SPECIAL HANDLING INSTRUCTIONS X GLOVES X GOGGLES OTHER QUANTITY 8 BBLS./ GLS. YARDS TONS DESIGNATED FACILITY NAME LIQUID WASTE MANAGEMENT ADDRESS HWY 58 AND HWY 33 CITY, STATE, ZIP MCKITTRICK, CA
TRANSPORTER (HAULER MUST COMPLETE) M.P. VACUUM TRUCK SERVICE INC. 3400 MANOR STREET MP JOB #EC5225 BAKERSFIELD, CA 93308 (805) 393-1151	TICKET # 2252 % UNIT NO. 476-3076 PICKUP DATE 1/- 20-9/ TIME AM SIGNATURE DATE 1/- 20-9/ NOTE: THIS FORM TO BE IN LIEU OF THE CALIFORNIA DEPARTMENT OF HEALTH SERVICES HAZARDOUS WASTE MANIFEST FOR NON-HAZARDOUS WASTES ONLY.
DISPOSAL FACILITY RELEASE #1191-1039 PB NAME LIQUID WASTE MANAGEMENT ADDRESS HWY 58 AND HWY 33 CITY,STATE,ZIP Mc KITTRICK, CA. PHONE (805) 762-7607 DISP. TICKET # SIGNATURE DATE	QUANTITY RECEIVED BBLS./GLS. YARDS TONS TIMEAMPM DISPOSAL METHOD: SURFACE IMPOUNDMENT LANDFILL INJECTION OTHER RETURN COPY TO: GENERATOR UNLESS OTHERWISE SPECIFIED NOTE: IT IS NOT NECESSARY TO SEND COPY TO DOHS REMARKS

٠,

☐ M.P. VACUUM TRUCK SERVICE INC.	M.P. ENVIRONMENTAL SERVICES INC.
To Be Used For: NON-HAZAR	DOUS WASTES ONLY 002944
GENERATOR (GENERATOR MUST COMPLETE) NAME R.S. EAGAN CO. FIELD ADDRESS 1675 7th STREET CITY,STATE,ZIP OAKLAND. CALIF. 94601 PHONE (415) 732-7300 SIGNATURE OF AUTHORIZED AGENT X THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED	WASTE TO BE DISPOSED TYPE SQIL. GENERATING LOCATION 1675 7th STREET OAKLAND, CA 94601 SPECIAL HANDLING INSTRUCTIONS X GLOVESX GOGGLES OTHER QUANTITY BBLS./ GLS/8 YARDS TONS DESIGNATED FACILITY NAMELIQUID WASTE MANAGEMENT ADDRESS HWY 58 AND HWY 33 CITY, STATE, ZIP MCKITTRICK, CA
IS 100% NON-HAZARDOUS TRANSPORTER (HAULER MUST COMPLETE) M.P. VACUUM TRUCK SERVICE INC. 3400 MANOR STREET BAKERSFIELD, CA 93308 (805) 393-1151	TICKET # 21297 UNIT NO. 475/3095 PICKUP DATE / 1/-20-51 TIME SIGNATURE AN DATE //-20-51 NOTE: THIS FORM TO BE IN LIEU OF THE CALIFORNIA DEPARTMENT OF HEALTH SERVICES HAZARDOUS WASTE MANIFEST FOR NON-HAZARDOUS WASTES ONLY.
DISPOSAL FACILITY RELEASE #1191-1039 PB NAME LIQUID WASTE MANAGEMENT ADDRESS HWY 58 AND HWY 33 CITY,STATE,ZIP Mc KITTRICK, CA. PHONE (805) 762-7607 DISP. TICKET # SIGNATURE DATE	QUANTITY RECEIVED BBLS./GLS. YARDS TONS TIME AM PM DISPOSAL METHOD: SURFACE IMPOUNDMENT LANDFILL INJECTION OTHER RETURN COPY TO: GENERATOR UNLESS OTHERWISE SPECIFIED NOTE: IT IS NOT NECESSARY TO SEND COPY TO DOHS REMARKS

☐ M.P. VACUUM TRUCK SERVICE INC.	☐ M.P. ENVIRONMENTAL SERVICES INC.
To Be Used For: NON-HAZAR	DOUS WASTES ONLY Nº 002949
GENERATOR MUST COMPLETE)	WASTE TO BE DISPOSED
NAME R.S. EAGAN CO. FIELD ADDRESS 1675 7th STREET CITY,STATE,ZIP OAKLAND, CALIF. 94601 PHONE (415) 732-7300 SIGNATURE OF AUTHORIZED AGENT X DATE: THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS	GENERATING LOCATION 1675 7th STREET OAKLAND, CA. 94601 SPECIAL HANDLING INSTRUCTIONS X GLOVES GOGGLES OTHER QUANTITY BBLS./ GLS. YARDS TONS DESIGNATED FACILITY NAME LIQUID WASTE MANAGEMENT ADDRESS BWY 58 AND HWY 33 CITY, STATE, ZIP McKITTRICK, CA PHONE (805) 762-7607
TRANSPORTER (HAULER MUST COMPLETE) M.P. VACUUM TRUCK SERVICE INC. 3400 MANOR STREET MP JOB #EC5225 BAKERSFIELD, CA 93308 (805) 393-1151	PICKUP DATE //- 30 - 308/- SIGNATURE DE L'EU DATE //- 30 NOTE: THIS FORM TO BE IN LIEU OF THE CALIFORNIA DEPARTMENT OF HEALTH SERVICES HAZARDOUS WASTE MANIFEST FOR NON-HAZARDOUS WASTES ONLY.
NAMELIQUID_WASTE_MANAGEMENT ADDRESSHWY_58_AND_HWY_33 CITY,STATE,ZIPMcKITTRICK,_CA. PHONE(805)_762-7607DISP. TICKET # SIGNATURE DATE	QUANTITY RECEIVED BBLS./GLS. YARDS TONS TIMEAMPM DISPOSAL METHOD: SURFACE IMPOUNDMENT LANDFILL INJECTION OTHER_ RETURN COPY TO: GENERATOR UNLESS OTHERWISE SPECIFIED NOTE: IT IS NOT NECESSARY TO SEND COPY TO DOHS REMARKS

; ;

☐ M.P. VACUUM TRUCK SERVICE INC.	☐ M.P. ENVIRONMENTAL SERVICES INC.
To Be Used For: NON-HAZAR	DOUS WASTES ONLY Nº 002947
GENERATOR MUST COMPLETE)	WASTE TO BE DISPOSED
NAME_R.S. EAGAN CO. FIELD ADDRESS1675 7th STREET CITY,STATE,ZIPOAKLAND. CALIF. 94601 PHONE	GENERATING LOCATION 1675 7th STREET OAKLAND, CA. 94601 SPECIAL HANDLING INSTRUCTIONS X GLOVES X GOGGLES OTHER
SIGNATURE OF AUTHORIZED AGENT X DATE: 1/20/96 THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS	QUANTITYBBLS./GLSYARDSTONS DESIGNATED FACILITY NAMELIQUID WASTE MANAGEMENT ADDRESSRWY 58 AND HWY 33 CITY,STATE,ZIPMCKITTRICK, CA PHONE(805) 762-7607
TRANSPORTER (HAULER MUST COMPLETE) M.P. VACUUM TRUCK SERVICE INC. 3400 MANOR STREET MP JOB #EC5225 BAKERSFIELD, CA 93308 (805) 393-1151	PICKUP DATE 1/- ZO -9 TIME SIGNATURE SIGNATUR
NAMELIQUID WASTE MANAGEMENT ADDRESSHWY 58 AND HWY 33 CITY,STATE,ZIP_Mc KITTRICK, CA. PHONE(805) 762-7607 DISP. TICKET # SIGNATURE DATE	QUANTITY RECEIVED BBLS./GLS. YARDS TONS TIME AMPM DISPOSAL METHOD: SURFACE IMPOUNDMENT LANDFILL INJECTION OTHER RETURN COPY TO: GENERATOR UNLESS OTHERWISE SPECIFIED NOTE: IT IS NOT NECESSARY TO SEND COPY TO DOHS REMARKS

☐ M.P. VACUUM TRUCK SERVICE INC.	☐ M.P. ENVIRONMENTAL SERVICES INC.
To Be Used For: NON-HAZAR	DOUS WASTES ONLY Nº 002939
GENERATOR (GENERATOR MUST COMPLETE)	WASTE TO BE DISPOSED
NAME R.S. EAGAN CO. FIELD ADDRESS 1675 7th STREET CITY,STATE,ZIP OAKLAND. CALIF. 94601 PHONE (415) 732-7300 SIGNATURE,OF AUTHORIZED AGENT X DATE: ///2 o/G/ THE GENERATOR CERTIFIES THAT	TYPE SOIL GENERATING LOCATION 1675 7th STREET OAKLAND, CA. 94601 SPECIAL HANDLING INSTRUCTIONS X GLOVES X GOGGLES OTHER QUANTITY BBLS./ GLS. YARDS TONS DESIGNATED FACILITY NAME LIQUID WASTE MANAGEMENT ADDRESS HWY 58 AND HWY 33
THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS TRANSPORTER (HAULER MUST COMPLETE) M.P. VACUUM TRUCK SERVICE INC. 3400 MANOR STREET MP JOB #EC5225 BAKERSFIELD, CA 93308 (805) 393-1151	CITY,STATE,ZIP McKITTRICK, CA PHONE (805) 762-7607 TICKET # UNIT NO. 1(2) 30.5(2) PICKUP DATE TIME DATE DATE 11. 20-5(1) NOTE: THIS FORM TO BE IN LIEU OF THE CALIFORNIA DEPARTMENT OF HEALTH SERVICES HAZARDOUS WASTE MANIFEST FOR NON-HAZARDOUS WASTES ONLY.
NAMELIQUID WASTE HANAGEMENT ADDRESS HWY 58 AND HWY 33 CITY,STATE,ZIP_Mc KITTRICK, CA. PHONE (805) 762-7607 DISP. TICKET # SIGNATURE DATE	QUANTITY RECEIVED BBLS./GLS. YARDS TONS TIMEAMPM DISPOSAL METHOD: SURFACE IMPOUNDMENT LANDFILL INJECTION OTHER RETURN COPY TO: GENERATOR UNLESS OTHERWISE SPECIFIED NOTE: IT IS NOT NECESSARY TO SEND COPY TO DOHS REMARKS

☐ M.P. VACUUM TRUCK SERVICE INC.	☐ M.P. ENVIRONMENTAL SERVICES INC.
To Be Used For: NON-HAZAR	DOUS WASTES ONLY No 002951
GENERATOR (GENERATOR MUST COMPLETE) NAME_R.S. EAGAN CO. FIELD ADDRESS1675_7th_STREET CITY,STATE,ZIPOAELAND,_CALIF94601 PHONE(415)732-7300 SIGNATURE OF AUTHORIZED AGENT X DATE://_3O/	WASTE TO BE DISPOSED TYPE SOIL GENERATING LOCATION 1675 7th STREET OAKLAND, CA. 94601 SPECIAL HANDLING INSTRUCTIONS X GLOVES X GOGGLES OTHER QUANTITY BBLS./ GLS. / YARDS TONS DESIGNATED FACILITY NAME LIQUID WASTE MANAGEMENT ADDRESS HWY 58 AND HWY 33
THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS TRANSPORTER (HAULER MUST COMPLETE) M.P. VACUUM TRUCK SERVICE INC. 3400 MANOR STREET MP JOB #EC5225 BAKERSFIELD, CA 93308 (805) 393-1151	CITY,STATE,ZIP McKITTRICK, CA PHONE (\$05) 762–7607 TICKET # UNIT NO. 4/3-309/ PICKUP DATE ///2//9/ TIME ///00/4. SIGNATURE ///////// DATE ////9/ NOTE: THIS FORM TO BE IN LIEU OF THE CALIFORNIA DEPARTMENT OF HEALTH SERVICES HAZARDOUS WASTE MANIFEST FOR NON-HAZARDOUS WASTES ONLY.
DISPOSAL FACILITY RELEASE \$1191-1039 PB NAME	QUANTITY RECEIVED BBLS./GLS. YARDS TONS TIMEAMPM DISPOSAL METHOD: LANDFILL INJECTION OTHER RETURN COPY TO: GENERATOR UNLESS OTHERWISE SPECIFIED NOTE: IT IS NOT NECESSARY TO SEND COPY TO DOHS REMARKS

☐ M.P. VACUUM TRUCK SERVICE INC.	☐ M.P. ENVIRONMENTAL SERVICES INC.
To Be Used For: NON-HAZAR	DOUS WASTES ONLY
GENERATOR (GENERATOR MUST COMPLETE)	WASTE TO BE DISPOSED
NAME R.S. EAGAN CO. FIELD ADDRESS 1675 7th STREET	TYPE SOIL GENERATING LOCATION 1675 7th STREET OAKLAND, CA. 94601
CITY,STATE,ZIPOAKLAND,_ CALIF94601 PHONE(415)732-7300 SIGNATURE OF AUTHORIZED AGENT X	SPECIAL HANDLING INSTRUCTIONS X GLOVES X GOGGLES OTHER QUANTITY BBLS./ GLS. YARDS TONS DESIGNATED FACILITY NAME LIQUID WASTE MANAGEMENT ADDRESS HWY 58 AND HWY 33 CITY,STATE,ZIP McKITTRICK, CA PHONE (805) 762-7607
TRANSPORTER (HAULER MUST COMPLETE) M.P. VACUUM TRUCK SERVICE INC. 3400 MANOR STREET MP JOB #EC5225 BAKERSFIELD, CA 93308 (805) 393-1151	PICKUP DATE //- 20-9/. TIME //-30 SIGNATURE FORM TO BE IN LIEU OF THE CALIFORNIA DEPARTMENT OF HEALTH SERVICES HAZARDOUS WASTE MANIFEST FOR NON-HAZARDOUS WASTES ONLY.
DISPOSAL FACILITY RELEASE #1191-1039 PB NAMELIQUID WASTE MANAGEMENT ADDRESSHWY_58 AND HWY_33 CITY,STATE,ZIP_Mc_KITTRICK, CA. PHONE(805)_762-7607DISP. TICKET # SIGNATURE DATE	QUANTITY RECEIVED BBLS./GLS. YARDS TONS TIME AM PM DISPOSAL METHOD: SURFACE IMPOUNDMENT LANDFILL INJECTION OTHER RETURN COPY TO: GENERATOR UNLESS OTHERWISE SPECIFIED NOTE: IT IS NOT NECESSARY TO SEND COPY TO DOHS REMARKS

☐ M.P. VACUUM TRUCK SERVICE INC.	☐ M.P. ENVIRONMENTAL SERVICES INC.
To Be Used For: NON-HAZAR	DOUS WASTES ONLY Nº 002942
GENERATOR (GENERATOR MUST COMPLETE) NAME R.S. EAGAN CO. FIELD ADDRESS CITY, STATE, ZIP OAKLAND, CALIF. 94601 PHONE (415) 732-7300 SIGNATURE OF AUTHORIZED AGENT X // // // // // // // // // // // // //	WASTE TO BE DISPOSED TYPE SOIL GENERATING LOCATION 1675 7th STREET OAKLAND, CA. 94601 SPECIAL HANDLING INSTRUCTIONS GLOVES GOGGLES OTHER QUANTITY BBLS./ GLS. YARDS TONS DESIGNATED FACILITY NAME ADDRESS HWY 58 AND HWY 33 CITY, STATE, ZIP McKITTRICK, CA PHONE (805) 762-7607
TRANSPORTER (HAULER MUST COMPLETE) M.P. VACUUM TRUCK SERVICE INC. 3400 MANOR STREET MP JOB #EC5225 BAKERSFIELD, CA 93308 (805) 393-1151	TICKET # 2186 UNIT NO. 496/368 PICKUP DATE MANAGE SIGNATURE AM SIGNATURE MANUFEST FORM TO BE IN LIEU OF THE CALIFORNIA DEPARTMENT OF HEALTH SERVICES HAZARDOUS WASTE MANIFEST FOR NON-HAZARDOUS WASTES ONLY.
DISPOSAL FACILITY NAMELIQUID_WASTE_MANAGEMENT ADDRESSHWY 58 AND HWY 33 CITY,STATE,ZIPMc KITTRICK, CA. PHONE(805) 762-7607DISP. TICKET # SIGNATURE DATE	QUANTITY RECEIVED BBLS./GLS. YARDS TONS TIMEAMPM DISPOSAL METHOD: SURFACE IMPOUNDMENT LANDFILL INJECTION OTHER RETURN COPY TO: GENERATOR UNLESS OTHERWISE SPECIFIED NOTE: IT IS NOT NECESSARY TO SEND COPY TO DOHS REMARKS

1

•

:

☐ M.P. VACUUM TRUCK SERVICE INC.	☐ M.P. ENVIRONMENTAL SERVICES INC.
To Be Used For: NON-HAZAI	RDOUS WASTES ONLY Nº 002943
GENERATOR (GENERATOR MUST COMPLETE) NAME_R.S. EAGAN CO. FIELD ADDRESS 1675 7th STREET CITY,STATE,ZIP OAKLAND, CALIF. 94601 PHONE (415) 732-7300 SIGNATURE OF AUTHORIZED AGENT X DATE: //- 7 () - 5/	WASTE TO BE DISPOSED TYPE SOIL //9/-/039 PB GENERATING LOCATION 1675 7th STREET CAKLAND, CA. 94601 SPECIAL HANDLING INSTRUCTIONS X GLOVES X GOGGLES OTHER QUANTITY BBLS./GLS. YARDS TONS DESIGNATED FACILITY NAME LIQUID WASTE MANAGEMENT
THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS TRANSPORTER (HAULER MUST COMPLETE) M.P. VACUUM TRUCK SERVICE INC. 3400 MANOR STREET MP JOB #EC5225 BAKERSFIELD, CA 93308 (805) 393-1151	ADDRESS NY 58 AND HWY 33 CITY,STATE,ZIP McKITTRICK. CA PHONE (805) 762-7607 TICKET # ZZZOS UNIT NO 477/3096 PICKUP DATE 11-20-91 TIME A.M SIGNATURE DATE 11/20/91 NOTE: THIS FORM TO BE IN LIEU OF THE CALIFORNIA DEPARTMENT OF HEALTH SERVICES HAZARDOUS WASTE MANIFEST FOR NON-HAZARDOUS WASTES ONLY.
DISPOSAL FACILITY RELEASE #1191-1039 PB NAMELIQUID WASTE MANAGEMENT ADDRESSHWY 58 AND HWY 33 CITY,STATE,ZIP_McRITTRICK, CA. PHONE(805) 762-7607 DISP. TICKET # SIGNATURE DATE	QUANTITY RECEIVED BBLS./ GLS. YARDS TONS TIME AM PM DISPOSAL METHOD: SURFACE IMPOUNDMENT LANDFILL INJECTION OTHER RETURN COPY-TO: GENERATOR UNLESS OTHERWISE SPECIFIED NOTE: IT IS NOT NECESSARY TO SEND COPY TO DOHS REMARKS

NON-HAZARDOUS WASTE DATA FORM

/ GENERATOR	NAME US Postal Service-San Bruno Facility
	ADDRESS 850 Cherry Ave., Site:Oakland Main Post Office 1D. E P A E X E M P T 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	CITY, STATE, ZIP San Bruno, CA 94099-0310 PHONE NO (415, 742-4526
	CONTAINERS: No. 206704 VOLUME 18 40 - WEIGHT
	TYPE: TANK DUMP THUCK CARTONS OTHER Soil contaminated WASTE DESCRIPTION 1th Petroleum hydrocarbons GENERATING PROCESS Underground Storage Tank Remove COMPONENTS OF WASTE PPM % COMPONENTS OF WASTE PPM %
ВУ	COMPONENTS OF WASTE PPM % COMPONENTS OF WASTE PPM %
COMPLETED	1 Soil 99+ 5.
	See anyalitical per Approval #1191-1039-PB
<u>م</u> ∑	
00	3
E E	4 8
7	PROPERTIES PH X SOLID LIQUID SLUDGE SLURRY OTHER
	HANDLING INSTUCTIONS: Approval#1191-1039-PB
	THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS DATE DATE
ANSPORTER	Dillard Trucking, Inc. 113/2 EPA C A D 9 8 1 6 9 2 8 0 9
	ADDRESS P. O. Box 218 SERVICE ORDER NO
	Byron, California 94514
Ž	CITY, STATE, ZIP PICK UP DATE
TR/	TRUCK UNIT, ID NO C-5 DERRY A. Hycliss Jury A Hugher 11-20-91 TYPED OF PRINTED FULL NAME & SIGNATURE 0 DATE
TSD FACILITY	NAME McKittrick Waste Disposal Site EPA C A D 9 8 0 6 3 6 8 3 1
	ADDRESS 56533 Hwy. 58 West LANDFILL OTHER
	McKittrick, Ca. 93251
	CITY, STATE, ZIP
	PHONE NO 805 7627366
	TYPED OR PRINTED FULL NAME & SIGNATURE DATE
	GEN OLD/NEW L A TONS
	TRANS S B RT/CO HWOF NONE DISCREPANCY
L	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

	NAME US Postal Service-San Bruno Facility						
	ADDRESS 830 Cherry Ave., Site:Oakland Main Post Office ID E.P.A.E.X.E.M.P.T						
	CITY, STATE, ZIP San Bruno, CA 94099-0310 PHONE NO (415, 742-4526						
ATOR	CONTAINERS: No. 206341 VOLUME 18145 WEIGHT -7766						
BY GENERATOR	TYPE: TANK THUCK DANMS CARTONS OTHER						
ED.	1 <u> </u>						
	See anyalitical per Approval #1191-1039-PB						
E COMPLETE	3,						
то в	4						
 -	PROPERTIES PH XX SOLID LIQUID SLUDGE SLURRY OTHER						
	HANDLING INSTUCTIONS. Approval#1191-1039-PB						
	THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS DAVID NEW SIGNATURE DATE						
X	Dillard Trucking, Inc. 113/2 EPA C A D 9 8 1 6 9 2 8 0 9 NO.						
HI	ADDRESS P. O. Box 218 SERVICE ORDER NO						
RANSPORTER	Byron, California 94514 CITY, STATE, ZIP PICK UP DATE 1/- 3C - 9/						
TRA	TRUCK UNIT, ID. NO T. N. 15, T /F TYPED OR PRINTED FULL NAME & SIGNATURE DATE						
	McKittrick Waste Disposal Site EPA C A D 9 8 0 6 3 6 8 3 1						
>-	DISPOSAL METHÓD ADDRESS 56533 HWV. 58 West						
ILIT	McKittrick, Ca. 93251						
FAC	PHONE NO 605 762-7366						
TSD FACILITY	TYPED OR PRINTED FULL NAME & SIGNATURE DATE						
	GEN OLD/NEW L A TONS						
	TRANS S B						
	C/O RT/CD HWDF NONE DISCREPANCY						

}	
İ	NAME US Postal Service-San Bruno Facility
	ADDRESS 850 Cherry Ave., Site:Oakland Main Post Office NO E P A E X E M P T
	CITY, STATE, ZIP San Bruno, CA 94099-0310 PHONE NO (415) 742-4526
ATOR	CONTAINERS: No. 205/24 VOLUME / Y/) S WEIGHT
GENERATO	TYPE: TANK DUMP THUCK DRUMS DEARTONS DOTHER Soil contaminated WASTE DESCRIPTION 1 Thuck DRUMS DEARTONS DOTHER SOIL CONTAMINATED STATEMENT SOI
В	COMPONENTS OF WASTE PPM % COMPONENTS OF WASTE PPM %
TED	1 5 5
빌	See anyalitical per Approval #1191-1039-PB
COMPLETE	3
BEC	4
10	PROPERTIES: Nepral Solid LIQUID SLUDGE SLURRY OTHER
	AA
	HANDLING INSTUCTIONS Approval#1191-1039-PB >
	THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. DATE TYPED OR PRINTED FULL NAME & SIGNATURE DATE
ER	Dillard Trucking, Inc. 113/2 NAME Dillard Trucking, Inc. 113/2 EPA LD. C A D 9 8 1 6 9 2 8 0 9 NO.
JRT	ADDRESS P. O. BOX 218 SERVICE ORDER NO
ANSPORTER	Byron, California 94314 4 PICK UP DATE 11/30/9/
TR/	PHONE NO \$10 634-6850 JAMES D JOSTES 10 James 17 July 11/20/91
-	TRUCK UNIT, ID. NO 2/ 260 TYPED OF PRINTED FULL NAME & SIGNATURE DATE
	NAME McKittrick Waste Disposal Site LD CJA D β β φ ξ 3 β β 1] DISPOSAL METHOD
ΤY	ADDRESS 56533 Hwy 58 West LANDFILL OTHER
CILI	CITY, STATE, ZIP McKittrick, Ca. 93251
TSD FACILITY	PHONE NO. 803 762-7366
TS	TYPED OR PRINTED FULL NAME & SIGNATURE DATE
	GEN OLD/NEW L A TONS
	TRANS S B
	C/O RT/CD HWDF NONE DISCREPANCY

	NAME US Postal Service-San Bruno Facility						
BY GENERATOR	ADDRESS 850 Cherry Ave., Site:Oakland Main Post Office NO. E P A E X E M P F 1 1						
	CITY, STATE, ZIP San Bruno, CA 94099-0310 PHONE NO (415,742-4526						
	CONTAINERS: No 206041 VOLUME WEIGHT 237						
	TYPE: TANK THUCK DRUMS CARTONS OTHER Soil contaminated WASTE DESCRIPTION 1th petroleum hydrocarbons GENERATING PROCESS Underground Storage Tank Remove COMPONENTS OF WASTE PPM & COMPONENTS OF WASTE PPM %						
TED	1 <u>Soil</u> 99+ 5						
COMPLETED	See anyalitical per Approval #1191-1039-PB						
WO	3						
ш							
TO B	8						
- [PROPERTIES: Neutral XX SOLID LIQUID SLUDGE SLURRY OTHER						
İ	HANDLING INSTUCTIONS: Approval#1191-1039-PB						
	THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. TYPED OR PRINTED FULL NAME & SIGNATURE DATE						
C	Dillard Trucking, Inc. 113/2 EPA C A D 9 8 1 6 9 2 8 0 9 NO						
ANSPORTE	ADDRESS P. O. Box 218 SERVICE ORDER NO.						
ISP(Byron, California 94514 CITY, STATE, ZIP						
TRAN	PHONE NO 110 634-6850 MARY MARK MARKS THE TOP 91						
	TRUCK UNIT, ID NO J TYPED OR PRINTED FULL NAME & SIGNATURE DATE						
	NAME McKittrick Waste Disposal Site ID. CAD 8 6 6 3 8 3 1 DISPOSAL METHOD						
Σ	ADDRESS 56333 Hwy. 58 West						
CIL	CITY, STATE, ZIP McKittrick, Ca. 93251						
TSD FACILITY	PHONE NO 805 762-7366						
TS	TYPED OR PRINTED FULL NAME & SIGNATURE DATE						
	GEN OLD/NEW L A TONS						
	TRANS S B ST/CD HWDF NONE DISCREPANCY						
							

	NAME US Postal Service-San Bruno Facility							
	ADDRESS 850 Cherry Ave., Site:Oakland Main Post Office NO. E P A E X E M P F							
~	CITY, STATE, ZIP San Bruno, CA 94099-0310 PHONE NO (415) 742-4326							
ATOF	CONTAINERS: No. 76 6 707 VOLUME By dc WEIGHT							
BY GENERATOR	TYPE: TANK XX THUCK DRUMS CARTONS OTHER Soil contaminated WASTE DESCRIPTION 1th petroleum hydrocarbons GENERATING PROCESS Underground Storage Tank Remove COMPONENTS OF WASTE PPM & COMPONENTS OF WASTE PPM &							
Ω	1							
COMPLETE	See anyalitical per Approval #1191-1039-PR							
OMF	37							
ш	4							
TO B	PROPERTIES: Neptral Qsolid Liquid SLUDGE SLURRY OTHER							
	AA							
	HANDLING INSTUCTIONS: Approval#1191-1039-PB							
ļ	THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. TYPED OR PRINTED FULL NAME & SIGNATURE DATE							
ER	Dillard Trucking, Inc. 113/2 EPA C A D 9 8 1 6 9 2 8 0 9 NO.							
ORT	ADDRESS P. O. Box 218 SERVICE ORDER NO							
ANSPORTER	Byron, California 94514 CITY, STATE, ZIP							
TRA	PHONE NO. 5:10 1634-6850 Butch Motzler Auth Mt. 11-20-91							
	TRUCK, UNIT, I D NO TYPED OF PRINTED FULL NAME & SIGNATURE DATE							
	NAME McKittrick Waste Disposal Site NO C A D 9806 3 683 DISPOSAL METHOD							
<u>}</u>	ADDRESS 56533 Hwy. 58 West							
CILI	CITY, STATE, ZIPMCKittrick, Ca. 93251							
TSD FACILITY	PHONE NO 805 762-7366							
13	TYPED OR PRINTED FULL NAME & SIGNATURE DATE							
	GEN OLD/NEW L A TONS TRANS S B							
	TRANS S B RT/CO HWDF NONE DISCREPANCY							

NAME ADDRESS 850 Cherry Ave., Site: Oakland Main Post Office i.b. E.P.A. E.X.E.M.P. CITY, STATE, ZIP San Bruno, CA 94099-0310 CONTAINERS: No. 26 6562 VOLUME / WEIGHT	4526						
c 00/01/2							
\mathbf{c}							
CONTAINERS: No CO O O O O O O O O O O O O O O O O O O							
COMPONENTS OF WASTE PPM % COMPONENTS OF WASTE PPM	c _D						
Ü , <u>Soil</u> 99+5							
See anyalitical per Approval #1191-1039-PB							
A A							
<u>w</u> 4	Ì						
PROPERTIES PH X SOLID LIQUID SLUDGE SLURRY OTHER							
HANDLING INSTUCTIONS: Approval#1191-1039-PB							
THE GENERATOR CERTIFIES THAT							
THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. TYPED OR PRINTED FULL NAME & SIGNATURE	201-91.						
Dillard Trucking, Inc. 113/2 MAME Dillard Trucking, Inc. 113/2 EPA C A D 9 8 1 6 9 NO	2809						
P. O. Box 218 ADDRESS SERVICE ORDER NO.							
Byron, California 94514							
O Byron, California 94514 CITY, STATE, ZIP PICK UP DATE							
# PHONE NO 510 1634-6850 TOUVELONES	11-20.01						
TRUCK UNIT, ID NO TYPED OF PRINTED FULL NAME & SIGNATURE	DATE						
McKittrick Waste Disposal Site NAME NO	6 8 3 1						
. 36533 Htm. 58 West							
ADDRESS MCKittrick, Ca. 93251 CITY, STATE, ZIP PHONE NO. 805 762-7366 TYPED OR PRINTED FULL NAME & SIGNATURE	l						
805 762~7366	805 762~7366						
PHONE NO.							
TYPED OR PRINTED FULL NAME & SIGNATURE	DATE						
GEN OLD/NEW L A TONS TRANS S B							
C/Q RT/CD HWDF NONE DISCREPANCY							

	NAME US Postal Service-San Bruno Facility						
RATOR	ADDRESS 850 Cherry Ave., Site:Oakland Main Post Office NO. EPA E X E M P T						
	CITY, STATE, ZIP SAN BYUNO, CA 94099-0310 PHONE NO 1415 1742-4526						
	CONTAINERS: No. 205833 VOLUME 1+445 WEIGHT						
GENERATO	TYPE: TANK THUCK XX THUCK DRUMS CARTONS OTHER Soil contaminated WASTE DESCRIPTION 1th petroleum hydrocarbons GENERATING PROCESS Underground Storage Tank Remove						
ВҰ	COMPONENTS OF WASTE PPM % COMPONENTS OF WASTE PPM %						
TED	1 5 <u></u>						
PLE	See anyalitical per Approval #1191-1039-PB						
COMPLET	3						
ເມ							
ОВ	8						
	PROPERTIES: Neutral Solio LIQUID SLUDGE SLUBRY OTHER						
	HANDLING INSTUCTIONSApprovs1#1191-1039-PB						
	THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. TYPEO OR PRINTED FULL NAME & SIGNATURE DATE						
EB	Dillard Trucking, Inc. 113/2 EPA C A D 9 8 1 6 9 2 8 0 9 NO.						
JRT	ADDRESS P. O. Box 218 SERVICE ORDER NO						
ANSPORTER	Byron, California 94514 CITY, STATE, ZIPPICK UP DATE						
TRAN	PHONE NO. 310 634-6850 - JOHN M. GODDWILL WAND 11-20-91						
	TRUCK UNIT, ID NO TYPED OP PRINTED FULL NAME & SIGNATURE DATE						
	NAME McKittrick Waste Disposal Site EPA C A D 9 & Q 6 3 6 4 3 1 DISPOSAL METHOD						
≿	ADDRESS 36533 Hwy. 58 West						
CIT	CITY, STATE, ZIP McKittrick, Ca. 93251						
TSD FACILITY	PHONE NO. 805 762-7366						
7.5	TYPED OR PRINTED FULL NAME & SIGNATURE DATE						
	GEN OLD/NEW L A TONS						
	TRANS S B ST/CO HWDF NONE DISCREPANCY						
	Liberty and the second						

	US Postal Service-San Bruno Facility						
	850 Cherry Ave., Site:Oakland Main Post Office EPA E X E M P T 10. ADDRESS 1675-7th St. Oakland NO.						
	CITY, STATE, ZIP San Bruno, CA 94099-0310 415 742-4526						
ATOR	CONTAINERS: No. 13 VOLUME 18 weight						
GENERATO	TYPE: TANK XX DUMP DRUMS CARTONS OTHER Soil contaminated with petroleum hydrocarbons Underground Storage Tank Removements De Waste Description Generating PROCESS COMPONENTS OF WASTE DEM						
ВҰ	WASTE DESCRIPTION GENERATING PROCESS COMPONENTS OF WASTE PPM % COMPONENTS OF WASTE PPM %						
ED.	1 Soil 99+ 5						
LET	See anyalitical per Approval #1191-1039-PB						
COMPLETED	·						
	37						
B	8						
10	Neutral PROPERTIES: pHXSolid						
	Approval#1191=1039=PB						
	HANDLING INSTUCTIONS:						
	THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. TYPED OR PRINTED FULL NAME & SIGNATURE DATE						
<u></u>	Dillard Trucking, Inc. 113/2 EPA C A D 9 8 1 6 9 2 3 8 5 10. NO. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1						
RTE	F. O. Box 218 ADDRESS SERVICE ORDER NO						
ANSPORT	Byron, California 94514						
	CITY, STATE, ZIPPICK UP DATE						
H H	TRUCK UNIT, ID NO DID 73 TYPED OF PRINTED FULL NAME & SIGNATURE DATE						
	McKittrick Waste Disposal Site PA C A D 9 8 0 6 3 6 8 3 1						
· >-	ADDRESS DISPOSAL METHOD ADDRESS LANDFILL OTHER						
TSD FACILITY	McKittrick, Ca. 93251						
ACI	CITY, STATE, ZIP						
Π.	PHONE NO						
TS	TYPED OR PRINTED FULL NAME & SIGNATURE DATE						
	GEN OLD/NEW L A TONS 1						
	TRANS S B						
	C/Q RT/CD HWDF NONE DISCREPANCY						

NAME US Postal Service-San Bruno Facility ADDRESS 850 Cherry Ave., Site: Oakland Main Post Office 1675-7th St, Oakland Mo E P A E X E M P T 1675-7th St. Oakland Mo E P A E X E M P T 1675-7th St. Oakland Mo E P A E X E M E X E	
CITY, STATE, ZIP SAN Bruno, CA 94099-0310 CONTAINERS: No. 2/1/. 240 VOLUME / OTHER TYPE: TANK TRUCK THUCK ORUMS CARTONS OTHER Soil contaminated Waste Description with petroleum hydrocarbons COMPONENTS OF WASTE PPM See anyalitical per Approval #1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% Dillard Trucking, Inc. 113/2 Dillard Trucking, Inc. 113/2 Did E P A E X E M P T I DE E X	
CONTAINERS: No. 2/1/2 340 VOLUME S V C S V V V V V V V V V V V V V V V V V V	
CONTAINERS: No. 2/1/24/C VOLUME SUPER WEIGHT TYPE: TANK THICK DAWNS DAW	
CONTAINERS: No. 2/7/340 VOLUME 16 VC/5 WEIGHT 70 VOLUME 15 VC/5 WEIGHT 70 VOLUME 16 VC/5 WEIGHT 70 VOLUME 16 VC/5 WEIGHT 70 VOLUME 16 VC/5 WEIGHT 70 VOLUME 16 VC/5 WEIGHT 70 VOLUME 16 VC/5 WEIGHT 70 VOLUME 16 VC/5 WEIGHT 70 VOLUME 16 VC/5 WEIGHT 70 VOLUME 16 VC/5 WEIGHT 70 VOLUME 16 VC/5 WEIGHT 70 VOLUME 16 VC/5 WEIGHT 70 VOLUME 16 VC/5 WEIGHT 70 VC	
TYPE: TANK XP THUCK DANMS CARTONS OTHER Soil contaminated WASTE DESCRIPTION/LIT PETFOLEUM hydrocarbons COMPONENTS OF WASTE PPM GENERATING PROCESS Underground Storage Tank COMPONENTS OF WASTE PPM See anyalitical per Approval #1191-1039-PB 3 4 PROPERTIES. Neutral PPM Approval #1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% DAIL THE WASTE AS DESCRIBED IS 100% DAIL TIPE OR PRINTED FULL NAME & SIGNATURE P. O. Box 218 P. O. Box 218	
TYPE: TANK XP THUCK DANMS CARTONS OTHER Soil contaminated WASTE DESCRIPTION/LIT PETFOLEUM hydrocarbons COMPONENTS OF WASTE PPM GENERATING PROCESS Underground Storage Tank COMPONENTS OF WASTE PPM See anyalitical per Approval #1191-1039-PB 3 4 PROPERTIES. Neutral PPM Approval #1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% DAIL THE WASTE AS DESCRIBED IS 100% DAIL TIPE OR PRINTED FULL NAME & SIGNATURE P. O. Box 218 P. O. Box 218	
TYPE: TANK XP THUCK DANMS CARTONS OTHER Soil contaminated WASTE DESCRIPTION/LIT PETFOLEUM hydrocarbons COMPONENTS OF WASTE PPM GENERATING PROCESS Underground Storage Tank COMPONENTS OF WASTE PPM See anyalitical per Approval #1191-1039-PB 3 4 PROPERTIES. Neutral PPM Approval #1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% DAIL THE WASTE AS DESCRIBED IS 100% DAIL TIPE OR PRINTED FULL NAME & SIGNATURE P. O. Box 218 P. O. Box 218	
Soil contaminated WASTE DESCRIPTION ILL PETROLEUM hydrocarbons COMPONENTS OF WASTE PPM COMPONENTS OF WASTE PPM COMPONENTS OF WASTE PPM COMPONENTS OF WASTE PPM COMPONENTS OF WASTE PPM See anyalitical per Approval #1191-1039-PB See anyalitical per Approval #1191-1039-PB Approval #1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. Dillard Trucking, Inc. 113/2 PROPERS P. O. Box 218	
COMPONENTS OF WASTE PPM COMPONENTS OF WASTE PPM COMPONENTS OF WASTE PPM See anyalitical per Approval #1191-1039-PB Approval #1191-1039-PB LIQUID SLUDGE SLURRY OTHER Approval #1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS Dillard Trucking, Inc. 113/2 ADDRESS P. O. Box 218	c Remov
COMPONENTS OF WASTE PPM COMPONENTS OF WASTE PPM COMPONENTS OF WASTE PPM COMPONENTS OF WASTE PPM See anyalitical per Approval #1191-1039-PB See anyalitical per Approval #1191-1039-PB Approval #1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. Dillard Trucking, Inc. 113/2 PADRESS P. O. Box 218 COMPONENTS OF WASTE PPM COMPONENT	c Remov
See anyalitical per Approval #1191-1039-PB See anyalitical per Approval #1191-1039-PB	Remov
See anyalitical per Approval #1191-1039-PB 3	c Kemov
See anyalitical per Approval #1191-1039-PB See anyalitical per Approval #1191-1039-PB	
Approval#1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. Dillard Trucking, Inc. 113/2 P. O. Box 218	
Approval#1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. Dillard Trucking, Inc. 113/2 P. O. Box 218	
Approval#1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% Dillard Trucking, Inc. 113/2 P. O. Box 218	
Approval#1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% Dillard Trucking, Inc. 113/2 P. O. Box 218	
PROPERTIES. Neutral ph	
PROPERTIES. Neutral ph Xx solid Liquid Studge Sturry OTHER HANOLING INSTUCTIONS: Approval#1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. DAVID 11/E:1 1/1/2 7/1/	1
Approval#1191-1039-PB THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. Dillard Trucking, Inc. 113/2 P. O. Box 218 Approval#1191-1039-PB Approval#1191-1039-PB Approval#1191-1039-PB Approval#1191-1039-PB Approval#1191-1039-PB Approval#1191-1039-PB Approval#1191-1039-PB Approval#1191-1039-PB Approval#1191-1039-PB	_
THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% DAVID 11/E 1 TYPED OR PRINTED FULL NAME & SIGNATURE DIllard Trucking, Inc. 113/2 EPA C A D 9 8 1 6 9 2 8 0 9 ADDRESS P. O. Box 218	_
THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% DAVID 11/E 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% DAVID 11/E 1 TYPED OR PRINTED FULL NAME & SIGNATURE DIllard Trucking, Inc. 113/2 EPA C A D 9 8 1 6 9 2 8 0 9 ADDRESS P. O. Box 218	
Dillard Trucking, Inc. 113/2 P. O. Box 218 DAVID 11/E:1 TYPED OR PRINTED FULL NAME & SIGNATURE DATE DATE C A D 9 8 1 6 9 2 8 0 9 NO.	- 1
Dillard Trucking, Inc. 113/2 Dillard Trucking, Inc. 113/2 EPA C A D 9 8 1 6 9 2 8 0 9 ADDRESS P. O. Box 218	
ADDRESS P. O. Box 218	1
ADDRESS P. O. Box 218	1
ADDRESS P. O. Box 218	_
Byron, California 94514	
CITY STATE TIP	_
CITY, STATE, ZIP SERVICE ORDER NO	1
	-
PHONE NO. 610 1634-6830	1
TRUCK UNIT, ID. NO DIS 19 TERRY CARTILL	1
TYPED OR PRINTED SU	
TYPED OR PRINTED FULL NAME & SIGNATURE	.
McKittrick Waste Disposal Site EPA DATE	
	7
wy. 58 West	
McKittrick, Ca. 93251 DISPOSAL METHOD	-
	1
HONE NO 805 762-7366	ı
TYPED OR PRINTED FULL NAME & SIGNATURE	
OCOVIEW A	
RANS DATE	
BYCO	
HWDF NONE DISCREPANCY	


	NAME US Postal Service-San Bruno Facility							
	ADDRESS 850 Cherry Ave., Site:Oakland Main Post Office LD E P A E X E M P T 1							
	CITY, STATE, ZIP San Bruno, CA 94099-0310 PHONE NO. (415) 742-4526							
ATOR	CONTAINERS: No. 20115115 VOLUME 17 YM2125 WEIGHT							
BY GENERATOR	TYPE: TANK XX THUCK DRUMS CARTONS OTHER							
ED	1. <u>Soil</u> <u>99+</u> 5							
Ē	See anyalitical per Approval #1191-1030-PP							
COMPLETE	2							
00	3 7							
8 E	4							
10	PROPERTIES. Neutral Solid Liquid Sludge Slurry Other							
	HANDLING INSTUCTIONSApproval#1191-1039-PB							
	THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS. A UID FILE TYPED OR PRINTED FULL NAME & SIGNATURE DATE							
H	Dillard Trucking, Inc. 113/2 NAME NO 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1							
)RT	ADDRESS P. 0. Box 218 SERVICE ORDER NO							
TRANSPORTER	Byron, California 94514							
AN								
H	Mark william Flar 11-2091							
	TRUCK UNIT, ID NO 5 TYPED OF PRINTED FULL NAME & SIGNATURE DATE							
	NAME McKittrick Waste Disposal Site EPA C, A, D, 9, 8 0 6 3 6 8 3 1							
>	ADDRESS 56533 Hwy. 58 West LANDFILL OTHER							
TSD FACILITY	CITY, STATE, ZIPMcKittrick, Ca. 93251							
FA(PHONE NO. 805 762-7366							
SD	PRONE NO.							
-	TYPED OR PRINTED FULL NAME & SIGNATURE DATE							
	GEN OLD/NEW L A TONS							
	TRANS S B C/O RT/CD HWDF NONE DISCREPANCY							
	C/O DISCREPANCY							

	NAME US Postal Service-San Bruno Facility
	ADDRESS 850 Cherry Ave., Site:Oakland Main Post Office NO. E P A E X E M P F 1675-7th St, Oakland
	CITY, STATE, ZIP San Bruno, CA 94099-0310 PHONE NO (415) 742-4526
ATOR	CONTAINERS: No
BY GENERATO	TYPE: TANK XX THUCK XX THUCK DRUMS CARTONS OTHER
[]	1Soil
COMPLET	See anyalitical per Approval #1191-1039-PB
	3
8	6
5	PROPERTIES: Neutral XX SOLID LIQUID SLUDGE SLURRY OTHER
Ì	HANDLING INSTUCTIONS: APPROVAL#1191-1039-PB
	THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS TYPED OR PRINTED FULL NAME & SIGNATURE DATE
œ	Dillard Trucking, Inc. 113/2 Hayty Trucking 1.D. 6 A D 9 8 1 6 9 2 8 0 9 NO. C A D 0 5 2 2 (6 6 2 4
ORTE	ADDRESS SERVICE ORDER NO.
TRANSPORTER	Byron, California 94514 Julia 93265 PICK UP DATE 11-21-51
TRA	TRUCK UNIT, ID. NO. 376 TYPED OF PRINTED FULL NAME & SIGNATURE TO BE TYPED OF PRINTED FULL NAME & SIGNATURE TO BE TO BE TO BE THE TYPED OF PRINTED FULL NAME & SIGNATURE
	NAME McKittrick Waste Disposal Site EPA C A D B Q G B B B B B B B B B
	DISPOSAL METHOD
FACILITY	ADDRESS 56533 Hwy. 58 West LANDFILL OTHER
ACI	CITY, STATE, ZIP
DF	PHONE NO. 805 762-7366
TSD	TYPED OR PRINTED FULL NAME & SIGNATURE DATE
	GEN OLD/NEW L A TONS
	TRANS S B RY/CD HWDF MONE OFFICE OFFICE OF STANDARD O
	C/O RY/CD HWDF NONE DISCREPANCY

	NAME US Postal Service-San Bruno Facility
	ADDRESS 850 Cherry Ave., Site:Oakland Main Post Office 100 E P A E X E M P T 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	CITY, STATE, ZIP San Bruno, CA 94099-0310 PHONE NO 1415, 742-4526
TOR	CONTAINERS: No. 204601 204800 VOLUME 184255 WEIGHT
BY GENERATOR	TYPE: TANK XX THUCK DRUMS CARTONS OTHER Soil contaminated WASTE DESCRIPTION With petroleum hydrocarbons GENERATING PROCESS Underground Storage Tank Remove COMPONENTS OF WASTE PPM & COMPONENTS OF WASTE PPM %
ED	1. <u>Soil</u> 99+ 5
COMPLETED	Con
ΜP	2. See anyalitical per Approval #[191-1039-PB
00	3 7
BE	4
70	PROPERTIES: Neutral XX SOLID LIQUID SLUDGE SLUBRY OTHER
	HANDLING INSTUCTIONS. Approval#1191-1039-PB
	THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 190% NON-HAZARDOUS. TYPED OR PRINTED FULL NAME & SIGNATURE PANDAUWU 1 2161.
Æ	Dillard Trucking, Inc. 113/2 NAME CAD 9 8 1 6 9 2 8 0 9 NO
TRANSPORTER	P. O. Box 218
SPO	Byron, California 94514
AN	CITY, STATE, ZIP PICK UP DATE
T.R.	TRUCK UNIT 10, NO \$7 + \$74 TYPED OR PRINTED FIRE NAME & SIGNATURE
	TRUCK UNIT, I.D. NO. 87 4 87-4 TYPED OP PRINTED FULL NAME & SIGNATURE
	NAME McKittrick Waste Disposal Site LD C A D 9 8 0 6 3 6 8 3 1
>	ADDRESS 56533 Hwy. 58 West LANDFILL OTHER
111	McKittrick, Ca. 93251
TSD FACILITY	PHONE NO. 805 762-7366 TYPER AR PRINTED FOLL NAMES SIGNATURE DATE
	GEN OLD/NEW L A TONS
	TRANS S B C/O . RT/CD HWDF NONE DISCREPANCY
	C/O . DISCREPANCY

APPENDIX H

Soil Sample Location Maps, Laboratory Analyses Results and Chain-of-Custody Records



Site: Oakland Main Post Office North
Address: 1675 7th Street //
Oakland, CA

X X X X X X X X X X X X Х X Х Х Х X X Truck Parking Lot Х X Х X Х Х **X X X X X X X X X X X X X** X Stockpile #1 Stockpile #2

Stockpile #3 (Waste Oil Tank) XXXXXXXXXX XXXX XXXXXXXXXXX Х Х 1 3 5 7 x Х Х 9 11 13 15 Х Х Χ Χ Х 17 18 19 20 Х 21 22 23 24 Χ Х Х Х Х Х 10 12 14 16 X XXXXXXXXXX XXXX XXXXXXXXXXXX

Wood Street

Requester: Robert Eagan
Customer: R.S. Eagan and Company

Address: 1992 National Avenue Date Sampled: 11/12/91

Hayward, CA 94545


Log #:

11/12/91 1519

D

Site: Oakland Main Post Office Address: 1675 7th Street Oakland, CA

North //\



Wood Street

MAP #2

Requestor: Robert Eagan

Customer: R.S. Eagan and Company

Address: Hayward, CA 94545

Log #:

__1500



November 13, 1991

Mr. Robert Eagan R.S. Eagan and Company 1992 National Avenue Hayward, California 94545-1787

Dear Mr. Eagan:

Trace Analysis Laboratory took twelve soil samples on November 8, 1991 for your project, Oakland Main Post Office, 1675 7th Street, Oakland, CA (our custody log number 1500 and 1500A).

These samples were composited and analyzed according to your chain of custody. Our analytical report and the completed chain of custody form are enclosed for your review.

Trace Analysis Laboratory is certified under the California Environmental Laboratory Accreditation Program. Our certification number is 1199.

If you should have any questions or require additional information, please call me.

Sincerely yours

Jennifer Pekol Project Specialist

Enclosures

Telephone (510) 783-6960 Facsimile (510) 783-1512

DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/08/91
DATE EXTRACTED: 11/08/91

DATE ANALYZED: 11/08/91

DATE REPORTED: 11/12/91

11/10/91, 11/11/91 and 11/12/91

CUSTOMER:

R.S. Eagan and Company

REQUESTER:

Robert Eagan

PROJECT:

Oakland Main Post Office, 1675 7th Street, Oakland, CA

	<u> </u>		Sample	Type:	Soil		
Method and Constituent: DHS Method:	<u>Units</u>	Concen- tration	Reporting Limit	Concen- tration	2 Reporting Limit	Concen- tration	3A Reporting Limit
Total Petroleum Hydro- carbons as Diesel	mg/kg	260 🗸	3.0	1,200 🗸	15	2,000 🗸	1 5
Method and Constituent: DHS Method:	<u>Units</u>	Concen- tration	3B Reporting Limit		A Reporting Limit	Concen- tration	4B Reporting Limit
Total Petroleum Hydro- carbons as Diesel	mg/kg	ND /	1.0	220 🗸	3.0	2,500 1	7.0

LOG NUMBER:

1500

DATE SAMPLED: DATE RECEIVED: 11/08/91 11/08/91

DATE EXTRACTED:

11/08/91

DATE ANALYZED:

11/10/91, 11/11/91 and 11/12/91 11/12/91

DATE REPORTED:

PAGE:

Two

	Sample Type: Soil					
Method and <u>Constituent</u> : DHS Method:	<u>Units</u>	6 Concen- Reporting tration Limit	7 Concen- Reporting tration Limit			
Total Petroleum Hydro- carbons as Diesel	mg/kg	1.4 √ 1.0	7,900 / 15			
Method and <u>Constituent</u> : DHS Method:	Units	8 Concen- Reporting tration Limit	Method Blank Concen- Reporting tration Limit			
Total Petroleum Hydro-carbons as Diesel OC Summary:	mg/kg	2,900 ✓ 15	ND - 1.0			

% Recovery: 88 and 72

% RPD:

33 and 0.7

Concentrations reported as ND were not detected at or above the reporting limit. Samples 4A, 4B and 8 indicate compounds eluting earlier than diesel.

LOG NUMBER: 1500
DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/08/91
DATE EXTRACTED: 11/09/91
DATE ANALYZED: 11/10/91.

DATE REPORTED: 17

11/10/91, 11/11/91 and 11/12/91 11/12/91 Three

PAGE: Thr

Sample Type: Soil

			1 .		າ	1	
Method and <u>Constituent</u> :	lin de a	Concen-	Reporting	Concen-	Reporting	Concen-	3A Reporting
·	<u>Units</u>	<u>tration</u>	Limit	<u>tration</u>	<u>Limit</u>	<u>tration</u>	Limit
DHS Method:							
Total Petroleum Hydro- carbons as Gasoline	mg/kg	3.4 🗸	0.50	76 🗸	0.50	59	1.5
EPA Method 8020 for:							
Benzene	mg/kg	0.80∜	0.0050.	0.59	0.013	0.27	/ 0.12
Toluene	mg/kg	0.0068	0.0050	0.23	0.013	0.79	✓ 0.13 0.11
Ethylbenzene	mg/kg	0.015	0.0050	3.5	0.012	1.4	0.11
Xylenes	mg/kg	0.12	0.015	52	0.030	5.3	0.12
		3	В	,			
Method and		Concen-	Reporting		A Reporting	Concen-	48 Reporting
<u>Constituent</u> :	<u>Units</u>	<u>tration</u>	Limit	<u>tration</u>	<u>Limit</u>	trat ion	<u>Limit</u>
DHS Method:							
Total Petroleum Hydro-		,		,			
carbons as Gasoline	mg/kg	ND 🗸	0.50	150 🗸	0.50	620 🗸	3.0
EPA Method 8020 for:		/					
Benzene	mg/kg	ND √	0.0050	7.5	0.026	37 √	1.0
Toluene	mg/kg	ND	0.0050	19	0.022	1.6	
Ethylbenzene	mg/kg	ND	0.0050	8.9	0.024	53	0.82
Xylenes	mg/kg	ND	0.015	32	0.060		1.0
Concentrations renewted						130	2.0
Concentrations reported	as NU Wer	e not dete	ected at or	above the	e reporting	limit.	

LOG NUMBER: 1500 DATE SAMPLED: 11/08/91 11/08/91 DATE RECEIVED: DATE EXTRACTED: 11/09/91 DATE ANALYZED:

DATE REPORTED:

11/10/91, 11/11/91 and 11/12/91 11/12/91

PAGE:

Four

Sample Type: Soil

			_		
Method and Constituent:	<u>Units</u>	Concen- tration	6 Reporting <u>Limit</u>	Concen- tration	7 Reporting Limit
DHS Method:					
Total Petroleum Hydro- carbons as Gasoline	mg/kg	36 ✓	0.50	210 🗸	0.50
EPA Method 8020 for:					
Benzene	mg/kg	11 /	0.013	ND V	0.026
Toluene	mg/kg	0.36	0.011	0.45	0.022
Ethylbenzene	mg/kg	0.82	0.012	1.4	0.024
Xylenes	mg/kg	8.1	0.030	14	0.060
Method and Constituent:	<u>Units</u>	Concen- tration	Reporting Limit	Meti Concen- tration	hod Blank Reporting Limit
DHS Method:					
Total Petroleum Hydro- carbons as Gasoline	mg/kg	610 🗸	3.0	ND	0.50
EPA Method 8020 for:					
Benzene	mg/kg	3.4 √	1.0	ND	0.0050
Toluene	mg/kg	60	0.82	ND	0.0050
Ethylbenzene	mg/kg	27	1.0	ND	0.0050
Xylenes	mg/kg	170	2.0	ND	0.015
OC Summary:					3,0,0

% Recovery:

120 and 88

% RPD:

5.6 and 27

LOG NUMBER: 1500
DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/08/91
DATE EXTRACTED: 11/11/91
DATE ANALYZED: 11/12/91
DATE REPORTED: 11/12/91
PAGE: Five

	***********	Comp	<u> </u>	Type:	Soil		
Method and Constituent:	<u>Units</u>	of 3	and 4 Reporting	Concen-	od Blank Reporting Limit	OC Su % Recovery	mmary % RPD
EPA Method 7420: Lead	mg/kg	7.2 √	2.5	ND	2.5	89	2.9

Concentrations reported as ND were not detected at or above the reporting limit

Louis W. DuPuis

Quality Assurance/Quality Control Manager

3423 Investment Boulevard, #8 • Hayward, California 94545

Telephone (510) 783-6960 Facsimile (510) 783-1512

DATE RECEIVED: 1500A 11/08/91 11/08/91

DATE EXTRACTED: 11/08/91
DATE ANALYZED: 11/10/91
DATE REPORTED: 11/13/91

CUSTOMER:

R.S. Eagan and Company

REQUESTER:

Robert Eagan

PROJECT:

Oakland Main Post Office, 1675 7th Street, Oakland, CA

Sample Type: Soil

Method and Constituent:

______5 _____Method Blank Concen- Reporting Concen- Reporting Units tration Limit tration Limit

DHS Method:

Total Petroleum Hydrocarbons as Diesel

mg/kg

ND /

ND

1.0

OC Summary:

% Recovery:

% RPD:

88 33

LOG NUMBER: 1500A
DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/08/91
DATE EXTRACTED: 11/09/91
DATE ANALYZED: 11/11/91
DATE REPORTED: 11/13/91
PAGE: Two

Sample Type: Soil

Method and Constituent:	Units	Concen- tration	5 Reporting Limit	Metho Concentration	d Blank Reporting Limit
DHS Method:					
Total Petroleum Hydro- carbons as Gasoline	mg/kg	ND 🗸	0.50	ND	0.50
EPA Method 8020 for:					
Benzene	mg/kg	0.0068	/ _{0.0050}	ND	0.0050
Toluene	mg/kg	ND	0.0050	ND	0.0050
Ethylbenzene	mg/kg	ND	0.0050	ND	0.0050
Xylenes	mg/kg	ND	0.015	ND	0.015

OC Summary:

% Recovery: 120 % RPD: 5.6

LOG NUMBER: 1500A
DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/108/91
DATE ANALYZED: 11/12/91
DATE REPORTED: 11/13/91
PAGE: Four

Sample Type: Soil

		2011			
Method and <u>Constituent</u>	<u>Units</u>	Concen- tration	5 Reporting Limit	Meth Concen- tration	od Blank Reporting Limit
EPA Method 8010:				<u> </u>	CIM(IC
Dichlorodifluoromethane	mg/kg	ND	0.0010	ND	0.0010
Chloromethane	mg/kg	ND	0.0010	ND	0.0010
Vinyl Chloride	mg/kg	ND	0.00050	ND	0.00050
Bromomethane	mg/kg	ND	0.00050	ND	0.00050
Chloroethane	mg/kg	ND	0.00050	ND	0.00050
Trichlorofluoromethane	mg/kg	ND	0.00050	ND	0.00050
Trichlorotrifluoroethane	mg/kg	ND	0.00050	ND	0.00050
1,1-Dichloroethene	mg/kg	ND	0,00050	ND	0.00050
Dichloromethane	mg/kg	0.0024	0.00050	ND	0.00050
Trans-1,2-Dichloroethene	mg/kg	ND	0.00050	ND	0.00050
1,1-Dichloroethane	mg/kg	ND	0.00050	ND	0.00050
Cis-1,2-Dichloroethene	mg/kg	ND	0.00050	ND	0.00050
Chloroform	mg/kg	ND	0.00050	ND	0.00050
1,1,1-Trichloroethane	mg/kg	ND	0.00050	ND	0.00050
Carbon Tetrachloride	mg/kg	ND	0.00050	ND	0.00050
1,2-Dichloroethane	mg/kg	ND	0.00050	ND	0.00050
Trichloroethene	mg/kg	ND	0.00050	ND	0.00050
1,2-Dichloropropane	mg/kg	ND	0.00050	ND	0.00050
				110	0.00000

LOG NUMBER: 1500A
DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/08/91
DATE ANALYZED: 11/12/91
DATE REPORTED: 11/13/91
PAGE: Five

		Sample Type: Soil				
Method and Constituent	<u>Units</u>	Concen- tration	5 Reporting Limit	Meth Concen- tration	od Blank Reporting Limit	
EPA Method 8010 (Continued	i):					
Bromodichloromethane 2-Chloroethylvinylether Cis-1,3-Dichloropropene Trans-1,3-Dichloropropene 1,1,2-Trichloroethane Tetrachloroethene Dibromochloromethane Chlorobenzene Bromoform 1,1,2,2-Tetrachloroethane 1,2-Dichlorobenzene 1,3-Dichlorobenzene	mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg mg/kg	ND ND ND ND O.0099 ND ND ND ND ND ND ND ND ND ND	0.00050 0.0010 0.00050 0.00050 0.00050 0.00050 0.00050 0.00050 0.00050 0.00050 0.00050	ND ND ND ND ND ND ND ND ND ND ND ND	0.00050 0.0010 0.00050 0.00050 0.00050 0.00050 0.00050 0.00050 0.00050 0.0010	
1,4-Dichlorobenzene	mg/kg	ND	0.0010	ND	0.0010	

OC Summary:

% Surrogate Recovery:

53

95

LOG NUMBER: 1500A
DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/08/91
DATE EXTRACTED: 11/12/91
DATE ANALYZED: 11/12/91
DATE REPORTED: 11/13/91
PAGE: Six

Sample	Tyna·	Cail
JOHN I C	TYPE.	3011

. .			5	Meth	od Blank
and and stituent	Units	Concen-	Reporting	Concen-	Reporting
<u> </u>	VILLES	<u>tration</u>	<u>Limit</u>	<u>tration</u>	<u>Limit</u>
ethod 8080:					
clor 1016	mg/kg	ND	0.080	ND	0.080
cor 1221	mg/kg	ND	0.080	ND	0.080
cTor 1232	mg/kg	ND	0.080	ND	0.080
or 1242	mg/kg	ND	0.080	ND	0.080
₃¶or 1248	mg/kg	ND	0.080	ND	0.080
or 1254	mg/kg	ND	0.16	ND	0.16
pr 1260	mg/kg	ND	0.16	ND	0.16
≩ u mmary:					
rogate Recovery:			110	•	99

LOG NUMBER: 1500A
DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/08/91
DATE EXTRACTED: 11/12/91
DATE ANALYZED: 11/13/91
DATE REPORTED: 11/13/91
PAGE: Seven

Sample Type: Soil

Method and Constituent:	<u>Units</u>	Concen- tration	5 Reporting Limit	Meth Concen- tration	od Blank Reporting Limit
EPA Method 8270:					
Phenol	mg/kg	ND	0.33	ND	0.33
Bis(2-Chloroethyl)Ether	mg/kg	ND	0.33	ND	0.33
2-Chlorophenol	mg/kg	ND	0.33	ND	0.33
1,3-Dichlorobenzene	mg/kg	ND	0.33	ND	0.33
1,4-Dichlorobenzene	mg/kg	ND	0.33	ND	0.33
Benzyl Alcohol	mg/kg	ND	0.33	ND	0.33
1,2-Dichlorobenzene	mg/kg	ND	0.33	ND	0.33
2-Methylphenol	mg/kg	ND	0.33	ND	0.33
Bis(2-Chloroisopropyl)Ether	mg/kg	ND	0.33	ND	0.33
4-Methylphenol	mg/kg	ND	0.33	ND	0.33
N-Nitroso-Di-N-Propylamine	mg/kg	ND	0.33	ND	0.33
Hexachloroethane	mg/kg	ND	0.33	ND	0.33
Nitrobenzene	mg/kg	ND	0.33	ND	0.33
Isophorone	mg/kg	ND	0.33	ND	0.33
2-Nitrophenol	mg/kg	ND	0.33	ND	0.33
2,4-Dimethylphenol	mg/kg	ND	0.33	ND	0.33
Benzoic Acid	mg/kg	ND	1.7	ND	1.7
Bis(-2-Chloroethoxy)Methane	mg/kg	ND	0.33	ND	0.33
2,4-Dichlorophenol	mg/kg	ND	0.33	ND	0.33
1,2,4-Trichlorobenzene	mg/kg	ND	0.33	ND	0.33
Naphthalene	mg/kg	ND	0.33	ND	0.33
4-Chloroaniline	mg/kg	ND	0.33	ND	0.33
Hexachlorobutadiene	mg/kg	ND	0.33	ND	0.33
4-Chloro-3-Methylphenol	mg/kg	ND	0.33	ND	0.33
2-Methylnaphthalene	mg/kg	ND	0.33	ND	0.33

LOG NUMBER: 1500A
DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/08/91
DATE EXTRACTED: 11/12/91
DATE ANALYZED: 11/13/91
DATE REPORTED: 11/13/91
PAGE: Eight

Sample Type: Soil

		5		Method Blank		
Method and		Concen-	Reporting	Concen-	d Blank Reporting	
Constituent	<u>Units</u>	<u>tration</u>	_Limit_	tration	Limit_	
EPA Method 8270 (Continued):						
Hexachlorocyclopentadiene	mg/kg	ND	0.33	ND	0.33	
2,4,6-Trichlorophenol	mg/kg	ND	0.33	ND	0.33	
2,4,5-Trichlorophenol	mg/kg	ND	1.7	ND	1.7	
2-Chloronaphthalene	mg/kg	ND	0.33	ND	0.33	
2-Nitroaniline	mg/kg	ND	1.7	ND	1.7	
Dimethylphthalate	mg/kg	ND	0.33	ND	0.33	
Acenaphthylene	mg/kg	ND	0.33	ND		
2,6-Dinitrotoluene	mg/kg	ND	0.33	ND	0.33 0.33	
3-Nitroaninline	mg/kg	ND	1.7	ND	1.7	
Acenaphthene	mg/kg	ND	0.33	NO	0.33	
2,4-Dinitrophenol	mg/kg	ND	1.7	ND		
4-Nitrophenol	mg/kg	ND	1.7	ND	1.7	
Dibenzofuran	mg/kg	ND	0.33	ND ND	1.7	
2,4-Dinitrotoluene	mg/kg	ND	0.33	ND	0.33	
Diethylphthalate	mg/kg	ND	0.33	ND	0.33	
4-Chlorophenyl-Phenylether	mg/kg	ND	0.33		0.33	
Fluorene	mg/kg	ND	0.33	ND	0.33	
4-Nitroaniline	mg/kg	ND	1.7	ND	0.33	
4,6-Dinitro-2-Methylphenol	mg/kg	ND		ND	1.7	
N-Nitrosodiphenylamine (1)	mg/kg	ND	1.7	ND	1.7	
4-Bromophenyl-Phenylether	mg/kg	ND	0.33	ND	0.33	
Hexachlorobenzene	mg/kg		0.33	ND	0.33	
Pentachlorophenol	•	ND	0.33	ND	0.33	
Phenanthrene	mg/kg	ND	1.7	ND	1.7	
Anthracene	mg/kg	ND	0.33	ND	0.33	
accesc	mg/kg	ND	0.33	ND	0.33	

LOG NUMBER: 1500A
DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/08/91
DATE EXTRACTED: 11/12/91
DATE ANALYZED: 11/13/91
DATE REPORTED: 11/13/91
PAGE: Nine

Sample Type: Soil

Method and		 _	5		od Blank
Constituent:	<u>Units</u>	Concen- tration	ReportingLimit_	Concen-	Reporting
EPA Method 8270 (Continued):	211.152	CIUCION	<u>L IIII I U</u>	<u>tration</u>	<u>Limit</u>
Di-N-Butylphthalate	mg/kg	ND	0.22	MD	0.00
Fluoranthene	• •		0.33	ND	0.33
	mg/kg	ND	0.33	ND	0.33
Pyrene	mg/kg 	ND	0.33	ND	0.33
Butylbenzylphthalate	mg/kg	ND	0.33	ND	0.33
3,3'-Dichlorobenzidine	mg/kg	ND	0.67	ND	0.67
Benzo(a)Anthracene	mg/kg	ND	0.33	ND	0.33
Chrysene	mg/kg	ND	0.33	ND	0.33
Bis(2-Ethylhexyl)Phthalate	mg/kg	ND	0.33	ND	0.33
Di-N-Octylphthalate	mg/kg	ND	0.33	ND	0.33
Benzo(b)Fluoranthene	mg/kg	ND	0.33	ND	0.33
Benzo(k)Fluoranthene	mg/kg	ND	0.33	ND	0.33
Benzo(a)Pyrene	mg/kg	ND	0.33	ND	0.33
Indeno(1,2,3-cd)Pyrene	mg/kg	ND	0.33	ND	0.33
Dibenz(a,h)Anthracene	mg/kg	ND	0.33	ND	0.33
Benzo(g,h,i)Perylene	mg/kg	ND	0.33	ND	0.33
Aniline	mg/kg	ND	0.33	ND	0.33
Azobenzene	mg/kg	ND	0.33	ND	0.33
Benzidine	mg/kg	ND	1.7	ND	1.7
Creosote	mg/kg	ND	3.3	ND	3.3
Surrogate % Recovery:					
2-Fluorophenol		52		48	
Phenol-D5		35		32	
Nitrobenzene-D5		56		52	
2-Flourobiphenyl		70		52 58	
2,4,6-Tribromophenol		66		55	
Terphenyl-D14		91		83	

14



		•		•						!	, ,	
* *		·		CIMIN.	DE CUSTOL	Y REC	ORD		•			
Proj. No.	0aKl	Kland	in Pos St, CA	+ Office	1 .		. /		<i> - </i>	1	500	-
Samplers	John .		for:	The :	of	; '		() ()	///	D.	e lo	
	John			•			/ /\&	7 /	/-/-	11 39	e ' = '	
Sample 1D	Date	Time	SITE L	ocation	tainers	13/3			/.	REMARK	s	
	11/8/9/	12:10	1675	7th 5t.	1-64	X/			è 61			
2	<u> </u>	12:15			<u> </u>	<u> </u>	4	_ - -	061	······································		
3A	· \	2:05				\leq			06!			-∤.
_3 <i>B</i>		2:10				Xz	$\leq _ $	_ : -	06'			
10		2:15				XX			06'			
<u>4B</u>		2:20		•		XX	$ \parallel \parallel $	_ 4	ø:6 '	•		
6		1:15	<u> </u>	. 1	:	$\times \times$	41		<u>@3</u> /	Diesel	15/2	, l
7		/:3D				스스	1		a 3'	Diesel	Islam	4
8	<u> </u>	1:35			<u> </u>	$x \mid x$	4_ _		a3' (6es	Island	-
Relinquis	hed by:	(signat	ure)	Date/Ti	me Recei	ved b	y: (s1g	natur	3)	Dat	e/Time	-
	•			1								
Relinquis	hed by:	(signat	ure)	Date/Ti	ne Recei	ved b	y: (sig	inature	. 4	Dat	e/Time	
Received	for Lab	oratory (by: (sig	nature) .				. i		Date	/Time	<i>\</i>
REMARKS	F/e/	1 Sam	rpling AT		ţ	•	· · · · · · · · · · · · · · · · · · ·	:				1 4 4 5 15
	1-6	t ex				***		,			() () () () () () () () () ()	;

Founding Member of the Association of California Testing Laboratories



		•		CHAIN	OF CUSTO	IY RE	cog	11)				•	D 2	
Proj.No. Project Name					No.								•	
Samplers: (signature)					of									f3
Sample 10	Date	Time	Site L	ocation	Con- tainers	/0						1	MARKS	٠.
3	11/8/7/	12:3 b	1675	7th st.	1-6t.	X					e	.6/2	Comper	ıle
5	. 1	1:00	V	/			쓰	<u>×</u>	<u>ک</u> رد		0	:51	. biste	
				<u> </u>				 -	+		68	ж 	11/11/91	lad
				. 1	:	1	 				¥ 8	у) 	A T	
		•							-	$\ \cdot\ $			c on 11	HA THE
·				,							Łu	c 11/1	491	
Relinqui	shed by:	(signat	ure)	Date/Ti	me Recei	ved	by:	(s	ign	ati	ire)		Date/T	me
Rel inquis		(signat	ure)	Date/Ti	me Recei	ved	by:	(s	ign	atı	ire)	-:	Date/T	me.
Rece I ved	for Labo	ratory	y: (sig	nature)					·		i į		Date/Tim	18
REMARKS		` ` ;				•								

LOG NUMBER: 1500A
DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/08/91
DATE EXTRACTED: 11/09/91
DATE ANALYZED: 11/11/91
DATE REPORTED: 11/13/91
PAGE: Three

Sample Type: Soil

Method and Constituent:

Concen- Reporting Concen- Reporting
Units tration Limit tration Limit

Standard Method 5520F Hydrocarbons:

Oil and Grease

mg/kg ND / 5

ND

50

OC Summary:

% Recovery: 72*

% RPD:

0.0

Concentrations reported as ND were not detected at or above the reporting limit.

* The Recovery is for the Laboratory Control Sample, due to interference in the spiked sample.

LOG NUMBER: 1500A
DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/08/91
DATE EXTRACTED: 11/11/91
DATE ANALYZED: 11/12/91
DATE REPORTED: 11/13/91
PAGE: Ten

 <u>Sampl</u>	<u>e_</u>	<u>lype:</u>	Soil

Method and Constituent:	<u>Units</u>	Concen- tration	5 Reporting Limit	Meth Concen- tration	od Blank Reporting	OC Sumr	%
EPA Method 7130:	<u> </u>	21 45 1511	<u> </u>	CLACION	<u>Limit</u>	Recovery	RPD
Cadmium	mg/kg	1.0 √	0.25	ND	0.25	110	2.1
EPA Method 7190:						1	
Chromium	mg/kg	24 √	1.2	ND	1.2	82	0.6
EPA Method 7420: Lead	mg/kg	68 /	2.5	ND.		1	
EPA Method 7520:	mg/kg	00 V	2.5	ND	2.5	89	2.9
Nickel	mg/kg	18 🗸	7.5	ND	7.5	100	1.9
EPA Method 7950:		,				·	
Zinc	mg/kg	90√	1.2	ND	1.2	95	0.9

Concentrations reported as ND were not detected at or above the reporting limit.

Louis W. DuPuis

Quality Assurance/Quality Control Manager

3423 Investment Boulevard, #8 • Hayward, California 94545

Telephone (510) 783-6960 Facsimile (510) 783-1512

LOG NUMBER: 1499 DATE SAMPLED:

11/08/91 DATE RECEIVED: 11/08/91 DATE EXTRACTED: 11/08/91

DATE ANALYZED: 11/10/91 DATE REPORTED: 11/11/91

CUSTOMER:

R.S. Eagan and Company

REQUESTER:

Bob Eagan

PROJECT:

USPS, 1675 7th Street

Sample Type:

Soil

Composite of

Alternate

. 2 and 3 Method Blank Method and Concen-Reporting Concen-Reporting

Constituent:

<u>Units</u> tration <u>Limit</u> tration

DHS Method:

Total Petroleum Hydro-

carbons as Diesel

mg/kg

ND

1.0

ND

1.0

QC Summary:

% Recovery: 88

% RPD:

33

LOG NUMBER: 1499
DATE SAMPLED: 11/08/91
DATE RECEIVED: 11/08/91
DATE EXTRACTED: 11/09/91
DATE ANALYZED: 11/11/91
DATE REPORTED: 11/11/91
PAGE: Two

	···		Sample	Type:	Şoil		
		Composi					
		Alter		Method Blank			
Method and			nd 3 Reporting	Concen-	<u>u blank</u> Reporting		
Constituent:	Units	tration	Limit	tration	<u>Limit</u>		
DHS Method:							
Total Petroleum Hydro-		/	•				
carbons as Gasoline	mg/kg	ND 🗸	0.50	ND	0.50		
EPA Method 8020 for:			I				
Benzene	mg/kg	ND /	0.0050	ND	0.0050		
Toluene	mg/kg	ND	0.0050	ND	0.0050		
Ethylbenzene	mg/kg	ND /	0.0050	ND	0.0050		
Xylenes	mg/kg	ND J	0.015	ND	0.015		

OC Summary:

% Recovery: 120 % RPD: 5.6

Concentrations reported as ND were not detected at or above the reporting limit.

Louis W. DuPuis

Quality Assurance/Quality Control Manager



November 15, 1991

Mr. Robert Eagan R.S. Eagan and Company 1992 National Avenue Hayward, California 94545-1787

Dear Mr. Eagan:

Trace Analysis Laboratory took twenty four soil samples on November 12, 1991 for your project, Oakland Main Post Office, 1675 7th Street, Oakland, CA (our custody log number 1519).

These samples were composited and analyzed for Total Petroleum Hydrocarbons as Diesel, Gasoline, Benzene, Toluene, Ethylbenzene and Xylenes. Our analytical report and the completed chain of custody form are enclosed for your review.

Trace Analysis Laboratory is certified under the California Environmental Laboratory Accreditation Program. Our certification number is 1199.

If you should have any questions or require additional information, please call me.

Sincerely yours,

Jennifer Pekol

Project Specialist

Enclosures

Telephone (510) 783-6960 Facsimile (510) 783-1512

LOG NUMBER: 1519
DATE SAMPLED: 11/12/91

DATE RECEIVED: 11/12/91 DATE EXTRACTED: 11/13/91 DATE ANALYZED: 11/15/91

DATE REPORTED: 11/15/91

CUSTOMER:

R.S. Eagan and Company

REQUESTER:

Robert Eagan

PROJECT:

Oakland Main Post Office, 1675 7th Street, Oakland, CA

		Sample	Type: Soil	
Method and Constituent:	<u>Units</u>	Composite of 1. 2. 3. and 4 Concen- Reporting tration Limit		Composite of 9, 10, 11, and 12 Concen Reporting tration Limit
DHS Method:				1
Total Petroleum Hydro- carbons as Diesel	mg/kg	1,500 1.8	1,600 / 1.8	1,600 9.8
Method and Constituent:	<u>Units</u>	Composite of 13. 14. 15. and 16 Concen- Reporting tration Limit	Composite of 17, 18, 19, and 20 Concen- Reporting tration Limit	21, 22, 23, and 24
DHS Method: Total Petroleum Hydro- carbons as Diesel	mg/kg	1,600 / 9.8	660 9.8	2,600 / 9.8

Concentrations reported as ND were not detected at or above the reporting limit.

Trace Analysis Laboratory, Inc.

LOG NUMBER: 1519
DATE SAMPLED: 11/12/91
DATE RECEIVED: 11/12/91

DATE EXTRACTED: 11/13/91
DATE ANALYZED: 11/15/91
DATE REPORTED: 11/15/91

PAGE:

Two

Sample Type: Soil

Method and Concen- Reporting

Constituent: Units tration Limit

DHS Method:

Total Petroleum Hydrocarbons as Diesel mg/kg ND 1.5

QC Summary:

% Recovery: 73* % RPD: 12

Concentrations reported as ND were not detected at or above the reporting limit;

* The Recovery is based on the Laboratory Control Sample due to high concentration of diesel in the spiked sample.

Trace Analysis Laboratory, Inc.

LOG NUMBER:	1519
DATE SAMPLED:	11/12/91
DATE RECEIVED:	11/12/91
DATE EXTRACTED:	11/12/91
DATE ANALYZED:	11/15/91
DATE REPORTED:	11/15/91
PAGE:	Three

			Sample	Type:	Soil		
Method and Constituent:	<u>Units</u>	1. 2. Concen-	osite of 3, and 4 Reporting Limit		osite of 7, and 8 Reporting Limit	Compo 9, 10, 1 Concen- tration	site of 1. and 12 Reporting Limit
DHS Method: Total Petroleum Hydro- carbons as Gasoline	mg/kg	590 🗸	4.2	770 🗸	4.2	240	
EPA Method 8020 for:						1	
Benzene	mg/kg	2.5	0.26	1.3	√ 0.26	3.1	0.26
Toluene	mg/kg	46	0.22	13	0.22	0.61	0.22
Ethylbenzene	mg/kg	12	0.26	12	0.26	4.3	0.26
Xylenes	mg/kg	160	0.62	180	0.62	77	0.62
Method and Constituent:	<u>Units</u>	Compo 13, 14, Concen- tration	site of 15. and 16 Reporting Limit		site of 19. and 20 Reporting Limit	21, 22, 2	site of 3. and 24 Reporting Limit
DHS Method:						, ——— <u>——</u> j	
Total Petroleum Hydro- carbons as Gasoline	mg/kg	280 /	4.2	190 🗸	4.2	210	4.2
EPA Method 8020 for:							
Benzene	mg/kg	ND 🗸	0.26	ND 🗸	0.26	ND X	0.26
Toluene	mg/kg	2.8	0.22	1.3	0.22	1.8	0.22
Ethylbenzene	mg/kg	3.2	0.26	0.93	0.26	2.8	0.26
Xylenes	mg/kg	100	0.62	18	0.62	63	0.62

Concentrations reported as ND were not detected at or above the reporting limit.

Trace Analysis Laboratory, Inc.

LOG NUMBER: 1519 DATE SAMPLED: 11/12/91 11/12/91 DATE RECEIVED: DATE EXTRACTED: 11/12/91 DATE ANALYZED: 11/15/91 DATE REPORTED: 11/15/91 PAGE: Four

Sample Type:

Soil

		Metho	<u>d Blank</u>
Method and		Concen-	Reporting
<u>Constituent:</u>	<u>Units</u>	<u>tration</u>	Limit_
DHS Method:			
Total Petroleum Hydro- carbons as Gasoline	mg/kg	ND	0.50
EPA Method 8020 for:			
Benzene	mg/kg	ND	0.0050
Toluene	mg/kg	ND	0.0050
Ethylbenzene	mg/kg	ND	0.0050
Xylenes	mg/kg	ND	0.015

QC Summary:

% Recovery: 80

% RPD: 24

Concentrations reported as ND were not detected at or above the reporting limit.

Louis W. DuPuis

Quality Assurance/Quality Control Manager

				CHAIN	DE CUSTON	Y REC	жо					
Proj.No	Daklam 1675 Oakla	ject Nam 7th nd, cA	ne Post	office	No.		. /					
Sampler	Samplers: (signature) John Kanj									Pay	e lof	3
Sample 1D	Date	Time	Site Lo	ocation	Con- tainers	13/2		//			L 51 9	., 1
1	11/12/91	2:25	1675	7 54.	1-6t.)					•	\ !	
2		230				<u> </u>	((Co-	e)	<u> </u>	tocke	1/c # 1	
3		2:35							1	•	posite	
4		2:40					<u> </u>		<u> </u>	 		_
		· ·		n	Residence		_ _	_ _		 		_
5		2.45			18	J-4	_ _	_	<u> </u>	•		
6		2:50				XX	(G)	η)	>5	tockp	le # 11	
7	 ,- -	2:55						_		comp	posite	_
:8 	₩.	2:00	Ψ		$-\Psi$		 	-	<u> </u>		<u> </u>	_
Relinquis	hed by:	(signat	ure)	Date/Tin	Rece 1	ved by	/: (s1g	gnatui	re)		Date/Ti	ae
Relinquis				Date/Tim	e Recei	ved by	': (siç	yna tur	(e)		Date/Tip	per
Received	for Labo	oratory (by: (sign	iature)				·			ate/Time	3. 3.1
REMARKS	Fiel 3-1 501	1	pling			•						1 5 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
	97. 1-6 97.	it a 2' K Equadic	na Mambae -1	the Association	a of College	Tastle				,		
. '	, 8'	\ \ \ UUINII	is wailinal Oi	the Associatio	n or Calliotti. `	# 1 ##UM	LEDOTAT	DF168				



					CHAIN	OF (CUSTOD	Y RI	FCOL	(1)					ì	
	Proj.No. Project Name Ookland Main Post Office 1675-7th St									386		/:				
Sampler	Samplers: (signature)						of	:.	· /	/	A				/ 2/c	20f
Sample 1D	Date	Time	Site	Loca	tion	ta	Con- iners					/.			ENARK	5 · ·
9 `	11/12/91	3:05	1675	フ州	St.	1-	-bt.						DE.			
10		3110						>×	X	(с	pmρ	<u>) </u>		Stick	pile	#3
11		3:15					1 1						<u> </u>	con	osite	
12		2.50					12					خ	_			
									<u>:</u>			<u> </u>			<u> </u>	
13		32.5					(1) ·		•	
14		2:30	··	•				≥Χ	×	<u>(</u> %	<u>~p)</u>		<u> </u>	stock	pile positi	<u>"3</u>
15	+	3:35												Com	ροσιπ	
. H	<u>- V.</u>	3:40														
Rel inquis	hed by:	(s ignat	urė)	0	ate/Ti	me	Recei	ved	by:	(:	ign	atu	re)		Dat	e/Time
Relinquis	_	(signat	ure)	- 1	ate/Ti	ne	Recei	ved	by:	(s	ign	atu	re)	•‡	Dat	e/Time
Received		oratory	by: (s	ignat	ure)			- M		/ 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 		•	i į	4.	Date	/Time
REMARKS			•					•	٠.		. *,					

				CHATH:	QE_CUSTO	DY R	FCORO				· 		
Proj.No		No.					//		1	p ireles in			
Sampler	Samplers: (signature)										Pa	e 3 of	3
Sample	Date	Time	Site	Location	Con- tainers				/n.	//	' ' '	ARKS -	
17	11/1491	5:45	1675	7th St	Hbt:	1)		 	
18		3:50)		\\\\\\	X	(con	9)	51	Focho	10 × 7	
19		5:55								/		posite	
70		4:00			1				;	<u> </u>			
	 		 				<u> </u>						_
2/		4:05		· · · · · · · · · · · · · · · · · · ·		7.				<u> </u>			_
22		4:10		. :	:	$ \times $	X ((com)	<u> </u>	ockpi	,	_
23	-	4:15	<u> </u>	7		1_1	-	_	_	}	comp	25 ME	4
29	· ·	4:28	+		4	-		-	<u>ب</u>		· · · · · · · · · · · · · · · · · · ·	 	-
Rel inquis	shed by:	(s ignat	ure)	Date/Ti	me Rece	lved	by:	 (s igr	l l latui	re)		Date/Time	-
Relinquis	_	(signat	ure)	Date/Ti	me Rece	lved	by:	(s ign	atur	•	.,	Date/Time	
			·····			 		·		· 		. 	
Received	for Lab	oratory :	by: (s1	gnature)	•				. ;	į		ate/Time	
REMARKS						•			,	:			



1912 Mational and Hayword. Ca.

				CHAIN C	7F (-)	US 1 C	וייטע	RECO	RD		Y	DATE		_ PAGE OF_	
PROJECT NAME Client	USPS	.167	5 724				Z		AA.	NALYS	is ရှိခ ြင့်ပ				7
Address			2.0			_/	7	//	7	7/	7/	7	O OF CONTRIBERS		SAMPLER-GOLD
	1675	774	IX Galile	end		//	//		/.	/{\}	" / ,	/ ,	Ori	•	ď
SAMPLERS (SIGNATION)	NATURE)	(com	Michael .		-/4	o. / 0.	/30/	%·/s	\sim	\mathcal{Y}	//		140	1499	E
SAMPLE NO.	DATE	TIME			120	12 × 12	27 12°	18 4 40. 44	Z		//		*o.	.1.10	. 4
	1	TIME	LOCATION		~	~~~	- 7	+	Y ,			_			1 8
Alternate 1	11-8-91	0845	6'					X							
afternot 2	11-8511	0847	9'	İ				X					Compasi	+3 saupl	4-4 ¥
Afternot 3	11-291	B850	/3'		1			X					1)		1 5
												1		エムエ	TRANSPORTER
					1			1				 	sol(TAT	
	1	 			┼─			 	-			├	welk-1	<u> </u>	-
· · · · · · · · · · · · · · · · · · ·			<u> </u>				_					<u> </u>	1-bt e	1	_
						} \					1		on ice		1
					1-							\vdash	1/2/2		┤┊
		<u> </u>				-		-	}}			 	δ		1 1
		ļ								-			ĺ		 7
															LAB-YELLOW
RELINQUISHED	<i>, ,</i>	DATE	3 RELINQUISHED BY	f: / 1	DATE	5 P	LINOU	SHED	BY:		DATE		TOTAL NUMBER	OF CONTAINERS	1
Signature	hal .	118				11/	$X \perp$	Sen 10			11/6/	 	SAMPLE COL		J _
, orginature		9/	Signature	/ L		Signa	ture //	1	-1	4	1/1/	1	O. (£2 00 .	KOTTIONS	1 38
Printed Name	1-	TIME	Printed Name		TIME	Printe	d Name	1 x v	me !		TIME	SE	ALED	YES/NO	AND GREEN
I'm Victor	<u>15 · </u>	0900									19:35	RE	CEIVED ON ICE	YES/NO	
Company						Comp	_				Į '	SF	ECIAL SHIPMEN	T/HANDLING	WHITE
2 RECEIVED BY:	1	DATE	4 RECEIVED BY:	1	DATE	6.RE	CEIVE	BY (LAB):	11	DATE		R STORAGE REQ		
Signature	5	1/891	Signature			()	MAL!	41/1	16	NO	1.7				GRC
PICK RENN	ICTT		Oignatul B	ļ 	····	Signat		Chras	- 101		11/8/91				1 0
Printed Name		TIME	Printed Name		TIME	Printe	d Nam	THE STATE OF THE S	> (N)	<u>~1</u>	TIME				ĺ
6		0900			į	Printe	mi fe	(P	kel		9:35	SHIF	PING TICKET NO	D.:	1
Company	T	-0	Company			Сопр	any					L			

APPENDIX I

PHOTOGRAPHS




Photo A: Uncovering one of the 10,000-gallon USTs.




Photo B: 5,000-gallon UST excavation with visible contamination on the side wall.

Oakland MPO

Project Number: 1708-001-00

Appr.

Date: 4/22/92

Seo/Resource Consultants, Inc.




Photo C: Contamination in the 10,000-gallon UST excavation on the bottom and side walls.




Photo D: 10,000-gallon UST excavation with sheet pile shoring.

Project	Name:
---------	-------

Oakland MPO

Project Number: 1708-001-00

Appr.

4/22/92 Date:




Photo E: H&H pump truck vacuuming the 10,000gallon UST.




Photo F: Removal of the 5,000-gallon UST.

Pr	oject	Name:	

Oakland MPO

Project Number: 1708-001-00

Appr.



Photo G: Soil sampling of the 10,000-gallon UST excavation side wall.




Photo H: Hole in the 5,000-gallon gasoline UST.

Project Name:	Oakland MPO
Project Number	1708-001-00

Appr.	
Date:	4/22/92




Photo I: Compacting soil during the backfilling operations.




Photo J: Foundation preparation for the concrete pad for the waste oil UST.

Oakland MPO

Project Number: 1708-001-00

Appr.

Date: 4/22/92

Geo/Resource Consultants, Inc.




Photo K: Bedding for the new USTs with the first of six deadmen being placed in the excavation.




Photo L: Soap-test inspection of the 12,000-gallon UST prior to placement into excavation.

Oakland MPO

Project Number:

1708-001-00

Appr.

Date: 4/22/92

Geo/Resource Consultants, Inc.




Photo _ M : Product pump plumbing for the USTs.




Photo N: UST electrical and plumbing connections.

Oakland MPO

Project Number: 1708-001-00

Appr.

Date: 4/22/92




Photo O: Three vents from the new USTs attached to the rail.



Photo P: Soap-test inspection of the product line joint with the inspector.

Project Name:	Oakland MPO
Project Number:	1708-001-00

Appr.		
ate:	4/22/92	




Photo Q: Two product lines, one vapor recovery line, and TLS-350 electrical conduit.




Photo R: Waste oil AGST.

Project Name: Project Number: 1708-001-00

Oakland MPO

Appr.

Date: 4/22/92

