Harding Lawson Associates



Transmittal/Memorandum

To:

Alameda County Department of Environmental Health

80 Swan Way, Room 200 Oakland, California 94621

Attention: Mr. Lowell Miller

From:

David Leland &

Date:

April 6, 1989

Subject:

February 1989 Treatment System Monitoring Report

Job No.:

09382,018.02

Remarks:

Please find attached a copy of the "Report of System Monitoring: February

1989, Dewatering Effluent Treatment System, Chinatown

Redevelopment Project Area, Oakland, California", describing the operations and monitoring of the treatment system located at 10th and Webster Streets in Oakland.

DL:cb/c9/032

cci



A Report Prepared for

California Regional Water Quality Control Board San Francisco Bay Region 1111 Jackson Street, Room 6000 Oakland, California 94607

REPORT OF SYSTEM MONITORING: FEBRUARY 1989 DEWATERING EFFLUENT TREATMENT SYSTEM CHINATOWN REDEVELOPMENT PROJECT AREA OAKLAND, CALIFORNIA

HLA Job No. 9382,018.02

Submitted on behalf of:

City of Oakland Redevelopment Agency One City Hall Plaza Oakland, California 94612

bу

Charles E. Myrick

Project Engineer

David F. Leland Associate Hydrologist

Harding Lawson Associates 7655 Redwood Boulevard P.O. Box 578 Novato, California 94948 415/892-0821

April 5, 1989

TABLE OF CONTENTS

LIST OF TAE	BLES	iii
I	INTRODUCTION	1
11	TREATMENT SYSTEM OPERATION	2
III	TREATMENT SYSTEM MONITORING	3
	A. Sample Collection and Analysis B. Discharge Limit Exceedences	3
IV	RESULTS	5
TABLES		
Appendix A	LABORATORY ANALYTICAL RESULTS FOR TREATMENT SYSTEM SAMPLES	
DISTRIBUTION	ON	

ii

A7910-H

LIST OF TABLES

Table 1	Treatment System Water Analysis:	Influent Samples
Table 2	Treatment System Water Analysis:	Intermediate Samples
Table 3	Treatment System Water Analysis:	Effluent Samples
Table 4	Treatment System Water Analysis:	Blank Samples

1 INTRODUCTION

This report discusses the operation and monitoring of the dewatering effluent treatment system at 10th and Webster streets, Oakland, California, from February 1 to February 28, 1989. The system is treating water produced during ground-water dewatering of the block bounded by 10th, 11th, Webster, and Franklin streets, in conjunction with construction in progress at the site. The system is designed to remove petroleum hydrocarbons from dewatering effluent before the effluent is discharged to the storm drain.

This report has been prepared by Harding Lawson Associates (HLA) and is submitted in compliance with NPDES Permit CA 0029394, adopted on July 20, 1988, by the California Regional Water Quality Control Board, San Francisco Bay Region (RWQCB). Under the NPDES permit, treatment system discharge limits are 50 parts per billion (ppb) for total petroleum hydrocarbons (TPH) identified as gasoline; 5.6 ppb for lead; 5.0 ppb each for chlorobenzene, 1,2-dichloroethane, 1,2-dichloropropane, trichloroethylene, 1,1,2-trichloroethane, benzene, xylenes, and ethylbenzene; 0.5 ppb for toluene; 0.01 ppb for ethylene dibromide; and 0.0 ppb for total residual chlorine.

II TREATMENT SYSTEM OPERATION

The dewatering effluent treatment system was installed March 8, 1988, and has been in continuous operation since March 14, 1988. Water is treated by pumping it through four carbon contactors arranged in pairs. Organic compounds in the influent are adsorbed on the carbon. Each pair of contactors is arranged in parallel, and together constitute a module; the two modules are arranged in series. The system is configured so that water from the dewatering wells may be pumped through either module first. The system also comprises a holding tank for influent water, pumps, filters, piping, and instrumentation. Four water sampling ports -- one influent, two intermediate, and one effluent -- enable water samples to be collected throughout the treatment process. The intermediate ports are located between the two modules so the effectiveness of the first pair of contactors in reducing influent concentrations can be monitored. Depending on the configuration of modules, only one of these ports is intermediate in the system at any one time.

Treated effluent is discharged to the storm drain. From February 1 to March 1, 1989, total discharge of the system was 357,000 gallons, based on readings of the flow totalizing meter located in the discharge line. Average flow for this period was 8.9 gallons per minute (gpm).

The system was backwashed on February 4. The carbon in all four adsorption vessels was replaced by Northwestern Carbon on February 13.

Throughout the month, a floating residential swimming pool type chlorinator was deployed in the holding tank to retard algal growth in the treatment system.

III TREATMENT SYSTEM MONITORING

A. Sample Collection and Analysis

During this reporting period, treatment system samples were collected on February 8 from the influent, intermediate, and effluent sampling ports. A field blank was submitted with the samples collected.

All treatment system samples collected were analyzed by Pace Laboratories, Novato, California, a California-certified laboratory. The samples and blank were analyzed for halogenated organics by EPA Test Method 8010. Influent, effluent and blank samples were analyzed for TPH as gasoline using EPA Test Method 8015 and for aromatic organics by EPA Test Method 8020. Influent and effluent samples were analyzed for ethylene dibromide by EPA Test Method 504, for residual chlorine by Standard Method 408E, and for dissolved oxygen by EPA Test Method 360.2.

Results of analyses of samples collected November 18, 1988 through February 8, 1989 are summarized in Tables 1 through 4. Only analytical results for samples collected in February are discussed in this report. Laboratory reports for treatment system samples collected on February 8 are presented in Appendix A.

B. <u>Discharge Limit Exceedences</u>

There were three possible exceedences of permitted effluent discharge limits during this reporting period. The reported concentration of 1,2-dichloroethane in an effluent sample collected on February 8 was 9.1 μ g/l (micrograms per liter, equivalent to ppb), as measured by EPA Test Method 8010. The reported concentration of toluene in an effluent sample collected on February 8 was 0.9 μ g/l. Ethylene dibromide was also detected in the same sample at a concentration of 0.06 μ g/l. Possible explanations for these exceedences include breakthrough as a result of carbon exhaustion, "channeling" in

the carbon beds, sample contamination during field operations, and/or laboratory analytical procedures. The most likely source of the 1,2-dichloroethane and ethylene dibromide is breakthrough. The most likely source of the toluene is either sample contamination or laboratory analytical procedures, since toluene was also detected in the field blank at a concentration of 1.0 μ g/l.

All carbon beds in the treatment system were replaced on February 13.

There were no other exceedences of permitted effluent discharge limits during this reporting period.

IV RESULTS

Results of influent, intermediate, and effluent sample analyses for TPH and for EPA Test Method 8010, 8020, 8240 and 504 compounds, indicate that on the sampling date, the treatment system removed most individual constituents to below detection levels. The following compounds were detected at the concentrations given in effluent samples collected February 8: toluene at 0.9 μ g/l, methylene chloride at 1.4 μ g/l, 1,1-dichloroethane at 1.4 μ g/l, chloroform at 1.6 μ g/l, 1,2-dichloroethane at 9.1 μ g/l, trichloroethene at 2.2 μ g/l, and ethylene dibromide at 0.06 μ g/l.

In the blank sample submitted February 8, methylene chloride was detected at a concentration of 2.9 μ g/l, and toluene was detected at a concentration of 1.0 μ g/l.

HLA SAMPLE ID # Date		61801 11/18		52301 11/23		73001 11/30		91201 12/07		01501 12/15	88512 12	2/21		10501 01/05		21201 01/12		60801 02/08
TEST METHOD/ COMPOUNDS		=====	======	*****	222222		:======	232222	======		=======	=====	******	======		22222		====
EPA 8020																		
Benzene	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NT			9.2	NT		ND <	0.2
Toluene	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NT			6.1	NT			1.1
Chlorobenzene	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NT		ND <	0.2	NT		ND <	0.2
Ethylbenzen e	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NŤ		ND <	0.2	NT		ND <	0.2
Xylenes	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NT		ND <	0.2	NT		ND <	0.3
1,2-Dichlorobenzene	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NT		ND <	0.2	NT		ND <	0.2
All other 8020 compounds	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NT		ND <	0.2	NT		ND <	0.2
EPA 8015																		
TPH (Gasoline)	ND <	50		60		90	ND <	50	NT		NT			130	NT		ND <	250
Diesel	NT		NT		NT		NT		NT		NT		NT		NT		NT	
EPA 8010																		
1,1-dichloroethene	ND <	0.5	ND <	0.5	NT		NT		ND <	0.5	ND <	0.5		0.8	ND <	0.5	ND <	0.5
Methylene chloride	ND <	0.5	ND <	0.5	NT		NT		ND <	0.5	ND <	0.5	ND <	0.5	ND <	0.5		6.3
1,1-dichloroethane		0.8	ND <	0.5	NT		NT		ND <	0.5	ND <	0.5		1.9		0.5		1.3
Chloroform		0.8		1.6	NT		NT		ND <	0.5		1.1		2.1		0.8		1.5
1,2-dichloroethane		5.7	ND <	0.5	NT		NT			9.2		4.8		10.5		4.9		8.6
Trichloroethene		54		210	NT		NT			390		112	NID. 4	140	un.	290	ur.	420
1,2-dichloropropane	ND <	0.5	ND <	0.5	NT		NT		ND <	0.5	ND <	0.5	ND <	0.5 1.4	ND <	0.5 0.4	ND <	0.5
Tetrachloroethene	ND <	0.5	ND <	0.5	NT		NT		ND <	0.5 0.5	> CIN	0.5 0.5	ND <	0.5	ND <	0.4	ND <	0.9
Chlorobenzene	ND <	0.5	ND <	0.5	NT		NT NT		ND <	0.5	ND <	0.5	ND <	0.5	MD <	0.5	ND <	
Bromoform	ND <	0.5 0.5	ND <	0.5 0.5	NT NT		NT		ND <	0.5	ND <	0.5	ND <	0.5	ND <	0.5	ND <	
1,1,2,2-tetrachloroethane	ND <	0.5	ND <	0.5	NT		NT		ND <	0.5	ND <	0.5	ND <	0.5	ND <	0.5	ND <	0.
Dibromochloromethane All other 8010 compounds	ND \	0.5	ND \	0.5	NT		NT		ND \	0.7	ND \	0.5	ND \	0.5	ND `	۷.,	ND	٠
EPA 8240																		
1,1-dichloroethene	NT		NT			0.5	ND <	0.5	NT		NT		NT		NT		NT	
Methylene chloride	NT		NŤ			0.6		0.6	ŇŤ		NT		NT		NT		NT	
1.1-dichloroethane	NT		NT			1.1		0.7	NT		NT		NT		NT		NT	
Chloroform	NT		NT			1.5		0.7	NT		NT		NT		NT		NT	
1,2-dichloroethane	NT		NT			9.4		5.8	NT		NT		NT		NT		NT	
Benzene	NT		NT		ND <	0.5	ND <	0.5	NT		NT		NT		NT		NT	
Trichloroethene	NT		NT			239		91.1	NT		NT		NT		NT		NT	
Toluene	NT		NT		ND <	0.5	ND <	0.5	NT		NT		NT		NT		NT	
1,1,2-trichloroethane	NT		NT		ND <	0.5	ND <	0.5	NT		NT		NT		NT		NT	
Tetrachloroethene	NT		NT			0.6	ND <	0.5	NT		NT		NT		NT		NT	
Chlorobenzene	NT		NT		ND <	0.5	ND <	0.5	NT		NT		NT		NT		NT	
All other 8240 compounds	NT		NT		ND <	0.5	ND <	0.5	NT		NT		NT		NT		NT	
EPA 504																		_
Ethylene dibromide	ND <	0.01		0.05	ND <	0.01		0.02	NT		NT		ND <	0.02	NT			0.0
Standard Method 408E Residual chlorine (mg/l)	ND <	0.2	ND <	0.01	ND <	0.01	ND <	0.01	NT		NT		ND <	0.01	NT		ND <	0.0
	,								***									
EPA 360.2 Dissolved oxygen (mg/l)	NT		NT		NT		NT		NT		NT		NT		NT			6.

ND - Not detected at stated detection limit.

NT - Not Tested.

All results reported in parts per billion (ppb) except where indicated.

HLA SAMPLE ID #	884618		88473002	88491202	88501502	88512102	89010502	89021202	89060802 02/08
DATE	11/	18 11/23	11/30	12/07	12/15	12/21	01/05	01/12	
	322223555	=======================================	=======================================	=======================================		:===============			========
TEST METHOD/COMPOUNDS									
EPA 8020									
Benzene	NT	NT	NT	NT	NT	NT	ND < 0.2	NT	NT
Toluene	NT	NT	NT	NT	NT	NT	ND < 0.2	NT	NT
Ethylbenzene	NT	NT	NT	NT	NT	NT	ND < 0.2	NT	NT
Xylenes	NT	NT	HT	MT	NT	NT	ND < 0.2	NT	NT
Chlorobenzene	NT	NT	NT	NT	NT	NT	ND < 0.2	NT	NT
1.3-Dichlorobenzene	NT	NT	NT	NT	NT	NT	ND < 0.2	NT	NT
All other 8020 compounds	NT	NT	NT	NT	NT	NT	ND < 0.2	NT	NT
EPA 8015									=
TPH (Gasoline)	NT	NT	NT	NT	NT	NT	ND < 50	NT	NT
Diesel	NT	NT	NT	NT	NT	NT	NT	NT	NT
EPA 8010									
Methylene chloride		.5 ND < 0.5		NT	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5	1.5
1,1-dichloroethane		.7 ND < 0.5		NT	ND < 0.5	0.6	ND < 0.5	ND < 0.5	1.3
Chloroform		.2 2.0		NT	ND < 0.5	1.2	ND < 0.5	ND < 0.5	1.4
1,2-dichloroethane		'.9 4.9		NT	7.1	6.0	3.4	1.4	8.
Trichloroethene		21 16.1	NT	NT	33.0	ND < 0.5	18.0	16.0	9.7
Tetrachloroethene	ND < 0).5 ND < 0.5		NT	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5
Chlorobenzene).5 ND < 0.9		NT	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5
Bromoform	ND < 0	1.5 ND < 0.5		NT	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.
1,3-dichlorobenzene	ND < 0).5 ND < 0.5		NT	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5
All other 8010 compounds	ND	ND	NT	NT	ND	ND	ND	ND	ND
EPA 8240									
Methylene chloride	NT	NT	2.0	ND < 0.5	NT	NT	NT	NT	NT
1,1-dichloroethane	NT	NT	1.2	1.5	NT	NT	NT	NT	NT
Chloroform	NT	NT	1. <u>7</u>	1.7	NT	NT	NT	NT	NT
1,2-dichloroethane	NT	NT	9.7	9.4	NŢ	NT	NT	NT	NT
Trichloroethene	NT	NŤ	28.3	18.7	NT	NT	NT	NT	NT
Toluene	NT	NT	ND < 0.5	ND < 0.5	NT	NT	NT	NT	NT
1,2-dichlorobenzene	NT	NT	ND < 0.5	ND < 0.5	NT	NT	NT	NT	NT
All other 8240 compounds	NT	NT	ND	ND	NT	NT	NT	NT	NT
EPA 504									u-
Ethylene dibromide	NT	NT	NT	NT	NT	NT	NT	NT	NT
Residual chlorine						4			NT
Residual chlorine (mg/l)	NT	NT	NŤ	NT	NT	NT	NT	NT	15 I

ND - Not detected at stated detection limit. NT - Not Tested. All results reported in parts per billion (ppb) except where indicated.

	\			TABLE	3. TR	EATMENT	SYSTEM	WATER /	NALYSIS	: EFFLU	ENT SAM	PLES				1	PAC	GE 1
HLA SAMPLE ID # DATE TOTAL FLOW (THOUSAND GALLONS	8846 1 64	1803 1/18 35.2	884	62303 11/23 5510.0		473004 11/30 6645.1	88	491204 12/07 6762.0	885	01503 12/15 830.6	885	12103 12/21 972.2	89	010504 01/05 7200.0	890	021204 01/12 7310.7	890	060803 02/08 7784.3
AVERAGE FLOW (GPM)	******	13.7		10.4	:=====	13.4		11.6 ======		6.0		16.4		10.5 	:======	11.0 		12.2
TEST METHOD/COMPOUNDS																		
EPA 8020																		
Benzen e	ND <	0.2	ND <	0.2	ND <		ND <		NT		NT		ND <		NT		ND <	
Toluene	ND <	0.2	ND <	0.2	ND 4		ND <		NT		NT		ND <		NT			0.9
Ethylbenzene	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NT		ND <		NT		ND <	
Xylenes	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NT		ND <	0.2	NT		ND <	0.2
Diphenylhydrazine	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NT		ND <	0.2	NT		ND <	0.2
All other 8020 compounds	ND <	0.2	ND <	0.2	ND <		ND <		NT		NT		ND <	0.2	NT		ND <	0.2
EPA 8015							*											
TPH (Gasoline)	ND <	50	ND <	50	ND <	50	ND <	50	NT		NT		ND <	50	NT		ND <	250
Diesel	NT		NT		NT		NT		NT		NT		NT		NT		NT	
EPA 8010																		
Dichlorodifluoromethane		28	ND <		NT		NT		ND <	2.0	ND <	2.0	ND <		ND <		ND <	
1,1-dichlorethene	ND <	0.5		12.3	NT		NT		ND <	0.5	ND <	0.5	ND <		ND <		ND <	
Methylene chloride	ND <	0.5	ND <	0.5	NT		NT		ND <	0.5	ND <	0.5	ND <	0.5	ND <			1.4
1.1-dichloroethane	ND <	0.5	ND <	0.5	NT		NT		ND <	0.5	ND <	0.5		1.0		0.9		1.4
Chloroform	ND <	0.5	ND <	0.5	NT		NT		ND <	0.5	ND <	0.5		1.4		1.0		1.6
1,1,1-trichloroethane	ND <	0.5		4.3	NT		NT		ND <	0.5	ND <	0.5	ND <	0.5	ND <	0.5	ND <	0.5
1,2-dichloroethane	110	3.6		2.7	NT		NT			4.3		3.5		6.8		5.3		9.1
Trichloroethene	ND <	0.5	ND <		NT.		NT		ND <	0.5	ND <	0.5		0.8		1.0		2.2
Tetrachloroethene	ND <	0.5	ND <		NT		NT		ND <		ND <	0.5	ND <		ND <		ND <	
All other 8010 compounds	ND \	0.5	ND	0.5	NT		NT		ND	0.5	ND	0.5	ND	0.5	ND	0.5	ND	0.2
EPA 8240																		
Methylene Chloride	NT		NT			1.6	ND <	0.5	NT		NT		NT		NT		NT	
1.1-dichloroethane					ND 4			0.8	NT		NТ		NT		NT		NT	
Chloroform					ND 4			0.8	NT		NT		NT		NT		NT	
1,2-dichloroethane	NT		NT		110	2.2		5.1	NT		NT		NT		NT		NT	
Trichloroethene	NT		NT		ND 4		ND <		NT		NT		NT		NT		NT	
Toluene	NT		NT			0.5	ND <		NT		NT		NT		NT		NT	
All other 8240 compounds	NT		NT		ND	. 0.5	ND \	0.5	NT		NT		ÑŤ		NT		NT	
•									•••								***	
EPA 360.2 Dissolved oxygen (mg/l)	NT		NT		NT		NT		NT		NT		NT		NT			9.9
EPA 625																		
All compounds	NT		NT		NT		NT		NT		NT		NT		NT		NT	
EPA 504																		
Ethylene dibromide	ND <	0.01	ND <	0.01	ND ·	< 0.01	ND <	0.02	NT		NT		ND <	0.02	NT			0.06
Standard Method 408E Residual chlorine (mg/l)	ND <	0.2	ND <	0.01	ND ·	< 0.01	ND <	0.01	NT		NT		ND <	0.01	NT		ND <	0.01
Lead 7421 Lead (mg/l)	NT		NT		NT		NT		NT		NT		NT		NT		NT	

ND - Not detected at stated detection limit. NT - Not Tested. All results reported in parts per billion (ppb) except where indicated.

ETTETTETTETTETTTTTTTTTTTTTTTTTTTTTTTTT		 61805		62305		73005	884	91205		01505		12105		10505		21205		60805
ATE		11/18		11/23		11/30		12/07		12/15		12/21		01/05		01/12		02/08
	ZZZZZZZ	z=====	======	======	======	======	======	======	#=====		======							
EST METHOD/COMPOUNDS																		
PA 8020				_													ND 4	
Benzene	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NŤ		NT		ND <	0.2	NT		ND <	0.2
l'oluene	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NT		ND <	0.2	NT			1.0
Ethylbenzene	₩ ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NŤ		NT		ND <	0.2	NT		ND <	0.2
(ylenes	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NT		ND <	0.2	NT		ND <	0.2
All other 8020 compounds	ND <	0.2	ND <	0.2	ND <	0.2	ND <	0.2	NT		NT		ND <	0.2	NT		ND <	0.2
A 8015																		
IPH (Gasoline)	ND <	50	ND <	50	ND <	50	ND <	50	NT		NT		NT		NT		NT	
Diesel	NT		NT		NŤ		NT		NT		NT		NT		NT		NT	
PA 8010																		
Dichlorodifluoromethane		28	ND <	2.0	NT		NT		ND <	2.0	ND <	2.0	ND <	2.0	ND <	2.0	ND <	2.0
.1-dichloroethene	ND <	0.5		1.3	NT		NT		ND <	0.5	ND <	0.5	ND <	0.5	ND <	0.5	ND <	
lethylene chloride		1.0		3.8	NT		NT			13	ND <	0.5		9.6		1.0		2.9
1,1,1-trichloroethane	ND <	0.5		0.7	NT		NT		ND <	0.5	ND <	0.5	ND <	0.5	ND <	0.5	ND <	
1.2-dichloroethane	ND <	0.5	ND <	0.5	NT		NT		ND <	0.5	ND <	0.5	ND <	0.5	ND <	0.5	ND <	0.5
All other 8010 compounds	ND		ND		NT		NT		ND		ND		ND		ND		ND	
PA 8240															_			
Toluene	NT		NT		ND <	0.5	ND <	0.5	NT		NT		NT		NT		NT	
Methylene Chloride	NT		NT			4.6		25.3	NT		NT		NT		NŤ		NT	
Chloroform	NT		NT		ND <	0.5	ND <	0.5	NT		NT		NT		NT		NT	
Diphenylhydrazine	NT		NT		ND <	0.5	ND <	0.5	NT		NT		NT		NT		NT	
All other 8240 compounds	NT		NT		ND		ND		NT		NT		NT		NŤ		NT	
PA 625																	44-7	
All compounds	NT		NT		NT		NT		NT		NT		NT		NT		NT	
PA 504													MT		мт		NT	
Ethylene dibromide	NT		NT		NT		NT		NT		NT		MT		NT		76 (

ND - Not detected at stated detection limit.

NT - Not Tested. All results reported in parts per billion (ppb) except where indicated.

Appendix A

LABORATORY ANALYTICAL RESULTS FOR TREATMENT SYSTEM SAMPLES

Pace laboratories, nc

REPORT OF LABORATORY ANALYSIS

Offices:

Minneapolis, Minnesota Tampa, Florida Coralville, Iowa Novato, California

FORMERLY WESCO LABORATORIES

Harding Lawson Associates 200 Rush Landing Road Novato, CA 94947 March 09, 1989

PACE Project Number: 490208.504

Attn: Mr. David Leland

Re: City of Oakland

Date Sample(s) Collected: 02/08/89 Date Sample(s) Received: 02/08/89 EFFLUENT WIDL INFLUENT 70539 70540 70541 PACE Sample Number: 89060802 89060803 MDL 89060801 Units Parameter **INORGANIC ANALYSIS** INDIVIDUAL PARAMETERS 0.01 ND ND mq/L Chlorine, Total Residual 9.9 0.5 6.6 Oxygen, Dissolved mg/L ORGANIC ANALYSIS INDIVIDUAL PARAMETERS Petroleum Fuels, Purgeable, as Gasoline mg/L ND ND 0.25 (EPA Method 8015, Modified) HALOGENATED VOLATILE COMPOUNDS EPA 8010 2.0 ND ND ND Dichlorodifluoromethane ug/L 2.0 ND ND ND Chloromethane ug/L ND ND Vinyl Chloride ug/L 2.0 ND 2.0 ND ND ND Bromomethane ug/L 2.0 ND ND ND Chloroethane ug/L ug/L 2.0 ND ND ND Trichlorofluoromethane ND ND 1,1-Dichloroethene ug/L 0.5 ND 6.3 1.5 1.4 0.5 Methylene Chloride ug/L ND trans-1,2-Dichloroethene ug/L 0.5 ND ND 0.5 1.2 1.3 1.4 1.1-Dichloroethane ug/L 1.6 0.5 1.5 1.4 Chloroform ug/L ND ND 0.5 ND 1,1,1-Trichloroethane (TCA) ug/L ND ND 0.5 ND Carbon Tetrachloride uq/L 8.2 0.5 8.6 9.1 1.2-Dichloroethane (EDC) ug/L 9.7 2.2 0.5 420 Trichloroethene (TCE) ug/L 0.5 ND ND 1,2-Dichloropropane ug/L ND ND ug/L 0.5 ND ND Bromodichloromethane 0.5 ND ND ND 2-Chloroethylvinyl ether ug/L

MDL

Method Detection Limit, Estimated Value.

ND

Not detected at or above the MDL.

Pace laboratories inc

REPORT OF LABORATORY ANALYSIS

Offices:

Minneapolis, Minnesota Tampa, Florida Coralville, Iowa Novato, California

FORMERLY WESCO LABORATORIES Mr. David Leland Page 2

March 09, 1989

PACE Project Number: 490208.504

PACE Sample Number: Parameter	<u>Units</u>	MDL	70539 89060801	70540 89060802	70541 89060803
ORGANIC ANALYSIS					
HALOGENATED VOLATILE COMPOUNDS EPA 8010					
trans-1,3-Dichloropropene	ug/L	0.5	ND	ND '	ND
cis-1,3-Dichloropropene	ug/L	0.5	ND	ND	ND
1,1,2-Trichloroethane	ug/L	0.5	ND	ND	ND
Tetrachloroethene	ug/L	0.5	0.66	ND	ND .
Dibromochloromethane	ug/L	0.5	ND	ND	ND
Ch1 orobenzene	ug/L	0.5	ND	ND	ND
Bromoform	ug/L	0.5	ND	ND	ND
1,1,2,2-Tetrachloroethane	ug/L	0.5	ND	ND	ND
1,3-Dichlorobenzene	ug/L	0.5	ND	ND	ND
1,4-Dichlorobenzene	ug/L	0.5	ND	ND	ND
1,2-Dichlorobenzene	ug/L	0.5	ND	ND	ND
Bromochloromethane (Surrogate Recovery)	ž . –		84	82	80
1,4-Dichlorobutane (Surrogate Recovery)	%		99	98	91
AROMATIC VOLATILE COMPOUNDS EPA 8020				•	
Benzene	ug/L	0.2	ND	-	ND
Toluene	ug/L	0.2	1.1	_	0.88
Chlorobenzene	ug/L	0.2	ND	-	ND
Ethylbenzene	ug/L	0.2	ND	-	ND
Xylene	ug/L	0.2	ND	-	ND
1,3-Dichlorobenzene	ug/L	0.2	ND	-	ND
1,4-Dichlorobenzene	ug/L	0.2	ND	_	ND
1,2-Dichlorobenzene	ug/L	0.2	ND	_	ND
Fluorobenzene (Surrogate Recovery)	%	V.L	98	-	86
1,2-DIBROMOETHANE (EDB) EPA METHOD 504					
1,2-Dibromoethane	ug/L	0.02	0.05	-	0.06
Date extracted	_		02-10-89	_	02-10-89

MDL Method Detection Limit, Estimated Value.
ND Not detected at or above the MDL.

PACE laboratories, nc

REPORT OF LABORATORY ANALYSIS

Offices:

Minneapolis, Minnesota Tampa, Florida Coralville, Iowa Novato, California

FORMERLY WESCO LABORATORIES
Mr. David Leland
Page 3

March 09, 1989

PACE Project Number: 490208.504

PACE Sample Number: Parameter	<u>Units</u>	MDL	70542 89060804	70543 89060805
ORGANIC ANALYSIS				
INDIVIDUAL PARAMETERS				
Petroleum Fuels, Purgeable, as Gasoline	mg/L	0.25	ND	ND .
HALOGENATED VOLATILE COMPOUNDS EPA 8010				
Dichlorodifluoromethane	ug/L	2.0	ND	ND
Chloromethane	ug/L	2.0	ND	ND
Vinyl Chloride	ug/L	2.0	ND	ND
Bromomethane	ug/L	2.0	ND	ND
Ch1oroethane	ug/L	2.0	ND	ND
Trichlorofluoromethane	ug/L	2.0	ND	ND
1,1-Dichloroethene	ug/L	0.5	ND	ND
Methylene Chloride	ug/L	0.5	1.4	2.9
trans-1,2-Dichloroethene	ug/L	0.5	ND	ND
1,1-Dichloroethane	ug/L	0.5	1.4	ND
Chloroform	ug/L	0.5	1.5	ND
1,1,1-Trichloroethane (TCA)	ug/L	0.5	ND	ND
Carbon Tetrachloride	ug/L	0.5	ND	ND
1,2-Dichloroethane (EDC)	ug/L	0.5	8.8	ND
Trichloroethene (TCE)	ug/L	0.5	2.0	ND ·
1,2-Dichloropropane	ug/L	0.5	ND	ND
Bromodichloromethane	ug/L	0.5	ND	ND
2-Chloroethylvinyl ether	ug/L	0.5	ND	ND
trans-1,3-Dichloropropene	ug/L	0.5	ND	ND
cis-1,3-Dichloropropene	ug/L	0.5	ND	ND
1,1,2-Trichloroethane	ug/L	0.5	N D	ND
Tetrachloroethene	ug/L	0.5	ND	ND
Dibromochloromethane	ug/L	0.5	ND	ND
Ch1orobenzene	ug/L	0.5	ND	ND
Bromoform	ug/L	0.5	ND	ND
1,1,2,2-Tetrachloroethane	ug/L	0.5	ND	ND
1,3-Dichlorobenzene	ug/L	0.5	ND	ND
1,4-Dichlorobenzene	ug/L	0.5	ND	ND

MDL Method Detection Limit, Estimated Value. ND Not detected at or above the MDL.

atories, inc.

REPORT OF LABORATORY ANALYSIS

Offices:

Minneapolis, Minnesota Tampa, Florida Coralville, Iowa Novato, California

FORMERLY WESCO LABORATORIES Mr. David Leland

Page

March 09, 1989

PACE Project Number: 490208.504

PACE Sample Number: Parameter	Units	MDL	70542 89060804	70543 89060805
ORGANIC ANALYSIS				
HALOGENATED VOLATILE COMPOUNDS EPA 8010 1,2-Dichlorobenzene Bromochloromethane (Surrogate Recovery) 1,4-Dichlorobutane (Surrogate Recovery)	ug/L %	0.5	ND 82 89	ND 73 84
AROMATIC VOLATILE COMPOUNDS EPA 8020 Benzene Toluene Chlorobenzene Ethylbenzene Xylene 1,3-Dichlorobenzene	ug/L ug/L ug/L ug/L ug/L ug/L	0.2 0.2 0.2 0.2 0.2 0.2	ND O.93 ND ND ND ND	ND O.95 ND ND ND ND
1,4-Dichlorobenzene 1,2-Dichlorobenzene Fluorobenzene (Surrogate Recovery)	ug/L ug/L %	0.2 0.2	ND ND 88	ND ND 84

MDL ND

Method Detection Limit, Estimated Value. Not detected at or above the MDL.

Approved:

Project Manager for PACE Laboratories

Technical Reviewer for

PACE Laboratories

SOURCE

2 3

2 3

 z^3

3

Job Number: ___

Project Manager: __

MATRIX

Sediment

LAB

Wk

NUMBER -

Sea

Soil

Water

Harding Lawson Associates

Name/Location: C:ty 4 Oakland

#CONTAINERS & PRESERV.

HNO3

Unpres. H₂ SO₄

3

5

CHAIN OF CUSTODY FORM

		100	,
Lab:	Lab:	PALL	_

ANALYSIS REQUESTED

200 Rush Landing Road P.O. Box 6107 Novato, California 94948 415/892-0821

Telecopy: 415/892-1586 09830202602

SAMPLE

NUMBER

OR

LAB

NUMBER

Sea

8 9 0

08 048 9

Wk:

Time

09131

091

0

DATE

Mo I Dv

208

0208

890208

Samplers: Caleb A. Ocanony

Recorder: _

(Signature Required)

esi, **200** 49815 STATION DESCRIPTION 118/10(**NOTES**

Serietar Produ bek - 5. 1

e in the dole

STEWN ROEN HAVE

EPA 602/8020 EPA 624/8240* EPA 625/8270* Priority Plitnt. Metals 601/8010 EPA (

X XX

Lance 1

QA

CODE

V .

COL

MTD

CD

DEPTH

1N

F.EET

MISCELLANEOUS

CHAIN OF CUSTODY RECORD

RELINQUISHED BY: (Signature)

RELINQUISHED BY: (Signature)

RECEIVED BY: (Signature)

RECEIVED BY: (Signature)

RECEIVED BY: (Signature)

RECEIVED BY: (Signature)

DATE/TIME DATE/TIME

DATE/TIME

DATE/TIME

RELINQUISHED BY: (Signature)

RELINQUISHED BY: (Signature)

DISRATCHED BY: (Signature)

DATE/TIME

RECEIVED FOR LAB BY: (Signeture)

DATE/TIME Strue Aloran

METHOD OF SHIPMENT

Laboratory Copy Project Office Copy Field or Office Copy Pink Yellow White

DISTRIBUTION

REPORT OF SYSTEM MONITORING: FEBRUARY 1989 DEWATERING EFFLUENT TREATMENT SYSTEM CHINATOWN REDEVELOPMENT PROJECT AREA OAKLAND, CALIFORNIA April 5, 1989

COPY NO. <u>4</u>

		Copy No.
1 copy:	California Regional Water Quality Control Board San Francisco Bay Region 1111 Jackson Street, Room 6000 Oakland, California 94607	1
	Attention: Mr. Scott Huganberger	
2 copies:	City of Oakland Redevelopment Agency One City Hall Plaza Oakland, California 94612	2-3
	Attention: Mr. Peter Chen	•
I copy:	Alameda County Department of Environmental Health 80 Swan Way, Room 200 Oakland, California 94621	4
	Attention: Mr. Lowell Miller	

CEM/DFL/CRS/clm/A7910-R

QUALITY CONTROL REVIEWER

Christopher R. Smith Geologist - 4619