



November 13, 1998 Project 20805-190.001

Mr. Paul Supple **ARCO Products Company** P.O. Box 6549 Moraga, California 94570

Quarterly Groundwater Monitoring Report, Second Quarter 1998, for ARCO Service Re:

Station No. 0374, located at 6407 Telegraph Avenue, Oakland, California

Dear Mr. Supple:

Pinnacle Environmental Solutions, a division of EMCON (Pinnacle), is submitting the attached report which presents the results of the second quarter 1998 groundwater monitoring program at ARCO Products Company (ARCO) Service Station No. 0374, located at 6407 Telegraph Avenue, Oakland, California. The monitoring program complies with the Regional Water Quality Control Board - San Francisco Bay Region requirements regarding underground tank investigations.

LIMITATIONS

No monitoring event is thorough enough to describe all geologic and hydrogeologic conditions of interest at a given site. If conditions have not been identified during the monitoring event, results should not be construed as a guarantee of the absence of such conditions at the site, but rather as the product of the scope and limitations of work performed during the monitoring event.

Please call if you have questions.

Sincerely,

Pinnacle

Glen Vander Veen Project Manager

Johnson, R.G.

Sénior Project Supervisor

Quarterly Groundwater Monitoring Report, Second Quarter 1998 Attachment:

cc: Ms. Susan Hugo, Alameda County Health Care Services Agency Mr. John Kaiser, Regional Water Quality Control Board - S.F. Bay Region

Walnut Creek, California 94596

Date:

November 13, 1998

ARCO QUARTERLY GROUNDWATER MONITORING REPORT

Facility No.	: 0374	Address:	6407 Telegraph Avenue, Oakland, California
	ARCO Environmental E	Engineer:	Paul Supple
	Consulting Co./Contact		· - · · · · · · · · · · · · · · · · · ·
	Consultant Pro	niect No.:	20805-190.001
Pr	imary Agency/Regulator		- w o water named C E Boy Region

WORK PERFORMED THIS QUARTER (SECOND - 1998):

- 1. Prepared and submitted quarterly groundwater monitoring report for first quarter 1998.
- 2. Performed quarterly groundwater monitoring and sampling for second quarter 1998.
- 3. Continued intrinsic bioremediation enhancement at Well MW-3 using oxygen release compound socks.

WORK PROPOSED FOR NEXT QUARTER (THIRD - 1998):

- 1. Prepare and submit quarterly groundwater monitoring report for second quarter 1998.
- 2. Perform quarterly groundwater monitoring and sampling for third quarter 1998.
- 3. Continue intrinsic bioremediation enhancement at Well MW-3. Install ORC socks into well MW-4.

QUARTERLY MONITORING:

Current Phase of Project: Monitoring/Remediation Frequency of Groundwater Sampling: Annual (3rd Quarter): MW-1, MW-2, MW-6 Semiannual (1st/3rd Quarter): MW-3, MW-4	
Semiannual (1st/3rd Quarter): MW-3, MW-4	
— — — — — — — — — — — — — — — — — — —	
Quarterly: MW-5	
Frequency of Groundwater Monitoring: Quarterly	
Is Free Product (FP) Present On-Site: No	
FP Recovered this Quarter: None	
Cumulative FP Recovered to Date: None	
Bulk Soil Removed This Quarter: None	
Bulk Soil Removed to Date: None	
Current Remediation Techniques: Bioremediation enhancement	
Average Depth to Groundwater: 6.0 feet	
Groundwater Flow Direction and Gradient	
(Average): 0.04 ft/ft toward southwest	<u></u>

DISCUSSION:

- TPPH-g and benzene concentrations at downgradient perimeter Well MW-5 remained below detection limits this quarter.
- The occurrence of intrinsic bioremediation at the site was documented during third quarter 1996.
- Intrinsic bioremediation enhancement at the off-site Well MW-3 is in progress. Please refer to Attachment D for details.

ATTACHMENTS:

- Groundwater Elevation and Analytical Data Table 1 -
- Groundwater Analytical Summary Map Figure 1 -
- Groundwater Elevation Contour Map Figure 2 -
- Appendix A Sampling and Analysis Procedures
- Appendix B Certified Analytical Report and Chain-of-Custody Documentation
- Appendix C Field Data Sheets
- Appendix D Remedial System Performance Summary

Table 1
Groundwater Elevation and Analytical Data
Total Purgeable Petroleum Hydrocarbons
(TPPH as Gasoline, BTEX Compounds, and MTBE)


ARCO Service Station 0374 6407 Telegraph Avenue at Alcatraz Avenue Oakland, California


		(17.11	Depth to	Groundwater	TPPH as			Ethyl-		_	Dissolved	Purged/
	Date	Well	Depin to Water	Elevation	Gasoline	Benzene	Toluene	benzene	Xylenes	MTBE	Oxygen	Not purge
Well	Gauged/	Elevation		(feet, MSL)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)	(ppb)	(ppm)	(P/NP)
Number	Sampled	(feet, MSL)							Annually			
MW-1	01/31/96	158.91	6.34	152.57				Sampled	Annually			
	04/10/96		5.82	153.09			 -0.5	. 3ampica 20.5	<0.5	340	NM	
	07/16/96		7.23	151.68	<50	<0.5	לייט. ומעני		Annually	,		
	10/14/96		8.34	150.57	**********		JAME	l Campica	Annually	,		
	03/27/97		6.37	152,54			17	t Gamelog t Gamelog	Annually			
	05/27/97		7.30	151.61				0.5<	<0.5	620	NM	
	08/12/97		8.22	150.69	<50	<0.5	C.U>		Annually		.,,	
	11/17/97		7.98	150.93			Wel	1 Sampieu 1 Campled	Annually			1
	03/16/98		4.94	153.97	A		Wel	1 Sampled	Amuany			
	05/12/98		5.28	153.63	************		Wel	I Sampled	Annually			
							Wal	II Campled	Annually	,,		
MW-2	01/31/96	157.92	6.51	151.41			Well	ii Sampicu Ii Sampled	Annually			3
	04/10/96		6.94	150.98	<50				<0.5	33	NM	l
	07/16/96		7.73	150.19	<30	1.2	- We	II Samoled	Annually			
	10/14/96		8.35	149.57			We	ii Sampica II Sampled	Annually			•
	03/27/97		7.40	150.52	********	***************	Wa.	u Sampiod U Samoled	Annually			-
	05/27/97		7.82	150.10					s <0.5	23	NM	[
	08/12/97		8.29	149.63	<50	<0.5	11/2	II Sampled	Annually			_
	11/17/97		8.05	149.87			 	II Sampled	Annually		,	-
	03/16/98		6.45	151.47			37/s	II Sampled	Annually			_
	05/12/98		6.93	150.99	-+-+	~	WC	n sampec	Millian y			
		100.01	7.02	146.62	140) 20	0.87	7 1	1 14	NA		
MW-3*	01/31/96	153.64	7.82	145.82	84		4 <0.5	5 1.	9 1.1	NA		
	04/10/96		6.80	146.84	<50		2 <0.5	< 0.	5 <0.5	<2.5		
	07/16/96			145.97	<50	•		5 <0.	5 0.81	2.9	NN	1
	10/14/96		7.67	146.02	<50			5 0	9 0.63	<2.5	NN	1
	03/27/97		7.62	146.92		-	Wei	Sampled	Semiannually	y		
	05/27/97		6.72	145.44	<51	0 <0.		-				A .
	08/12/97		8.20		<u> </u>		Well Sami	oled Semia	nnually		12.	0
	11/17/97		7.64	146.00	<5				5 <0.5	<3	4.	0 P
	03/18/98		5.14	148.50	ζ,	0	Wel		Semiannuall	y	·	
	05/12/98		5.53	148.11			,, 0,	. Dumpise		•		
	24.24.26	156.51	5.64	150.89	23	0 2	3 2.	2 3	.7 32	, NA		
MW-4	01/31/96	156.53		149.87	7.30			0 3:	50 830			
	04/10/96		6.66	148.80	5,60		-		40 520) 150		
	07/16/96		7.73	147.98	4,50		_		50 340) <62		
	10/14/96		8.55	147.98	25,00				50 2,600	<250) NI	M
	03/27/97		7.15						Semiannuall	ly		
	05 <i>/</i> 27 <i>/</i> 97		7.75	148.78	4,80	00 95			40 210) N	M
	08/12/97		8.46	148.07	4,00	,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			Semiannual	ly		
	11/17/97		8.24	148.29	<:	50 <0	5 <0	.5 <0).5 <0.5	5 <	3 1	.5 P
	03/16/98		5.32	151.21	<	,			Semiannual	jy		
	05/12/98	ı	6.38	150.15			716			•		

Table 1 Groundwater Elevation and Analytical Data Total Purgeable Petroleum Hydrocarbons (TPPH as Gasoline, BTEX Compounds, and MTBE)

ARCO Service Station 0374 6407 Telegraph Avenue at Alcatraz Avenue Oakland, California

Well	Date Gauged/	Well Elevation	Depth to Water	Groundwater Elevation (feet, MSL)	TPPH as Gasoline (ppb)	Benzene (ppb)	Toluene (ppb)	Ethyl- benzene (ppb)	Xylenes (ppb)	MTBE (ppb)	Dissolved Oxygen (ppm)	Purged/ Not purged (P/NP)
Number	Sampled	(feet, MSL)					<0.5	<0.5	<0.5	NA.	NM	
MW-5	01/31/96	151.33	8.64	142.69	<50 -50	<0.5 <0.5	<0.5	<0.5	<0.5	NA	NM	
	04/10/96		N/A		<50	0.79	1.3	<0.5	<0.5	<2.5	NM	
	07/16/96		8.15	143.18	<50	<0.5	<0.5	<0.5	<0.5	<2.5	NM	
	10/14/96		7.92	143.41	<50	<0.5	<0.5	<0.5	<0.5	<2.5	NM	
	03/27/97		7.75	143.58	<50	<0.5	<0.5	<0.5	<0.5	<2.5	NM	ĺ
	05 <i>/</i> 27 <i>/</i> 97		8.16	143.17	<50		II Inaccessi				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	•
	08/12/97					 0.5>	0.5>	<0.5	<0.5	<2.5	4,0	NP
	11/17/97		8.75	142.58	<50	<0.5	<0.5			<3	1.5	P
	03/16/98		6.90	144,43	<50	<0.5	<0.5		<0.5	<3	2.2	P
	05/12/98		7.24	144.09	<50	<0.5	νυ	702	10.0			
			- 4-	140.40			W el	I Sampled	Annually			•
MW-6	01/31/96	153.84	5.15	148.69			We	I Sampled	Annually			-
	04/10/96		4.58	149.26	<50				<0.5	150	NM	5
	07/16/96		4.96	148.88	<30	~0.0	We					-
	10/14/96		6.15	147.69			We	II Sampled	Annually			-
	03/27/97		4.40	149.44			We	II Sampled	Annually			-
	05/27/97		4.90	148.94	<50		<0.5	<0.5	<0.5	39	NN	1
	08/12/97		5.43	148,41	\ 30	~~~	We					•
	11/17/97		5.87	147.97			We	II Sampled	Annually		~~~~~	-
	03/16/98		4,52	149.32	# 7777		We	II Sampled	Annually			
	05/12/98	_	4.42	149.42								
MTBE MSL	= Methyl ter	t-butyl ether.										
MSL TOC	= Top of cas											
	= Parts per b											
ppb	= Parts per t	nillion.										
ppm	= taus por t	innioni Ishoratory del	ection limit st	ated to the right								
< N 4	= Not analy											
NA	= Not measi											
NM NC	= Not measi											
NS	= Not samp											
N/A	= LAOT SASIIS	1010. 11 - I !11	L!ina 11/	14/95. Please 16	fer to Anne	ndiv D for e	fetails.					





APPENDIX A SAMPLING AND ANALYSIS PROCEDURES

APPENDIX A

SAMPLING AND ANALYSIS PROCEDURES

The sampling and analysis procedures for water quality monitoring programs are contained in this appendix. The procedures provided for consistent and reproducible sampling methods, proper application of analytical methods, and accurate and precise analytical results. Finally, these procedures provided guidelines so that the overall objectives of the monitoring program were achieved.

The following documents have been used as guidelines for developing these procedures:

- Procedures Manual for Groundwater Monitoring at Solid Waste Disposal Facilities, Environmental Protection Agency (EPA)-530/SW-611, August 1977
- Resource Conservation and Recovery Act (RCRA) Groundwater Monitoring Technical Enforcement Guidance Document, Office of Solid Waste and Emergency Response (OSWER) 9950.1, September 1986
- Test Methods for Evaluating Solid Waste: Physical/Chemical Methods, EPA SW-846,
 3rd edition, November 1986
- Methods for Organic Chemical Analysis of Municipal and Industrial Waste Water, EPA-600/4-82-057, July 1982
- Methods for Organic Chemical Analysis of Water and Wastes, EPA-600/4-79-020, revised March 1983
- Leaking Underground Fuel Tank (LUFT) Field Manual, California State Water Resources Control Board, revised October 1989

Sample Collection

Sample collection procedures include equipment cleaning, water level and total well depth measurements, and well purging and sampling.

Equipment Cleaning

Before the sampling event was started, equipment that was used to sample groundwater was disassembled and cleaned with detergent water and then rinsed with deionized water. During field sampling, equipment surfaces that were placed in the well or came into contact with groundwater during field sampling were steam cleaned with deionized water before the next well was purged or sampled.

Water Level, Floating Hydrocarbon, and Total Well Depth Measurements

Before purging and sampling occurred, the depth to water, floating hydrocarbon thickness, and total well depth were measured using an oil/water interface measuring system. The oil/water interface measuring system consists of a probe that emits a continuous audible tone when immersed in a nonconductive fluid, such as oil or gasoline, and an intermittent tone when immersed in a conductive fluid, such as water. The floating hydrocarbon thickness and water level were measured by lowering the probe into the well. Liquid levels were recorded relative to the tone emitted at the groundwater surface. The sonic probe was decontaminated by being rinsed with deionized water or steam cleaned after each use. A bottom-filling, clear Teflon bailer was used to verify floating hydrocarbon thickness measurements of less than 0.02 foot. Alternatively, an electric sounder and a bottom-filling Teflon bailer may have been used to record floating hydrocarbon thickness and depth to water.

The electric sounder is a transistorized instrument that uses a reel-mounted, two-conductor, coaxial cable that connects the control panel to the sensor. Cable markings are stamped at 1-foot intervals. The water level was measured by lowering the sensor into the monitoring well. A low-current circuit was completed when the sensor contacted the water, which served as an electrolyte. The current was amplified and fed into an indicator light and audible buzzer, signaling when water had been contacted. A sensitivity control compensated for highly saline or conductive water. The electric sounder was decontaminated by being rinsed with deionized water after each use. The bailer was lowered to a point just below the liquid level, retrieved, and observed for floating hydrocarbon.

Liquid measurements were recorded to the nearest 0.01 foot on the depth to water/floating product survey form. The groundwater elevation at each monitoring well was calculated by subtracting the measured depth to water from the surveyed elevation of the top of the well casing. (Every attempt was made to measure depth to water for all wells on the same day.) Total well depth was then measured by lowering the sensor to the bottom of the well. Total well depth, used to calculate purge volumes and to determine whether the well screen was partially obstructed by silt, was recorded to the nearest 0.1 foot on the depth to water/floating product survey form.

Well Purging

If the depth to groundwater was above the top of screens of the monitoring wells, then the wells were purged. Before sampling occurred, a polyvinyl chloride (PVC) bailer, centrifugal pump, low-flow submersible pump, or Teflon bailer was used to purge standing water in the casing and gravel pack from the monitoring well. Monitoring wells were purged according to the protocol presented in Figure A-1. In most monitoring wells, the amount of water purged before sampling was greater than or equal to three casing volumes. Some monitoring wells were expected to be evacuated to dryness after removing fewer than three casing volumes. These low-yield monitoring wells were allowed to recharge for up to 24 hours. Samples were obtained as soon as the monitoring wells recharged to a level sufficient for sample collection. If insufficient water recharged after 24 hours, the monitoring well was recorded as dry for the sampling event.

Groundwater purged from the monitoring wells was transported in a 500-gallon water trailer, 55-gallon drum, or a 325-gallon truck-mounted tank to EMCON's San Jose or Sacramento office location for temporary storage. EMCON arranged for transport and disposal of the purged groundwater through Integrated Waste Stream Management, Inc.

Field measurements of pH, specific conductance, and temperature were recorded in a waterproof field logbook. Figure A-2 shows an example of the water sample field data sheet on which field data are recorded. Field data sheets were reviewed for completeness by the sampling coordinator after the sampling event was completed.

The pH, specific conductance, and temperature meter were calibrated each day before field activities were begun. The calibration was checked once each day to verify meter performance. Field meter calibrations were recorded on the water sample field data sheet.

Well Sampling

A Teflon bailer was the only equipment acceptable for well sampling. When samples for volatile organic analysis were being collected, the flow of groundwater from the bailer was regulated to minimize turbulence and aeration. Glass bottles of at least 40-milliliters volume and fitted with Teflon-lined septa were used in sampling for volatile organics. These bottles were filled completely to prevent air from remaining in the bottle. A positive meniscus formed when the bottle was completely full. A convex Teflon septum was placed over the positive meniscus to eliminate air. After the bottle was capped, it was inverted and tapped to verify that it contained no air bubbles. The sample containers for other parameters were filled, filtered as required, and capped.

When required, dissolved concentrations of metals were determined using appropriate field filtration techniques. The sample was filtered by emptying the contents of the Teflon bailer into a pressure transfer vessel. A disposable 0.45-micron acrylic copolymer filter was threaded onto the transfer vessel at the discharge point, and the vessel was sealed. Pressure was applied to the vessel with a hand pump and the filtrate directed into the appropriate containers. Each filter was used once and discarded.

Sample Preservation and Handling

The following section specifies sample containers, preservation methods, and sample handling procedures.

Sample Containers and Preservation

Sample containers vary with each type of analytical parameter. Container types and materials were selected to be nonreactive with the particular analytical parameter tested.

Sample Handling

Sample containers were labeled immediately prior to sample collection. Samples were kept cool with cold packs until received by the laboratory. At the time of sampling, each sample was logged on an ARCO chain-of-custody record that accompanied the sample to the laboratory.

Samples that required overnight storage prior to shipping to the laboratory were kept cool (4° C) in a refrigerator. The refrigerator was kept in a warehouse, which was locked when not occupied by an EMCON employee. A sample/refrigerator log was kept to record the date and time that samples were placed into and removed from the refrigerator.

Samples were transferred from EMCON to an ARCO-approved laboratory by courier or taken directly to the laboratory by the environmental sampler. Sample shipments from EMCON to laboratories performing the selected analyses routinely occurred within 24 hours of sample collection.

Sample Documentation

The following procedures were used during sampling and analysis to provide chain-of-custody control during sample handling from collection through storage. Sample documentation included the use of the following:

- Water sample field data sheets to document sampling activities in the field
- Labels to identify individual samples
- Chain-of-custody record sheets for documenting possession and transfer of samples
- Laboratory analysis request sheets for documenting analyses to be performed

Field Logbook

In the field, the sampler recorded the following information on the water sample field data sheet (see Figure A-2) for each sample collected:

- Project number
- · Client's name
- Location
- Name of sampler
- Date and time
- · Well accessibility and integrity
- Pertinent well data (e.g., casing diameter, depth to water, well depth)

- Calculated and actual purge volumes
- · Purging equipment used
- · Sampling equipment used
- Appearance of each sample (e.g., color, turbidity, sediment)
- Results of field analyses (temperature, pH, specific conductance)
- General comments

The water sample field data sheet was signed by the sampler and reviewed by the sampling coordinator.

Labels

Sample labels contained the following information:

- Project number
- Sample number (i.e., well designation)
- · Sample depth

- · Sampler's initials
- Date and time of collection
- Type of preservation used (if any)

Sampling and Analysis Chain-of-Custody Record


The ARCO chain-of-custody record initiated at the time of sampling contained, at a minimum, the sample designation (including the depth at which the sample was collected), sample type, analytical request, date of sampling, and the name of the sampler. The record sheet was signed, timed, and dated by the sampler when transferring the samples. The number of custodians in the chain of possession was minimized. A copy of the ARCO chain-of-custody record was returned to EMCON with the analytical results.

Groundwater Sampling and Analysis Request Form

A groundwater sampling and analysis request form (see Figure A-3) was used to communicate to the environmental sampler the requirements of the monitoring event. At a minimum, the groundwater sampling and analysis request form included the following information:

- Date scheduled
- Site-specific instructions
- Specific analytical parameters

- Well number
- Well specifications (expected total depth, depth of water, and product thickness)



	WAT	ER SAMPI	LE FIELD	DATA SH	EET	Rev. 5/96
OWT	PURGED BY : _			CLIENT NAME :		
TYPE: G	roundwater			eachate		
	AMETER (Inches):			_	· · · · · · · · · · · · · · · · · · ·	
ASING ELE	EVATION (feet/MSL):	vo	LUME IN CASING	(gal.) :	
DEI	PTH OF WELL (feet):	CAL	CULATED PURGE	(gal.) :	
OEPT	H OF WATER (fee):	ACT	UAL PURGE VOL.	(gal.) :	
DA	ATE PURGED :			END PURGE :		
DA [*]	TE SAMPLED :	<u></u>	SA	MPLING TIME :		
TIME	VOLUME	рН		TEMPERATURE		
(2400 HR)	(gal.)	(units)	(µmhos/cm@25°c)	(°F)	(Visual/NTU)	(2400 HR)
			·			
······································					***************************************	
					ومنايره منشر بالناكان بينت	
OTHER:			ODOR:			
OTHER:		······································			(COBALT 0-100)	(NTU 0-200)
FIELD QC	SAMPLES COLLE	CTED AT THIS WE	ELL (i.e. FB-1, X	DUP-1):	البريسة والمشروب المستدارة	
1	PURGING EQUIPM	ENT		SAMPLIN	IG EQUIPMENT	
2° B	lladder Pump	Bailer (Teflon)		2" Bladder Pu	mpBaile	(Teffon)
	itrifugal Pump	Bailer (PVC)		Bomb Sample	Baile	r (Stainless Steel
	mersible Pump	Bailer (Stainless	s Ste el)	Dipper		nersible Pump
	ii Wizard™	Dedicated	•	Well Wizard ⁿ Other:	4 Dedik	:2teg
			··			
ÆLL INTE	GRITY:				LOCI	<u>ر:</u>
EMARKS:						
H, E.C., Ter	np. Meter Calibration ()ate:	Time:	Me	ter Serial No.:	
				10 /		
emperatura	' F		-			
CICALATI I	m#.			THEN OV.		



WATER SAMPLE FIELD DATA SHEET

FIGURE

A-2



EMCON - SACRAMENTO GROUNDWATER SAMPLING AND ANALYSIS REQUEST FORM

PROJECT NAME:

SCH	EDL	ILED	DATE	:

CIAL INSTI	RUCTIONS / C	ONSIDERATI	IONS :		Project Authorization: EMCON Project No.: OWT Project No.: Task Code: Originals To:	
СНЕСК ВО	X TO AUTHOR	LZE DATA EN	TRY	Site Contact:		Well Lock Number (s)
Well Number or	Casing Diameter	Casing Length	Depth to Water		Name (SES REQUESTED	Phone #
		,	(feet)			



EMCON

SAMPLING AND ANALYSIS REQUEST FORM

FIGURE

A-3

APPENDIX B

CERTIFIED ANALYTICAL REPORTS, AND CHAIN OF CUSTODY DOCUMENTATION



Service Request No.: S9801194

May 27, 1998

Glen Vanderveen **PINNACLE** 144-A Mayhew Wy. Walnut Creek, CA 94596

21775-261.003/TO#22312.00/RAT8/374 OAKLAND RE:

Dear Mr. Vanderveen:

The following pages contain analytical results for sample(s) received by the laboratory on May 12, 1998. Results of sample analyses are followed by Appendix A which contains sample custody documentation and quality assurance deliverables requested for this project. The work requested has been assigned the Service Request No. listed above. To help expedite our service, please refer to this number when contacting the laboratory.

Analytical results were produced by procedures consistent with Columbia Analytical Services' (CAS) Quality Assurance Manual (with any deviations noted). Signature of this CAS Analytical Report below confirms that pages 2 through 8, following, have been thoroughly reviewed and approved for release in accord with CAS Standard Operating Procedure ADM-DatRev3.

Please feel welcome to contact me should you have questions or further needs.

Sincerely,

Steven L. Green

Project Chemist

Greg Anderson

Regional QA Coordinator

Bernaditte I. Cox for

Acronyms

A2LA American Association for Laboratory Accreditation

ASTM American Society for Testing and Materials

BOD Biochemical Oxygen Demand

BTEX Benzene, Toluene, Ethylbenzene, Xylenes

CAM California Assessment Metals
CARB California Air Resources Board

CAS Number Chemical Abstract Service registry Number

CFC Chlorofluorocarbon
CFU Colony-Forming Unit
COD Chemical Oxygen Demand

DEC Department of Environmental Conservation
DEQ Department of Environmental Quality
DHS Department of Health Services
DLCS Duplicate Laboratory Control Sample

DMS Duplicate Matrix Spike
DOE Department of Ecology
DOH Department of Health

EPA U. S. Environmental Protection Agency

ELAP Environmental Laboratory Accreditation Program

GC Gas Chromatography

GC/MS Gas Chromatography/Mass Spectrometry

IC Ion Chromatography

ICB Initial Calibration Blank sample

Inductively Coupled Plasma atomic emission spectrometry

ICV Initial Calibration Verification sample

J Estimated concentration. The value is less than the MRL, but greater than or equal to

the MDL. If the value is equal to the MRL, the result is actually <MRL before rounding.

LUFT Leaking Underground Fuel Tank

M Modified

MBAS Methylene Blue Active Substances

MCL Maximum Contaminant Level. The highest permissible concentration of a

substance allowed in drinking water as established by the U. S. EPA.

MDL Method Detection Limit
MPN Most Probable Number
MRL Method Reporting Limit

M8 Matrix Spike

MTBE Methyl tert-Butyl Ether
NA Not Applicable
NAN Not Analyzed
NC Not Calculated

NCASI

National Council of the paper industry for Air and Stream Improvement

ND

Not Detected at or above the method reporting/detection limit (MRL/MDL)

NIOSH National Institute for Occupational Safety and Health

NTU Nephelometric Turbidity Units

ppb Parts Per Billion ppm Parts Per Million

PQL Practical Quantitation Limit
QA/QC Quality Assurance/Quality Control
RCRA Resource Conservation and Recovery Act

RPD Relative Percent Difference SIM Selected ion Monitoring

SM Standard Methods for the Examination of Water and Wastewater, 18th Ed., 1992

STLC Solubility Threshold Limit Concentration

SW Test Methods for Evaluating Solid Waste, Physical/Chemical Methods, SW-846,

3rd Ed., 1986 and as amended by Updates I, II, IIA, and IIB.

TCLP Toxicity Characteristic Leaching Procedure

TDS Total Dissolved Solids

TPH Total Petroleum Hydrocarbons

trace level. The concentration of an analyte that is less than the PQL but greater than or equal

to the MDL. If the value is equal to the PQL, the result is actually <PQL before rounding.

TRPH Total Recoverable Petroleum Hydrocarbons

TSS Total Suspended Solids

TTLC Total Threshold Limit Concentration

VOA Volatile Organic Analyte(s) ACRONLST.DOC 7/14/95

Analytical Report

Client:

ARCO Products Company

Project:

21775-261.003/TO#22312.00/RAT8/374 OAKLAND

Sample Matrix:

Water

Service Request: \$9801194

Date Collected: 5/12/98
Date Received: 5/12/98

BTEX, MTBE and TPH as Gasoline

Sample Name:

MW-5(23)

Lab Code:

\$9801194-001

Test Notes:

Units: ug/L (ppb) Basis: NA

Analyte	Prep Method	Analysis Method	MRL	Dilution Factor	Date Extracted	Date Analyzed	Result	Result Notes
TPH as Gasoline	EPA 5030	CA/LUFT	50	1	NA	5/14/98	ND	
Benzene	EPA 5030	8020	0.5	1	NA	5/14/98	ND	
Toluene	EPA 5030	8020	0.5	1	NA	5/14/98	ND	
Ethylbenzene	EPA 5030	8020	0.5	i	NA	5/14/98	ND	
Xylenes, Total	EPA 5030	8020	0.5	1	NA	5/14/98	ND	
Mothyl tert-Butyl Ether	EPA 5030	8020	3	1	NA	5/14/98	ND	

IS22/020597p

Analytical Report

Client:

ARCO Products Company

Project:

21775-261.003/TO#22312.00/RAT8/374 OAKLAND

Date Collected: NA

Service Request: S9801194

Sample Matrix:

Water

Date Received: NA

BTEX, MTBE and TPH as Gasoline

Sample Name:

Method Blank

Units: ug/L (ppb)
Basis: NA

Lab Code: Test Notes:

Code: \$980514-WB1

Analyte	Prep Method	Analysis Method	MRL	Dilution Factor	Date Extracted	Date Analyzed	Result	Result Notes
TPH as Gasoline	EPA 5030	CA/LUFT	50	1	NA	5/14/98	ND	
Benzene	EPA 5030	8020	0.5	1	NA	5/14/98	ND	
Toluene	EPA 5030	8020	0.5	1	NA	5/14/98	ND	
Ethylbenzene	EPA 5030	8020	0.5	1	NA	5/14/98	ND	
Xylenes, Total	EPA 5030	8020	0.5	1	NA	5/14/98	ND	
Methyl tert -Butyl Ether	EPA 5030	8020	3	1	NA	5/14/98	ND	

1522/020597p

APPENDIX A

QA/QC Report

Client: ARCO Products Company Service Request: S9801194

Project: 21775-261.003/TO#22312.00/RAT8/374 OAKLAND

Date Collected: NA

Date Received: NA

Date Extracted: NA

Date Analyzed: NA

Surrogate Recovery Summary BTEX, MTBE and TPH as Gasoline

Prep Method: EPA 5030 Units: PERCENT

Analysis Method: 8020 CA/LUFT Basis: NA

		Test	Percent	Recovery
Sample Name	Lab Code	Notes	4-Bromofluorobenzene	a,a,a-Trifluorotoluene
MW-5(23)	S9801194-001		101	86
BATCH QC	S9801158-001MS		98	96
BATCH QC	\$9801158-001DMS		97	103
Method Blank	S980514-WB1		107	91

CAS Acceptance Limits: 69-116 69-116

QA/QC Report

Client: ARCO Products Company

Project: 21775-261.003/TO#22312.00/RAT8/374 OAKLAND

Sample Matrix Water

Service Request: S9801194

Date Collected: NA
Date Received: NA
Date Extracted: NA

Date Analyzed: 5/14/98

Matrix Spike/Duplicate Matrix Spike Summary

TPH as Gasoline

S9801158-001DMS

Sample Name: BATCH QC Lab Code: S9801158-001MS, Units: ug/L (ppb)

Basis: NA

Lab Code: Test Notes:

Percent Recovery

	Prep	Analysis		Spike	e Level	Sample	Spike	Result			CAS Acceptance	Relative Percent	Result
Analyte	Method	Method	MRL	MS	DMS	Result	MS	DMS	MS	DMS	Limits	Difference	Notes
Gasoline	EPA 5030	CA/LUFT	50	250	250	ND	240	240	96	96	75-135	<1	

QA/QC Report

Client: Project: ARCO Products Company

21775-261.003/TO#22312.00/RAT8/374 OAKLAND

Service Request: S9801194

Date Analyzed: 5/14/98

Initial Calibration Verification (ICV) Summary BTEX, MTBE and TPH as Gasoline

Sample Name:

ICV

Units: ug/L (ppb)

Lab Code:

ICV1

Basis: NA

Test Notes:

ICV Source:

CAS

IC V Source.					Percent Recovery		
Analyte	Prep Method	Analysis Method	True Value	Result	Acceptance Limits	Percent Recovery	Result Notes
TPH as Gasoline	EPA 5030	CA/LUFT	250	240	90-110	96	
Benzene	EPA 5030	8020	25	27	85-115	108	
Toluene	EPA 5030	8020	25	27	85-115	108	
Ethylbenzene	EPA 5030	8020	25	28	85-115	112	
Xylenes, Total	EPA 5030	8020	75	85	85-115	113	
Methyl tert -Butyl Ether	EPA 5030	8020	25	23	85-115	92	

ICV/032196

FL, PC, TPH-VOA. **ARCO Products Company Chain of Custody** Task Order No. 22312.00 Division of Atlantic/Richfield Company Project manager GIEN VANGETVEEN

Telephone no (408) 453-730 (Consultant) (408) 437-9520 ARCO Facility no. 0374 City (Facility) Cakland Laboratory Name Telephone no. (ARCO) ARCO engineer Address (Consultant) 144-A Marhew War Walnut Creek, CA 94590 Consultant name TCLP Seria
Metals YOAD YOAD
CAM Metals EPA 60107000
TTLCG STLCG
Lead OrgCHSCG
Lead EPA 74207421C] Method of shipment Matrix Preservation Sampler will deliver TPH EPA 418, 153M 503E TPH Modified 8015 Gas © Diesel © Oil and Grease 413.1 © 413.2 © ٤ EPA 601/8010 EPA 624/8240 EPA 625/8270 Container Soil Water Other Ice Acid Special Detection Limit/reporting Lowest Possible Special QA/QC As Normal Remarks RAT8 2-40m1HQ WOAS Lab Number Tumaround Time: Priority Rush 1 Business Day Rush 2 Business Days Expedited Temperature received: Condition of sample: 5 Business Days Relinguished by sampler Received by Standard Relinguished by Received by 10 Business Days Received by laboratory Time Relinquished by CAS Distribution: White Copy - Laboratory: Canary Copy - ARCO Environmental Engineering: Pink Copy - Consultant

APPENDIX C FIELD DATA SHEETS

EMCON - Groundwater Sampling and Analysis Request Form

PROJECT NAME: ARCO STATION 0374

6407 Telegraph Ave, Oakland, CA

Sampling Project #: 21775-261.003

Reporting Project#: ?

OWT Project#: 71028

DATE REQUESTED: 12-May-98

ND = None Detected

Project Manager: Glen Vanderveen

Groundwater Monitoring Instructions	Treatment System Instructions
Quarterly Monitoring - Third Month of the Quarter	
Perform a water level survey prior to sampling (see ARCO SOP))
Well survey points are top of well casings:	
Purge three (3) casing volumes.	
You will have to bring a trailer for purge water transport.	
Wells MW-5 and MW-6 are in the street.	
Sample each well with a Teflon bailer.	
Sample ID's on the C-O-C and the sample bottles must include	
the depth at which the sample was collected [i.e. MW-1 (30)]	Lisle Rath Pager # (408) 798-2928

Site Contact: Mr. S. Sud Site Phone: (510) 658-7508 Well Locks: ?

Well ID or Source	Casing Diameter	Casing Length	Top Of Screen	Analyses Requested
	(inches)	(feet)	(feet)	
MW-1	4.0	26.8		Depth to Water Depth to Floating Product
MW-6	4.0	14.7		Floating Product Thickness Total Depth
MW-5	4.0	23.0		Well Integrity
MW-2	4.0	26.3		
MW-3	4.0	26.8		
MW-4	4.0	26.6		If depth to water is below the top of the screen
Above wel	ls in indicate	ed order		take a grab sample. If the water level is above the top of the screen purge as normal.
MW-5		(See Abov	e)	Add: Dissolved Oxygen (Field Measurement) TPHG/ BTEX/ MTBE by (EPA 8020) (Fill 2- 40ml HCL VOAs)
Provide low	Instruction yest detection the EMCON	limits poss		er () on the CAR.

IP = Intermitent Product

FIELD REPORT DEPTH TO WATER/FLOATING PRODUCT SURVEY

PROJECT #: 21775-261.003 STATION ADDRESS: 6407 Telegraph Ave, Oakland, CA DATE: 5/12/98

ARCO STATION # : 374 FIELD TECHNICIAN : Mike Ross DAY : Tuesday

		Well	Well			Туре	FIRST	SECOND	DEPTH TO	FLOATING	WELL	
DTW	WELL	Box	Lid	Gasket	Lock	Of Well	DEPTH TO	DEPTH TO	FLOATING	PRODUCT	TOTAL	
Order	ID	Seal	Secure	Present	Number	Cap	WATER	WATER	PRODUCT	THICKNESS	DEPTH	COMMENTS
							(feet)	(feet)	(feet)	(feet)	(feet)	
1	MW-1	OK	Hex	NO	ARCO	LWC	5.28	5,28	NR	NR-	Her8	Missons 2 Bdos
2	MW-6	OK	15/16"	15	ARCO	LWC	4.42	4.42	N	MZ	14.7	
3		OK	15/6	89	ARCO	LWC	7.24	7.24	NR		<u> </u>	BOCT STRING
4	MW-2	ok	Hex	No	ARCO	LWC	6.93	6.13	NR	m	26.3	Missing But
5	MW-3	OK	Hex				5.53	5.53	NR	m	26.8	
6	MW-4	6K	Hex		ARCO	[]	6.38	6.38	M	m	27.0	
									<u> </u>			
		-										
		 		 								
		 	 			 						
 		 	 	<u> </u>					 			
		 	 	 	 	 		 		 	 	
	······································	<u> </u>	<u> </u>			1	V DOINTS	1		1.0000	<u> </u>	

SURVEY POINTS ARE TOP OF WELL CASINGS

WATER SAMPLE FIELD DATA SHEET Rev 1/97
PROJECT NO 21775 - 261,003 PURGED BY M. 2055 CLIENT NAME ARCS 0374
OWT SAMPLED BY M. Poss LOCATION Oakland, Ca.: TYPE Groundwater Surface Water Leachate Other
CASING DIAMETER (inches) 2 3 4 45 6 Other
CASING ELEVATION (feet/MSL) DEPTH OF WELL (feet) DEPTH OF WATER (feet) DEPTH OF WATER (feet) NA VOLUME IN CASING (gal.) CALCULATED PURGE (gal.) ACTUAL PURGE VOL. (gal.) 25.0
DATE PURGED 5/12/97 END PURGE 12/9 DATE SAMPLED 5/12/99 SAMPLING TIME 1300
TIME VOLUME PH E.C. TEMPERATURE COLOR TURBIDITY (visual) (visual) (visual)
(2400 HR) (gal) (units) (units
OTHER D.D. D.D. MG/L ODOR MOVE NR NA (COBALT 0-100) (NTU 0-200) FIELD QC SAMPLES COLLECTED AT THIS WELL (i.e. FB-1, XDUP-1)
PURGING EQUIPMENT
2" Bladder Pump Bailer (Teflon) Centrifugal Pump Bailer (PVC) Submersible Pump Bailer (Stainless Steel) Well Wizard ¹ Dedicated Other Dipper Submersible Pump Well Wizard ¹ Dedicated Other
WELL INTEGRITY: OK LOCK. ARLS
PH E.C. Temp. Meter Calibration Date 5/12/48 Time 1243 Meter Senal No 600/12
EC 1000 97/1 1000 pH7 736 1700 pH 10 992 1 1000 pH4 1 900
SIGNATURE TO REVIEWED BY THE PAGE OF

. .

r

٠

ARCO Facility no 0374 City CCK ION ARCO anglinee POU SUDDIC Tele Consultant name POU SUDDIC ARCONING Mattix			}	A Aire			BESK CIGGI IN	100000000000000000000000000000000000000	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			, , , , ,	***	1. 600			がある。	11 多次是代表
naultant name	027	7	200	グ書	KICIK	P		Projectinate (Consultant)		enl	an	161	2	3				
naultant name	Pal	150	pote	'nn'le	Tole	phone no		Out output (100)		1452-77 (LiConsultant) (458) 437-957	720	Cons.	ultant)	S S S	342	292		South Co.
	FK	3	1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		(-3)	¥ გე	Address Consultant		V	Mai	Mil	Wain	び	B	K	15765 V	18	
		2	Mattrix	Par A	Preservation					30	1361 - 1364 1361 - 1364	100	DWOV DWOV		D) SN/JÓ	V.		W
Sample I.O.	n Tenlatrico	3	Weger	3 2 0	Adid	eleb grügme?	ente graphic		Dieseld Class) season brack	ESY 418 1/2M PO	ELV CETUS 10	EPA 626/8270	OAOV Delsein CAOV Delsein A93 elsein MAO	Dehamo pont. Dehamo pont.	LONG EDA 742			
13			X	X	DH	5/10/6	13.00				(6) (6) (6)							
		では、	To see		· 新文章	タ、 () () ()		0			以野							
		, 3, 7° 100, 7° 100, 7°										X119 31			,à.,	10 (5) (5) (6) (6) (6) (6) (6) (6) (6) (6) (6) (6		
					J É ,									逐變				116
		<u>广</u> ,		かな		i -					\$0, 0				127	\$ \$ \$ \$ \$		
	23 - 12 - 12 - 12 - 12 - 12 - 12 - 12 -					4 (2 3 (2 4 (2 4 (2)					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	で変数			3 11		
		1				W.					<u>.</u> .	462; 13.1						
		47. 8			4 X X X X X X X X X X X X X X X X X X X	(X) (A) (A) (A)						3 198 17 E				- 10 m (12 m (12 m		
		1.00			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	seljá ja												
	藏																	
でいるから		のでは、										模型人						
		ないので			が悪くている													
					を表える。				.									
	Ŋ.																	
		-7,3																
						i de Gile												
	1 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4																	
						ではなった。												
Condition of sample:	8																	
Relinguished by sempler	sampler	N			Med I													
Relinguished by					Date		(Interest											
Relinguished by					Date		TIME			<i>W</i>		Date	100		(James	(100)		

APPENDIX D REMEDIAL SYSTEM PERFORMANCE SUMMARY

APPENDIX D

REMEDIAL SYSTEM PERFORMANCE SUMMARY

GWE System

Groundwater extraction (GWE) was conducted between December 21, 1993, and October 13, 1995. No evidence of additional plume migration has been observed since system deactivation. The GWE system was comprised of a pneumatic pump in Well W-2 and three 200-pound granular activated carbon vessels arranged in series to treat the extracted groundwater. Extracted and treated groundwater was discharged into the East Bay Municipal Utility District (EBMUD) Permit Account Number 502-85611. Based on verbal approval from the ACHCSA, indicating that GWE would no longer be required at the site, the EBMUD permit was relinquished on June 14, 1996. Overall, approximately 0.1 million gallons of groundwater were extracted and less than 0.05 gallon of benzene was removed.

Please refer to the Second Quarter 1997 Groundwater Monitoring Report, for historical GWE system performance and analytical data.

Intrinsic Bioremediation Evaluation

Intrinsic bioremediation indicator parameters (bioparameters) were monitored during the third quarter 1996 groundwater monitoring event. Groundwater samples from Wells MW-3, MW-4, and MW-5 were analyzed for total alkalinity, dissolved oxygen (DO), ferrous iron, nitrate, sulfate, methane, biological oxygen demand (BOD), chemical oxygen demand (COD), and carbon dioxide (CO₂). Intrinsic bioremediation evaluation data are presented in Table D-1.

It is generally accepted that depleted concentrations of electron acceptors (DO, nitrate, and sulfate), and elevated concentrations of bioremediation byproducts (CO₂, methane, and ferrous iron) within the hydrocarbon-impacted plume compared to background levels indicate that intrinsic bioremediation is occurring. Collected data follow a trend that indicates the occurrence of intrinsic bioremediation.

Bioremediation Enhancement Program

On November 14, 1995, at the request of ARCO, twelve oxygen releasing compound (ORC) socks manufactured by Regenesis Bioremediation Products, Inc. were installed below the groundwater surface in Well MW-3. ORC is a formulation of very fine, insoluble magnesium peroxide that releases oxygen at a slow, controlled rate when hydrated. ORC product literature was presented in PEG's fourth quarter 1995 report.

Data collected from Well MW-3 indicate that concentrations of TPPH-g and benzene have declined since ORC units were installed. ORC units are changed when dissolved oxygen data indicate that they have been depleted.

Conclusions

As indicated above, GWE at the site has been terminated with verbal approval from ACHCSA. Bioremediation enhancement program will continue during third quarter 1998.

Attachments: Table D-1 - Intrinsic Bioremediation Evaluation Data

Table D-1 Intrinsic Bioremediation Evaluation and Enhancement Data

ARCO Service Station 0374 6407 Telegraph Avenue at Alcatraz Avenue Oakland, California

			Fie	eld Analyses						<u>L</u>	aboratory A					
	Date	Groundwater Temperature	ρH	Conductivity	D.O.	Ferrous Iron	Total Alkalinity	B.O.D.	Carbon Dioxide	C.O.D.	Methane	Nitrate as Nitrate	Nitrite as Nitrite	Sulfate	TPH as Gasoline	Total BTEX
Welt	Sampled	(deg F)	(units)	(µmhos)	(mg/L)_	(mg/L)	(mg CaCO3/L	(mg/L)	(mg/L)	(mg/L)	(%)	(mg/L)	(mg/L)	(mg/L)	(µg/L)	(µg/L
	11/14/95 **	65.5*	6.76*	508*	7.17	N/A	NS	NS	NS	NS	NS	6.6	<1.0	NS	140	46
	06/06/96 **	66.2	7.38	700	12.28	N/A	NS	NS	NS	NS	NS	NS	NS	NS	84†	5.4†
	07/16/96	67.8	7.08	1,010	8.73	0.0	280	1.8	270	44	<0.020	<1.0	NS	78	<50	2.2
	01/21/97 ***	59	N/A	N/A	11.15	0.5	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	08/12/97 **	74.4	6.65	600	6.7	1.6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NA	N/A	N/A
	00,120,	N/A	N/A	N/A	12.0	0.2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	11/17/97	68.5	7.75	806	4.0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	ND	ND
	03/16/98	NM	NM	NM	NM	NM	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	05/12/98	i inni	14141	1 ****			1									
		69.5	6.72	1,370	3.20	4.20	420	NS	470	NS	0.11	<1.0	NS	18	5,600	2,02
!W-4	07/16/96	1	6.89	1,411	1.50	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	ND	NE
	03/16/98	66.2	NM	NM	NM	NM	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	05/12/98	NM	1,41562	Mark	, 401,											
		70.4	6.85	690	6.80	0.0	170	NS	180	NS	<0.020	<1.0	NS	35	<50	1.1
MW-5	07/16/96	70.4	7.19	584	1.5	N/A	N/A	NA	N/A	N/A	N/A	N/A	N/A	N/A	ND	NC
	03/16/98	69.5	7.19	619	2.2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	ND	NE
	05/12/98	65.9	7.04	015		. 4.	}									
		N/A	N/A	N/A	3.47	N/A	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
MW-6	06/06/96	N/A N/A	N/A	N/A	N/A	N/A	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	03/16/98	NM	NM	NM	NM	NM	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	05/12/98	izitai	14141	, , , , ,	,									 		
D.O.	= Dissolved	oxygen					μg/L		grams per l	iter						
B.O.D	= Biochemic	al oxygen dema	nd				NM	•	easured							
C.O.D	= Chemical	oxygen demand					NS	= Not s								
TPPH		eable petroleum	hydrocarl	ons			ND	= Not d								
BTEX		toluene, ethylbe					N/A		vailable		d Blace	har 2 100	=			
deg F	= Degrees F						*				d on Novem	Der 2, 199	٥,			
multos	_						**		stailed follo							
mg/L	= Milligrams						†	From A	vpril 10, 199	6 groundw	ater monitor	ıng event.				