

Broadbent & Associates, Inc.
1324 Mangrove Ave., Suite 212
Chico, CA 95926
Voice (530) 566-1400
Fax (530) 566-1401

RECEIVED

3:59 pm, Jan 30, 2009

Alameda County
Environmental Health

BROADBENT & ASSOCIATES, INC
ENVIRONMENTAL, WATER RESOURCES & ENGINEERING

January 28, 2009

Project No. 06-82-608

Atlantic Richfield Company
P.O. Box 1257
San Ramon, CA 94583
Submitted via ENFOS

Attn.: Mr. Paul Supple

Re: Fourth Quarter, 2008 Status Report, Atlantic Richfield Company (a BP affiliated company) Station #771, 899 Rincon Avenue, Livermore, California. ACEH Case No. RO0000200.

Dear Mr. Supple:

Attached is the *Fourth Quarter, 2008 Status Report* for Atlantic Richfield Company Station #771 (herein referred to as Station #771) located at 899 Rincon Avenue, Livermore, California (Property).

Should you have questions please do not hesitate to contact us at (530) 566-1400.

Sincerely,


BROADBENT & ASSOCIATES, INC.



Matthew G. Herrick, P.G., C.HG.
Senior Hydrogeologist



Robert H. Miller, P.G., C.HG.
Principal Hydrogeologist



Enclosures

cc: Mr. Paresh Khatri, Alameda County Environmental Health, 1131 Harbor Bay Parkway, Suite 250, Alameda, CA, 94502 (Submitted via ACEH ftp Site)
Mr. Paul M. Smith, Livermore-Pleasanton Fire Department, 3560 Nevada St., Pleasanton, CA 94566
Mr. Chuck Headlee, RWQCB, 1515 Clay St. Suite 1400, Oakland, CA 94612 (Submitted via GeoTracker)
GeoTracker

STATION #771 QUARTERLY STATUS REPORT

Facility: #771	Address:	899 Rincon Avenue, Livermore, California
Station #771 Environmental Business Manager:		Mr. Paul Supple
Consulting Co./Contact Persons:		Broadbent & Associates, Inc. (BAI) / Rob Miller & Matt Herrick
Primary Agency/Regulatory ID No.:		Alameda County Environmental Health (ACEH) / ACEH Case No. RO0000200
Consultant Project No.:		06-82-608
Facility Permits/Permitting Agency.:		NA

WORK PERFORMED THIS QUARTER (Fourth Quarter, 2008):

1. Submitted Third Quarter, 2008 Semi-Annual Ground-Water Monitoring Report. Report completed by BAI.
2. In accordance with the ACEH December 12, 2008 letter, submitted the December 31, 2008 email regarding additional reports not currently available on the ACEH's website. The email stated that no additional reports were located that are currently not provided on the ACEH's website. Email completed by BAI.
3. No ground-water monitoring/sampling work activities were completed on the Property during the Fourth Quarter, 2008.

WORK PROPOSED FOR NEXT QUARTER (First Quarter, 2009):

1. Submit Fourth Quarter, 2008 Status Report (contained herein).
2. Conduct ground-water monitoring/sampling for First Quarter, 2009.
3. In accordance with the ACEH December 12, 2008 letter, complete a site conceptual model and if appropriate a soil and water investigation work plan.

QUARTERLY RESULTS SUMMARY:


Current phase of project:	Ground-water monitoring/sampling
Frequency of ground-water sampling:	MW-4, MW-7, RW-1 = Semi-Annual (1Q and 3Q) MW-2, MW-5, MW-6, MW-11, VW-1, = Annual (3Q)
Frequency of ground-water monitoring:	Semi-annual (1Q and 3Q)
Is free product (FP) present on-site:	No
FP recovered this quarter:	NA (FP last recovered in 1992)
Cumulative FP recovered:	3.06 gallons, Wells MW-1, MW-2, and MW-5
Current remediation techniques:	Air diffusion
Depth to ground water (below TOC):	NA
General ground-water flow direction:	NA
Approximate hydraulic gradient:	NA

DISCUSSION:

No ground-water monitoring/sampling activities took place at Station #771 during the Fourth Quarter, 2008. The attached Drawing 1 depicts the site and monitor well locations. The most recent quarterly data can be referenced in the Third Quarter, 2008 Semi-Annual Ground-Water Monitoring Report.


ATTACHMENTS:

Drawing 1. Site Map, Station #771, Livermore, CA



LEGEND

- Monitoring well location
- Vapor extraction well location
- Well** — Well designation
- A,SA — Sampling frequency
- A(3) — Sampled annually during 3rd quarter
- SA(1,3) — Sampled semi-annually during 1st & 3rd quarters
- NS — Not sampled
- - - Remediation piping



NOTE: SITE MAP ADAPTED FROM URS FIGURES.
SITE DIMENSIONS AND FACILITY LOCATIONS NOT VERIFIED.