97 MAR 21 PM 2: 11

March 20, 1997

76 Products Company 2000 Crow Canyon Place, Suite 400 P.O.Box 5155 San Ramon, California 94583

Attention: Mr. Edward C. Ralston

RE: Quarterly Data Report

Unocal Service Station #5781

3535 Pierson Street
Oakland, California

Dear: Mr. Ralston:

In reference to our report (MPDS-UN5781-04), enclosed please find a revised report (MPDS-UN5781-04R) dated March 18, 1997 for the above referenced site. Please discard our previous report dated March 4, 1997. This revision corrects the TPH as diesel concentration detected in monitoring well MWA, in Table 2 and Figure 2.

Should you have any questions, please do not hesitate to contact me at (510) 602-5120.

Sincerely,

MPDS Services, Inc.

Haig (Gary) Tejirian Senior Staff Geologist

Enclosure

cc: Mr. Thomas J. Berkins, Kaprealian Engineering, Inc.

Ms. Susan Hugo, Alameda County Health Care Services Agency



MPDS-UN5781-04R March 18, 1997

76 Products Company 2000 Crow Canyon Place, Suite 400 P.O. Box 5155 San Ramon, California 94583

Attention: Mr. Edward C. Ralston

RE: Annual Data Report

Unocal Service Station #5781

3535 Pierson Street
Oakland, California

Dear Mr. Ralston:

This data report presents the results of the most recent monitoring and sampling of the monitoring well at the referenced site by MPDS Services, Inc.

RECENT FIELD ACTIVITIES

Monitoring well MWA was monitored and sampled once during this annual period as indicated in Table 1. Prior to sampling, the well was checked for depth to water and the presence of free product or sheen. The monitoring data and the ground water elevations are summarized in Table 1. The monitoring well location and ground water elevation is shown on the attached Figure 1.

A ground water sample was collected on February 5, 1997. Prior to sampling, the well was purged of 16.5 gallons of water. A sample was then collected using a clean Teflon bailer. The sample was decanted into clean VOA vials and/or one-liter amber bottles, as appropriate, which were then sealed with Teflon-lined screw caps, labeled, and stored in a cooler, on ice, until delivery to a state-certified laboratory. MPDS Services, Inc. transported the purged ground water to the Unocal Refinery located in Rodeo, California, for treatment and discharge to San Pablo Bay under NPDES permit.

ANALYTICAL RESULTS

The ground water sample was analyzed at Sequoia Analytical Laboratory and was accompanied by properly executed Chain of Custody documentation. The analytical results of the ground water samples collected to date are summarized in Table 2. The concentrations of Total Petroleum Hydrocarbons (TPH) as gasoline, TPH as diesel, and benzene detected in the ground water sample collected during this monitoring and sampling event are shown on the attached Figure 2. Copies of the laboratory analytical results and the Chain of Custody documentation are attached to this report.

MPDS-UN5781-04R March 18, 1997 Page 2

LIMITATIONS

Environmental changes, either naturally-occurring or artificially-induced, may cause changes in ground water levels and flow paths, thereby changing the extent and concentration of any contaminants.

DISTRIBUTION

A copy of this report should be sent to Ms. Susan Hugo of the Alameda County Health Care Services Agency.

If you have any questions regarding this report, please do not hesitate to call Mr. Joel G. Greger at (510) 602-5120.

JOEL G. GREGER No. EG 1633 CERTIFIED ENGINEERING

Sincerely,

MPDS Services, Inc.

Haig (Gary) Tejirian Senior Staff Geologist

Joel G. Greger, C.E.G. Senior Engineering Geologist

License No. EG 1633 Exp. Date 8/31/96

Attachments: Tables 1 & 2

Location Map Figures 1 & 2

Laboratory Analyses

Chain of Custody documentation

cc: Mr. Thomas Berkins, Kaprealian Engineering, Inc.

Table 1
Summary of Monitoring Data

| Well# | Ground Water Elevation (feet) | Depth to Water (feet) * | Total Well Depth (feet) * | Product Thickness (feet) | Sheen | Water Purged (gallons) |
|-------|-------------------------------------|-------------------------------|---------------------------------|--------------------------------|-------|------------------------------|
| | (1) | Monitored and | Sampled on Feb | ruary 5, 1997) | | |
| MWA | 138.79 | 13.01 | 45.02 | 0 | No | 16.5 |
| | (T | Monitored and | Sampled on Feb | ruary 6, 1996) | | |
| MWA | 139.28 | 12.52 | 37.60 | 0 | No | 23 |
| | Q | Monitored and | l Sampled on Feb | oruary 9, 1995) | | |
| MWA | 136.12 | 15.68 | 45.10 | 0 | No | 21 |
| | (I | Aonitored and | Sampled on Feb | ruary 10, 1994) | | |
| MWA | 136.55 | 15.25 | 44.93 | 0 | No | 21 |
| | | | | | | |

| | | Well Casino |
|---|-------|-----------------|
| | | 17 C11 C4134136 |
| | | Elevation |
| W | oll # | (feet)* |

MWA 151.80

- ♦ The depth to water level and total well depth measurement was taken from the top of the well casing.
- * Relative to MSL.

Note: Monitoring data prior to February 10, 1994 were provided by Kaprealian Engineering, Inc.

Table 2
Summary of Laboratory Analyses
Water

| Well# | Date | TPH as Diesel | TPH as Gasoline | Benzene | Toluene | Ethyl- Benzene | Xylenes | мтве |
|-------|-----------|------------------|--------------------|---------|---------|-------------------|---------|------|
| | | = 2 | | NT. | NIF | NITS | ND | |
| MWA | 12/18/90* | 7 3 | ND | ND | ND | ND | | |
| | 5/3/91* | ND | ND | ND | ND | ND | ND | |
| | 8/7/91* | ND | ND | ND | ND | ND | ND | |
| | 11/8/91* | ND | ND | ND | ND | ND | ND | |
| | 2/6/92* | ND | ND | ND | ND | ND | ND | |
| | 8/4/92* | ND | ND | ND | ND | ND | 0.51 | |
| | 2/10/93* | ND | ND | ND | ND | ND | ND | |
| | 2/10/94* | ND | ND | ND | 0.52 | ND | 0.92 | |
| | 2/9/95* | ND | ND | ND | ND | ND | ND | |
| | 2/6/96** | 120† | ND | ND | ND | ND | 2.1 | |
| | 2/5/97* | 61†† | ND | ND | ND | ND | ND | ND |

- * TOG and all EPA method 8010 compounds were non-detectable.
- ** TOG and all EPA method 8010 compounds were non-detectable except for tetrachloroethene, which was detected at a concentration of 1.8 μg/L.
- † Sequoia Analytical Laboratory reported that the hydrocarbons detected did not appear to be diesel.
- †† Sequoia Analytical Laboratory reported that the hydrocarbons detected appeared to be a diesel and non-diesel mixture.

MTBE = Methyl tert butyl ether.

ND = Non-detectable.

-- Indicates analysis was not performed.

Results are in micrograms per liter (µg/L), unless otherwise indicated.


Note: TOG and all EPA method 8010 compounds were non-detectable, except as noted above.

The detection limit for results reported as ND by Sequoia Analytical Laboratory is equal to the stated detection limit times the dilution factor indicated on the laboratory analytical sheets.

Prior to August 1, 1995, the total purgeable petroleum hydrocarbon (TPH as gasoline) quantification range used by Sequoia Analytical Laboratory was C4 - C12. Since August 1, 1995, the quantificiation range used by Sequoia Analytical Laboratory is C6 - C12.

Laboratory analyses data prior to February 10, 1994 were provided by Kaprealian Engineering, Inc.






Base modified from 7.5 minute U.S.G.S. Oakland East Quadrangle (photorevised 1980)






UNOCAL SERVICE STATION #5781 3535 PIERSON STREET OAKLAND, CALIFORNIA LOCATION MAP






UNOCAL SERVICE STATION #5781 3535 PIERSON STREET OAKLAND, CALIFORNIA FIGURE

1



LEGEND

- → Monitoring well
- () Concentration of TPH as gasoline in $\mu\text{g/}L$
- [] Concentration of benzene in μ g/L
- < > Concentration of TPH as diesel in µg/L
- ND Non-detectable



PETROLEUM HYDROCARBON CONCENTRATIONS IN GROUND WATER ON FEBRUARY 5, 1997



UNOCAL SERVICE STATION #5781 3535 PIERSON STREET OAKLAND, CALIFORNIA

FIGURE

2



Redwood City, CA 94063 Walnut Creek, CA 94598 Sacramento, CA 95834 (415) 364-9600 (510) 988-9600 (916) 921-9600

FAX (415) 364-9233 FAX (510) 988-9673 FAX (916) 921-0100

MPDS Services

2401 Stanwell Dr., Ste. 300 Concord, CA 94520 Attention: Jarrel Crider

Client Project ID: Matrix Descript:

Unocal #5781, 3535 Pierson St., Oakland Water

EPA 5030/8015 Mod./8020

Analysis Method: EPA 5030 First Sample #: 702-0387 Sampled: Feb 5, 1997 Received: Feb 5, 1997

Reported: Feb 19, 1997

TOTAL PURGEABLE PETROLEUM HYDROCARBONS with BTEX DISTINCTION

| Sample Number | Sample Description | Purgeable Hydrocarbons μg/L | Benzene μg/L | Toluene μg/L | Ethyl Benzene μg/L | Total Xylenes μg/L | MTBE μg/L |
|------------------|-----------------------|-----------------------------------|------------------------|------------------------|--------------------------|--------------------------|---------------------|
| 702-0387 | MW-A | ND | ND | ND | ND | ND | ND |

Detection Limits: 50 0.50 0.50 0.50 0.50 5.0

Total Purgeable Petroleum Hydrocarbons are quantitated against a fresh gasoline standard. Analytes reported as ND were not present above the stated limit of detection.


SEQUOIA ANALYTICAL, #1271

Signature on File

Alan B. Kemp Project Manager

Page 1 of 2





Redwood City, CA 94063 Walnut Creek, CA 94598 Sacramento, CA 95834

(415) 364-9600 (510) 988-9600 (916) 921-9600

FAX (415) 364-9233 FAX (510) 988-9673 FAX (916) 921-0100

MPDS Services

2401 Stanwell Dr., Ste. 300 Concord, CA 94520

Client Project ID: Matrix Descript:

); Unocal #5781, 3535 Pierson St., Oakland Sampled: Water

Feb 5, 1997 Feb 5, 1997

Attention: Jarrel Crider

Analysis Method: First Sample #:

EPA 5030/8015 Mod./8020 702-0387

Received: Reported:

Feb 19, 1997

TOTAL PURGEABLE PETROLEUM HYDROCARBONS with BTEX DISTINCTION

| Sample | Sample | Chromatogram | DL Mult. | Date | Instrumen | nt Surrogate |
|----------|-------------|--------------|----------|----------|-----------|-------------------------------------|
| Number | Description | Pattern | Factor | Analyzed | ΙĐ | Recovery, % QC Limits: 70-130 |
| 702-0387 | MW-A | | 1.0 | 2/12/97 | HP-2 | 81 |

SEQUOIA ANALYTICAL, #1271

Signature on File

Alan B. Kemp Project Manager

Page 2 of 2



Redwood City, CA 94063 Walnut Creek, CA 94598 Sacramento, CA 95834

(415) 364-9600 (510) 988-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 988-9673 FAX (916) 921-0100

MPDS Services

2401 Stanwell Dr., Ste. 300 Concord, CA 94520 Attention: Jarrel Crider

Client Project ID:

Unocal #5781, 3535 Pierson St., Oakland

Water

Sample Matrix: Analysis Method: EPA 3510/8015 Mod.

First Sample #: 702-0387 Sampled:

Feb 5, 1997

Feb 5, 1997 Received: Reported: Feb 19, 1997

TOTAL EXTRACTABLE PETROLEUM HYDROCARBONS

| Analyte | Reporting Limit μg/L | Sample I.D. 702-0387 MW-A^ | |
|-----------------------------|----------------------------|--|--|
| Extractable Hydrocarbons | 50 | 61 | |

Chromatogram Pattern:

Diesel & Unidentified Hydrocarbons >C20

Quality Control Data

Report Limit Multiplication Factor:

1.0

Date Extracted:

2/11/97

Date Analyzed:

2/13/97

Instrument Identification:

HP-3A

Extractable Hydrocarbons are quantitated against a fresh diesel standard. Analytes reported as N.D. were not detected above the stated reporting limit.


SEQUOIA ANALYTICAL, #1271

Please Note:

Signature on File

Alan B. Kemp Project Manager This sample appears to contain diesel and non-diesel mixtures. "Unidentified Hydrocarbons

> C20" refers to unidentified peaks in the total oil and grease range.



Redwood City, CA 94063 Walnut Creek, CA 94598 Sacramento, CA 95834 (415) 364-9600 (510) 988-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 988-9673 FAX (916) 921-0100

MPDS Services 2401 Stanwell Dr., Ste. 300 Concord, CA 94520 Attention: Jarrel Crider Client Project ID: Matrix Descript:

Unocal #5781, 3535 Pierson St., Oakland Water

Analysis Method: SM 5520 B&F (Gravimetric) First Sample #: 702-0387

ıu

Sampled: Feb 5, 1997 Received: Feb 5, 1997

Extracted: Feb 13, 1997 Analyzed: Feb 14, 1997 Reported: Feb 18, 1997

TOTAL RECOVERABLE PETROLEUM OIL

| Sample Number | Sample Description | Oil & Grease mg/L (ppm) | Detection Limit Multiplication Factor |
|------------------|-----------------------|-------------------------------|--|
| 702-0387 | MW-A | N.D. | 1.1 |

Detection Limits:

5.0

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL, #1271

Signature on File

Alan B. Kemp Project Manager



Redwood City, CA 94063 Walnut Creek, CA 94598 Sacramento, CA 95834

(415) 364-9600 (510) 988-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 988-9673 FAX (916) 921-0100

MPDS Services 2401 Stanwell Dr., Ste. 300 Concord, CA 94520 Attention: Jarrel Crider

Client Project ID: Sample Descript: Analysis Method: Lab Number:

Water, MW-A EPA 5030/8010 702-0387

ject ID: Unocal #5781, 3535 Pierson St., Oakland Sampled: Feb 5, 1997 Feb 5, 1997 Received: Feb 14, 1997 Analyzed: Feb 19, 1997 Reported:

HALOGENATED VOLATILE ORGANICS (EPA 8010)

| Analyte | Detection Limit µg/L | | Sample Results µg/L |
|---------------------------|-------------------------|---|------------------------|
| Bromodichloromethane | 0.50 | *************************************** | N.D. |
| Bromoform | 0.50 | | N.D. |
| Bromomethane | 1.0 | | N.D. |
| Carbon tetrachloride | 0.50 | | N.D. |
| Chlorobenzene | 0.50 | | N.D. |
| Chloroethane | 1.0 | | N.D. |
| 2-Chloroethylvinyl ether | 1.0 | | N.D. |
| Chloroform | 0.50 | | N.D. |
| Chloromethane | 1.0 | | N.D. |
| Dibromochloromethane | 0.50 | | N.D. |
| 1,3-Dichlorobenzene | 0.50 | | N.D. |
| 1,4-Dichlorobenzene | 0.50 | , | N.D. |
| 1,2-Dichlorobenzene | 0.50 | | N.D. |
| 1,1-Dichloroethane | 0.50 | | N,D. |
| 1,2-Dichloroethane | 0.50 | *************************************** | N.D. |
| 1,1-Dichloroethene | 0.50 | | N.D. |
| cis-1,2-Dichloroethene | 0.50 | *************************************** | N.D. |
| trans-1,2-Dichloroethene | 0.50 | 4************************************** | N.D. |
| 1,2-Dichloropropane | 0.50 | | N.D. |
| cis-1,3-Dichloropropene | 0.50 | | N.D. |
| trans-1,3-Dichloropropene | 0.50 | | N.D. |
| Methylene chloride | 5.0 | | N.D. |
| 1,1,2,2-Tetrachloroethane | 0.50 | | N.D. |
| Tetrachloroethene | 0.50 | | N.D. |
| 1,1,1-Trichloroethane | 0.50 | | N.D. |
| 1,1,2-Trichloroethane | 0.50 | | N.D. |
| Trichloroethene | 0.50 | , | N.D. |
| Trichlorofluoromethane | 0.50 | | N.D. |
| Vinyl chloride | 1.0 | | N.D. |

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL, #1271

Signature on File

Alan B. Kemp Project Manager





Redwood City, CA 94063 Walnut Creek, CA 94598 Sacramento, CA 95834 (415) 364-9600 (510) 988-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 988-9673 FAX (916) 921-0100

MPDS Services

2401 Stanwell Dr., Ste. 300 Concord, CA 94520 Attention: Jarrel Crider Client Project ID:

Unocal #5781, 3535 Pierson St., Oakland

Matrix: Liquid

QC Sample Group: 702-0387

Reported:

Feb 20, 1997

30330 HARAGO

QUALITY CONTROL DATA REPORT

| ANALYTE | Benzene | Toluene | Ethyl | Xylenes | Diesel | Oil & |
|-------------------|------------|-----------------|-------------|------------|-----------|--------------------|
| ANALTIE | Berizerie | roidene | Benzene | Aytonoo | 2,111 | Grease |
| | | | Delizerie | | | <u>.</u> |
| Method: | EPA 8020 | EPA 8020 | EPA 8020 | EPA 8020 | EPA 8015 | SM 5520BF |
| Analyst: | K. Nill | K, Nill | K. Nill | K. Nill | D. Sharma | I. Dalvand |
| , <u>, ,</u> | | | | | - | |
| MS/MSD | | | | | | |
| Batch#: | 7020387 | 7020387 | 7020387 | 7020387 | BLK021197 | BLK021397 |
| | | | | | | |
| Date Prepared: | 2/11/97 | 2/11/97 | 2/11/97 | 2/11/97 | 2/11/97 | 2/13/97 |
| Date Analyzed: | 2/11/97 | 2/11/97 | 2/11/97 | 2/11/97 | 2/13/97 | 2/14/97 |
| Instrument I.D.#: | HP-2 | HP-2 | HP-2 | HP-2 | HP-3B | Manual |
| Conc. Spiked: | 20 μg/L | 20 μg/L | 20 μg/L | 60 μg/L | 300 μg/L | 100 mg/L |
| Matrix Oakla | | | | | | |
| Matrix Spike | 00 | 95 | 90 | 88 | 107 | 93 |
| % Recovery: | 80 | 95 | 30 | 80 | 107 | |
| Matrix Spike | | | | | | |
| Duplicate % | | | | | | |
| Recovery: | 80 | 95 | 85 | 83 | 100 | 97 |
| 1,000,000,000 | | | | | | |
| Relative % | | | | | | |
| Difference: | 0.0 | 0.0 | 5.7 | 5.8 | 6.5 | 4.2 |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| LCS Batch#: | 2LCS021197 | 2LCS021197 | 2LC\$021197 | 2LCS021197 | LCS021197 | LCS021397 |
| | | | | | 0 (44 /07 | 2/42/07 |
| Date Prepared: | 2/11/97 | 2/11/9 7 | 2/11/97 | 2/11/97 | 2/11/97 | 2/13/97 2/14/97 |

| LCS Batch#: | 2LCS021197 | 2LCS021197 | 2LC\$021197 | 2LCS021197 | LCS021197 | LCS021397 | |
|---|----------------------------|----------------------------|----------------------------|----------------------------|-----------------------------|------------------------------|--|
| Date Prepared: Date Analyzed: Instrument I.D.#: | 2/11/97 2/11/97 HP-2 | 2/11/97 2/11/97 HP-2 | 2/11/97 2/11/97 HP-2 | 2/11/97 2/11/97 HP-2 | 2/11/97 2/13/97 HP-3B | 2/13/97 2/14/97 Manual | |
| LCS % Recovery: | 85 | 100 | 90 | 88 | 103 | 96 | |
| % Recovery Control Limits: | 60-140 | 60-140 | 60-140 | 60-140 | 60-140 | 60-140 | |

Please Note:

SEQUOIA ANALYTICAL, #1271

Signature on File

Alan B. Kemp Project Manager The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.





Redwood City, CA 94063 Walnut Creek, CA 94598 Sacramento, CA 95834 (415) 364-9600 (510) 988-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 988-9673 FAX (916) 921-0100

MPDS Services

2401 Stanwell Dr., Ste. 300 Concord, CA 94520 Attention: Jarrel Crider Client Project ID: Unocal #5781, 3535 Pierson St., Oakland

Matrix: Liquid

QC Sample Group: 702-0387 Reported: Feb 19, 1997

QUALITY CONTROL DATA REPORT

| | | | | ······································ |
|-------------------|---------------|------------|-----------|--|
| ANALYTE | 1,1-Dichloro- | Trichloro- | Chloro- | ł |
| | ethene | ethene | benzene | |
| Method: | EPA 8010 | EPA 8010 | EPA 8010 | |
| Analyst: | P. Horton | P. Harton | P. Horton | |
| MS/MSD | | | | |
| Batch#: | 7020387 | 7020387 | 7020387 | |
| Date Prepared: | 2/14/97 | 2/14/97 | 2/14/97 | |
| Date Analyzed: | 2/14/97 | 2/14/97 | 2/14/97 | |
| Instrument Í.D.#: | HP-6 | HP-6 | HP-6 | |
| Conc. Spiked: | 10 μg/L | 10 μg/L | 10 μg/L | |
| Matrix Spike | | | | |
| % Recovery: | 98 | 115 | 95 | |
| Matrix Spike | | | | |
| Duplicate % | | | | |
| Recovery: | 90 | 102 | 89 | |
| Relative % | | | | |
| Difference: | 8.5 | 12 | 6.5 | |
| | | | | |
| | | | | |

| LCS Batch#: | LCS021397 | LCS021397 | LCS021397 |
|--------------------|-----------|-----------|-----------|
| Date Prepared: | 2/13/97 | 2/13/97 | 2/13/97 |
| Date Analyzed: | 2/13/97 | 2/13/97 | 2/13/97 |
| Instrument I.D.#: | HP-6 | HP-6 | HP-6 |
| LCS % Recovery: | 96 | 106 | 93 |

| • | | | | | |
|-----------------|--------|--------|--------|------|--|
| % Recovery | | | | | |
| Control Limits: | 60-140 | 60-140 | 60-140 | | |

SEQUOIA ANALYTICAL, #1271

Signature on File

Alan B. Kemp Project Manager

Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.



M P D S Services, Inc.

2401 Stanwell Drive, Suite 400, Concord, CA 94520 Tel: (510) 602-5120 Fax: (510) 689-1918

STATISTICS CHAIN OF CUSTODY

SAMPLER UNOCAL **ANALYSES REQUESTED** S/S # <u>5781</u> CITY: <u>Oskland</u> JOE ATEMIAN TURN AROUND TIME: ADDRESS: 3535 Piersonst. 706 TPHC BTEX MTBE 8010 Regular WITNESSING AGENCY SAMPLING WATER GRAB COMP REMARKS DATE TIME LOCATION NO. OF CONT. SAMPLE ID NO. 70203874-F MTBE: Spps. 2-5-97 12:00 AVOA MW-A Well p. m 2 Amber THE FOLLOWING MUST BE COMPLETED BY THE LABORATORY ACCEPTING SAMPLES FOR ANALYSES: DATE/TIME RELINQUISHED BY: RECEIVED BY: 1. HAVE ALL SAMPLES RECEIVED FOR ANALYSIS BEEN STORED ON ICE? (SIGNATURE) SIGNATURE) 2. WILL SAMPLES REMAIN REFRIGERATED UNTIL ANALYZED? 2 (5/17 1245 2/5/97 (345 (SIGNATURE) 3. DID ANY SAMPLES RECEIVED FOR ANALYSIS HAVE HEAD SPACE? (SIGNATURE) 4. WERE SAMPLES IN APPROPRIATE CONTAINERS AND PROPERLY PACKAGED? ISIGNATURE SIGNATURE: Group leader