June 17, 2003 Letter 0274.L4

Mr.Amir Gholami Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502

SUBJECT:

REPORT TRANSMITTAL

Fuel Leak Case RO0000319

Former Western Stucco Products Site

5115 East Eighth Street Oakland, California 94601

Dear Mr. Gholami:

Attached you will find one copy of a Subsurface Investigation Report (B1-B6) and Sensitive Receptor Survey for the subject site dated June 16, 2003 by RGA Environmental, Inc. Field activities were performed on March 25 and 26, 2003.

I certify under penalty of perjury that the contents of the attached report are true and correct to the best of my knowledge.

Should you have any questions, please do not hesitate to call me at (510) 325-3606.

Sincerely,

Al Avendang

July 1-05

20319 June 16, 2003 Letter 0274.L3 RGA Job # WEST8698

Alameda County



Mr. Al Avendano 3228 Hyde St. Oakland, CA 94601

Environmental Health

SUBJECT:

REPORT TRANSMITTAL

Former Western Stucco Products Site

5115 East Eighth Street Oakland, California 94601

Dear Mr. Avendano:

Attached you will find one copy of a Subsurface Investigation Report (B1-B6) and Sensitive Receptor Survey for the subject site dated June 16, 2003 by RGA Environmental, Inc. Field activities were performed on March 25 and 26, 2003.

For your convenience, you will also find enclosed a transmittal letter to the Alameda County Department of Environmental Health for the report. The transmittal letter should be on your letterhead. We recommend that you make a copy of the signed transmittal letter for your file.

One copy of the report should be forwarded to Mr. Amir Gholami as follows.

Mr. Amir Gholami Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502

Should you have any questions, please do not hesitate to contact us at (510) 547-7771.

Sincerely,

Karin Schroeter Project Manager

Paul H. King

California Registered Geologist

IN, King

Registration No.: 5901

Expires: 12/31/03

PHK/wrw 0274.L3

QC SUMMARY REPORT FOR SW8260B

Matrix: W

WorkOrder: 0303449

EPA Method: SW8260B	Extraction: SW5030B			}	BatchID:	6430	Spiked Sample ID: N/A						
	Sample	Spiked	MS*	MSD*	MS-MSD*	LCS	LCSD	LCS-LCSD	Acceptance	Criteria (%)			
Compound	µg/L	hg/L	µg/L % Rec.		% RPD	% Rec.	% Rec.	% RPD	Low	High			
Methyl-t-butyl ether (MTBE)	N/A	10	N/A	N/A	N/A	106	107	0.163	. 70	130			
%SS:	N/A	100	N/A	N/A	N/A	97.8	98.2	60.5	70	130			

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or lanalyte content.

% Recovery = 100 * (MS-Sample) / (Amount Spiked); RPD = 100 * (MS - MSD) / (MS + MSD) * 2.

* MS and / or MSD spike recoveries may not be near 100% or the RPDs near 0% if: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) if that specific sample matrix interferes with spike recovery.

McCampbell Analytical Inc.

CHAIN-OF-CUSTODY RECORD

110 Second Avenue South, #D7 Pacheco, CA 94553-5560 (925) 798-1620

WorkOrder: 0303449

Client:

RGA Environmental 4701 Doyle Street, Suite #14 Emeryville, CA 94608-2947

TEL:

PO:

(510) 547-7771

FAX:

(510) 547-1983

ProjectNo:

West 8698; Former Western Stucco

Date Printed:

3/26/03

Date Received:

4/3/03

							1	Requested Tests	- 5			1
Sample ID	ClientSampID	Matrix	Collection Date	Hold	SW8015C	8021B/8015	SW8260B	!			· •	
	B1	Water	3/25/03		В	A	Α				.l	
0303449-001	4 4 4 4	- Water	3/25/03	•	В	A	h	i				
0303449-002	B2 ⁻	1		1	В	A			<u> </u>	! 1	ļ	
0303449-003	_ B3	Water	3/25/03	ļ	.al	'`				†· · · · · ·	1	
0303449-004	B4	Water	3/25/03		В	A						4
0303449-005	B5	Water	3/25/03		В	Α				 		l
0303449-006	В6	Water	3/25/03		В	A					1 .	i

Prepared by: Maria Venegas

Comments:

MTBE by 8260 added on sample B6 on 5d 4/3/03

NOTE: Samples are discarded 60 days after results are reported unless other arrangements are made. Hazardous samples will be returned to client or disposed of at client expense.



ENVIRONMENTAL INC.

4701 DOYLE ST #14

Tri (\$10) \$47-7771

FAX: (510) 547-1983 EMERYVILLE, CA 94608

0303449

CHAIN OF CUSTODY

Project Number: WEST 86 Sampled By: (Printe With elm We	d and Signat	ure):	- Form	N N	Zowai :	No. of Containers:	PH Analysistes	William India		A STA	4.35	A Tank	Preservatives	Remarks
Sample Number	Date	Time	T	ype	Sample Location							ICE	4	nd Jury Im
81	3/25/63		Wa	fer		6	X	Ÿ.				×		
<u> </u>						6	X	X				×	()	
<u> </u>						7	人	<u>*</u>					(1	·
64						7	X	Χ.				×		
85	_					17_	X	X						
B6	+			·		7	メ	Х		$\langle \mathbf{x} \rangle$)_		1,	
			·						The A die for					
				TENP	PRESERVATION YOU	1 000		9 6						
			G H D	OOD CONDI EAD SPACE BCHLORINA	APPROPRIATE CONTAINERS									
Relinquished By (Signature):		Date 3/26/03	Time 10!24	Received By: (Signature):	Total No	Total No. of Samples Total No. of Containers 40 Mc(au				bell Anality				
Relinquished By: (Signature):			3/26/03	Time 1220	Received By: (Signature):	- [.	Laboratory Contact: Laboratory Phone Number Lyde INS 925-798-16							
Relinquished By: (Signature):			Date	Time	Received For Laboratory By: (Signature)	7,057	Sample Analysis Request Sheet Attached () Yes (XNo						rect	

Comments:

IF INTBE detected, please Ellow with 8260 MTBE confirmation.

(VOAs preserved with HCL)