

76 Broadway Sacramento, California 95818

October 26, 2006

Alameda County Environmental Health

2:01 pm, Jul 23, 2008

RECEIVED

Mr. Don Hwang Alameda County Health Agency 1131 Harbor Bay Parkway Alameda, California 94502

Re:

Report Transmittal
Third Quarter 2006
76 Service Station 5484
18950 Lake Chabot Road
Castro Valley, CA

Dear Mr. Hwang:

I declare under penalty of perjury that to the best of my knowledge the information and/or recommendations contained in the attached report is/are true and correct.

If you have any questions or need additional information, please contact

Shelby S. Lathrop (Contractor) ConocoPhillips Risk Management & Remediation 76 Broadway Sacramento, CA 95818 Phone: 916-558-7609

Fax: 916-558-7639

Sincerely,

Thomas Kosel

Risk Management & Remediation

Home H. Koal

Attachment

October 26, 2006

Mr. Donald Hwang Alameda County Environmental Health Services 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

Re: Quarterly Summary Report - Third Quarter 2006 Delta Project No. C105484041

Dear Mr. Hwang:

On behalf of ConocoPhillips (COP), Delta Consultants (Delta) submitting this Quarterly Summary Report – Third Quarter 2006 for the following location:

Service Station

Location

76 Service Station No. 5484

18950 Lake Chabot Road Castro Valley, California

No regulatory correspondence was received or sent since the last summary report was submitted on May 16, 2006. TRC will continue conducting annual monitoring and sampling at the site; the next monitoring and sampling event at the site will occur during the first quarter 2007. During the third quarter 2006, Delta submitted a Sensitive Receptor Survey for the site.

Sincerely,

Delta Consultants

Ben Wright Staff Geologist

Daniel J. Davis, R.G.

Senior Project Manager

Ms. Shelby Lathrop, ConocoPhillips (electronic copy)

DANIEL J.

DAVIS

No. 6435

Attachment A - Historic Groundwater Flow Directions




DELTA

Attachment A
Historic Groundwater Flow Directions

Historic Groundwater Flow Directions ConocoPhillips Site No. 5484

18950 Lake Chabot Road Castro Valley, California



Legend

Concentric circles represent
quarterly montoring events
Fourth Quarter 1990 through First
Quarter 2006
15 data points shown

■ Groundwater Flow Direction