

September 5, 1991

Mr. Charles Carmel ARCO Petroleum Products P.O. Box 5811 San Mateo, California 94402

SUBJECT: LETTER REPORT

LIMITED SOIL PERFORMANCE TEST

ARCO FACILITY NO. 2185 9800 EAST 14TH STREET OAKLAND, CALIFORNIA

Dear Mr. Carmel:

Roux Associates (Roux) performed a Limited Soil Performance Test (LSPT) on June 6, 1991, at ARCO Products Company (ARCO) Facility No. 2185 located at 9800 East 14th Street, Oakland, California (Site, Figure 1).

PURPOSE:

This test was done to determine whether the subsurface conditions at the Site would be amenable to soil venting/vacuum extraction techniques, should the need arise.

METHOD:

The method used to determine if the subsurface is amenable to a soil venting/vacuum extraction process is to apply a vacuum to one well and measure any influence at another well over time and distance. In this limited soil performance test, the distance was fixed by well location. Once vacuum was applied to the extraction well, the amount of vacuum, extraction air flow and influence at the test well was recorded at regular intervals until the extraction vacuum and the extraction air flow maximized. Test vacuum pressures were used to establish a capture radius relative to the extraction vacuum and air flow.

The equipment used for this test included:

- 1) Thompson Vacuum Pump 6 SCFM air flow @ 0 PSIG Vacuum
- 2) Magnahelic Gauge 0 2 inches water
- 3) Magnahelic Gauge 0 10 inches water

Vapor well VW-2 was used as the extraction well and vapor well VW-1 was used to determine influence. The attached Site Plan (Figure 2) shows the locations of these wells. Also attached are soil boring logs and well construction diagrams for vapor wells VW-1 and VW-2.

Data obtained during the test is provided in Table 1.

RESULTS:

Extraction vacuum stabilized at five inches of Mercury after 10 minutes of operation at 210 standard cubic feet per hour of air flow from the subsurface. No vacuum pressure was detected at the test well indicating that, at the extraction vacuum and extraction air flows obtained, sufficient air could not be moved through the subsurface environment to achieve a capture radius of 21 feet. The soils at this Site, as shown in the vapor extraction well logs, consist entirely of silty clay and clayey silt with low permeabilities.

CONCLUSIONS:

The results of this LSPT indicate that, at the screened depth of the vapor wells, the subsurface at this Site is not amenable to soil venting/vacuum extraction remediation techniques.

Roux appreciates the opportunity to do this work. If you have any questions, please call Dr. John Sammons at (415) 370-2275.

Sincerely,

ROUX ASSOCIATES

John Sammons

Senior Engineer

Ceith G. Kennedy, R.G.

Principal

Environmental Manager

California Registered Geologist No. 4903

Attachments:

Table 1.

Limited Soil Performance Test Data

Figure 1.

Location of Site

Figure 2.

Site Plan


Vapor Extraction Well Logs (2)


Table 1. Limited Soil Performance Test Data
ARCO Facility No. 2185
9800 East 14th Street
Oakland, California

Date of test: 6/6/91
Extraction Well No: VW-2
Influence Well No: VW-1
Distance between wells: 21 feet
Duration of test: 60 minutes

Time	Extraction Vacuum inches mercury	Extraction Air Flow S.D.F.H. (1)	Test Vacuum inches water	
				Start
1105	5	210	0	
1115	5	210	0	
1125	5	210	0	
1135	5	210	0	
1145	5	210	0	
1155	5	210	0	
1205	5	210	0	
				Finis

⁽¹⁾ Standard Cubic Feet per Hour





EXPLANATION

SOIL BORING LOCATION AND DESIGNATION •₈₃

 $oldsymbol{\circ}^{VW-1}$ Vapor extraction well location AND DESIGNATION

SOURCE:

MAP MODIFIED FROM BLUEPRINT PROVIDED BY BARGHAUSEN CONSULTING ENGIGNEERS (1986)



SITE PLAN

ARCO FACILITY NO. 2185

PREPARED FOR

THE

ARCO PRODUCTS COMPANY

ROUX	
ROUX ASSOCIATES,	INC
ENDORONNEWIAL CONSIDER	401

Andrew Pro. Pro.	T.R.	DATE:	-	15/91	I FIGURE
COMPILED BY:	1700	100,41,000	_		1
REPARED BY:	R.P.		11111111	SHOWN	10
PROJECT MANAGER	B.T	REVISION		0	1
DOUBLE NO		102W01			

ROUX

Ргоје	ect: ARCO 2185 9800 East 14th Street, Oakland	Log of Well No. VW-1					
Date Started: 5/14/91		Total Dept	h: 10.0-ft	Casing Elev: 2	5 feet	GW A	TD:ft/ft
Date	Completed: 5/14/91	Perforation	: 0.020 Sk	ot PVC			feet To 4.8 fee
Logged By: Jonathan Florez Checked By: T. R.			Sand Pack		fre		
_	g Co: Gregg Drilling Driller:	Seal: Ber				om 41	
_	g Method: HSA					from 3 feet To 0 fee	
	g Equipment: Mobile B-61		!-inch diam	eter PVC D	rill Bit Dii	imeter:	0.3
	g Equipment. Mobile 6-6 1	Sampler: N	I/A	Monitoring &	60		
Depth (feet)	LITHOLOGIC DESCRIPTION	1	Lithology	Monitoring Well Construction	Blow Counts	(mdd)	REMARKS
	Mottled olive-black silty CLAY and gravel fill.		18 9 18 9 18 9 18 9 18 9 18 9 18 9 18 9				
5	Black silty CLAY, trace coarse sand.		CL				
	Medium brown clayey SILT, trace fine sand, no odor.		ML				
10							
	-			ic i			
15	_						
	Project: A102W01 Ro	ux Asso	ciates				Page 1 of 1

ROUX

Project: ARCO 2185 9800 East 14th Street, Oakland		Log of Well No. VW-2				
Date Started: 5/14/91		Total Depth: 10.0-ft Casing Elev: 25 feet GW ATE	D:ft/ft			
Date	Completed: 5/14/91	Perforation: 0.020 Slot PVC from 10 for	eet To 4.2 fee			
Logg	ed By: Jonathan Florez Checked By: T. R.	Pack: #3 Sand Pack from 10 for	eet To 4 feet			
-	ng Co: Gregg Drilling Driller:	Seal: Bentonite from 4 fee				
-		Cement/Bentonite Grout from 3 fee				
-	ng Method:HSA	Casing: 2-inch diameter PVC Drill Bit Diameter: 6.	.5			
-	ng Equipment: Mobile B-61	Sampler: N/A				
Depth (feet)	LITHOLOGIC DESCRIPTION	Monitoring Well Construction S S S S S S S S S S S S S S S S S S S	REMARKS			
	Coarse sand, little gravel fill.	CL				
	Black sitty CLAY, trace fine sand.					
10	Light brown to black silty CLAY, trace fine sand, no odor.	CL				
15						
		ıx Associates Pa	age 1 of 1			