R0445

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT					
EM	PROFINCY HAS STATE OFFICE OF EMERGENCY SERV	FOR LOCAL AGENCY USE ONLY			
YES W NO SHAUG TO NO			I HEREBY CERTIFY THAT I HAVE DISTRIBUTED THIS INFORMATION ACCORDING TO THE DISTRIBUTION SHOWN ON THE INSTRUCTION, SIDEET ON THE BACK PAGE OF THIS FORM.		
REPORT DATE CASE #			MARIA		1/22/90
0 × 8 × 1 d 7 d 9 × 4 ×			SIGNED /		DATE
	NAME OF INDIVIDUAL FILING REPORT	PHON	Ė	SIGNATURE	
REPORTED BY	Lee N. Huckins	51		the Hucken	4
	REPRESENTING X OWNER/OPERATOR REGIONAL BOARD		COMPANY OR AGENCY NAME		
Ö	LOCAL AGENCY OTHER Tank Protect Engineering of Northern Californ				orthern California,
"	2821 Whipple Road		Union City,	CA	94587
_	NAME		CITY CONTACT PERSON	3	PHONE ZIP
RESPONSIBLE		NOWN		~~~	(209) 462–5761
	ADDRESS		Ken Eva	IIS	1209 / 462-5761
	1161 South Airport Way		Stockton cmy	CA s	95206 ZIP
	FACILITY NAME (IF APPLICABLE)		OPERATOR		PHONE
NO	C.A.R.S Rent-A-Car (Formerly)				()
LOCATION	6301 San Pablo Avenue,		Oakland, cmy	Alame	eda 94608
BITEL	CROSS STREET		спу		COUNTY ZIP
8	GROSS STREET				
Ø	LOCAL AGENCY AGENCY NAME		CONTACT PERSON		PHONE
IMPLEMENTING AGENCIES	Alameda County Health Care Services	3 con	Susan H	וווח	(510)567-6700
LEME		Agen	Cy Cabarri	290	PHONE
F A	CRWQCB - San Francisco Bay Region		KEVIN	GRAVES	(510)286-1255
SHIC		AME			DUANTITY LOST (GALLONS)
ANC	Petroleum hydrocarbons - see below				UNKNOWN
SUBSTANCES	(2)				
_	DATE DISCOVERED HOW DISCOVERED NUMBER CONTIDUE SUBSIDERACE MONITORING NUMBER CONDUCTORS				
OVERY/ABATEMENT	THYENTON CONTINUE SUBSURFACE MONITORING NOISINGE CONDITIONS				
ATE	O M 8 M O D 5 D 9 4 Y TANK TEST X TANK REMOVAL OTHER DATE DISCHARGE BEGAN METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)				
TYIAE	I I I I I I I I I I I I I I I I I I I				
Sei	HAS DISCHARGE BEEN STOPPED? REPAIR TANK CLOSE TANK & FILL IN PLACE CHANGE PROCEDURE				
DISC	YES NO IF YES, DATE M M D D Y Y REPLACE TANK CTHER				
	SOURCE OF DISCHARGE CAUSE(S)				
SOURCE/	TANK LEAK V UNKNOWN OVERFILL RUPTURE/FAILURE SPILL				
18,	PIPING LEAK OTHER CORROSION X UNKNOWN OTHER				
CASE	CHECK ONE ONLY				
3 6					
CURRENT	CHECK ONE ONLY NO ACTION TAKEN PRELIMINARY SITE ASSESSMENT WORKPLAN SUBMITTED POLLUTION CHARACTERIZATION				
	LEAK BEING CONFIRMED PRELIMINARY SITE ASSESSMENT UNDERWAY POST CLEANUP MONITORING IN PROGRESS				
	REMEDIATION PLAN CASE CLOSED (CLEANUP COMPLETED OR UNNECESSARY) CLEANUP UNDERWAY				
REMEDIAL	CHECK APPROPRIATE ACTION(S) EXCAVATE A DIS	POSE IFI) REMOVE F	REE PRODUCT (FP)	ENHANCED BIO DEGRADATION (IT)
	(BEE BACK FOR DETAILS) CAP SITE (CD) EXCAVATE & TRE			EAT GROUNDWATER (GT)	REPLACE SUPPLY (RS)
	CONTAINMENT BARRIER (CB) NO ACTION REQU		A) TREATMEN	IT AT HOOKUP (HU)	VENT SOIL (VS)
	VACUUM EXTRACT (VE) OTHER (OT)				
w					
COMMENTS	Removed four 2,000-gallon gasoline underground storage tanks				
and one 350-gallon waste oil underground storage tank.					
1					MSC 05 (8/90)