Ms. Eva Chu Alameda County Health Care Services Agency 1131 Harbor Bay Parkway, 2nd Floor Alameda, California 94502

Re: Monitoring and Remediation Performance Report First Quarter 2001

ARCO Service Station No. 6041 7249 Village Parkway Dublin, California Cambria Project # 438-1643





Dear Ms. Chu:

On behalf of ARCO, Cambria Environmental Technology, Inc. (Cambria) is submitting the attached report which presents the results of the first quarter 2001 groundwater monitoring program at ARCO Service Station No. 6041, located at 7249 Village Parkway, Dublin, California. Operation and performance data for the mobile dual-phase vacuum extraction (DVE) program is also presented. The monitoring program complies with the ACHCSA requirements regarding underground tank investigations.

Please call if you have any questions.

Sincerely,

Cambria Environmental Technology, Inc.

Ron Scheele, RG

Senior Project Manager

B. Schul

Attachment: Quarterly Groundwater Monitoring Report, First Quarter 2001

Oakland, CA

San Ramon, CA

Sonoma, CA

cc:

Mr. Paul Supple, ARCO, PO Box 6549, Moraga, California 94570

Ms. Karen Petryna, Equiva Services, LLC, PO Box 7869, Burbank, California 91510-7869

Cambria Environmental Technology, Inc.

1144 65th Street Suite B Oakland, CA 94608 Tel (510) 420-0700 Fax (510) 420-9170

Monitoring and Remediation Performance Report First Quarter 2001

ARCO Service Station No. 6041
7249 Village Parkway
Dublin, California
Cambria Project # 438-1643



Prepared For:

Mr. Paul Supple ARCO

April 25, 2001

Prepared By:
Cambria Environmental Technology, Inc.
6262 Hollis Street
Emeryville, California 94608

Written by:

Jason D. Olson

Senior Staff Environmental Scientist

Ron Scheele, RG

No. 6842

Senior Project Manager

CAMBRIA

Date:

April 25, 2001

Quarter:

1st Quarter, 2001

ARCO QUARTERLY GROUNDWATER MONITORING REPORT

| Station No.: 6041 Address: | 7249 Village Parkway, Dublin, California |
|--|--|
| ARCO Environmental Engineer/Phone No.: | Paul Supple /(925) 299-8891 |
| Consulting Co./Contact Person: | Cambria Environmental Technology, Inc. / Ron Scheele, RG |
| Consultant Project No.: | 438-1643 |
| Primary Agency/Regulatory ID No.: | ACHCSA |

WORK PERFORMED THIS QUARTER (FIRST - 2001):

- 1. Submitted quarterly groundwater monitoring report for fourth quarter, 2000.
- 2. Performed quarterly groundwater monitoring and sampling on February 9, 2001.
- 3. Prepared remediation piping design for upcoming station remodel.
- 4. Performed monthly mobile dual phase vacuum extraction (DVE) remediation (January 30, February 26, and March 20, 2001).

WORK PROPOSED FOR NEXT QUARTER (SECOND - 2001):

- 1. Prepare and submit quarterly groundwater monitoring report for first quarter 2001.
- 2. Perform quarterly groundwater monitoring and sampling for second quarter 2001.
- 3. Perform final DVE remediation event in May 2001.

MONITORING:

| Current Phase of Project: | Interim Remediation |
|---|---|
| Frequency of Groundwater Sampling | Quarterly: MW-1, MW-3, VW-2, Shell MW-6, Shell MW-7 |
| | Semi-annual: MW-2 (1 st /3 rd) |
| Frequency of Groundwater Monitoring | Quarterly |
| Is Free Product (FP) Present On-site: | No |
| Bulk Soil Removed to Date: | 15 cubic yards of TPH impacted soil |
| Water Wells or Surface Waters, | |
| within 2000 ft., impacted by site: | None |
| Current Remediation Techniques: | DVE (8 hours monthly) |
| Average Depth to Groundwater: | 8.92 feet |
| Groundwater Flow Direction and Gradient | 0.003 ft/ft toward west-southwest |
| | |



CAMBRIA

Date:

April 25, 2001

Quarter:

1st Quarter, 2001

MOBILE DVE QUARTERLY OPERATION AND PERFORMANCE

22.75 hours

Event Frequency: Monthly (began on 11/22/00)

Event Duration This Quarter (average): 7.6 hours

To Date: 37.75 hours

Extraction Wells: TP-1, TP-2, MW-1, MW-3, VW-2 discontinued 12/13/00

Total TPHg removed this guarter: < 3.32 pounds

Total TPHg removed to date: < 5.96 pounds

Total Benzene removed this quarter < 0.143 pounds

Total Benzene removed to date: < 0.235 pounds

Total MTBE removed this quarter: 3.68 pounds

Total MTBE removed to date: 4.21 pounds

SOIL VAPOR EXTRACTION

Total Extraction Time - This Quarter:

TPHg Vapor Conc. End of Period (lab): 9,780 ppmv (MW-1 on 3/20/01)

Benzene Vapor Conc. End of Period (lab): 176 ppmv (MW-1 on 3/20/01)
MTBE Vapor Conc. End of Period (lab): 453 ppmv (MW-1 on 3/20/01)

System vapor flow rates: 4.3 to 17.9 cfm

GROUNDWATER EXTRACTION

Groundwater extracted this quarter: 5,163 gallons

Total groundwater extracted: 5,829 gallons

System groundwater flow rates: 0.27 to 11.52 gallons per minute

Source of groundwater analytical data: 4th Quarter 2000 / 1st Quarter 2001

Max TPHg groundwater concentration (lab): 29,700 ug/L (MW-3)

Max Benzene groundwater concentration (lab): 2,590 ug/L (MW-3)

Max MTBE groundwater concentration (lab): 85,500 ug/L (MW-3)

DISCUSSION:

Based on field measurements collect on February 9, 2001, groundwater beneath the site flows towards the west-southwest at a gradient of 0.003 ft/ft. This is consistent with the historic groundwater flow direction and gradient.

Hydrocarbon concentrations detected this quarter show a decrease in MTBE concentrations in MW-1 and MW-2, and an increase in TPHg, benzene, and MTBE concentrations in well MW-3 as compared with the previous sampling event. The maximum TPHg, benzene, and MTBE concentrations were detected in well MW-3 at 29,300, 2,590, and 85,500 micrograms per liter (μ g/L), respectively.

Five mobile DVE events have been performed at the site since November 22, 2000. Cambria will perform the final approved DVE event in May 2001. Site DVE remediation effectiveness will be assessed after the completion of the third quarter groundwater sampling event. Please note that DVE data presented in Cambria's *Quarterly Groundwater Monitoring Report, Fourth Quarter 2000* dated February 23, 2001 was revised due to incorrect flow data.



CAMBRIA

Date: April 2

April 25, 2001

Quarter:

1st Quarter, 2001

ATTACHMENTS:

Figure 1 - Groundwater Elevation Contour and Analytical Summary Map

• Table 1 - Groundwater Monitoring Data

• Table 2 - Groundwater Flow Direction and Gradient

• Table 3 - Groundwater Extraction – Mass Removal Data

• Table 4 - Soil Vapor Extraction – Mass Removal Data

• Appendix A - Sampling and Analysis Procedures

Appendix B - Certified Analytical Reports and Chain-of-Custody Documentation

Appendix C - Field Data Sheets




FIGURE

FORMER

MARKET





BP STATION BUILDING



325.91 2,600 308

326.00

326.10

CHIROPRACTOR'S

OFFICE

MW-6 326.22

Scale (ft)

AS-1

VW-1

TP-1

AS-2

TP-2 VW-2

EXISTING-USTs

MW-3 325.92

€ VW-3

UNOCAL SITE

Table 1
Historical Groundwater Elevation and Analytical Data
Petroleum Hydrocarbons and Their Constituents
1995 - Present**

| | <u> </u> | TOC | Depth | FP | Groundwater | | ТРН | | | Ethyl- | Total | MTBE | MTBE | Dissolved | Purged/ |
|--------|----------|-----------|--------------|-----------|------------------|----------|----------|--------|--------|--------|-----------------|------------|--------|-----------|------------|
| Well | Date | Elevation | to Water | Thickness | Elevation | Date | Gasoline | | | | Xylenes | 8021B* | 8260 | Oxygen | Not Purged |
| Number | Gauged | (ft-MSL) | (feet) | (feet) | (ft-MSL) | Sampled | (μg/L)_ | (μg/L) | (μg/L) | (μg/L) | (μ <u>g</u> /L) | (μg/L) | (μg/L) | (mg/L) | (P/NP) |
| MW-1 | 02-15-95 | 336.56 | 8.53 | 0.00 | 328.03 | 02-15-95 | 820 | 15 | <1 | 5.2 | 1.4 | | | | |
| MW-1 | 05-24-95 | 336.56 | 9.00 | 0.00 | 327.56 | 05-24-95 | 640 | 12 | <1 | 7.3 | <1 | | | | |
| MW-1 | 08-25-95 | 336.56 | 10.30 | 0.00 | 326.26 | 08-25-95 | 780 | 2 | <1 | 2 | 2 | 2,500 | | | |
| MW-1 | 11-28-95 | 336.56 | 11.01 | 0.00 | 325.55 | 11-28-95 | 570 | 2.2 | < 0.5 | 1.4 | 0.9 | | | | |
| MW-1 | 02-26-96 | 336.56 | 7.35 | 0.00 | 329.21 | 03-13-96 | 1,100 | 28 | <7 | 13 | 7 | 3,400 | | | |
| MW-1 | 05-23-96 | 336.56 | 8.73 | 0.00 | 327.83 | 05-23-96 | 560 | 8.5 | <1 | 1.1 | <1 | 3,900 | | | |
| MW-1 | 08-23-96 | 336.56 | 10.25 | 0.00 | 326.31 | 08-23-96 | 860 | <1 | <1 | <4 | 2 | 5,600 | | | |
| MW-1 | 03-21-97 | 336.56 | 9.35 | 0.00 | 327.21 | 03-21-97 | 520 | 12 | < 0.5 | 2.7 | 1.5 | 6,200 | | | |
| MW-1 | 08-20-97 | 336.56 | 10.75 | 0.00 | 325.81 | 08-20-97 | <5,000 | <50 | <50 | <50 | < 50 | 7,400 | | | |
| MW-1 | 11-21-97 | 336.56 | 11.10 | 0.00 | 325.46 | 11-21-97 | <5,000 | <50 | <50 | <50 | <50 | 8,500 | | | |
| MW-1 | 02-12-98 | 336.56 | 7.05 | 0.00 | 329.51 | 02-12-98 | 210 | < 0.5 | <0.5 | <0.5 | < 0.5 | 8,900 | | | |
| MW-1 | 07-31-98 | 336.56 | 10.04 | 0.00 | 326.52 | 07-31-98 | <20,000 | <200 | <200 | <200 | <200 | 18,000 | | | |
| MW-1 | 02-17-99 | 336.56 | 8.50 | 0.00 | 328.06 | 02-17-99 | <20,000 | <200 | <200 | <200 | <200 | 16,000 | | | |
| MW-1 | 08-24-99 | 336.56 | 10.40 | 0.00 | 326.16 | 08-24-99 | 190 | < 0.5 | 4.4 | < 0.5 | 1.1 | 15,000 | | NR | |
| MW-1 | 03-01-00 | 336.56 | 8.85 | 0.00 | 327.71 | 03-01-00 | 310 | 20 | 0.5 | 7.6 | 4 | 80,000 | | 1.57 | |
| MW-1 | 08-18-00 | 336.56 | 9.35 | 0.00 | 327.21 | 08-18-00 | <10,000 | <100 | <100 | <100 | <100 | 48,400 | 63,700 | | |
| MW-1 | 12-27-00 | 336.56 | 10.81 | 0.00 | 325.75 | 12-27-00 | <10,000 | 309 | <100 | <100 | 289 | 44,400 | | 0.51 | |
| MW-1 | 02-09-01 | 336.56 | 10.65 | 0.00 | 325.91 | 02-09-01 | 2,820 | 368 | <25.0 | 116 | 176 | 23,300 | | | |
| DUP | 02-09-01 | NR | NR | NR | NR | 02-09-01 | 3,490 | 432 | 9.56 | 146 | 235 | 31,800 | | NR | |
| MW-2 | 02-15-95 | 334.80 | 6.75 | 0.00 | 328.05 | 02-15-95 | 730 | 110 | 1.7 | 25 | 66 | <u>.</u> . | | | |
| | | | 6.88 | 0.00 | 327.92 | 05-24-95 | 370 | | | | | | | | |
| MW-2 | 05-24-95 | 334.80 | | 0.00 | 326.89 | 03-24-93 | 150 | | | | | | | | |
| MW-2 | 08-25-95 | 334.80 | 7.91 9.06 | | 325.74 | 11-28-95 | <50 | | | | | • | | | |
| MW-2 | 11-28-95 | 334.80 | | 0.00 | 323.74 | 03-13-96 | 350 | | | | | | | | |
| MW-2 | 02-26-96 | 334.80 | 6.65 | 0.00 | 328.13 327.90 | 05-23-96 | 540 | | | | | | | | |
| MW-2 | 05-23-96 | 334.80 | 6.90 | 0.00 | 327.90 | UJ-23-90 | 540 | 140 | ۷.3 | 13 | ~2.5 | 7,000 | | | |

Table 1
Historical Groundwater Elevation and Analytical Data
Petroleum Hydrocarbons and Their Constituents
1995 - Present**

| . <u>-</u> | | TOC | Depth | FP | Groundwater | · - · | TPH | | | Ethyl- | Total | MTBE | MTBE | Dissolved | Purged/ |
|------------|-------------|-----------|----------|-----------|-------------|------------------|-------------|-----------|-------------|-------------|---------|--------|------------|-----------|------------|
| Well | Date | Elevation | to Water | Thickness | Elevation | Date | Gasoline | Benzene | Toluene | benzene | Xylenes | 8021B* | 8260 | Oxygen | Not Purged |
| Number | Gauged | (ft-MSL) | (feet) | (feet) | (ft-MSL) | Sampled | (μg/L) | (μg/L) | (μg/L) | (μg/L) | (μg/L) | (μg/L) | (μg/L) | (mg/L) | (P/NP) |
| MW-2 | 08-23-96 | 334.80 | 8.45 | 0.00 | 326.35 | 08-23-96 | 180 | 0.8 | 2 | 0.7 | 2.6 | 4,000 | | | |
| MW-2 | 03-21-97 | 334.80 | 7.28 | 0.00 | 327.52 | 03-21-97 | 410 | 90 | <1 | 14 | 4 | 3,800 | | | |
| MW-2 | 08-20-97 | 334.80 | 8.87 | 0.00 | 325.93 | 08-20-97 | <5,000 | <50 | <50 | <50 | <50 | 3,100 | | | |
| MW-2 | 11-21-97 | 334.80 | 9.28 | 0.00 | 325.52 | 11-21-97 | <2,000 | <20 | <20 | <20 | <20 | 2,600 | | | |
| MW-2 | 02-12-98 | 334.80 | 5.90 | 0.00 | 328.90 | 02-12-98 | 310 | 54 | < 0.5 | 6.2 | 1.1 | 3,800 | | 3.76 | |
| MW-2 | 07-31-98 | 334.80 | 8.12 | 0.00 | 326.68 | 07-31-98 | 6,100 | 52 | 220 | 110 | 1100 | 7,700 | | 2.96 | |
| MW-2 | 02-17-99 | 334.80 | 7.18 | 0.00 | 327.62 | 02-17-99 | <5,000 | <50 | <50 | < 50 | <50 | 4,200 | | 1.0 | |
| MW-2 | 08-24-99 | 334.80 | 8.68 | 0.00 | 326.12 | 08-24-99 | 200 | 1.8 | 16 | 3.0 | 32 | 3,100 | | NR | |
| MW-2 | 03-01-00 | 334.80 | 7.02 | 0.00 | 327.78 | 03-01-00 | 760 | 24 | 12 | 13 | 59 | 6,300 | | 1.92 | |
| MW-2 | 08-18-00 | 334.80 | 7.75 | 0.00 | 327.05 | 08-18-00 | <500 | <5.00 | <5.00 | | <5.00 | 1,610 | 1,980 | | |
| MW-2 | 12-27-00 | 334.80 | 8.85 | 0.00 | 325.95 | Not Sample | d: Well sar | npled dur | ing first a | nd third qu | arters | | | NR | |
| MW-2 | 02-09-01 | 334.80 | 8.50 | 0.00 | 326.30 | 02-09-01 | <50.0 | < 0.500 | <0.500 | <0.500 | <0.500 | 9.11 | | 0.53 | P |
| MW-3 | 02-15-95 | 335.53 | 8.55 | 0.00 | 326.98 | 02-15-95 | 100 | 14 | <0.5 | 6.3 | <0.5 | | | | |
| MW-3 | 05-24-95 | 335.53 | 8.17 | 0.00 | 327.36 | 05-24-95 | 110 | 8 | <0.5 | 2.7 | <0.5 | | | | |
| MW-3 | 08-25-95 | 335.53 | 9.27 | 0.00 | 326.26 | 08-25-95 | 210 | 3.6 | <0.5 | 2.9 | 0.6 | 20,000 | | | |
| MW-3 | 11-28-95 | 335.53 | 9.91 | 0.00 | 325.62 | 11-28-95 | 81 | 1.5 | <0.5 | 1.4 | < 0.5 | | 15,000 | | |
| MW-3 | 02-26-96 | 335.53 | 8.42 | 0.00 | 327.11 | 03-13-96 | 16,000 | 1,600 | 1,200 | 300 | 2,000 | 9,500 | - - | | |
| MW-3 | 05-23-96 | 335.53 | 7.70 | 0.00 | 327.83 | 05-23-96 | 6,500 | 690 | <10 | 120 | 14 | 8,600 | | | |
| MW-3 | 08-23-96 | 335.53 | 9.25 | 0.00 | 326.28 | 08-23-96 | 1,700 | 85 | 2 | 61 | 5.3 | 11,000 | | | |
| MW-3 | 03-21-97 | 335.53 | 8.72 | 0.00 | 326.81 | 03-21-97 | 100 | 2 | <1 | 1 | <1 | 6,600 | | | |
| MW-3 | 08-20-97 | 335.53 | 9.73 | 0.00 | 325.80 | 08-20-97 | <5,000 | <50 | <50 | <50 | | . , | | | |
| MW-3 | 11-21-97 | 335.53 | 10.10 | 0.00 | 325.43 | 11-21-97 | <5,000 | <50 | <50 | <50 | < 50 | - | | | |
| MW-3 | 02-12-98 | 335.53 | 6.68 | 0.00 | 328.85 | 02-12-98 | 110 | 11 | < 0.5 | < 0.5 | 1.9 | | | | |
| MW-3 | 07-31-98 | 335.53 | 7.98 | 0.00 | 327.55 | 07-31-98 | <10,000 | | | | | • | | | |
| MW-3 | 02-17-99 | 335.53 | 8.40 | 0.00 | 327.13 | 02-17-99 | <20,000 | <200 | <200 | <200 | <200 | 23,000 | | 1.0 |) P |

2 of 6

Table 1
Historical Groundwater Elevation and Analytical Data
Petroleum Hydrocarbons and Their Constituents
1995 - Present**

| | | TOC | Depth | FP | Groundwater | | TPH | | <u>. </u> | Ethyl- | Total | MTBE | MTBE | Dissolved | Purged/ |
|--------|----------|-----------|-------------|--------|-------------|-----------|--------------|--------------|--|--------------|--------------|-----------------|--------|-----------|------------|
| Well | Date | Elevation | to Water | | Elevation | Date | Gasoline | Benzene | Toluene | benzene | Xylenes | 8021 B * | 8260 | Oxygen | Not Purged |
| Number | Gauged | (ft-MSL) | (feet) | (feet) | (ft-MSL) | Sampled | (μg/L)_ | (μg/L) | (μg/L)_ | (μg/L) | (μg/L) | (μg/L) | (μg/L) | (mg/L) | (P/NP) |
| MW-3 | 08-24-99 | 335.53 | 9.45 | 0.00 | 326.08 | 08-24-99 | 200 | 0.6 | 5.6 | 0.6 | 1.7 | 22,000 | | NR | P |
| MW-3 | 03-01-00 | 335.53 | 8.32 | 0.00 | 327.21 | 03-01-00 | 320 | 32 | 1.0 | 6.1 | 4 | 58,000 | | 2.42 | P |
| MW-3 | 08-18-00 | 335.53 | 8.35 | 0.00 | 327.18 | 08-18-00 | <10,000 | <100 | <100 | <100 | <100 | 46,200 | 55,600 | 1.59 | P |
| DUP | 08-18-00 | NR | NR | NR | NR | 08-18-00 | <10,000 | <100 | <100 | <100 | <100 | 45,500 | 51,700 | NR | |
| MW-3 | 12-27-00 | 335.53 | 9.75 | 0.00 | 325.78 | 12-27-00 | 29,700 | 1,620 | 1,730 | <250 | 6,230 | 62,600 | | 1.59 | P |
| MW-3 | 02-09-01 | 335.53 | 9.61 | 0.00 | 325.92 | 02-09-01 | 29,300 | 2,590 | 3,530 | 440 | 7,080 | 85,500 | | 0.51 | P |
| MW-4 | 02-15-95 | 334.22 | 7.85 | 0.00 | 326.37 | 02-15-95 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | | | | |
| MW-4 | 05-24-95 | 334.22 | 6.68 | 0.00 | 327.54 | | | | | | he first and | l third quart | ters | | |
| MW-4 | 08-25-95 | 334.22 | 6.93 | 0.00 | 327.29 | 08-25-95 | <50 | <0.5 | | <0.5 | <0.5 | <3 | | | |
| MW-4 | 11-28-95 | 334.22 | 8.21 | 0.00 | 326.01 | | ed: well sa | mpled ser | ni-annuall | y, during th | he first and | l third quart | ters | | |
| MW-4 | 02-26-96 | 334.22 | 6.65 | 0.00 | 327.57 | 03-13-96 | <50 | <0.5 | | <0.5 | <0.5 | <3 | | | |
| MW-4 | 05-23-96 | 334.22 | 6.47 | 0.00 | 327.75 | Not sampl | ed: well sa | mpled ser | ni-annuall | y, during t | he first and | l third quart | ters | | |
| MW-4 | 08-23-96 | 334.22 | 7.66 | 0.00 | 326.56 | | ed: well no | | | | | | | | |
| MW-4 | 03-21-97 | 334.22 | 6.84 | 0.00 | 327.38 | Not sampl | ed: well no | t part of s | ampling p | rogram | | | | | |
| MW-4 | 08-20-97 | 334.22 | 8.32 | 0.00 | 325.90 | Not sampl | ed: well no | t part of s | ampling p | rogram | | | | | |
| MW-4 | 11-21-97 | 334.22 | 8.65 | 0.00 | 325.57 | Not sampl | ed: well no | t part of s | ampling p | rogram | | | | | |
| MW-4 | 02-12-98 | 334.22 | 6.35 | 0.00 | 327.87 | Not sampl | ed: well no | t part of s | ampling p | rogram | | | | | |
| MW-4 | 07-31-98 | 334.22 | 6.84 | 0.00 | 327.38 | Not sampl | ed: well no | ot part of s | ampling p | rogram | | | | | |
| MW-4 | 02-17-99 | 334.22 | 7.50 | 0.00 | 326.72 | Not sampl | ed: well no | ot part of s | sampling p | rogram | | | | | |
| MW-4 | 08-24-99 | 334.22 | 9.50 | 0.00 | 324.72 | • | led: well no | - | | _ | | | | | |
| MW-4 | 03-01-00 | 334.22 | 6.93 | 0.00 | 327.29 | _ | led: well no | _ | | | | | | | |
| MW-4 | 08-18-00 | 334.22 | 7.03 | 0.00 | 327.19 | - | led: well no | _ | _ | | | | | | |
| MW-4 | 12-27-00 | 334.22 | 8.10 | 0.00 | 326.12 | - | led: well no | - | | | | | | | |
| MW-4 | 02-09-01 | 334.22 | 7.97 | 0.00 | 326.25 | Not samp | led: well n | ot part o | f samplin | g program | 1 | | | | |

Table 1
Historical Groundwater Elevation and Analytical Data
Petroleum Hydrocarbons and Their Constituents
1995 - Present**

| 337-11 | Date | TOC Elevation | Depth | FP Thickness | Groundwater Elevation | TPH Ethyl- Total MTBE MTBE Dissolved Date Gasoline Benzene Toluene benzene Xylenes 8021B* 8260 Oxygen 1 | Purged/ Not Purged |
|--------|----------|------------------|--------|-----------------|--------------------------|---|-----------------------|
| Well | Gauged | (ft-MSL) | (feet) | (feet) | (ft-MSL) | Sampled $(\mu g/L)$ | (P/NP) |
| Number | | | | | | Samples (48-) (48-) (40-) (40-) (40-) | |
| MW-5 | 02-15-95 | 335.87 | 7.80 | 0.00 | 328.07 | 02-15-95 <50 <0.5 <0.5 <0.5 | |
| MW-5 | 05-24-95 | 335.87 | 8.10 | 0.00 | 327.77 | Not sampled: well sampled annually, during the first quarter | |
| MW-5 | 08-25-95 | 335.87 | 9.43 | 0.00 | 326.44 | Not sampled: well sampled annually, during the first quarter | |
| MW-5 | 11-28-95 | 335.87 | 10.12 | 0.00 | 325.75 | Not sampled: well sampled annually, during the first quarter | |
| MW-5 | 02-26-96 | 335.87 | 6.73 | 0.00 | 329.14 | 03-13-96 <50 <0.5 <0.5 <0.5 <3 | |
| MW-5 | 05-23-96 | 335.87 | 7.87 | 0.00 | 328.00 | Not sampled: well sampled annually, during the first quarter | |
| MW-5 | 08-23-96 | 335.87 | 9.46 | 0.00 | 326.41 | Not sampled: well not part of sampling program | |
| MW-5 | 03-21-97 | 335.87 | 8.23 | 0.00 | 327.64 | Not sampled: well not part of sampling program | |
| MW-5 | 08-20-97 | 335.87 | 9.92 | 0.00 | 325.95 | Not sampled: well not part of sampling program | |
| MW-5 | 11-21-97 | 335.87 | 10.18 | 0.00 | 325.69 | Not sampled: well not part of sampling program | |
| MW-5 | 02-12-98 | 335.87 | 6.45 | 0.00 | 329.42 | Not sampled: well not part of sampling program | |
| MW-5 | 07-31-98 | 335.87 | 8.98 | 0.00 | 326.89 | Not sampled: well not part of sampling program | |
| MW-5 | 02-17-99 | 335.87 | 7.65 | 0.00 | 328.22 | Not sampled: well not part of sampling program | |
| MW-5 | 08-24-99 | 335.87 | 8.10 | 0.00 | 327.77 | Not sampled: well not part of sampling program | |
| MW-5 | 03-01-00 | 335.87 | 7.31 | 0.00 | 328.56 | Not sampled: well not part of sampling program | |
| MW-5 | 08-18-00 | 335.87 | 8.65 | 0.00 | 327.22 | Not sampled: well not part of sampling program | |
| MW-5 | 12-27-00 | 335.87 | 9.80 | 0.00 | 326.07 | Not sampled: well not part of sampling program | |
| MW-5 | 02-09-01 | 335.87 | 9.65 | 0.00 | 326.22 | Not sampled: well not part of sampling program | |
| MW-6 | 02-15-95 | 335.84 | 7.81 | 0.00 | 328.03 | 02-15-95 <50 <0.5 <0.5 <0.5 | |
| MW-6 | 05-24-95 | 335.84 | 8.35 | 0.00 | 327.49 | Not sampled: well sampled annually, during the first quarter | |
| MW-6 | 08-25-95 | 335.84 | 9.71 | 0.00 | 326.13 | Not sampled: well sampled annually, during the first quarter | |
| MW-6 | 11-28-95 | 335.84 | 10.28 | 0.00 | 325.56 | Not sampled: well sampled annually, during the first quarter | |
| MW-6 | 02-26-96 | 335.84 | 6.60 | 0.00 | 329.24 | 03-13-96 <50 <0.5 <0.5 <0.5 <0.5 <3 | |
| MW-6 | 05-23-96 | 335.84 | 8.05 | 0.00 | 327.79 | Not sampled: well sampled annually, during the first quarter | |
| MW-6 | 08-23-96 | 335.84 | 9.58 | 0.00 | 326.26 | Not sampled: well not part of sampling program | |

Table 1
Historical Groundwater Elevation and Analytical Data
Petroleum Hydrocarbons and Their Constituents
1995 - Present**

| | | TOC | Depth | FP | Groundwater | • | TPH | | | Ethyl- | Total | MTBE | MTBE | Dissolved | Purged/ |
|--------------|----------|-----------|----------|--------|-------------|------------|-------------|-------------|-----------|------------|---------|--------|--------|-----------|------------|
| Well | Date | Elevation | to Water | | Elevation | Date | Gasoline | Benzene | Toluene | benzene | Xylenes | 8021B* | 8260 | Oxygen | Not Purged |
| Number | Gauged | (ft-MSL) | (feet) | (feet) | (ft-MSL) | Sampled | (μg/L)_ | (μg/L) | (μg/L) | (μg/L) | (μg/L) | (μg/L) | (μg/L) | (mg/L) | (P/NP) |
| MW-6 | 03-21-97 | 335.84 | 8.39 | 0.00 | 327.45 | Not sample | ed: well no | t part of s | ampling p | orogram | | | | | |
| MW-6 | 08-20-97 | 335.84 | 9.98 | 0.00 | 325.86 | - | ed: well no | - | | | | | | | |
| MW-6 | 11-21-97 | 335.84 | 10.31 | 0.00 | 325.53 | Not sample | ed: well no | t part of s | ampling p | rogram | | | | | |
| MW-6 | 02-12-98 | 335.84 | 3.15 | 0.00 | 332.69 | Not sampl | ed: well no | t part of s | ampling p | rogram | | | | | |
| MW-6 | 07-31-98 | 335.84 | 9.29 | 0.00 | 326.55 | Not sampl | ed: well no | t part of s | ampling p | rogram | | | | | |
| MW-6 | 02-17-99 | 335.84 | 7.72 | 0.00 | 328.12 | Not sampl | ed: well no | t part of s | ampling p | rogram | | | | | |
| MW-6 | 08-24-99 | 335.84 | 9.65 | 0.00 | 326.19 | Not sampl | ed: well no | t part of s | ampling p | orogram | | | | | |
| MW-6 | 03-01-00 | 335.84 | 7.35 | 0.00 | 328.49 | Not sampl | ed: well no | t part of s | ampling p | rogram | | | | | |
| MW-6 | 08-18-00 | 335.84 | 8.65 | 0.00 | 327.19 | Not sampl | ed: well no | t part of s | ampling p | огоgram | | | | | |
| MW-6 | 12-27-00 | 335.84 | 9.83 | 0.00 | 326.01 | Not sampl | ed: weil no | t part of s | ampling p | orogram | | | | | |
| MW-6 | 02-09-01 | 335.84 | 9.62 | 0.00 | 326.22 | Not samp | led: well n | ot part o | f samplin | g progran | 1 | | | | |
| VW-2 | 03-21-97 | NR | 8.22 | 0.00 | NR | 03-21-97 | 150 | 8.9 | <0.5 | <0.5 | 0.6 | 270 | | - | |
| VW-2 | 08-20-97 | NR | 9.16 | 0.00 | NR | 08-20-97 | | | | f sampling | | | | | |
| VW-2 VW-2 | 11-21-97 | NR | 8.27 | 0.00 | NR | 11-21-97 | <200 | 3 | · • | | | 180 | | | |
| VW-2 | 02-12-98 | NR | 6.65 | 0.00 | NR | 02-12-98 | 200 | 19 | | | < 0.5 | 2,200 | | | |
| VW-2 | 07-31-98 | NR | 7.01 | 0.00 | NR | 07-31-98 | | oled: well | | f sampling | program | , | | | |
| VW-2 | 02-17-99 | NR | 8.47 | 0.00 | NR | 02-17-99 | | | | f sampling | | | | | |
| VW-2 | 08-24-99 | NR | 8.20 | 0.00 | NR | 08-24-99 | _ | | _ | f sampling | | | | | |
| VW-2 | 03-01-00 | NR | 8.72 | 0.00 | NR | 03-01-00 | - | | _ | f sampling | | | | | |
| VW-2 | 08-18-00 | NR | 8.40 | 0.00 | NR | 08-18-00 | <250 | | | | | 537 | | 1.59 | NP |
| VW-2 | 12-27-00 | NR | 8.95 | 0.00 | NR | Not sample | | | | | | | | | |
| VW-2 | 02-09-01 | NR | 8.87 | 0.00 | NR | Not sample | | | | | | | | | |

Table 1
Historical Groundwater Elevation and Analytical Data
Petroleum Hydrocarbons and Their Constituents
1995 - Present**

| | | TOC | Depth | FP | Groundwater | | TPH | | | Ethyl- | Total | MTBE | MTBE | Dissolved | Purged/ |
|------------|----------|-----------|----------|-----------|-------------|----------|----------|---------|---------|---------|---------|--------|--------|-----------|------------|
| Well | Date | Elevation | to Water | Thickness | Elevation | Date | Gasoline | Benzene | Toluene | benzene | Xylenes | 8021B* | 8260 | Oxygen | Not Purged |
| Number | Gauged | (ft-MSL) | (feet) | (feet) | (ft-MSL) | Sampled | (μg/L) | (μg/L) | (μg/L) | (μg/L) | (μg/L) | (μg/L) | (μg/L) | (mg/L) | (P/NP) |
| Shell MW-6 | 12-27-00 | NR | 9.13 | 0.00 | NR | 12-27-00 | 74.7 | < 0.500 | <0.500 | < 0.500 | < 0.500 | <2.50 | | 1.30 | P |
| DUP | 12-27-00 | NR | NR | NR | NR | 12-27-00 | 79.3 | < 0.500 | < 0.500 | < 0.500 | < 0.500 | <2.50 | | NR | |
| Shell MW-6 | 02-09-01 | NR | 9.05 | 0.00 | NR | 02-09-01 | <50.0 | < 0.500 | < 0.500 | < 0.500 | < 0.500 | <2.50 | | 1.29 | P |
| Shell MW-7 | 12-27-00 | NR | 6.45 | 0.00 | NR | 12-27-00 | <50.0 | <0.500 | 0.696 | <0.500 | 0.795 | <2.50 | | 1.33 | P |
| Shell MW-7 | 02-09-01 | NR | 6.39 | 0.00 | NR | 02-09-01 | <50.0 | < 0.500 | < 0.500 | < 0.500 | < 0.500 | <2.50 | | 1.13 | P |

Notes:

TOC: top of casing

ft-MSL: elevation in feet, relative to mean sca level

TPH: total petroleum hydrocarbons, California DHS LUFT Method

BTEX: benzene, toluene, ethylbenzene, total xylenes by EPA method 8021B. (EPA method 8020 prior to 03/01/00).

MTBE: Methyl tert-butyl ether

EPA: United States Environmental Protection Agency

*: EPA method 8020 prior to 03/01/00

μg/L: micrograms per liter mg/L: milligrams per liter

ND: none detected

NR: not reported; data not available or not measurable

- -: not analyzed or not applicable
- <: denotes concentration not present at or above laboratory detection limit stated to the right.
- **: For previous historical groundwater elevation and analytical data please refer to Fourth Quarter 1995 Groundwater Monitoring Program Results, ARCO Service Station 6041, Dublin, California, (EMCON, February 26, 1996).

Table 2 Groundwater Flow Direction and Gradient

| Date | Average | Average |
|----------|-----------------|--------------------|
| Measured | Flow Direction | Hydraulic Gradient |
| | | |
| 02-15-95 | NR | NR |
| 05-24-95 | East-Southeast | 0.002 |
| 08-25-95 | Northwest | 0.006 |
| 11-28-95 | North | 0.006 |
| 02-26-96 | East | 0.012 |
| 05-23-96 | Flat Gradient | Flat Gradient |
| 08-23-96 | Flat Gradient | Flat Gradient |
| 03-21-97 | South-Southeast | 0.005 |
| 08-20-97 | South-Southwest | 0.001 |
| 11-21-97 | South-Southwest | 0.002 |
| 02-12-98 | East | 0.024 |
| 07-31-98 | Northwest | 0.01 |
| 02-17-99 | Southeast | 0.007 |
| 08-24-99 | South-Southwest | 0.013 |
| 03-01-00 | South-Southeast | 0.005 |
| 09-26-00 | South-Southeast | 0.002 |
| 12-27-00 | West-Southwest | 0.003 |
| 02-09-01 | West-Southwest | 0.003 |

Table 3
Groundwater Extraction
Mass Removal Data

| · · · · · · | | Froundwate | r Extraction D | ata | | Hydroca | rbon Conce | ntrations | TPHg F | Removal | Benzene | Removal | MTBE | Removal |
|------------------|-------------|-------------|----------------|------------|-------------|------------|---------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| | | Groundwater | | Extraction | | | | | Mass | Mass | Mass | Mass | Mass | Mass |
| | | Extraction | Groundwater | Flow | Groundwater | | | | Extracted | Extracted | Extracted | Extracted | Extracted | Extracted |
| Event | Well | Duration | Extracted | Rate | Sample | TPHg | Benzene | MTBE | Per Event | To Date | Per Event | To Date | Per Event | To Date |
| Date | ΙD | (hours) | (gallons) | (gpm) | Date | (Conc | entrations in | ug/L) | (lbs) | (lbs) | (lbs) | (lbs) | (lbs) | (lbs) |
| 11/22/00 | MW-1 | 3.08 | 235 | 1.27 | 09/26/00 | <10,000 | <100 | 63,700 | <0.01961 | < 0.01961 | <0.00020 | <0.00020 | 0.1249 | 0.1249 |
| 12/13/00 | MW-1 | 3.25 | 170 | 0.87 | 09/26/00 | <10,000 | <100 | 63,700 | <0.01419 | < 0.03379 | <0.00014 | < 0.00034 | 0.09036 | 0.2153 |
| 01/30/01 | MW-1 | 1.50 | 50 | 0.56 | 12/27/00 | <10,000 | 309 | 44,400 | <0.00417 | < 0.03797 | 0.00013 | < 0.00047 | 0.01852 | 0.2338 |
| 03/20/01 | MW-1 | 3.50 | 200 | 0.95 | 02/13/01 | 2,820 | 368 | 23,300 | 0.004706 | < 0.04267 | 0.00061 | < 0.00108 | 0.03888 | 0.2727 |
| 11/22/00 | MW-3 | 2.00 | 71 | 0.59 | 09/26/00 | <10,000 | <100 | 55,600 | <0.00592 | <0.00592 | <0.00006 | <0.00006 | 0.03294 | 0.03294 |
| 12/13/00 | MW-3 | 3.00 | 110 | 0.61 | 09/26/00 | <10,000 | <100 | 55,600 | <0.00918 | < 0.01510 | <0.00009 | < 0.00015 | 0.05103 | 0.08397 |
| 01/30/01 | MW-3 | 6.25 | 100 | 0.27 | 12/27/00 | 29,700 | 1,620 | 62,600 | 0.02478 | < 0.03989 | 0.00135 | < 0.00150 | 0.05224 | 0.1362 |
| 02/26/01 | MW-3 | 1.25 | 30 | 0.40 | 02/09/01 | 29,300 | 2,590 | 85,500 | 0.00733 | < 0.04722 | 0.00065 | <0.00215 | 0.02140 | 0.1576 |
| 02/26/01 | TP-1 | 2.75 | 1,900 | 11.52 | 2/9/2001* | 29,300 | 2,590 | 85,500 | 0.4645 | 0.4645 | 0.04106 | 0.04106 | 1.356 | 1.356 |
| 02/26/01 | TP-2 | 3.00 | 800 | 4.44 | 2/9/2001* | 29,300 | 2,590 | 85,500 | 0.1956 | 0.1956 | 0.01729 | 0.01729 | 0.5708 | 0.5708 |
| 03/20/01 | TP-2 | 4.50 | 2,083 | 7.71 | 2/9/2001* | 29,300 | 2,590 | 85,500 | 0.5093 | 0.7049 | 0.04502 | 0.0623 | 1.4861 | 2.0569 |
| 00,2 0,0x | | | _, | | | ĺ | , | ĺ | | | | | | |
| 11/22/00 | VW-1 | 2.17 | 75 | 0.58 | 09/26/2000* | <10,000 | <100.00 | 63,700 | <0.00626 | <0.00626 | <0.00006 | <0.00006 | 0.03987 | 0.03987 |
| 12/13/00 | VW-2 | 1.50 | 5 | 0.06 | 09/26/00 | <250 | <2.50 | 554 | <0.00001 | <0.00001 | 0.00000 | 0.00000 | 0.00002 | 0.00002 |
| Total Gallor | ns Extracte | ed: | 5,829 | | | Total Pour | nds Remove | d: | <1.266 | | <0.1067 | | 3.883 | |

Table 3 Groundwater Extraction Mass Removal Data

ARCO Service Station 6041 7249 Village Parkway, Dublin, California

Notes:

* = Concentrations inferred from closest monitoring well TPHg = Total petroleum hydrocarbons as gasoline MTBE = Methyl tertiary butyl ether ug/L = Micrograms per liter lbs = Pounds gpm = Gallons per minute

TPHg and benzene analyzed by EPA Method 8015/8020

MTBE analyzed by EPA Method 8020 or 8260 (if available)

Groundwater extracted by vacuum trucks provided by ACTI.

Concentrations based on the groundwater monitoring results from prior quarterly sampling event.

Table 4
Soil Vapor Extraction
Mass Removal Data

| Soil | Vapor E | xtraction Da | ıta | Hydroca | rbon Conce | ntrations | T | PHg Remov | val | Ben | zene Remo | oval | M' | ГВЕ Remo | val |
|------------|---------|--------------|--------|----------|---------------|-----------|------------|-----------|-----------|------------|-----------|-----------|------------|-----------|-----------|
| | | Vapor | System | | | | Mass | Mass | Mass | Mass | Mass | Mass | Mass | Mass | Mass |
| | | Extraction | Flow | | | | Extraction | Extracted | Extracted | Extraction | Extracted | Extracted | Extraction | Extracted | Extracted |
| Event | Well | Duration | Rate | TPHg | Benzene | MTBE | Rate | Per Event | To Date | Rate | Per Event | To Date | Rate | Per Event | To Date |
| Date | ID | (hours) | (scfm) | (Солсе | entrations in | ppmv) | (lbs/hour) | (lbs) | (lbs) | (lbs/hour) | (lbs) | (lbs) | (lbs/hour) | (lbs) | (lbs) |
| 11/22/00 | MW-1 | 3.08 | 9.4 | 3,660 | 161 | 253 | 0.459 | 1.415 | 1.415 | 0.018 | 0.056 | 0.056 | 0.032 | 0.100 | 0.100 |
| 12/13/00 | MW-1 | 3.25 | 7.7 | 2.979 | <0.0310 | < 0.111 | 0.000 | 0.001 | 1.416 | 0.000 | 0.000 | 0.056 | 0.000 | 0.000 | 0.100 |
| 01/30/01 | MW-1 | 1.50 | 9.7 | 9.6 | 0.11 | 0.58 | 0.001 | 0.002 | 1.418 | 0.000 | 0.000 | 0.056 | 0.000 | 0.000 | 0.100 |
| 03/20/01 | MW-1 | 3.50 | 4.3 | 9,780 | 176 | 453 | 0.561 | 1.963 | 3.381 | 0.009 | 0.032 | 0.089 | 0.027 | 0.093 | 0.193 |
| 11/22/00 | MW-3 | 2.00 | 8.1 | 3,462 | 119 | 333 | 0.375 | 0.750 | 0.750 | 0.012 | 0.023 | 0.023 | 0.037 | 0.074 | 0.074 |
| 12/13/00 | MW-3 | 3.00 | 5.2 | <2.838 | < 0.0310 | < 0.111 | 0.000 | 0.000 | 0.750 | 0.000 | 0.000 | 0.023 | 0.000 | 0.000 | 0.074 |
| 01/30/01 | MW-3 | 6.25 | 5.6 | 280 | 12 | 71 | 0.021 | 0.131 | 0.881 | 0.001 | 0.005 | 0.028 | 0.005 | 0.034 | 0.108 |
| 02/26/01 | MW-3 | 1.25 | 17.9 | <2.84 | < 0.0314 | 1.08 | 0.000 | 0.000 | 0.881 | 0.000 | 0.000 | 0.028 | 0.000 | 0.000 | 0.108 |
| 02/26/01 | TP-1 | 2.00 | 11.8 | 24.3 | 0.181 | 9.83 | 0.004 | 0.008 | 0.008 | 0.000 | 0.000 | 0.000 | 0.002 | 0.003 | 0.003 |
| 02/26/01 | TP-2 | 3.00 | 17.1 | 5.79 | <0.0314 | 9.16 | 0.001 | 0.004 | 0.004 | 0.000 | 0.000 | 0.000 | 0.002 | 0.006 | 0.006 |
| 11/22/00 | VW-1 | 2.17 | 22.0 | 653 | 19.5 | 21.8 | 0.192 | 0.417 | 0.417 | 0.005 | 0.011 | 0.011 | 0.007 | 0.014 | 0.014 |
| 12/13/00 | VW-2 | 1.50 | 23.0 | <2.838 | < 0.0310 | <0.111 | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 |
| Total Poun | ds Remo | ved: | | <u>.</u> | | | | 4.69 | | | 0.128 | | | 0.325 | |

Table 4 Soil Vapor Extraction Mass Removal Data

ARCO Service Station 6041 7249 Village Parkway, Dublin, California

Abbreviations and Notes:

TPHg = Total petroleum hydrocarbons as gasoline (C6-C12) by modified EPA Method 8015 in 1 liter tedlar bag samples

MTBE = Methyl tertiary butyl ether

cfm = Cubic feet per minute

ppmv = Parts per million by volume

lbs = Pounds

TPHG, Benzene, and MTBE analyzed by EPA Method 8015/8020 in 1 liter tedlar bag samples

TPHg / Benzene / MTBE Removal Rate = Based on Bay Area Air Quality Management District's Manual of Procedures for Soil Vapor Extraction dated July 17, 1991.

(Rate = Concentration (ppmv) x system flow rate (cfm) x (11b-mole/386ft3) x molecular weight (86 lb/lb-mole for TPHg, 78 lb/lb-mole for benzene, 88 lb/lb-mole for MTBE) x 60 min/hour x 1/1,000,000)

APPENDIX A SAMPLING AND ANALYSIS PROCEDURES

APPENDIX A

SAMPLING AND ANALYSIS PROCEDURES

The sampling and analysis procedures for water quality monitoring programs are contained in this appendix. The procedures provided for consistent and reproducible sampling methods, proper application of analytical methods, and accurate and precise analytical results. Finally, these procedures provided guidelines so that the overall objectives of the monitoring program were achieved.

The following documents have been used as guidelines for developing these procedures:

- Procedures Manual for Groundwater Monitoring at Solid Waste Disposal Facilities, Environmental Protection Agency (EPA)-530/SW-611, August 1977
- Resource Conservation and Recovery Act (RCRA) Groundwater Monitoring Technical Enforcement Guidance Document, Office of Solid Waste and Emergency Response (OSWER) 9950.1, September 1986
- Test Methods for Evaluating Solid Waste: Physical/Chemical Methods, EPA SW-846, 3rd edition, November 1986
- Methods for Organic Chemical Analysis of Municipal and Industrial Waste Water, EPA-600/4-82-057, July 1982
- Methods for Organic Chemical Analysis of Water and Wastes, EPA-600/4-79-020, revised March 1983
- Leaking Underground Fuel Tank (LUFT) Field Manual, California State Water Resources Control Board, revised October 1989

Sample Collection

Sample collection procedures include equipment cleaning, water level and total well depth measurements, and well purging and sampling.

Equipment Cleaning

Before the sampling event was started, equipment that was used to sample groundwater was disassembled and cleaned with detergent water and then rinsed with tap water. During field sampling, equipment surfaces that were placed in the well or came into

contact with groundwater during field sampling were washed with detergent and double rinsed with tap water before the next well was purged or sampled.

Water Level, Floating Hydrocarbon, and Total Well Depth Measurements

Before purging and sampling occurred, the depth to water, floating hydrocarbon thickness and total well depth were measured using an oil/water interface measuring system. The oil/water interface measuring system consists of a probe that emits a continuous audible tone when immersed in a nonconductive fluid, such as oil or gasoline and an intermittent tone when immersed in a conductive fluid, such as water. The floating hydrocarbon thickness and water level were measured by lowering the probe into the well. Liquid levels were recorded relative to the tone emitted at the groundwater surface. The sonic probe was decontaminated after each use. A bottom-filling, clear disposable bailer was used to verify floating hydrocarbon thickness measurements of less than 0.02 foot. Alternatively, an electric sounder and a bottom-filling Teflon bailer may have been used to record floating hydrocarbon thickness and depth to water.

The electric sounder is a transistorized instrument that uses a reel-mounted, two-conductor, coaxial cable that connects the control panel to the sensor. Cable markings are stamped at 1-foot intervals. The water level was measured by lowering the sensor into the monitoring well. A low-current circuit was completed when the sensor contacted the water, which served as an electrolyte. The current was amplified and fed into an indicator light and audible buzzer, signaling when water had been contacted. A sensitivity control compensated for highly saline or conductive water. The electric sounder was decontaminated after each use. The bailer was lowered to a point just below the liquid level, retrieved, and observed for floating hydrocarbon.

Liquid measurements were recorded to the nearest 0.01 foot on the depth to water/floating product survey form. The groundwater elevation at each monitoring well was calculated by subtracting the measured depth to water from the surveyed elevation of the top of the well casing. (Every attempt was made to measure depth to water for all wells on the same day.) Total well depth was then measured by lowering the sensor to the bottom of the well. Total well depth, used to calculate purge volumes and to determine whether the well screen was partially obstructed by silt, was recorded to the nearest 0.1 foot on the depth to water/floating product survey form.

Well Purging

If the depth to groundwater was above the top of screens of the monitoring wells, then the wells were purged, otherwise non-purge groundwater samples were collected. Before sampling occurred, a polyvinyl chloride (PVC) bailer, centrifugal pump, low-flow submersible pump, or disposable bailer was used to purge standing water in the casing and gravel pack from the monitoring well. In most monitoring wells, the amount of water purged before sampling was greater than or equal to three casing volumes. Some monitoring wells were expected to be evacuated to dryness after removing fewer than three casing volumes. These low-yield monitoring wells were allowed to recharge for up to 24 hours. Samples were obtained as soon as the monitoring wells recharged to a level

sufficient for sample collection. If insufficient water recharged after 24 hours, the monitoring well was recorded as dry for the sampling event.

Groundwater purged from the monitoring wells was transported in a 240-gallon truck-mounted tank to Integrated Waste Management's Milpitas storage facility for disposal.

Field measurements of pH, specific conductance, and temperature were recorded in a waterproof field logbook. Field data sheets were reviewed for completeness by the sampling coordinator after the sampling event was completed.

The pH, specific conductance, and temperature meter were calibrated each day before field activities were begun. The calibration was checked once each day to verify meter performance. Field meter calibrations were recorded on the water sample field data sheet.

Well Sampling

A disposable bailer was the only equipment acceptable for well sampling. When samples for volatile organic analysis were being collected, the flow of groundwater from the bailer was regulated to minimize turbulence and aeration. Glass bottles of at least 40-milliliters volume and fitted with Teflon-lined septa were used in sampling for volatile organics. These bottles were filled completely to prevent air from remaining in the bottle. A positive meniscus formed when the bottle was completely full. A convex Teflon septum was placed over the positive meniscus to eliminate air. After the bottle was capped, it was inverted and tapped to verify that it contained no air bubbles. The sample containers for other parameters were filled, filtered as required, and capped.

When required, dissolved concentrations of metals were determined using appropriate field filtration techniques. The sample was filtered by emptying the contents of the disposable bailer into a pressure transfer vessel. A disposable 0.45-micron acrylic copolymer filter was threaded onto the transfer vessel at the discharge point, and the vessel was sealed. Pressure was applied to the vessel with a hand pump and the filtrate directed into the appropriate containers. Each filter was used once and discarded.

Sample Preservation and Handling

The following section specifies sample containers, preservation methods, and sample handling procedures.

Sample Containers and Preservation

Sample containers vary with each type of analytical parameter. Container types and materials were selected to be nonreactive with the particular analytical parameter tested.

Sample Handling

Sample containers were labeled immediately prior to sample collection. Samples were kept cool with cold packs or ice until received by the laboratory. At the time of

sampling, each sample was logged on an ARCO chain-of-custody record that accompanied the sample to the laboratory. Samples that required overnight storage prior to shipping to the laboratory were kept cool (4°C) in a refrigerator.

Samples were transferred from Cambria to an ARCO-approved laboratory by courier or taken directly to the laboratory by the environmental sampler. Sample shipments from Cambria to laboratories performing the selected analyses routinely occurred within two to three days of sample collection.

Sample Documentation

The following procedures were used during sampling and analysis to provide chain-of-custody control during sample handling from collection through storage. Sample documentation included the use of the following:

- Water sample field data sheets to document sampling activities in the field
- Labels to identify individual samples
- Chain-of-custody record sheets for documenting possession and transfer of samples
- Laboratory analysis request sheets for documenting analyses to be performed

Field Logbook

In the field, the sampler recorded the following information on the water sample field data sheet (see Figure A-2) for each sample collected:

- Project number
- Client's name
- Location
- Name of sampler
- Date and time
- Well accessibility and integrity
- Pertinent well data (e.g., casing diameter, depth to water, well depth)

- Calculated and actual purge volumes
- Purging equipment used
- Sampling equipment used
- Appearance of each sample (e.g., color, turbidity, sediment)
- Results of field analyses (temperature, pH, specific conductance)
- General comments

The water sample field data sheet was signed by the sampler and reviewed by the sampling coordinator.

Labels

Sample labels contained the following information:

- Project number
- Sample number (i.e., well designation)
- Sample depth

- Sampler's initials
- Date and time of collection
- Type of preservation used (if any)

Sampling and Analysis Chain-of-Custody Record

The ARCO chain-of-custody record initiated at the time of sampling contained, at a minimum, the sample designation (including the depth at which the sample was collected), sample type, analytical request, date of sampling, and the name of the sampler. The record sheet was signed, timed, and dated by the sampler when transferring the samples. The number of custodians in the chain of possession was minimized. A copy of the ARCO chain-of-custody record was returned to Cambria with the analytical results.

Groundwater Sampling and Analysis Request Form


A groundwater sampling and analysis request form (see Figure A-3) was used to communicate to the environmental sampler the requirements of the monitoring event. At a minimum, the groundwater sampling and analysis request form included the following information:

- Date scheduled
- Site-specific instructions
- Specific analytical parameters

- Well number
- Well specifications (expected total depth, depth of water, and product thickness)

APPENDIX B

CERTIFIED ANALYTICAL REPORTS AND CHAIN-OF-CUSTODY DOCUMENTATION



5 February, 2001

Jason Olson Cambria - Oakland 1144 65th St. Suite C Oakland, CA 94608

RE: Arco Sequoia Report: W101682

Enclosed are the results of analyses for samples received by the laboratory on 30-Jan-01 13:35. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Charlie Westwater Project Manager

CA ELAP Certificate #1271



404 N. Wiget Lane Walnut Creek, CA 94598 (925) 988-9600 FAX (925) 988-9673 www.sequoialabs.com

Cumbria - Oakland 1144 65th St. Suite C Oakland CA, 94608

Project: Arco

Project Number: Arco # 6041 Project Manager: Jason Olson Reported: 05-Feb-01 07:43

ANALYTICAL REPORT FOR SAMPLES

| Sample ID | Laboratory ID | Matrix | Date Sampled | Date Received |
|-----------|---------------|--------|-----------------|-----------------|
| MW-1 | W101682-01 | Air | 30-Jan-01 09:30 | 30-Jan-01 13:35 |
| MW-3 | W101682-02 | Air | 30-Jan-01 12:30 | 30-Jan-01 13:35 |

Sequoia Analytical - Walnut Creek

Charlie Westwater, Project Manager

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Page 1 of 5





Cambria - Oakland 1144 65th St. Suite C Oakland CA, 94608

Project: Arco

Project Number: Arco # 6041 Project Manager: Jason Olson **Reported:** 05-Feb-01 07:43

Total Purgeable Hydrocarbons (C6-C12), BTEX and MTBE by DHS LUFT

| Sequoia | Analytical - | Walnut Creek |
|---------|--------------|--------------|
| | | |

| Analyte | Result | Reporting Limit | Units | Dilution | Batch | Prepared | Analyzed | Method | Notes |
|------------------------------|--------------------------|--------------------|-----------|----------|---------|-----------|-----------|----------|-------|
| MW-1 (W101682-01) Air | Sampled: 30-Jan-01 09:30 | Received: | 30-Jan-01 | 13:35 | | | | | P-02 |
| Purgeable Hydrocarbons | 34 | 10 | mg/m³ Air | 0.2 | 1B02015 | 31-Jan-01 | 31-Jan-01 | DHS LUFT | |
| Benzene | 0.35 | 0.10 | - 11 | ** | н | п | n n | ** | |
| Toluene | 0.18 | 0.10 | n n | ** | 11 | II . | п | | |
| Ethylbenzene | 0.78 | 0.10 | n | u | ** | н | ** | н | |
| Xylenes (total) | 0.93 | 0.10 | н | и | ** | ** | ** | ** | |
| Methyl tert-butyl ether | 2.1 | 0.50 | •• | п | ** | ** | " | ** | |
| Surrogate: a,a,a-Trifluoroto | oluene | 81.3 % | 70-1 | 30 | " | " | " | rr . | |
| MW-3 (W101682-02) Air | Sampled: 30-Jan-01 12:30 | Received: | 30-Jan-01 | 13:35 | | | | | P-02 |
| Purgeable Hydrocarbons | 1000 | 250 | mg/m³ Air | 5 | 1B02015 | 31-Jan-01 | 31-Jan-01 | DHS LUFT | |
| Benzene | 38 | 2.5 | - 11 | * | 11 | ш | п | ** | |
| Toluene | 59 | 2.5 | п | 11 | * | н | " | 17 | |
| Ethylbenzene | 14 | 2.5 | 14 | " | ** | ** | ** | ** | |
| Xylenes (total) | 66 | 2.5 | ** | 11 | н | 10 | It | | |
| Mathyl tert-butyl ether | 260 | 13 | | н | ** | " | " | п | |
| ogate: a,a,a-Trifluoroto | luene | 104 % | 70-1 | 30 | # | " | rr | п | |



Cambria - Oakland 1144 65th St. Suite C Oakland CA, 94608

Project: Arco

Project Number: Arco # 6041 Project Manager: Jason Olson **Reported:** 05-Feb-01 07:43

Total Purgeable Hydrocarbons (C6-C12) and BTEX in Air by DHS LUFT Sequoia Analytical - Walnut Creek

| Analyte | Result | Reporting Limit | Units | Dilution | Batch | Prepared | Analyzed | Method | Notes |
|-------------------------|--------------------------|--------------------|----------|----------|---------|-----------|-----------|----------|-------|
| MW-1 (W101682-01) Air | Sampled: 30-Jan-01 09:30 | Received: 3 | 0-Jan-01 | 13:35 | | | | | |
| Purgeable Hydrocarbons | 9.6 | 2.8 | ppmv | 1 | 1B02015 | 31-Jan-01 | 31-Jan-01 | DHS LUFT | |
| Benzene | 0.11 | 0.016 | " | II . | H | ** | н | ** | |
| Toluene | 0.048 | 0.013 | ** | II . | " | II . | # | er | |
| Ethylbenzene | 0.18 | 0.012 | н | н | 19 | 77 | н | п | |
| Xylenes (total) | 0.21 | 0.012 | ** | ** | n | Ħ | " | п | |
| Methyl tert-butyl ether | 0.58 | 0.14 | ** | ** | п | u | II. | п | |
| MW-3 (W101682-02) Air | Sampled: 30-Jan-01 12:30 | Received: 3 | 0-Jan-01 | 13:35 | | | | | |
| Purgeable Hydrocarbons | 280 | 2.8 | ppmv | 1 | 1B02015 | 31-Jan-01 | 31-Jan-01 | DHS LUFT | |
| Benzene | 12 | 0.016 | "" | п | ** | ** | ** | " | |
| Toluene | 16 | 0.013 | ** | 11 | ** | ** | 11 | ** | |
| Ethylbenzene | 3.2 | 0.012 | ** | h | 11 | Ħ | ** | H | |
| Xylenes (total) | 15 | 0.012 | н | 'n | ** | " | * | п | |
| Methyl tert-butyl ether | 71 | 0.14 | ** | ** | 10 | " | n n | п | |



cambria - Oakland 1144 65th St. Suite C Oakland CA, 94608 Project: Arco

Project Number: Arco # 6041 Project Manager: Jason Olson **Reported:** 05-Feb-01 07:43

Total Purgeable Hydrocarbons (C6-C12), BTEX and MTBE by DHS LUFT - Quality Control Sequoia Analytical - Walnut Creek

| Analyte | Result | Reporting Limit | | Spike Level | Source Result | %REC | %REC Limits | RPD | RPD Limit | Notes |
|-------------------------------------|--------|--------------------|-----------|----------------|------------------|------------|----------------|------|--------------|-------|
| Batch 1B02015 - EPA 5030B [P/T] | | | | | • | | | | • | |
| Blank (1B02015-BLK1) | | | | Prepared | & Analyz | ed: 31-Jan | -01 | ··· | | |
| Purgeable Hydrocarbons | ND | 10 | mg/m³ Air | <u></u> | <u> </u> | | | | | |
| Benzene | ND | 0.10 | u | | | | | | | |
| Toluene | ND | 0.10 | u | | | | | | | |
| Ethylbenzene | ND | 0.10 | п | | | | | | | |
| Xylenes (total) | ND | 0.10 | 11 | | | | | | | |
| Methyl tert-butyl ether | ND | 0.50 | 77 | | | | | | | |
| Surrogate: a,a,a-Trifluorotoluene | 5.38 | | " | 6.00 | | 89.7 | 70-130 | | | |
| LCS (1B02015-BS1) | | | | Prepared | & Analyze | ed: 31-Jan | -01 | | | Q-01 |
| Benzene | 2.48 | 0.10 | mg/m³ Air | 2.00 | | 124 | 70-130 | | | |
| Toluene | 2.50 | 0.10 | ** | 2.00 | | 125 | 70-130 | | | |
| Ethylbenzene | 2.80 | 0.10 | 77 | 2.00 | | 140 | 70-130 | | | |
| nes (total) | 8.36 | 0.10 | u | 6.00 | | 139 | 70-130 | | | |
| Surrogate: a,a,a-Trifluorotoluene | 5.08 | | " | 6.00 | | 84.7 | 70-130 | | * | |
| LCS Dup (1B02015-BSD1) | | | | Prepared | & Analyze | ed: 31-Jan | -01 | | | Q-01 |
| Benzene | 2.36 | 0.10 | mg/m³ Air | 2.00 | | 118 | 70-130 | 4.96 | 25 | |
| Toluene | 2.38 | 0.10 | ** | 2.00 | | 119 | 70-130 | 4.92 | 25 | |
| Ethylbenzene | 2.76 | 0.10 | ** | 2.00 | | 138 | 70-130 | 1.44 | 25 | |
| Xylenes (total) | 8.18 | 0.10 | " | 6.00 | | 136 | 70-130 | 2.18 | 25 | |
| Surrogate: a, a, a-Trifluorotoluene | 5.02 | | " | 6.00 | | 83,7 | 70-130 | | | |





Cambria - Oakland 1144 65th St. Suite C Oakland CA, 94608

P-02

Project: Arco

Project Number: Arco # 6041

Reported: 05-Feb-01 07:43

Project Manager: Jason Olson

Notes and Definitions

Chromatogram Pattern: Gasoline C6-C12 + Unidentified Hydrocarbons <C6

Q-01 The spike recovery for this QC sample is outside of established control limits. Review of associated batch QC indicates the

recovery for this analyte does not represent an out-of-control condition for the batch.

DET Analyte DETECTED

ND Analyte NOT DETECTED at or above the reporting limit

NR Not Reported

dry Sample results reported on a dry weight basis

RPD Relative Percent Difference



26 February, 2001

Jason Olson Cambria - Emeryville 6262 Hollis St. Emeryville, CA 94608

RE: Arco

Sequoia Report: MKB0502

Enclosed are the results of analyses for samples received by the laboratory on 02/14/01 19:35. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Jeff Smyly

Project Manager

CA ELAP Certificate #1210



885 Jarvis Drive Morgan Hill, CA 95037 (408) 776-9600 FAX (408) 782-6308 www.sequoialabs.com

Cambria - Emeryville

6262 Hollis St. Emeryville CA, 94608 Project: Arco

Project Number: Arco # 6041 Project Manager: Jason Olson **Reported:** 02/26/01 17:37

ANALYTICAL REPORT FOR SAMPLES

| Sample ID | Laboratory ID | Matrix | Date Sampled | Date Received |
|------------|---------------|--------|----------------|----------------|
| MW-1 | MKB0502-01 | Water | 02/09/01 08:46 | 02/14/01 19:35 |
| MW-2 | MKB0502-02 | Water | 02/09/01 09:07 | 02/14/01 19:35 |
| MW-3 | MKB0502-03 | Water | 02/09/01 09:30 | 02/14/01 19:35 |
| Shell MW-6 | MKB0502-04 | Water | 02/09/01 07:41 | 02/14/01 19:35 |
| Shell MW-7 | MKB0502-05 | Water | 02/09/01 07:41 | 02/14/01 19:35 |
| DUP | MKB0502-06 | Water | 02/09/01 00:00 | 02/14/01 19:35 |

Sequoia Analytical - Morgan Hill

Jeff Smyly, Project Manager

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.





6262 Hollis St.

Emeryville CA, 94608

Project: Arco

Project Number: Arco # 6041

Reported: Project Manager: Jason Olson 02/26/01 17:37

Total Purgeable Hydrocarbons (C6-C12), BTEX and MTBE by DHS LUFT Sequoia Analytical - Morgan Hill

| Analyte Result Limit Units Dilution Batch Prepared Analyzed Method MW-1 (MKB0502-01) Water Sampled: 02/09/01 08:46 Received: 02/14/01 19:35 Purgeable Hydrocarbons 2820 2500 ug/l 50 1821002 02/21/01 02/21/01 DHS LUFT Benzene 368 25.0 " | | | Reporting | v | | | | | | |
|---|----------------------------------|-------------------------|-----------|---------|----------|---------|----------|----------|----------|--------|
| Purgeable Hydrocarbons 2820 2500 ug/l 50 1B21002 02/21/01 02/21/01 DHS LUFT | Analyte | | | Units | Dilution | Batch | Prepared | Analyzed | Method | Notes |
| Benzene 368 25.0 " < | MW-1 (MKB0502-01) Water | Sampled: 02/09/01 08:46 | Received: | 02/14/0 | 1 19:35 | | | | | |
| Toluene ND 25.0 " <t< th=""><th>Purgeable Hydrocarbons</th><th>2820</th><th>2500</th><th>ug/l</th><th>50</th><th>1B21002</th><th>02/21/01</th><th>02/21/01</th><th>DHS LUFT</th><th>P-01</th></t<> | Purgeable Hydrocarbons | 2820 | 2500 | ug/l | 50 | 1B21002 | 02/21/01 | 02/21/01 | DHS LUFT | P-01 |
| Ethylbenzene 116 25.0 " | Benzene | 368 | 25.0 | " | 79 | U | 10 | II . | ¢) | |
| Name | Toluene | ND | 25.0 | " | tf | n | • | 11 | ** | |
| Methyl tert-butyl ether 23300 250 " 100 " " 02/22/01 " 02/22/01 " 02/22/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 " 02/21/01 DESTRICT CONTROL CON | Ethylbenzene | 116 | 25.0 | | u | " | IF | D | ** | |
| Surrogate: a,a,a-Trifluorotoluene 100 % 70-130 " " 02/21/01 " MW-2 (MKB0502-02) Water Sampled: 02/09/01 09:07 Received: 02/14/01 19:35 Purgeable Hydrocarbons ND 50.0 ug/l 1 1821002 02/21/01 02/21/01 02/21/01 DHS LUFT Benzene ND 0.500 " " " " " " " " " " " " " " " " " " | Xylenes (total) | 176 | 25.0 | n | ti ti | ** | 11 | " | Ħ | |
| MW-2 (MKB0502-02) Water Sampled: 02/09/01 09:07 Received: 02/14/01 19:35 Purgeable Hydrocarbons ND 50.0 ug/l 1 1821002 02/21/01 02/21/01 DHS LUFT Benzene ND 0.500 " | Methyl tert-butyl ether | 23300 | 250 | н | 100 | ** | 11 | 02/22/01 | н | M-03 |
| Purgeable Hydrocarbons ND 50.0 ug/l 1 1821002 02/21/01 02/21/01 DHS LUFT | Surrogate: a,a,a-Trifluorotoluen | ne | 100 % | 70- | -130 | " | " | 02/21/01 | ** | |
| Benzene ND 0.500 " < | MW-2 (MKB0502-02) Water | Sampled: 02/09/01 09:07 | Received: | 02/14/0 | 1 19:35 | | <u></u> | | | |
| Toluene | Purgeable Hydrocarbons | ND | 50.0 | ug/l | 1 | 1B21002 | 02/21/01 | 02/21/01 | DHS LUFT | |
| Ethylbenzene | | ND | 0.500 | н | ** | ** | * | 10 | п | |
| ND 0.500 " " " " " " " " " " " " " " | | ND | 0.500 | ** | ** | II . | ** | ** | n | |
| Methyl tert-butyl ether 9.11 2.50 " " " " " " " " " " " " " " " " " " " | Ethylbenzene | ND | 0.500 | ** | n | ц | u | * | '' | |
| Surrogate: a,a,a-Trifluorotoluene 107 % 70-130 " " " " " " " " MW-3 (MKB0502-03) Water Sampled: 02/09/01 09:30 Received: 02/14/01 19:35 Purgeable Hydrocarbons 29300 2500 ug/l 50 1B21002 02/21/01 02/21/01 DHS LUFT Benzene 2590 25.0 " " " " " " " " " " " " " " Toluene 3530 25.0 " " " " " " " " " " " " " " " " " " Ethylbenzene 440 25.0 " " " " " " " " " " " " " " Xylenes (total) 7080 25.0 " " " " " " " " " " " " " " " Methyl tert-butyl ether 85500 1250 500 " " 02/22/01 " 02/22/01 | Xylenes (total) | ND | 0.500 | # | n n | ii . | 4 | 11 | n | |
| MW-3 (MKB0502-03) Water Sampled: 02/09/01 09:30 Received: 02/14/01 19:35 Purgeable Hydrocarbons 29300 2500 ug/l 50 1B21002 02/21/01 02/21/01 DHS LUFT Benzene 2590 25.0 " " " " " " Toluene 3530 25.0 " " " " " " Ethylbenzene 440 25.0 " " " " " " " Xylenes (total) 7080 25.0 " " " " " " Methyl tert-butyl ether 85500 1250 " 500 " 02/22/01 " | Methyl tert-butyl ether | 9.11 | 2.50 | | н | | n | ч | и | |
| Purgeable Hydrocarbons 29300 2500 ug/l 50 lB21002 02/21/01 02/21/01 DHS LUFT Benzene 2590 25.0 " | Surrogate: a,a,a-Trifluorotoluen | e | 107 % | 70- | 130 | " | n | n | " | |
| Benzene 2590 25.0 " " " " " " " " " " " " " " " " " " " | MW-3 (MKB0502-03) Water | Sampled: 02/09/01 09:30 | Received: | 02/14/0 | 1 19:35 | | | | | |
| Toluene 3530 25.0 " < | Purgeable Hydrocarbons | 29300 | 2500 | ug/l | 50 | 1B21002 | 02/21/01 | 02/21/01 | DHS LUFT | , b-01 |
| Ethylbenzene 440 25.0 " " " " " " " " " " " " " " " " " " " | Benzene | 2590 | 25.0 | н | II . | * | 11 | n | ** | |
| Xylenes (total) 7080 25.0 " " " " " " Methyl tert-butyl ether 85500 1250 500 " " 02/22/01 " | Toluene | 3530 | 25.0 | , | · · | | п | * | ** | |
| Methyl tert-butyl ether 85500 1250 500 " " 02/22/01 " | Ethylbenzene | 440 | 25.0 | ** | u ' | ** | и . | H | ** | |
| | Xylenes (total) | 7080 | 25.0 | ** | n . | н | п | ** | •• | |
| Surrogate: a,a,a-Trifluorotoluene 97.8 % 70-130 " " 02/21/01 " | Methyl tert-butyl ether | 85500 | 1250 | | 500 | | | 02/22/01 | * | M-03 |
| | Surrogate: a,a,a-Trifluorotoluen | e | 97.8 % | 70- | 130 | rr | " | 02/21/01 | v | |



Project: Arco

6262 Hollis St. Emeryville CA, 94608 Project Number: Arco # 6041

Reported: 02/26/01 17:37


Project Manager: Jason Olson

Total Purgeable Hydrocarbons (C6-C12) RTF3

Total Purgeable Hydrocarbons (C6-C12), BTEX and MTBE by DHS LUFT Sequoia Analytical - Morgan Hill

| Analyte | Result | Reporting Limit | Units | Dilution | Batch | Prepared | Analyzed | Method | Notes |
|-----------------------------------|--------------------|--------------------|-----------|--------------|---------|----------|----------|----------|-------|
| Shell MW-6 (MKB0502-04) Water | Sampled: 02/09/01 | 07:41 Rec | eived: 02 | 2/14/01 19:3 | 35 | | | | |
| Purgeable Hydrocarbons | ND | 50.0 | ug/l | 1 | 1B22001 | 02/22/01 | 02/22/01 | DHS LUFT | |
| Вепzеле | ND | 0.500 | " | H | 11 | ıt | n . | n n | |
| Toluene | ND | 0.500 | n | н | II . | ıı | u u | | |
| Ethylbenzene | ND | 0.500 | н | H | 11 | и | n | " | |
| Xylenes (total) | ND | 0.500 | " | 11 | 15 | ii. | п | II . | |
| Methyl tert-butyl ether | ND | 2.50 | " | ** | ,, | " | n | 17 | |
| Surrogate: a,a,a-Trifluorotoluene | | 101 % | 70- | 130 | " | " | ,, | " | |
| Shell MW-7 (MKB0502-05) Water | Sampled: 02/09/01 | 07:41 Rec | eived: 02 | 2/14/01 19:3 | 35 | | | | |
| Purgeable Hydrocarbons | ND | 50.0 | ug/l | 1 | 1B21002 | 02/21/01 | 02/21/01 | DHS LUFT | |
| Benzene | ND | 0.500 | n | 11 | 1* | •• | ** | • | |
| Toluene | ND | 0.500 | . " | ш . | n | * | 10 | . н | |
| Ethylbenzene | ND | 0.500 | ** | n | 19 | | II | ** | |
| Xylenes (total) | ND | 0.500 | ** | " | 78 | " | " | ** | |
| Methyl tert-butyl ether | ND | 2.50 | ** | n | ** | 17 | н | ** | |
| Surrogate: a,a,a-Trifluorotoluene | | 105 % | 70- | 130 | " | " | " | " | |
| DUP (MKB0502-06) Water Sampl | ed: 02/09/01 00:00 | Received: 0 | 2/14/01 | 19:35 | | | | | |
| Purgeable Hydrocarbons | 3490 | 500 | ug/l | 10 | 1B22001 | 02/22/01 | 02/22/01 | DHS LUFT | P-01 |
| Benzene | 432 | 5.00 | п | ** | п | * | н | II | |
| Toluene | 9.56 | 5.00 | " | n | | ** | 4 | 11 | |
| Ethylbenzene | 146 | 5.00 | н | 11 | n | ** | It | и . | |
| Xylenes (total) | 235 | 5.00 | 11 | 10 | | ** | If | 11 | |
| Methyl tert-butyl ether | 31800 | 250 | " | 100 | U | It | 02/22/01 | | M-03 |
| Surrogate: a,a,a-Trifluorotoluene | | 92.1 % | 70- | 130 | ,, | <i>n</i> | 02/22/01 | # | |







6262 Hollis St.

Emeryville CA, 94608

Project: Arco

Project Number: Arco # 6041

Project Manager: Jason Olson

Reported:

02/26/01 17:37

MTBE Confirmation by EPA Method 8260A

Sequoia Analytical - Morgan Hill

| Analyte | Result | Reporting Limit | Units | Dilution | Batch | Prepared | Aлalyzęd | Method | Notes |
|----------------------------------|----------------------|--------------------|---------|----------|---------|----------|----------|-----------|-------|
| MW-3 (MKB0502-03) Water Sam | pled: 02/09/01 09:30 | Received: | 02/14/0 | 1 19:35 | | | | | |
| Methyl tert-butyl ether | 87700 | 2000 | ug/l | 2000 | 1B26012 | 02/23/01 | 02/23/01 | EPA 8260A | |
| Surrogate: 1,2-Dichloroethane-d4 | | 87.5 % | 70- | -130 | " | " | ır | " | |





Emeryville CA, 94608

Project: Arco

6262 Hollis St.

Project Number: Arco # 6041 Project Manager: Jason Olson **Reported:** 02/26/01 17:37

Total Purgeable Hydrocarbons (C6-C12), BTEX and MTBE by DHS LUFT - Quality Control Sequoia Analytical - Morgan Hill

| Analyte | Result | Reporting Limit | Units | Spike Level | Source Result | %REC | %REC Limits | - RPD | RPD Limit | Notes |
|-----------------------------------|--------|--------------------|--------|----------------|------------------|-------------|----------------|-------|--------------|-------|
| Batch 1B21002 - EPA 5030B [P/T] | | | | | | | | | | |
| Blank (1B21002-BLK1) | | | | Prepared | & Analyze | ed: 02/21/0 | 01 | ï | | |
| Purgeable Hydrocarbons | ND | 50.0 | ug/l | | | | | | | |
| Benzene | ND | 0.500 | " | | | | | | | |
| Toluene | ND | 0.500 | " | | | | | | | |
| Ethylbenzene | ND | 0.500 | " | | | | | | | |
| Xylenes (total) | ND | 0.500 | ** | | | | | | | |
| Methyl tert-butyl ether | ND | 2.50 | ** | | | | | | | |
| Surrogate: a,a,a-Trifluorotoluene | 11.4 | | | 10.0 | | 114 | 70-130 | | | |
| LCS (1B21002-BS1) | | | | Prepared | & Analyze | ed: 02/21/0 |) 1 | | | |
| Purgeable Hydrocarbons | 221 | 50.0 | ug/l | 250 | • | 88.4 | 70-130 | | • | |
| Surrogate: a,a,a-Trifluorotoluene | 10.6 | | п | 10.0 | | 106 | 70-130 | | | |
| Matrix Spike (1B21002-MS1) | Soi | ırce: MKB0: | 502-02 | Prepared | & Analyze | ed: 02/21/0 |)1 | | | |
| Purgeable Hydrocarbons | 201 | 50.0 | ug/l | 250 | ND | 80.4 | 60-140 | | | |
| Surrogate: a,a,a-Trifluorotoluene | 11.5 | | ır. | 10.0 | - | 115 | 70-130 | | | |
| Matrix Spike Dup (1B21002-MSD1) | Soi | ırce: MKB0: | 502-02 | Prepared | & Analyze | ed: 02/21/0 | 10 | | | |
| Purgeable Hydrocarbons | 203 | 50.0 | ug/l | 250 | ND | 81.2 | 60-140 | 0.990 | 25 | |
| Surrogate: a,u,a-Trifluorotoluene | 11.8 | | " | 10.0 | | 118 | 70-130 | | | |
| Batch 1B22001 - EPA 5030B [P/T] | | | | | | | | | | |
| Blank (1B22001-BLK1) | | | | Prepared | & Analyze | ed: 02/22/0 |)1 | | | |
| Purgeable Hydrocarbons | ND | 50.0 | ug/l | | | | | | | |
| Benzene | ND | 0.500 | " | | | | | | | |
| Toluene | ND | 0.500 | н | | | | | | | |
| Ethylbenzene | ND | 0.500 | н | | | | | | | |
| Xylenes (total) | ND | 0.500 | • | - | | | | | | |
| Methyl tert-butyl ether | ND | 2.50 | * | | | | | | | |
| Surrogate: a,a,a-Trifluorotoluene | 10.4 | | " | 10.0 | | 104 | 70-130 | | | |





Cambria - Emeryville

Project: Arco

6262 Hollis St. Emeryville CA, 94608 Project Number: Arco # 6041 Project Manager: Jason Olson **Reported:** 02/26/01 17:37

Total Purgeable Hydrocarbons (C6-C12), BTEX and MTBE by DHS LUFT - Quality Control Sequoia Analytical - Morgan Hill

| | | | Spike | Source | | %REC | | RPD | | |
|-----------------------------------|--------|-----------|--------|----------|-----------|-------------|--------|------|-------|-------|
| Analyte | Result | Limit | Units | Level | Result | %REC | Limits | RPD | Limit | Notes |
| Batch 1B22001 - EPA 5030B [P/T] | | | | | | | | | | |
| LCS (1B22001-BS1) | | | | Prepared | & Analyzi | ed: 02/22/0 | 01 | | | |
| Purgeable Hydrocarbons | 225 | 50.0 | ug/l | 250 | | 90.0 | 70-130 | | | •• |
| Surrogate: a,a,a-Trifluorotoluene | 9.08 | | " | 10.0 | | 90.8 | 70-130 | | | • |
| Matrix Spike (1B22001-MS1) | Sou | rce: MKB0 | 513-01 | Prepared | & Analyze | ed: 02/22/0 | 01 | | | |
| Purgeable Hydrocarbons | 236 | 50.0 | ug/l | 250 | ND | 94.4 | 60-140 | | | |
| Surrogate: a,a,a-Trifluorotoluene | 10.0 | | | 10.0 | | 100 | 70-130 | | | |
| Matrix Spike Dup (1B22001-MSD1) | Sou | rce: MKB0 | 513-01 | Prepared | & Analyze | ed: 02/22/0 | Οl | | | |
| Purgeable Hydrocarbons | 229 | 50.0 | ug/l | 250 | ND | 91.6 | 60-140 | 3.01 | 25 | |
| Surrogate: a,a,a-Trifluorotoluene | 9.38 | | " | 10.0 | | 93.8 | 70-130 | | | |



Cambria - Emeryville 6262 Hollis St. Emeryville CA, 94608

Surrogate: 1,2-Dichloroethane-d4

Project: Arco

Project Number: Arco # 6041 Project Manager: Jason Olson

Reported: 02/26/01 17:37

MTBE Confirmation by EPA Method 8260A - Quality Control Sequoia Analytical - Morgan Hill

| Analyte | Result | Reporting Limit | Units | Spike Level | Source Result | %REC | %REC Limits | - RPD | RPD Limit | Notes |
|----------------------------------|--------|--------------------|---------------|----------------|------------------|-------------|----------------|-------|--------------|-------|
| Batch 1B26012 - EPA 3510B | | | - | | | | | | | |
| Blank (1B26012-BLK1) | | | | Prepared | & Analyze | :d: 02/23/0 |)1 | | | |
| Methyl tert-butyl ether | ND | 1.00 | ug/l | | | | | | | |
| Surrogate: 1,2-Dichloroethane-d4 | 8.41 | - | # | 10.0 | | 84.1 | 70-130 | | | |
| LCS (1B26012-BS1) | | | | Prepared | & Analyze | :d: 02/23/0 |)1 | | | |
| Methyl tert-butyl ether | 11.9 | 1.00 | ug/l | 10.0 | | 119 | 70-130 | | | |
| Surrogate: 1,2-Dichloroethane-d4 | 9.48 | | | 10.0 | | 94.8 | 70-130 | | | |
| Matrix Spike (1B26012-MS1) | So | urce: MKB04 | 196-03 | Prepared | & Analyze | :d: 02/23/0 |)1 | | | |
| Methyl tert-butyl ether | 56.3 | 1.00 | ug/l | 10.0 | 45.4 | 109 | 70-130 | | | |
| Surrogate: 1,2-Dichloroethane-d4 | 8.96 | | " | 10.0 | | 89.6 | 70-130 | • | | |
| Matrix Spike Dup (1B26012-MSD1) | So | urce: MKB04 | 496-03 | Prepared | & Analyze | d: 02/23/0 |)1 | | | |
| Methyl tert-butyl ether | 54.9 | 1.00 | ug/l | 10.0 | 45.4 | 95.0 | 70-130 | 2.52 | 25 | |


10.0

8.72

70-130

87.2





Cambria - Emeryville

6262 Hollis St.

Emeryville CA, 94608

Project: Arco

Project Number: Arco # 6041

Project Manager: Jason Olson

Reported: 02/26/01 17:37

Notes and Definitions

M-03 Sample was analyzed at a second dilution.

P-01 Chromatogram Pattern: Gasoline C6-C12

DET Analyte DETECTED

ND Analyte NOT DETECTED at or above the reporting limit


NR Not Reported

dry Sample results reported on a dry weight basis

RPD Relative Percent Difference

| ARCO | Pro | 2ts rdi Atlantic | Compared Confield Conf | pany (| () | PATI | 18 | Task Or | der Nó. | | | h | AR. | # | a7 | 187 | . 00 | | | | | С | hain or Custody |
|--------------|---------------|---------------------|--|------------------|----------------|-------|----------|-------------|-------------------|----------------------|------------------------------|-------------------------------|---------------------------------|---------------------------------------|--------------|--------------|----------------|--------------------------|------------------------------------|--|---------------------------------------|-------------|--|
| ARCO Facil | ity no. 60 | 4-11 | | Cir (Fi | ty acility) | Dub | lin | | | Project (Consu | manag Itant) | er (| 12.21 | _< | ر آم | أمم | نع | 75 | | · (|)/c | ~~ | Laboratory name |
| ARCO engir | neer O. | 1 < | | 10 | | | Telephor | ne по. | 12 J 20 | Telepho | one no. | | 1.60 | 7 10 | , 2 2 | Fax | k no. | |) e i S u | | _ 0. | 21. 20.4 | Scamic |
| Consultant | name | | verte | /ι . Τ. | ch | | | Address | <u>, / 2 /</u> | 2 | 1 , | , /U-: | <u>4 26</u> C |) - / ` | 125 | <u></u> | | <u>")</u> | / () ' | 430. | _ 0. | 475 | Contract number |
| <u> </u> | MAGE | \ \ \ \ | Znv | | E (1/7 | | | Consulta | ni) <i>62 (</i> : | ; <u>~</u> _ | 1701 | $I_i \leq$ | د | . /- | | me |) (<i>)</i> ; | . <i> </i> | | | | I | Mathad of chiamont |
| | | | | Matrix | | Prese | rvation | உ | <u> </u> | | 17. S | 50 | | 38 | | | | VOA | 10.700 | r 1 | | ! | Wethod of Shipment |
| Sample I.D. | Lab no. | Container no. | Soil | Water | Other | Ice | Acid | Sampling da | Sampling tim | BTEX 602/EPA 8020 | BTEX/TPH P. F. EPA M602/8020 | TPH Modified 80 Gas Diesel | Oil and Grease 413.1 □ 413.2 | TPH EPA 418.1/SM5 | EPA 601/8010 | EPA 624/8240 | EPA 625/8270 | TCLP Ser Metals⊡ VOA⊡ | CAM METALS EPA 60 TTLC 3 STLC C | Lead Org./DHS Lead EPA 7420/7421 ⊡ | | | Laboratory name Segue, S Contract number Method of shipment Special detection Limit/reporting Lowes t |
| MW-1 | ļ | ۲ | | X | | X | X | 2-9-01 | 8:46 | | X | | | | | | | | | | | e i | Limit/reporting |
| mw-2 | | 4 | | X | | X | X | 2-9-01 | 9:07 | | 7 | | | | | | | | | | | v v | Lowest possible |
| MW-3 | | Ч | ļ | <u> </u> | | × | X | 7-9-01 | 9:30 | | X | | | | | | | | ļ | | | v3 | , , , , , , , |
| Shellm | t | 4 | | <u> </u> | | | X | 2-9-01 | 7:41 | | X | | | | | | | | | | | vy | Special QA/QC |
| Shellmh | 1 | Ц | | (| | * | X | 7-9-01 | 821 | | \checkmark | | _ | | | | | | | | | 55 | · |
| nye | | 4/ | <u> </u> | λ | | ^ | X | 2-9-0 | | | X | | | | | | | | | | | t/t | MKB0502 |
| | | | | | | | | | | | | | | | | | | | | | | | . Remarks |
| | | | | | | | | | | | | | | | | | - | | | | | | |
| | | | | | | | | | , | | | | | | | | | | | | | | · |
| | | | | | | | | | | | | | | | | | | | | | | | · |
| | | | | | | | | | | | | | | | | | : | | | | | | Lab number |
| | | | | | | | | | | | | | | | | | | | 1 | | | | Turnaround time |
| | | | | | | | | | | | | | | | | | | | | | | | Priority Rush 1 Business Day |
| Condition of | <u>'</u> | | | | | | | | | Tempe | rature r | eceive | i: | | | | | | | | · · · · · · · · · · · · · · · · · · · | | Rush |
| Relinquished | by samp | ller M. | | | | _ | Date | 2601 | Time 13⇔ | Receiv | red by | | Į. | 2 | | | ×7 | \geq | | _(| | | 2 Business Days |
| Relinquished | l by | Į. | | / , - | 2 | | Date | e601 | Time /3 00 | Receiv | ed by | 1 Le | Ru | 2 | · ., | | 2/12 | 3/13/ | | 2~ | | | Expedited 5 Business Days |
| quished | | leve | T | 92 | | | Date / | //4 | Time | | ed by | \$ | | ـــــــــــــــــــــــــــــــــــــ | | | Pate // | 1/0 | , 1 | Time 19 | 35 | | Slandard 10 Business Days |





March 01, 2001

Jason Olson Cambria Environmental - Emeryville 6262 Hollis Street Emeryville, CA 94608 RE: ARCO / P102646

Enclosed are the results of analyses for samples received by the laboratory on 02/27/01. If you have any questions concerning this report, please feel free to contact me.

Sincerely,


Angelee Cari

Client Services Representative

CA ELAP Certificate Number 2374

Angelee Cari





6262 Hollis Street Emeryville CA, 94608 Project: ARCO

Project Number: 6041 Project Manager: Jason Olson

Reported: 03/01/01 16:25

ANALYTICAL REPORT FOR SAMPLES


| Sample ID | Laboratory ID | Matrix | Date Sampled | Date Received |
|-----------|---------------|--------|----------------|----------------|
| TP-1 | P102646-01 | Air | 02/26/01 09:30 | 02/27/01 15:25 |
| TP-2 | P102646-02 | Air | 02/26/01 11:30 | 02/27/01 15:25 |
| MW-3 | P102646-03 | Air | 02/26/01 14:00 | 02/27/01 15:25 |



6262 Hollis Street Emeryville CA, 94608 Project: ARCO

Project Number: 6041 Project Manager: Jason Olson Reported: 03/01/01 16:25

| Analyte | Result | Reporting Limit | Units | Dilution | Batch | Prepared | Analyzed | Method | Notes |
|---------------------------------------|----------------|--------------------|-----------|----------|---------|----------|----------|--------------------|--------------|
| TP-1 (P102646-01) Air Sampled: 02/2 | 26/01 09:30 Re | ceived: 02/27 | /01 15:25 | 1 | | | | ` | |
| Gasoline (ppmv, MW 86.2) | 24.3 | 2.84 | ppmv | 0.2 | 1020723 | 02/28/01 | 02/28/01 | EPA 8015M/8020M | |
| Benzene (ppmv) | 0.181 | 0.0314 | N | ** | II . | n | 11 | | |
| Toluene (ppmv) | 0.502 | 0.0266 | ** | " | ч | tt | ** | • | |
| Ethylbenzene (ppmv) | 0.313 | 0.0230 | ** | | " | ** | •• | ** | |
| Xylenes (total) (ppmv) | 1.28 | 0.0230 | н | | н | н | •• | ** | |
| Methyl tert-butyl ether (ppmv) | 9.83 | 0.111 | n | " | н | II | | ** | |
| Gasoline | 85.7 | 10.0 | ug/l | " | ** | п | • | н | |
| Benzene | 0.579 | 0.100 | 11 | н | ** | п | " | II | |
| Toluene | 1.89 | 0.100 | II . | II | " | н | " | II . | |
| Ethylbenzene | 1.36 | 0.100 | н | п | | 11 | | D | |
| Xylenes (total) | 5.56 | 0.100 | н | 11 | | 11 | • | п | |
| Methyl tert-butyl ether | 35.4 | 0.500 | II . | II | " | ** | ** | II . | |
| Surrogate: a,a,a-Trifluorotoluene | | 99.7 % | 65- | 135 | " | n | " | * | |
| ogate: 4-Bromofluorobenzene | | 104 % | 65- | 135 | * | " | ** | " | |
| TP-2 (P102646-02) Air Sampled: 02/2 | 26/01 11:30 Re | ceived: 02/27. | /01 15:25 | ; | | | | | |
| Gasoline (ppmv, MW 86.2) | 5.79 | 2.84 | ppmv | 0.2 | 1020723 | 02/28/01 | 02/28/01 | EPA 8015M/8020M | |
| Benzene (ppmv) | ND | 0.0314 | | 4 | | Ħ | u | u | |
| Toluene (ppmv) | ND | 0.0266 | | • | • | N | 11 | • | |
| Ethylbenzene (ppmv) | 0.105 | 0.0230 | 14 | ** | " | 17 | li . | * | |
| Xylenes (total) (ppmv) | 0.134 | 0.0230 | H | *1 | " | 17 | II | н | |
| Methyl tert-butyl ether (ppmv) | 9.16 | 0.111 | 16 | " | | - 11 | ij | н | |
| Gasoline | 20.4 | 10.0 | ug/l | * | ** | " | H | 14 | |
| Benzene | ND | 0.100 | 10 | | н | " | 11 | π | |
| Toluene | ND | 0.100 | ** | n | P | ** | 11 | s# | |
| | 0.454 | 0.100 | | TT TT | n | ** | Н | и | |
| Ethylbenzene | | | | | * | ** | 11 | | |
| Ethylbenzene Xylenes (total) | 0.579 | 0.100 | ** | * | ** | | •• | | |
| · · · · · · · · · · · · · · · · · · · | | 0.100 0.500 | ** | H | H | ** | ,, | " | |
| Xylenes (total) | 0.579 | | | H | | | | 17 | |





6262 Hollis Street Emeryville CA, 94608 Project: ARCO

Project Number: 6041 Project Manager: Jason Olson Reported: 03/01/01 16:25

| Analyte | Result | Reporting Limit | Units | Dilution | Batch | Prepared | Analyzed | Method | Note |
|----------------------------------|-----------------------|--------------------|-----------|----------|---------|----------|----------|--------------------|------|
| MW-3 (P102646-03) Air San | npled: 02/26/01 14:00 | Received: 02/2 | 7/01 15:2 | 5 | | | | | |
| Gasoline (ppmv, MW 86.2) | ND | 2.84 | ppmv | 0.2 | 1020723 | 02/28/01 | 02/28/01 | EPA 8015M/8020M | |
| Benzene (ppmv) | ND | 0.0314 | " | " | ır | " | •• | " | |
| Toluene (ppmv) | 0.0588 | 0.0266 | ** | * | н | ** | 10 | • | |
| Ethylbenzene (ppmv) | ND | 0.0230 | н | ** | п | ** | | н | |
| Xylenes (total) (ppmv) | 0.131 | 0.0230 | н | | н | н | ** | " | |
| Methyl tert-butyl ether (ppmv) | 1.08 | 0.111 | n | " | n | II . | " | tt | |
| Gasoline | ND | 10.0 | ug/l | ** | " | II. | ** | и | |
| Benzene | ND | 0.100 | Ü | # | ** | н | | н | |
| Toluene | 0.221 | 0.100 | п | II . | " | 11 | " | 11 | |
| Ethylbenzene | ND | 0.100 | 11 | II | " | ** | н | 11 | |
| Xylenes (total) | 0.567 | 0.100 | 11 | и | ** | ** | n | ** | |
| Methyl tert-butyl ether | 3.87 | 0.500 | ** | " | 19 | * | II | 44 | |
| Surrogate: a,a,a-Trifluorotoluen | ie | 98.0 % | 65-1 | 135 | " | " | " | " | |
| rogate: 4-Bromofluorobenze | | 102 % | 65-1 | 135 | " | " | " | # | |






6262 Hollis Street Emeryville CA, 94608 Project: ARCO

Project Number: 6041
Project Manager: Jason Olson

Reported: 03/01/01 16:25

| Analyte | Result | Reporting Limit | Units | Spike Level | Source Result | %REC | %REC Limits | RPD | RPD Limit | Notes |
|-----------------------------------|--------|--------------------|-------|----------------|------------------|------------|----------------|------|--------------|--------|
| - | Neaun | Little | Onus | LCVCI | - INCOURT | /01/11/0 | Lannes | ND . | Lillia | 110165 |
| Batch 1020723 - EPA 5030, waters | | | | | | | | | | |
| Blank (1020723-BLK1) | | | | Prepared | & Analyz | ed: 02/28/ | 01 | | | |
| Gasoline | ND | 50.0 | ug/l | | | | | | | |
| Вепzепе | ND | 0.500 | ** | | | | | | | |
| Toluene | ND | 0.500 | н | | | | | | | |
| Ethylbenzene | ND | 0.500 | 11 | | | | | | | |
| Xylenes (total) | ND | 0.500 | ** | | | | | | | |
| Methyl tert-butyl ether | ND | 2.50 | 11 | | | | | | | |
| Surrogate: a,a,a-Trifluorotoluene | 296 | | " | 300 | | 98.7 | 65-135 | | | |
| Surrogate: 4-Bromofluorobenzene | 294 | | " | 300 | | 98.0 | 65-135 | | | |
| LCS (1020723-BS1) | | | | Prepared | & Analyz | ed: 02/28/ | 01 | | | |
| Gasoline | 2230 | 50.0 | ug/l | 2750 | | 81.1 | 65-135 | | | |
| nzene · | 34.3 | 0.500 | | 32.0 | | 107 | 65-135 | | | |
| <i>i</i> епе | 182 | 0.500 | • | 193 | | 94.3 | 65-135 | | | |
| Ethylbenzene | 40.0 | 0.500 | ** | 46.0 | | 87.0 | 65-135 | | | |
| Xylenes (total) | 201 | 0.500 | ** | 231 | | 87.0 | 65-135 | | | |
| Methyl tert-butyl ether | 61.9 | 2.50 | n | 52.0 | | 119 | 65-135 | | | |
| Surrogate: a,a,a-Trifluorotoluene | 333 | | " | 300 | | 111 | 65-135 | | | |
| Surrogate: 4-Bromofluorobenzene | 308 | | n | 300 | | 103 | 65-135 | | | |
| Matrix Spike (1020723-MS1) | Sou | rce: P10262 | 9-02 | Prepared | & Analyze | ed: 02/28/ | 01 | | | |
| Gasoline | 2310 | 50.0 | ug/l | 2750 | ND | 84.0 | 65-135 | | | |
| Benzene | 32.t | 0.500 | п | 32.0 | ND | 100 | 65-135 | | | |
| Toluene | 171 | 0.500 | n n | 193 | ND | 88.6 | 65-135 | | | |
| Ethylbenzene | 38.5 | 0.500 | п | 46.0 | ND | 83.7 | 65-135 | | | |
| Xylenes (total) | 191 | 0.500 | n n | 231 | ND | 82.7 | 65-135 | | | |
| Methyl tert-butyl ether | 59.2 | 2.50 | п | 52.0 | ND | 113 | 65-135 | | | |
| Surrogate: a,a,a-Trifluorotoluene | 309 | | " | 300 | | 103 | 65-135 | | | |
| Surrogate: 4-Bromofluorobenzene | 314 | | " | 300 | | 105 | 65-135 | | | |





6262 Hollis Street Emeryville CA, 94608 Project: ARCO

Project Number: 6041
Project Manager: Jason Olson

Reported: 03/01/01 16:25

| | Reporting | | | | Source | | %REC | | RPD | |
|-----------------------------------|-----------|-------------|------|----------|-----------|------------|--------|------|-------|-------|
| Analyte | Result | Limit Units | | Level | Result | %REC | Limits | RPD | Limit | Notes |
| Batch 1020723 - EPA 5030, waters | | | | | | | | | | |
| Matrix Spike Dup (1020723-MSD1) | Sour | rce: P10262 | 9-02 | Prepared | & Analyze | ed: 02/28/ | 01 | | | |
| Gasoline | 2310 | 50.0 | ug/l | 2750 | ND | 84.0 | 65-135 | 0 | 20 | |
| Benzene | 34.1 | 0.500 | ш | 32.0 | ND | 107 | 65-135 | 6.04 | 20 | |
| Тоіцепе | 189 | 0.500 | п | 193 | ND | 97.9 | 65-135 | 10.0 | 20 | |
| Ethylbenzene | 40.5 | 0.500 | н | 46.0 | ND | 88.0 | 65-135 | 5.06 | 20 | |
| Xylenes (total) | 207 | 0.500 | 11 | 231 | ND | 89.6 | 65-135 | 8.04 | 20 | |
| Methyl tert-butyl ether | 64.1 | 2.50 | ** | 52.0 | ND | 122 | 65-135 | 7.95 | 20 | |
| Surrogate: a,a,a-Trifluorotoluene | 335 | | " | 300 | | 112 | 65-135 | | | |
| Surrogate: 4-Bromofluorobenzene | 314 | | " | 300 | | 105 | 65-135 | | | |



1455 McDowell Blvd. North, Ste. D Petaluma, CA 94954 (707) 792-1865 FAX (707) 792-0342 www.sequoialabs.com

Cambria Environmental - Emeryville

6262 Hollis Street

Emeryville CA, 94608

Project: ARCO

Project Number: 6041

Project Manager: Jason Olson

Reported:

03/01/01 16:25

Notes and Definitions

DET Analyte DETECTED


ND Analyte NOT DETECTED at or above the reporting limit

NR Not Reported

dry Sample results reported on a dry weight basis

RPD Relative Percent Difference

| ARCO | | | | | ⇔ | | | Task O | rder No. | - | Z 7 | 18 | 7. | 00 |) | | | | | | | (| Chain of Custod | y |
|----------------|---------|---------------|------|------------|----------------|---------|---------------------------------------|--|---------------|--|---------------------------------|-------------------|-------------------------|------------------------|--------------|------------------|--------------|-----------------------------------|--------------------------------|--------------------------------------|----------------------|---|--------------------------------------|------|
| ARCO Facili | ty no. | 604 | // | Cit (Fi | ly acility) | DUB | 615 | | | Project (Consu | manaç | Jer J | A 50 | 2/1 | or | .50 | N | | | | | | Laboratory name | |
| ARCO engin | | PAU | | | LE | | Telephor | ie no. 7でが)ですり | -8871 | Telepho (Consu | one no | 10/4 | 50- | 829 | 1 | Fax | x no. | (51 | o)45 | 0-8 | 299 | 5 | SEQUOIA | |
| Consultant n | ame | CAI | nBR | 1.4 | | | | ne no. フェラン ユザブ Address (Consults | ant) // 4 | 16 | 5 1 | 57 | . * | c 0 | AK | AV | D,Ca | 9, 4 | 146 | 08 | | · | Contract number | |
| | | | | Matrix | | Prese | rvation | | | | 1 | | i | I | | | | | 10,7000 | | | | Method of shipment | |
| Sample I.D. | Lab 70. | Container no. | Şoil | Water | Other A1R | Ice | Acid | Sampling date | Sampling time | BTEX / # 602/6020 | BTEXTPH/79 7 EPA M60Z/8020/8 | TPH Modified 8015 | Oil and Grease 413.1 | TPH EPA 418.1/SM503 | EPA 601/8010 | EPA 624/8240 | EPA 625/8270 | TCLP Semi Metals □ VOA □ VOA [| CAM Metals EPA 60 TTLC STLC | Lead Org./DHS CLead EPA 7420/7421 | | | | |
| TP-1 | | | | | X | | | 2/26 | 9:30 | | X | P | 202 | 6 | H, | -0 | 7/ | | | | | | Special detection Limit/reporting | |
| TP-Z | • | | | | 1 | | | | 11:30 | ! | 1 | | , , | , | | | 2 | | | | | | LOWEST POSSIE | , LE |
| MW-3 | | | | | \checkmark | | | V | 2000 | | 1 | | | | | _ | 3 | | | | | | LOWEST POSSIE REPORT IN PPM/V | |
| | | | | | | • | | | | | | | | | | - | | | | | | | Special QA/QC | |
| | | | | | | | | | <u> </u> | | ļ | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | - | |
| | | | | | | | | | | | | | | | | _ | | | | | | | Remarks | |
| | | | | | | | | | | | | | | | | | | | | | | | TPH9, | |
| | | | | | | · · · · | | | | | | | | | | | | | | | | | BTEX, | |
| | | - | | | | | · · · · · · · · · · · · · · · · · · · | | | | | | | | | | | | | | | | MTBE | |
| | | | | | | | | | | | | | | | | | | | | | | ļ | | |
| | | | | | | | | | | | | | | | POLE | n C | ISTO | by s | ı | s int | | | Lab number | |
| - | | | | | | | | | | | | | | | | | | 1 | NO | INT | АСТ _2 | | Turnaround time | |
| | | | | | | | | | | | | | | 7,9 | OLA | IR 71 | MP | RAT | URE | Z | _ | | ر Priority Rush 1 Business Day | |
| Condition of | | | | | | | | | | Tempe | erature | receive | d: | | | · | | . | | | | | Rush | ט |
| Relinquistible | m | npler _ | | n | | | Date Z | 7/01 | 1320 | Rece | ved/by | رر | A | m | بع | _ | , | | | • | | | 2 Business Days | |
| Figlingvished | | · | | | | | Date | 77 | Time | Receiv | red by | | 7 | | | | | - | | | | | Expedited 5 Business Days | 风 |
| Relinquished | by | | | | | | Date | | Time | Receiv | ved by | laborato | эгу | | | Ċ | ate | • | | Time | | | Standard 10 Business Days | |





March 23, 2001

Ron Scheele Cambria Environmental - Oakland 1144 65th St., Suite C Oakland, CA 94608 RE: ARCO / P103468

Enclosed are the results of analyses for samples received by the laboratory on 03/21/01. If you have any questions concerning this report, please feel free to contact me.


Sincerely,


Angelee Cari

Client Services Representative

CA ELAP Certificate Number 2374

yele Cari






1144 65th St., Suite C Oakland CA, 94608 Project: ARCO


Project Number: 6041-Dublin Project Manager: Ron Scheele Reported:

03/23/01 16:52

ANALYTICAL REPORT FOR SAMPLES

| Sample ID | Laboratory ID | Matrix | Date Sampled | Date Received |
|-----------|---------------|--------|----------------|----------------|
| MW-1 | P103468-01 | Air | 03/20/01 09:15 | 03/21/01 15:49 |






1144 65th St., Suite C Oakland CA, 94608 Project: ARCO

Project Number: 6041-Dublin Project Manager: Ron Scheele Reported: 03/23/01 16:52

Total Petroleum Hydrocarbons as Gasoline and BTEX by EPA 8015M/8020M Sequoia Analytical - Petaluma


Reporting Analyzed Method Notes Analyte Result Limit Units Dilution Batch Prepared MW-1 (P103468-01) Air Sampled: 03/20/01 09:15 Received: 03/21/01 15:49 **EPA** 9780 1420 100 1030490 03/22/01 03/22/01 Gasoline ppmv 8015M/8020M Benzene 176 15.7 Toluene 15.8 13.3 QR-04 Ethylbenzene 50.7 11.5 Xylenes (total) 51.2 11.5 Methyl tert-butyl ether 453 55.6 Surrogate: a,a,a-Trifluorotoluene 110% 65-135 Surrogate: 4-Bromofluorobenzene 101 % 65-135




1144 65th St., Suite C Oakland CA, 94608 Project: ARCO

Project Number: 6041-Dublin Project Manager: Ron Scheele Reported: 03/23/01 16:52

| Analyte | Result | Reporting Limit | Units | Spike Level | Source Result | %REC | %REC Limits | RPD | RPD Limit | Notes |
|-----------------------------------|--------|--------------------|-------|----------------|------------------|-------------|----------------|-----|--------------|-------|
| | Result | Littit | Oma | 20101 | 100011 | 70.03.0 | | | | |
| Batch 1030490 - EPA 5030, waters | | | | | | | | | | |
| Blank (1030490-BLK1) | | | | Prepared . | & Analyze | ed: 03/21/0 | 01 | | | |
| Gasoline | ND | 14.2 | ppmv | | | | | | | |
| Benzene | ND | 0.157 | " | | | | | | | |
| Toluene | ND | 0.133 | II . | | | | | | | |
| Ethylbenzene | ND | 0.115 | п | | | | | | | |
| Xylenes (total) | ND | 0.115 | " | | | | | | | |
| Methyl tert-butyl ether | ND | 0.556 | и | | | | | | | |
| Surrogate: a,a,a-Trifluorotoluene | 55.3 | | " | 50.3 | | 110 | 65-135 | | | |
| Surrogate: 4-Bromofluorobenzene | 39.2 | | " | 41.9 | | 93.6 | 65-135 | | | |
| Blank (1030490-BLK2) | | | | Prepared | & Analyze | ed: 03/22/ | 01 | | | |
| Gasoline | ND | 14.2 | ppmv | | | | | | | |
| Benzene | ND | 0.157 | и | | | | | | | |
| Toluene | ND | 0.133 | н | | | | | | | |
| Ethylbenzene | ND | 0.115 | н | | | | | | | |
| Xylenes (total) | ND | 0.115 | * | | | | | | | |
| Methyl tert-butyl ether | ND | 0.556 | н | | | | | | | |
| Surrogate: a,a,a-Trifluorotoluene | 54.4 | | " | 50.3 | | 108 | 65-135 | | | |
| Surrogate: 4-Bromofluorobenzene | 42.0 | | н | 41.9 | | 100 | 65-135 | | | |
| LCS (1030490-BS1) | | | | Prepared | & Analyzo | ed: 03/21/ | 01 | | | |
| Gasoline | 733 | 14.2 | ppmv | 780 | | 94.0 | 65-135 | | | |
| Вепzепе | 13.2 | 0.157 | •• | 10.0 | | 132 | 65-135 | | | |
| Toluene | 55.9 | 0.133 | ** | 51.3 | | 109 | 65-135 | | | |
| Ethylbenzene | 11.8 | 0.115 | ** | 10.6 | | 111 | 65-135 | | | |
| Xylenes (total) | 59.5 | 0.115 | | 53.3 | | 112 | 65-135 | | | |
| Methyl tert-butyl ether | 16.2 | 0.556 | ** | 14.5 | | 112 | 65-135 | | | |
| Surrogate: a,a,a-Trifluorotoluene | 62.9 | | " | 50.3 | | 125 | 65-135 | . — | | |
| Surrogate: 4-Bromofluorobenzene | 42.7 | | # | 41.9 | | 102 | 65-135 | | | |





Cambria Environmental - Oakland 1144 65th St., Suite C


Oakland CA, 94608

Project ARCO
Project Number: 6041-Dublin
Project Manager: Ron Scheele

Reported: 03/23/01 16:52

| | | Reporting | | Spike | Source | | %REC | | RPD | |
|-----------------------------------|--------|-------------|-------|----------|-----------|------------|--------|-----|-------|-------|
| Analyte | Result | Limit | Units | Level | Result | %REC | Limits | RPD | Limit | Notes |
| Batch 1030490 - EPA 5030, waters | | | | | | | | | | |
| LCS (1030490-BS2) | | | | Prepared | & Analyze | ed: 03/22/ | 01 | | | |
| Gasoline | 640 | 14.2 | ppmv | 780 | | 82.1 | 65-135 | | | |
| Benzene | 10.5 | 0.157 | 11 | 10.0 | | 105 | 65-135 | | | |
| Toluene | 49.4 | 0.133 | 11 | 51.3 | | 96.3 | 65-135 | | | |
| Ethylbenzene | 10.5 | 0.115 | 44 | 10.6 | | 99.1 | 65-135 | | | |
| Xylenes (total) | 54.0 | 0.115 | 44 | 53.3 | | 101 | 65-135 | | | |
| Methyl tert-butyl ether | 16.1 | 0.556 | " | 14.5 | | 111 | 65-135 | | | |
| Surrogate: a,a,a-Trifluorotoluene | 59.5 | | " | 50.3 | | 118 | 65-135 | | | |
| Surrogate: 4-Bromofluorobenzene | 44.3 | | * | 41.9 | | 106 | 65-135 | | | |
| Matrix Spike (1030490-MS1) | Sou | rce: P10344 | 0-01 | Prepared | & Analyze | ed: 03/21/ | 01 | | | |
| Gasoline | 937 | 14.2 | ppmv | 780 | 174 | 97.8 | 65-135 | | | |
| Benzene | 25.1 | 0.157 | •• | 10.0 | 14.2 | 109 | 65-135 | | | |
| Toluene | 53.3 | 0.133 | ** | 51.3 | 2.53 | 99.0 | 65-135 | | | |
| Ethylbenzene | 11.7 | 0.115 | ** | 10.6 | ND | 110 | 65-135 | | | |
| Xylenes (total) | 73.7 | 0.115 | •• | 53.3 | 19.6 | 102 | 65-135 | | | |
| Methyl tert-butyl ether | 21.4 | 0.556 | 14 | 14.5 | 2.79 | 128 | 65-135 | | | |
| Surrogate: a,a,a-Trifluorotoluene | 57.8 | | " | 50.3 | | 115 | 65-135 | | | |
| Surrogate: 4-Bromofluorobenzene | 42.4 | | " | 41.9 | | 101 | 65-135 | | | |
| Matrix Spike (1030490-MS2) | Sou | rce: P10347 | 8-03 | Prepared | & Analyze | d: 03/22/ | 01 | | | |
| Gasoline | 611 | 14.2 | ppmv | 780 | ND | 78.3 | 65-135 | | | |
| Вепzепе | 9.94 | 0.157 | " | 10.0 | ND | 99.4 | 65-135 | | | |
| Toluene | 47.5 | 0.133 | ** | 51.3 | ND | 92.6 | 65-135 | | | |
| Ethylbenzene | 10.4 | 0.115 | 44 | 10.6 | ND | 98.1 | 65-135 | | | |
| Xylenes (total) | 52.6 | 0.115 | 11 | 53.3 | ND | 98.7 | 65-135 | | | |
| Methyl tert-butyl ether | 18.1 | 0.556 | 11 | 14.5 | ND | 125 | 65-135 | | | |
| Surrogate: a,a,a-Trifluorotoluene | 57.3 | | " | 50.3 | | 114 | 65-135 | | | |
| Surrogate: 4-Bromofluorobenzene | 43.4 | | " | 41.9 | | 104 | 65-135 | | | |






1144 65th St., Suite C Oakland CA, 94608 Project: ARCO

Project Number: 6041-Dublin Project Manager: Ron Scheele Reported: 03/23/01 16:52

| | | Reporting | | Spike | Source | ******* | %REC | 200 | RPD | Mass |
|-----------------------------------|--------|-------------|-------|----------|-----------|------------|--------|----------|-------|----------|
| Analyte | Result | Limit | Units | Level | Result | %REC | Limits | RPD | Limit | Notes |
| Batch 1030490 - EPA 5030, waters | | | | | | | | | | |
| Matrix Spike Dup (1030490-MSD1) | Sour | rce: P10344 | 0-01 | Prepared | & Analyze | ed: 03/21/ | 01 | <u>-</u> | | <u>.</u> |
| Gasoline | 799 | 14.2 | ppmv | 780 | 174 | 80.1 | 65-135 | 15.9 | 20 | |
| Benzene | 24.9 | 0.157 | ** | 10.0 | 14.2 | 107 | 65-135 | 0.800 | 20 | |
| Toluene | 52.2 | 0.133 | •• | 51.3 | 2.53 | 96.8 | 65-135 | 2.09 | 20 | |
| Ethylbenzene | 10.9 | 0.115 | * | 10.6 | ND | 103 | 65-135 | 7.08 | 20 | |
| Xyleπes (total) | 74.6 | 0.115 | " | 53.3 | 19.6 | 103 | 65-135 | 1.21 | 20 | |
| Methyl tert-butyl ether | 19.7 | 0.556 | ** | 14.5 | 2.79 | 117 | 65-135 | 8.27 | 20 | |
| Surrogate: a,a,a-Trifluorotoluene | 61.1 | | п | 50.3 | | 121 | 65-135 | | | |
| Surrogate: 4-Bromofluorobenzene | 40.9 | | " | 41.9 | | 97.6 | 65-135 | | | |
| Matrix Spike Dup (1030490-MSD2) | Sour | rce: P10347 | 8-03 | Prepared | & Analyze | ed: 03/22/ | 01 | | | |
| Gasoline | 628 | 14.2 | ppmv | 780 | ND | 80.5 | 65-135 | 2.74 | 20 | |
| Benzene | 9.95 | 0.157 | * | 10.0 | ND | 99.5 | 65-135 | 0.101 | 20 | |
| Toluene | 47.8 | 0.133 | ** | 51.3 | ND | 93.2 | 65-135 | 0.630 | 20 | |
| Ethylbenzene | 10.4 | 0.115 | ** | 10.6 | ND | 98.1 | 65-135 | 0 | 20 | |
| Xylenes (total) | 53.7 | 0.115 | •• | 53.3 | ND | 101 | 65-135 | 2.07 | 20 | |
| Methyl tert-butyl ether | 18.1 | 0.556 | ** | 14.5 | ND | 125 | 65-135 | 0 | 20 | |
| Surrogate: a,a,a-Trifluorotoluene | 56.6 | | " | 50.3 | | 113 | 65-135 | | | |
| Surrogate: 4-Bromofluorobenzene | 44.6 | | " | 41.9 | | 106 | 65-135 | | | |







1144 65th St., Suite C Oakland CA, 94608 Project: ARCO

Project Number: 6041-Dublin Project Manager: Ron Scheele Reported: 03/23/01 16:52

Notes and Definitions

QR-04 Results between the primary and confirmation columns varied by greater than 40% RPD.

DET Analyte DETECTED

ND Analyte NOT DETECTED at or above the reporting limit

NR Not Reported

dry Sample results reported on a dry weight basis

RPD Relative Percent Difference

| ARCO F | Pro- | is lantic | Comp Flichfield C | | | | | Task Or | | | | W. | 7 K. | # 87. | 0υ | , | | | | | | Chai | n / 🗀 | ustod | ly |
|--|--------------|---------------|----------------------|-----------------|---------------|-------|--------------------|---------------|---------------|---|-----------------------------|---------|------------|---------------------|------------|-------------------------|--------------|------------------------|--|--|--------------|--------------------------|--|-------|--------------|
| ARCO Facility ARCO engine Consultant na | <u></u> | <u> </u> | ple bri | | y acility) | Du | Telephon (ARCO) | 425-24 | (1-284) | Project (Consulted (Consulted (Co | ltant) one no. ltant) | 510 | <u>}on</u> | < 50- | 324 329 | ŧ c ∫α Fax i) (Cc | onsultan | 1) 5kg | <u> </u> | <u> 50 -</u> | 150n 8295 | Lab S Con | eratory name eg woi tract numbe | | |
| Sample I.D. | Lab no. | Container no. | Soil | Matrix Water | Other Air | Prese | rvation Acid | Sampling date | Sampling time | BTEX 602/EPA 8020 | ABE ME | | | | | EPA 624/8240 | EPA 625/8270 | TCLP Semi Netals⊒ VOA⊡ | CAM METALS EPA 6010/7000 TTLC STLC ST | Lead Org./DHS □ Lead EPA 7420/7421 □ | | | nod of shipm | | |
| MW-I | | 2 | | | × | PIB | 168-1 | 3-20-01 | 9115 | | × | | | | | | | | | | | Limi | cial detection treporting the est | Pusi | Si bie ts |
| | | | | | | | | | 200 | LED | CUST | on | e.H.A | LSI | T.A.C | T [| | | | | | Ren | narks PHS 3 TEX | | |
| | | | | | | | | | | LER | | | -N | OT IN | | | | (| A7 | <u> </u> | RB 18 | Turr | number naround time rity Rush usiness Day | | |
| Condition of s Relinquished Relinquished | by sam by | pler |) | | | | Date 3/2 Date Date | (| Time Time | Recei | erature yed by ved by | receive | d: - Ø | (h |) ~ | <u>~</u> | Date | 3/2 | 1/01 | Time | 1430 | Hus 2 B Exp 5 B | · | /s | X |

APPENDIX C FIELD DATA SHEETS

CAMBRIA

WELL DEPTH MEASUREMENTS

| Well ID | Time | Top of Screen | DTB | DTP | DTW | DOP | Casing Dia | Comments |
|---------------|------|------------------|-------|-----|-------|-----|---------------|--|
| MW-1 | 7:00 | 12' | 17.5' | | 10.65 | | 4'' | |
| MW-2 | 6:57 | 10' | 14.1' | | 8.50 | | 4" | |
| MW-3 | 6:58 | 11' | 14.7' | | 9.61 | | 4'' | |
| MW-4 | 6:55 | | | | 7.97 | | 4 % | |
| MW-5 | 6:50 | | | | 9.65 | | n " | |
| MW-6 | 6:53 | | | | 9.62 | | 4 " | |
| VW-2 | 7:02 | 4' | 9.0' | | 8.87 | | h " | |
| SHELL MW-6 | 6:40 | | 22.70 | | 9.05 | | 4 " | Wells Located at neighboring shell station |
| SHELL MW-7 | 6:45 | | 16.30 | | 6.39 | | h " | |
| | | | | | | | | |
| | į | | | | | | | |
| | | | | | | | | |
| | | | | | | | | : |
| | | | | | | | | |
| | | | | | | | | |

Project Name: **ARCO 6041_____** Project Number: **436-1610____**

Measured By:

CAMBRIA

Date: 2-5-01

| Project Name: ARCO 6041 | Cambria Mgr: Darryk Ataide | Well ID: MW-1 | | |
|----------------------------------|----------------------------|---------------------------|--|--|
| Project Number: 436 - 1610 | Date: 2-9-01 | Well Yield: | | |
| Site Address: 7249 Village Pkwy, | Sampling Method: | Well Diameter: "pvc | | |
| Dublin | Disposable bailer | Technician(s): 54 | | |
| Initial Depth to Water: 10.65 | Total Well Depth: 17.50 | Water Column Height: 6.85 | | |
| Volume/ft: 0-65 | 1 Casing Volume: 4.45 | 3 Casing Volumes: 13.35 | | |
| Purge/No Purge: pur 50 | | | | |
| Purging Device: Submersible Pump | Did Well Dewater?: 16 | Total Gallons Purged: 3 | | |
| Start Purge Time: 8:30 | Stop Purge Time: 7:40 | Total Time: Umins | | |

1 Casing Volume = Water column height x Volume/ ft.

| Well Diam. | Volume/ft (gallons |
|------------|--------------------|
| 2" | 0.16 |
| 4" | 0.65 |
| 6" | 1.47 |

| Time | Casing Volume | Temp. C | рН | Cond. uS | Comments |
|-------|------------------|------------|------|-------------|------------|
| 8:32 | L | 13.1 | 239 | 2139 | |
| 8: 35 | 8 | 12.7 | 7.85 | 1352 | |
| 8:40 | 12, | 13.5 | 7.81 | 1317 | |
| • | | | | | |
| | | , | | | |
| | | | | | 1-M- |
| | | | | | W- |
| | | | | | (). 58 ms/ |
| | | | | | 10 |

| Sample ID | Date | Time | Container Type | Preservative | Analytes | Analytic Method |
|-----------|--------|------|-------------------|--------------|------------------|-----------------|
| MW-3 | 2-9-01 | 8:46 | 4 VOA | HCL | TPHg, BTEX, MTBE | 8020 |
| D41' - | | | | | | |
| | | | | | | |

| Project Name: ARCO 6041 | Cambria Mgr: Darryk Ataide | Well ID: MW-2 | |
|-----------------------------------|---------------------------------------|---------------------------|--|
| Project Number: 436 - 1610 | Date: 2-9-01 | Well Yield: | |
| Site Address: 7249 Village Pkwy, | Sampling Method: | Well Diameter: "pvc | |
| Dublin | Disposable bailer | Technician(s): 56 | |
| Initial Depth to Water: 8.50 | Total Well Depth: 10 | Water Column Height: 5.60 | |
| Volume/ft: 0.65 | 1 Casing Volume: 3.64 | 3 Casing Volumes: 10.92 | |
| Purge/No Purge: purs- | | | |
| Purging Device: Submersible Pump | Did Well Dewater?: $\Lambda \upsilon$ | Total Gallons Purged: 1) | |
| Start Purge Time: 3:55 | Stop Purge Time: 9:01 | Total Time: 6 mins | |

1 Casing Volume = Water column height x Volume/ ft.

| Well Diam. | Volume/ft (gallons |
|------------|--------------------|
| 2" | 0.16 |
| 4" | 0.65 |
| 6" | 1.47 |

| Casing Volume | Temp. C | pН | Cond. uS | Comments |
|------------------|------------|------|-----------------------------------|---|
| 3 | 13.7 | 7.51 | 1315 | |
| | /3. 9 | 7.60 | 1242 | |
| | | | | |
| | | | | 00 5 |
| | | | | ().53 M5/, |
| | | | Volume C 3 /3.7 7.51 6 /3.5 7.85 | Volume C uS 3 /3.7 7.51 /3/5 6 /3.5 7.85 /2/7 |

| Sample ID | Date | Time | Container Type | Preservative | Analytes | Analytic Method |
|-----------|--------|------|-------------------|--------------|------------------|-----------------|
| MW-2 | 2-9-01 | 9:07 | 4 VOA | HCL | TPHg, BTEX, MTBE | 8020 |
| | | | | | | |

| Project Name: ARCO 6041 | Cambria Mgr: Darryk Ataide | Well ID: Mu-3 | | |
|----------------------------------|----------------------------|---------------------------|--|--|
| Project Number: 436 - 1610 | Date: 2-5-01 | Well Yield: | | |
| Site Address: 7249 Village Pkwy, | Sampling Method: | Well Diameter: "pvc | | |
| Dublin | Disposable bailer | Technician(s): 55 | | |
| Initial Depth to Water: G.61 | Total Well Depth: 14.70 | Water Column Height: 5.09 | | |
| Volume/ft: 0-65 | 1 Casing Volume: 3.30 | 3 Casing Volumes: 9.92 | | |
| Purge/No Purge: | | | | |
| Purging Device: Submersible Pump | Did Well Dewater?: 10 | Total Gallons Purged: 10 | | |
| Start Purge Time: 9:/8 | Stop Purge Time: 9: 24 | Total Time: /minc | | |

 Volume
 Volume/ft (gallons)

 1 Casing Volume = Water column height x Volume/ft.
 2" 0.16

 4" 0.65

 6" 1.47

| Time | Casing Volume | Temp. C | pН | Cond. uS | Comments |
|------|------------------|------------|------|-------------|----------|
| 9:20 | 3 | 13.0 | 7.08 | 1115 | |
| 9:22 | 6 | 13.5 | 7.21 | 972 | |
| 9:25 | 10 | 13.9 | 7.15 | 984 | |
| | | | | | |
| | | | | | |
| , | -, | | | | |
| | | **** | | | 1 00= |
| | | | | | 0.51mg/2 |
| | | | | | |

| Sample ID | Date | Time | Container Type | Preservative | Analytes | Analytic Method |
|-----------|--------|------|-------------------|--------------|------------------|-----------------|
| Mw-3 | 2-9-01 | 9:30 | 4 VOA | HCL | TPHg, BTEX, MTBE | 8020 |
| | | | | | | |
| | | | | | | |

| Project Name: ARCO 6041 | Cambria Mgr: Darryk Ataide | Well ID: Shell MU-6 |
|-----------------------------------|---------------------------------------|----------------------------|
| Project Number: 436 - 1610 | Date: 2-9-01 | Well Yield: |
| Site Address: 7249 Village Pkwy, | Sampling Method: | Well Diameter: "," pvc |
| Dublin | Disposable bailer | Technician(s): SG |
| Initial Depth to Water: 9-0 5 | Total Well Depth: 2270 | Water Column Height: 13.65 |
| Volume/ft: 0-65 | 1 Casing Volume: Q.77 | 3 Casing Volumes: 26.61 |
| Purge/No Purge: purge | · · · · · · · · · · · · · · · · · · · | |
| Purging Device: Submersible Pump | Did Well Dewater?: | Total Gallons Purged: 71 |
| Start Purge Time: 7:20 | Stop Purge Time: 7:35 | Total Time: /5mins |

 1 Casing Volume = Water column height x Volume/ft.
 Weil Diam.
 Volume/ft (gallons)

 1 Casing Volume = Water column height x Volume/ft.
 2" 0.16

 4" 0.65
 6" 1.47

| Time | Casing Volume | Temp. | рН | Cond. uS | Comments |
|-------|------------------|-------|------|-------------|----------|
| 7: 25 | 8 | 14.6 | 7.31 | 21/5 | |
| 7:30 | 16 | 14.9 | 7.59 | 1822 | |
| 7: 36 | 26 | 15.3 | 7.63 | 1751 | |
| _ | • | | | | Apple 4 |
| | . | | | | |
| | | | | | |
| | | | | | |
| | | | | | 1.29 mg/ |
| | | | |] | 12 |

| Sample ID | Date | Time | Container Type | Preservative | Analytes | Analytic Method |
|------------|--------|------|-------------------|--------------|------------------|-----------------|
| Shell mu-b | 2-8-01 | 7:41 | 4 VOA | HCL | TPHg, BTEX, MTBE | 8020 |
| | | | | | | |

| Project Name: ARCO 6041 | Cambria Mgr: Darryk Ataide | Well ID: Shell MW-7 |
|----------------------------------|----------------------------|---------------------------------|
| Project Number: 436 - 1610 | Date: 2-9-0 (| Well Yield: |
| Site Address: 7249 Village Pkwy, | Sampling Method: | Well Diameter: 4" pvc |
| Dublin | Disposable bailer | Technician(s): 5 4 |
| Initial Depth to Water: 6.39 | Total Well Depth: 16.30 | Water Column Height: 9.91 |
| Volume/ft: 0.65 | 1 Casing Volume: 6.44 | 3 Casing Volumes: 19.3 2 |
| Purge/No Purge: | | |
| Purging Device: Submersible Pump | Did Well Dewater?: n o | Total Gallons Purged: 49 |
| Start Purge Time: 7:55 | Stop Purge Time: 2:/0 | Total Time: 15 m/ns |

1 Casing Volume = Water column height x Volume/ ft.

| Well Diam. | Volume/ft (gallons |
|------------|--------------------|
| 2" | 0.16 |
| 4" | 0.65 |
| 6" | 1.47 |

| Time | Casing Volume | Temp. C | рH | Cond. uS | Comments |
|------|------------------|---------------------------------------|------|-------------|-----------|
| 7:59 | Ь | 15.4 | 7.50 | /3/2 | |
| 7:0≤ | /z | 15.1 | 7.59 | 1384 | |
| 8:11 | 19 | 14.8 | 7.51 | 1319 | |
| | | · · · · · · · · · · · · · · · · · · · | | | |
| | | | | | 4178444-7 |
| | | | | | |
| | | | | | 100= |
| | | | | | 1.13 ms/ |
| | <u> </u> | | | | |

| Sample ID | Date | Time | Container Type | Preservative | Analytes | Analytic Method |
|------------|----------|------|-------------------|--------------|------------------|-----------------|
| Shell Muiz | 02-09-01 | 3:21 | 4 VOA | HCL | TPHg, BTEX, MTBE | 8020 |
| | | | | | | |

| Project Name: ARCO 6041 | Cambria Mgr: Darryk Ataide | Well ID: VW-2 | |
|----------------------------------|----------------------------|-----------------------|--|
| Project Number: 436 - 1610 | Date: 2-8-0/ | Well Yield: | |
| Site Address: 7249 Village Pkwy, | Sampling Method: | Well Diameter: "pvc | |
| Dublin | Disposable bailer | Technician(s): 54 | |
| Initial Depth to Water: 9.77 | Total Well Depth: 9.00 | Water Column Height: | |
| Volume/ft: | 1 Casing Volume: | 3 Casing Volumes: | |
| Purge/No Purge: | A. | | |
| Purging Device: Submersible Pump | Did Well Dewater?: | Total Gallons Purged: | |
| Start Purge Time: | Stop Purge Time: | Total Time: | |

1 Casing Volume = Water column height x Volume/ ft.

| Well Diam. | Volume/ft (gallons) |
|------------|---------------------|
| 2" | 0.16 |
| 4" | 0.65 |
| 6" | 1 47 |

| Time | Casing Volume | Temp. C | pН | Cond. uS | Comments |
|------|------------------|------------|-------|-------------|----------|
| | | | | | |
| | | 1 +0 | • | | |
| | Insuffi | cent was | · | | |
| | | V 0 | Sampk | | |
| | | | | | |

| Sample ID | Date | Time | Container Type | Preservative | Analytes | Analytic Method |
|-----------|--------|------|-------------------|--------------|------------------|-----------------|
| VW-2 | 7-9-01 | | 4 VOA | HCL | TPHg, BTEX, MTBE | 8020 |
| | | | | | | |