

Ms. Jennifer Eberle Alameda County Health Care Services Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

work

Chevron 6:5:A. Products Company 2410 Camino Ramon San Ramon, CA 94583 P.O. Box 5004 San Ramon, CA 94583-0804

Marketing Department Phone 510 842 9500

Re:

Former Signal Service Station #S0800

5-20-96

800 Center Street Oakland, California

Dear Ms. Eberle:

Enclosed is a work plan prepared by our consultant Pacific Environmental Group, Inc. (Pacific), to investigate the soil/and groundwater conditions at the above referenced site. This work plan is prepared in accordance with a letter from the Alameda County Health Care Services agency and supplemental conversation with you by (Pacific). In the conversation between you and (Pacific) it was agreed that the work plan for site remediation would be prepared subsequent to this investigation.

To complete the delineation of petroleum hydrocarbons in the groundwater at the site, Chevron proposes to install a total of three groundwater monitoring wells and one optional well. Two wells are proposed to be installed west of the site across Center Street, one well to be installed northeasterly of the site and the optional well installed north of the site. This northerly well be installed initially as a boring and if hydrocarbon constituents are detected by a photo ionization detector, it will be converted into a monitoring well. Soil and water samples will be analyzed for TPPH-g and BTEX constituents. Groundwater will also be analyzed for dissolved oxygen, alkalinity, oxidation-reduction potential, sulfates, nitrates and ferrous iron. These last sample parameters, can be used for any future remediation/risk evaluation scenarios.

If you have any questions or comments, call me at (510) 842-9136.

Sincerely,

CHEVRON PRODUCTS COMPANY

Alter K Burs

Philip R. Briggs

Site Assessment and Remediation Project Manager

Enclosure

cc. Ms. B. C. Owen, Chevron

Mr. J. N. Robbins, Chevron



Ms. Jennifer Eberle July 10, 1996 Former Signal Service Station S800 Page 2

cc:

Mr. Terrell A. Sadler 618 Brooklyn Avenue Oakland, CA. 94606

Mr. James Scott BPH, Inc. 580 Market Street, Suite 400 San Francisco, CA. 94104

Ms. Sandi Nichols Washburn, Briscoe & McCarthy 55 Francisco Street, Suite 600 San Francisco, CA. 94133