

# PROTECTION

98 MAY -4 PM 4: 57

May 1, 1998

Alameda County Health Care Services Agency Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 Attn: Mr. Larry Seto Senior HMS

SUBJECT:

CASE CLOSURE SUMMARY; WEYERHAEUSER PAPER COMPANY, ALAMEDA CORRUGATED BOX FACILITY, 1801 HIBBARD ST., STID 1202

Dear Mr. Seto,

We have compiled the attached summary of information to assist you with the closure process for the Weyerhaeuser Paper Company site referenced above.

If you have any questions or require additional information please contact me at (707) 451-1360.

Sincerely,

Brennan Mahoney CPSS

Project Manager

West & Associates Environmental Engineers, Inc.

cc: James E. McCourt, Weyerhaeuser Office of the Environment, Tacoma

CASE CLOSURE SUMMARY
Leaking Underground Fuel Storage Tank Program

I. AGENCY INFORMATION Date: April 14, 1998

Agency name: Alameda County-HazMat Address: 1131 Harbor Bay Pkwy.

City/State/Zip: Alameda, CA 94502 Phone: (510) 567-6774

Responsible staff person: Larry Seto Title: Senior HMS

II. CASE INFORMATION

Site facility name: Weyerhaeuser Paper Company

Site facility address: 1801 Hibbard St., Alameda

RB LUSTIS Case No: Local Case No./LOP: STID 1202

URF filing date: Unknown SWEEPS No: N/A

Responsible Parties: Addresses: Phone Numbers:

Weyerhaeuser

Office of the Environment Tacoma, Washington 98477 (253) 924-6513

Tank No	<u>Size in Gallons</u>	Contents:	Closed in-place or Removed?	<u>Date</u>
	10,000	diesel	Removed	2/7/91
	1,000	waste oil	Removed	2/7/91
	1,000	gas	Removed	2/7/91
	1,000	gas	Removed	2/7/91
	20,000	diesel	Removed	1/13/94

### III. RELEASE AND SITE CHARACTERIZATION INFORMATION

Cause and type of release: UST leakage, gasoline & diesel fuel

Monitoring Wells installed? yes Number: 14 total,

6 removed, 8 remain

Site characterization complete? yes, 1/95

Date approved by oversight agency: 2/8/95

Proper screened interval? yes

Highest GW depth below ground surface: ~1.5' Lowest depth: ~7'

Flow direction: north

Most sensitive current use: Recharge to Oakland Inner Harbor

Are drinking water wells affected? No Aquifer Name: NA

Is surface water affected? No Nearest affected SW name: NA

Off-site beneficial use impacts (addresses/locations): Unknown

Reports(s) on file: Presented on following page

Where is report(s) filed? Alameda County 1131 Harbor Bay Pkwy

Alameda, CA 94502

# Reports on File with Alameda County:

UST Removal						
Workplan						
Preliminary Site Inv. Report						
Supplemental Site Inv. Report						
Quarterly Monitoring Report						
Additional Site Inv. Report						
Quarterly Monitoring Report						
Quarterly Monitoring Report						
Proposed Corrective Action Plan						
Proposed Site Assessment Workplan						
UST Closure Report						
Supplemental Site Inv. Workplan						
Report of Findings, Letter						
Site Inv. Rept. Former UGT Sites						
Quarterly Groundwater Mon. Report						
Quarterly Groundwater Mon. Report						
Proposed Remediation Workplan						
Quarterly Groundwater Mon. Report						
Remedial Action Report						
Quarterly Groundwater Mon. Report						
Soil Disposal Manifests						
Groundwater Sparge/Vapor Ext. Test						
Quarterly Groundwater Mon. Report						
Quarterly Groundwater Mon. Report						
Quarterly Groundwater Mon. Report						
Addendum to Quart. GW Mon. Report						
Quarterly Groundwater Mon. Report						
Quarterly Groundwater Mon. Report						
Quarterly Groundwater Mon. Report						
Quarterly Groundwater Mon. Report						
Quarterly Groundwater Mon. Report						

January 1991 October 15, 1991 January 20, 1992 May 18, 1992 August 10, 1992 January 28, 1993 April 13, 1993 July 19, 1993 November 1, 1993 November 1993 March 1994 May 9, 1994 October 1994 January 1995 May 1995 August 1995 September 1995 December 1995 January 1996 January 1996 March 1996 t April 1996 June 1996 October 1996 December 1996 February 1997 June 1997 March 1997 October 1997 December 1997 March 1998

Minter & Fahy Const. Soil Tech Engineering West & Associates West & Associates

Treatment and Disposal of Affected Material:

Material	Amount (include units)	Action (Treatment or Disposal/destination)	<u>Date</u>
petroleum oil	2,240 gal	Demenno Kerdoon, Compton CA	02/91
fuel, oil & water	8,500 gal	H & H Ship Service Company San Francisco, CA	04/91
diesel	4,600 gal	Refinery Services, Patterson, CA	01/94
oil & water	110 gal	P.R.C., Paterson, CA	06/93
soil	75 cu yds	Redwood Sanitary Landfill Novato, CA	02/94
soil	420 cu yds	BFI - Vasco Rd., Livermore, CA	11/95
soil	420 cu yds	Aerated on site/used as backfill 10	-11/95
UGT	4 tanks	Erickson, Inc.	02/91
UGT	1 tank	Erickson, Inc.	01/94

# III. RELEASE AND SITE CHARACTERIZATION INFORMATION Maximum Documented Contaminant Concentrations -- Before and After Cleanup

Contaminant	Soil (ppm) Before/After	Water (ppb) Before/After
TPH(g)	550/ND	42,000/2,370
TPH(d)	ND/ND	1,400/650
Benzene	0.56/ND	9,900/176
Toluene	1.0/ND	3,000/10.9
Ethylbenzene	1.5/ND	1,600/22.5
Xylenes	8.5/ND	4,100/20.9

Comments (Depth of Remediation, etc.): See "Additional Comments" section.

#### IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? yes

Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? yes

Does corrective action protect public health for current land use? yes

Site management requirements: none

Should corrective action be reviewed in land use changes? yes

List enforcement actions taken: none

List enforcement actions rescinded: none

### V. LOCAL AGENCY REPRESENTATIVE DATA

Name: Larry Seto Title: Senior HMS

Signature: Date:

Reviewed by

Name: Title: Hazardous Materials Specialist

Signature: Date:

Name: Thomas Peacock Title: Supervising HMS

Signature: Date:

VI. RWQCB NOTIFICATION

Date Submitted to RB: RB Response:

RWQCB Staff Name: Stephen Hill Title: Supervising Environ. Specialist

Date:

VII. ADDITIONAL COMMENTS, DATA, ETC.