

## REFER TO.

TO-435 ENV-5.00

# United States Department of the Interior

#### **BUREAU OF RECLAMATION**

Mid-Pacific Region Tracy Office (CVP) Route 1 Box 35 Byron, California 94514-9614



JAN 24 1995

Ms. Eva Chu Hazardous Material Specialist Alameda County Health Agency 1131 Harbor Bay Parkway Alameda, California 94502

Underground Storage Tank Removal -- Tracy Office -- Monitoring

Well Test Results -- Delta Division -- Central Valley Project (CVP)

CA

Enclosed are the test results for the monitoring of the subject project.

The next sampling is scheduled for March 1995.

If there are any questions, please contact Brian Shinmoto of my staff at (209) 836-6261.

Sincerely,

Elizabeth Partridge

Chief, Civil Engineering

Enclosure

Report Date: 01/05/95

Date Received: 12/30/94



U.S. Department of the Interior Sample Date: 12/28/94 Bureau of Reclamation

2800 Cottage Way, MP-470

Sacramento, California 95825-1898

Attn: QA Section

Page 1 of 1

Sample I.D. No: Tracy UST TMW004

APPL Sample No: R19160-17454W A-D Date Extracted: 01/03/95

### Test Results: \*\*

Compound	Concentration µg/L	Detection limit $\mu$ g/L
Benzene Ethylbenzene	ND*	0.5 0.5
Toluene Total Xylenes	ND ND	0.5 0.5
TPH-Gasoline	ND	20

#### ND = None Detected

Tested By

Checked By

<sup>\*\*</sup> B.T.E. & X. analyzed by EPA Method 8020 & 5030. TPH (Total Purgeable Hydrocarbons) analyzed by EPA Method 5030 and GC/FID.