



ENVIRONMENTAL BIO-SYSTEMS, INC.

Innovative Solutions for a Better Environment

March 23, 1990

Zaccor Corporation
791 Hamilton Avenue
Menlo Park, California 94025

Attention: Mr. Gary Zaccor

The following documentation concerns the initial tank removal sampling and assessment performed by Environmental Bio-Systems, Inc. for Zaccor Corporation, on March 1, 1990 at:

ALAMEDA CELLARS 2425 ENCINAL ALAMEDA, CALIFORNIA


On this date two 10,000 gallon gasoline tanks were removed. Subsequent sampling of surrounding soil within the tank pit excavation was performed in the presence of Inspector Katherine Chesick of the Alameda County Department of Environmental Health.

FIELD OBSERVATIONS

Tank A was constructed of single walled steel with a tar wrap that was approximately 70% intact at the time of removal. A visual inspection of the tank did not reveal any rusting, pitting or holes. The backfill material underlying the tank was stained and had a strong hydrocarbon odor.

Tank B was constructed of single walled steel and had a mostly intact tar wrap. No rusting, pitting or holes were noted upon inspection. Hydrocarbon staining and a strong hydrocarbon odor was noted in the backfill material and native soil underlying the tank.

Water was present in the southern corner of the tank pit at a depth of approximately 11.0 feet below grade upon removal of the tanks.



SAMPLING

Composite samples were collected from the approximate 75 cubic yards of stockpiled soil generated during tank removal procedures. These composite samples were designated as sample #1A-E and sample #4A-B.

At the discretion of Inspector Chesick, one soil sample was collected from the southeastern wall of the tank pit at a depth of 8.0 feet below grade (sample #2) and one soil sample (sample #3) was collected from the northeastern wall of the pit at a depth of 8.0 feet below grade. Sloughing of the walls of the tank pit disallowed the collection of interface samples and samples from the southwestern and northwestern walls of the pit..

SAMPLE ANALYSIS

All samples were analyzed for total petroleum hydrocarbons (TPH) as gasoline, benzene, toluene, xylenes, and ethylbenzene (BTX&E).

SAMPLING METHODOLOGY

Composite soil samples were collected from the stockpiled material in accordance with Bay Area Air Quality Management District (BAAQMD) guidelines.

Soil sample material from the tank pit was removed using a backhoe bucket. After removing the first 3 to 4 inches of soil just above the teeth of the bucket, presumably slough, samples were contained by driving clean brass tubes (1.92" x 6") into the exposed layer of soil. Soil was packed into the tubes to eliminate the possibility of headspace. Thus prepared, the ends of the tubes were wrapped with aluminum foil and sealed with plastic caps. After removing excess foil, electrical tape was applied to the seams between cap and tube in an effort to reduce the evaporative loss of volatile constituents.

The samples were placed in cooler on ice and transported under chain of custody documentation to Mobile Chem Labs, Inc., a certified hazardous materials testing laboratory (HMTL #289)

Analytical methods used by Mobile Chem Labs, Inc. were consistent with procedures presented in EPA document SW-846.

RESULTS

The certified analytical report documenting the findings of sample analyses has been attached to this report.

Composite sample #1A-E contained TPH as gasoline at a concentration of 770 parts per million (ppm), benzene at 9.7 ppm, toluene at 57 ppm, xylenes at 110 ppm, and ethylbenzene at 23 ppm.

Sample #2 contained TPH as gasoline at a concentration of 1,500 ppm, benzene at 15 ppm, toluene at 0.5 ppm, xylenes at 32 ppm, and ethylbenzene at 18 ppm.

Sample #3 contained TPH as gasoline at a concentration of 58 ppm, benzene at 0.3 ppm, toluene at 0.1 ppm, xylenes at 0.8 ppm, and ethylbenzene at 0.4 ppm.

Composite sample #4A-B contained TPH as gasoline at a concentration of 330 ppm, benzene at 5.0 ppm, toluene at 24 ppm, xylenes at 37 ppm, and ethylbenzene at 7.2 ppm.

RECOMMENDATIONS

The State Water Resources Control Board document, Leaking Underground Fuel Tank Field Manual (LUFT), supported by the San Francisco Regional Water Quality Control Board (SFRWQCB), defines acceptable limits and appropriate actions in dealing with tank removal and associated contamination.

The presence of fuel hydrocarbons in excess of 100 ppm in sample #2 necessitates further excavation of affected soils and a subsequent investigation of the impact of hydrocarbons on the shallow water bearing zone beneath the site. Excavation of soils containing concentrations of hydrocarbons in excess of 100 ppm should be performed until certified laboratory analysis confirms that acceptable levels have been attained or until additional excavation is no longer feasible.

In accordance with the LUFT manual, investigatory actions would include the installation of at least one groundwater monitoring well within ten feet of the former tank pit for the collection of groundwater quality data. Also in accordance with LUFT guidelines, a minimum of three groundwater reference points are necessary in order to determine groundwater flow direction beneath the site. This requirement may be satisfied by the installation of two additional groundwater reference points, either peizometers or wells. The three reference points will allow triangulation and subsequent determination of groundwater gradient. Properly installed and screened wells located on adjacent properties (if any) may qualify as eligible reference points.

Analytical results for sample #1A-E and #4A-B, the approximate 75 cubic yards of stockpiled material, indicate that this material contains concentrations of hydrocarbons which exceed acceptable limits for disposal at a class III landfill. We recommend, therefore, that this material be aerated on site in accordance with BAAQMD guidelines until residual levels of hydrocarbons have been diminished to acceptable levels for class III landfill disposal.

REPORTAGE

Copies of the sampling report, the chain of custody, and the certified analytical report should be submitted to the SFRWQCB, the Alameda County Water District, and the Alameda County Department of Environmental Health.

The following addresses have been listed for your convenience:

Water Quality Control Board San Francisco Bay Region 1800 Harrison Street Room 700 Oakland, CA 94612 ATTN: Fuel Leaks Division

Alameda County Water District P.O. Box 5110 43885 S. Grimmer Blvd. Fremont, CA 94537 ATTN: Linda Spencer

County of Alameda Department of Environmental Health Hazardous Materials Program 80 Swan Way, Room 200 Oakland, CA 94621 ATTN: Katherine Chesick

If you have any questions, or if I may be of service please contact me at (415) 429-9988.


Sincerely,

ENVIRONMENTAL BIO-SYSTEMS, INC.

Brenda D. McNabb Project Manager

Timothy M. Babcock Environmental Scientist

BDM



ZACCOR CORP. ©
ALAMEDA CELLARS
2425 ENCINAL AVE.
ALAMEDA,CA.
3/1/90



1678 Reliez Valley Road Lafayette, CA 94549 • (415) 945-1266

Environmental Bio-Systems 30028 Industrial Pkway. S.W. Hayward, CA 94544-6904

Attn: Timothy Babcock

Environmental Scientist

Date Sampled: 03-01-90 Date Received:03-01-90 Date Reported: 03-02-90

Sample Number

V030009

Sample Description

Alemeda Cellars - Alemeda

2425 Encinal

Comp 1 A-E SOIL


ANALYSIS

	Detection Limit	Sample Results
	Ppm	ppm
Total Petroleum Hydrocarbons as Gasoline	1.0	770
Benzene	0.1	9.7
Toluene	0.1	57
Xylenes	0.1	110
Ethylbenzene	0.1	23

Analysis was performed using EPA methods 5030 and TPH LUFT with method 8020 used for BTX distinction.

MOBILE CHEM LABS

Jupe a V Duskman.



1678 Reliez Valley Road Lafayette, CA 94549 • (415) 945-1266

Environmental Bio-Systems 30028 Industrial Pkway. S.W. Hayward, CA 94544-6904

Attn: Timothy Babcock

Environmental Scientist

Date Sampled: 03-01-90 Date Received: 03-01-90 Date Reported: 03-02-90

Sample Number

V030010

Sample Description

Alemeda Cellars - Alemeda

2425 Encinal

2 SOIL

ANALYSIS

	Detection Limit	Sample Results
	ppm	ppm
Total Petroleum Hydrocarbons as Gasoline	1.0	1,500
Benzene	0.1	15
Toluene	0.1	0.5
Xylenes	0.1	32
Ethylbenzene	0.1	18

Note: Analysis was performed using EPA methods 5030 and TPH LUFT with method 8020 used for BTX distinction.

MOBILE CHEM LABS



1678 Reliez Valley Road Lafayette, CA 94549 • (415) 945-1266

Environmental Bio-Systems 30028 Industrial Pkway. S.W. Hayward, CA 94544-6904

Attn: Timothy Babcock

Environmental Scientist

Date Sampled: 03-01-90 Date Received: 03-01-90 Date Reported: 03-02-90

Sample Number

V030011

Sample Description

Alemeda Cellars - Alemeda

2425 Encinal

3 SOIL

ANALYSIS

	Detection Limit	Sample Results
	ppm	ppm
Total Petroleum Hydrocarbons as Gasoline	1.0	58
Benzene	0.1	0.3
Toluene	0.1	0.1
Xylenes	0.1	0.8
Ethylbenzene	0.1	0.4

Note: Analysis was performed using EPA methods 5030 and TPH LUFT with method 8020 used for BTX distinction.

MOBILE CHEM LABS



1678 Reliez Valley Road Lafayette, CA 94549 • (415) 945-1266

Environmental Bio-Systems 30028 Industrial Pkway. S.W. Hayward, CA 94544-6904

Attn: Timothy Babcock

Environmental Scientist

Date Sampled: 03-01-90 Date Received: 03-01-90 Date Reported: 03-02-90

Sample Number

V030012

Sample Description

Alemeda Cellars - Alemeda

2425 Encinal

Comp # 4 A-B SOIL

ANALYSIS

	Detection Limit	Sample Results
	ppm	ppm
Total Petroleum Hydrocarbons as Gasoline	1.0	330
Benzene	0.1	5.0
Toluene	0.1	24
Xylenes	0.1	37
Ethylbenzene	0.1	7.2

Note: Analysis was performed using EPA methods 5030 and TPH LUFT with method 8020 used for BTX distinction.

MOBILE CHEM LABS

Opyce a V Dishman

ENVIRONMENTAL BIO-SYSTEMS, INC. 30028 INDUSTRIAL PKWY., S.W. MAYWARD, CA. 94544

(415) 429-9988

CHAIN OF CUSTODY

	SITE ADDRESS:	CLIENT:	
	Alaneda Cellaes	ZaccoR	(Crp.
	2425 Encival	EBS #: 003-10	3
	Alaneda, (A	DATE SAMPLED: 3	11,90
	LABORATORY: Probile Ch	en. IIMTL#: 28	9
.5	SAMPLE # MATRIX ANAL	YSIS	TURNAROUND
200099.	# IA-E Soil TPH	as Gasoline, B	TEX
10	#2		
10:11	#3		
mp!2	#4A-B 1	,	
,			
	Sampling Performed By	erela D. Mi	Malls
	Sampling Completed At	O_AMPM	
	Released By: Accepted Accepted		Time/Date
		in acyus -	3/1/90
			//
			/