SONNENSCHEIN NATH & ROSENTHAL

1301 K STREET NW

CHICAGO
LOS ANGELES
NEW YORK
SAN FRANCISCO
ST LOUIS

SUITE 600, EAST TOWER WASHINGTON, D.C. 20005

(202) 408-6400 FACSIMILE (202) 408-6399

John S. Hahn (202) 408-6430

September 22, 1994

HAZMAT 911 SEP 26 MIII: 55

VIA FEDERAL EXPRESS

Ms. Juliet Shin
Hazardous Materials Specialist
Alameda County Department of
Environmental Health
80 Swan Way, Room 200
Oakland, California 94621

Re: STID 3856; 1055 Eastshore Highway, Albany, CA

Dear Ms. Shin:

Enclosed is the Preliminary Site Assessment prepared for the above-referenced site.

Sincerely yours,

John S. Hahn

cc: John Frank (w/o enclosure)

George E. Lindsay, Jr. (w/enclosure)



AllWest Environmental, Inc.

Specialists in Environmental Due Diligence and Remedial Services

One Sutter Street, Suite 600 San Francisco, Ca 94104 Tel 415 391 2510 Fax 415 391 2008

Sey 1994 PRELIMINARY SITE ASSESSMENT

1055 Eastshore Highway Albany, California

ALLWEST PROJECT No. 93070.23

September 19, 1994

PREPARED BY:

Anibal Mata-Sol Project Geologist

REVIEWED BY:

Long Ching, P.E. Senior Engineer

2 1731

91, SEP 26 MIII



TABLE OF CONTENTS

I.	EXEC	CUTIVE SUMMARY	Page 1
п.	INTR	ODUCTION	Page 3
	A.	Site Location	Page 3
	B.	Background	Page 3
III.	SCOF	PE OF WORK	Page 5
IV.	UND	ERGROUND UTILITY CLEARING	Page 5
V.	FIEL	D INVESTIGATION	Page 6
	A.	Drilling of Soil Boreholes	Page 6
	B.	Soil Sampling Procedure	Page 6
	C.	Groundwater Monitoring Wells	Page 7
VI.	INVE	ESTIGATION FINDINGS	Page 7
	A.	Stratigraphy and Groundwater Depth	Page 7
VII.	CER	TIFIED ANALYTICAL RESULTS	Page 11
	A.	Soil Sampling Results	Page 12
	B.	Groundwater Sampling Results	Page 13
VIII.	DISC	CUSSION AND RECOMMENDATIONS	Page 14
IX.	REPO	ORT LIMITATIONS	Page 16

X. FIGURES

Figure 1 -Site Regional Map Figure 2 -Site Location Map

Figure 3 -Site Map

Figure 4 -Site Map Showing Soil Borings and Monitoring Well Locations

Figure 5 -Concentration of TPH in Site Soils

Figure 6 -Concentration of TPH in Site Groundwater

XI. APPENDICES

Appendix A - Field Procedures

Appendix B - Logs of Soil Boring and Well Sampling Appendix C - Laboratory Report and Chain-of-Custody



I. EXECUTIVE SUMMARY

AllWest conducted a preliminary site assessment at 1055 Eastshore Highway, Albany, California on June 23-24, 1994. The investigation consisted of drilling seven soil borings, including a slant boring, and converting three borings into groundwater monitoring wells. Monitoring well MW-1 was drilled 25 feet below the ground surface, MW-2 and MW-3 were drilled to a depth of 20 feet below the ground surface. The depth to groundwater at the site is approximately 6.4 feet below the ground surface (bgs).

A total of 14 soil and three groundwater samples were collected and forwarded to a state certified laboratory for chemical analyses. Laboratory tests revealed detectable concentrations of Total Petroleum Hydrocarbons as Gasoline (TPH-G), and gasoline constituents Benzene, Toluene, Ethylbenzene, and Total Xylenes (BTEX) in soil and groundwater.

Contaminated soil appears limited to the shallow soils overlying the soil/groundwater interface, between 4 and 6.5 feet bgs.

Soil sampling results demonstrate the levels of TPH-G and BTEX diminish considerably away from the immediate area of the former tank pit, indicating most contaminated soils were removed during over-excavation of the UST pit in September 1992.

The highest concentration of TPH-related compounds in groundwater was reported for MW-2, located within 10 feet south-southwest of the former tank pit. Low to non-detectable concentrations of contaminants were detected in MW-1 and MW-3, located hydraulically downgradient and upgradient respectively from the former UST. The results again demonstrate the levels of TPH-G and BTEX diminish significantly within a short distance from the former UST.

The groundwater flow direction was measured to the south-southeast and to the south at a gradient ranging from 0.009 ft/ft to 0.003 ft/ft, respectively.

The groundwater sampling results indicate that the contaminant plume appears to be confined to the immediate area of the tank. AllWest believes that based on the analytical results, the non-permeable nature of the soils, and the shallow hydraulic gradient of the groundwater, contamination is not likely to be spread beyond the immediate area of the former UST.

Based on the levels of TPH-G and BTEX detected at the site, further subsurface investigations are not warranted. AllWest recommends that the impacted soils exceeding 100 ppm TPH near SB-2 be excavated. Soils exceeding 100 ppm TPH will be identified either by field readings followed by confirmatory laboratory analyses or by an on-site field laboratory. AllWest also recommends that a quarterly groundwater sampling program be implemented for four quarters to assess contaminant degradation and reduction.

PRELIMINARY SITE ASSESSMENT

1055 Eastshore Highway Albany, California

II. INTRODUCTION

This report presents the results of preliminary site assessment conducted at 1055 Eastshore Highway, Albany, California. The purpose of this investigation was to delineate the extent to which residual Petroleum Hydrocarbon compounds have impacted the site's soils and groundwater. This subsurface investigation was conducted to meet the requirements mandated by the Alameda County Health Care Services Agency, Department of Environmental Health (ACDEH) in its letter of July 16, 1993.

A. Site location

The subject property lies in the western-most part of the City of Albany, California, amidst an industrial area. The site is located on the east side of Eastshore Highway, approximately 200 feet east of the Albany off-ramp from Interstate Highway 80. San Francisco Bay is located approximately 2,000 feet west of the subject property. Refer to Site Figures.

B. Background

On September 2, 1992 a 550-gallon gasoline tank and associated piping were removed from the subject property. AllWest Environmental provided consulting services associated with tank closure and documented its work in a October 30, 1992 closure report.

Regulatory oversight of tank closure activities was provided by Mr. Larry Seato, Environmental Health Specialist, of the Alameda County Department of Environmental Health (ACDEH) and Lieutenant Winding of the Albany Fire Department.

An underground storage tank unauthorized release (leak) contamination site report was completed upon receipt of analytical results and forwarded ACDEH on September 9, 1992.

Due to evidence of contamination near the tank pit, the pit was over-excavated in depth and areal extent on September 30, 1992. The pit was enlarged in a westerly and southerly direction and excavated to a depth of 10 feet.

The ACDEH mandated in a letter dated July 16, 1993 that a Preliminary Site Assessment be conducted at the subject site.

A Work Plan for Preliminary Site Assessment was prepared by AllWest in October 1993 and submitted to ACDEH. AllWest was notified that the Work Plan had been approved by ACDEH in a letter dated November 4, 1993.

III. SCOPE OF WORK

The scope of this subsurface investigation included the following tasks:

- Prepare site Work Plan and attain permits;
- Prepare site Health and Safety Plan;
- Retain a drilling contractor;
- Conduct utility scan for subsurface conduits;
- Drill four soil borings to approximately 10 feet below the surface, including one slant boring at the specific request of ACDEH;
- Drill three soil borings to approximately 20 feet below the ground surface and convert the borings into monitoring wells;
- Collect 14 soil and three groundwater samples;
- Deliver the samples to a state certified laboratory for appropriate chemical analysis;
- Analyze soil and groundwater samples for: Total Petroleum Hydrocarbons as Gasoline(EPA Method mod. 8015); and Volatile Hydrocarbons as Benzene, Ethylbenzene, Toluene, and Total Xylenes (BTEX);
- Prepare a Preliminary Site Assessment report

The purpose of this investigation was to delineate the extent to which residual Petroleum Hydrocarbon compounds have impacted the site's soils and groundwater.

IV. UNDERGROUND UTILITY CLEARING

To avoid damage to underground utility installations during the course of subsurface investigation, AllWest contacted *Underground Service Alert (USA)*, an organization for public utility information, on the pending subsurface investigation. *USA* then notified each of the public and private entities that maintained underground utilities at the site to locate and mark their installations for field identification. The notification number given to AllWest by *USA* was 194982.

In addition to notifying USA, AllWest also employed the services of a private underground locator to map any underground utilities existing at the site. No such utilities were detected by the locator.

V. FIELD INVESTIGATION AND SAMPLING

A. Drilling of Soil Boreholes

Prior to the commencement of field work, Ms. Juliet Shin of the ACDEH was notified to allow for agency inspection of drilling and/or sampling activities. A total of seven soil borings were advanced into the subsurface near the former UST. The soil boring locations are graphically depicted in Figure 4. The borehole drilling was performed by Soils Exploration Services, a drilling contractor with a valid C-57 license. The soil borings were drilled with 3.75-inch inside diameter (I.D.) hollow stem augers. During the drilling operation, a geologist from AllWest was present to collect representative soil samples, to conduct field screening, and to maintain a continuous log.

The boring logs contain all pertinent information on drilling and soil conditions, in particular the lithology of the soils and any Organic Vapor Meter readings measured during the subsurface investigation. Boring logs, the boring log legend, and the Unified Soil Classification System (USCS) are included as Appendix B.

B. Soil Sampling Procedures

Soil samples were collected at regular intervals and where changes to stratigraphy occurred. At a minimum, the sampling frequency was every 5 feet to the boring termination depth, typically between 10 and 20 feet below the ground surface.

Soil samples were obtained from within the borehole by advancing the boring to a point immediately above the sampling depth and driving a 2-inch split-spoon sampler (modified California sampler) into the soil through the hollow center of the drill auger. The soil sampler containing three separate six-inch brass sleeves were driven 18 inches with a standard 140 pound hammer repeatedly dropped from a height of 30 inches. The number of blows to drive the sampler each successive 6 inches was counted to evaluate the relative consistency of the soil.

Each soil sample was field screened with a photo-ionizing detector (PID) and readings of the PID, if any, were recorded on the boring logs. All soil samples were placed in 6-inch long by 2-inch diameter, pre-clean brass liners, capped at both ends with Teflon sheets and plastic end caps, sealed with inert silicon tape, labeled, and refrigerated for subsequent laboratory analyses.

C. Groundwater Monitoring Wells

Three soil borings were converted into groundwater monitoring wells after drilling and logging for subsurface soil strata was completed.

The monitoring wells were constructed with 2-inch inside-diameter PVC well casing with factory perforated 0.02" slot section as the well screen. A total of 20 feet of well screen was used for Monitoring Well One (MW-1), and 15-foot screen for MW-2, and MW-3. This provided a screen section of 14 feet below the soil/groundwater interface. The annular space between the well screen and the wall of the boring was back-filled with clean #3 Monterey sand to about one foot above the top of the screen section. A one-foot bentonite plug was then placed over the sand pack to provide a seal against surface water infiltration. The remaining space was then back-filled with cement grout. The top of the well casing was sealed with a locking water-tight cap and set in a traffic-grade "Christy" box for well head protection. The location of the monitoring wells is depicted in Figure 3. A graphic presentation of the well construction is included in Appendix B.

Well development was conducted on June 28, 1994 about 72 hours after the well installation to prevent damage to well packing and sealing materials. Well development was accomplished with combined surging and pumping method. Groundwater samples were collected approximately 24 hours after well development. Detailed descriptions on well development and groundwater sampling procedures are presented in Appendix A of this report. There was no product sheen observed on the groundwater surface. No fuel odor was noted in any of the well casings at the time of groundwater sampling. A copy of the groundwater sampling log is presented in Appendix B.

VI. INVESTIGATION FINDINGS

A. Stratigraphy and Groundwater Depth

The soil borings revealed the near surface soils, underlying the fill, were mostly dark brown to black organic sandy silts and silty sand with minor gravel. In general, the ground surface of the site was covered with asphalt or concrete pavement. Immediately beneath the asphalt/concrete pavement was a 2 feet thick soil fill layer consisting of sandy silt, and sandy silt with gravel. This is commonly known as the base rock. Native soil below the fill normally consisted of sandy silts interbedded with gravel and clay normally referred to as Bay Muds.

Four soil borings (SB-1 through SB-4) were advanced to a depth of 10 feet below the ground surface. SB-1 was advanced approximately 12 feet southeast of the former excavation. The soil underlying the base rock consisted of greyish black organic sandy silt of firm consistency. A silty sand layer was encountered at approximately 7 feet bgs. The sand layer was fine-grained, well graded, and of medium dense consistency. Moderate hydrocarbon odor was noted at the 5-foot level. The boring was terminated at 10 feet bgs.

SB-2 was advanced approximately 18 feet south-southeast of the former excavation. Soil underlying the base rock was an organic greyish black, well graded silty sand of loose consistency. Slight discoloration and moderate hydrocarbon odor was appreciable at the five-foot level. Underlying the silty sand a yellowish brown sand layer was encountered at approximately 7.5 feet bgs. The sand was fine grained, well graded, and of medium dense consistency. No odor was noted at the 10-foot level. The boring was terminated at 10 feet bgs.

SB-3 was advanced approximately 26 feet south of the former excavation. The soil underlying the base rock was a yellowish brown silty sand layer extending down to approximately 4 feet bgs. The sand was coarse-grained, well graded, and of loose consistency. Underlying the silty sand layer was an organic sandy silt layer extending down to approximately 7 feet bgs. The silt layer graded stiff. A yellowish brown silty sand layer was encountered below the silt layer. The sand layer was well-graded and fine-grained. The boring was terminated at 10 feet bgs. No hydrocarbon odor was detected at this boring.

SB-4 was a slant boring, advanced at the specific request of the Alameda County Department of Environmental Health. The boring was advanced through the former excavation at an angle of approximately 19-20° from vertical in an attempt to assess the presence/absence of contamination beneath the building. The excavation backfill consisted of well graded fine grained sand and gravel. At approximately 3.5 feet bgs a yellowish brown, fine grained sand with minor gravel was encountered. No soil discoloration was observed. Beneath the sand layer a sandy gravel layer was encountered. The sand was coarse grained, well graded, and brownish grey in color. The consistency of the sandy gravel layer was medium dense. Soil discoloration and moderate hydrocarbon odor was noted at the 10-foot level. The sandy gravel layer extended down to a depth of approximately 13 feet bgs. Below 13 feet a poorly graded fine grained sand with minor gravel layer was encountered. A gravel layer was encountered at a depth of 13.5 feet extending down to 14 feet bgs. The size of the gravel ranged from 6 to 14 mm in diameter, and the shape was subangular to rounded. The boring was terminated at 15 feet bgs.

MW-1 was drilled approximately 30 feet hydraulically downgradient from the former UST. At MW-1, the soil underlying the base rock was a dark brown silty clay stratum with minor fine-grained sand and gravel down to a depth of approximately 9 feet below the ground surface. Below the silty clay layer was a yellowish brown sandy silt and clay layer extending down to approximately 13 feet in depth. The sandy silt and sandy clay layer graded very stiff and was of medium plasticity. Underlying the sandy clay layer was a fine-grained sand layer of medium dense consistency extending to a depth of approximately 18 feet. A silty sand layer was encountered at approximately 18 feet. The first groundwater level was initially encountered at a depth of about 14 feet below the ground surface (bgs) during the drilling operation of MW-1. The soil conditions observed from the test borings agree with regional geologic features as described in the various geologic literature. MW-1 was terminated at a depth of 24 feet. For the location of monitoring wells, please refer to Figure 4.

MW-2 was drilled within 10 feet from the former tank in a hydraulically downgradient direction. The soil underlying the base rock was a greyish brown, well graded sand layer with minor gravel of loose consistency extending to a depth of approximately 7 feet bgs. Below the sand layer was a brownish grey silty clay layer of medium to high plasticity extending down to approximately 13.5 feet in depth. The clay layer graded very stiff. A silty sand layer of medium dense consistency was encountered below the silty clay layer. The sand was fine-grained. MW-2 was terminated at approximately 19 feet bgs. The first groundwater level was initially encountered at a depth of about 12 feet below the ground surface during the drilling operation of MW-2.

MW-3 was drilled approximately 24 feet upgradient from the former UST. The soil underlying the base rock was an organic greyish black sandy silt layer. The silt layer graded firm, and the plasticity was medium to high. The approximate gravel size was 5 millimeters. This silt layer extended to a depth of approximately 7 feet bgs. Underlying the silt layer a well graded yellowish brown fine-grained sand layer. The sand was of medium dense consistency. The sand layer extended to a depth of approximately 17.5 feet bgs. Underlying the sand layer was a well graded gravel and sand mixture of medium dense consistency. The gravel size was approximately 14 millimeters in diameter and having a subangular shape. The first groundwater level was initially encountered at a depth of about 15 feet below the ground surface during the drilling operation of MW-3. The boring was terminated at a depth of 19.5 feet bgs. The boring was plugged with two feet of bentonite, and the monitoring well was constructed afterward.

Groundwater measurements were taken on three different days to assess fluctuations. The different measurements taken during this subsurface investigation are tabulated on the following page:

TABLE 1. GROUNDWATER LEVEL MEASUREMENTS

Well Number and Measurement Date	Well Casing Elevation	Depth to Water (In feet)	Groundwater Elevation (Assumed Datum = 12 ')	Change Since Last Measurement (In feet)	Average Hydraulic Gradient
MW-1 6/28/94 6/29/94 7/20/94	6.62 feet	6,06 6.04 6.08	0.56 0.58 0.54	+ 0.02 -0.04	0.009 ft/ft SSE 0.004 ft/ft WNW 0.003 ft/ft S
MW-2 6/28/94 6/29/94 7/20/94	6.92 feet	6.26 6.34 6.33	0.66 0.58 0.59	-0.08 +0.01	0.009 ft/ft SSE 0.004 ft/ft WNW 0.003 ft/ft S
MW-3 6/28/94 6/29/94 7/20/94	7.02 feet	6,30 6,29 6,36	0.72 0.73 0.66	+0.01 -0.07	0.009 ft/ft SSE 0.004 ft/ft WNW 0.003 ft/ft S

The well heads were surveyed after the installation of the monitoring wells. The datum adopted to measure the well head elevation was an assumed datum of 12 feet. The hydraulic gradient was computed for three different occasions when groundwater level measurements were taken. The hydraulic gradient computed for site during this investigation were: 0.009 ft/ft to the south-southeast on June 28, 1994; 0.004 ft/ft to the west-northwest, and 0.003 ft/ft to the south on July 20, 1994.

VII. CERTIFIED ANALYTICAL RESULTS

A. Soil Sampling Results

A total of 14 soil samples were collected from the seven borings drilled at the site. Sampling was performed on June 24, 1994. The soil samples were forwarded to *California Laboratory Services* of Rancho Cordova, California, a state certified analytical laboratory. Analyses performed on each submitted soil sample included Total Petroleum Hydrocarbons as Gasoline (EPA Method mod. 8015); and Volatile Hydrocarbons as Benzene, Ethylbenzene, Toluene, and Total Xylenes (BTEX), EPA Method 8020.

Soil samples were collected from the 5, and the 10-foot level at each boring. Laboratory results revealed that the soils collected from the 5-foot level contained detectable concentrations of TPH-G, and BTEX. Only two samples collected at the 10'-level contained TPH-G and BTEX above the laboratory reporting limits.

The highest concentration of target compounds was reported from SB-2, advanced approximately 18 feet south-southeast of the former excavation. The concentration of petroleum hydrocarbons reported for SB-2 at the 5-foot level was: TPH-G at 2,000 ppm; Benzene at 5.90 ppm; Toluene at 74.0 ppm; Ethylbenzene at 63.0 ppm; and Total Xylenes at 360 ppm. The sample collected at the 10-foot level revealed non-detectable concentrations of TPH compounds.

The slant boring (SB-4), required the ACDEH, was drilled within 4 feet of the building at an angle of 19° from vertical. Soil sampling results from the 5-foot level revealed the following concentrations: TPH-G at 39 ppm; Benzene at 0.023 ppm; Toluene at 0.19 ppm; Ethylbenzene at 0.044 ppm; and Total Xylenes at 2.5 ppm. The only target compounds detected at the 10-foot level included: Benzene at 0.021 ppm; Ethylbenzene at 0.0085 ppm; and Total Xylenes at 0.019 ppm. The soil sampling results are graphically depicted in Figure 5.

All other sampling results from the 5, and 10-foot level indicated that the concentration of TPH-G and related compounds were below 15 ppm, with the exception of the sample collected from the 10'-level at MW-2 which revealed a concentration of 32 ppm.

The concentrations of target chemicals appear to diminish significantly from the former UST. No target contaminants were detected in the soil borings MW-1 and MW-3, respectively located hydraulically downgradient and upgradient from the former UST.

The analytical results for soil samples are tabulated on the following page and are graphically depicted in Figure 5. A copy of the laboratory report and chain-of-custody are presented in Appendix C of this report.

	TABLE 2 SOIL SAMPLING RESULTS June 28, 1994							
Sample ID	TPH-G	Benzene	Toluene	Ethylbenzene	Total Xylenes			
SB1-5'	14	0.33	0.013	0.70	0.85			
SB1-10'	ND	ND	ND	ND	ND			
SB2-5'	2,000	5.90	74.0	63.0	360			
SB2-10'	ND	ND	ND	ND	ND			
SB3-5'	5.5	ND	0.0081	0.029	0.078			
SB3-10'	ND	ND	ND	ND	ND			
SB4-5'	39	0.023	0.19	0.44	2.5			
SB4-10'	ND	0.021	ND	0.0085	0.019			
MW1-5'	ND	ND	ND	ND	ND			
MW1-10'	ND	ND	ND	ND	ND			
MW2-5'	ND	ND	ND	ND	ND			
MW2-10'	32	0.028	0.590	0.980	3.90			
MW3-5'	ND	ND	ND	ND	ND			
MW3-10'	ND	ND	ND	ND	ND			
Detection Limit	1.0 ppm	0.005 ppm	0.005 ppm	0.005 ppm	0.01 ppm			

Note: All concentrations reported in parts per million. mg/kg = ppm
ND = Not detected

B. Groundwater Sampling Results

The monitoring wells at the site were sampled on June 29, 1994, 24 hours after well development. For the sampling methodology employed, refer to Appendix A.

Three groundwater samples were collected. The samples were analyzed for Total Petroleum Hydrocarbons as Gasoline (EPA Method mod. 8015); and Volatile Hydrocarbons as Benzene, Ethylbenzene, Toluene, and Total Xylenes (BTEX), EPA Method 8020.

Groundwater sampling results indicated that the groundwater at the site has been impacted by low concentrations of TPH-G, and BTEX. The highest concentration of target chemicals reported by the analytical laboratory was detected in Monitoring Well-2 (MW-2). The laboratory reported 330 ppb for TPH-G, 130 ppb of Benzene, 11.0 ppb of Toluene, 20.0 ppb of Ethylbenzene, and 10.0 ppb of Total Xylenes. This well is located within 10 feet south-southwest of the former tank in hydraulically downgradient direction.

The analytical results of the groundwater samples are tabulated in Table 2 below, and the results are graphically depicted in Figure 6.

TABLE 3 GROUNDWATER SAMPLING RESULTS June 23-24, 1994							
Sample ID	TPH-G	Benzene	Toluene	Ethylbenzene	Total Xylenes		
MW-1A	ND	ND	0.60	2.5	9.0		
MW-2A	330	130	11.0	20.0	10.0		
MW-3A	52.0	ND	ND	4.0	13.0		
Detection Limit	50 ppb	0.30 ppb	0.30 ppb	0.30 ppb	0.60 ppb		

Note: All concentrations reported in parts per billion. $\mu g/L = ppb$

ND = Not Detected

VIII. DISCUSSION AND RECOMMENDATIONS

The soil sampling results indicate the target petroleum hydrocarbon compounds are confined to shallow depth, extending from approximately 4 to 6.5 feet bgs in an area immediately to the south and south-southeast of the former UST. This is corroborated by the sampling results from the 10-foot level from borings SB-1, SB-2, SB-3, MW-1, and MW-3 which revealed non-detectable concentrations of target compounds.

Soil sampling results collected from borings at the 5-foot level indicated that soils above the soil/groundwater interface have low concentrations of TPH-G and gasoline-related compounds. The highest concentrations of target compounds reported were for SB2-5', collected approximately 18 feet south-southeast of the former excavation. The analytical results revealed a concentration of TPH-G at 2,000 ppm, Benzene at 5.9 ppm, Toluene at 74.0 ppm, Ethylbenzene at 63.0 ppm, and Total Xylenes at 360.0 ppm.

The non-detectable levels of target compounds at the 10-foot level suggest that the hydrocarbon compounds reside in the unsaturated zone.

Results of samples collected during this preliminary site assessment indicate that the over-excavation of September 30, 1992 was successful in removing most of the contaminated soil. Based on the soil sampling results, we believe that further excavation of the site soils is only appropriate centered on SB-2 as the residual Petroleum Hydrocarbons in both soil and groundwater have been delineated.

AllWest recommends that the impacted soil exceeding 100 ppm TPH near SB-2 be excavated. Soils exceeding 100 ppm TPH will be indentified either by field readings followed by confirmatory laboratory analyses or by an on-site laboratory.

The soil sampling results from the slant boring revealed that at the 5-foot level the concentrations of target chemicals were as follow: TPH-G 39 ppm; Benzene at 0.023 ppm; Toluene at 0.19 ppm; Ethylbenzene at 0.0085 ppm; and Total Xylenes at 2.5 ppm. The low levels of gasoline-related compounds indicate that the soils beneath the building were only minimally impacted by the operation of the former UST.

AllWest believes that further subsurface investigations are unnecessary beneath the building as the levels of TPH-related compounds are below the guideline levels established by the Tri-Regional Board Staff, the site lithology indicates that the soils are of a non-permeable nature, and the low levels of TPH-related compounds do not pose a health threat to building occupants.

Groundwater analyses indicate that detectable concentrations of TPH-G, Benzene, Toluene, Ethylbenzene, and Total Xylenes are present in groundwater and diminish considerably beyond the immediate area of the former tank pit.

The groundwater contained a concentration of Benzene of 130 ppb in a monitoring well located within 10 feet from the former UST.


The groundwater flow direction was measured to the south-southeast with a gradient of 0.009 ft/ft on June 28, 1994, and to the south on July 20, 1994 with a gradient of 0.003 ft/ft. One measurement taken on June 29, 1994 revealed that the groundwater flow direction on that day was to the west-northwest with a hydraulic gradient of 0.004 ft/ft.

In addition to limited soil excavation, AllWest recommends that a quarterly groundwater sampling program be implemented for four quarters at the site to assess contaminant degradation and reduction.

IX. REPORT LIMITATIONS


The work described in this report is performed in accordance with generally accepted engineering principles and practices. The conclusions and recommendations contained in this report are made based on observed conditions existing at the site and on laboratory test results of the submitted soil samples. It must be recognized that changes can occur in soil conditions due to site use or other reasons. Furthermore, the distribution of chemical concentrations in the soil can vary spatially and over time. The results of chemical analysis are valid as of the date and at the sampling location only. AllWest cannot be held accountable for the accuracy of the test data from an independent laboratory nor for any analyte quantities falling below the recognized standard detection limits for the method utilized by the independent laboratory.

FIGURES



1055 East Shore Highway, Albany, California

Source **AllWest**







Vicinity Map

1055 East Shore Highway, Albany, California

Source Rand McNally








July 1994


Monitoring Well & Soil Boring Locations

Project 93070.23

Figure 4

1055 East Shore Highway, Albany, California Source AllWest





APPENDIX A

APPENDIX A

FIELD PROCEDURES

1. Drilling and Soil Sampling

An engineer from AllWest was present during drilling to assist in collecting relatively undisturbed samples of subsurface materials, to maintain logs of the boring, to make detailed observations of site conditions, and to provide technical assistance as required. All borings were advanced by a truck-mounted CME-75 drill rig equipped with 3.25-inch inside diameter hollow stem augers. Soil samples were collected at 5-foot intervals or where drilling conditions indicated a change in lithology.

Relatively undisturbed soil samples were obtained by driving a modified California sampler lined with brass tubes into the bottom of the bore hole with a 140-pound hammer falling 30 inches. The procedures used in obtaining soil samples are identical with the Standard Split Spoon Sampler (ASTM D-1786). When the sampler was withdrawn from the borings, the brass tubes containing the soil samples were removed, field examined, labeled, and sealed for later laboratory testing.

During field examination, the soil type, color, moisture condition, visible evidence of contamination, and other relevant data of the soil sample were noted and recorded in the field log. Soil types were classified according to the Unified Soil Classification System (ASTM D-2487). After field examination, the exposed ends of each brass tube were covered with 2-mil Teflon sheeting, fitted with plastic end caps, sealed with inert adhesive tapes, and then labeled. The sample label contained project number, boring number, sample number, depth, and sampling date.

Between each sample interval, the sampler was cleaned with a solution of Alconox (a non-phosphate detergent) and tap water, then double rinsed with distilled water, and reassembled with clean brass tubes. In addition, drilling and sampling equipment was steam cleaned between each boring to reduce the potential of cross contamination. All decontamination water generated from equipment cleaning and all drill cuttings generated from soil boring were contained in Department of Transportation (DOT) approved 55-gallon drums and stored on site for later disposal.

After sealing and labeling, collected soil samples were placed immediately in an ice chest cooled to 4°C with "blue ice" to preserve their chemical characteristics. At the conclusion of the drilling process, the soil sample from a depth immediately above the groundwater surface was randomly selected and submitted for testing. Samples selected for testing were delivered to a state certified analytical laboratory by a special courier on the same day of sampling. A chain-of-custody record form was maintained for all samples during travel to the laboratory.

2. Well Development and Groundwater Sampling

Well development was performed 24 hours after the installation of groundwater monitoring well. A combination of pumping and surging method was used for well development. Pumping was accomplished by an electric submersible pump and surging was performed in the same manner. Well development was considered complete after the discharged water during pumping stage was clear and free of sediment. All discharged water from well development were stored in 55-gallon drums for future disposal. Approximately 18 to 24 gallons of groundwater was removed from each well during well development process.

Groundwater sampling was conducted 24 hours after the well had been fully developed. Upon arrival at the well site, the conditions of well vault and well casing were first examined for any damage which may render the well inoperable. After the upper end-cap was removed, an electric water level sounder was lowered into the well casing to measure the water level depth to the nearest 0.01 feet. A clear teflon bailer was then lowered into the well casing and partially submerged. Upon retrieval of the clear bailer, the surface of the water column retained in the bailer was carefully examined for any floating product or product sheen.

After all initial measurements were completed and recorded, each well was purged by submersible pumps. At least five well volumes of groundwater was purged and the groundwater physical property indicators (temperature, pH, and conductivity) were monitored with a combination meter at each well volume interval. Purging was considered complete when indicators were stabilized and the purged water was relatively free of sediments. All purged water was temporarily stored on-site in 55-gallon drums awaiting test results to determine the proper disposal method.

Sampling was performed after the water level had been recovered to at least 80% of the initial level after purging. Groundwater samples were collected with disposable bailers. Upon retrieval of the disposable bailer, the retained water was carefully transferred to appropriate glassware furnished by the analytical laboratory. A special adopter at the bottom end of the bailer was used to minimize the loss of volatile organics during transfer. All sample containers were fitted with teflon lined septum/cap and filled such that no headspace was present. After the water sample had been properly transferred to the appropriate container, the container was labeled and immediately placed on ice to preserve its chemical characteristics.

To prevent cross contamination, all groundwater sampling equipment that came into contact with the groundwater were thoroughly cleaned by washing in an Alconox solution and rinsed with distilled water prior to each well sampling event. Samples were field stored and transported in an ice chest fitted with blue ice and/or ice that is capable of maintaining a 4°C temperature. After samples had arrived at the AllWest's office, they were rechecked and then placed in a refrigerator awaiting for special courier from the analytical laboratory. All samples were transported under proper chain of custody documentation.

APPENDIX B

UNIFIED SOIL CLASSIFICATION SYSTEM

PRIMARY DIVISIONS			GROUP SYMBOL	SECONDARY DIVISIONS
CO	GRAVELS	Clean gravels (less than 5% of fines)	GW	Well graded gravel-sand mixtures, little or no fines.
O A R	More than half of course fraction is		GP	Poorly graded gravels or gravel-sand mixtures, little or no fines.
S	larger than No. 4 sieve.	Gravel with fines	GM	Silty gravels or gravel-sand-silt mixtures, with non-plastic fines.
G R			GC	Clayey gravels or gravel-sand-clay mixtures, with plastic fines.
A I N	SANDS	Clean sands (less than 5% of fines)	sw	Well graded sands or gravelly sands, little or no fines.
E D	More than half of course fraction is		SP	Poorly graded sands or gravelly sands, little or no fines.
S O	smaller than No. 4 sieve.	Sands with fines	SM	Silty sands or sand-silt mixtures, with non- plastic fines.
Ĺ			SC	Clayey sands or sand-clay mixtures, with plastic fines.
F	SILTS AND CLAYS		ML	Inorganic silts and very fine sands, rock flour, or clayey silts, with slight plasticity.
N E	Liquid Limit less than 50	0%	CL	Inorganic clays of low to medium plasticity, gravelly clays, sandy clays, silty clays, lean clays.
G R D			OL	Organic silts and organic silty clays of low plasticity.
N E D	SILTS AND CLAYS		мн	Inorganic silts, micaceous or diatomaceous fine sandy or silty soils, elastic silts.
\$ O	Liquid Limit greater than	1 50%	СН	Inorganic clays of high plasticity, fat clays.
ال _ (ОН	Organic clays of medium to high plasticity, organic silts.
Н	IIGHLY ORGANIC SOILS		PT	Peat and other highly organic soils.

BORING LOG LEGEND

Sampling Interval Relatively Undisturbed Sample Collected and Preserved

Sampler Driven, Sample Not Collected Disturbed Sample Collected and Preserved



	PRIMARY DIVISORS			SECONDARY DIVISORS
c	STATELS	Cleen gravels	~	Tell graded gravels-sand mistures little or no fines.
o A	HORE TRAF BALF OF	(less then 3% fines)	e 7	Poorly graded gravels or gravel- east mixtures, little or no fines.
1	COURSE PRACTION IS LARGES THAN NO. 4 SIEVE.	Gravel	ent.	Filty gravels, gravel-sand-silt mixtures, sem-plantic fixes.
g R		with fines	\$ 6	Glayey gravels, gravel-send-elay mixtures, plastic fines.
1 2 2	EATHS.	Cleam cands (less than	##	Vell graded cands, gravelly sands little or no fines.
	MORE TRAN RALY OF CODESE PRACTICE	SE Zines)	57	Poorly graded sands or gravelly sands, little or so fines.
e I	IS SWALLER TRANS NO. 4 SIEVE.	Sands with fines	FX	filty sands, sand-silt Biktures, non-plastic fines.
\$	ļ		sc	Cleyey wards, sand-aley mixtures, plastic fines.
<u>.</u>	EILTE AND C	LATS)CL	Inorganic silts and very fine sands, took flour silty or clayer fine sands or clayer silts with slight plessicity.
I I I	LIGHT THAT S		6.T	Inorganic clays of low to modium plasticity, gravelly clays, sandy clays, silty clays, loam clays.
1 A			OL.	Organic silts and organic silty clays of low planticity.
I I I	EXLIFE AND C	-ATF	N/R	Inorganic silts, misacoous or distensesous fine sandy or silty soils, electic silts.
8 0 I	FIGRID FIRE	r zs	CE	Inorganic eleys of high planticity, fat clays.
L E	GREATER THAI	50%	O%	Organic clays of modium to high plasticity, organic silts.
1	IORLY ORGANIC SOILS		Pt	Year and ether highly erganic soils.

Specialists in Environmental Due Diligence and Remedial Services

One Sutter Street, Suite 600 San Francisco, CA 94104

		ax.	AIR EIR	EE			
U.S. Standard	Standard Series Sieve			Clea	r Squere	Sieve Openings	
	90 5	0 1	4		/4=	5° 5	-
ilts 4 clays		SAND		GLAVEL			
of plantialty	Pine	Rodius	Course	Fine	Course	Cobblas	Boulder
sler	*	OISTURE (CORDITIO	- /YE	CREATEC	MOTETURE	

	T	MOI	TURE CO	MDITION (HCREASIRC M	DISTURE
Grey Brown Tan Tallov	PRT	ETYCEATTA	DAMY D	AMP MOIS	TERT HOIST	TET SATURATED
Red Block Oreen						
Thite Orange						

PLANTICITY						
TERY	PI	DRY STREE	CTE	FIELD	TEET	
Souplastic Slightly plastic Sodium plantic Eighly plastic	0-3 3-15 13-30 31 er mere	Very lew Slight Wedium High	Rasil Piffi	y crest	eneily had with fingers p erush p erush with fingers	

	HEISTESCT	RELATIVE DESERVE		
EILTE AND CLATS	STREEGIE++	BLOWS/YOUT+	SANDE & GRAVELS	\$L0¥\$/7007
Very Soft Soft Firm Stiff Very Stiff Hard	0 - 1/4 1/4 - 1/2 1/2 - 1 1 - 2 2 - 4 Over 4	0 - 2 2 - 4 4 - 8 8 - 16 16 - 32 Over 32	Very Leese Leese Redium Dense Dense Very Dense	0 - 4 4 - 10 10 - 30 30 - 30 Over 30

* Runber of blows of 140 pound hamner failing 30 inches to drive a 2 inch 0.b. (1-3/8 inch I.b.) split spees (AFTM B-1586), ****Ownerfined compressive strength in tems/sq.ft. as determined by laboratory testing or approximated by the standard description test (AFTM B-1586) pocket passtrometer, torwine, or visual observations

_ 3			
4	-	COLUMN	
	imer.	tration of a 3-inch 0.5.	amor falling 30 inches for each inches ring sampler (classification approximately -inch 0,p. split speem at 1 feet
ı		Briven Interval	₩ Territation

▼ Groundwater Incommised

Todistarbed Sample

FE	90	DCI ODOK		
Z-		Bo Oder		
		Elight Oder		
md	٠	Mederate Oder		
IE	-	Strong Oder		
*	•	Photoiomisation	Detector	Lordine
7	•	Planelogisation	Detector	Resting

	T	
PROJECT NO.:	KEY TO EXPLORATION LOG	FIGURE
	<u> </u>	
DATE:	!	
	i	



Log of Boring: SB-1

Project Name: 1055 Eastshore Highway, Albany

Project Number: 93070.23

Drilling Date: June 24, 1994

Drilling Contractor: Soils Exploration Services

Drill Rig: CME-75

Auger: Hollow Stem - 8" O.D.

Sampler: 2.0" Mod. California Sampler

Sheet 1 of 1

Hammer: 140 lbs - 30" drop Logged By: Anibal Mata-Sol

	Blow Count	OVM Reading	Sample Interval	Depth in Feet	Well Profile	USCS Code	Soil Description
Ħ							Concrete, 6"
	:			1 - 2 -		ML	Sandy silt and gravel, well graded, yelowish brown, gravel size ~ 16 mm, subangular (base rock)
				3 -			
	2 2 3	153	T	4 -		OL	Silty sand, poorly graded, black, organic matter abundant, medium plasticity, firm, damp to moist, modedrate odor
	3	100		5 ~ - 6 -		02	modulis places, simily during to molec, moderate occor
	:			7 -			
			i	8 -		SM	Silty sand, fine-grained, poorly graded, yelowish brown, medium
	3			9 -			dense, damp no odor
	7 10	0		10 -			
				11 -			
			: 	12 -			
			'	13 -			
				14 -			
				15 -			
				16 -			
				17 -			
				- 18 -			
T				19 -			
				20			
				21 -			

Boring terminated at 10'.
Borehole grouted to surface.



Log of Boring: SB-2

Project Name: 1055 Eastshore Highway, Albany

Project Number: 93070.23

Drilling Date: June 24, 1994

Drilling Contractor: Soils Exploration Services

Drill Rig: CME-75

Auger: Hollow Stem - 8" O.D.

Sampler: 2.0" Mod. California Sampler

Sheet 1 of 1

Hammer: 140 lbs - 30" drop Logged By: Anibal Mata-Sol

Blov	w OVM nt Reading	Sample Interval	Depth in Feet	Well Profile	USCS Code	Soil Description
			1 - 2 -		ML	Concrete, 6" Sandy silt and gravel, well graded, yelowish brown (base rock)
3 2 2 2	188		3 - 4 - 5 - 6 - 7 -		OL	Silty sand, poorly graded, black, organic matter abundant, medium plasticity, soft to firm, moist, soil discoloration, modedrate odor
6 8 10	35	Ţ	8 - 9 - 10 -		SP	Sand, fine-grained, poorly graded, minor coarse sand, yelowish brown, medium dense, damp no odor
			11 -			
			14 ~ 15 ~ 16 ~			
			17 - 18 - 19 -			
			20 - - 21 -			

Boring terminated at 10'. Borehole grouted to surface.



Log of Boring: SB-3

Project Name: 1055 Eastshore Highway, Albany

Project Number: 93070.23

Drilling Date: June 24, 1994

Drilling Contractor: Soils Exploration Services

Drill Rig: CME-75

Auger: Hollow Stem - 8" O.D.

Sampler: 2.0" Mod. California Sampler

Sheet 1 of 1

Hammer: 140 lbs - 30" drop Logged By: Anibal Mata-Sol

Blow Count	OVM Reading	Sample Interval	Depth in Feet	Well Profile	USCS Code	Soil Description
			-			Concrete, 6"
			1 -		ML	Sandy silt and gravel, well graded, yelowish brown (base rock)
5	15.4	T	3 - 3 - 4 -		SM	Silty sand, coarse-grained, poorly graded, yellowish brown with streaks of grey, soft, damp, soil discoloration, modedrate odor
3 2	15.4		5 - 6 -		OL	Organic sandy silt, black, firm, damp to moist, no odor
5 7 10	o	T	7 - 8 - 9 - 10 -		SM	Silty sand, fine-grained, poorly graded, yelowish brown with streaks of grey, damp, no odor
			11 - 12 -			
			13 -			
			14 -			
			15 -			
			16 -			
			17 -			
			18 -			
			19 - -			
			20 -			
			21 -			

Boring terminated at 10'. Borehole grouted to surface.



Log of Boring: SB-4 (Slant Boring)

Project Name: 1055 Eastshore Highway, Albany

Project Number: 93070.23

Drilling Date: June 24, 1994

Drilling Contractor: Soils Exploration Services

Drill Rig: CME-75

Auger: Hollow Stem - 8" O.D.

Sampler: 2.0" Mod. California Sampler

Sheet 1 of 1

Hammer: 140 lbs - 30" drop Logged By: Anibal Mata-Sol

•						
Blow Count	OVM Reading	Sample Interval	Depth in Feet	Well Profile	USCS Code	Soil Description
· · · · · · ·			-			Concrete, 6"
3			1 - 2 - 3 -		GW SW	Sand with gravel, fine-grained sand, well graded (base rock > backfill of foremr excavtion)
3	235		4 - 5 - 6 -		SP	Sand, fine-grained, minor gravel, poorly graded, yellowish brown, loose, damp, slight to moderate odor
5 8 12	120		7 - 8 - 9 - 10 -		GP	Sandy gravel, coarse-grained sand, poorly graded, brownish grey, medium dense, damp to moist, slight odor Soil discoloration at 9' with moderate odor
7 9 10	0		11 - 12 - 13 - 14 -	<u>-</u>		Sand, minor gravel, fine-grained, well graded, brownish grey, medium dense, wet, no odor Gravel layer at 13.5-14', subangular to rounded, approximate size ~6 to 9 mm
			15 - 16 - 17 - 18 - 19 - 20 - 21 -			

Boring terminated at 15'.

Borehole grouted to surface.

Groundwater encountered during drilling at 13'.



Project Name: 1055 Eastshore Highway, Albany

Project Number: 93070.23

Drilling Date: June 23, 1994

Drilling Contractor: Soils Exploration Services

Drill Rig: CME-75

Auger: Hollow Stem - 8" O.D.

Sampler: 2.0" Mod. California Sampler

Sheet 1 of 2

Hammer: 140 lbs - 30" drop Logged By: Anibal Mata-Sol

L							30 /			
	Blow Count	OVM Reading	Sample Interval	Depth in Feet	Well Profile	USCS Code	Soil Description			
Į							Concrete, 6"			
				1 - 2 -		SP	Sand, fine grained, poorly graded, yelowish brown, damp (base rock)			
	5 10 16	0	 ▼	4 - 5 - 6 - 7 -		OL	Organic silty sand and clay, minor gravel, dark brown, very stiff, damp to moist, no odor			
	6 8 9	0		8 - 9 - 10 - 11 - 12 -		ML	Sandy silt, fine-grained, poorly graded, yelowish brown, medium dense, damp no odor			
	4 6 8	0	Ţ▽ ■	13 - 14 - - 15 - 16 -		SP	Sand, fine-grained, poorly graded, yelowish brown, medium dense, very moist, no odor			
	5 7 9	0		17 - 18 - 19 - 20 - 21 -		SP	Silty sand, fine grained, poorly graded, yellowish brown, saturated, no odor			
		<u> </u>	<u> </u>	l		<u> </u>	<u></u>			

Boring log continues on next sheet. Boring converted into monitoring well



Project Name: 1055 Eastshore Highway, Albany

Project Number: 93070.23

Drilling Date: June 23, 1994

Drilling Contractor: Soils Exploration Services

Drill Rig: CME-75

Auger: Hollow Stem - 8" O.D.

Sampler: 2.0" Mod. California Sampler

Sheet 2 of 2

Hammer: 140 lbs - 30" drop Logged By: Anibal Mata-Sol

Blow Count	OVM Reading	Sample Interval	Depth in Feet	Well Profile	USCS Code	Soil Description
			21 - 22 - 22 - 23 - 24 -		SM	Silty sand, fine grained, poorly graded, yellowish brown, saturated, no odor
			25 - 26 - 27 - 28 - 29 - 30 - 31 - 32 -			
			33 - 34 - 35 - 36 - 37 - 38 - 39 - 40 -			
			40 -			

Boring terminated at 25'.

Boring converted into monitoring well.



Project Name: 1055 Eastshore Highway, Albany

Project Number: 93070.23

Drilling Date: June 23, 1994

Drilling Contractor: Soils Exploration Services

Drill Rig: CME-75

Auger: Hollow Stem - 8" O.D.

Sampler: 2.0" Mod. California Sampler

Sheet 1 of 1

Hammer: 140 lbs - 30" drop Logged By: Anibal Mata-Sol

Blow Count	OVM Reading	Sample Interval	Depth in Feet	Well Profile	USCS Code	Soil Description
			_			Concrete, 6"
			1 - 2 -	0 L 0 3 L	ML	Sandy silt, dark brown, med. plasticity, damp, no odor (base rock)
			3 -	24.7	Bentonite	
3 4 5	6		4 - 5 - 6 -		SP	Sand, minor gravel, poorly graded, geyish brown, loose, damp, no odor
4 12 16	138		7 - 8 - 9 - 10 - 11 -	S S a n d	1	Silty clay, brownish grey, very stiff, medium to high plasticity, damp, slight odor
6 8 9	2.3		11 - 12 - 13 - 14 - 15 - 16 - 17 - 18 - 19 - 19 - 1		SM	Silty sand, fine-grained, poorly graded, yellowish brown, medium dense, moist to wet, no odor
			20 - - 21 -			

Boring terminated at 19.5'. Boring converted into monitoring well. Groundwater encountered at approximately 12' during drilling. Thereafter, it stabilized at around 7'.



Project Name: 1055 Eastshore Highway, Albany

Project Number: 93070.23

Drilling Date: June 23, 1994

Drilling Contractor: Soils Exploration Services

Drill Rig: CME-75

Auger: Hollow Stem - 8" O.D.

Sampler: 2.0" Mod. California Sampler

Sheet 1 of 1

Hammer: 140 lbs - 30" drop Logged By: Anibal Mata-Sol

Blow Count	OVM Reading	Sample Interval	Depth in Feet	Well Profile	USCS Code	Soil Description
			1 - 2 -	(G) K 0 3 K	ML	Concrete, 6" Sandy silt, poorly graded, dark brown, damp (base rock)
2 2 3	o	—	3 - 4 - 5 - 6 -		Bentonite OL	Organic sandy silt, poorly graded, greyish black, medium to high plasticity, firm, damp, no odor
5 8 10	0	T _▽	7 - 8 - 9 - 10 - 11 - 12 - 13 - 14 -	S a n d	SP	Sand, fine-grained, poorly graded, minor silt, yelowish brown, medium dense, damp no odor
3 6 11	0		15 - 15 - 16 - 17 -			
6 8 9	0		18 - 19 - 20 -		GW SW Bentonite	Gravel and sand mixture, coarse grained sand, well graded, medium dense, gravel up to 14 mm and subangular, wet, no odor
			21 -			

Boring terminated at 19.5'

Bottom of well plugged with 2' of bentonite.



California Laboratory Services	1115408	CHAIN OF CUSTODY	LOG NO. 1	7406		
CLIENT NAME ALLWEST ENVIRONMENTAL	CLIENT JOB NUMBER	ANALYSIS REQUESTED	FIELD CONDITIONS:	72.5		
ADDRESS CITIES CT #600	DESTINATION LABORATORY	PRES	Sunny + hot ~ 78°F			
SAN FRANCISCO CA 94104		<u>E</u>	COMPOSITE:			
TMFRG IL	CLS 3249 FITZGERALD RD.	WAR:				
PROJECT MANAGER ANIBAL MATA. S. RHONE # 391-25	3249 FITZGERALD RD. RANCHO CORDOVA,CA 95742	S + BIEX	State of the second			
SAMPLED BY MATA- So J	OTHER		SPECIAL INSTRUCTIONS:			
JOB DESCRIPTION PRE 11 MINARY SITE	PH: (916) 638-7301	Signature				
STEATON AND A LOCATION	-		TURN AROUND TIME NOTE / FI	ELD READINGS		
SITE LOCATION AMPAC, ALBANY			HOURS HOURS HOURS WEEK WEEKS			
DATE TIME IDENTIFICATION METHOD	CONTAINER MATRIX NO. TYPE		H W W			
SY		31				
. 0955 SB2.51						
1029 SB3.S'						
1201 SB4-S'						
1216 SB4-10'						
0904 SB1-10'						
1005 532-10'						
1038 SB3-10'						
623940851 MW1-5'						
0857 MWF-10'						
SK 146 MW 2-5'						
1106 MWZ-10						
1320 MW3.5	V		RESERVATIVES: (1) HCL (3)	COLD		
SUSPECTED CONSTITUENTS TPH-Gal			(2) HNO3 (4)			
RELINQUISHED BY (SIGN) PRINT	NAME / COMPANY	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ST (STOTA)	note CD		
CLILA JI AMIBAIT	1474-701/4/101/19	385/1100 /S/1024+	AMINAM (CLASTIA			
Flood Sould Flood	more fue be	4074 1921)	6 38 XX 58 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
			CONDITIONS / COMMENTS:			
REC'DATUAGE OF HORTH COLO	DATE / TIME:	4144 DU				
SHIPPED VIA FED X	UPS 💢 OTH	ER CIDIOUNIV	AIR BILL #			

	anform	a Laborat	ory Serv	ices	17)	570	6		CH/	AIN	OF C	บรา	ODY				LC	DG NO. 14	766
PROJECT NAM PROJECT MAN SAMPLED BY	PROJECT NAME PROJECT MANAGER PHONE #			CLIENT JOB NUMBER DESTINATION LABORATORY CLS 3249 FITZGERALD RD. RANCHO CORDOVA,CA H: (916) 638-7301 OTHER			PRESERVATIVES	ANALY ANALY	YSIS REQ		STED	COMP	COMPOSITE: SPECIAL INSTRUCTIONS:						
SITE LOCATIO	N			/					\mathbb{Z}	٠,		.	,	TURN AROUND TIME NOTE / FIELD READINGS					
DATE	TIME		SAM	PLE			TAINER							24 HOURS	48 HOURS	WEEK	WEEKS		
DATE	TIME . 133 S		FICATION .	METHOD SPILE SMO!	MATRIX So/	NO.	TYPE	3	×						=	X	>		
0 23.1		Hund	-6	34001															
<u> </u>						-						-					-		· · · · · · · · · · · · · · · · · · ·
						<u> </u>					_	-			 	 			
								ļ							 	<u> </u>	-		
			<u></u>				 		·			 							
			,												<u> </u>	-	-		
									-					-					
SUSPECTED	CONSTITUENTS	3 									ENTION TIM	IE		RESERVAT		(1) (2)	HCL HNO3	(3) = 6	- <u> </u>
A	RELINQUISHE	D BY (SIGN)		AN BA	MY A-	(NY	W	DATE	TIM V	i Dec	3 18	Ilec	REC'D	BY (SIGN	man)	K_	TE	PRIMT NAME (4100
Elle.	417	dforce	to V	USE	nate	1012	563	B	TY.	Q.									7 0
DECIM AT Z		1 1 =		****	DATE /	TIME:) (a		de 1973			CONDITION		IMENTS:	<u></u>		-2/30 -2/30
REC'TO AT	72 (L	1/20-	tho) (Q			φ/\Rightarrow	18/		1	10 K		<u> </u>		31LL #		······································		
SHIPP	ED VIA	FED FED) X		JPS 		OTHE	<u> </u>		<u></u>	-1 C V	-		WILL F					

AllWest Environmental One Sutter Street Ste 600 San Francisco, CA 94104 07/05/94

Attention: Anibal Mata-Sol

Reference: Analytical Results

Project Name: AMFAC II
Project No.: 93070.23
Date Received: 06/28/94
Chain Of Custody: 14766, 17406

CLS ID No.: M5408 CLS Job No.: 795408

The following analyses were performed on the above referenced project:

No. of Samples	Turnaround Time	Analysis Description
14	5 Days	TPH Gasoline and BTXE (soil)

These samples were received by California Laboratory Services in a chilled, intact state and accompanied by a valid chain of custody document.

Analytical results are attached to this letter. Please call if we can provide additional assistance.

Sincerely,

RECYCLED PAPER

Laboratory Director

Analysis Report: BTEX, EPA Method 8020

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project No.: 93070.23
Contact: Anibal Mata-Sol

Phone: (415)391-2510

2.0

5.0

2.0

Project: AMFAC II

Date Sampled: 06/24/94 Date Received: 06/28/94

Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: SB1-5'

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-1A

13

700

850

10

25

20

Batch No.: 13948 Matrix: SOIL

SURROGATE

Analyte	CAS No		ırr Conc. ıg/kg)	Recovery (percent)	
o-Chlorotoluene	95-49-	8 10	000	99	
	Sample: SB1-5'			······	
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution	
Benzene	71-43-2	330	10	2.0	

108-88-3

100-41-4

1330-20-7

ND = Not detected at or above indicated Reporting Limit Rep. Limit = Reporting Limit

Toluene

Ethylbenzene

Xylenes, total

Analysis Report: BTEX, EPA Method 8020

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project No.: 93070.23 Contact: Anibal Mata-Sol Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-2A

Batch No.: 13948 Matrix: SOIL

Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: SB2-5'

Date Sampled: 06/24/94
Date Received: 06/28/94
Date Extracted: 06/29/94

Project: AMFAC II

SURROGATE

Analyte	CAS No.		ırr Conc. ıg/kg)	Surrogate Recovery (percent)	
o-Chlorotoluene	95-49-8	10	0000		
	Sample: SB2-5'			<u>-</u>	
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution	
Benzene Toluene Ethylbenzene Xylenes, total	71-43-2 108-88-3 100-41-4 1330-20-7	5900 74000 63000 360000	500 5000 5000 10000	100 1000 1000 1000	

Analysis Report: BTEX, EPA Method 8020

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/24/94 Date Received: 06/28/94 Date Extracted: 06/29/94

Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: SB3-5'

Project No.: 93070.23

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408

COC Log No.: 14766, 17406 CLS ID No.: M5408-3A

Batch No.: 13948

Matrix: SOIL

SURROGATI	3
-----------	---

Analyte	CAS No.		rr Conc. g/kg)	Surrogate Recovery (percent)
o-Chlorotoluene	95-49-8	10	0	101
	Sample: SB3-5'			
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution
Benzene Toluene Ethylbenzene Xylenes, total	71-43-2 108-88-3 100-41-4 1330-20-7	ND 8.1 29 78	5.0 5.0 5.0	1.0 1.0 1.0 1.0

Analysis Report: BTEX, EPA Method 8020

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/24/94 Date Received: 06/28/94

Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: SB4-5'

Project No.: 93070.23 Contact: Anibal Mata-Sol Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-4A Batch No.: 13948

Matrix: SOIL

SURROGATE

Analyte	CAS No.		r Conc. /kg)	Surrogate Recovery (percent)
o-Chlorotoluene	95-49-8	100		99
	Sample: SB4-5' _			
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution
Benzene Toluene Ethylbenzene Xylenes, total	71-43-2 108-88-3 100-41-4 1330-20-7	23 190 440 2500	5.0 5.0 25 50	1.0 1.0 5.0 5.0

Analysis Report: BTEX, EPA Method 8020
Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project No.: 93070.23
Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-5A Batch No.: 13948

Matrix: SOIL

Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: SB4-10'

Date Sampled: 06/24/94 Date Received: 06/28/94

Project: AMFAC II

SURROGATE

Analyte	CAS No.		rr Conc. g/kg)	Recovery (percent)	
o-Chlorotoluene	95-49-8	10	0	99	
	Sample: SB4-10' _				
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution	
Benzene Toluene Ethylbenzene Xylenes, total	71-43-2 108-88-3 100-41-4 1330-20-7	21 ND 8.5 19	5.0 5.0 5.0 10	1.0 1.0 1.0	

ND = Not detected at or above indicated Reporting Limit

Rep. Limit = Reporting Limit

Analysis Report: BTEX, EPA Method 8020

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/24/94
Date Received: 06/28/94
Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No. 691-10/

Client ID No.: SB1-10'

Project No.: 93070.23
Contact: Anibal Mata-Sol
Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-6A

Batch No.: 13948 Matrix: SOIL

SURROGATE

Analyte	CAS No.		err Conc. eg/kg)	Surrogate Recovery (percent)
o-Chlorotoluene	95-49-8	10	00	99
	Sample: SB1-10'			
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution
Benzene Toluene Ethylbenzene Xylenes, total	71-43-2 108-88-3 100-41-4 1330-20-7	ND ND ND ND	5.0 5.0 5.0 10	1.0 1.0 1.0

Analysis Report: BTEX, EPA Method 8020

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Contact: Anibal Mata-Sol

Phone: (415)391-2510

Project No.: 93070.23

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-7A

Batch No.: 13948

Matrix: SOIL

Project: AMFAC II

Date Sampled: 06/24/94
Date Received: 06/28/94 Date Extracted: 06/29/94

Date Analyzed: 06/29/94 Date Reported: 07/01/94 Client ID No.: SB2-10'

SURROGATE

Surrogate Surr Conc. Recovery (ug/kg) (percent) CAS No. Analyte 100 100 95-49-8 o-Chlorotoluene Sample: SB2-10'

Rep. Limit (ug/kg) Results CAS No. (ug/kg) Dilution Analyte 71-43-2 ND 5.0 1.0 Benzene 108-88-3 5.0 1.0 Toluene ND 1.0 100-41-4 5.0 Ethylbenzene ND1330-20-7 10 1.0 ND Xylenes, total

ND = Not detected at or above indicated Reporting Limit

Analysis Report: BTEX, EPA Method 8020

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project No.: 93070.23 Contact: Anibal Mata-Sol Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406

CLS ID No.: M5408-8A

Batch No.: 13948 Matrix: SOIL

Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: SB3-10'

Date Sampled: 06/24/94
Date Received: 06/28/94
Date Extracted: 06/29/94

Project: AMFAC II

SURROGATE

Analyte	CAS No.		rr Conc. g/kg)	Surrogate Recovery (percent)	
o-Chlorotoluene	95-49-8	10	0	99	
	Sample: SB3-10' _			<u>, </u>	
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution	

Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution
Benzene Toluene Ethylbenzene Xylenes, total	71-43-2 108-88-3 100-41-4 1330-20-7	ND ND ND ND	5.0 5.0 5.0 10	1.0 1.0 1.0

Analysis Report: BTEX, EPA Method 8020

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project No.: 93070.23
Contact: Anibal Mata-Sol

Phone: (415)391-2510

Project: AMFAC II

Date Sampled: 06/23/94 Date Received: 06/28/94

Date Extracted: 06/29/94 Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: MW1-5'

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-9A

Batch No.: 13948 Matrix: SOIL

Analyte	CAS No.		rr Conc. g/kg)	Surrogate Recovery (percent)
o-Chlorotoluene	95-49-8	100)	99
	Sample: MW1-5'			<u></u>
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution
Benzene Toluene Ethylbenzene Xylenes, total	71-43-2 108-88-3 100-41-4 1330-20-7	ND ND ND ND	5.0 5.0 5.0 10	1.0 1.0 1.0 1.0



Analysis Report: BTEX, EPA Method 8020 Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406

Project No.: 93070.23
Contact: Anibal Mata-Sol
Phone: (415)391-2510

Project: AMFAC II

CLS ID No.: M5408-10A

Batch No.: 13948

Matrix: SOIL

Date Sampled: 06/23/94
Date Received: 06/28/94
Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: MW1-10'

SURROGATE

Analyte	CAS No.		r Conc. /kg)	Surrogate Recovery (percent)
o-Chlorotoluene	95-49-8	100		98
	_ Sample: MW1-10' _			
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution
Benzene Toluene Ethylbenzene Xylenes, total	71-43-2 108-88-3 100-41-4 1330-20-7	ND ND ND ND	5.0 5.0 5.0 10	1.0 1.0 1.0 1.0

ND = Not detected at or above indicated Reporting Limit

Analysis Report: BTEX, EPA Method 8020

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project No.: 93070.23 Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-11A

Batch No.: 13948

Matrix: SOIL

Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: MW2-5'

Date Sampled: 06/23/94
Date Received: 06/28/94

Project: AMFAC II

SURROGATE

Analyte	CAS No.		rr Conc. g/kg)	Surrogate Recovery (percent)
o-Chlorotoluene	95-49-8	10	0	97
	Sample: MW2-5' _			
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution
Benzene Toluene Ethylbenzene Xylenes, total	71-43-2 108-88-3 100-41-4 1330-20-7	ND ND ND ND	5.0 5.0 5.0	1.0 1.0 1.0 1.0

ND = Not detected at or above indicated Reporting Limit

Analysis Report: BTEX, EPA Method 8020

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project No.: 93070.23
Contact: Anibal Mata-Sol
Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406

CLS ID No : M5408-12A

Batch No.: 13948 Matrix: SOIL

Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94 Client ID No.: MW2-10'

Date Sampled: 06/23/94
Date Received: 06/28/94

Project: AMFAC II

SURROGATE

Analyte	CAS No.	Surr Conc. (ug/kg)	Surrogate Recovery (percent)
o-Chlorotoluene	95-49-8	2500	99
	Sample: MW2-10'		

Rep. Limit Results (ug/kg) Dilution CAS No. (ug/kg) Analyte 71-43-2 28 Benzene 590 25 5.0 108-88-3 Toluene 25 100-41-4 980 5.0 Ethylbenzene 3900 100 10 1330-20-7 Xylenes, total

Analysis Report: BTEX, EPA Method 8020

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

Project: AMFAC II

Ethylbenzene

Xylenes, total

Date Sampled: 06/23/94 Date Received: 06/28/94

Date Extracted: 06/29/94 Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: MW3-5'

One Sutter Street Ste 600 San Francisco, CA 94104

Project No.: 93070.23 Contact: Anibal Mata-Sol Phone: (415)391-2510

5.0

10

1.0

1.0

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406

CLS ID No.: M5408-13A

Batch No.: 13948 Matrix: SOIL

SURROGATE

Analyte	CAS No.		urr Conc. ug/kg)	Surrogate Recovery (percent)
o-Chlorotoluene	95-49-8	3 1	00	98
	Sample: MW3-5'			<u></u>
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution
Benzene Toluene	71-43-2 108-88-3	ND ND	5.0 5.0	1.0

100-41-4

1330-20-7

ND

ND

Analysis Report: BTEX, EPA Method 8020
Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Contact: Anibal Mata-Sol Phone: (415)391-2510

Project No.: 93070.23

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-14A

Batch No.: 13948 Matrix: SOIL

Date Sampled: 06/23/94 Date Received: 06/28/94 Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: MW3-10'

Project: AMFAC II

SURROGATE

Analyte	CAS No.		rr Conc. g/kg)	Surrogate Recovery (percent)
o-Chlorotoluene	95-49-8	100)	98
	Sample: MW3-10' _			
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution

Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)	Dilution
Benzene Toluene Ethylbenzene Xylenes, total	71-43-2 108-88-3 100-41-4 1330-20-7	ND ND ND ND	5.0 5.0 5.0 10	1.0 1.0 1.0

Analysis Report: BTEX, EPA Method 8020
Purge and Trap, EPA Method 5030

Client: AllWest Environmental

Project: AMFAC II

Date Extracted: 06/29/94
Date Analyzed: 06/29/94

Date Reported: 07/01/94

One Sutter Street Ste 600 San Francisco, CA 94104

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408

Contact: Anibal Mata-Sol Phone: (415)391-2510

Project No.: 93070.23

Batch No.: 13948 Matrix: SOIL

Analyte	CAS No.	Surr Conc. (ug/kg)	MB Surrogate Recovery (percent)
o-Chlorotoluene	95-49-8	100	99
	METHOD BLANK		
Analyte	CAS No.	Results (ug/kg)	Rep. Limit (ug/kg)
Benzene Toluene Ethylbenzene Xylenes, total	71-43-2 108-88-3 100-41-4 1330-20-7	ND ND ND ND	5.0 5.0 5.0

MB SURROGATE

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-1A Batch No.: 13948 Matrix: SOIL

Project No.: 93070.23
Contact: Anibal Mata-Sol
Phone: (415)391-2510

Date Sampled: 06/24/94
Date Received: 06/28/94
Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: SB1-5'

Project: AMFAC II

Sample: SB1-5'

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution
TPH as Gasoline	N/A	14	2.0	2.0

ND = Not detected at or above indicated Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/24/94 Date Received: 06/28/94

Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: SB2-5'

Project No.: 93070.23
Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-2A Batch No.: 13948

Matrix: SOIL

Sample: SB2-5' _

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution
TPH as Gasoline	N/A	2000	1.000	1000

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Phone: (415)391-2510

Project No.: 93070.23
Contact: Anibal Mata-Sol

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-3A

Batch No.: 13948

Matrix: SOIL

Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: SB3-5'

Date Sampled: 06/24/94 Date Received: 06/28/94

Project: AMFAC II

Sample: SB3-5'

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution	
TPH as Gasoline	N/A	5.5	1.0	1.0	_

ND = Not detected at or above indicated Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/24/94 Date Received: 06/28/94

Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: SB4-5'

Project No.: 93070.23

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-4A

Batch No.: 13948

Matrix: SOIL

Sample: SB4-5'

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution
TPH as Gasoline	N/A	39	5.0	5.0

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/24/94 Date Received: 06/28/94 Date Extracted: 06/29/94

Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: \$B4-10'

Project No.: 93070.23
Contact: Anibal Mata-Sol Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-5A

Batch No.: 13948

Matrix: SOIL

Sample: SB4-10'

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution
TPH as Gasoline	N/A	ND	1.0	1.0

ND = Not detected at or above indicated Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

TPH as Gasoline

Date Sampled: 06/24/94 Date Received: 06/28/94 Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: SB1-10'

Project No.: 93070.23

Contact: Anibal Mata-Sol

Phone: (415)391-2510

1.0

1.0

CLS Contact: George Hampton

Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-6A

Batch No.: 13948 Matrix: SOIL

ND

Analyte	CAS	No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution

N/A

Sample: SB1-10'

ND = Not detected at or above indicated Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/24/94
Date Received: 06/28/94
Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: SB2-10'

Project No.: 93070.23

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-7A

Batch No.: 13948 Matrix: SOIL

Sample: SB2-10'

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution	
TPH as Gasoline	N/A	ND	1.0	1.0	•

ND = Not detected at or above indicated Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/24/94 Date Received: 06/28/94

Date Extracted: 06/29/94 Date Analyzed: 06/29/94 Date Reported: 07/01/94 Client ID No.: SB3-10'

Project No.: 93070.23

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-8A

Batch No.: 13948 Matrix: SOIL

Sample: SB3-10'

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution
TDU na Chaoline	N/A	ND	1.0	1.0
TPH as Gasoline	N/A	ND	1.0	1.0

ND = Not detected at or above indicated Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/23/94 Date Received: 06/28/94 Date Extracted: 06/29/94

Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: MW1-5'

Project No.: 93070.23

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-9A

Batch No.: 13948 Matrix: SOIL

Sample: MW1-5'	
----------------	--

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution
TPH as Gasoline	N/A	ND	1.0	1.0

ND = Not detected at or above indicated Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/23/94
Date Received: 06/28/94
Date Extracted: 06/29/94

Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: MW1-10'

Project No.: 93070.23

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-10A

Batch No.: 13948

Matrix: SOIL

Sample: MW1-10'

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution	_
TPH as Gasoline	N/A	ND	1.0	1.0	

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015 Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/23/94
Date Received: 06/28/94
Date Extracted: 06/29/94 Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: MW2-5'

Project No.: 93070.23
Contact: Anibal Mata-Sol
Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-11A

Batch No.: 13948 Matrix: SOIL

Sample: MW2-5'

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution
TPH as Gasoline	N/A	ND	1.0	1.0

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015 Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/23/94 Date Received: 06/28/94 Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94

Client ID No.: MW2-10'

Project No.: 93070.23 Contact: Anibal Mata-Sol Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-12A

Batch No.: 13948 Matrix: SOIL

Sample: MW2-10'

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution
TPH as Gasoline	N/A	32	5.0	5.0

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015 Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/23/94
Date Received: 06/28/94
Date Extracted: 06/29/94 Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: MW3-5'

Project No.: 93070.23
Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-13A

Batch No.: 13948 Matrix: SOIL

Sample: MW3-5'

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution
TPH as Gasoline	N/A	ND	1.0	1.0

ND = Not detected at or above indicated Reporting Limit Rep. Limit = Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project No.: 93070.23
Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408-14A

Batch No.: 13948

Matrix: SOIL

Project: AMFAC II

Date Sampled: 06/23/94 Date Received: 06/28/94 Date Extracted: 06/29/94

Date Analyzed: 06/29/94
Date Reported: 07/01/94
Client ID No.: MW3-10'

Sample: MW3-10'

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)	Dilution
TPH as Gasoline	N/A	ND	1.0	1.0

ND = Not detected at or above indicated Reporting Limit Rep. Limit = Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, BPA Method 8015 Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Extracted: 06/29/94 Date Analyzed: 06/29/94 Date Reported: 07/01/94

Project No.: 93070.23
Contact: Anibal Mata-Sol Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408

Batch No.: 13948 Matrix: SOIL

METHOD BLANK

Analyte	CAS No.	Results (mg/kg)	Rep. Limit (mg/kg)
TPH as Gasoline	N/A	ND	1.0

 ${\tt ND} = {\tt Not}$ detected at or above indicated Reporting Limit Rep. Limit = Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015 Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94

Project No.: 93070.23

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408

Batch No.: 13948 Matrix: SOIL

	MATRIX	SPIKE		
Analyte		CAS No.	MS Conc. (mg/kg)	MS Recovery (percent)
Gasoline		N/A	2.5	94
	MATRIX SPIKE	DUPLICATE _		
Analyte		CAS No.	MSD Conc. (mg/kg)	MSD Recovery (percent)
Gasoline		N/A	2.5	92
	RELATIVE % I	IFFERENCE		
Analyte	-	CAS	No.	Relative Percent Difference (percent)
Gasoline		N/A	1	2

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015 Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Extracted: 06/29/94
Date Analyzed: 06/29/94
Date Reported: 07/01/94

Project No.: 93070.23

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795408 COC Log No.: 14766, 17406 CLS ID No.: M5408

Batch No.: 13948 Matrix: SOIL

LAB	CONTROL	SAMPLE
-----	---------	--------

Analyte	CAS No.	LCS Conc. (mg/kg)	LCS Recovery (percent)
Gasoline	N/A	2.5	98

.

AllWest Environmental One Sutter Street Ste 600 San Francisco, CA 94104 07/05/94

Attention: Anibal Mata-Sol

Reference: Analytical Results

Project Name: AMFAC II Project No.: 93070 Date Received: 06/30/94 Chain Of Custody: 13230 CLS ID No.: M5435 CLS Job No.: 795435

The following analyses were performed on the above referenced project:

No. of Samples	Turnaround Time	Analysis Description
3	5 Days	TPH Gasoline and BTXE (water)

These samples were received by California Laboratory Services in a chilled, intact state and accompanied by a valid chain of custody document.

Analytical results are attached to this letter. Please call if we can provide additional assistance.

Sincerely

George Hampton/ Laboratory Director

Analysis Report: BTEX, EPA Method 602

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/29/94 Date Received: 06/30/94 Date Extracted: 07/01/94

Date Analyzed: 07/01/94
Date Reported: 07/05/94
Client ID No.: MW1-A+B

Project No.: 93070

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795435 COC Log No.: 13230 CLS ID No.: M5435-1A

Batch No.: 13962 Matrix: WATER

SURROGATE

Analyte	CAS No.		rr Conc. g/L)	Surrogate Recovery (percent)
o-Chlorotoluene	95-49-8	20		104
	Sample: MW1-A+B _			
Analyte	CAS No.	Results (ug/L)	Rep. Limit (ug/L)	Dilution
Benzene	71-43-2	ND	0.30	1.0
Toluene	108-88-3	0.60	0.30	1.0
Ethylbenzene	100-41-4	2.5	0.30	1.0
Xylenes, total	1330-20-7	9.0	0.60	1.0

ND = Not detected at or above indicated Reporting Limit

Rep. Limit = Reporting Limit

Xylenes, total

Analysis Report: BTEX, EPA Method 602
Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/29/94
Date Received: 06/30/94
Date Extracted: 07/01/94

Date Analyzed: 07/01/94 Date Reported: 07/05/94 Client ID No.: MW2-A+B Project No.: 93070 Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795435

COC Log No.: 13230 CLS ID No.: M5435-2A

Batch No.: 13962 Matrix: WATER

SURROGATE

Analyte	CAS No.	Surr Conc. (ug/L)	Surrogate Recovery (percent)		
o-Chlorotoluene	95-49-8	20	94		
Sample: MW2-A+B					

Analyte	CAS No.	Results (ug/L)	Rep. Limit (ug/L)	Dilution
Benzene	71-43-2	130	1.5	5.0
Toluene	108-88-3	11	0.30	1.0
Ethylbenzene	100-41-4	20	0.30	1.0
Xylenes, total	1330-20-7	10	0.60	1.0

ND = Not detected at or above indicated Reporting Limit

Rep. Limit = Reporting Limit

Analysis Report: BTEX, EPA Method 602
Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

CLS Contact: George Hampton

Contact: Anibal Mata-Sol

Phone: (415)391-2510

Project No.: 93070

Job No.: 795435 COC Log No.: 13230 CLS ID No.: M5435-3A

Batch No.: 13962 Matrix: WATER

Project: AMFAC II

Date Sampled: 06/29/94
Date Received: 06/30/94
Date Extracted: 07/01/94

Date Analyzed: 07/01/94 Date Reported: 07/05/94 Client ID No.: MW3-A+B

SURROGATE

Surrogate Surr Conc. Recovery (percent) CAS No. (ug/L) Analyte 95-49-8 20 94 o-Chlorotoluene

Sample: MW3-A+B

Analyte	CAS No.	Results (ug/L)	Rep. Limit (ug/L)	Dilution
Benzene	71-43-2	ND	0.30	1.0
Toluene	108-88-3	ND	0.30	1.0
Ethylbenzene	100-41-4	4.0	0.30	1.0
Xylenes, total	1330-20-7	13	0.60	1.0

ND = Not detected at or above indicated Reporting Limit

Rep. Limit = Reporting Limit

Analysis Report: BTEX, EPA Method 602
Purge and Trap, EPA Method 5030

Client: AllWest Environmental

Date Extracted: 07/01/94
Date Analyzed: 07/01/94
Date Reported: 07/05/94

One Sutter Street Ste 600 San Francisco, CA 94104

Project No.: 93070 Contact: Anibal Mata-Sol Phone: (415)391-2510

Project: AMFAC II

CLS Contact: George Hampton Job No.: 795435 COC Log No.: 13230 CLS ID No.: M5435 Batch No.: 13962 Matrix: WATER

MB	SURROGAT	E
----	----------	---

	· · · · · · · · · · · · · · · · · · ·			
Analyte	CAS No.	Surr Conc. (ug/L)	MB Surrogate Recovery (percent)	
o-Chlorotoluene	95-49-8	20	100	
	METHOD BLANK			
Analyte	CAS No.	Results (ug/L)	Rep. Limit (ug/L)	
Benzene	71-43-2	ND	0.30	
Toluene	108-88-3	ND	0.30	
Ethylbenzene	100-41-4	ND	0.30	
Xylenes, total	1330-20-7	ND	0.60	

ND = Not detected at or above indicated Reporting Limit

Rep. Limit = Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015

Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/29/94 Date Received: 06/30/94 Date Extracted: 07/01/94 Date Analyzed: 07/01/94
Date Reported: 07/05/94
Client ID No.: MW1-A+B

Project No.: 93070

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795435 COC Log No.: 13230 CLS ID No.: M5435-1A Batch No.: 13962

Matrix: WATER

Sampl	le:	WMT-Y+	В
-------	-----	--------	---

Analyte	CAS No.	Results (mg/L)	Rep. Limit (mg/L)	Dilution
TPH as Gasoline	N/A	ND	0.050	1.0

ND = Not detected at or above indicated Reporting Limit Rep. Limit = Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015 Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/29/94
Date Received: 06/30/94 Date Extracted: 07/01/94

Date Analyzed: 07/01/94
Date Reported: 07/05/94
Client ID No.: MW2-A+B

Project No.: 93070

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795435 COC Log No.: 13230 CLS ID No.: M5435-2A Batch No.: 13962

Matrix: WATER

Sample: MW2-A+B

Analyte	CAS No.	Results (mg/L)	Rep. Limit (mg/L)	Dilution
TPH as Gasoline	N/A	0.33	0.050	1.0

 $\ensuremath{\mathtt{ND}} = \ensuremath{\mathtt{Not}}$ detected at or above indicated Reporting Limit Rep. Limit = Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015 Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Sampled: 06/29/94
Date Received: 06/30/94
Date Extracted: 07/01/94

Date Analyzed: 07/01/94
Date Reported: 07/05/94
Client ID No.: MW3-A+B

Project No.: 93070

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795435 COC Log No.: 13230 CLS ID No.: M5435-3A

Batch No.: 13962

Matrix: WATER

Sample: MW3-A+B

Analyte	CAS No.	Results (mg/L)	Rep. Limit (mg/L)	Dilution
TPH as Gasoline	N/A	0.052	0.050	1.0

 $\ensuremath{\mathtt{ND}} = \ensuremath{\mathtt{Not}}$ detected at or above indicated Reporting Limit Rep. Limit = Reporting Limit

Analysis Report: Total Petroleum Hydrocarbons, EPA Method 8015 Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Extracted: 07/01/94 Date Analyzed: 07/01/94 Date Reported: 07/05/94

Project No.: 93070 Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795435 COC Log No.: 13230 CLS ID No.: M5435

Batch No.: 13962

Matrix: WATER

METHOD BLANK

Analyte	CAS No.	Results (mg/L)	Rep. Limit (mg/L)
TPH as Gasoline	N/A	ND	0.050

ND = Not detected at or above indicated Reporting Limit Rep. Limit = Reporting Limit

Analysis Report: BTEX, EPA Method 602
Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600 San Francisco, CA 94104

Project: AMFAC II

Date Extracted: 07/01/94 Date Analyzed: 07/01/94 Date Reported: 07/05/94

Project No.: 93070 Contact: Anibal Mata-Sol Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795435

COC Log No.: 13230 CLS ID No.: M5435

Batch No.: 13962 Matrix: WATER

SURROGATE		
CAS No.	MS Surr. Conc. (ug/L)	MS Surrogate Recovery (percent)
95-49-8	20	97
RIX SPIKE		
CAS No.	MS Conc. (ug/L)	MS Recovery (percent)
71-43-2	20	99
108-88-3	20	102
100-41-4	20	115
1330-20-7	60	108
SURROGATE		
CAS No.	Surr. Conc. (ug/L)	MSD Surrogate Recovery (percent)
95-49-8	20	97
PIKE DUPLICATE		
CAS No.	MSD Conc. (ug/L)	MSD Recovery (percent)
71-43-2	20	94
108-88-3	20	100
100-41-4	20	118
1330-20-7	60	110
	CAS No. 95-49-8 RIX SPIKE CAS No. 71-43-2 108-88-3 100-41-4 1330-20-7 SURROGATE CAS No. 95-49-8 PIKE DUPLICATE CAS No. 71-43-2 108-88-3 100-41-4	CAS No. (ug/L) 95-49-8 20 RIX SPIKE CAS No. (ug/L) 71-43-2 20 108-88-3 20 100-41-4 20 1330-20-7 60 SURROGATE CAS No. (ug/L) 95-49-8 20 PIKE DUPLICATE CAS No. (ug/L) 71-43-2 20 108-88-3 20 100-41-4 20

Analysis Report: BTEX, EPA Method 602
Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Extracted: 07/01/94 Date Analyzed: 07/01/94 Date Reported: 07/05/94

Project No.: 93070

Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795435 COC Log No.: 13230 CLS ID No.: M5435

Batch No.: 13962 Matrix: WATER

RELATIVE % DIFFERENCE

	BRIIVE O DIFFBRENCE	
Analyte	CAS No.	Relative Percent Difference (percent)
Benzene	71-43-2	5
Toluene	108-88-3	2
Ethylbenzene	100-41-4	3
Xylenes, total	1330-20-7	2

Analysis Report: BTEX, EPA Method 602
Purge and Trap, EPA Method 5030

Client: AllWest Environmental

One Sutter Street Ste 600

San Francisco, CA 94104

Project: AMFAC II

Date Extracted: 07/01/94
Date Analyzed: 07/01/94
Date Reported: 07/05/94

Project No.: 93070 Contact: Anibal Mata-Sol

Phone: (415)391-2510

CLS Contact: George Hampton Job No.: 795435

COC Log No.: 13230 CLS ID No.: M5435

Batch No.: 13962 Matrix: WATER

LCS SURROGATE					
Analyte	CAS No.	LCS Conc. (ug/L)	LCS Surrogate Recovery (percent)		
o-Chlorotoluene	95-49-8	20	98		
	LAB CONTROL SAMPLE		<u></u>		
Analyte	CAS No.	LCS Conc.	LCS Recovery (percent)		
Benzene	71-43-2	20	107		
Ethylbenzene	100-41-4	20	107		
Toluene	108-88-3	20	109		
Xylenes, total	1330-20-7	60	104		