March 8, 1994

Eva Chu Department of Environmental Health 80 Swan Way, Rm. 200 Oakland, CA 94621

RE:

5965 Dougherty Road

Dublin, CA 94568

Dear Ms. Chu:

Enclosed is a revised soil boring and well location map, for the Soil Boring and Monitoring Well Installation Work Plan dated January 13, 1994, as you requested. The map has been updated to show the location of the monitoring well on the adjoining property to the north that will be used in groundwater flow direction determination.

Please call me should you have any questions.

Sincerely,

Steve Penshorn Project Engineer

cc: Mr. R.N. Stefan, La Mirada Association, 18 Sunnyside Ln.

Orinda, CA 94563

3/14/04 S Pendron says they will verify excoting well depth & screen interval. Told steve that those wells will need to be montered w/ murphand for la mirada to verify flow direction

