# HAGEMAN-AGUIAR, INC.

Underground Contamination Investigations Groundwater Consultants, Environmental Engineering reviewed 12/11/42

3732 Mt. Diablo Blvd. Suite 372 Lafayette, California 94549 (510) 284-1661 FAX (510) 284-1664

REPORT OF SEMI-ANNUAL GROUNDWATER SAMPLING

(sampled September 8, 1992)

ADOBE PLAZA
3098 Castro Valley Blvd
Castro Valley, CA

September 15, 1992

#### TABLE OF CONTENTS

I.	INTRODUCTION	1
II.	FIELD WORK	4
	Monitoring Well Sampling	4
	Wastewater Generation	
III.	RESULTS OF WATER LEVEL MEASUREMENTS	€
	Shallow Groundwater Flow Direction	6
	Shallow Water Table Hydraulic Gradient	6
	Historical Water Level Measurements	6
IV.	SHALLOW GROUNDWATER SAMPLING RESULTS	10
	Laboratory Analysis	10
	Results of Laboratory Analysis	10

ATTACHMENT A -- Well Sampling Logs

ATTACHMENT B -- Analytical Results: Groundwater

#### I. INTRODUCTION

The site location is 3098 Castro Valley Blvd, Castro Valley, California, and has been maintained by the current owners for a number of years as a car wash and gasoline station. The location of the site is shown in Figure 1.

On July 26, 1988, two underground gasoline storage tanks were removed by Hageman-Schank, Inc. A map of the site is shown in Figure 2. This map shows the present layout of the facility (Adobe Plaza Shopping Center, constructed in 1989), along with the location of the previous underground tank excavation and removal. Analysis of a pit water sample collected at the time of the tank removals indicated the presence of Gasoline and Benzene at concentrations of 2.0 mg/L (ppm) and 32  $\mu$ g/L (ppb), respectively.

The three on-site shallow groundwater monitoring wells MW-1, MW-2 and MW-3 were subsequently installed on August 11, 1989, by Hageman-Schank, Inc.

On September 8, 1992, all three of the on-site monitoring wells were sampled for the laboratory analysis for dissolved petroleum constituents. In addition to the monitoring well sampling, other tasks included water level measurements for each monitoring well. This round of groundwater sampling has been conducted as part of the continued groundwater monitoring program at the site, as required by the Alameda County Department of Environmental Health and the California Regional Water Quality Control Board (RWQCB), San Francisco Bay Region.





FIGURE 1. Site Location Map.



CASTRO VALLEY BLVD

W

FIGURE 2. Site Map.

#### II. FIELD WORK

#### Monitoring Well Sampling

On September 8, 1992, groundwater samples were collected from each of the on-site monitoring wells. The locations of the monitoring wells are shown in Figure 2 (site map). groundwater sampling, each well was purged by bailing approximately 10 casing volumes of water. conductivity, temperature, and pH meters were present on-site during the monitoring well sampling. As the purging process proceeded, the three parameters were monitored. continued until readings appeared to have reasonably stabilized. After the water level in the well had attained 80% or more of the original static water level, a groundwater sample was collected using a clean teflon bailer. The water sample was placed inside appropriate 40 mL VOA vials free of any headspace. The samples were immediately placed on ice, then transported under chain-of-custody to the laboratory at the end of the work day.

At the time each monitoring well was sampled, the following information was recorded in the field: 1) depth-to-water prior to purging, using an electrical well sounding tape, 2) identification of any floating product, sheen, or odor prior to purging, using a clear teflon bailer, 3) sample pH, 4) sample temperature, and 5) specific conductance of the sample.

Copies of the well sampling logs are included as Attachment A.

#### Wastewater Generation

All water removed from the wells during development and purging was drummed and stored on-site until the results of laboratory analyses were obtained. Based upon these results, the water should be sewered as a non-hazardous liquid waste in accordance with local sewering agency permit requirements. The disposal of wastewater is the responsibility of the property owner (waste generator), and is beyond the scope of work as described in this report.

#### III. RESULTS OF WATER LEVEL MEASUREMENTS

#### Shallow Groundwater Flow Direction.

Shallow water table elevations were measured on September 8, 1992. These measurements are shown in Table 1. Figure 3 presents a contour map for the shallow groundwater table beneath the site. As shown in this figure, the data from these monitoring wells indicate that the shallow groundwater flow beneath the site at the time of the groundwater sampling was in the southeasterly direction.

#### Shallow Water Table Hydraulic Gradient

Figure 3 presents the contour map for the shallow groundwater table beneath the site. As shown in this figure, the shallow groundwater table appears to have a calculated hydraulic gradient of dH/dL = 2!/102! = 0.02.

#### <u>Historical Water Level Measurements</u>

In addition to the most recent measurement of the shallow water table elevations prior to the groundwater sampling on September 8, 1992, a tabulation of all historical water level measurements for the site has been completed. Table 2 presents the results of all water level measurements collected between August 23, 1989, and the present time.

TABLE 1.

Shallow Water Table Elevations
September 8, 1992

Well	Top of Casing Elevation (feet)	Depth to Water (feet)	Water Table Elevation (feet)
MW-1	99.73	10.04	89.69
MW-2	100.00	7.13	92.87
MW-3	99.76	7.66	92.10




TABLE 2. Historical Water Table Elevations (feet)

		Date of Measurement														
Well	8-23-89	6-8-90	8-29-90	11-28-90	3-8-91	10-10-91	3- <del>9-</del> 92	9-8-92								
MW-1	90.27	91.23	90.33	90.24	90.17	88.57	91.13	89.69								
MW-2	92.45 93.07		92.78	92.79	93.12	92.80	93.04	92.87								
MW-3	92.38	93.35	92.17	92.17	93.98	92.16	94.26	92.10								
Flow Direction	SE	SE	SE	SE	SE	SE	SE	SE								

#### IV. SHALLOW GROUNDWATER SAMPLING RESULTS

#### Laboratory Analysis

All analyses were conducted by a California State DOHS certified laboratory in accordance with EPA recommended procedures (Priority Environmental Laboratory, Milpitas, CA). All Groundwater samples were analyzed for Total Petroleum Hydrocarbons as Gasoline (EPA method 8015), and Benzene, Toluene, Ethylbenzene, and Total Xylenes (EPA method 602).

#### Results of Laboratory Analysis.

Table 3 presents the results of the laboratory analysis for TPH and BTEX of the groundwater samples collected from the monitoring wells. For this round of groundwater sampling, no detectable concentrations of either Gasoline, Benzene, Toluene, Ethylbenzene, or Total Xylenes were detected in any of the shallow groundwater samples.

A copy of the laboratory certificate for the water sample analysis is included as Attachment B.

TABLE 3.
Shallow Groundwater Sampling Results

Well	Date	TPH as Gasoline (ug/L)	Benzene (ug/L)	Toluene (ug/L)	Ethyl- benzene (ug/L)	Xylenes (ug/L)		
1	08-22-89	ND	0.5 1.2		ND	3.1		
	05-24-90	ND	ND	ND	ND	ND		
	08-29-90	ND	ND	ND	ND	ND		
	11-28-90	ND	ND	ND	ND	ND		
	03-08-91	ND	ND	ND	ND	ND		
	10-10-91	ND	ND	ND	ND	ND		
	03-09-92	ND	ND	ND	ND	ND		
	09-08-92	ND	ND	ND	ND	ND		
2	08-22-89	110	5.3	ND	ND	ND		
_	09-06-89	ND	ND	ND	ND	ND		
	05-24-90	ND	ND	ND	ND	ND		
	08-29-90	i I		0.8	1.1	0.6		
	11-28-90	1		ND	ND	ND		
	03-08-91	ND	ND	ND	ND	ND		
!	10-10-91	160	13	3.2	2.0	18		
	03-09-92	ND	ND	ND	ND	ND		
	09-08-92	ND	ND	ND	ND	ND		
	00.00.00				LIP			
3	08-22-89 06-08-90	ND	ND ND	ND ND	ND	ND ND		
	08-29-90	ND ND	ND ND	ND	ND ND	ND		
	•			ND	į.	ND ND		
	11-28-90 03-08-91	ND ND	ND ND	ND ND	ND ND	, ND		
	10-10-91	ND ND	1	i	ND ND	ND ND		
	03-18-92	ND	ND ND		ND ND	ND ND		
	09-08-92	ND	ND ND	ND ND	ND	ND		
Detection Limit		50	0.5	0.5	0.5	0.5		

REPORT OF SEMI-ANNUAL GROUNDWATER SAMPLING ADOBE PLAZA
3098 Castro Valley Blvd, Castro Valley, CA

September 15, 1992

No.\*C-34262

No.\*C-34262

ROY Aguiar

ROE 34262

Bruce Hageman

# ATTACHMENT A

WELL SAMPLING LOGS

## WELL SAMPLING LOG

Project/No. ADOBE PLAZA Page	of
Well No. Mw /	e <u>9-8-9</u> 2 d <u>1455</u>
Weather CLESSE 75°F Complete	d <u>7422</u>
EVACUATION DATA	
Description of Measuring Point (MP) WEU Box AT	GRADE_
Total Sounded Depth of Well Below MP 22-88 Diameter	
- Depth to Water Below MP 10.04 of Casing	2"
= Water Column in Well 12-84	
Gallons in Casing $\frac{2 \cdot 1}{2 \cdot 1}$ + Annular Space $\frac{1}{2} \times \frac{10}{2} = 1$	al Gallons 21
(30% porosity)	
Gallons Pumped Prior to	Sampling 2/
Evacuation Method ACRYLIC HAND BAILE	~
SAMPLING DATA / FIELD PARAMETER	as
Inspection for Free Product: None DETECTED  (thickness to 0.1 inch, if any)	_
Time 1423 1437 1447	1455
Gals Removed <u>0 10 16</u>	21
Temperature <u>23.5</u> <u>23./ 22.9</u>	22.8
Conductivity 1000 1000 950	
pH 8.4 8.2 8.0	
color / Odor GRY/NO GRY/NO GRY/NO G	Sev/No
Turbidity MED MED MED	MED
Comments: NONE	

## WELL SAMPLING LOG

Project/No. ADOBE PLAZA	Page $Z$ of $S$
Site Location CASTRO VALLEY	Date <u>9-8-9</u> 2
Well No. MW 2	Time Began <u>1515</u>
Weather CLEAR 750F	Completed 1550
EVACUATION DATA	
Description of Measuring Point (MP) WELL	BOX AT GRADE
Total Sounded Depth of Well Below MP 18,46	
- Depth to Water Below MP 7.13	Diameter 2 //
	Of Casting
= Water Column in Well	10
Gallons in Casing / 8 + Annular Space _ ) (30% porosity)	$\times /O$ = Total Galions $O$
	18
	ns Pumped Prior to Sampling 18
Evacuation Method <u>ACEYUC</u> HA	IND BAILER
SAMPLING DATA / FI	ELD PARAMETERS
Inspection for Free Product: None (thickness to 0.1 inch, if any)	DETECTED
Time 15/5 1525	1333 1541
Gals Removed 0	12 18
Temperature <u>28,3</u> <u>27.1</u>	25.7 25.1
Conductivity <u>800   1000   </u>	1050 1100
н <u>7.8</u> <u>7.5</u> _	7.3 7.3
color / Odor Sey ORG Sey ORG	
Turbidity MED MES	low Low
comments: LARGE AMOUNT OF	BLACK
SUSPENDED S	50LIDS.

#### WELL SAMPLING LOG

Project/No. ADOBE PLAZA	Page <u>3</u> of <u>3</u>
Site Location <u>CASTRO VALLEY</u>	Date 9-8-92
Well No. MW3	Time Began
Weather CLEAR 75°F	Completed 1640
EVACUATION DATA	
Description of Measuring Point (MP) WEU	BOX AT GRADE
Total Sounded Depth of Well Below MP 23.30	
- Depth to Water Below MP 7.66	Diameter of Casing
= Water Column in Well 15.64	· <del></del>
Gallons in Casing 2.5 + Annular Space _	× /0 = Total Callera 2.5
(30% porosity)	70 - Total dations
Gaile	ons Pumped Prior to Sampling 25
Evacuation Method ACRYUC HAND	
**************************************	
SAMPLING DATA / F	IELD PARAMETERS
Inspection for Free Product: Nove (thickness to 0.1 inch, if any)	DETECTED_
Time 1600 1612	1622 1631
Gals Removed 0 9	18 25
Temperature <u>28.4</u> <u>26.9</u>	25,4 24.2
Conductivity <u>1580</u> <u>1780</u>	
м <u>7.7</u> <u>7.5</u>	7.4 7.3
color / Odor CLR/NO Ben/No	BEN/NO BEN/NO
Turbidity Low MED	
Comments: NONE	

# ATTACHMENT B

ANALYTICAL RESULTS: GROUNDWATER



# PRIORITY ENVIRONMENTAL LABS

Precision Environmental Analytical Laboratory

September 10, 1992

PEL # 9209019

HAGEMAN AGUIAR, INC.

Attn: Jeffrey Roth

Re: Three water samples for Gasoline/BTEX analysis.

Project name: Adobe Plaza

Project location: Castro Valley Rd. -Castro Valley, CA.

Date sampled: Sep 08, 1992

Date extracted: Sep 09-10,1992

Date submitted: Sep 09, 1992

Date analyzed: Sep 09-10,1992

#### RESULTS:

CAMPIE

SAMPLE I.D.	Gasoline	Benzene	Toluene	Ethyl Benzene	Total Xylenes
	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(nd/T)
MW 1	N.D.	N.D.	N.D.	N.D.	N.D.
MW 2	N.D.	N.D.	N.D.	N.D.	N.D.
MW 3	N.D.	N.D.	N.D.	N.D.	N.D.
Blank	N.D.	N.D.	N.D.	N.D.	N.D.
Spiked Recovery	101.2%	100.6%	97.8%	103.1%	104.8%
Duplicate Spiked Recovery	82.8%	94.0%	90.7%	96.2%	100.9%
Detection limit	50	0.5	0.5	0.5	0.5
Method of Analysis	5030 / 8015	602	602	602	602

Laboratory Director

1764 Houret Court Milpitas, CA. 95035

Tel: 408-946-9636

Fax: 408-946-9663

PEL# - 9209019.

# CHAIN OF CUSTODY RECORD

INV # 23062

PROJECT NAME AND ADDRESS: ABOTS FLAZA				SAMPLER: (Signature)	Butt	 2_ 			A / \/	210				7	//	//	7	
CASTRO VALLEY BLUD CASTRO VALLEY, CA			HAGEMAN - AGUIAR, INC. 3732 Mt. Diablo Blvd., Suite 372 Lafayette, CA 94549 (415)284-1661 (415)284-1664 (FAX)			ANALYSIS REQUESTED							//					
CROSS REFERENCE NUMBER	DATE	TIME	S O 1 L	W A T E R	STATION LO	CATION				/.	John John			/	/	/ F	/ EMARK	s
mul	9-8-92			X	MONTORING	WELL	*	1		X	X			<u> </u>		NoR	TAT	
MW 2				X	4	2,		2		X	X					11		
MW3	9-8-92			X	er	4		3		X	X					11	11	
		·	<u> </u>															
<del></del>	<del>  </del>																	
	<del> </del>		<b> </b>			<del></del>												
									1									
										]	]		]					
																		<del></del>
		<del></del>																
										1								
——————————————————————————————————————			<u>  </u>					ــــــــــــــــــــــــــــــــــــــ										
								<del></del>	<b></b>	[								
RELINQUISHED BY:	(Signature)					7											~	
					DATS TIME	72 HEC	#IAFD	BY: (Signa	uure)								DATE TIME	
RELINQUISHED BY:	(Signature)				DATE		EIVEO	8Y: (Signa	ture)							· · · · · · · · · · · · · · · · · · ·	DATE	<del></del>
The work of the same	•				TIME			TIME						<del></del>				
REUNQUISHED BY:	(Signature)				DATE	REC	EIVED	BY: (Signa	pre)								DATE	
ELINQUISHED BY:	(Signature)		·		TIME										····	<u> </u>	TIME	
	1				DATE TIME			FORLABO		3Y; (Si	gnahue)	) 					DATE 09	
		<del></del>				برناس	gamil	Marie P		$\rightarrow$						<u></u>	**** (6	: 20