

UNDERGROUND STORAGE TANK LEAK REPORT - ALAMEDA COUNTY

05/09/89

Emergency: N Case Number:
 Site Name: WEATHERFORD BMW
 Operator: NISSHO LWAI CO. Phone: (415) 654-8280
 Address: 5903 CHRISTIE AVENUE
 EMERYVILLE 94608
 Cross Street: 64TH STREET
 Case Type: Undetermined (U)
 Status: Preliminary Assessment in Progress (3)
 Abatement Methods: Excavate and Dispose
 Regional Board: 02 Local Agency: COUNTY OF ALAMEDA
 Lead Agency:
 Substance Leaked: WASTE WATER Quantity Leaked:

Responsible Party Information: MCGINNIS, LEROY
 WAST BAY PARK
 6425 #406 CHRISTIE AVENUE, EMERYVILLE, CA 94608
 Phone: () -

Reported By Information: Date Reported: 05/02/89
 BYRNE, DENNIS Represents: Local Agency
 80 SWAN WAR, ROOM 200, OAKLAND, CA 94621

Date Discovered: 05/02/89 How Discovered: Tank Closure
 Date Stopped: 05/02/89 How Stopped: Repair Tank
 Source of Leak: Tank
 Cause of Leak: Overfill

COMMENTS:

TOTAL OIL AND GREASE OF UP TO 1,500 PPM DELECTED. FURTHER EXCAVATION TO BE CONDUCTED. MONITORING WELL PROPOSAL PENDING.

ALAMEDA COUNTY
 DEPT. OF ENVIRONMENTAL HEALTH
 HAZARDOUS MATERIALS
 5/10

NORTHERN CALIFORNIA OFFICE
2645 Appian Way, Suite 27 Pinole, California 94804 (415) 223-5973

SOUTHERN CALIFORNIA OFFICE
7530 Rosedale Hwy., Bakersfield, California 93312 (805) 589-7135

CHAIN OF CUSTODY
SAMPLING ANALYSIS REQUEST

5/10/87

AMATEA COUNTY
DEPT. OF ENVIRONMENTAL HEALTH
HAZARDOUS MATERIAL

Part I: Field Section Weatherford B.M.W. Emergville Co
Collector J. Munday Date Sampled 5-4-87 Time 10:30 AM hours
Affiliation of Sampler MEGA CONT
Address 7530 Rosedale Hwy BAKSF
number street city state zip
Telephone (805) 589-7135 Company Contact Bill Pardo

LABORATORY SAMPLE NUMBER	COLLECTOR'S SAMPLE NO.	TYPE OF SAMPLE*	FIELD INFORMATION**
<u>1037</u>	<u>1</u>	<u>SOIL 1037A</u>	<u>NORTH WALL OF TANK AT BOTTOM LINE</u>
<u>1038</u>	<u>2</u>	<u>SOIL 1038A</u>	<u>EAST</u>
<u>1039</u>	<u>3</u>	<u>SOIL 1039A</u>	<u>SOUTH</u>
<u>1040</u>	<u>4</u>	<u>SOIL 1040A</u>	<u>WEST</u>

Analysis Requested TOG Total Oil & Grease 24 hour Rush ±5'

FROM W.O. TANK EXCAVATION
Special Handling and/or Storage TRANSPORT IN ICE CHEST
-40-

PART II: LABORATORY SECTION**
Received by Kate Henry Title Secretary Date 5-05-87
Analysis Required _____

* Indicate whether sample is soil, sludge, etc.
**Use back of page for additional information relative to sample location.

GENERAL & ENVIRONMENTAL CONTRACTING INC.

CHAIN OF CUSTODY RECORD

SME #
1046
1047


Walle for 1046
Joel Murdoch

BACKUP
SAMPLES

No.	Time	Status	Station Location	No. of Containers	T	O	G	Remarks
#5	5/14/11 11:05	X	4' Sod #3	1	✓			Use of #3 as Boil
#6	✓ 11:15	X	4' Sod #5 <i>(No. 1046)</i>	1	✓			✓ ✓ ✓ ✓

Received by: (Signature) <i>Joel Murdoch</i>	Date Time 5/14/11 5:17 PM	Received by: (Signature) <i>Rails Henry</i>	Relinquished by: (Signature)	Date Time	Received by: (Signature)
Received by: (Signature)	Date Time	Received by: (Signature)	Relinquished by: (Signature)	Date Time	Received by: (Signature)
Received by: (Signature)	Date Time	Received for Laboratory by: (Signature)	Remarks Samples Cool upon arrival		

⊗ SAMPLE AT 5'-GROUND WATER
 |
 REAR O.H. DOOR



- #5 - BACK UP SAMPLE - AT WATER LINE - 5'
- #6 - ✓ ✓ ✓ - IN BAY MUD - 6'
- #7 - NOT TAKEN