

Mike Bauer Project Manager Marketing Business Unit Chevron Environmental Management Company 145 S. State College Blvd Brea, CA 92821 Tel (714) 671-3200 Fax (714) 671-3440 mbauer@chevron.com

February 10, 2015

RECEIVED

By Alameda County Environmental Health at 2:23 pm, Apr 14, 2015

Mr. Jerry Wickham Alameda County Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Former Signal Oil Marine Storage and Distribution Facility

(Former Chevron Bulk Plant 206127)

2301-2311 Blanding Avenue

Alameda, California LOP Case RO0002466

Dear Mr. Wickham:

The purpose of this letter is to verify that as a representative for Chevron Environmental Management Company (Chevron), I reviewed, and concur with, the comments in the *Site Conceptual Model and Low Threat Closure Request* for the referenced facility, prepared on behalf of Chevron by Conestoga-Rovers & Associates. I declare under penalty of perjury that the foregoing is true and correct.

Please feel free to contact me at (714) 671-3207 if you have any questions.

Sincerely,

Mike Bauer Project Manager

MS Bauer



SITE CONCEPTUAL MODEL AND LOW-THREAT CLOSURE REQUEST

FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON FACILITY 206127) 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA AGENCY CASE NO. RO0002466

Prepared For:

Mr. Jerry Wickham Alameda County Health Care Services Agency Environmental Health Services 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502

> Prepared by: Conestoga-Rovers & Associates

10969 Trade Center Drive, Suite 107 Rancho Cordova, California U.S.A. 95670

Office: (916) 889-8900 Fax: (916) 889-8999

web: http:\\www.CRAworld.com

FEBRUARY 10, 2015 REF. NO. 631916D(34)



SITE CONCEPTUAL MODEL AND LOW-THREAT CLOSURE REQUEST

FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON FACILITY 206127) 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA AGENCY CASE NO. RO0002466

Brian Silva

Greg Barclay, PG 6260

Prepared by: Conestoga-Rovers & Associates

10969 Trade Center Drive, Suite 107 Rancho Cordova, California

U.S.A. 95670

Office: (916) 889-8900 Fax: (916) 889-8999

web: http:\\www.CRAworld.com

TABLE OF CONTENTS

			Page		
1.0	INTROD	UCTION	1		
2.0	SITE CONCEPTUAL MODEL (SCM)				
	2.1	SITE DESCRIPTION AND VICINITY	1		
	2.2	REGIONAL SETTING	2		
	2.3	REGIONAL AND SITE GEOLOGY AND HYDROLOGY	2		
	2.4	RELEASE HISTORY	3		
	2.5	SUMMARY OF PREVIOUS INVESTIGATION AND REMEDIAL ACTIVITIES	3		
	2.5.1	AST, PRODUCT PIPING AND DISPENSER EXCAVATION HISTORY	3		
	2.5.2	SITE ASSESSMENT AND REMEDIATION HISTORY	3		
	2.6	OFFSITE SOURCES	10		
	2.7	SOURCE	10		
	2.8	MEDIA AND CONTAMINANTS OF CONCERN	10		
	2.8.1	SOIL	11		
	2.8.2	GROUNDWATER	11		
	2.8.3	SOIL VAPOR	12		
	2.9	PLUME DELINEATION AND STABILITY	13		
	2.10	PATHWAYS AND RECEPTORS	13		
	2.10.1	SURFACE WATER	13		
	2.10.2	WATER SUPPLY WELLS	_		
	2.10.3	POTENTIAL HUMAN RECEPTORS			
	2.10.4	SUMMARY OF POTENTIAL EXPOSURE PATHWAYS	_		
	2.11	DATA GAP ANALYSIS	15		
3.0	REQUEST FOR LOW-THREAT CLOSURE				
3.0	3.1	GENERAL CRITERIA	15		
	3.2	MEDIA-SPECIFIC CRITERIA	16		
	3.2.1	GROUNDWATER-SPECIFIC CRITERIA	17		
	3.2.2	VAPOR INTRUSION TO INDOOR AIR			
	3.2.3	DIRECT CONTACT AND OUTDOOR AIR EXPOSURE	18		
4.0	RECOM	MENDATIONS	19		

LIST OF FIGURES (Following Text)

FIGURE 2	SITE PLAN
FIGURE 3	GEOLOGIC CROSS-SECTION A-A'
FIGURE 4	GEOLOGIC CROSS-SECTION B-B'
FIGURE 5	TPHD IN SOIL ABOVE ESL (0-15 FBG)
FIGURE 6	TPHG IN SOIL ABOVE ESL (0-15 FBG)
FIGURE 7	BENZENE IN SOIL ABOVE ESL (0-15 FBG)
FIGURE 8	TPHD IN GROUNDWATER
FIGURE 9	TPHG IN GROUNDWATER
FIGURE 10	BENZENE IN GROUNDWATER
	<u>LIST OF TABLES</u> (Following Text)
TABLE 1	HISTORICAL SOIL ANALYTICAL RESULTS
TABLE 2	HISTORICAL SOIL ANALYTICAL RESULTS (METALS)
TABLE 3	HISTORICAL GRAB-GROUNDWATER ANALYTICAL RESULTS
TABLE 4	HISTORICAL SOIL VAPOR ANALYTICAL RESULTS
TABLE 5	HISTORICAL INDOOR-OUTDOOR AIR ANALYTICAL RESULTS
TABLE 6	WELL CONSTRUCTION DETAILS

FIGURE 1 VICINITY MAP

LIST OF APPENDICES

APPENDIX A BORING LOGS

APPENDIX B GROUNDWATER MONITORING AND SAMPLING DATA TABLES

APPENDIX C MASS FLUX

APPENDIX D DEGRADATION CALCULATIONS

APPENDIX E SENSITIVE RECEPTOR SURVEY

1.0 INTRODUCTION

Conestoga-Rovers & Associates (CRA) is submitting this *Site Conceptual Model and Low-Threat Closure Request* for former Signal Oil Marine Storage and Distribution facility (Chevron facility 206127) located at 2301-2311 Blanding Avenue in Alameda, California (site) on behalf of Chevron Environmental Management Company (Chevron). This report provides a Site Conceptual Model (SCM) summarizing current site conditions and compares these conditions to the low-threat closure criteria specified in the *Low-Threat Underground Storage Tank Case Closure Policy* (the "*Low-Threat Policy*") adopted by the State Water Resources Control Board (SWRCB) May 1, 2012. Based on CRA's review of site conditions, the site meets the general and media-specific criteria for closure specified in the *Low-Threat Policy* and should be closed. A site conceptual model, evaluation of site conditions to the *Low-Threat Policy* case closure criteria, and recommendations are presented herein.

2.0 SITE CONCEPTUAL MODEL (SCM)

2.1 <u>SITE DESCRIPTION AND VICINITY</u>

The approximately 3.5-acre site is located on the northeast side of Blanding Avenue between Oak and Park Streets in Alameda, California (Figures 1 and 2). Land use in the site vicinity is primarily commercial and industrial. The Alameda Canal and a marina are located adjacent to the northeast side of the site. The site is currently occupied by three large commercial buildings, which are used for office, retail, and storage space, and identified as Park Street Landing at 2307-2337 Blanding Avenue.

A Sanborn map dated 1897 showed the site as occupied by several residential structures and outbuildings; the southeast portion of the site was shown as occupied by a laundry facility and a blacksmith. From at least 1930 until approximately 1961, the northwestern portion of the site was occupied by a petroleum bulk plant operated by Signal Oil & Gas Company. Former bulk plant facilities consisted of one large and seven smaller aboveground gasoline storage tanks (ASTs) within concrete secondary containment, underground piping, an office building, a loading rack, and a small structure containing gasoline pumps (Figure 2). The northeast portion of the facility was shown as occupied by a structure identified as an auto garage and also used for paint storage on Sanborn maps dated between 1932 and 1950. A rail spur was shown to service the facilities on Blanding Avenue. The central portion of the site was shown as occupied by two structures identified as wholesale tires and a can warehouse. An additional larger structure was shown in the central portion of the site that was identified as vacant on the 1948 Sanborn map and as a ladder factory on the 1950 Sanborn map. Several structures appeared to be present in the southeast portion of the site in the 1939 aerial photograph. However, only one or two small

sheds were shown in this area on the 1948 and 1950 Sanborn maps. In the 1958 aerial photograph, the ladder factory structure no longer appeared present and the southeast portion of the site appeared vacant and used for parking. Between 1957 and 1963, the buildings at the site were reportedly removed; it is assumed that the ASTs and piping were also removed at this time. In the 1965 aerial photograph, all the bulk plant facilities appear to have been removed and the majority of the site appears occupied by a construction materials yard with several small structures. Several additional structures also appear present in the southeast portion of the site. From 1973 to 1983, the northwestern portion of the site reportedly was used as a construction yard and for boat repair activities; and the southeastern portion was occupied by a restaurant, paved parking area, and a possible automobile sales lot. In 1987, the site was redeveloped with the current configuration.

2.2 REGIONAL SETTING

The site is located along the northeastern edge of Alameda adjacent to the Alameda Harbor Canal. The City of Alameda is an island surrounded by the San Francisco Bay to the south and the Alameda Harbor Canal to the north. The City of Oakland sits directly across from the Alameda Canal. The site is at an elevation of approximately 12 feet above mean sea level and is relatively flat.

2.3 REGIONAL AND SITE GEOLOGY AND HYDROLOGY

The area was originally marshlands which were filled in with a mixture of man-made refuse, sand dredged from San Francisco Bay, bay mud, and imported fill that ranges in thickness from 2 to 25 feet, underlain by fat clay (bay mud) that ranges in thicknesses from a few inches to 95 feet. According to the East Bay Municipal Utility District (EBMUD), Alameda's drinking water begins at the Mokelumne River watershed in the Sierra Nevada and extends 90 miles to the East Bay.

Previous investigation indicates that subsurface soil beneath the site generally consists of silty sand and clayey sand from just beneath grade to approximately 5 to 9 feet below grade (fbg). Fill consisting of black sand and debris, including concrete fragments, has been reported in several borings at shallow depths. A 4- to 5-foot thick layer of clay with some sand underlies the silty sand and clayey sand. Below the clay is silty sand and sandy silt to the maximum depth explored of approximately 20.5 fbg. Groundwater is typically encountered in site borings at approximately 14.5 to 15 fbg within the silty sand and sandy silt, and subsequently rises in the

United States Geological Survey publication, 1959, Areal and Engineering Geology of the Oakland West Quadrangle, California.

borings/wells to approximately 7 to 10 fbg suggesting the groundwater beneath the site is semi-confined. Cross-sections depicting soil encountered beneath the site are presented as Figures 3 and 4. Boring logs are included in Appendix A.

Depth to groundwater on site typically ranges from approximately 3 to 10 fbg with flow predominately toward the northeast at a gradient ranging from 0.01 to 0.02. A rose diagram depicting groundwater flow direction is presented on Figure 2.

2.4 RELEASE HISTORY

No records of historical releases have been located for the site. Based on soil and groundwater data, the source area appears to be from the former ASTs and loading rack area. All facilities were removed between 1957 and 1965.

2.5 SUMMARY OF PREVIOUS INVESTIGATION AND REMEDIAL ACTIVITIES

Several environmental investigations have been performed at the site beginning in 1995. To date, 28 soil borings, 7 groundwater monitoring wells, 2 piezometers, 3 shallow soil sample locations, 6 soil vapor probes, and 7 sub-slab soil vapor wells have been completed at the site. Quarterly groundwater monitoring and sampling was conducted from 2001 until 2013 when the schedule was changed to semi-annual monitoring/sampling, which is ongoing. The approximate well and boring locations are shown on Figure 2. Historical soil, groundwater, soil vapor, and air analytical data are presented in Tables 1 through 5 and Appendix B. Well construction details are summarized in Table 6.

2.5.1 AST, PRODUCT PIPING AND DISPENSER EXCAVATION HISTORY

All facilities were removed between 1957 and 1965. No other information has been located regarding the details of the facility removal and the 1987 redevelopment activities.

2.5.2 SITE ASSESSMENT AND REMEDIATION HISTORY

In February 1995, Geomatrix Consultants, Inc. (Geomatrix) advanced eight soil borings to approximately 10 feet below grade (fbg) in the northwestern portion of the site. Groundwater was not encountered in the borings. Two to three soil samples were collected at various depths from each boring for laboratory analysis (Table 1). Nineteen samples were analyzed for total

petroleum hydrocarbons as diesel (TPHd) and gasoline (TPHg) and benzene, toluene, ethylbenzene, and xylenes (BTEX). TPHd was detected in the majority of the samples at concentrations ranging from 10 to 250 milligrams per kilogram (mg/kg). TPHg was detected in six of the samples at concentrations ranging from 4.0 to 2,000 mg/kg. BTEX were also detected in several of the samples (benzene up to 3.7 mg/kg). The highest concentrations of petroleum hydrocarbons generally were detected in borings SB-2 and SB-4 located in the vicinity of the former ASTs and gasoline pump, respectively, between 4 and 7 fbg. One sample from each boring (depths ranging from 0.5 to 3 fbg) was also analyzed for CAM 17 metals. The detected metals concentrations generally appeared to be within the range of natural background levels with the exception of slightly elevated arsenic in a few samples (Table 2). Arsenic was detected in the samples collected at 1 fbg from borings SB-3, SB-4, and SB-6 at 68 mg/kg, 46 mg/kg, and 130 mg/kg, respectively. As a result, deeper samples collected from borings SB-3 (6.5 fbg) and SB-6 (8 fbg) were also analyzed for arsenic; arsenic was not detected in the sample collected from SB-3, but was detected at 2.5 mg/kg in the sample collected from SB-6. Based on these results, the soil impacted with arsenic appeared to be of limited vertical extent. The Geomatrix report did not include these analytical results in a table or provide the analytical report. They were only discussed in the text of the report. Three soil samples (SB-4-7', SB-5-6', and SB-8-7') were also analyzed for VOCs, which were not detected. Based on the soil analytical results, a shallow groundwater survey was recommended to evaluate if groundwater had been impacted by petroleum hydrocarbons. A summary of this investigation can be found in Geomatrix's September 1995 Soil Investigation and Shallow Groundwater Survey, Northwest portion of Park Street Landing Site.

In April 1995, Geomatrix collected grab-groundwater samples from 10 shallow borings (GWS-7 through GWS-16) drilled to depths of 15 to 21.5 fbg at the site. Based on an assumed groundwater flow direction toward Alameda Canal, borings GWS-7 through GWS-12 were located in the northeastern portion of the site adjacent to the canal to evaluate if impacted groundwater was flowing toward the canal. Groundwater was reported at a depth of approximately 9 fbg. Borings GWS-13 through GWS-15 were located on the southwest and northwest property boundaries in the assumed upgradient and perimeter crossgradient directions to evaluate the quality of groundwater coming onto the site. Boring GWS-16 was located to the northeast of the former ASTs and was drilled approximately 6 feet deeper than the remaining borings to evaluate deeper groundwater quality. Groundwater samples were analyzed for TPHd, TPHg, and BTEX; the samples were filtered by the laboratory to remove turbidity and a silica-gel cleanup was performed to remove non-petroleum organic matter prior to the TPHd analysis (Table 3). TPHd was detected in samples collected from borings GWS-8 through GWS-11 at concentrations ranging from 60 micrograms per liter (μg/L) (GWS-8) to 1,200 µg/L (GWS-9). TPHg was detected in samples collected from borings GWS-8 through GWS-11 and GWS-16 at concentrations ranging from 70 (GWS-16) to 22,000 µg/L (GWS-9). Benzene was detected in samples collected from borings GWS-8 through GWS-10 at

concentrations of $36 \,\mu g/L$, $6,200 \,\mu g/L$, and $880 \,\mu g/L$, respectively. Toluene, ethylbenzene, and xylenes (up to $1,200 \,\mu g/L$) were also detected in several of the samples. The highest concentrations were detected in boring GWS-9 located downgradient of the gasoline pump and loading rack. Petroleum hydrocarbons were not detected in the upgradient borings GWS-13 through GWS-15. The deeper sample (GWS-16) contained only low to trace hydrocarbon concentrations.

A black granular material was encountered in boring GWS-7 near the northern corner of the site from approximately 2.5 to 6 fbg. This material appeared similar to a small pile of black granular material observed on the northwestern property boundary that appeared to have originated from the adjacent property (a metal fabrication company). A sample of this material was collected and analyzed for TPHd, VOCs, semi-VOCs, and CAM 17 metals. An elevated concentration of copper (1,700 mg/kg) was detected in the sample. The detected concentration did not exceed the Total Threshold Limit Concentration (TTLC) of 2,500 mg/kg, which is the concentration above which a waste may be considered hazardous in California. The sample was also analyzed for soluble copper using the Waste Extraction Test (WET) method; 0.04 milligrams per liter (mg/L) was detected. The detected soluble lead concentration did not exceed the Soluble Threshold Limit Concentration (STLC) of 25 mg/L, which is also the concentration above which a waste may be considered hazardous in California. Details of this investigation were presented in the September 1995 Geomatrix report titled *Soil Investigation and Shallow Groundwater Survey, Northwestern Portion of the Park Street Landing Site*.

In July 1998, RRM, Inc. (RRM) performed a Tier 1 Risk-Based Corrective Action (RBCA) assessment to evaluate potential health risks posed by residual petroleum hydrocarbons in soil and groundwater at the site. Based on the results, RRM recommended the collection of site-specific data to complete a Tier 2 RBCA evaluation, identification of the beneficial uses of groundwater beneath the site, evaluation of background water quality in Alameda Canal, and assessment of biodegradation of hydrocarbons at the site. Results of the Tier 1 evaluation were presented in RRM's July 24, 1998 report entitled *Risk-Based Corrective Action (RBCA) Tier 1 Evaluation, Park Street Landing Site*.

In October 1998, RRM performed an additional soil and groundwater investigation at the site. Four borings (SB-9 through SB-12) were advanced to depths of 15 to 18 fbg and eight soil samples were collected at various depths for analysis of TPHd, TPHg, BTEX, and methyl tertiary butyl ether (MTBE). TPHd was detected in soil samples collected at 5, 13, and 15 fbg from boring SB-9 (3,300 mg/kg, 1,300 mg/kg, and 1.2 mg/kg, respectively), in the sample collected at 5.5 fbg from boring SB-10 (130 mg/kg), and in the sample collected at 6 fbg from boring SB-11 (60 mg/kg). TPHg was detected in soil samples collected at 5 and 13 fbg from boring SB-9 (130 mg/kg and 900 mg/kg, respectively), and in a sample collected at 6 fbg from boring SB-11 (140 mg/kg). BTEX (up to 3.3 mg/kg) were detected in soil samples collected from borings SB-9

and SB-11. MTBE (using EPA Method 8020) was only detected in a sample collected at 13 fbg from boring SB-9 (12 mg/kg). Following initial TPHd analysis, two rounds of silica gel cleanup followed by TPHd analysis were performed on soil samples from boring SB-9. Based on reduction of TPHd concentrations, RRM concluded that biodegradation was occurring and natural organic matter was present in the subsurface.

Grab-groundwater samples were collected from each boring and analyzed for TPHd, TPHg, BTEX, and MTBE. TPHd was detected in samples collected from borings SB-9 (83,000 μ g/L), SB-10 (97 μ g/L), and SB-11 (270 μ g/L). TPHg was only detected in samples collected from borings SB-9 (14,000 μ g/L) and SB-11 (310 μ g/L). Benzene and MTBE (using EPA Method 8020) were detected in the sample collected from boring SB-9 (1,400 and 260 μ g/L, respectively); however, after re-analyzing the sample for MTBE using EPA Method 8260, MTBE was not detected. Toluene, ethylbenzene, and xylenes (up to 630 μ g/L) were detected in samples collected from borings SB-9 and SB-11. As with the soil samples, lower TPHd concentrations were reported using a silica-gel cleanup. Using boring elevation and depth to water data from the borings, groundwater flow direction was calculated to be northerly. Based on natural biodegradation indicator parameters in groundwater (dissolved oxygen, oxidation-reduction potential, nitrate, and sulfate), RRM concluded that petroleum hydrocarbons were being degraded both aerobically and anaerobically, although anaerobic processes appeared dominant.

Three grab-water samples (CS-1 through CS-3) were collected from Alameda Canal (Figure 2) and analyzed for TPHd, TPHg, BTEX, and MTBE; no analytes were detected. Water level measurements were collected from Alameda Canal and four temporary wells placed in borings SB-9 through SB-12 to evaluate potential tidal influence on groundwater beneath the site. RRM reported fluctuations in borings SB-10 through SB-12 were minimal indicating that groundwater was tidally influenced to a limited degree in these areas. A more significant fluctuation was observed in SB-9 suggesting groundwater in this area was tidally influenced, and tidal fluctuations would tend to stabilize the petroleum hydrocarbon plume in this area. RRM concluded that two concrete sea walls separating shallow groundwater beneath the site from canal waterlimit tidal influence. Based on the site data, relevant beneficial uses, and associated water quality parameters, the most applicable beneficial use of groundwater beneath the site was determined to be freshwater replenishment to surface water.

A well survey performed within a ½-mile radius of the site identified one recovery well, one irrigation well, five extraction wells, and two industrial wells within the search radius. All wells were either located upgradient of the site or across Alameda Canal. Based on the results of the Tier 2 RBCA evaluation, RRM concluded petroleum hydrocarbon concentrations in soil and groundwater at the site did not exceed the site-specific target levels (SSTLs). Details of this investigation were presented in RRM's May 7, 1999 report entitled *Soil and Groundwater Investigation Results, Former Signal Oil Marine Terminal*.

In December 2000, Gettler-Ryan Inc., under the supervision of Delta Environmental Consultants, Inc. (Delta), installed one groundwater monitoring well (MW-1) along the northeastern portion of the site adjacent to the Alameda Canal. Soil samples were collected at depths of 5, 10, and 15 fbg from the well boring and analyzed for TPHd, TPHg, BTEX, and MTBE. TPHd was detected in samples collected at 5 and 10 fbg (30 and 160 mg/kg, respectively). TPHg was detected in the sample collected at 10 fbg (320 mg/kg). Low concentrations of BTEX were detected in all three samples, and MTBE was not detected in any of the samples. Initial groundwater samples collected from the well contained TPHd, TPHg, and benzene at 1,100 μ g/L, 5,210 μ g/L, and 868 μ g/L, respectively. Details of this investigation were presented in Delta's April 10, 2001 report entitled *Monitoring Well Installation Report*.

In January 2004, Cambria Environmental Technology, Inc. (Cambria) collected three surface soil samples (S1, S2, and S3) from the bank above the western shore of the Alameda Canal. Sample S2 was collected directly down-slope of well MW-1 near a water seep observed on the slope above the canal. Samples S1 and S3 were collected approximately 70 feet east and 90 feet north of well MW-1, respectively, to evaluate background concentrations. The three samples were analyzed for TPHd, TPHg, BTEX, and MTBE. TPHg, BTEX, and MTBE were not detected in any of the samples. TPHd was detected in samples S1, S2, and S3 at 14 mg/kg, 220 mg/kg, and 220 mg/kg, respectively. The laboratory chromatographs indicated that the hydrocarbon pattern observed in these soil samples was not typical of diesel fuel. Therefore, it was concluded the TPHd detections may have represented either highly-degraded diesel fuel from various historical onsite and nearby operations, or residual organic material of unknown origin present in local fill material. Details of this investigation were presented in Cambria's February 18, 2004 report entitled *Soil Sampling Report*.

In July 2008, CRA advanced six soil borings (SB-13 through SB-15 and SB-17 through SB-19) to a maximum depth of 16 fbg to further assess soil and groundwater conditions, and advanced six additional borings to depths of 4.5 to 6 fbg for installation of soil vapor wells (VP-1 through VP-6) to assess potential vapor intrusion. Soil boring SB-16 was cleared to 3 fbg but could not be completed due to refusal encountered at three locations (SB-16A, B, and C). Shallow soil samples were collected from SB-16A, B, and C at depths of 1 to 3 fbg, and from the other 12 borings at depths of 1 to 10 fbg. Soil analytical data indicated that the majority of TPHd and TPHg concentrations in soil are generally located in the area of and downgradient of the former ASTs (Table 1). The highest concentrations were detected in boring VP-4 at 5 fbg. Relatively low concentrations of TPHd and TPHg were detected in the perimeter borings. Low concentrations of petroleum-related VOCs were also detected in the majority of the soil samples. The BTEX and VOC concentrations generally did not exceed the ESLs, with the exception of a few samples, and concentrations generally attenuate or were significantly reduced at 10 fbg. Concentrations of

metals were consistent with background levels and only exceeded the ESLs in a few of the samples (Table 2). Metals in shallow soil across the northwest portion of the site do not appear to be a result of former bulk plant operations. With the exception of barium in MW-1, metals do not appear to have impacted groundwater. Chlorinated solvents were not detected in any of the soil samples.

Analysis of grab-groundwater samples from SB-13 through SB-15, SB-18, and SB-19 indicated the highest concentrations of hydrocarbons in groundwater were located downgradient (north-northeast) of the former ASTs. TPHd, TPHg, and benzene were detected in downgradient boring SB-18 at 19,000 μ g/L, 3,800 μ g/L, and 590 μ g/L, respectively; in boring SB-19 adjacent to the former large AST, TPHd, TPHg, and benzene were detected at 1,600 μ g/L, 650 μ g/L, and 3 μ g/L, respectively (Table 3). Relatively low concentrations of TPHd (up to 750 μ g/L) were detected in perimeter borings SB-13, SB-14, and SB-15. Low concentrations of TCE, cis-1,2-DCE, and vinyl chloride were reported in the sample from boring SB-15 on the northeast corner of the site.

The highest hydrocarbon concentrations in soil gas were detected in vapor wells VP-4, VP-5, and VP-6 located in the area of the former ASTs (Table 4). Significantly lower concentrations were detected in vapor wells VP-1 and VP-2 located downgradient of VP-4. Chlorinated solvents were not detected in the soil vapor samples. Additional details of this investigation are presented in CRA's October 2008 report entitled *Site Investigation Report*.

In June 2009, CRA installed monitoring wells MW-2 through MW-5 to total depths of 16 to 20.5 fbg to further evaluate soil and groundwater quality beneath the site. The wells were installed within the area of the former ASTs (MW-3), and north (MW-5), south (MW-2), and east (MW-4) of the former ASTs. Soil analytical data suggested the majority of TPHd and TPHg in soil is located north to south through the former AST area and generally decreases with depth. The highest TPHd concentration detected was 610 mg/kg from boring MW-3 at 4 fbg (Table 1), and the highest TPHg concentration detected was 1,100 mg/kg from boring MW-2 at 4.5 fbg.. No petroleum hydrocarbons were detected in perimeter well boring MW-4. No grab-groundwater samples were collected.

CRA also installed sub-slab vapor points beneath the two western buildings at the site in order to further evaluate potential vapor intrusion beneath the buildings. Two sub-slab vapor points (VP-7 and VP-8) were installed inside 2317 Blanding Avenue and five sub-slab vapor points (VP-9 through VP-13) were installed inside 2307 Blanding Avenue. The highest hydrocarbon concentrations in soil gas were detected in vapor points VP-9 and VP-13, located west-southwest of the former ASTs (Table 4). Lower concentrations were detected in vapor points VP-8, and VP-10 through VP-12. All detected concentrations were below the shallow soil gas ESL of 29,000 micrograms per cubic meter (μg/m³). Target chlorinated solvents were not

detected in the soil vapor samples. Additional details of this investigation are presented in CRA's September 8, 2009 *Well Installation and Sub-Slab Vapor Sampling Report*.

In October 2009, CRA re-installed sub-slab vapor points VP-9 through VP-13 due to ambient air leaks detected during the initial sampling, and the sub-slab vapor probes were re-sampled. Results of the sampling of the sub-slab vapor wells after being re-installed indicated no soil vapor concentrations in four of the five probes; low concentrations were reported in VP-10 (Table 4). To further evaluate elevated soil vapor concentrations initially detected in vapor wells VP-1 through VP-6, the vapor wells were sampled. Results of the sampling were consistent in vapor wells VP-3 through VP-5; however, results of sampling VP-1 and VP-2 were not consistent with initial results and indicated no TPHg or benzene vapor concentrations at each of these locations. Soil vapor samples could not be collected from VP-1 and VP-6 due to excess moisture in the vapor well tubing most likely due to the wet weather. Additional details are presented in CRA's December 2, 2009 *Vapor Sampling Report*.

In August 2010, CRA replaced well MW-1 with a more discretely screened well, MW-1RB, and installed two new wells MW-1RA and MW-6 to depths between 13 to 20 fbg to further evaluate shallow groundwater near Alameda Canal. Wells MW-1RA and MW-1RB are located in the vicinity of former well MW-1 and MW-6 is located downgradient of well MW-5. The highest TPHd and TPHg concentrations detected in soil were 260 mg/kg at 10 fbg and 490 mg/kg at 13.5 fbg, respectively from boring MW-1RA. Only trace concentrations of hydrocarbons were detected in boring MW-6 (Table 1). Initial groundwater sampling of wells MW1RA, MW-1RB and MW-6 in October 2010 indicated higher concentrations of hydrocarbons in MW-1A compared to MW-1RB and MW-6 (Appendix A). Additional details are presented in CRA's September 29, 2010 Well Installation Report.

In September 2012, CRA installed piezometers P-1 and P-2 to total depths of 20 fbg and 12 fbg, respectively, in order to further evaluate the interaction between on site groundwater flow and potential mass flux to Alameda Canal. Submersible data loggers capable of measuring conductivity, temperature, and depth to water were placed in site wells (MW-1RA through MW-6) and newly installed piezometers (P-1 and P-2) to evaluate the effects of tide and saline/freshwater interactions on groundwater flow. A data logger was also installed in a temporary stilling well placed on the adjacent pier to collect water level fluctuations in Alameda Canal. Periodic depth-to-water measurements were manually collected during a two-week period. Water level and conductivity data suggest wells screened within the deeper silty sand zone (MW-1RB through MW-6 and P-1) are tidally influenced and shallow wells MW-1RA and P-2 show little, if any tidal influence. During high tide there was minor groundwater flow from the canal toward the site, but overall groundwater flow was toward the canal. It was concluded that mass flux into Alameda Canal from the site is significantly less than the marine and estuary habitat ESLs for site constituents of concern and do not pose a threat to Alameda Canal.

Additional details can be found in CRA's November 30, 2012 *Piezometer Installation and Tidal Study Report*.

2.6 OFFSITE SOURCES

The site and surrounding properties have been occupied by industrial operations since the early 1900s. A site (known as The Collins Property) located at 2235 Clement Avenue (west of site) is currently an open Envirostor case (#01390007) with The Department of Toxic Substances Control (DTSC). The site operated as several industrial businesses and plants over the years including a diesel engine manufacturing plant for marine vessels and a foundry for brass casting. Site investigation determined that soil and groundwater have been impacted with metals (arsenic, lead and total chromium), TPH compounds (benzene, toluene, ethylbenzene, and xylenes), and semi-volatile organic compounds (SVOC) such as naphthalene, 2-methylnaphthalene, chrysene, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene anddibenzo (a,h)anthracene. A March 15, 2007 DTSC letter stated that remedial actions implemented at the site have been completed. It is unknown if future cleanup and investigation are warranted by the DTSC.

2.7 **SOURCE**

The primary source of hydrocarbons, the ASTs and piping, were removed by 1965 indicating that a release or releases of hydrocarbons occurred 50 or more years ago. The highest remaining concentrations of TPHd, TPHg, and benzene are 6,900 mg/kg, 11,000 mg/kg, and 16 mg/kg, respectively, from soil samples collected from VP-4. Given the tight nature of the site soils, migration of hydrocarbons through soil to groundwater and migration in groundwater is likely limited in extent, and oxygen exchange in this type of soil is very limited resulting in hydrocarbons still remaining at the concentrations found in soil and soil vapor at the suspected source areas during past site investigation.

2.8 MEDIA AND CONTAMINANTS OF CONCERN

The primary constituents of concern (COCs) are TPHd (soil and water), TPHg (soil, soil vapor, water), benzene (soil vapor and water), and ethylbenzene (soil vapor).

Toluene, xylenes, methyl tertiary butyl ether (MTBE), and other volatile organic compounds (VOCs) are not considered COCs due to the relative low concentrations detected. Metals are considered background.

2.8.1 **SOIL**

Eighty-one soil samples have been collected between the depths of 0.5 fbg and 15 fbg and analyzed during confirmation sampling, soil boring, and monitoring well advancement activities since 1995. Hydrocarbons in soil are primarily detected in the area of VP-4, within the vicinity of the former fueling facility at a depth of approximately 5 fbg. The highest historical residual hydrocarbon concentrations detected at VP-4 include 6,900 mg/kg TPHd and 11,000 mg/kg TPHg. Concentrations that exceed applicable ESLs² are primarily detected between 2 to 14 fbg. Concentrations decrease with depth and are vertically delineated outside the source area and to low levels at depth within the source area by confirmation samples collected from MW-1, MW-4, MW-6, and SB-9 at 15 fbg (Figures 3 through Figure 7). Historical soil analytical results are presented as Table 1 through 2. Soil data presented in Table 1 were also compared to the Low-Threat Policy criteria and results are presented in Section 3.

2.8.2 GROUNDWATER

Groundwater has been monitored and sampled on a regular basis since 2001. Historical groundwater data tables and Gettler-Ryan's August 4, 2014 *Groundwater Monitoring and Sampling Report,* which includes the results of the most recent monitoring and sampling event (July 25, 2014), are in Appendix B. The lateral and vertical extent of dissolved hydrocarbons above water quality objectives (WQOs³) is defined.

The majority of total petroleum hydrocarbon mass in groundwater appears confined to the area of the former fuel pumps, and north of the former aboveground storage tanks. As of the most recent monitoring and sampling event, dissolved TPHd was detected above the ESL in six of the seven wells. However, TPHd analyzed using a 10-gram silica gel column cleanup (SGC) resulted in a significant reduction in dissolved TPHd concentrations (two of the seven wells detected above ESL for TPHd). This suggests that samples not analyzed using SGC contain polar non-hydrocarbons and/or non-dissolved petroleum compounds. The TPHg plume is limited in extent, localized around onsite well MW-5 and defined by crossgradient well MW-4, and upgradient by well MW-2. Benzene was detected during the most recent sampling event; however, benzene detections are concentrated in the source area and appear to be generally stable. The groundwater flows consistently towards the northeast (Alameda Canal). However,

Environmental Screening Level (ESL) from the San Francisco Regional Water Quality Control Board's (RWQCB's) Screening for Environmental Concerns at Sites with Contaminated Soil and Groundwater, Interim Final November 2007, Revised May 2008

Water Quality Objectives (WQO) from the San Francisco Water Quality Control Board (RWQCB), Chapter 3, 3.1 Water Quality Objectives for the state of California

CRA demonstrated in the 2012 tidal mass flux study that the impacted groundwater beneath the site is not impacting the water of the canal⁴. The study findings are presented as Appendix C. Degradation calculations showing dissolved TPHd with SGC, TPHg and benzene concentrations from MW-3, and MW-5 are presented in Appendix D. Isoconcentration contours for TPHd, TPHg, and benzene are presented in Figures 8 through 10. Groundwater analytical data were compared to *Low-Threat Policy* criteria as presented in Section 3.2.1. The downgradient extent of the dissolved petroleum hydrocarbon plume (TPHd and TPHg) is estimated to be less than 100 feet from the source area.

2.8.3 SOIL VAPOR

Soil vapor sampling was initiated at the site in August 2008. The highest soil vapor concentrations detected were from vapor wells VP-4 and VP-5 in August and October 2008 at concentrations of 110,000 micrograms per cubic meter ($\mu g/m^3$) TPHd in VP-5, 220,000,000 $\mu g/m^3$ TPHg, 1,100,000 $\mu g/m^3$ benzene, and 650,000 $\mu g/m^3$ ethylbenzene in VP-4. Subsequent soil vapor sampling indicates concentrations are relatively stable or decreasing.

Sub-slab vapor sampling was initiated in July 2009. The highest sub-slab vapor concentrations were mainly detected during the first two sampling events in August and October 2009, with subsequent sampling events indicating minor or concentrations below the detection limit. The highest sub-slab vapor concentrations detected were from sub-slab vapor probes VP-8, VP-9, and VP-10 in July 2009 and June 2010 at concentrations of 8,800 μ g/m³ TPHg in VP-9, 24 μ g/m³ benzene and 71 μ g/m³ toluene in VP-8, and 52 μ g/m³ ethylbenzene in VP-10. During the last two sub-slab sampling events, all COCs were below ESLs except for a slight exceedance of benzene in VP-8 during the June 2010 sampling event; benzene was below the ESL in VP-8 during the most recent (November 2010) event.

Indoor and outdoor air sampling was initiated in June 2010. Indoor and outdoor air samples collected in site buildings contained relatively low concentrations with the highest at indoor location IA-3 at $530\,\mu\text{g/m}^3$ TPHg, $4.20\,\mu\text{g/m}^3$ benzene, and $6.00\,\mu\text{g/m}^3$ ethylbenzene. The disparity between the sub-slab and indoor air results suggest that other sources within the buildings are contributing to the indoor air results. Each of the suites where the indoor air samples were collected had numerous sources of VOCs present/stored inside and the outdoor air sample also contained TPHg and benzene levels above the indoor air ESLs.

Current sub-slab results are all below ESLs for indoor air under commercial/industrial land use adjusted by a factor of 100 to account for attenuation between sub-slab and indoor air (Table E,

_

⁴ CRA, Piezometer Installation and Tidal Study Report, November 30, 2012

SFRWQCB, 2008). This further supports that there are other indoor sources contributing to the indoor air results. While there are highly elevated concentrations observed in the vapor well samples collected at 5 fbg, sub-slab results show low level vapor impact in near surface soil suggesting vapor intrusion from deeper soil (5 fbg) into the site buildings is not a risk. The soil vapor, sub-slab vapor, and indoor and outdoor air analytical results are presented in Tables 5 and 6. As discussed in Sections 3.2.2 and 3.2.3 below, benzene concentrations are compared to *Low-Threat Policy* criteria in assessing vapor intrusion risk.

2.9 PLUME DELINEATION AND STABILITY

The remaining dissolved hydrocarbon plume appears to be located in the area of the former loading rack and ASTs (MW-5). The tidal influence study performed by CRA in 2012 demonstrated that the plume is stable and flows toward the Alameda Canal and that there is limited to no impact to the surface water of the canal by the remaining hydrocarbon plume. Further details are presented in the CRA *Piezometer Installation and Tidal Study Report* dated November 30, 2012.

2.10 PATHWAYS AND RECEPTORS

2.10.1 SURFACE WATER

The nearest surface water to the site is Alameda Canal which is located along the northern property boundary. Historical grab surface water samples collected from canal sample location CS-2 indicated only minor, sporadic hydrocarbon detections (mainly total petroleum hydrocarbons as diesel [TPHd] since July 2001). Given the limited extent and concentration of the residual dissolved hydrocarbon plume, results of the tidal influence study, and background conditions, surface water bodies do not appear to be at risk of future impact by the site plume. The 2011 sensitive receptor study findings are presented in Appendix E.

2.10.2 WATER SUPPLY WELLS

In June 2011, CRA reviewed Department of Water Resources (DWR) well completion reports to identify wells within a 2,000-foot radius of the site. DWR records identified two industrial wells within the 2,000-foot radius of the site located at the same property on 2307 Clement Avenue, approximately 310 to 340 feet southwest of the site (Appendix E). No domestic, irrigation, or municipal water supply wells were identified.

The wells identified in the survey are not considered at risk from the petroleum hydrocarbons originating from the site, as these wells are located upgradient of the site and petroleum hydrocarbon concentrations detected in well MW-2 onsite, nearest to these wells, have been below ESLs since sampling began. Given the relative lack of petroleum hydrocarbon detections in MW-2 and the direction of groundwater flow, it is unlikely that the shallow dissolved petroleum hydrocarbon plume onsite is migrating to the identified well receptors; therefore they are not considered at risk. The location and construction details of these wells and the other wells identified from DWR records are presented in Appendix E.

2.10.3 POTENTIAL HUMAN RECEPTORS

The site is occupied by three large commercial buildings, which are used for office, retail, and storage space. With the exception of planters and the area between the site and the Alameda Canal, the site is capped with asphalt and concrete slabs under the buildings. As such, the general public is not considered a potential receptor to residual impacted soil under current site conditions. There are no current plans for redevelopment; however, if redevelopment were to occur, construction workers performing trenching or excavating activities at the site could potentially encounter the residual impacted shallow soil. Additionally, the maximum residual COC concentrations in soil presented in Section 2.8.1 are well below the ESLs associated with direct exposure by construction/trench workers per Regional Water Quality Control Board — Region 2 ESL Lookup Table K-3, Interim Final December 2013. Thus, potential exposure to impacted soil by construction workers is not a significant concern.

Based on information provided in CRA's 2011 sensitive receptor search, one school (Alameda Christian School) was identified approximately 1,775 feet southwest of the site (upgradient). Due to the distance and direction from the site, the school should not be impacted by the site. No daycare centers, hospitals, or nursing homes were identified within a 2,000-foot radius of the site (Appendix E). Based on soil and groundwater analytical results, dissolved plume extent and the site's current use as commercial/industrial, there does not appear to be a risk to the sensitive receptors listed above or a vapor intrusion risk to future workers or occupants in an onsite building.

2.10.4 <u>SUMMARY OF POTENTIAL EXPOSURE PATHWAYS</u>

Based on the above evaluation, there do not appear to be any potential exposure pathways of concern.

2.11 DATA GAP ANALYSIS

Based on the information presented above, there are no data gaps at the site.

3.0 REQUEST FOR LOW-THREAT CLOSURE

On August 17, 2012, the SWRCB adopted the *Low-Threat Policy* via Resolution 2012-0016. The intent of the *Low-Threat Policy* is to increase cleanup process efficiency at petroleum release sites. A benefit of improved efficiency is the preservation of limited resources for mitigation of releases posing the greatest threat to human and environmental health. Per the *Low-Threat Policy*, sites that meet the specified general and media-specific criteria pose a low threat to human health, safety, or the environment and are appropriate for case closure pursuant to Health and Safety Code section 25296.10. The *Low-Threat Policy* further states that those sites that meet the criteria for low-threat closure do not require further corrective action and shall be issued a uniform closure letter. Based on the information presented herein, the site meets all General and Media-Specific Criteria within the *Low-Threat Policy*. Discussion of site conditions with respect to each criterion is provided in this section.

3.1 GENERAL CRITERIA

The eight general criteria that must be satisfied by all candidate sites, and the site-specific evaluation for each of these criteria, are presented below.

a. The unauthorized release is located within the service area of a public water system.

<u>Satisfied:</u> As described in Section 2.3, water for the site and surrounding properties originates from the Mokelumne River watershed in the Sierra Nevada.

b. The unauthorized release consists only of petroleum.

<u>Satisfied</u>: The unauthorized release at the site has been characterized as a release of petroleum-based products (gasoline and related constituents).

c. The unauthorized ("primary") release from the UST system has been stopped.

<u>Satisfied</u>: Petroleum storage and handling equipment that were potential sources of the release (loading rack, product piping, and ASTs) were removed by 1965. Environmental investigation beginning in 1995 and monitoring since 2001 indicate that no additional releases have occurred. Therefore, site data supports that the primary release has been stopped.

d. Free product has been removed to the maximum extent practicable.

<u>Satisfied:</u> No light non-aqueous phase liquid (LNAPL) has been observed in any of the site wells.

e. A conceptual site model that assesses the nature, extent, and mobility of the release has been developed.

<u>Satisfied:</u> Previous reports (referenced in Section 2.4) and information contained herein contain all elements of a conceptual site model.

f. Secondary source has been removed to the extent practicable.

<u>Satisfied:</u> Review of historical documents did not contain information related to secondary source removal. However, soil and groundwater data from the site demonstrate that hydrocarbon impact is limited to the areas of the former ASTs and loading rack. The soil observed beneath the site is mostly clay and appears to have limited petroleum hydrocarbon migration.

g. Soil and groundwater has been tested for MTBE and results reported in accordance with Health and Safety Code section 25296.15.

Satisfied: Soil and groundwater samples have been analyzed for MTBE, and reported in accordance with Health and Safety Code section 25296.15.

h. Nuisance as defined by Water Code section 13050 does not exist at the site.

<u>Satisfied:</u> Conditions defined as a "nuisance" in Water Code section 13050 do not exist at the site.

3.2 MEDIA-SPECIFIC CRITERIA

Impacts to human health and the environment can occur due to releases from USTs through contact with contaminated media (groundwater, surface water, soil, and soil vapor) via various exposure pathways. In the *Low-Threat Policy*, the most common exposure scenarios have been combined into three media-specific criteria:

- Groundwater
- 2. Vapor Intrusion to Indoor Air
- 3. Direct Contact and Outdoor Air Exposure

16

3.2.1 GROUNDWATER-SPECIFIC CRITERIA

It is a fundamental tenet of the *Low-Threat Policy* that if the closure criteria described in the policy are satisfied at an unauthorized petroleum release site, attaining background water quality is not feasible, and applicable water quality objectives (WQOs) will be attained through natural attenuation within a reasonable amount of time, prior to the expected need for use of any affected groundwater. If a site has groundwater with a designated beneficial use that is affected by an unauthorized release, to satisfy the media-specific criteria for groundwater, the contaminant plume that exceeds WQOs must be stable or decreasing in aerial extent, and meet all of the additional characteristics of one of the five classes of sites listed in the policy:

Satisfied: The site satisfies the characteristics of Class 5.

Based on CRA's November 30, 2012 *Piezometer Installation and Tidal Study Report* the dissolved hydrocarbon plume is stable and decreasing in aerial extent.

- Wells screened within the deeper silty sand zone (MW-1RB through MW-6 and P-1) are tidally influenced based on water level and conductivity data.
- During high tide there was minor groundwater flow from the canal toward the site, but overall groundwater flow was toward the canal.
- Mass flux into Alameda Canal from the site is significantly less than the marine and estuary habitat ESLs for site constituents of concern and do not pose a threat to Alameda Canal.

Additionally, as the site is currently developed as a commercial property and is capped with asphalt and concrete, dermal contact/ingestion is unlikely. Shallow groundwater in the area is not used as a drinking water source and there are no municipal wells in the vicinity of the site as described in Sections 2.3 and 2.10.2. Based on these findings the remaining dissolved hydrocarbons meet the groundwater-specific criteria of the Low Threat Policy.

3.2.2 <u>VAPOR INTRUSION TO INDOOR AIR</u>

The low-threat vapor intrusion criteria described below apply to sites where the release originated and impacted or potentially impacted adjacent parcels when the following exist: (1) existing buildings are occupied or may be reasonably expected to be occupied in the future, or (2) buildings for human occupancy are reasonably expected to be constructed in the future.

Petroleum release sites will satisfy the media-specific screening criteria for petroleum vapor intrusion if the following are met:

- Site-specific conditions at the release site satisfy all of the characteristics and criteria of scenarios 1 through 3 as applicable, or all of the characteristics and criteria of scenario 4 as applicable; or,
- b. A site-specific risk assessment for vapor intrusion is conducted and demonstrates that human health is protected to the satisfaction of the regulatory agency; or,
- c. The regulatory agency determines there is no significant risk of adversely affecting human health through the use of institutional or engineering controls.

Petroleum release sites shall satisfy the media-specific criteria for petroleum vapor intrusion to indoor air and be considered low-threat for the vapor intrusion to indoor air pathway if any of the above criteria are met.

Satisfied: The site satisfies the characteristics of criteria (b).

CRA performed a vapor intrusion pathway assessment including sub-slab vapor, soil vapor, and indoor/outdoor air sampling. As discussed in Section 2.8.3 CRA's assessment demonstrated that current sub-slab results were all below ESLs for indoor air under commercial/industrial land use adjusted by a factor of 100 to account for attenuation between sub-slab and indoor air. While there are highly elevated concentrations observed in the vapor well samples collected at 5 fbg, sub-slab results show low level vapor impact in near surface soil suggesting vapor intrusion from deeper soil (5 fbg) into the site buildings is not a risk. This suggests that there are other indoor sources contributing to the indoor air results. The soil vapor, sub-slab vapor, and indoor and outdoor air analytical results are presented in Tables 5 and 6.

3.2.3 <u>DIRECT CONTACT AND OUTDOOR AIR EXPOSURE</u>

The *Low-Threat Policy* describes conditions where direct contact with contaminated soil or inhalation of contaminants volatized to outdoor air poses an insignificant threat to human health. Release sites where human exposure may occur satisfy media-specific criteria for direct contact and outdoor air exposure and shall be considered low-threat if they meet any one of the following:

a. Maximum concentrations of petroleum constituents in soil are less than or equal to those listed in the table below for the specified depth below ground surface. The limits from 0 to 5 fbg protect from ingestion, dermal contact, and outdoor inhalation of volatile and particulate emissions. The >5 to 10 fbg limits protect from inhalation of volatile emissions only; the ingestion and dermal contact pathways not considered significant. In addition, if exposure to construction workers or utility trench workers is reasonably anticipated, the concentration limits for Utility Worker shall also be satisfied.

	Residential		Commercial/Industrial		Utility Worker	Site Data	
Constituent	0 – 5 fbg (mg/kg)	Volatilization to outdoor air (5 – 10 fbg) (mg/kg)	0 – 5 fbg (mg/kg)	Volatilization to outdoor air (5 – 10 fbg) (mg/kg)	0 – 10 fbg (mg/kg)	0-5 fbg mg/kg	>5-10 fbg mg/kg
Benzene	1.9	2.8	8.2	12	14	16	0.54
Ethylbenzene	21	32	89	134	314	120	3.6
Naphthalene	9.7	9.7	45	45	219	42	0.007
PAH*	0.063	NA	0.68	NA	4.5	NA	NA

^{*} Based on the seven carcinogenic polycyclic aromatic hydrocarbons (PAHs) as benzo(a)pyrene toxicity equivalent [BaPe]. The PAH screening level is only applicable where soil is affected by either waste oil and/or Bunker C fuel.

NA = Not applicable


- b. Maximum concentrations of petroleum constituents in soil are less than levels that a site-specific risk assessment demonstrates will have no significant risk of adversely affecting human health.
- c. As a result of controlling exposure through the use of mitigation measures or through the use of institutional or engineering controls, the regulatory agency determines that the concentrations of petroleum constituents in soil will have no significant risk of adversely affecting human health.

<u>Satisfied:</u> The site satisfies criteria (b). As discussed in Section 2.8.3, the most recent sub-slab vapor results are all below ESLs for indoor air under commercial/industrial land use adjusted by a factor of 100 to account for attenuation between sub-slab and indoor air (Table E, SFRWQCB, 2008). While there are highly elevated concentrations observed in the vapor well samples collected at 5 fbg, sub-slab results show low level vapor impact in near surface soil suggesting vapor intrusion from deeper soil (5 fbg) into the site buildings is not a risk. Additionally the site is capped with asphalt and concrete further limiting the upward migration of soil vapors. It is unlikely that redevelopment of the site will occur anytime in the near future, however, upon request CRA can prepare a soil management plan that can help guide future redevelopment at the site.

4.0 RECOMMENDATIONS

Based on the information presented in this and previous reports, site conditions meet the general and media-specific criteria of a low-threat UST release case established in the Low-Threat Policy, and therefore pose a low threat to human health, safety, and the








SOURCE: TOPO! MAPS.


figure 1

VICINITY MAP FORMER SIGNAL OIL BULK PLANT (CHEVRON FACILITY 206127) 2301-2311 BLANDING AVENUE Alameda, California










CONCENTRATIONS ARE IN MILLIGRAMS PER KILOGRAM (mg/kg)

TPHd CONCENTRATIONS IN SOIL - 0 TO 15 FBG FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON FACILITY 206127) 2301-2311 BLANDING AVENUE Alameda, California

GRA

NOTES

- WELL LOCATIONS ARE BASED ON MAP PROVIDED BY MORROW SURVEYING (DWG NO.0857-149 ct, DATED 7-30-09).
 ALL OTHER LOCATIONS ARE APPROXIMATE.
- TPHd = TOTAL PETROLEUM HYDROCARBONS AS DIESEL; HIGHEST CONCENTRATION USED FOR CONTOURING.



CONCENTRATIONS ARE IN MILLIGRAMS PER KILOGRAM (mg/kg)

WELL LOCATIONS ARE BASED ON MAP PROVIDED BY MORROW SURVEYING (DWG NO.0857-149 ct, DATED 7-30-09).


ALL OTHER LOCATIONS ARE APPROXIMATE.


TPHg = TOTAL PETROLEUM HYDROCARBONS AS GASOLINE; HIGHEST CONCENTRATION USED FOR CONTOURING.





631916D-2014.3(034)GN-WA005 DEC 17/2014

(CHEVRON FACILITY 206127) 2301-2311 BLANDING AVENUÉ Alameda, California









SOIL ANALYTICAL RESULTS FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON FACILITY 206127) 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA

Boring ID	Depth (fbg)	Sample Date	ТРН	ТРНд	Benzene	Toluene	Ethylbenzene	m+p-Xylene	o-Xylene	Total Xylenes	МТВЕ	Acetone	Carbon Disulfide	2-Butanone	Isopropyl- benzene	n-Propyl- benzene	1,3,5 - Trimethyl- benzene	tert-Butyl- benzene	1,2,4- Trimethyl- benzene	sec-Butyl- benzene	p-Isopropyl- toluene	n-Butyl- benzene	Naphthalene
<u>Low-Threa</u>	t Policy -	Direct Contact	t and Outd	oor Air Ex	<u>posure</u>																		
0 to 5 fbg, Re	esidential		NE	NE	1.9	NE	21	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	9.7
5 to 10 fbg, I	Residential,	Outdoor Air	NE	NE	2.8	NE	32	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	9.7
0 to 5 fbg, C,			NE	NE	8.2	NE	89	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	45
5 to 10 fbg, 0	C/I, Outdo	or Air	NE	NE	12	NE	134	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	45
0 to 10 fbg, U			NE	NE	14	NE	314	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	219
O'	J													ım per kilogran									
SB-1	3.5	2/17/1995	110	ND	ND^1	ND^1	ND^1			ND^1													
SB-1	5.5	2/17/1995	10	390	0.08^{1}	0.20^{1}	0.58^{1}			0.86^{1}													
SB-1	9.5	2/17/1995	ND	ND	ND^1	ND^1	ND^1			ND^1													
SB-2	3.5	2/20/1995	40	ND	ND^1	ND^1	ND^1			ND^1													
SB-2	7	2/20/1995	35	2,000	3.7^{1}	34^1	14^1			46 ¹													
SB-3	1.5	2/17/1995	ND	ND	ND^1	ND^1	ND^1			ND^1													
SB-3	7	2/17/1995	230	150	ND^1	0.46^{1}	0.58^{1}			0.51^{1}													
SB-3	10	2/17/1995	ND	ND	ND^1	ND^1	ND^1			ND^1													
SB-4	1.5	2/17/1995	20	ND	ND^1	ND^1	ND^1			ND^1													
SB-4	6.5	2/17/1995	240	860	2.0^{1}	0.81^{1}	3.6^{1}			13 ¹													
SB-4	7	2/17/1995			2.3^{2}	8.7^{2}	3.5^{2}			35 ²													
SB-4	10	2/17/1995	ND	4	0.34^{1}	ND^1	ND^1			ND^1													
SB-5	1.5	2/17/1995	10	ND	ND^1	ND^1	ND^1			ND^1													
SB-5	5.5	2/17/1995	15	ND	ND^1	ND^1	ND^1			ND^1													
SB-5	6	2/17/1995			ND^2	ND^2	ND^2			ND^2													
SB-6	1.5	2/17/1995	40	ND	ND^1	ND^1	ND^1			ND^1													
SB-6	7	2/17/1995	170	400	ND^1	0.12^{1}	0.56^{1}			ND^1													
35-0	,	2/1//1//0	170	400	112	0.12	0.50			112													
SB-7	1	2/17/1995	110	ND	ND^1	ND^1	ND^1			ND^1													
SB-7	4	2/17/1995	250	ND	ND^1	ND^1	ND^1			ND^1													
SB-8	1	2/20/1995	75	ND	ND^1	ND^1	ND^1			ND^1													
SB-8	6.5	2/20/1995	ND	ND	ND^1	ND^1	ND^1			ND^1													
SB-8	7	2/20/1995			ND^2	ND^2	ND^2			ND^2													
SB-9	5	10/28/1998	3,300 ³	130	0.36^{1}	< 0.12 ¹	<0.12 ¹			0.28^{1}	<0.62 ¹												
SB-9	13	10/28/1998	1,300 ³	900	3.3^{1}	<1.2 ¹	2.1			2.0^{1}	<12 ⁴												
SB-9	15	10/28/1998	1.2^{3}	<1.0	0.22^{1}	< 0.0050 ¹	<0.0050 ¹			< 0.0050 ¹	<0.025 ¹												
SB-10	5.5	10/28/1998	130 ³	<1.0	< 0.0050 ¹	< 0.0050 ¹	< 0.0050 ¹			< 0.0050 ¹	<0.025 ¹												
					1																		
SB-11	6	10/28/1998	60^{3}	140	< 0.10 ¹	0.12^{1}	0.24^{1}			0.49^{1}	< 0.50 ¹												
SB-12	5	10/28/1998	<1.0	<1.0	< 0.0050 ¹	< 0.0050 ¹	< 0.0050 ¹			< 0.0050 ¹	< 0.025 ¹												
SB-12	7	10/28/1998	<1.0	<1.0	< 0.0050 ¹	< 0.0050 ¹	< 0.0050 ¹			< 0.0050 ¹	< 0.025 ¹												

SOIL ANALYTICAL RESULTS
FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY
(CHEVRON FACILITY 206127)
2301-2311 BLANDING AVENUE
ALAMEDA, CALIFORNIA

Boring ID	Depth (fbg)	Sample Date	TPHd	ТРНд	Benzene	Toluene	Ethylbenzene	m+p-Xylene	o-Xylene	Total Xylenes	МТВЕ	Acetone	Carbon Disulfide	2-Butanone	Isopropyl- benzene	n-Propyl- benzene	1,3,5 - Trimethyl- benzene	tert-Butyl- benzene	1,2,4- Trimethyl- benzene	sec-Butyl- benzene	p-Isopropyl- toluene	n-Butyl- benzene	Naphthalene
<u>Low-Threa</u>	t Policy -	Direct Contact	t and Outd	oor Air Ex	<u>posure</u>																		
0 to 5 fbg, Re	sidential		NE	NE	1.9	NE	21	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	9.7
5 to 10 fbg, I	desidential,	Outdoor Air	NE	NE	2.8	NE	32	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	9.7
0 to 5 fbg, C,	'I		NE	NE	8.2	NE	89	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	45
5 to 10 fbg, 0	C/I, Outdoo	or Air	NE	NE	12	NE	134	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	45
0 to 10 fbg, U			NE	NE	14	NE	314	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	219
, and a second														ım per kilogran									
SB-12	14	10/28/1998	<1.0	<1.0	< 0.0050 ¹	< 0.0050 ¹	< 0.0050 ¹			< 0.0050 ¹	< 0.025 ¹												
MW-1	5	12/29/2000	30	<1.0	< 0.0050	< 0.0050	< 0.0050			0.017	< 0.050												
MW-1	10	12/29/2000	160	320	0.40	1.6	0.90			1.1	<1.2												
MW-1	15	12/29/2000	<1.0	<2.5	0.53	0.021	0.028			0.065	<0.12												
S1	0.5	1/13/2004	14	<1.0	<0.0005	< 0.001	< 0.001			< 0.001	< 0.0005												
S2	0.5	1/13/2004	220	<20	<0.0005	< 0.001	<0.001			<0.001	<0.0005												
S3	0.5	1/13/2004	220	<10	<0.0005	<0.001	<0.001			<0.001	<0.0005												
VP-1	3	7/9/2008	12	<1.0	0.001	0.003	0.002	0.004	0.002		<0.0005	<0.007	<0.001	<0.004	0.001	0.003	<0.001	<0.001	<0.001	<0.001	0.002	<0.001	<0.001
VP-2*	3	7/9/2008	240	330	0.079	0.080	0.080	0.18	0.066		< 0.026	< 0.36	< 0.051	< 0.21	0.23	0.51	0.088	0.098	0.29	0.18	< 0.051	0.22	0.28
VP-2	5	7/9/2008	2,100	670	0.52	0.16	0.36	0.46	0.085		< 0.025	0.44	< 0.50	< 0.20	4.6	9.9	0.065	0.84	0.11	1.8	0.051	4.4	0.48
VP-3	2.5	7/14/2008	5.4	<1.0	<0.0005	<0.0009	<0.0009	<0.0009	<0.0009		<0.0005	< 0.007	< 0.0009	<0.004	<0.0009	<0.0009	<0.0009	<0.0009	< 0.0009	<0.0009	<0.0009	<0.0009	<0.0009
VP-3	5	7/14/2008	<4.0	<1.0	0.001	< 0.0009	<0.0009	<0.0009	<0.0009		<0.0005	0.039	<0.0009	0.007	<0.0009	<0.0009	<0.0009	<0.0009	<0.0009	<0.0009	<0.0009	<0.0009	<0.0009
		7 /4 / / 2 000	4 =00	4.000	- 0	0.54	4.0	0.4	2.62			0.45	.0.010	.0.10		- 0						• 0	
VP-4 VP-4	2.5 5	7/14/2008 7/14/2008	1,700 6,900	1,300 11,000	5.0 16	0.54 2.4	13 120	8.1 15	0.60 2.8		<0.024 <0.093	0.65 <1.3	<0.048 <0.19	<0.19 <0.74	3.7 27	5.9 48	4.1 11	0.32 3.0	41 5.0	1.4 11	2.5 13	2.0 23	3.4 42
V 1 -4	3	7/14/2008	0,900	11,000	10	2.4	120	13	2.0		\0.093	\1.5	<0.19	\0.74	21	40	11	3.0	5.0	11	13	23	42
VP-5	2.5	7/14/2008	20	1.7	0.0008	< 0.001	< 0.001	< 0.001	< 0.001		< 0.0005	< 0.007	< 0.001	< 0.004	< 0.001	0.001	< 0.001	< 0.001	0.001	< 0.001	0.001	0.001	0.010
VP-5	5	7/14/2008	6,000	540	0.11	0.051	0.11	0.23	0.072		<0.023	<0.33	< 0.047	<0.19	1.1	1.6	0.13	<0.047	0.33	0.37	0.42	0.37	0.83
VP-6	3	7/9/2008	340	<10	<0.0005	< 0.001	< 0.001	< 0.001	< 0.001		< 0.0005	< 0.007	< 0.001	< 0.004	< 0.001	< 0.001	<0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001
VP-6	5	7/9/2008	350	910	<0.026	< 0.053	0.31	0.37	< 0.053		< 0.026	< 0.37	< 0.053	0.33	2.1	3.3	0.10	0.060	< 0.053	1.1	0.26	1.7	2.9
SB-13	1	7/7/2008	47	1.0	< 0.0005	<0.001	< 0.001	0.002	< 0.001		< 0.0005	< 0.007	< 0.001	< 0.004	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	0.003	< 0.001	< 0.001
SB-13	5	7/7/2008	630	350	< 0.027	< 0.054	<0.054	< 0.054	< 0.054		< 0.027	<0.38	< 0.054	<0.22	0.12	0.14	< 0.054	< 0.054	< 0.054	0.23	< 0.054	0.12	0.16
SB-13	10	7/8/2008	<4.0	<1.0	<0.0005	< 0.001	<0.001	<0.001	<0.001		< 0.0005	< 0.007	<0.001	< 0.004	<0.001	< 0.001	<0.001	< 0.001	< 0.001	< 0.001	<0.001	<0.001	<0.001
SB-14	1	7/7/2008	89	<1.0	0.002	0.004	0.002	0.005	0.003		<0.0005	0.018	< 0.001	<0.004	< 0.001	<0.001	<0.001	< 0.001	0.001	<0.001	0.001	< 0.001	< 0.001
SB-14	5	7/7/2008	29	<1.0	0.002	0.003	0.002	0.003	0.002		< 0.0005	0.026	< 0.001	0.005	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001
SB-14	10	7/8/2008	<4.0	<1.0	0.0006	0.001	<0.001	0.002	0.001		<0.0005	< 0.007	<0.001	< 0.004	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	0.001	<0.001	<0.001
SB-15	1	7/7/2008	45	<1.0	0.0007	0.001	<0.001	0.001	< 0.001		< 0.0005	< 0.007	< 0.001	< 0.004	< 0.001	< 0.001	<0.001	< 0.001	<0.001	<0.001	< 0.001	< 0.001	<0.001
SB-15	5	7/7/2008	42	<1.0	< 0.0005	< 0.001	< 0.001	< 0.001	< 0.001		< 0.0005	< 0.007	< 0.001	< 0.004	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001
SB-15	9.5	7/8/2008	71	1.0	0.002	0.006	0.005	0.012	0.006		<0.0005	< 0.007	< 0.001	<0.004	0.001	0.001	0.001	<0.001	0.002	<0.001	0.008	<0.001	0.001
SB-16A	1	7/7/2008	140	<10	0.004	0.012	0.008	0.024	0.013		<0.0005	<0.007	<0.001	<0.004	0.001	0.001	0.001	<0.001	0.003	<0.001	0.007	<0.001	<0.001

SOIL ANALYTICAL RESULTS FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON FACILITY 206127) 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA

Boring ID	Depth (fbg)	Sample Date	ТРНа	ТРНд	Benzene	Toluene	Ethylbenzene	m+p-Xylene	o-Xylene	Total Xylenes	МТВЕ	Acetone	Carbon Disulfide	2-Butanone	Isopropyl- benzene	n-Propyl- benzene	1,3,5 - Trimethyl- benzene	tert-Butyl- benzene	1,2,4- Trimethyl- benzene	sec-Butyl- benzene	p-Isopropyl- toluene	n-Butyl- benzene	Naphthalene
Low-Three	at Policy ·	- Direct Contact	t and Out	door Air Ex	<u>cposure</u>																		
0 to 5 fbg, F	Residential		NE	NE	1.9	NE	21	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	9.7
5 to 10 fbg,	Residentia	l, Outdoor Air	NE	NE	2.8	NE	32	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	9.7
0 to 5 fbg, 0	C/I		NE	NE	8.2	NE	89	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	45
5 to 10 fbg,	C/I, Outdo	oor Air	NE	NE	12	NE	134	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	45
0 to 10 fbg,	Utility Wo	orker	NE	NE	14	NE	314	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	219
											Concen	trations repor	ted in milligra	am per kilograi	n - mg/kg								
SB-16B	1	7/7/2008	83	<1.0	0.004	0.013	0.012	0.035	0.019		< 0.0005	< 0.007	< 0.0009	< 0.004	0.002	0.002	0.002	< 0.0009	0.006	< 0.0009	0.015	< 0.0009	< 0.0009
SB-16C	2	7/8/2008	250	<10	0.003	0.009	0.006	0.018	0.011		< 0.0005	< 0.007	< 0.001	< 0.004	0.001	0.001	0.002	< 0.001	0.004	< 0.001	0.007	< 0.001	< 0.001
SB-16C	3	7/8/2008	960	<40	0.005	0.008	0.006	0.018	0.011		<0.0005	0.063	0.002	0.012	0.001	0.002	0.003	<0.001	0.006	< 0.001	0.01	<0.001	0.001
SB-17	1	7/7/2008	120	<10	0.0007	0.001	<0.001	0.002	0.001		< 0.0005	0.015	0.001	< 0.004	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	0.002	< 0.001	< 0.001
SB-17	5	7/7/2008	97	40	0.22	0.053	0.63	1.3	0.19		< 0.025	< 0.35	< 0.050	< 0.20	0.14	0.35	0.73	< 0.050	2.7	0.063	0.18	0.13	0.96
SB-17	9.5	7/8/2008	<4.0	4.9	0.021	0.003	0.025	0.013	0.003		< 0.0005	0.015	<0.001	< 0.004	0.016	0.015	0.003	0.001	0.002	0.005	0.003	0.004	0.007
SB-18	1	7/7/2008	61	150	0.0008	0.002	0.003	0.005	0.003		< 0.0005	< 0.007	0.002	< 0.004	0.003	0.003	<0.001	0.005	0.002	0.013	0.003	0.005	0.013
SB-18	5	7/7/2008	1,500	630	0.21	< 0.052	0.053	0.098	< 0.052		< 0.026	< 0.37	< 0.052	< 0.21	0.36	0.61	0.089	< 0.052	0.57	0.44	0.45	0.72	4.9
SB-18	10	7/8/2008	310	160	0.056	< 0.049	< 0.049	<0.049	< 0.049		< 0.024	< 0.34	< 0.049	<0.19	0.10	0.11	< 0.049	< 0.049	< 0.049	0.053	0.079	0.095	< 0.049
SB-19	1	7/7/2008	190	<10	0.001	0.002	<0.001	0.002	0.001		<0.0005	<0.008	< 0.001	< 0.004	< 0.001	< 0.001	< 0.001	< 0.001	0.002	< 0.001	0.002	< 0.001	< 0.001
SB-19	5	7/7/2008	680	960	0.29	0.92	3.9	7.6	3.3		< 0.023	0.43	< 0.047	< 0.19	4.5	4.7	3.2	0.28	5.3	1.4	42	2.0	3.8
SB-19	10	7/8/2008	<4.0	<1.0	<0.0005	<0.001	<0.001	<0.001	<0.001		<0.0005	< 0.007	< 0.001	< 0.004	<0.001	<0.001	<0.001	<0.001	< 0.001	<0.001	<0.001	<0.001	<0.001
MW-2	4.5	6/18/2009	480	1,100	<0.027	< 0.055	0.19			0.19	<0.027												
MW-2	8.5	6/19/2009	17	4.8	< 0.0005	< 0.001	< 0.001			< 0.001	< 0.0005												

SOIL ANALYTICAL RESULTS FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON FACILITY 206127) 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA

Boring ID	Depth (fbg)	Sample Date	TPHd	ТРНд	Benzene	Toluene	Ethylbenzene	m+p-Xylene	o-Xylene	Total Xylenes	MTBE	Acetone	Carbon Disulfide	2-Butanone	Isopropyl- benzene	n-Propyl- benzene	1,3,5 - Trimethyl- benzene	tert-Butyl- benzene	1,2,4- Trimethyl- benzene	sec-Butyl- benzene	p-Isopropyl- toluene	n-Butyl- benzene	Naphthalene
Low-Threa	t Policy -	Direct Contact	t and Out	door Air Ex	<u>posure</u>																		
0 to 5 fbg, Re	esidential		NE	NE	1.9	NE	21	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	9.7
5 to 10 fbg, R	Residential,	Outdoor Air	NE	NE	2.8	NE	32	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	9.7
0 to 5 fbg, C/	/I		NE	NE	8.2	NE	89	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	45
5 to 10 fbg, C	C/I, Outdo	or Air	NE	NE	12	NE	134	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	45
0 to 10 fbg, U	Jtility Wo	rker	NE	NE	14	NE	314	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	219
											Concen	trations repo	ted in milligr	am per kilograi	m - mg/kg								
MW-3	4	6/18/2009	610	700	0.64	0.099	6.1			0.85	<0.026												
MW-3	6	6/18/2009	170	960	0.39	0.069	2.5			0.67	<0.025												
MW-3	8.5	6/19/2009	16	66	0.062	0.003	0.058			0.012	<0.0005												
MW-4	15	6/19/2009	<4.0	<1.0	<0.0005	<0.0009	<0.0009			<0.0009	<0.0005												
MW-5	7	6/19/2009	500	520	0.076	< 0.049	0.061			< 0.080	<0.024												
MW-5	10.5	6/23/2009	36	170	0.043	< 0.048	< 0.048			0.048	< 0.024												
MW-5	14	6/23/2009	270	170	0.075	< 0.047	< 0.047			< 0.047	<0.023												
MW-1RA ⁵	10	8/4/2010	260^{3}	380	0.54	< 0.050	0.43			0.12	<0.025												
MW-1RA ⁵	13.5	8/4/2010	120^{3}	490	0.24	< 0.050	0.068			0.057	< 0.025												
MW-6	15	8/4/2010	<4.0 ³	1.2	0.12	0.002	0.003			0.003	<0.0005												
	ESLs		180	180	0.27	9.3	4.7	11	11	11	8.4	0.5	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	2.8

Abbreviations and Notes:

fbg = Feet below grade

TPHd = Total petroleum hydrocarbons as diesel by EPA Method 8015

TPHg = Total petroleum hydrocarbons as gasoline by EPA Method 8015

<x = not detected at or above stated laboratory reporting limit

ND = Not detected

VOCs = Volatile organic compounds by EPA method 8260B

Note: Other VOCs not included in the table were not detected in any of the samples.

ESL = Environmental screening level for shallow soil (<3m fbg) at commercial/industrial sites where groundwater is not a current or potential source of drinking water (Table B)-RWQCB May 2008

NE = Not established

Benzene, toluene, ethylbenzene, and xylenes EPA Method 8260B

MTBE = Methyl tertiary butyl ether EPA Method 8260B

¹ = EPA Method 8020

 $^{^2}$ = EPA Method 8240

³ = Additional analyses were performed with silica gel cleanup

⁴ = RRM reported as a false positive associated with EPA Method 8020

⁵ = The GC/MS volatile analysis was performed according to the high level soil method due to the level of non-target compounds. Therefore, the reporting limits were raised.

 $^{^{6}}$ = Benzene detected at 2.3 mg/kg, toluene detected at 8.7 mg/kg, ethylbenzene detected at 8.7 mg/kg, and total xylenes detected at 35 mg/kg.

^{-- =} Not Analyzed

^{* 1,2,3-}Trichlorobenzene also detected at 0.067 mg/kg

TABLE 2

SOIL ANALYTICAL DATA - METALS FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON BULK PLANT 206127) 2301-2311 BLANDING AVENUE, ALAMEDA, CALIFORNIA

Boring ID	Depth (ft)	Sample Date	Mercury	Thallium	Arsenic	Selenium	Antimony	Barium	Beryllium	Cadmium	Chromium	Cobalt	Copper	Lead	Molybdenum	Nickel	Silver	Vanadium	Zinc
									Concentrati	ons reporte	d in milligran	ı per kilogi	ram (mg/kg))					
SB-1	3	2/17/1995	0.43	7	6.1	ND	2	110	0.2	0.7	39	9.6	51	110	ND	30	0.1	37	210
SB-2	2	2/20/1995	0.7	ND	9.7	ND	2	120	0.1	ND	89	11	170	77	0.7	49	0.1	35	280
SB-3	1	2/17/1995	0.71	6	68	ND	2	56	0.2	ND	12	7.4	19	22	0.3	16	0.2	32	90
SB-4	1	2/17/1995	0.63	4	46	ND	2	59	0.2	ND	17	9.3	36	30	0.7	22	0.3	34	110
SB-5	1	2/17/1995	0.37	3	12	ND	1	46	0.2	ND	19	7.7	21	12	ND	22	0.2	32	74
SB-6	1	2/17/1995	0.94	8	130	ND	4	67	0.2	ND	16	8.7	31	32	1.1	23	0.7	34	100
SB-7	1.5	2/17/1995	0.16	ND	ND	ND	2	150	0.1	0.3	36	7.1	44	89	ND	24	0.1	47	200
SB-8	0.5	2/20/1995	0.09	ND	4.5	ND	2	88	0.2	ND	23	7.8	30	30	ND	15	ND	29	110
VP-1	3	7/9/2008	0.0756	<1.25	2.32	< 0.961	<0.980	92.6	0.225	<0.137	5.68	2.95	23	42.1	0.565	6.08	0.184	27.6	117
VP-2 VP-2	3 5	7/9/2008 7/9/2008	0.247 0.025	<1.26 <1.21	6.78 1.78	<0.970 <0.933	<0.990 <0.952	137 78.8	0.392 0.166	<0.139 <0.133	17.9 24.9	7.01 4.13	47.4 7.19	185 9.67	1.04 0.463	15.8 9.17	0.302 <0.162	38.3 22.2	167 10.7
VP-3 VP-3	2.5 5	7/14/2008 7/14/2008	0.285 0.155	2.26 <1.22	9.45 3.46	<0.980 <0.942	2.64 <0.962	164 94.5	0.235 0.149	<0.700 <0.135	101 34.5	7 3.47	175 13.7	189 19.5	3.26 <0.423	45.7 33.7	0.393 <0.163	51.3 23.6	690 45.5
VP-4 VP-4	2.5 5	7/14/2008 7/14/2008	0.883 0.0134	<1.25 <1.25	8.37 3.19	<0.961 <0.961	4.15 <0.980	1,090 70.4	0.221 0.149	2.44 <0.137	41.4 34.4	3.41 2.46	139 5.91	903 16.3	0.743 <0.431	21.4 13.7	0.351 <0.167	27.9 32.6	1,670 15.5
VP-5 VP-5	2.5 5	7/14/2008 7/14/2008	0.256 0.0849	2.24 <1.26	5.74 3.2	<0.970 <0.970	1.23 <0.990	198 94.2	0.3 0.136	<0.139 <0.139	29.4 27.6	7.44 3.17	40.8 11.2	63.9 21.9	0.582 <0.436	26.1 10.8	0.421 <0.168	61.7 25.5	190 138
VP-6 VP-6	3 5	7/9/2008 7/9/2008	0.154 0.0342	<1.27 <1.25	5.86 3.72	<0.980 <0.961	<1.00 <0.980	80.6 188	0.562 0.325	<0.140 <0.137	18.6 46.4	7.43 2.12	27.7 11.1	50.6 5.24	1.08 <0.431	29.3 42.2	0.203 <0.167	27.9 39.1	88.5 29.3
SB-13 SB-13 SB-13	1 5 10	7/7/2008 7/7/2008 7/8/2008	0.118 0.0529 0.0223	<1.25 <1.26 <1.26	21.6 3.27 3.14	<0.961 <0.970 <0.970	<0.980 <0.990 <0.990	105 98.2 127	0.265 0.364 0.3	0.329 <0.137 <0.139	34.7 55.2 52.1	6.84 5.13 5.77	28.4 8.47 12.5	141 4.08 3.8	0.559 <0.436 <0.436	20.2 48.7 45	<0.167 <0.168 <0.168	30.5 32.1 36.6	144 23 30.2
SB-14 SB-14 SB-14	1 5 10	7/7/2008 7/7/2008 7/8/2008	0.114 0.0353 0.028	<1.25 <1.21 <1.27	8.17 5.39 3.04	<0.961 <0.933 <0.980	<0.980 <0.952 <1.00	111 53.4 397	0.242 0.272 0.306	<0.139 <0.139 <0.140	29.9 12 51.4	8.27 5.29 9.57	59.4 15.3 11.8	115 14 3.29	1.02 <0.419 <0.440	28.9 4.9 51.1	<0.167 <0.162 0.547	42.4 25.2 37.2	369 84.6 28.8
SB-15 SB-15 SB-15	1 5 9.5	7/7/2008 7/7/2008 7/8/2008	0.117 0.157 <0.0109	<1.27 <1.22 <1.25	7.1 34.7 3.23	<0.980 <0.942 <0.961	1.75 <0.962 <0.980	126 112 132	0.303 0.249 0.362	0.267 0.169 <0.137	71.5 41.5 43.9	11.3 7.66 3.25	116 58.7 11.7	107 74.1 5.77	0.809 0.888 0.673	167 27.5 42.1	0.191 <0.163 <0.167	42.7 30.4 27.6	283 153 30.1
SB-16A SB-16B SB-16C SB-16C	1 1 2 3	7/7/2008 7/7/2008 7/8/2008 7/8/2008	0.14 0.112 0.219 0.233	<1.27 <1.22 <1.27 <1.27	22.2 9.6 9.74 12.5	<0.980 <0.942 <0.980 <0.980	<1.00 5.8 2.4 <1.0	230 181 184 183	0.459 0.228 0.229 0.263	0.263 <0.135 0.272 2.61	45.9 275 66.3 49.5	9.07 12.7 6.54 4.8	184 180 254 90.7	115 125 204 264	0.958 10.6 1.63 1.25	34.3 129 39.1 39.4	0.387 0.469 0.363 0.247	37.4 42.7 36.1 31.4	1,340 876 408 268

CRA 631916 (34)

TABLE 2

SOIL ANALYTICAL DATA - METALS FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON BULK PLANT 206127) 2301-2311 BLANDING AVENUE, ALAMEDA, CALIFORNIA

Boring ID	Depth (ft)	Sample Date	Mercury	Thallium	Arsenic	Selenium	Antimony	Barium	Beryllium	Cadmium	Chromium	Cobalt	Copper	Lead	Molybdenum	Nickel	Silver	Vanadium	Zinc
									Concentrati	ions reporte	d in milligran	n per kilog	ram (mg/kg))					
SB-17	1	7/7/2008	0.144	<1.25	4.49	< 0.961	< 0.980	121	0.322	0.316	63.1	9.16	65.2	81.5	0.678	49.5	0.177	38.3	162
SB-17	5	7/7/2008	0.0337	<1.22	2.47	< 0.942	< 0.962	87.8	0.209	< 0.137	26.2	5.37	12.2	22.4	< 0.423	10.7	< 0.163	24.1	38.5
SB-17	9.5	7/8/2008	< 0.0113	1.52	14.9	< 0.961	< 0.980	118	0.154	< 0.137	48.5	6.3	12.2	3.69	< 0.431	47.6	0.34	38.5	29
SB-18	1	7/7/2008	0.0528	<1.27	3.1	< 0.980	<1.00	106	0.293	< 0.136	53.7	7.41	43.5	30.5	< 0.440	42.1	< 0.170	31.8	58.1
SB-18	5	7/7/2008	0.361	<1.25	3.14	< 0.961	< 0.980	117	0.206	0.605	30.4	7.15	32.9	164	0.544	12.9	0.338	24	478
SB-18	10	7/8/2008	0.0163	4.78	6.05	< 0.942	< 0.962	82.3	0.123	< 0.135	48	5.14	13.6	3.56	< 0.423	44.8	0.244	35.9	27.2
SB-19	1	7/7/2008	0.184	<1.21	8.31	0.965	3.11	313	0.455	60.6	29.7	6.81	26.7	353	0.438	24.4	0.296	25.3	318
SB-19	5	7/7/2008	0.033	<1.22	3.63	< 0.942	< 0.962	114	0.397	< 0.133	52.9	6.51	10.2	10.4	< 0.423	66.6	< 0.163	39.7	30.9
SB-19	10	7/8/2008	0.0568	<1.25	1.78	< 0.961	< 0.980	91.8	0.145	< 0.137	54.1	5.19	11.1	2.9	< 0.431	44.3	0.201	35.7	29.8
	ESLs		10	16	1.6	10	40	1,500	8.0	7.4	750*	80	230	750	40	150	40	200	600

Abbreviations / Notes

CAM 17 Metals by EPA Method 6010B/7471A

x =not detected at or above the stated laboratory reporting limit

Concentrations in **bold** indicate that the constituent exceed their respective ESL

ND = Not detected at or above the stated laboratory reporting limit

ESL = Environmental screening level for shallow soil (<3m fbg) at commercial/industrial sites where groundwater is not a current or potential source of drinking water (Table B)-RWQCB May 2008

CRA 631916 (34)

^{*} ESL is for Chromium III

TABLE 3

HISTORICAL GRAB GROUNDWATER ANALYTICAL DATA FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON BULK PLANT 206127) 2301-2311 BLANDING AVENUE, ALAMEDA, CALIFORNIA

Boring/ Well ID	Sample Date	ТРНа	ТРНд	Benzene	Toluene	Ethyl- benzene	m+p Xylene	o-Xylene	Total Xylenes	MTBE	Vinyl Chloride	cis-1,2- DCE	TCE	Isopropyl- benzene	n-Propyl- benzene	1,3,5- Trimethyl- benzene	tert-Butyl- benzene	1,2,4- Trimethyl- benzene	sec-Butyl- benzene	p- Isopropyl- toluene	n-Butyl- N benzene	Naphthale ne	TBA	Acetone	Metals
												Concent	rations in	nicrogran	ıs per liter (µ			venzene		ioinene					
GWS-7	4/24/1995	ND	ND	ND	ND	ND			ND																
GWS-8	4/24/1995	60	3700	36	6.9	27			11																
GWS-9	4/24/1995	1,200	22,000	6,200	140	1,100			1,200																
GWS-10	4/24/1995	240.00	11,000	880	40	100			50																
GWS-11	4/24/1995	70.00	140	ND	1	1.4			8.4																
GWS-12	4/24/1995	ND	ND	ND	0.06	ND			ND																
GWS-13	4/24/1995	ND	ND	ND	ND	ND			ND																
GWS-14	4/24/1995	ND	ND	ND	ND	ND			ND																
GWS-15	4/24/1995	ND	ND	ND	ND	ND			ND																
GWS-16	4/24/1995	ND	70	ND	ND	2			1.1																
***SB-9	10/28/1998	83,000 62,000	14,000	1,400	58	490			630	260/<10 ²															
***SB-10	10/28/1998	97 <50	<50	<0.50	<0.50	<0.50			<0.50	<2.5															
***SB-11	10/28/1998	270 170	310	<0.50	0.69	1.6			2.4	<2.5															
***SB-12	10/28/1998	<50	<50	<0.50	< 0.50	< 0.50			<0.50	<2.5															
SB-13	7/8/2008	600	<50	<0.5	<0.5	<0.5	<0.5	<0.5		3.0	<1.0	<0.8	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<5.0	<6.0	
SB-14	7/8/2008	750	<50	<0.5	<0.5	<0.5	<0.5	<0.5		<0.5	<1.0	<0.8	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<5.0	<6.0	
SB-15	7/8/2008	430	<50	<0.5	<0.5	<0.5	<0.5	<0.5		0.8	1.0	69	5.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<5.0	<6.0	
SB-18	7/8/2008	19,000	3,800	590	18	7.0	15	3.0		<0.5	<1.0	<0.8	<1.0	45	67	1.0	2.0	3.0	5.0	2.0	5.0	2.0	15	35	
SB-19	7/8/2008	1,600	650	3.0	8.0	9.0	26	16		<0.5	<1.0	<0.8	<1.0	4.0	4.0	5.0	<1.0	13	<1.0	58	<1.0	2.0	<5.0	6.0	
MW-1	7/8/2008	2,800	120	0.8	<0.5	<0.5	<0.5	<0.5		<0.5	<1.0	<0.8	<1.0	<1.0	<1.0	<1.0	1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<5.0	8.0	ND^2
E	SLs	210	210	46	130	43	1	00*		1,800	3.8	590	360	NE	NE	NE	NE	NE	NE	NE	NE	24	18,000	1,500	1,000**

Abbreviations/notes:
TPHg/TPHd = Total petroleum hydrocarbons as gasoline/diesel by EPA Method 8015
VOCs = Volatile Organic Compounds by EPA Method 8260B
MTBE = Methyl tertiary butyl ether

cis-1,2-DCE = cis-1,2-Dichloroethene

TCE = Trichloroethene

TBA = Tertiary butyl alcohol

x =not detected at or above stated laboratory detection limit

--= Not analyzed

ND = Not detected; detection limits vary

¹ Total xylenes

CRA 631916 (34)

Page 1 of 2

TABLE 3

HISTORICAL GRAB GROUNDWATER ANALYTICAL DATA FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON BULK PLANT 206127) 2301-2311 BLANDING AVENUE, ALAMEDA, CALIFORNIA

² EPA Method 8020/ EPA Method 8260

* ESL is for total xylenes

NE = Not established

** ESL for barium

*** Samples analyzed using EPA Method 8015Mod/8020. TPHD analyzed using silica gel cleanup. TPHd wan twice for samples SB-9 through SB-11.

Note

GWS-7 through GWS-16 were converted from milligrams per liter to micrograms per liter for consistancy.

BTEX were analyzed using EPA Method 8020 at samples GWS-7 through GWS-16 and SB-9 through SB-12. MTBE was analyzed using EPA Method 8020 at samples SB-9 through SB-12 unless otherwise noted.

SOIL VAPOR ANALYTICAL RESULTS FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON FACILITY 206127) 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA

1,3,5-

						T411			Cl.1 41						D.,1	1,3,3- T	4 F411					
		ТРНа	ТРНд	Danzana	Toluene	Ethyl-	m,p- Xylene	Naphthalene	Chloromethan	Bromomethane	Цамана	Cualahayana	Uantana	Carraga		Trimethy	U	0	N T	CO	CH	Не
									<u>e</u>									O 2	N_2	CO ₂	CH ₄	
Vapor Well	Sample Date	(µg/m°)	(μg/m ³)	(µg/m³)	(μg/m³)	(μg/m³)	(μg/m³)	(μg/m³)	(μg/m³)	(μg/m³)	(μg/m³)	(μg/m³)	(µg/m°)	(µg/m°)	(μg/m³)	(μg/m³)	(μg/m³)	(%)	(%)	(%)	(%)	(%)
C '1 T/ T// 11																						
Soil Vapor Wells	00 /10 /00	12 000	1 200 000	200	140	240	E40		~ 1.00	~7F	0.400	12 000	27 000	1 (00	2 000	-0 F	((0	17		4.00		<0.1 0
VP-1	08/19/08	13,000	1,300,000	<u>300</u>	140	240	540		<160	<75	9,400	12,000	27,000	1,600	2,800	<95	660	17		4.00		<0.12
	10/22/09	NIC	<88	<3.4	<4.1	<4.7	<4.7	NIC	<8.9	<4.2	<3.8	<3.7	<4.4	<5.3	<5.3	<5.3	<5.3	9.4	NIC	5.70	NIC	<0.11
	06/29/10 11/16/10	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS	NS NS
	11/10/10	NS	113	NS	NS	NS	NS	INS	113	IN3	NS	113	NS	NS	NS	113	NS	INS	NS	113	NS	NS
VP-2	08/19/08	24,000	1,500,000	<u>140</u>	<86	130	300		<190	<89	5,500	19,000	12,000	900	1,700	<110	370	8.9		11.00		<0.11
	10/22/09		<95	<3.7	<4.4	< 5.0	< 5.0		<9.6	<4.5	<4.1	<4.0	<4.8	< 5.7	< 5.7	< 5.7	<5.7	13		8.00		< 0.12
	06/29/10		<280	<4.3	<5	< 5.9	< 5.9	<28										16	79	5.10	0.0005	< 0.14
	$06/29/10^1$		820	<4.3	< 5.0	< 5.8	< 5.8	<28										16	79	5.10	< 0.00027	7 < 0.13
	$11/16/10^2$		<160	<3.8	<4.4	<5.1	< 5.1	<25										18	79	3.10	< 0.00024	4 < 0.12
VP-3	08/19/08	53,000E	4,100,000	< 700	<830	<960	1,200		<1,800	<850	38,000	47,000	77,000	4,000	5,700	1,200	<1100	1.7		11.00		< 0.11
	10/22/09		1,800,000	<130	<150	<180	<180		<330	<160	6,200	6,200	1,800	<200	<200	<200	<200	1.4		8.10		< 0.12
	06/29/10	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	11/16/10		340,000	<38	<45	<52	<52	<250										4.1	87	8.10	0.66	< 0.12
VP-4	08/19/08	91,000S	220,000,000	1,100,000	49,000	<u>570,000</u>	70,000		3,900,000	<u>70,000</u>	8,400,000	3,600,000	5,100,000	57,000	84,000	<19,000	37,000	0.55		16.00		< 0.13
	10/22/09		140,000,000	1,100,000	<48,000	650,000	71,000		<100,000	<49,000	7,700,000	3,400,000	4,900,000	64,000	110,000	<62,000	<62,000	0.64		15.00		< 0.13
	$10/22/09^1$		130,000,000	1,000,000	<46,000	540,000	57,000		<100,000	<47,000	7,300,000	3,200,000	4,600,000	<59,000	92,000	<59,000	<59,000	0.62		14.00		< 0.12
	06/29/10	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	11/16/10		130,000,000	830,000	30,000	470,000	44,000	<25,000										1.1	43	12.00	41	0.28
VP-5	08/19/08	110,000S	29,000,000	28,000	<4,400	<5,000	<5,000		<9,600	<4,500	630,000	430,000	660,000	7,000	<5,700	<5,700	<5,700	2.0		15.00		< 0.12
	10/22/09		20,000,000	16,000	<4,800	<5,500	<5,500		<10,000	<4,900	370,000	310,000	490,000	12,000	15,000	<6,200	<6,200	1.3		17.00		< 0.13
	06/29/10	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	11/16/10		18,000,000	11,000	1,600	<1600	1,600	<8000										1.5	82	16.00	0.030	< 0.11
	$11/16/10^1$		18,000,000	12,000	1,500	<1600	1,700	<8000										1.4	82	16.00	0.030	< 0.11
	, ,				,		,												-			
VP-6	08/19/08	<u>96,000S</u>	150,000,000	20,000	<10,000	<12,000	<12,000		1,200,000	<u>25,000</u>	3,300,000	3,200,000	2,800,000	17,000	<14,000	<14,000	<14,000	3.9		9.80		<0.11
	$08/19/08^1$	<u>22,000</u>	<u>840,000</u>	<u>100</u>	<86	130	290		<190	<89	4,400	9,800	12,000	890	1,700	<110	390	9.2		10.00		< 0.11
	06/29/10	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	11/16/10	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS

CRA 631916 (34) Page 1 of 3

SOIL VAPOR ANALYTICAL RESULTS FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON FACILITY 206127) 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA

1,3,5-

		ТРНа	ТРНg	Benzene	Toluene	Ethyl- benzene	m,p- Xylene	Naphthalene	Chloromethan	Bromomethane	Hexane	Cuclohexane	. Hentane	Cumene		1,3,5- Trimethy l-benzene		O_2	N_{2}	CO ₂	CH 4	Не
Vapor Well	Sample Date		(μg/m ³)	(μg/m ³)	(μg/m ³)	(μg/m ³)	$(\mu g/m^3)$	(μg/m ³)	(μg/m³)	(μg/m ³)	(μg/m ³)	(μg/m ³)	$(\mu g/m^3)$	$(\mu g/m^3)$	(μg/m ³)	(μg/m ³)	(μg/m ³)	(%)	(%)	(%)	(%)	(%)
	,	, , , , , , , , , , , , , , , , , , ,	4.8	1.0	1.0	4.8	18 /	10	40	4.8	<u> </u>	, , , , , , , , , , , , , , , , , , ,	, <u>, , , , , , , , , , , , , , , , , , </u>	13 /	4 8 /	10 /	, , , , , , , , , , , , , , , , , , ,	(10)	(10)	(13)		(10)
Sub-Slab Soil Vapo	or Probes																					
VP-7	07/24/09		<95	<3.7	<4.4	< 5.0	< 5.0		<9.6	<4.5	<4.1	<4.0	<4.8	<5.7	<5.7	<5.7	<5.7	19		0.60		< 0.12
	06/29/10		<240	<3.7	<4.3	< 5.0	< 5.0	<24										21	78	0.30	< 0.00023	3 0.21
	11/16/10		<260 ³	<4.1	<4.9	<5.6	<5.6	<27										20	79	0.50	< 0.00026	6 0.54
VP-8	07/24/09		490	<3.5	<4.1	<4.8	<4.8		<9.1	<4.3	<3.9	<3.8	<4.5	< 5.4	<5.4	<5.4	<5.4	21		0.56		<0.11
	$07/24/09^1$		<u>8,200</u>	7	48	24	100		<9.1	<4.3	<3.9	<3.8	<4.5	< 5.4	14	33	79	21		0.56		< 0.11
	06/29/10		310	<u>24</u>	71	5.9	47	<25										20	79	0.61	< 0.00024	4 0.57
	$06/29/10^1$		340	<u>24</u>	70	5.3	44	<25														
	11/16/10		$<250^3$	<3.9	<4.6	<5.2	<5.2	<25										19	79	0.98	< 0.00024	4 1.10
VP-9	07/24/09		<u>8,800</u>	<3.8	38	<5.3	19		<9.8	<4.6	<4.2	<4.1	<4.9	<5.8	<5.8	<5.8	<5.8	15		0.14		29.00
VI)	10/22/09		<90	<3.5	<4.1	<4.8	<4.8		<9.1	<4.3	<3.9	<3.8	<4.5	<5.4	<5.4	<5.4	<5.4	20		0.73		< 0.11
	06/29/10		<230	<3.6	<4.3	<4.9	<5.0	<24										19	80		< 0.00023	
	11/16/10		<250 ³	<3.9	<4.6	<5.3	<5.3	<26										19	80		< 0.00024	
VP-10	07/24/09		<u>2,500B</u>	<3.7	7	52	130		<9.6	<4.5	<4.1	<4.0	12	<5.7	12	21	59	17		0.48		16.00
V1-10	10/22/09		<u>2,100</u>	16	6.1	12	<5.2		<10	<4.7	100	45	91	<5.9	<5.9	<5.9	< 5.9	20		0.29		2.40
	06/29/10		<250	<3.8	<4.5	<5.2	<5.2	<25					<i></i>					19	73	0.43	< 0.00024	
	11/16/10		260^3	<4.0	6.3	<5.4	<5.4	<26										18	72		< 0.00025	
VP-11	07/24/00		4E0D	~ 2.0	10	∠ E 2	8		~ 10	<4.7	<4.3	~ 4.2	<5.0	<5.9	∠ E 0	<5.9	∠ E 0	16		0.26		22.00
V13-11	07/24/09 10/22/09		450B <99	<3.9 <3.9	13 <4.6	<5.2 <5.2	<5.2		<10 <10	<4.7 <4.7	<4.3 <4.3	<4.2	<5.0 <5.0	<5.9 <5.9	<5.9	<5.9 <5.9	<5.9 <5.9	16		0.26 4.00		22.00 <0.12
	06/29/10		<240	<3.9 <3.8	<4.5	<5.2 <5.1	<5.2 <5.1	<25				<4.2			<5.9			14 18	80	1.90	< 0.00024	
	11/16/10		<240 <260	<4.0	<4.7	<5.1 <5.4	<5.1 <5.4	<26										18	80		<0.00025	
	$11/16/10^{1}$ $11/16/10^{1}$		$<260^3$	<4.0	<4.7 <4.7	<5.4 <5.4	<5.4 <5.4	<26										18	80		<0.00025	
VP-12	07/24/09		190B	<3.6	<4.2	<4.9	<4.9		<9.2	<4.3	<3.9	<3.8	<4.6	<5.5	<5.5	<5.5	< 5.5	19		0.73		0.43
V1-12	, ,																					
	$07/24/09^1$		<u>1,600B</u> <95	<3.6	<4.2	<4.9	<4.9		<9.2	<4.3	<3.9	<3.8	<4.6	<5.5	<5.5	<5.5	<5.5 <5.7	19		0.73		0.44
	10/22/09			<3.7	<4.4	<5.0	<5.0	 -02	<9.6	<4.5	<4.1	<4.0	<4.8	<5.7	<5.7	<5.7		18	90	1.40	<0.00022	<0.12
	06/29/10 11/16/10		<220 <240 ³	<3.5 <3.8	<4.1 <4.5	<4.8 <5.2	<4.8 <5.2	<23 <25										20 20	80 80		< 0.00024	
LID 40								-						.= .	.= -	.= -						
VP-13	07/24/09		8,600B	<3.6	200	<5.0	9		<9.4	<4.4	<4.0	<3.9	<4.7	<5.6	<5.6	<5.6	<5.6	15		0.16		26.00
	10/22/09		<95	<3.7	<4.4	<5.0	<5.0	 -25	<9.6	<4.5	<4.1	<4.0	<4.8	<5.7	<5.7	<5.7	<5.7	20		1.30	 <0.000 0	<0.12
	06/29/10		<240	<3.8	<4.4	<5.1	<5.1	<25										16	82		< 0.00024	
	11/16/10		450^{3}	<3.9	<4.6	<5.3	<5.3	<26										15	78	2.60	< 0.00024	4.70
SFRWQCB ESLs ^a	!	29,000	29,000	280	180,000	3,300	58000 ⁴	240	53,000	2,900	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE
SFRWQCB ESLs b	1	1,400	1,400	14	8,800	160	2,900 ⁴	12	2,600	150	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE	NE

CRA 631916 (34) Page 2 of 3

SOIL VAPOR ANALYTICAL RESULTS
FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY
(CHEVRON FACILITY 206127)
2301-2311 BLANDING AVENUE
ALAMEDA, CALIFORNIA

					Ethyl-	т,р-		Chloromethan						Propyl-	Trimethy	4-Ethyl-					
	TPHd	ТРНд	Benzene	Toluene	benzene	Xylene	Naphthalene	e	Bromomethane	Hexane	Cyclohexane	Heptane	Cumene	benzene	l-benzene	toluene	O_2	N_2	CO ₂	CH_4	He
Vapor Well	Sample Date (µg/m³)	(μg/m³)	(µg/m³)	(μg/m³)	(µg/m³)	(µg/m³)	(μg/m ³)	(μg/m³)	(μg/m³)	(µg/m³)	(µg/m³)	(μg/m³)	(μg/m³)	(μg/m³)	(µg/m³)	(µg/m³)	(%)	(%)	(%)	(%)	(%)

Abbreviations and Notes:

Bold = indicates that measured concentration exceeds the ESL for shallow soil gas under commercial/industrial land use.

<u>Underline</u> = indicates that measured concentration exceeds the ESL for indoor air under commercial/industrial land use adjusted by a factor of 100 to account for attenuation between sub-slab and indoor air.

TPHd = Total petroleum hydrocarbons as diesel by EPA Method TO-17

TPHg = Total petroleum hydrocarbons as gasoline by EPA Method TO-3 (8/19/08) or TO-15 GC/MS

Volatile Organic Compounds by EPA Method TO-15

Oxygen (O₂₎, nitrogen (N₂), carbon dioxide (CO₂₎, methane (CH₄) and helium (He) by ASTM Method D-1946

NE = Not established

NS = Not sampled due to the presence of water in vapor well

B = Compound present in laboratory blank greater than reporting limit, background subtraction not per

^a = Environmental Screening Levels for shallow soil gas associated with potential vapor intrusion concerns at commercial/industrial sites (Table E, SFRWQCB, 2008).

b = Environmental Screening Levels for indoor air under commercial/industrial land use adjusted by a factor of 100 to account for attenuation between sub-slab and indoor air (Table E, SFRWQCB, 2008).

¹ = Field duplicate sample

 2 = TPHg analysis by TO-15 APH

³ = Estimated value due to laboratory error

⁴ = ESL is for total xylenes

< = Not detected at or above stated laboratory reporting limit

-- = Not analyzed

CRA 631916 (34) Page 3 of 3

TABLE 5 Page 1 of 1

INDOOR AND OUTDOOR AIR ANALYTICAL RESULTS FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON FACILITY 206127) 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA

		ТРНд	Benzene	Toluene	Ethylbenzene	m,p-Xylene	Naphthalene	O_2	N_2	CO_2	CH_4	Не
Vapor Well	Sample Date					(μ <i>g/</i> n	n ³)					
IA-1	06/29/10	290	0.52	4.50	0.27	0.97	<4.0					
	$11/16/10^2$	220	1.70	7.70	0.61	2.20	<4.1	22	78	0.042	0.00021	<0.078
IA-2	06/29/10	490	0.57	5.20	2.30	8.3	<4.1					
	$11/16/10^2$	390	0.97	15.00	1.80	5.7	<4.4	22	78	0.048	0.00021	< 0.084
IA-3	07/09/10	110	0.39	1.80	0.27	0.92	<4.3	22	78	0.040	0.00019	<0.082
	$07/09/10^3$	100	0.41	2.00	0.26	0.91	<4.3					
	$11/16/10^2$	530	4.20	35.00	6.00	23.00	<4.2	22	78	0.046	0.00021	<0.081
IA-4	06/29/10	490	1.80	16.00	2.10	7.9	<4.0					
	$11/16/10^2$	200	0.77	4.40	0.74	2.5	<4.4	22	78	0.041	0.00020	< 0.084
OA-1	06/29/10	<160	0.24	0.78	0.15	0.48	<4.0					
	$11/16/10^2$	110	0.61	2.10	0.38	1.20	<4.1	22	78	0.043	0.00021	<0.078
SFRWQCB ESLs		14	0.14	88.00	1.60	29 ¹	0.12	NE	NE	NE	NE	NE

Abbreviations and Notes:

Bold = indicates that measured concentration exceeds the ESL for indoor air under commercial/industrial land use.

TPHg = Total petroleum hydrocarbons as gasoline by EPA Method TO-15 GC/MS SIM.

Volatile organic compounds by EPA Method TO-15 GC/MS SIM.

Oxygen (O₂), nitrogen (N₂), carbon dioxide (CO₂), methane (CH₄) and helium (He) by ASTM Method D-1946.

ESLs = Environmental Screening Levels associated with ambient and indoor air at commercial/industrial sites (Table E, SFRWQCB, 2008).

NE = Not established.

¹ = ESL is for total xylenes.

² = Samples analyzed by Modified TO-15 APH

³ = Field duplicate sample

< = Not detected at or above stated laboratory reporting limit.

^{-- =} Not analyzed/not applicable.

TABLE 6 Page 1 of 1

WELL CONSTRUCTION SPECIFICATIONS FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (CHEVRON BULK PLANT 206127) 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA

W WID	ъ.	TO C	T (1 D (1	Casing Diameter ¹	01 . 0:		Elle D. I	<i>.</i>
Well ID	Date Installed	TOC	Total Depth (fbg)	(inches)	Slot Size (inches)	Screen Interval (fbg)	Filter Pack (fbg)	Status
Monitoring			γ δ'		, ,	y G ²	у О	
MW-1	8/15/1990	13.49	19.5	2	0.020	4-19	3-19.5	Replaced w/MW-1RB
MW-1RA	8/4/2010	13.02	13	2	0.020	8-13	7-13	Active
MW-1RB	8/4/2010	13.21	20	2	0.020	16.5-20	15.5-20	Active
MW-2	6/19/2009	10.63	18	2	0.020	10.5-15.5	10-16	Active
MW-3	6/19/2009	10.72	18.5	2	0.020	13.5-18.5	12.5-18.5	Active
MW-4	6/19/2009	11.40	20.5	2	0.020	15.5-20.5	14.5-20.5	Active
MW-5	6/23/2009	10.50	18	2	0.020	13-18	12-18	Active
MW-6	8/4/2010	12.98	20	2	0.020	16.5-20	15.5-20	Active
<u>Piezometer</u>	<u>Wells</u>							
P-1	9/28/2012	13.23	20	1	0.020	16.5-20	15.5-20	Active
P-2	9/28/2012	13.51	12	1	0.020	7-12	6-12	Active
Vapor Wells	<u>s</u>							
VP-1	7/9/2008	NS	4.25	1	0.020	3.75-4.25	3.5-4.5	Vapor only
VP-2	7/9/2008	NS	4.75	1	0.020	4.25-4.75	4-5	Vapor only
VP-3	7/14/2008	NS	5.75	1	0.020	5.25-5.75	5-6	Vapor only
VP-4	7/14/2008	NS	5.75	1	0.020	5.25-5.75	5-6	Vapor only
VP-5	7/14/2008	NS	5.75	1	0.020	5.25-5.75	5-6	Vapor only
VP-6	7/9/2008	NS	5.75	1	0.020	5.25-5.75	5-6	Vapor only
Sub-Slab Va	<u>apor Probes</u>							
VP-7	7/17/2009	NS	0.5	0.25	NA	NA	NA	Vapor only
VP-8	7/17/2009	NS	0.5	0.25	NA	NA	NA	Vapor only
VP-9	7/22/2009	NS	0.5	0.25	NA	NA	NA	Vapor only
VP-10	7/22/2009	NS	0.5	0.25	NA	NA	NA	Destroyed
VP-11	7/17/2009	NS	0.5	0.25	NA	NA	NA	Destroyed
VP-12	7/22/2009	NS	0.5	0.25	NA	NA	NA	Destroyed
VP-13	7/22/2009	NS	0.5	0.25	NA	NA	NA	Vapor only

Abbreviations / Notes

TOC = Top of casing elevation (feet above mean sea level)

fbg = Feet below grade

NA = Not applicable

NS = Not surveyed

¹ = Schedule 40 PVC casing material

Appendix A

Boring Logs



ROJECT: PARK	(STREE eda, Cali	T LANDING fornia		ring No. SB1
Alame	c ua, cal		ELEVATION AND DATUM:	:
ORING LOCATION	N:		Ground surface DATE STARTED:	DATE FINISHED:
		Precision Sampling	2/17/95	2/17/95 MEASURING POINT:
			TOTAL DEPTH: 10 feet bgs.	Ground surface
RILLING METHOL			DEPTH TO FIRST WATER	COMPL. 24 HRS.
RILLING EQUIPM			LOGGED BY:	252 112
		riro Core System DROP:	RESPONSIBLE PROFESS A. L. Spencer	SSIONAL: REG. NO. RG 5713
SAMPLES		DESCRIPTI NAME (USCS Symbol): color, moist, % by wt., plast., density	201	REMARKS
Sample No. Sample Blows/	Foot U	NAME (USCS Symbol): color, moist, % by wc, plast, delisity Surface Elevati		
- v v d	- -	Asphalt		1
1 -	7 7 357 491	Color change to dark gray (5Y greenish gray (5BG 4/1)	avel; 20% medium plasticity oist; 60-70% fine to medium fines; firm	
12 -				[]
13-				14
				B-
14 14397	1	Geomatrix Consultants	Project No.	

ROJECT: PARK STE Alameda,	REET I	LANDING nia		_		ing ive	o. SB2
	Camor		E	LEVATION AN Ground surface	D DATUM: :e		
ORING LOCATION:				ATE STARTE		DATE FIN 2/20/95	SHED:
RILLING CONTRACTO	R: Pre	cision Sampling		2/20/95 TOTAL DEPTH:		MEASURI	NG POINT:
RILLING METHOD: D		•		10 feet bgs DEPTH TO	FIRST	Ground s	24 HRS.
PILLING EQUIPMENT			1	WATER			
SAMPLING METHOD:			Į.	LOGGED BY: T. F. Wood			REG. NO.
		DROP:		RESPONSIBLE A. L. Spence	E PROFESS r	IONAL:	RG 5713
HAMMER WEIGHT:							
SAMPLES E	(wdd)	DESCRIPT NAME (USCS Symbol): color, moist, % by wt., plast., densit	y, structure, ceme	intation, react. w/HC	, geo. inter.	ļ F	REMARKS
(feet) Sample No. Sample Blows/ Foot	<u> </u>	Surface Elevati	ion:				
core		Concrete - sidewalk		DAVEL (CD	-SC)	-	
1 17 1		POORLY GRADED SAND with CL Dark brown (10YR 3/3); moist; 70%				+	
1- X		Dark brown (10YR 3/3); moist, 70% coarse sand); 20% fine to coarse a	ingular gra	vel; 10% low	to	4	
SB2-		medium plasticity fines; loose					
2 - 2.0	0	•				-	
- 1 IXI I]	
3 - 582							
3 SB2-	0						
SB2-1	0					1	
4-1 [7]						1	
7 1\/1 1		??		— —? — —		1	
5-		SANDY LEAN CLAY (CL)	oist: 60-65	% fines: 35-	40%	+	
		SANDY LEAN CLAY (CL) Dark greenish gray (5BG 4/1); m fine to medium sand; medium pla	asticity; firr	n		4	
6-		fine to medium same, meaning	-		Ì	4	
- _{SB2} -	040					-	
7 - 7.0	848						
8-							
"]							
]	
9 - _{SB2} -	158						
SB2-	178					11	
10 - 10.5		Bottom of boring at 10 feet bgs				11	
						14	
11-						14	
						14	
12-						14	
13 -							
'3						17	
8 14					Onnie -A Nie	0426.02	B-1 Figure
14		Geomatrix Consultants			Project No.	2430.02	

	PROJE	CT:	PAF	RK S	TREE	T LANDIN	G		<u> </u>		Log	of Bor	ing	No.	SB3	
			Alar	neda	a, Cal	fornia					ELEVATION AN	ID DATUM:				
L	BORIN										Ground surface			E FINIS	HED:	
. [DRILLI	NG C	ONT	'RAC'	TOR: F	Precision S	ampling				2/17/95 2/17/95 TOTAL DEPTH: MEASURING F					
Γ	DRILLI	NG M	ETH	IOD:	Direc	t push					10 feet bgs DEPTH TO	FIRST		ound su MPL.	rface 24 HRS.	
ľ	DRILLI	NG E	QUII	PMEN	NT: XI) 1				<u></u>	WATER LOGGED BY:		<u> </u>		<u></u>	
f	SAMP	LING	MET	HOD	: Env	iro Core Sy	stem				T. F. Wood	PPOEESS	IONAL	•	T REG. N	10.
t	HAMM	ER W	/EIG	HT:			DROP:	-			A. L. Spence		1011712	•	RG 5	
f	DEPTH (feet)		VPLI 물	ot ot	PID Reading (ppm)	NAME (USC	S Symbol): color	, moist, % b	DESCRI y wt., plast., de	PTION ensity, structure, cer	mentation, react. w/HCl	, geo. inter.		RE	MARKS	
	DE S	Sample No.	Sam	Blows/ Foot	ē,			5	Surface Ele	vation:		 T	-			
ſ						Aspha		0	DAV(51 /	(CC)			1			
-	1- - 2-	SB3- 1.0 SB3- 1.5	\ /		7 36	1/0011	ine to coa	(10VR :	3/11: drv:	40% tine to	medium sand edium plasticit	d; y	+			
	3-	1	N										1			
	4 -					SANI	OY LEAN	CLAY (CL) BG 4/1):	_ — — — — moist: 60 -6	5% fines; 35-	40%	-			
	5-					fine s	and; med	jum pla	sticity; fir	m			4			
	6.	SB3			244											
`	7	6.5 SB3- 7.0			338											
	8	-											-			
		-											1			
	9	SB3			11	₩ Mc	ottled with	dark gr	ray (5Y 4	/1)						
	10	SB3			19	Botto	om of bori	ng at 1	0 feet bg	s			1			
	11										٠		+			
	12	1														
	13	+														
•		+														B-1 (11/92)
6	14		<u> </u>				eomatrix (Consult	ants		Pr	oject No. 2	436.02		Figure	
Š	3					G	EUMANIA (

ROJECT: PARK S	STREI a, Cal	ET LANDING lifornia	_	of Bori	ng No	. SB4		
ORING LOCATION:			ELEVATION AN Ground surface	ce				
		Precision Sampling	DATE STARTED 2/17/95	D:	DATE FINIS 2/17/95			
		Precision Sampling	TOTAL DEPTH:	;	MEASURIN Ground su	IG POINT: Irface		
RILLING METHOD:			10 feet bgs DEPTH TO	FIRST	COMPL.	24 HRS.		
RILLING EQUIPME	NT: X	D1	WATER LOGGED BY:	<u> </u>				
AMPLING METHOD): Env	viro Core System	T. F. Wood RESPONSIBLE	PROFESSIO)NAL:	REG. NO.		
HAMMER WEIGHT:		DROP:	A. L. Spence		· - ·	RG 5713		
(leet) (sample Sample Blows/ Foot	PID Reading (ppm)	DESCRIPTION NAME (USCS Symbol): color, moist, % by wt., plast, density, stru	cture, cementation, react, w/HCl	, geo. inter.	RE	EMARKS		
Sample No. Sample Blows/ Foot	e e	Surface Elevation:						
		Asphalt						
SB4-	59	CLAYEY SAND with GRAVEL (SC) Very dark gray (10YR 3/1) to dark yel	lowish brown (10YF	٦ 4/4);				
1 SB4-	19	dry: 40% fine to coarse sand; 40% fin	ie to coarse aligular	r. 				
		gravel; 20% medium plasticity fines; le		1 =				
2		•		-				
7 //				-				
3 -				-	1			
1								
4-		SANDY LEAN CLAY (CL)	60_65°/ fines: 35 4	0%				
 \ 		Dark greenish gray (5BG 4/1); moist; fine sand; medium plasticity fines; firm	, ou-oo% iines; 35-4 m	.575				
5 -		mne sand, medium plasticity lines, im						
4 1/11				-				
6 - _{SB4}				-				
6.5 SB4-	726			`				
7 - SB4-	1247	' h		-	1			
]]]]		Black mottling		.	1			
ا لـ ۵		DIACK INCLUMY		.	1			
8		H			1			
7				.	4			
9 - _{SB4-}	270	1			4			
SB4-	111	İ			4			
10 - 10.0	'''	Bottom of boring at 10 feet bgs			4			
4					_			
11 -								
1					7			
12 -					1			
-					†			
					+			
13 -					4			
14						B-1 (
14		Geomatrix Consultants	Dr.	roject No. 243)6.00	Figure		

PROJECT: PARK STRE Alameda, C	EET LANDING alifornia		oring No. SB5
		ELEVATION AND DATE	UM:
BORING LOCATION:		DATE STARTED:	DATE FINISHED:
DRILLING CONTRACTOR:	Precision Sampling	2/17/95 TOTAL DEPTH:	2/17/95 MEASURING POINT:
DRILLING METHOD: Dire	ect push	10 feet bgs	Ground surface COMPL. 24 HRS.
DRILLING EQUIPMENT:	XD 1	WATER	
SAMPLING METHOD: Er	nviro Core System	T. F. Wood	FSSIONAL: REG. NO.
HAMMER WEIGHT:	DROP:	RESPONSIBLE PROF A. L. Spencer	RG 5713
DEPTH (feet) Sample Sample Sample Sample Foot Foot (ppm)	DESCR	RIPTION Jensity, structure, cementation, react, w/HCl, geo. inter	r. REMARKS
(feet) (sample No. Sample No. Sample Blows/ Foot PID Read (ppm)	Surface Ele		
	Asphalt		44
5 - SB5- 1.5 1643 2 - 3 - 4 - 4 - 4 - 5 - SB5- 5.5 SB5- 6.0 176	POORLY GRADED SAND with Dark yellowish brown (10YR4/4) 30% fine to coarse angular gradines; loose Color change to dark brown CLAYEY SAND (SC) Black (2.5YR 2.5/0); moist; 60-medium plasticity fines; soft	(7.5YR 3/2) 	Brick and plastic pieces present
9 SB5- 9.5	6		
10 - SB5-	Bottom of boring at 10 feet bg	ıs	-11
	Bottom of boiling at 10 leet by	, .	
11 -			
12-			
13 -			
80 44			B-1 (11/92
14 14	Geomatrix Consultants	Project No	o. 2436.02 Figure

Γ	PROJE					ET LANDING ifornia		g of Bo		o. SB6
-	BORIN	GIC	CAT	ION:			ELEVATION Ground su	AND DATUM:		
L						Precision Sampling	DATE STAR 2/17/95		DATE FINI 2/17/95	
-							TOTAL DEP 10 feet bg		MEASURII Ground s	NG POINT: surface
-						t push	DEPTH TO	FIRST	COMPL.	24 HRS.
					NT: X		LOGGED B			
	SAMP	LING	ME	THOD	: Env	iro Core System	T. F. Wood	d BLE PROFESS	SIONAL:	REG. NO.
	HAMN					DROP:	A. L. Sper	ncer	T	RG 5713
	DEPTH (feet)		MPL 음		PID Reading (ppm)	DESCRIPTION NAME (USCS Symbol): color, moist, % by wt., plast., density, stru	ucture, cementation, react. w	/HCl, geo. inter.	R	EMARKS
		Sample No.	Sample	Blows/ Foot	g g	Surface Elevation:	•			
						Asphalt			4	
	1-	SB6- 1.0			26	CLAYEY SAND with GRAVEL (SC) Very dark gray (10YR 3/1); dry; 40%	fine to medium s	and;	+	
	' <u>-</u>	SB6- 1.5			36	40% fine to coarse angular gravel; 20)% medium plasti	icity	-	
-	2-		N /			fines; loose			‡	
	-		V						1	
	3-		$ \Lambda $						1	
	-		//							
	4-	\mid				SANDY LEAN CLAY (CL)]	
	-	1	\mathbb{N}			Dark greenish gray (5BG 4/1); moist; fine sand; medium plasticity; firm	60-65% fines; 3	5-40%		
	5-	1	IV			ine sand, medium plasticity,			1	
	-	1	$I \land$							
	6-		/ \	V					4	
`	_ '	SB6 7.0			248				4	
	7		\boxtimes						4	
	8	SB6 8.0			26				+	
									+	
	9	J				Black mottling		ļ		
		SB6			86				-	
	10	SB6		Ŋ.	32	Bottom of boring at 10 feet bgs				
		4				Dollow or point at 10 1000 250			1	
	11	4							1	
		4								
	12	4								
		+								
	13	+								
7.		4								B-1 (11/92)
2436.02.007	14					Geomatrix Consultants		Project No. 2	436.02	Figure
24.	ــــــ									

PROJECT: PARK STREE	ET LANDING lifornia	Log of Boring No. SB7					
		ELEVATION AND DATUM: Ground surface	·				
BORING LOCATION:		DATE STARTED:	DATE FINISHED:				
DRILLING CONTRACTOR: [Precision Sampling	2/17/95 TOTAL DEPTH:	2/17/95 MEASURING POINT:				
DRILLING METHOD: Direct	et push	10 feet bgs	Ground surface COMPL. 24 HRS.				
DRILLING EQUIPMENT: X	D 1	WATER					
SAMPLING METHOD: Env		LOGGED BY: T. F. Wood					
HAMMER WEIGHT:	DROP:	RESPONSIBLE PROFESS A. L. Spencer	IONAL: REG. NO. RG 5713				
	DESCRII	PTION					
DEPTH (feet) Sample No. No. Blows/ Eoot Cpm) (ppm)	NAME (USCS Symbol): color, moist, % by wt., plast., de	nsity, structure, cementation, react. w/HCl, geo. inter.	REMARKS				
San San San Pio	Surface Elev	ration:					
	Asphalt		Poor recovery				
SB7-			Unable to log				
1 - _{SB7-}			4				
- · · ·		•	-				
2 \/	•		.				
X	?		Concrete in shoe				
3- / \			_ Contracte in circo				
SB7-							
4 - 4.0							
4 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			1				
5-		İ	1				
			1				
6- /\			-				
	?		4				
SB7- 7.0			+				
7-1			4				
			4				
8 /\							
			-				
9 - 887.			_				
9.5 SB7-							
10 - 10.0	Bottom of boring at 10 feet bgs	3					
	Bottom of Barning and the second		1				
11 -			1				
			1				
12 -			4				
'			-				
			-				
13 -							
14			B-1 (11/9				
[14 	Geomatrix Consultants	Project No. 24					

PROJECT: PARK Alame	STREET da, Califor	LANDING mia	Log o		ng No	. SB8
		15 feet N of North corner of trash house	ELEVATION AND Ground surface			
		cision Sampling	DATE STARTED: 2/20/95		DATE FINIS 2/20/95	
			TOTAL DEPTH: 10 feet bgs		MEASURIN Ground st	G POINT: Irface
DRILLING METHOD			DEPTH TO	FIRST	COMPL.	24 HRS.
DRILLING EQUIPM			LOGGED BY:		1	
SAMPLING METHO	D: Enviro	Core System	T. F. Wood RESPONSIBLE F	ROFESSIO	ONAL:	REG. NO.
HAMMER WEIGHT	:	DROP:	A. L. Spencer			RG 5713
SAMPLES	ading (n	DESCRIPTION NAME (USCS Symbol): color, moist, % by wt., plast, density, struct	ture, cementation, react. w/HCl, g	so, inter.	RE	MARKS
Sample Sample Sample Blows/	PID Reading (ppm)	Surface Elevation:				
SB8- 0.5 SB8- 1.0 2 - 3 - 4 - 5 - 6 - 5 - 8 - 8 - 7 - 8 - 9 - 8 - 9 - 9 - 5 - 8 - 10 - 11 - 11 -	10	POORLY GRADED SAND with CLAY All Dark brown (10YR 3/3); moist; 70% fine coarse sand); 15-20% fine to coarse and to medium plasticity fines; loose - ? Increase in fine gravel to 40%; decrea to coarse sand; decrease in fines to 5	to medium sand (tragular gravel; 10-15%) use in sand to 55% fill % ? to medium sand; 60-70% fines; 30-40	ne -	SB8-1.0 new hole approxim north of poor rechole only deep s collected spoon Rock in One 1 ii subrour	nately 1 foot SB8 due to overy. New y 18 inches samples I with split
12 -					- - -	B-1 (11)
14		Geomatrix Consultants		ect No. 243	20.00	Figure

10/	EU/B	ORIN	GI	oc	ATI	ON MA	Р		REMI	EDI	ATI	ON RI	SK N	ANAGEMENT, INC. WELL/BORII				
N	CLU D	J1 (11 4			•	J. 7	ŀ	DATE:						DRILLING METHOD:GEOPI				
1	_						.	PROJE	CT:AA	46				SAMPLING METHOD:CONT	INUOUS CORE			
•		.9	\equiv	_	_		İ	CLIEN	T:CHE	VR	ON			BORING DIAMETER:2"				
	35	· •			_	_	Ì	LOCA	TION:B	LAI	NDI	NG AV	E.	BORING DEPTH:16'				
)			_		}		LAME						WELL CASING:Temporary 1" sch 40 PVC			
		<u> </u>		L				CO./S	TATE:A	LA	ME	DA .		WELL SCREEN:				
						\mathcal{I}			ER:EC					SAND PACK:				
							<u></u>							WATER LEVEL: 6.59 6.60'				
			-	ZED	띭	≥ #	ES.	SAMPLE NUMBER	ΞE	ER	u ₹	GRAPHIC	USCS SYMBOL	TIME: 13:55 14:10				
NEL	L/BOR	ING	FIRST	STABILIZED	SI	NSI	LD TE HNU	MB	DEPTH (FEET)	Š	SAMPLE	ΑP	SSY	DATE: 10/28/98 10/28/98				
COM	IPLET	IOIN		S	MOISTURE	DENSITY BLOWS / ft.	FIELD TEST HNU	S UN	ے تے	RECOVERY	\ _o ≅	GR	oso	DESCRIPTION/LOGGED BY:DR				
	С		又	Y	2	р	LL.		2 -			***		0-3": Asphalt 3"-3':Fill Material; native clayey sandy soil with d	ebris			
 - 	E	<u>-</u>			D D		162	SB-9 4-5' SB-9 5-6'	4 -				CL	3'-13.5':Sandy Clay; greenish gray; 80% low to plasiticity clayey fines; 20% fine sand;roots com	noderate mon			
- - -	E - V M M M 2							SB-9 9-10.5'	8 -					· • • • • • • • • • • • • • • • • • • •				
- - -	R	_			м		287 323 158	SB-9 13-14'	12 -					@13': 40% fine sand				
- -						4.4		16 -				SP	13.5-16': Sand; greenish gray; trace clayey silty 16': Bottom of Boring	fines; fine sand				
- - -		_	-						18 -	+								
<u>-</u> -			-						22	+								
- 									26									
		- -							28	++		 						
_		- -	-						32	+								
-		- -							34	++	+							
		_	_						38									
F		-					42											
		-							44	+	+	_						

_									REMEDIATION RISK MANAGEMENT, INC. WELL/BORING:SB-10									
		ELL/B(ORIN	G L	OC/	ATIO	AM.NC	P	DATE:			ON KI	3K W	DRILLING METHOD:GEOPROBE				
1	Ņ ↑	SB-1	0					1	PROJE					SAMPLING METHOD:CONTINUOUS CORE				
			^					}	CLIEN					BORING DIAMETER:2"				
		/		\	_			}	LOCAT			NG AV	E BORING DEPTH:18'					
	_	_			7			}	CITY:A				WELL CASING:Temporary 1" sch 40 PVC					
	_	BLAN	Vo	\	/			}	CO./S			DA		WELL SCREEN:				
		BLAN	VOING	AU	_			}	DRILL					SAND PACK:				
			- 	\geq				 					,	WATER LEVEL: 9.60'				
				닖	IZED	뿔	_ #	ES	SAMPLE NUMBER	EE		GRAPHIC	USCS SYMBOL	TIME: 14:05				
		JBORI PLETI	NG	FIRST	STABILIZED	ST	NSN SWS	LD TE HNU	MP JMB	DEPTH (FEET)		\$	SSS	DATE: 10/28/98				
	COM		ا ···	- 1	S	MOISTURE	DENSITY BLOWS / ft.	FIELD TEST HNU	SAMPLE NUMBER DEPTH (FEET) RECOVERY SAMPLE INTERVAL					DESCRIPTION/LOGGED BY:DR				
				뫼	Y		Р					∞		0-3":Asphalt;				
	-	- —								2 -		$\otimes\!\!\!\otimes$	Fill					
	-		_			P			3-4'			$\times\!\!\times\!\!\times$		3"-3":fill is a siltiy to clayey sand; olive brown				
		C								4 -	-							
		- E									-	1///	sc	3-7':Clayey Sand: dark brown; 20% clayey fines; 80% fine				
	-							1.0	SB-10 5.5-6.5			1//	30	sand; organic matter, dark brown to black				
	-	E	_		Y				SB-10	8 -								
:	+	- N - T								"	-		1					
										10 -			CL	7-14':Sandy Clay:dark brown; low plasticity clayey fines; 25%				
			_	1	1	1				10	++		1	fine sand; roots common				
	-	- G								12 -			1					
	上							1.7		14			1					
		U	_	\cdot		W		'.'			+		}	14-16': No Recovery				
		"		1			1		SB-10 17-18'					16-18':Sand: greenish gray; trace fines; fine sand				
	 		_		-			1.0		18			SP	18': Bottom of Boring				
	H	لـــا								10								
				-						20		-	1					
			-	-							++	┪						
	-		_			Ì				22	++							
	` 		_	_						24	$oldsymbol{oldsymbol{oldsymbol{\square}}}$							
	H		_	-				-		-	++	4	Ì					
			_	-					1	26	++	-						
			-	-			1				++	-						
	-									28	$\perp \perp$							
	H		_	_					Ì	30	\perp							
			-	-				ļ			+-+	_						
			_	-	1		į			32	+++							
	<u> </u>		•	-						1	++							
	-		-				1			34								
		<u> </u>								36	44	_						
		<u>-</u>									+-+	_						
										38	+-	\dashv						
	—									40								
	H		-							40								
	一		-	_						42	+-							
				-						İ	+-			}				
			-	-						44	+-	\dashv						

r		<u></u>	000	-		A T1/	ON MA	p		REMEDIATION RISK MANAGEMENT, INC. WELL/BORING:SB-11										
	Ň	FLLB	OKIN	G L		~ I I	AM NC	-	DATE:						DR	ILLING MET	HOD:GEOPRO			
ł	1			<u> </u>				ŀ	PROJE								THOD:CONTIN	IUOS CORE		
ı					\supset	•		Ì	CLIEN			NC			BORING DIAMETER:2"					
									LOCA	TION:B	LAN	NDII	NG AV	E	BORING DEPTH:~15'					
		\ \			•	\$	SB-11	Ì		LAME					WELL CASING:Temporary 1" sch 40 PVC					
	8/8	andin		/					CO/S	TATE:	ALA	ME	DA		WELL SCREEN:					
		anding A	lve.		_				DRILL	ER:EC	Α				SA	ND PACK:				
					्रो	ш	نبر	<u> </u>	~		≿		O	겁	WATER LEVEL:	8.19'	7.57'	6.50'		
ı	NA/ELI	L/BOR	ING	ST	STABILIZED	MOISTURE	S 1	FIELD TEST HNU	SAMPLE NUMBER	DEPTH (FEET)	RECOVERY	F.E.	GRAPHIC	USCS SYMBOL	TIME:	09:30	09:47	10:10		
		IPLET		FIRST	IAB	ISI	SNS SNS	LD TE	N N	병판	18	SAMPLE INTERVAL	R	cs s	DATE: 10/28/98 10/28/98 10/28/98					
				윌	DENSITY BLOWS / ft.	믣	υZ		문		၅	ຶ່	DESCRIPTION/LOG	GED BY:DR						
		TT		모	▼		р					1	XXX		0-3":Asphalt					
		c				D			SB-11	2 -			\ggg	Fill	3"-5.5':Fill: baseroc	k-native-debris	; silty to clayey s	sand; olive		
		E						16.8	2.5-3.5	-			888		brown; 15% silty to	clayey fines; 8	5% sand	ļ		
	L	M	_			D				4 -	+	1	$\otimes\!\!\!\otimes$							
	-	E							SB-11					CL	5.5-14': Sandy Clay clayey fines; 15% s	r: greenish gray	/; 85% moderate	plasticity		
	F	N	_	1	Y	м		0.3	6-7'	6 -	_				clayey fines; 15% s	and, some nor	I-Oxide Staining			
		T							SB-11 7-8'	8 -	-	نفي. آيو آوا					ح :			
-		G				١		1.0	SB-11		-						 20 25% fine sa	ad		
	F	R	_	-		W		1.0	10-11	10 -					@11':Increase in sa					
	卜	0		1	ļ			0.3		12 -					@13':25% fine san	d; occasional s	and stringers ar	nd root holes		
		U				w			SB-11 12]						@14': Sand; greeni		clayey to silty fir	es; fine sand		
		T	_	-		l		0.3	14-15' 14 -						15': Bottom of Bori	ng				
	—			-	}	Ì		İ					1		1					
	H		_	-						16	I]	}						
				_						18	+	╀-	4							
				_							+	╫	┥							
	F		_	-						20	十	+	1							
	-		_	-		1				22	工]							
	<u>, </u>		_		-				1	22	+	+	-					l		
	F		-	_						24	+	┿	┪	1						
	 -		_	-							十	╅	7							
	H		-	-		1		ļ		26	I]		İ					
			_				1			28	+	\bot	4							
				_		1	-		l		+	+	-							
	\vdash			-						30	+	+	-							
	\vdash		_	-						1 22	\pm	工		1						
	H		•					İ		32	T	\bot	4							
			_							34	+	+	-							
			_	_		1					+	十	\dashv							
	\vdash			-						36	+	十	_							
			-	_						38	I	\perp	4							
			_							30	+	+								
				_						40	+	+	\dashv							
	—		-	-							+	+	7							
	H			-						42	1		\exists							
			-	_						44	Ţ	\perp								
	1																			

:


_	MELL/ROPING LOCATION MAP							В	REMEDIATION RISK MANAGEMENT, INC. WELL/BORING:SB-12								
	WELL/BORING LOCATION MAP								REMEDIATION RISK MANAGEMENT, 11101						DRILLING METHOD:GEOPROBE		
	↑ <u> </u>								PROJECT:AA46						SAMPLING METHOD:CONTINUOS CORE		
ı			- 1						CLIEN						BORING DIAMETER:2"		
			、	J.					LOCA				VG AV	/E.	BORING DEPTH:~15'		
					р_				CITY:/						WELL CASING:Temporary 1" sch 40 PVC		
		RI A	NDING		\$B-	12			CO./S			ME	DA.		WELL SCREEN:		
ı			VE.			\				ER:CA					SAND PACK:		
L							` .	<u> </u>			T.				WATER LEVEL: 4.63'		
ı				<u> </u>	STABILIZED	품	7	ES.	SAMPLE	ΞE	H	백론	GRAPHIC	USCS SYMBOL	TIME: 11:35		
	VELL COM		RING	FIRST	ABIL	ST	NSI	디	M M M	DEPTH (FEET)	8	SAMPLE INTERVAL	API	SSYI	DATE: 10/28/98		
	COIVII	 1	ION	i I	ST	MOISTURE	DENSITY BLOWS / ft.	FIELD TEST HNU	S ≥	ا ت ا	RECOVERY	ς Ξ	GR	nsc	DESCRIPTION/LOGGED BY:DR		
L		· ·		又	Y	2		<u>L</u>			14.		∞				
-	-						р					7	888		Planter Fill Top Soil; silty to clayey sand; olive brown		
\vdash	•	C	_			ام			SB-12	2-			888	Fill			
-	-	E							2-3'	1 4-]	\ggg				
r	-	M	_		¥					4							
	_	E				М		1.0	SB-12 6-7'	6-	-			CL	4-12.5':Sandy Clay: dark grayish brown; low plasticity 80% fines;		
L		N		-						ŀ	-	•			20% fine sand		
-	-	T	_	-				1.0	SB-12 7-8'	8-	Ħ				200/ 5 250/		
H		G		1					}	10-		-		1	@9':Sandy Clay: olive yellow;; low plasticity 80% fines; 25% fine sand		
t	-	R				м				10	4			1	@11':Sandy Clay: greenish gray; low plasticity 80% fines;		
	_	0	_				Ì	1.0		12-	-			sc	20% fine sand 12.5-14.5': Clayey Sand: greenish gray; 25% fines; 75% sand		
L	_	U		-		VM	ļ !		00.40						14.5-15': Sand; greenish gray; trace fines		
ŀ		T		-		i		1.0	SB-12 14-15	14		Ħ	444	SP	• ***		
ŀ	_	ت		1	Ì					40.] .				
t	-									16	1	_					
	_		_							18	+	+	-				
ŀ				-	-				1	1	+	╁	┪				
ŀ	-		_	-			ļ	Ì		20	+	+	1				
ŀ			_	-	1		ł			22.	工]				
ŀ	_		_				1			22	\perp	1	4				
Ì	_		_							24	+		-				
1			_	-							+	+	1				
ł	_		-	-	1					26	\top	十	1				
ł				-						200	工]				
ı	_		_	_					ľ	28	+	+	4	-			
			_	_				1	İ	30	+	+	-{				
				-				1			+	+	-				
	<u> </u>		-	-						32	十	十	1				
	—		-	-							I						
	_		_							34	I	\perp	4				
			_							36	+	+	-				
	<u> </u>			_							+	+	-				
	 		-	-						38	+	\top	1				
	<u> </u>			\dashv					-	40	I]				
	 		-							40	I	\perp	_				
										42	+	+	-				
	<u> </u>			_							+	+	-				
										44	+	+	7				

BORING/ WELL LOG



Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900 Fax: 916-889-8999

CLIENT NAME Chevron Environmental Management Co. **BORING/WELL NAME SB-13** 07-Jul-08 **JOB/SITE NAME** Former Signal Oil Bulk Plant **DRILLING STARTED** DRILLING COMPLETED 08-Jul-08 2301-2311 Blanding Avenue, Alameda, CA **LOCATION** PROJECT NUMBER 631916 (20-6127) WELL DEVELOPMENT DATE (YIELD) NA **DRILLER** Woodward Drilling Co. Inc. **GROUND SURFACE ELEVATION** NA NA **DRILLING METHOD** Hydraulic push TOP OF CASING ELEVATION NA **BORING DIAMETER** 2 inches **SCREENED INTERVALS LOGGED BY** C. Benedict DEPTH TO WATER (First Encountered) 15.0 fbg (08-Jul-08) **REVIEWED BY** J. Kiernan, PE# C68498 NA **DEPTH TO WATER (Static) REMARKS** Hand-Augered/Airknifed to 8 fbg.



BORING/WELL LOG



Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900 Fax: 916-889-8999

CLIENT NAME Chevron Environmental Management Co. **BORING/WELL NAME** SB-14 07-Jul-08 JOB/SITE NAME Former Signal Oil Bulk Plant **DRILLING STARTED** DRILLING COMPLETED 08-Jul-08 2301-2311 Blanding Avenue, Alameda, CA LOCATION PROJECT NUMBER 631916 (20-6127) WELL DEVELOPMENT DATE (YIELD) NA NA **DRILLER** Woodward Drilling Co. Inc. **GROUND SURFACE ELEVATION DRILLING METHOD** Hydraulic push TOP OF CASING ELEVATION NA NA **BORING DIAMETER SCREENED INTERVALS** 2 inches **LOGGED BY** C. Benedict **DEPTH TO WATER (First Encountered)** 14.5 fbg (08-Jul-08) **REVIEWED BY** J. Kiernan, PE# C68498 **DEPTH TO WATER (Static)** NA **REMARKS** Hand-Augered/Airknifed to 8 fbg.

_							_		+	 	
	PID (ppm)	BLOW COUNTS	SAMPLE ID	EXTENT	DEPTH (fbg)	U.S.C.S.	GRAPHIC LOG	LITHOLOGIC DESCRIPTION	CONTACT DEPTH (fbg)	WEL	L DIAGRAM
EVRONI6319-\631916~1\632941~1\BORING~1\20-6127 BORING LOGS.GPJ DEFAULT.GDT 7/9/09	2.0	CON	SB-14 -10		ID (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	SC SM CL CL SM SM	GRA LICE CONTROL OF THE CONTROL OF T	Asphalt Clayey SAND:Dark brown; dry; 65% sand, 15% clay, 10% silt, 10% gravel; low plasticity. Silty SAND:Black; moist; 45% sand, 30% silt, 25% clay; low plasticity. CLAY:Grey; moist; 55% clay, 30% silt, 15% sand (well-sorted fined grained); medium plasticity; CLAY:Brown; moist; 55% clay, 30% silt, 15% sand; medium plasticity. Sandy CLAY:Brown; moist; 50% clay, 35% sand, 15% silt; medium plasticity. Silty SAND:Brown with grey mottling; moist 55% sand, 30% silt, 10% clay; low plasticity.	NOO 0.5 - 4.0 - 5.5 - 10.5 - 11.5 - 13.0 □ 14.5		Concrete ✓ Concrete ✓ Portland Type I/II Bottom of Boring @ 16 fbg
WELL LOG (PID) \\RAC-S1\SHARED\CH \\											

BORING/WELL LOG



Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900 Fax: 916-889-8999

CLIENT NAME Chevron Environmental Management Co. **BORING/WELL NAME** SB-15 07-Jul-08 JOB/SITE NAME Former Signal Oil Bulk Plant **DRILLING STARTED** DRILLING COMPLETED 08-Jul-08 2301-2311 Blanding Avenue, Alameda, CA LOCATION PROJECT NUMBER 631916 (20-6127) WELL DEVELOPMENT DATE (YIELD) NA NA **DRILLER** Woodward Drilling Co. Inc. **GROUND SURFACE ELEVATION DRILLING METHOD** Hydraulic push TOP OF CASING ELEVATION NA NA **BORING DIAMETER SCREENED INTERVALS** 2 inches **LOGGED BY** C. Benedict **DEPTH TO WATER (First Encountered)** 15.0 fbg (08-Jul-08) **REVIEWED BY** J. Kiernan, PE# C68498 **DEPTH TO WATER (Static)** NA **REMARKS** Hand-Augered/Airknifed to 8 fbg.

(E)	S	<u>Q</u>	þ	Į,	ν _j	2		(fbg)	
PID (ppm)	BLOW	SAMPLE ID	EXTENT	DEPTH (fbg)	U.S.C.S.	GRAPHIC LOG	LITHOLOGIC DESCRIPTION	CONTACT DEPTH (fbg)	WELL DIAGRAM
0		SB-15 -1			SM		Asphalt Silty SAND: Dark brown; moist; 65% sand, 20% silt, 15% clay, 5% gravel; low plasticity.	0.5	Concrete Concrete
6 LOGS. GPJ DEFAULT, GDJ 7/8/09		SB-15 -5		- 5 - 	sc		Clayey SAND:Black; moist; 60% sand, 20% clay, 10% silt, 10% gravel; low plasticity. Clayey SAND:Dark brown; moist; 60% sand, 20% clay, 10% silt, 10% gravel; low plasticity.	_4.0	▼ Portland Type
EVKONI6319-1-1631916-11632941-1160KiNG-1120-612/ BOKING LOGS.GFJ DEFAULT.GDI //9/09/09/09/19/09/09/09/09/09/09/09/09/09/09/09/09/09		SB-15 -9.5			CL		CLAY with sand: Green; moist; 45% clay, 30% sand, 20% silt, 5% gravel; medium plasticity.	_9.5	1/11
WELL LOG (PID) (IRAC-STISHARED)CHEVRONI6319-1				15 	SM		Silty SAND: Greenish grey; wet; 55% sand (medium to fine grained), 30% silt, 10% clay; low plasticity.	14.5 <u>Z</u> 16.0	Bottom of Boring @ 16 fbg

BORING/ WELL LOG



Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900 Fax: 916-889-8999

LIENT NAME	Chevron Environmental Management Co.	BORING/WELL NAME SB-16		
OB/SITE NAME	Former Signal Oil Bulk Plant	DRILLING STARTED 07-Jul-08		
OCATION	2301-2311 Blanding Avenue, Alameda, CA	DRILLING COMPLETED 08-Jul-08		
ROJECT NUMBER	631916 (20-6127)	WELL DEVELOPMENT DATE (YIELD)	NA	
RILLER	Woodward Drilling Co. Inc.	_ GROUND SURFACE ELEVATION _	NA	
RILLING METHOD	Hydraulic push	TOP OF CASING ELEVATION	NA	
ORING DIAMETER	2 inches	SCREENED INTERVALS	NA	
OGGED BY	C. Benedict	DEPTH TO WATER (First Encountered)) NA	Z
REVIEWED BY	J. Kiernan, PE# C68498	DEPTH TO WATER (Static)	NA	Ţ
DEMARKS		- , ,		

REMAR										
PID (ppm)	BLOW	SAMPLE ID	EXTENT	DEPTH (fbg)	U.S.C.S.	GRAPHIC LOG	LITHOLOGIC DESCRIPTION	CONTACT DEPTH (fbg)	WEL	L DIAGRAM
WELL LOG (PID) NRAC-STISHAREDICHEVRONI6319-J631916-11632941-11BORING-1120-6127 BORING LOGS.GPJ DEFAULT.GDT 7/9/09					SM		Silty SAND: Brown; dry; 50% sand, 20 gravel, 20% silt, 10% clay; low plasticity. Refusal at 3 feet.	3.0		Bottom of Boring @ 3 fbg

BORING/WELL LOG



Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900

CLIENT NAME Chevron Environmental Management Co. **JOB/SITE NAME** Former Signal Oil Bulk Plant 2301-2311 Blanding Avenue, Alameda, CA **LOCATION** PROJECT NUMBER 631916 (20-6127) **DRILLER** Woodward Drilling Co. Inc. **DRILLING METHOD** Hydraulic push **BORING DIAMETER** 2 inches **LOGGED BY** C. Benedict **REVIEWED BY** J. Kiernan, PE# C68498 **REMARKS** Hand-Augered/Airknifed to 8 fbg.

Fax: 916-889-8999

BORING/WELL NAME SB-17 07-Jul-08 **DRILLING STARTED** DRILLING COMPLETED 08-Jul-08 WELL DEVELOPMENT DATE (YIELD) NA **GROUND SURFACE ELEVATION** NA NA TOP OF CASING ELEVATION NA **SCREENED INTERVALS DEPTH TO WATER (First Encountered)** NA **DEPTH TO WATER (Static)** NA


CONTACT DEPTH (fbg) GRAPHIC LOG PID (ppm) BLOW EXTENT U.S.C.S. DEPTH (fbg) SAMPLE LITHOLOGIC DESCRIPTION WELL DIAGRAM Asphalt Concrete 0.5 Silty SAND: Grey; moist; 60% sand, 20% silt, 10% clay, 10% gravel; low plasticity. SB-17 -1 1.7 SM 4.0 Clayey SAND:Black; moist; 55% sand, 20% clay, 15% WELL LOG (PID) \\RAG-S1\SHARED\CHEVRON\6319-\631916~1\632941~1\BOR\NG~1\20-6127 BOR\NG LOGS.GPJ DEFAULT.GDT 7/9/09 silt, 10% gravel (coarse angular); low plasticity. SC 122 SB-17 -5 6.0 CLAY with sand: Greenish grey; moist; 45% 5 clay, 25% silt, 20% sand; medium plasticity. Portland Type CL SB-17 -9.5 10.5 <u>Silty SAND</u>:Greenish grey; moist 55% sand (medium to fine grained), 30% silt, 10% clay; low plasticity. SM 16.0 Bottom of Boring @ 16 fbg

BORING/ WELL LOG



Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900 Fax: 916-889-8999

CLIENT NAME Chevron Environmental Management Co. **BORING/WELL NAME SB-18** 07-Jul-08 **JOB/SITE NAME** Former Signal Oil Bulk Plant **DRILLING STARTED** DRILLING COMPLETED __08-Jul-08 2301-2311 Blanding Avenue, Alameda, CA **LOCATION PROJECT NUMBER** 631916 (20-6127) WELL DEVELOPMENT DATE (YIELD) NA **DRILLER** Woodward Drilling Co. Inc. **GROUND SURFACE ELEVATION** NA NA **DRILLING METHOD** Hydraulic push TOP OF CASING ELEVATION NA **BORING DIAMETER** 2 inches **SCREENED INTERVALS LOGGED BY** C. Benedict **DEPTH TO WATER (First Encountered)** 14.5 fbg (08-Jul-08) **REVIEWED BY DEPTH TO WATER (Static)** J. Kiernan, PE# C68498 NA **REMARKS** Hand-Augered/Airknifed to 8 fbg.



BORING/ WELL LOG



Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900 Fax: 916-889-8999

CLIENT NAME Chevron Environmental Management Co. **BORING/WELL NAME** SB-19 07-Jul-08 **JOB/SITE NAME** Former Signal Oil Bulk Plant **DRILLING STARTED** DRILLING COMPLETED __08-Jul-08 2301-2311 Blanding Avenue, Alameda, CA **LOCATION** PROJECT NUMBER 631916 (20-6127) **DRILLER** Woodward Drilling Co. Inc. **GROUND SURFACE ELEVATION DRILLING METHOD** Hydraulic push TOP OF CASING ELEVATION **BORING DIAMETER** 2 inches **SCREENED INTERVALS** LOGGED BY C. Benedict **REVIEWED BY** J. Kiernan, PE# C68498 **DEPTH TO WATER (Static) REMARKS** Hand-Augered/Airknifed to 8 fbg.

WELL DEVELOPMENT DATE (YIELD) NA NA NA NA **DEPTH TO WATER (First Encountered)** 14.5 fbg (08-Jul-08) NA

CONTACT DEPTH (fbg) GRAPHIC LOG (mdd) BLOW EXTENT U.S.C.S. DEPTH (fbg) SAMPLE LITHOLOGIC DESCRIPTION WELL DIAGRAM Ы Asphalt Concrete 0.5 Silty SAND: Dark brown; moist; 60% sand, 20% silt, 10% clay, 10% gravel; low plasticity; conrete fragements. SB-19 -1 362 Brown; wet; 75% sand, 15% silt, 10% clay; low plasticity. SM Black; moist; 60% sand, 20% silt, 10% clay, 10% gravel; WELL LOG (PID) \\RAG-S1\SHARED\CHEVRON\6319-\631916~1\632941~1\BOR\NG~1\20-6127 BOR\NG LOGS.GPJ DEFAULT.GDT 7/9/09 low plasticity. 1,373 SB-19 -5 Grey; moist; 60% sand, 20% silt, 10% clay, 10% gravel; low plasticity. Greenish grey; moist; 70% sand, 20% silt, 10% clay; low plasticity. 7.0 CLAY with sand: Greenish grey with balck mottling; moist; 45% clay, 30% sand, 25% silt; medium plasticity. Portland Type SB-19 -10 10 CL 14.0 Silty SAND: Greenish grey; wet; 65% sand (poorly ∇ graded), 20% silt, 15% clay; low plasticity. SM 16.0 Bottom of Boring @ 16 fbg

BORING LOCATION: Northwest corner by canal DRILLING CONTRACTOR: Precision Sampling DRILLING METHOD: Direct push DRILLING METHOD: Direct push DRILLING METHOD: Enviro Core System HAMMER WEIGHT: E 3	Log of Boring No. GWS-7A				
DRILLING CONTRACTOR: Precision Sampling DRILLING METHOD: Direct push DEP DRILLING METHOD: Enviro Core System SAMPLING METHOD: Enviro Core System DROP: DESCRIPTION NAME (USCS Symbol): color, moist, % by wt., plast, density, structure, camendator. Surface Elevation: Gravel sidewalk CLAYEY SAND (SC) Very dark grayish brown (10Y 3/2), dry, 60% me sand, 30% low plasticity fines, 10% small gravel for gray concrete and brick fragments GRANULAR MATERIAL Black (7.5YR 2.5/1), moist, 60% fine to medium low plasticity fines, 5% small gravel, loose Refusal at 6 feet bgs Refusal at 6 feet bgs	ELEVATION AND DATUM: Gravel sidewalk				
DRILLING METHOD: Direct push AMPLING METHOD: Enviro Core System HAMMER WEIGHT: E	ATE STARTED: 1/24/95	DATE FINISHED:			
DEP WAR SAMPLING METHOD: Enviro Core System S.L.	OTAL DEPTH: 5 feet	MEASURING POINT: Ground surface			
SAMPLING METHOD: Enviro Core System HAMMER WEIGHT: E G G SAMPLES Symbol: color, moist, % by wt., plast. dently, stucture, comentation Surface Elevation: CLAYEY SAND (SC) Very dark grayish brown (10Y 3/2), dry, 60% me sand, 30% low plasticity fines, 10% small gravel for plasticity fines, 10% small gravel low plasticity fines, 5% small gravel, loose Refusal at 6 feet bgs	DEPTH TO FIRST	COMPL. 24 HRS.			
HAMMER WEIGHT: E a g g g g g g g g g g g g g g g g g g	OGGED BY:				
SAMPLES SAMPLES Set of the content	RESPONSIBLE PROFESSI	ONAL: REG. NO. RG 5713			
Gravel sidewalk CLAYEY SAND (SC) Very dark grayish brown (10Y 3/2), dry, 60% me sand, 30% low plasticity fines, 10% small gravel Gray concrete and brick fragments GRANULAR MATERIAL Black (7.5YR 2.5/1), moist, 60% fine to medium low plasticity fines, 5% small gravel, loose Refusal at 6 feet bgs 7- 10- 11- 12- 13- 14-	A. L. Spencer	, NG 9713			
Gravel sidewalk CLAYEY SAND (SC) Very dark grayish brown (10Y 3/2), dry, 60% me sand, 30% low plasticity fines, 10% small gravel Gray concrete and brick fragments GRANULAR MATERIAL Black (7.5YR 2.5/1), moist, 60% fine to medium low plasticity fines, 5% small gravel, loose Refusal at 6 feet bgs 7- 10- 11- 12- 13- 14-	tation, react. w/HCl, geo. inter.	REMARKS			
CLAYEY SAND (SC) Very dark grayish brown (10Y 3/2), dry, 60% me sand, 30% low plasticity fines, 10% small gravel Gray concrete and brick fragments GRANULAR MATERIAL Black (7.5YR 2.5/1), moist, 60% fine to medium low plasticity fines, 5% small gravel, loose Refusal at 6 feet bgs 7- 8- 9- 10- 11- 12- 13- 14-					
	vei, ioose				
		B-1 (11/9)			
2436.02.038 Geomatrix Consultants	Project No. 243	6.02 Figure			

PROJECT: PARK STREE	ET LANDING ifornia	Log of Boring No. GWS-7B				
BORING LOCATION: North	ELEVATION AND DATUM: Gravel sidewalk					
DRILLING CONTRACTOR: F	DATE FINISHED:					
	MEASURING POINT: Ground surface					
DRILLING METHOD: Direct		6 feet DEPTH TO FIRST	COMPL. 24 HRS.			
DRILLING EQUIPMENT: XI		LOGGED BY:				
SAMPLING METHOD: Env		S. L. Anich RESPONSIBLE PROFESS	IONAL: REG. NO. RG 5713			
HAMMER WEIGHT:	DROP:	A. L. Spencer	, AG 5715			
DEPTH (feet) Sample No. No. Blows/ Smple Foot Foot (ppm)	DESCRIP NAME (USCS Symbol): color, moist, % by wt., plast, den:	sity, structure, cementation, react. w/HCl, geo. inter.	REMARKS			
San San San PB PB PB PB PB PB PB PB PB PB PB PB PB	Surface Eleva Gravel sidewalk	ation:				
1- 1- 2- 3- 3- 4- 3- 5- 5- 6- 7- 8- 9- 10- 11- 12-	CLAYEY SAND (SC) Very dark grayish brown (10Y 3/sand, 30% low plasticity fines, 10 Gray concrete / brick GRANULAR MATERIAL Black (7.5YR 2.5/1), moist, 60% low plasticity fines, 5% small gray Refusal at 6 feet bgs	fine to medium grains, 35%				
13						
			B-1 (11/92			
14	Geomatrix Consultants	Project No. 24	436.02 Figure			

2436 02 039

PROJECT: PARK STREET LAN Alameda, California	DING	Log of Boring No. GWS-7			
BORING LOCATION: Northwest co	orner of property	ELEVATION AND DATUM: Gravel sidewalk			
DRILLING CONTRACTOR: Precision	n Sampling	DATE STARTED: DATE FINISHED: 4/24/95 1000 hrs.			
DRILLING METHOD: Direct push		TOTAL DEPTH: 15 feet	MEASURING POINT: Ground surface		
DRILLING EQUIPMENT: XD-3		DEPTH TO FIRST WATER bgs 9 feet	COMPL. 24 HRS. 9.6 feet		
SAMPLING METHOD: Enviro Core	System	LOGGED BY: S. L. Anich RESPONSIBLE PROFESSIO	NAL: REG. NO.		
HAMMER WEIGHT:	DROP:	A. L. Spencer	RG 5713		
(feet) Sample Sample Sample Poot Foot (pm) (pm) (pm)	DESCRIPTION USCS Symbol): color, moist, % by wt., plast., density, structure, cen	nentation, react. w/HCl, geo. inter:	REMARKS		
1- CL Versar Sar	AN CLAY with SAND (CL) ack (10YR 2/1), moist, 80% fines, 20% satisticity, soft 1-inch lense of coarse gravel EAN CLAY (CL) ack (10YR 4/1), wet, 95% fines, 5% sand	o medium avel, loose nents, moist, small gravel,			
Gr me	EAN CLAY (CL) reenish gray gley (5G 5/1), moist, 95% firedium plasticity	nes, 5% sand,			
2436.02.016	Geomatrix Consultants	Project No. 2436.0	B-1 (11/92) 02 Figure		

PROJECT: PARK STREET LANDING Log of Boring No. GWS-7 (cont.) Alameda, California OVM Reading DESCRIPTION REMARKS Sample No. Sample Blows/ Foot NAME (USCS Symbol): color, moist, % by wt., plast., density, structure, cementation, react. w/HCl, geo. inter. LEAN CLAY (CL) (continued) Orange mottling 15 Bottom of boring at 15 feet bgs 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 B-2 (11/92) Project No. 2436.02 Figure ---**Geomatrix Consultants**

PROJECT: PARK STRE Alameda, Ca		Log of	Borir	ıg No.	GWS-8
BORING LOCATION: Side	ewalk, northwest corner	ELEVATION AND Grassy area	DATUM:		
DRILLING CONTRACTOR:		DATE STARTED 4/24/95	:	DATE FINIS 4/24/95 -	
		TOTAL DEPTH:		MEASURIN	IG POINT:
DRILLING METHOD: Dire			FIRST	Ground s	24 HRS.
DRILLING EQUIPMENT: X		WATER LOGGED BY:	***	9' 0"	
SAMPLING METHOD: En	viro Core System	S. L. Anich RESPONSIBLE	PROFESSI	ONAL:	REG. NO.
HAMMER WEIGHT:	DROP:	A. L. Spencer			RG 5713
DEPTH (feet) Sample No. Sample ASample Foot Foot (ppm)	DESCRIPT NAME (USCS Symbol): color, moist, % by wt., plast, densi	TON tv. structure, cementation, react. w/HCl. (eo. inter.	RE	EMARKS
Cleet) (feet) Sample No. Sample Blows/ Foot PiD Reading (ppm)	Surface Elevat				
				No recov	ery in upper
				2 feet	cry in appor
1-					
					•
2	CLAYEY SAND (SC)				
	Very dark gray (10YR 3/1) with at grass), moist, 65% medium sand,	oundant organics (roots, 25% low plasticity fines,	_		
3	10% fine to coarse gravel, loose	, .	_		
4-					
			_		
5			_		
	Increased sand content to 80%	20% low plasticity fines	_		
6	Increased saild content to 50%	, 20 % low plasticity in oc	되 -		
			_ _		
71					
	LEAN CLAY with SAND (CL)	05% fine cond low	_		
8 -	Black (10YR 2/1), moist, 75% fine plasticity	es, 25% fine sand, low	-		
	pido.i.c.i.y				
9	LEAN CLAY (CL)	050/ 5 59/ 5no con			
	Greenish gray (10GY 5/1), moist, plasticity	95% lines, 5% line sand	1, 10W -		
10-	p.ac.ic.i,		-		
]	
			-		
]	
12 -	 				
	♥				
13 -			1.	1	
					B-1 (11/9)
14	Geomatrix Consultants	Projec	t No. 2436	5.02	Figure

ROJECT:	PA Ala	RK ame	STRE da, Ca	ET LANDING Llifornia	Log of Borir	ng No. GW	S-8 (cont.)
Sample Somple No.	MPL		OVM - Reading	DESCF NAME (USCS Symbol): color, moist, % by wt., plast, c	IPTION lensity, structure, cementation, react. w/H	CI, geo. inter.	REMARKS
- -	X	<u></u>		LEAN CLAY (CL) (continued) Increase sand content to 20°	//a		
15				CLAYEY SAND (SC) Light olive brown (2.5Y 5/4) wi moist, 60% fine sand, 40% low	th green and brown mottl plasticity fines	ling,	
17-				Bottom of boring at 16 feet bgs	3		
18					•		
19							
20				•			
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31						Project No. 2436.02	8-2 (1

DRING LOCATION: Along canal - middle Sidewalk (grave) DATE STARTED: 472/495 1330 hrs 1071AL DEPTH: MESSURING POINT: 1071AL DEPTH: MESSURING POINT: 1071AL DEPTH: MESSURING POINT: 1071AL DEPTH: MESSURING POINT: 1071AL DEPTH: MESSURING POINT: 1071AL DEPTH: MESSURING POINT: 1071AL DEPTH: MESSURING POINT: 1071AL DEPTH: MESSURING POINT: 1071AL DEPTH: MESSURING POINT: 1071AL DEPTH: TO FIRST COMPL. 24 HRS. MANUEL PROPERTY: COMPL. 24 HRS. MANUEL PROPERTY: COMPL. 24 HRS. DESCRIPTION AMMET USOS Symbolic color. Roll 16 by vs. pleat. combly, structure, contretibility, mack. wh/OL pos. Infer. PEMARKS Surface Elevation: Not recovery in upper 3 feet Sample CLAY with GRAVEL (CL) Very dark gray (10/YR 3/1), calcium deposits, dry, 60% fine to medium sand, 15% medium gravel, low plasticity CLAYEY SAND with GRAVEL (SC) Very dark gray (10/YR 3/1), calcium deposits, dry, 60% fine to medium sand, 25% low plasticity fines, 15% fine gravel, loose Increase sand content to 80% CLAYEY SAND with GRAVEL (SC) Very dark gray (10/YR 3/1), moist, 85% fines, 15% fine sand, low plasticity Increase sand content to 30% LEAN CLAY with SAND (CL) Black (10/YR 2/1), moist, 85% fines, 5% fine sand, low plasticity Increase sand content to 30% LEAN CLAY (CL) Greenish gray (10/YS 5/1), moist, 95% fines, 5% fine sand, low plasticity Orange mottling Increase sand content to 30% Increase sand content to 30% Increase sand content to 30% Increase sand content to 30%	PROJECT: PARK STREET LANDING Alameda, California Log of Boring N						GWS-9
RILLING CONTRACTOR: Precision Sampling 4/2495 RILLING METHOD: Direct push 16 feet 1707AL DEPTH: MEASURING POINTS 1303 hrs 16 feet 1707AL DEPTH: MEASURING POINTS 1107AL DEPTH: MEASURING							
RILLING REULING CONTRACTOR'S PROSTRICT COMPL. RILLING REULING EQUIPMENT: XD-3 AMPLING METHOD: Direct push It feet OEPTH TO FIRST COMPL. 24 HRS. WATER S. L. Anich AMMER WEIGHT: — DROP: — RESPONSIBLE PROFESSIONAL: REG. NO. RG 5713 SAMPLES SURface Elevasion: No recovery in upper 3 feet CLAYEY SAND with GRAVEL (CL) Very dark gray (10YR 3/1), dry, 60% fines, 25% fine to medium sand, 15% medium gravel, low plasticity CLAYEY SAND with GRAVEL (SC) Very dark gray (10YR 3/1), calcium deposits, dry, 60% fine to medium sand, 25% low plasticity fines, 15% fine gravel, loose Increase sand content to 80% LEAN CLAY with SAND (CL) Black (10YR 2/1), moist, 85% fines, 15% fine sand, low plasticity Increase sand content to 30% LEAN CLAY (CL) Greenish gray (10GY 5/1), moist, 95% fines, 5% fine sand, low plasticity Increase sand content to 30% Increase sand content to 30% Increase sand content to 30% Increase sand content to 30%	ORING LOCATION:	Along canal -	midale		DATE STARTED: DATE FINISHE		
FILLING METHOD: Direct push RILLING EQUIPMENT: XD-3 AMPLING EQUIPMENT: XD-3 AMPLING METHOD: Enviro Core System AMMER WEIGHT: SAMPLES SAMPLES SAMPLES SAMPLES SAMPLES SAMPLES SAMPLE AND MAKE (USCS Symbols: color, molat, % by vt., peat, demay, stockins, comentation, mach, wirld, gest, inter. SUrface Elevation: No recovery in upper 3 feet CLAYEY SAND with GRAVEL (CL) Very dark gray (10YR 3/1), doly, 60% fines, 25% fine to medium sand, 15% medium gravel, low plasticity CLAYEY SAND with GRAVEL (SC) Very dark gray (10YR 3/1), calcium deposits, dry, 60% fine to medium sand, 25% low plasticity fines, 15% fine gravel, loose Increase sand content to 80% LEAN CLAY with SAND (CL) Black (10YR 2/1), moist, 85% fines, 15% fine sand, low plasticity Increase sand content to 30% LEAN CLAY (CL) Greenish gray (10GY 5/1), moist, 95% fines, 5% fine sand, low plasticity Orange mottling Increase sand content to 30% Increase sand content to 30% Increase sand content to 30% Increase sand content to 30%	RILLING CONTRAC	TOR: Precision	Sampling			4/24/95 -	1330 hrs
RILLING EQUIPMENT: XD-3 MAPPLING METHOD: Enviro Core System AMPLING METHOD: Enviro Core System DROP: — DESCRIPTION AMMER WEIGHT: — DROP: — DESCRIPTION NAME (UBCS Symbol): color. molar. System. System. plant, almost, shouth, demandation, mact. whicit, spo. link. SAMPLES SAMPLES SAMPLES SAMPLES SAMPLES SAMPLES SAMPLES SAMPLES SAMPLES SAMPLES SAMPLES SAMPLES SAMPLES SUrface Elevation: No recovery in upper 3 feet CLAYEY SAND with GRAVEL (CL) Very dark gray (10YR 3/1), dny, 60% fines, 25% fine to medium sand, 15% medium gravel, low plasticity CLAYEY SAND with GRAVEL (SC) Very dark gray (10YR 3/1), calcium deposits, dry, 60% fine to medium sand, 25% low plasticity fines, 15% fine gravel, loose Increase sand content to 80% LEAN CLAY with SAND (CL) Black (10YR 2/1), moist, 85% fines, 15% fine sand, low plasticity Increase sand content to 30% LEAN CLAY (CL) Greenish gray (10QY 5/1), moist, 95% fines, 5% fine sand, low plasticity Orange mottling Increase sand content to 30%	RILLING METHOD:	Direct push				Ground st	urface
MAMPLING METHOD: Enviro Core System S. L. Anich RESPONSIBLE PROFESSIONAL: RESPONSIBLE PROFESSIO				·	FIRST	i	24 HRS.
AMMER WEIGHT: DROP:				LOGGED BY:			<u> </u>
SANDY LEAN CLAY with GRAVEL (CL) Sandy Lean CLAY with GRAVEL (CL) Very dark gray (10YR 3/1), dry, 60% fines, 25% fine to medium sand, 15% medium gravel, low plasticity CLAYEY SAND with GRAVEL (SC) Very dark gray (10YR 3/1), calcium deposits, dry, 60% fine to medium sand, 25% low plasticity fines, 15% fine gravel, loose Increase sand content to 80% LEAN CLAY with SAND (CL) Black (10YR 2/1), moist, 85% fines, 15% fine sand, low plasticity Increase sand content to 30% LEAN CLAY (CL) Greenish gray (10GY 5/1), moist, 95% fines, 5% fine sand, low plasticity Orange mottling Increase sand content to 30% Increase sand content to 30% Increase sand content to 30% Increase sand content to 30% Increase sand content to 30% Increase sand content to 30% Increase sand content to 30% Increase sand content to 30%				RESPONSIBL		ONAL:	
SANDY LEAN CLAY with GRAVEL (CL) Very dark gray (10YR 3/1), dry, 60% fines, 25% fine to medium sand, 15% medium gravel, low plasticity CLAYEY SAND with GRAVEL (SC) Very dark gray (10YR 3/1), calcium deposits, dry, 60% fine to medium sand, 25% low plasticity fines, 15% fine gravel, loose Increase sand content to 80% LEAN CLAY with SAND (CL) Black (10YR 2/1), moist, 85% fines, 15% fine sand, low plasticity Increase sand content to 30% LEAN CLAY (CL) Greenish gray (10GY 5/1), moist, 95% fines, 5% fine sand, low plasticity Orange mottling Increase sand content to 30% Increase sand content to 30%					er	1	; HG 5/13
SANDY LEAN CLAY with GRAVEL (CL) Very dark gray (10YR 3/1), dry, 60% fines, 25% fine to medium sand, 15% medium gravel, low plasticity CLAYEY SAND with GRAVEL (SC) Very dark gray (10YR 3/1), calcium deposits, dry, 60% fine to medium sand, 25% low plasticity fines, 15% fine gravel, loose Increase sand content to 80% LEAN CLAY with SAND (CL) Black (10YR 2/1), moist, 85% fines, 15% fine sand, low plasticity Increase sand content to 30% LEAN CLAY (CL) Greenish gray (10GY 5/1), moist, 95% fines, 5% fine sand, low plasticity Orange mottling Increase sand content to 30% Increase sand content to 30%	SAMPLES	O NAME (U	DESCRII SCS Symbol): color, moist, % by wt., plast., del	PTION nsity, structure, cementation, react. w/HC	CI, geo. inter.	RE	EMARKS
SANDY LEAN CLAY with GRAVEL (CL) Very dark gray (10YR 3/1), dry, 60% fines, 25% fine to medium sand, 15% medium gravel, low plasticity CLAYEY SAND with GRAVEL (SC) Very dark gray (10YR 3/1), calcium deposits, dry, 60% fine to medium sand, 25% low plasticity fines, 15% fine gravel, loose Increase sand content to 80% LEAN CLAY with SAND (CL) Black (10YR 2/1), moist, 85% fines, 15% fine sand, low plasticity Increase sand content to 30% LEAN CLAY (CL) Greenish gray (10GY 5/1), moist, 95% fines, 5% fine sand, low plasticity Orange mottling Increase sand content to 30% Increase sand content to 30%	Samp No. Samp Blow Fool	G g					
	2- 3- 3- 4- 5- 6- 7- 8- 9- 10- 11-	CLA Ven med loos In The LEA Bla plas	y dark gray (10YR 3/1), dry, dium sand, 15% medium gravitum sand, 15% medium gravitum sand, 25% low plasticities and content to 80% and CLAY with SAND (CL) ck (10YR 2/1), moist, 85% firsticity acrease sand content to 30% and CLAY (CL) eenish gray (10GY 5/1), moist plasticity or plasticity or plasticity or content gray (10GY 5/1), moist plasticity or content gray (10GY 5/1), mois	60% fines, 25% fine to evel, low plasticity (SC) fium deposits, dry, 60% fry fines, 15% fine gravel, fines, 15% fine sand, low 6 st, 95% fines, 5% fine sa	모		very in upper

Log of Boring No. GWS-9 (cont.) PROJECT: PARK STREET LANDING Alameda, California SAMPLES Blows/ Foot OVM Reading DESCRIPTION REMARKS NAME (USCS Symbol): color, moist, % by wt., plast., density, structure, cementation, react. w/HCl, geo, inter. LEAN CLAY (CL) (continued) CLAYEY SAND (SC) 15 Greenish gray (10Y 5/1) with orange mottling, moist, 60% fine sand, 40% low plasticity fines 16 Bottom of boring at 16 feet bgs 17 18 19 20 21 22 23 24 25 26 27 28 29 30 B-2 (11/92) Figure ---Project No. 2436.02

Geomatrix Consultants

PROJECT: PARK STREE Alameda, Cali	ET LANDING ifornia		ng No. GWS-10
BORING LOCATION: Along		ELEVATION AND DATUM: Gravel sidewalk	
		DATE STARTED: 4/24/95	DATE FINISHED: 4/24/95 - 1430 hrs
PRILLING CONTRACTOR: P		TOTAL DEPTH:	MEASURING POINT: Ground surface
ORILLING METHOD: Direct		DEPTH TO FIRST	COMPL. 24 HRS.
DRILLING EQUIPMENT: X		WATER	
SAMPLING METHOD: Envi	riro Core System	S. L. Anich RESPONSIBLE PROFESS	SIONAL: REG. NO.
HAMMER WEIGHT:	DROP:	A. L. Spencer	RG 5713
	DESCRIPTIO NAME (USCS Symbol): color, moist, % by wt., plast, density, :	ON structure, cementation, react. w/HCl, geo. inter.	REMARKS
(faet) Sample No. Sample Blows/ Foot PID Reading (ppm)	NAME (USCS Symbol): color, moist, 76 by W., place, Gardyn Surface Elevation		
1- 1- 2- 3- 3- 4- 5- 6- 8- 8- 9- 10- 11- 11- 12- 13-	CLAYEY SAND (SC) Very dark gray (10YR 3/1), moist, 7 plasticity fines, 5% fine to coarse state of the sand of the sand, low plasticity, soft Increase moisture LEAN CLAY (CL) Dark greenish gray (5G 4/1), mode brown organics, moist, 80-90% fire sand, trace fine gravel, low plasticity. Organics and orange mottling	fines, 30-40% fine to coarse derate amount yellow to nes, 10-20% fine to coarse	No recovery in upper 2 feet
]]]]]]	,		B-1 (11)
2436.02.022	Geomatrix Consultants	Project No. 2	2436.02 Figure —

PROJECT: PARK STREET LANDING Log of Boring No. GWS-10 (cont.) Alameda, California **SAMPLES** OVM Reading **DESCRIPTION** REMARKS NAME (USCS Symbol): color, moist, % by wt., plast., density, structure, cementation, react. w/HCl, geo. inter. LEAN CLAY (CL) (continued) **-1200** 15 POORLY GRADED SAND WITH CLAY (SP - SC) Gray (N5/), moist, 90% fine to medium sand, 10% low plasticity fines, loose 16 Bottom of boring at 16 feet bgs 17 18 19 20 21 22 23 24 25 26 27 28 29 30 B-2 (11/92) Project No. 2436.02 Figure ---**Geomatrix Consultants** 2436.02.023

PROJ	ECT:				ET LANDING Ilifornia	Log of B	Borin	g No. (GWS-11	
BOBI	NG I C				ng canal - southeast side	ELEVATION AND Gravel sidewalk				
			<u> </u>			DATE STARTED: 4/24/95		DATE FINISHED: 4/24/95 - 1530 hrs		
DRILLING CONTRACTOR: Precision Sampling 4/24/95 TOTAL DEPTH: 16 feet								MEASURIN Ground s	NG POINT:	
<u> </u>				NT: X		DEPTH TO F	TRST	COMPL.	24 HRS.	
						WATER LOGGED BY:		1		
					riro Core System DROP:	S. L. Anich RESPONSIBLE PI	ROFESSI	ONAL:	REG. NO.	
		MPL	HT:			A. L. Spencer			RG 5713	
DEPTH (feet)	Sample No.	_	ws/	PID Reading (ppm)	DESCRIPTION NAME (USCS Symbol): color, moist, % by wt., plast., density, structure, ce	mentation, react. w/HCl, ged	o. inter.	RE	EMARKS	
<u>a</u> =	San	San	용고	GP.	Surface Elevation:					
_		М			GRAVEL SIDEWALK				ery in upper	
1-		Ň					-	1 1/2 fee	t	
-		\Box			SANDY LEAN CLAY (CL)		-			
2-	-				Very dark gravish brown (10YR 3/2), moist	, 60% fines, 30%	, -			
-	-				fine to coarse sand, 10% subangular grave soft	n, low plasticity,				
3-					T					
-	1				Increase organic content, wood fragmen	ts				
4-	1	\bigvee					-			
5]	\triangle		1300			-	-		
							-	-		
6	-				TANK CLAN WHITE CAND (CL)	<u> </u>				
	-				LEAN CLAY with SAND (CL) Black (10YR 2/1) with tan mottling, moist, 8	35% fines, 15%	. -	1		
7	-	H		50	fine to coarse sand, trace fine to coarse gr medium hard	avel, low plasticit	ty, -			
	-	尸			median nara		-			
8	-				LEAN CLAY (CL)					
	1				Bluish gray (10B 6/1), moist, 90% fines, 10 coarse sand, low plasticity, firm	% medium to]		
9	1				coarse sariu, low plasticity, iiiiii					
1.0	1				Color change to pale olive with green an	d orange mottling	g .	_		
10]	П		50	V Oolor Grange to pare that		` .	4		
11								4		
''	4						-	1		
12	4				Increase sand content to 25%		-	-		
	4				▼			1		
13	4	H	{					1		
	4									
14				<u></u>	Geomatrix Consultants	Project	No. 2436	6.02	8-1 (11/9 Figure	
2436.0	2.024				Geomatrix Consultants	1, 13,350			L	

PROJECT: PARK STREET LANDING Log of Boring No. GWS-11 (cont.) Alameda, California OVM DESCRIPTION **REMARKS** NAME (USCS Symbol): color, moist, % by wt., plast., density, structure, cementation, react. w/HCl, geo. inter. SANDY LEAN CLAY (CL) 100 Greenish gray (10Y 5/1), moist, 60% fines, 40% fine to coarse sand, low plasticity, firm 15 CLAYEY SAND (SC) Dark bluish gray (10B 4/1), moist, 70% fine to coarse sand, 16 30% low plasticity fines, dense Bottom of boring at 16 feet bgs 17 18 19 20 21 22 23 24 25 26 27 28 29 30

2436.02.025 Geomatrix Consultants Project No. 2436.02 Figure ---

8-2 (11/92)

Alameda, California BORING LOCATION: Along canal - southeast side DRILLING CONTRACTOR: Precision Sampling DRILLING METHOD: Direct push DRILLING EQUIPMENT: XD-3	ELEVATION AI Gravel sidew DATE STARTE 4/24/95	/alk				
DRILLING CONTRACTOR: Precision Sampling DRILLING METHOD: Direct push DRILLING EQUIPMENT: XD-3	DATE STARTE 4/24/95		LOATE CIVIL			
DRILLING METHOD: Direct push DRILLING EQUIPMENT: XD-3			4/24/95 -	SHED: 1630 hrs		
DRILLING EQUIPMENT: XD-3	TOTAL DEPTH	{:	MEASURIN Ground s	NG POINT:		
	16 feet DEPTH TO	FIRST	COMPL.	24 HRS.		
	WATER LOGGED BY:		<u> </u>			
SAMPLING METHOD: Enviro Core System	S. L. Anich RESPONSIBL	E PROFESS	SIONAL:	REG. NO.		
HAMMER WEIGHT: DROP:	A. L. Spence		1	RG 5713		
THE SAMPLES DESCRIPTION NAME (USCS Symbol): color, molst, % by wt., plast, density, structure, cert Surface Elevation:	nentation, react. w/HC	I, geo. inter.	RI	EMARKS		
NAME (USCS Symbol): color, molst, % by wt. plast, density, structure, cerr						
1- 2- 2-			No recove 2 1/2 fee	very in upper et		
Dark gray (7.5YR 4/1), moist, 70% fine to complete low plasticity fines, 5% rounded and subangmedium density, glass fragments Increase in low plasticity fines to 30% White "chalky" mottling or inclusions	Increase in low plasticity fines to 30%					
WELL-GRADED SAND (SW) Light olive brown (2.5Y 5/3), moist, 95% fin 5% low plasticity fines, loose Color change to very dark gray (2.5Y 3/1 plasticity fines to 20%						
LEAN CLAY with SAND (CL) Olive (5Y 5/4) with green mottling, moist, 8 fine to medium sand, low plasticity, soft Increase sand content to 30% with orange		%	-			
CLAYEY SAND (SC) Olive (5Y 5/4) with green and orange mott	iling, very mo ty fines	ist,	-	B-1 (11/5		
14						

PROJECT: PARK STREET LANDING Log of Boring No. GWS-12 (cont.) Alameda, California SAMPLES OVM Reading DESCRIPTION REMARKS Blows/ Foot NAME (USCS Symbol): color, moist, % by wt., plast., density, structure, cementation, react. w/HCl, geo. inter. CLAYEY SAND (SC) (continued) Increase sand content to 80% and color change to greenish 15 gray (10GY 5/1) 16 Bottom of boring at 16 feet bgs 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 B-2 (11/92) Figure -Project No. 2436.02 **Geomatrix Consultants** 2436.02.027

PROJECT:	PARK S Alamed		ET LANDING lifornia	Log of Borin	g No. C	3WS-13
BORING L			g Blanding Ave., N side of driveway, next to bldg	ELEVATION AND DATUM: Vegetated area		
			Precision Sampling	DATE STARTED: 4/25/95	DATE FINIS 4/25/95 - 1	
				TOTAL DEPTH:	MEASURIN Ground su	G POINT:
DRILLING			•	16 feet DEPTH TO FIRST	COMPL.	24 HRS.
DRILLING				LOGGED BY:		<u> </u>
			viro Core System	S. L. Anich RESPONSIBLE PROFESS	IONAL:	REG. NO.
HAMMER '			DROP:	A. L. Spencer		RG 5713
	MPLES	PID Reading (ppm)	DESCRIPTION NAME (USCS Symbol): color, moist, % by wt., plast., density, structure, cen	nentation, react. w/HCl, geo. inter.	RE	MARKS
DEPT (feet) Sample No.	Sample Blows/ Foot	OF P	Surface Elevation:			
1- 1- 2- 3- 4- 5- 6- 7- 8- 9- 10- 11- 12- 13-		162 120 170 190 380	sand, 40% low plasticity fines, including 10 dense LEAN CLAY (CL) Olive gray (5Y 4/2), moist, 80% fines, 20%	asticity fines, lules (roots, black to medium sand, fine to coarse ATD hes, 5-10% fine to creasing clay content fine to coarse % silt, medium	Did not en petroleum however, readings measured recovery 2 1/2 feet	n-like odors; PID were d. No in upper
14		650		Braight No. 242	16.02	8-1 (11/92) Figure
2436.02.028			Geomatrix Consultants	Project No. 243	00.02	90.0

Log of Boring No. GWS-13 (cont.) PROJECT: PARK STREET LANDING Alameda, California **SAMPLES** OVM Reading DESCRIPTION REMARKS NAME (USCS Symbol): color, moist, % by wt., plast., density, structure, cementation, react. w/HCl, geo. inter. WELL-GRADED SAND with CLAY (SW-SC) Dark greenish gray (10GY 4/1), moist, 90% fine to coarse sand, 40% low plasticity fines, loose Color change to olive brown (2.5Y 4/4) 15 Bottom of boring at 16 feet bgs 16 17 18 _19 20 21 22 23 -24 25 26 27 28 29 30 B-2 (11/92) 31 Project No. 2436.02 Figure -**Geomatrix Consultants**

PROJECT: PARK		ET LANDING alifornia	Log of Borir	ng No. GWS-14
BORING LOCATION:	Alon	g Blanding Ave., south side of driveway	ELEVATION AND DATUM: Vegetated area	
		Precision Sampling	DATE STARTED: 4/25/95	DATE FINISHED: 4/25/95 - 930 hrs
DRILLING METHOD:			TOTAL DEPTH: 16 feet	MEASURING POINT: Ground surface
DRILLING EQUIPME			DEPTH TO FIRST	COMPL. 24 HRS.
			LOGGED BY:	
		viro Core System DROP:	S. L. Anich RESPONSIBLE PROFESS	SIONAL: REG. NO.
HAMMER WEIGHT: SAMPLES			A. L. Spencer	RG 5713
(feet) (ample No. No. Sample Sample Foot	PID Reading (ppm)	DESCRIPTION NAME (USCS Symbol): color, moist, % by wt., plast, density, structure, ce	mentation, react. w/HCl, geo. inter.	REMARKS
(feet) Sample No. Sample Blows/ Foot	Old (Surface Elevation:		
1- 1- 2- 3- 3- 4- 5- 6- 7- 8- 8- 9- 10- 11- 12-	160 271	CLAYEY SAND (SC) Reddish black (10R 2.5/1), moist, 60-70% sand, 30-40% low plasticity fines, loose Increased sand content to 80-85%, color (10YR 5/3) SANDY LEAN CLAY (CL) Light yellowish brown (2.5Y 6/4), moist, 60 to coarse sand, 10% fine gravel, low plastic Color change to pale olive (5Y 6/4)), incr CLAYEY SAND (SC) Greenish gray (5G 5/1) with orange mottlin organic pockets, moist, 60-70% fine to coal low plasticity fines, medium dense to dens LEAN CLAY with SAND (CL) Olive (5Y 5/3) with orange mottling and black gockets (some roots), moist, 80% fines (infine to medium sand, low plasticity, firm CLAYEY SAND (SC) Olive (5Y 5/6) with orange and black mottle 60-70% fine to coarse sand, 30-40% low processed in the coarse	change to brown % fines, 30% fine city, firm rease fines to 75% ag and black arse sand, 30-40% e ack organic cluding silt), 20%	Did not encounter petroleum-like odors; however, PID readings were measured. No recovery in upper 2 1/2 feet.
13		medium dense		4
14 111	25			B-1 (11/92
2438.02.030		Geomatrix Consultants	Project No. 240	36.02 Figure

PROJECT: PARK STREET LANDING

Log of Boring No. GWS-14 (cont.)

Sample No. Sample Blows/ Sample Foot Ovivi	DESCF NAME (USCS Symbol): color, moist, % by wt., plast., c	RIPTION density, structure, cementation, react. w/HCl, geo. Inter.	R	EMARKS
		70% fines 20% fine to	1	
	Dark greenish gray (5G 3/1), m coarse sand, low plasticity, de	noist, 70% tines, 30% line to		
5-	WELL-GRADED SAND with C	LAY (SW-SC)		
4 111 1	Olive (5Y 4/3), moist, 90% fine	to coarse sand, 10% low	1	
16-	plasticity fines, loose		1	
' "]	Bottom of boring at 16 feet bgs	' [-	1	
		-	-	•
17-		1.	4	
		1.	_	
18-		1.	_	
-				
19-		.	- 	
20-	•	.	1	
20			4	
7			4	
21			_	
			_	
22				
4				
23-			7	
4				
24-			1	
			4	
			4	
25			4	
1				
26				
		•		•
27		1		
4		İ	7	
28			1	
		·	+	
			4	
29			4	
7			4	
30-			_	
31				8-2 (1
	Geomatrix Consultants	Project No. 24	36.02	Figure —

PROJECT: PARK S' Alameda	TREET LANDIN a, California	IG	Log	of	Bor	ing	g No.	GWS-15	
BORING LOCATION:	North side of pro	ppertydriveway	ELEVATION Asphalt			M:	<u> </u>		
DRILLING CONTRACT	OR: Precision S	ampling	DATE STA 4/25/95				DATE FINISHED: 4/25/95 - 1200 hrs		
DRILLING METHOD: 'Direct push TOTAL DEPTH: 16 feet								NG POINT:	
DRILLING EQUIPMEN	<u></u>		DEPTH TO	0	FIRST		COMPL.	24 HRS.	
SAMPLING METHOD:	Enviro Core Sy	stem	LOGGED S. L. Ani		L		·		
HAMMER WEIGHT:	-	DROP:	RESPON A. L. Sp	SIBLE		SSIC	NAL:	REG. NO. RG 5713	
E SAMPLES	G	DESCRIPTION						· · · · · · · · · · · · · · · · · · ·	
(feet) Sample No. Sample Blows/ Foot	POR (USCS)	Symbol): color, moist, % by wt., plast, density, structure, cem Surface Elevation:	entation, react	. w/HCl,	geo. inter.	-	RI	EMARKS	
		Odinado Elovatori.				П			
							No reco 2 1/2 fe	very in upper et	
1-									
		· 							
3 -	GRAV								
		EY SAND (SC) ark grayish brown (10YR 3/2), moist,	70-80%	fine to	o				
4-	coarse	sand, 20-30% low plasticity fines, loc	ose			$ \cdot $			
	LEAN	CLAY with SAND (CL)				$ \cdot $			
5 - 8	Black ((10YR 2/1), some orange organic nod % fines (5-10% silt), 30-40% fine to c			147				
	plastic	ity, soft	uaise sai	ilu, iu	W	1			
6	250								
_]	CLAYE	EY SAND (SC)	on, mois	•	V				
7	75-85%	ellowish brown (10YR 4/4), moist to v % fine to coarse sand, 15-25% low pla			\int				
8-	50	o medium dense							
		Y LEAN CLAY (CL) 5Y 5/3), moist, 70% fines, 30% fine to	coarse	sand,		4			
9-	low pla	asticity, firm				-			
		reasing sand content to 20%				+			
10-	1 4	k organic nodules, greenish gray (5G	5/1) poc	kets,		\exists			
	▼ oran	ge mottling				1			
11	200								
			,			1			
12	900d								
	1-0	paging cand content to 20 40% color	chance t	^					
13	▼ yello	easing sand content to 30-40%, color wish brown (10YR 5/6)	criariye t	•					
14]	200					Ш		B-1 (11/92)	
2436 02 032	Geor	matrix Consultants		Projec	t No. 24	36.0	2	Figure	

PROJECT: PARK STREET LANDING Log of Boring No. GWS-15 (cont.) Alameda, California **SAMPLES** (feet)
Sample
No. OVM DESCRIPTION REMARKS Blows/ Foot NAME (USCS Symbol): color, moist, % by wt., plast., density, structure, cementation, react. w/HCl, geo. inter. SANDY LEAN CLAY (CL) (Continued) CLAYEY SAND (SC) Light olive brown (2.5Y 5/4) black organic nodules, green 15 470 mottling, moist, 60% fine to coarse sand, 40% low plasticity fines, soft to firm, 16 - Increase sand content to 70-80% Bottom of boring at 16 feet bgs 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 B-2 (11/92) Figure --Project No. 2436.02 **Geomatrix Consultants** 2436.02.033

			ET LANDING lifornia	Log of Boring No. GW				
BORING LOCA	TION:	Main	driveway	ELEVATION AND DATE Asphalt driveway	JM:			
	RILLING CONTRACTOR: Precision Sampling DATE STARTED: 4/25/95							
DRILLING MET	<u>·</u>				MEASURIN Ground su			
DRILLING EQU				21.5 feet DEPTH TO FIRST WATER		COMPL.	24 HRS.	
			iro Core System	LOGGED BY: S. L. Anich				
HAMMER WEIG			DROP:	RESPONSIBLE PROFI	ESSIC	NAL:	REG. NO	
				A. L. Spencer			, RG 37	
Sample C Sample Sample Sample C Sample	Blows/ M Foot	Readin (ppm)	DESCRIPTION NAME (USCS Symbol): color, moist, % by wt., plast, density, structur	re, cementation, react. w/HCl, geo. inter		RE	MARKS	
San San	용도	2	Surface Elevation:		+			
1-					1 1 1 1	No recov 2 1/2 fee	rery in upp t	
3- 4-		1000	GRAVEL CLAYEY SAND (SC) Black (7.5YR 2.5/1), moist, 70% fine to low plasticity fines, loose to medium der Increased sand content to 80%	- — — — — — — — — — — — — — — — — — — —				
5- 6- 7-		200	SANDY LEAN CLAY (CL) Dark greenish gray (5GY 4/1), moist, 60 fine to coarse sand, low plasticity, medical coarse sand, low plasticity, low plasticity, medical coarse sand, low plasticity, medical coarse sand, low plasticity, medical coarse sand, low plasticity, medical coarse sand, low plasticity, medical coarse sand, low plasticity, medical coarse sand, low plasticity, medical coarse sand, low plasticity, medical coarse sand, low plasticity, medical coarse sand, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plasticity, low plastic	0-70 % fines, 30-40% um hard				
8- 9-			Orange organic nodules					
10 -		14	LEAN CLAY with SAND (CL) Olive (5Y 5/4), with green and orange n 70-80% fines, 20-30% fine to coarse sa hard	nottling, moist, and, low plasticity,				
	1		WELL-GRADED SAND with CLAY (SW	V-SC)	7			
13 -		8	Greenish gray (5G 5/1), moist, 85-90% 10-15% low plasticity fines, loose to me	fine to coarse sand, edium dense				
4		8	Greenish gray (5G 5/1), moist, 85-90% 10-15% low plasticity fines, loose to me	fine to coarse sand, edium dense			B-1 Figure	

PROJECT: PARK STREET LANDING Log of Boring No. GWS-16 (cont.) Alameda, California SAMPLES OVM DESCRIPTION REMARKS Blows/ Foot NAME (USCS Symbol): color, moist, % by wt., plast., density, structure, cementation, react. w/HCl, geo. inter. WELL-GRADED SAND with CLAY (SW-SC) (Continued) Increase sand content to 90-95% 15 16 Color change to olive (5Y 4/3) 18 Orange mottling 19 20 21 Bottom of boring at 21.5 feet bgs 22 23 24 25 26 27 28 29 30 31 B-2 (11/92) Project No. 2436.02 Figure -**Geomatrix Consultants** 2436.02,035

	G	ettler	-Ry	an, Ir	nc.	Log of Boring	j MW−1			
PROJ	ECT:	Former C	hevron	Service	Station No. 20-6127	LOCATION: 2801-2337 Blanding Avenue, Alameda, CA				
GR PI	ROJEC	T NO.: 、	346498	.03		CASING ELEVATION: 10.62 Ft. (MS	SL)			
DATE	DATE STARTED: 12/29/00					WL (ft. bgs): 17 DATE: 12/29/00	TIME: 16:50			
DATE	FINI	SHED: 12	2/29/00)		WL (ft. bgs): 8 DATE: 12/30/00	TIME: 11:00			
DRIL	LING N	METHOD:	8 in. H	ollow Ste	em Auger	TOTAL DEPTH: 19.5 feet				
DRIL	LING (COMPANY:	Greg	g Drilling		GEOLOGIST: Andrew Smith				
DEPTH (feet)	PID (ppm)	SAMPLE NUMBER	SAMPLE INT. GRAPHIC LOG	SOIL CLASS	GEC	DLOGIC DESCRIPTION	WELL DIAGRAM			
			77		Native material.		PVG PVG			
3-	57	MW−1−5		CL	CLAY WITH SAND (CL moist, soft; 85% clay, Trace of coarse grav Concrete fragments a	el.				
9-	98	MW-1-10		SC	CLAYEY SAND (SC) - loose; 75% fine to med	dark brown (7.5YR 3/2), moist, very dium sand, 15% clay, 10% silt.	VC (0.020 inch) ————————————————————————————————————			
12-				SP	moist, very loose; 959	ID (SP) - blueish gray (Gley 5B6/1), % fine to medium sand, 5% silt. ck (7.5YR, N 2/0) at 14.5 feet.				
15-	118	MW-1-15				eish gray (Gley 5B6/1) at 15 feet.				
21-	109	MW-1-19			Bottom of boring at	19.5 feet bgs.				

JOB NUMBER: 346498.03

Page 1 of 1

PAGE 1 OF



REMARKS

Conestoga-Rovers & Associates 2000 Opportunity Drive, Suite 110 Roseville, CA Telephone: (916) 677-3407

Fax: (916) 677-3687

CLIENT NAME Chevron Environmental Management Co. **JOB/SITE NAME** Former Signal Oil Bulk Plant 20-6127 2301-2311 Blanding Avenue, Alameda, CA **LOCATION** PROJECT NUMBER 631916 Gregg Drilling **DRILLER** Direct Push / Hollow-Stem Auger DRILLING METHOD BORING DIAMETER E. Namba **LOGGED BY** REVIEWED BY G. Barclay

Cleared to 8 fbg with air-knife

BORING/WELL NAME MW-2

DRILLING STARTED 18-Jun-09

DRILLING COMPLETED 19-Jun-09

WELL DEVELOPMENT DATE (YIELD) 30-Jun-09

GROUND SURFACE ELEVATION 10.87 ft above msl

TOP OF CASING ELEVATION 10.63 ft above msl

SCREENED INTERVAL 10.5 to 15.5 fbg

DEPTH TO WATER (First Encountered) 11.5 fbg (18-Jun-09)

DEPTH TO WATER (Static) 4.0 fbg (19-Jun-09)

CONTACT DEPTH (fbg) GRAPHIC LOG PID (ppm) BLOW EXTENT U.S.C.S. DEPTH (fbg) SAMPLE LITHOLOGIC DESCRIPTION WELL DIAGRAM Asphalt 0.5 Silty SAND with gravel: Brown; dry 0.0 SM 4.0 Portland Type 189 MW-2- 4.5 Sandy SILT: Grey; dry ML I/II 5.0 Silty SAND: Greyish green; dry SM 2" diam.. Schedule 40 7.0 MW-2- 7.5 0.0 Sandy SILT with clay: Greyish green with brown; dry; moderate plasticity MW-2- 8.5 0.0 Grey staining observed Bentonite Seal ML Less grey staining observed 0.0 Monterey Sand #2/12 ☑ 11.5 WELL LOG (PID) C;\DOCUMENTS AND SETTINGS\NALLEN\\DESKTOP\631916-GINT.GPJ DEFAULT.GDT 8/26/09 <u>Silty SAND with clay</u>: Grey; wet; fine grain; grey staining observed; decreasing clay content with depth 0.0 ■ 2"-diam., 0.0 MW-2- 13 0.020" Slotted SM Schedule 40 **PVC** 0.0 MW-2- 15.5 16.0 Bottom of Boring @ 16 fbg

PAGE 1 OF



Conestoga-Rovers & Associates 2000 Opportunity Drive, Suite 110 Roseville, CA Telephone: (916) 677-3407

Fax: (916) 677-3687

CLIENT NAME Chevron Environmental Management Co. **JOB/SITE NAME** Former Signal Oil Bulk Plant 20-6127 2301-2311 Blanding Avenue, Alameda, CA **LOCATION** PROJECT NUMBER 631916 **DRILLER** Gregg Drilling **DRILLING METHOD** Direct Push / Hollow-Stem Auger BORING DIAMETER **LOGGED BY** E. Namba REVIEWED BY G. Barclay

BORING/WELL NAME MW-3

DRILLING STARTED 18-Jun-09

DRILLING COMPLETED 19-Jun-09

WELL DEVELOPMENT DATE (YIELD) 30-Jun-09

GROUND SURFACE ELEVATION 11.08 ft above msl

TOP OF CASING ELEVATION 10.72 ft above msl

SCREENED INTERVAL 13.5 to 18.5 fbg

DEPTH TO WATER (First Encountered) 8.5 fbg (18-Jun-09)

DEPTH TO WATER (Static) 4.8 fbg (19-Jun-09)

REMARKS Cleared to 8 fbg with air-knife CONTACT DEPTH (fbg) GRAPHIC LOG PID (ppm) BLOW U.S.C.S. EXTENT DEPTH (fbg) SAMPLE LITHOLOGIC DESCRIPTION WELL DIAGRAM Asphalt 0.5 Silty SAND: Dark brown; dry SM 206 MW-3-4 ¥ Portland Type 6.0 1/11 MW-3- 6 141 Sandy SILT: Grayish green; dry; moderate plasticity Clayey SILT Moist; moderate to high plasticity 2" diam., ∇ Schedule 40 MW-3- 8.5 12 Wet at 8.5 fbg **PVC** MLWELL LOG (PID) C:DOCUMENTS AND SETTINGS\NALLEN\DESKTOP\631916-GINT.GPJ DEFAULT.GDT 8/26/09 Bentonite Seal 0.0 Monterey 14.0 Sand #2/12 Silty SAND: Grayish green; wet 15 0.0 MW-3- 15.5 2"-diam., SM 0.020" Slotted Schedule 40 Decreasing silt content with depth. Brown at 17 fbg PVC. 18.5 MW-3- 18 0.0 Bottom of Boring @ 18.5 fbg

6.8 fbg (19-Jun-09)

PAGE 1 OF



REMARKS

Conestoga-Rovers & Associates 2000 Opportunity Drive, Suite 110 Roseville, CA

Telephone: (916) 677-3407 Fax: (916) 677-3687

CLIENT NAME Chevron Environmental Management Co. **JOB/SITE NAME** Former Signal Oil Bulk Plant 20-6127 2301-2311 Blanding Avenue, Alameda, CA **LOCATION** PROJECT NUMBER 631916 **DRILLER** Gregg Drilling Direct Push / Hollow-Stem Auger DRILLING METHOD BORING DIAMETER E. Namba **LOGGED BY** REVIEWED BY G. Barclay

BORING/WELL NAME MW-4 **DRILLING STARTED** 18-Jun-09 DRILLING COMPLETED 19-Jun-09 WELL DEVELOPMENT DATE (YIELD) 30-Jun-09 **GROUND SURFACE ELEVATION** 11.65 ft above msl TOP OF CASING ELEVATION 11.40 ft above msl SCREENED INTERVAL 15.5 to 20.5 fbg DEPTH TO WATER (First Encountered) 17.0 fbg (18-Jun-09)

DEPTH TO WATER (Static)

Cleared to 8 fbg with air-knife CONTACT DEPTH (fbg) GRAPHIC LOG PID (ppm) BLOW EXTENT U.S.C.S. DEPTH (fbg) SAMPLE LITHOLOGIC DESCRIPTION WELL DIAGRAM Asphalt 0.5 **Gravelly SILT:** Brown; dry; low to moderate plasticity; 0.0 MW-4- 5 Sandy SILT: Dark brown; damp Portland Type ₹ 1/11 ML 0.0 Clayey SILT with sand: Light green to brown; moderate 2" diam., Slight grey staining Schedule 40 PVC 0.0 MW-4- 10 Light brown with some light green; iron oxide staining WELL LOG (PID) C;\DOCUMENTS AND SETTINGS\NALLEN\\DESKTOP\631916-GINT.GPJ DEFAULT.GDT 8/26/09 Bentonite Seal 14.0 Silty SAND: Light green to light brown; damp; fine grain MW-4- 15 0.0 Monterey Sand #2/12 ∇ SM Wet; decreasing silt content with depth 2"-diam., 0.020" Slotted Schedule 40 0.0 MW-4- 19.5 Greyish brown PVC 20.5 Bottom of Boring @ 20.5 fbg



REMARKS

Conestoga-Rovers & Associates 2000 Opportunity Drive, Suite 110 Roseville, CA Telephone: (916) 677-3407

Fax: (916) 677-3687

CLIENT NAME Chevron Environmental Management Co. **JOB/SITE NAME** Former Signal Oil Bulk Plant 20-6127 2301-2311 Blanding Avenue, Alameda, CA **LOCATION** PROJECT NUMBER 631916 **DRILLER** Gregg Drilling Direct Push / Hollow-Stem Auger DRILLING METHOD BORING DIAMETER **LOGGED BY** E. Namba REVIEWED BY G. Barclay

Cleared to 8 fbg with air-knife

BORING/WELL NAME MW-5

DRILLING STARTED 23-Jun-09

DRILLING COMPLETED 23-Jun-09

WELL DEVELOPMENT DATE (YIELD) 30-Jun-09

GROUND SURFACE ELEVATION 11.01 ft above msl

TOP OF CASING ELEVATION 10.50 ft above msl

SCREENED INTERVAL 13 to 18 fbg

DEPTH TO WATER (First Encountered) 14.0 fbg (18-Jun-09)

DEPTH TO WATER (Static) 5.9 fbg (23-Jun-09)


CONTACT DEPTH (fbg) GRAPHIC LOG PID (ppm) BLOW EXTENT U.S.C.S. DEPTH (fbg) SAMPLE LITHOLOGIC DESCRIPTION WELL DIAGRAM Asphalt 0.5 FILL: Silty Gravel; coarse; dark brown; dry; bricks and Portland Type ▼ I/II 7.0 MW-5- 7 404 Sandy CLAY: Greenish grey; dry; moderate to high plasticity; fine grain 2" diam., Schedule 40 **PVC** CL MW-5- 10.5 78.1 Bentonite Seal WELL LOG (PID) C:\DocumenTS AND SETTINGS\NALLEN\DESKTOP\\631916-GINT\GPJ DEFAULT\GDT 8/26/09 98.4 Monterey ∇ 14.0 Sand #2/12 12.8 MW-5- 14 Silty SAND: Greenish grey; wet 2"-diam., SM 0.020" Slotted Schedule 40 **PVC** Decreasing silt content with depth 18.0 3.4 MW-5- 17.5 Bottom of Boring @ 18 fbg PAGE 1 OF



Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, California Telephone: 916-889-8900

Fax: 916-889-8999

CLIENT NAME Chevron Environmental Management Co. **BORING/WELL NAME** MW-1RA 04-Aug-10 **JOB/SITE NAME** Former Signal Oil Bulk Plant (Chevron 20-6127) **DRILLING STARTED** DRILLING COMPLETED 04-Aug-10 2301-2311 Blanding Avenue, Alameda, CA **LOCATION** WELL DEVELOPMENT DATE (YIELD) NA **PROJECT NUMBER** 631916 **DRILLER** Penecore **GROUND SURFACE ELEVATION** 13.68 ft above msl 13.02 ft above msl **DRILLING METHOD** Hollow-stem auger TOP OF CASING ELEVATION 8 to 13 fbg **BORING DIAMETER SCREENED INTERVALS LOGGED BY** B. Yifru **DEPTH TO WATER (First Encountered)** 8.0 fbg (04-Aug-10) **REVIEWED BY** G. Barclay **DEPTH TO WATER (Static)** NA **REMARKS** Cleared to 8 fbg with Air Knife





CLIENT NAME

JOB/SITE NAME

Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, California Telephone: 916-889-8900 Fax: 916-889-8999

Chevron Environmental Management Co. Former Signal Oil Bulk Plant (Chevron 20-6127)

2301-2311 Blanding Avenue, Alameda, CA **LOCATION** PROJECT NUMBER 631916

DRILLER Penecore

DRILLING METHOD Hollow-stem auger **BORING DIAMETER**

LOGGED BY B. Yifru

REVIEWED BY G. Barclay **BORING/WELL NAME** MW-1RB 04-Aug-10 **DRILLING STARTED** DRILLING COMPLETED 04-Aug-10


WELL DEVELOPMENT DATE (YIELD) NA

13.65 ft above msl **GROUND SURFACE ELEVATION** 13.21 ft above msl TOP OF CASING ELEVATION

16.5 to 20 fbg **SCREENED INTERVALS**

DEPTH TO WATER (First Encountered) 8.0 fbg (04-Aug-10) **DEPTH TO WATER (Static)** NA

REMARKS Cleared to 8 fbg with Air Knife; re-installed well, previously MW-1






Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, California Telephone: 916-889-8900

Fax: 916-889-8999

CLIENT NAME Chevron Environmental Management Co. **BORING/WELL NAME** MW-6 04-Aug-10 **JOB/SITE NAME** Former Signal Oil Bulk Plant (Chevron 20-6127) **DRILLING STARTED** DRILLING COMPLETED 04-Aug-10 2301-2311 Blanding Avenue, Alameda, CA **LOCATION** WELL DEVELOPMENT DATE (YIELD) NA PROJECT NUMBER 631916 **DRILLER** Penecore **GROUND SURFACE ELEVATION** 13.21 ft above msl 12.98 ft above msl **DRILLING METHOD** Hollow-stem auger TOP OF CASING ELEVATION 16.5 to 20 fbg **BORING DIAMETER SCREENED INTERVALS LOGGED BY** B. Yifru **DEPTH TO WATER (First Encountered)** 8.0 fbg (04-Aug-10) **REVIEWED BY** G. Barclay **DEPTH TO WATER (Static)** NA **REMARKS** Cleared to 8 fbg with Air Knife





Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900 Fax: 916-889-8999

CLIENT NAME	Chevron Environmental Management Co.	BORING/WELL NAME	VP-1		
JOB/SITE NAME	Former Signal Oil Bulk Plant	DRILLING STARTED	09-Jul-08		
OCATION	2301-2311 Blanding Avenue, Alameda, CA	DRILLING COMPLETED	09-Jul-08		
PROJECT NUMBER	631916 (20-6127)	WELL DEVELOPMENT DA	TE (YIELD)	NA	
DRILLER	Woodward Drilling Co. Inc.	GROUND SURFACE ELEV	ATION _	NA	
ORILLING METHOD	Hand-Auger/Airknife	TOP OF CASING ELEVATION	ON	NA	
BORING DIAMETER	3.25 inches	SCREENED INTERVALS		3.75 to 4.25 fbg	
OGGED BY	C. Benedict	DEPTH TO WATER (First E	ncountered) NA	$\overline{\Sigma}$
REVIEWED BY	J. Kiernan, PE# C68498	DEPTH TO WATER (Static)	1	NA	
		,			

	REMAR	KS									
	PID (ppm)	BLOW	SAMPLE ID	EXTENT	DEPTH (fbg)	U.S.C.S.	GRAPHIC LOG	LITHOLOGIC DESCRIPTION	CONTACT DEPTH (fbg)	WEI	LL DIAGRAM
WELL LOG (PID) \\RAC-S1\SHARED\CHEVRON\6319-\631916~1\632941~1\BORING~1\20-6127 BORING LOGS.GPJ DEFAULT.GDT 7/9/09			VP-1-3			SM GM		Silty SAND with gravel Brown; dry; 45% sand, 25% silt, 15% clay, 15% coarse gravel; low plasticity; 1/2-3/4 inch subangular pebbles. Silty GRAVEL with sand Brown; dry; 45% gravel, 30% sand, 15% silt, 10% clay; low plasticity. Clayey GRAVEL with sand Brown; dry; 60% gravel, 20% clay, 10% silt, 10% sand; low plasticity.	3.0		 ✓ Concrete ✓ Portland Type I/II ✓ 1/4"-inner diam. Nylaflow® tubing ✓ Bentonite Seal ✓ Monterey Sand #3 ✓ 1"-diam., 0.020" Slotted Schedule 40 PVC Bottom of Boring @ 4.5 fbg



Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900 Fax: 916-889-8999

CLIENT NAME Chevron Environmental Management Co. **BORING/WELL NAME JOB/SITE NAME** Former Signal Oil Bulk Plant **DRILLING STARTED** 2301-2311 Blanding Avenue, Alameda, CA **LOCATION PROJECT NUMBER** 631916 (20-6127) **DRILLER** Woodward Drilling Co. Inc. **DRILLING METHOD** Hand-Auger/Airknife TOP OF CASING ELEVATION **BORING DIAMETER** 3.25 inches **SCREENED INTERVALS LOGGED BY** C. Benedict **REVIEWED BY** J. Kiernan, PE# C68498 **DEPTH TO WATER (Static)**

BORING/WELL NAME VP-2

DRILLING STARTED 09-Jul-08

DRILLING COMPLETED 09-Jul-08

WELL DEVELOPMENT DATE (YIELD) NA

GROUND SURFACE ELEVATION NA

TOP OF CASING ELEVATION NA

SCREENED INTERVALS 4.25 to 4.75 fbg

DEPTH TO WATER (First Encountered) NA

DEPTH TO WATER (Static) NA

REMARKS CONTACT DEPTH (fbg) SAMPLE ID GRAPHIC LOG PID (ppm) BLOW EXTENT U.S.C.S. DEPTH (fbg) LITHOLOGIC DESCRIPTION WELL DIAGRAM Asphalt Concrete 0.5 Silty SAND: Brown; dry; 45% sand, 35% silt, 20% clay; low plasticity. Portland Type SM 1/4"-inner diam. Nylaflow® WELL LOG (PID) \\RAC-S1\SHARED\CHEVRON\6319-\631916~1\632941~1\BORING~1\20-6127 BORING LOGS.GPJ DEFAULT.GDT 7/9/09 2.0 tubing CLAY with sand :Brown; dry; 45% clay, 30% silt, 25% sand; medium plasticity. ■ Bentonite Seal CL VP-2- 3 4.0 Silty SAND: Brown; moist; 55% sand, 30% silt, 15% Monterey clay; low plasticity. Sand #3 SM 1"-diam.. 649 VP-2-5 0.020" Slotted Schedule 40 5.0 5 Bottom of Boring @ 5 fbg



REMARKS

Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900 Fax: 916-889-8999

CLIENT NAME Chevron Environmental Management Co. **BORING/WELL NAME** VP-3 14-Jul-08 **JOB/SITE NAME** Former Signal Oil Bulk Plant **DRILLING STARTED** DRILLING COMPLETED 14-Jul-08 2301-2311 Blanding Avenue, Alameda, CA **LOCATION PROJECT NUMBER** 631916 (20-6127) WELL DEVELOPMENT DATE (YIELD) NA **DRILLER** Woodward Drilling Co. Inc. **GROUND SURFACE ELEVATION** NA NA **DRILLING METHOD** Hand-Auger/Airknife TOP OF CASING ELEVATION 5.25 to 5.75 fbg **BORING DIAMETER** 3.25 inches **SCREENED INTERVALS** LOGGED BY **DEPTH TO WATER (First Encountered)** B. Campbell NA **REVIEWED BY** J. Kiernan, PE# C68498 **DEPTH TO WATER (Static)** NA


CONTACT DEPTH (fbg) GRAPHIC LOG PID (ppm) BLOW EXTENT U.S.C.S. DEPTH (fbg) SAMPLE LITHOLOGIC DESCRIPTION WELL DIAGRAM Asphalt Concrete 0.5 GRAVEL with sand: Brown; dry; 60% gravel, 30% sand, 5% clay, 5% silt; low plasticity. Portland Type GW 1/4"-inner diam. Nylaflow® WELL LOG (PID) \\RAG-S1\SHARED\CHEVRON\6319-\631916~1\632941~1\BOR\NG~1\20-6127 BOR\NG LOGS.GPJ DEFAULT.GDT 7/9/09 2.0 tubing Silty SAND with gravel Dark brown; moist; 30% sand, 30% silt, 30% gravel,10% clay; low-medium plasticity. 1.5 VP-3- 2.5 Bentonite Seal SP 5.0 VP-3- 5 4.5 Silty SAND with clay Dark brown; moist; 40% sand, Monterey 35% silt, 25% clay; medium plasticity. SM Sand #3 5.5 1"-diam.. **CLAY:** Grey; moist; 55% clay, 35% silt, 25% clay; medium plasticity. 0.020" Slotted CL Schedule 40 6.0 **PVC** Bottom of Boring @ 6 fbg



Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900

Fax: 916-889-8999


CLIENT NAME Chevron Environmental Management Co. **BORING/WELL NAME** VP-4 14-Jul-08 **JOB/SITE NAME** Former Signal Oil Bulk Plant **DRILLING STARTED** DRILLING COMPLETED 14-Jul-08 2301-2311 Blanding Avenue, Alameda, CA **LOCATION** WELL DEVELOPMENT DATE (YIELD) NA **PROJECT NUMBER** 631916 (20-6127) NA **DRILLER** Woodward Drilling Co. Inc. **GROUND SURFACE ELEVATION** NA **DRILLING METHOD** Hand-Auger/Airknife TOP OF CASING ELEVATION 5.25 to 5.75 fbg **BORING DIAMETER** 3.25 inches **SCREENED INTERVALS** LOGGED BY DEPTH TO WATER (First Encountered) B. Campbell NA **REVIEWED BY** J. Kiernan, PE# C68498 **DEPTH TO WATER (Static)** NA





Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900 Fax: 916-889-8999

CLIENT NAME	Chevron Environmental Management Co.	BORING/WELL NAMEVP-5		
JOB/SITE NAME	Former Signal Oil Bulk Plant	DRILLING STARTED14-Jul-08		
LOCATION	2301-2311 Blanding Avenue, Alameda, CA	DRILLING COMPLETED 14-Jul-08		
PROJECT NUMBER	631916 (20-6127)	WELL DEVELOPMENT DATE (YIELD)	NA	
DRILLER	Woodward Drilling Co. Inc.	_ GROUND SURFACE ELEVATION _	NA	
DRILLING METHOD	Hand-Auger/Airknife	_ TOP OF CASING ELEVATION _	NA	
BORING DIAMETER	3.25 inches	SCREENED INTERVALS	5.25 to 5.75 fbg	
LOGGED BY	B. Campbell	DEPTH TO WATER (First Encountered	d) NA	Ž
REVIEWED BY	J. Kiernan, PE# C68498	DEPTH TO WATER (Static)	NA	j
REMARKS				






Conestoga Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900

Fax: 916-889-8999

CLIENT NAME	Chevron Environmental Management Co.	BORING/WELL NAME	VP-6		
JOB/SITE NAME	Former Signal Oil Bulk Plant	DRILLING STARTED	09-Jul-08		
LOCATION	2301-2311 Blanding Avenue, Alameda, CA	DRILLING COMPLETED	09-Jul-08		
PROJECT NUMBER	631916 (20-6127)	WELL DEVELOPMENT DAT	TE (YIELD)_	NA	
DRILLER	Woodward Drilling Co. Inc.	GROUND SURFACE ELEVA	ATION _	NA	
DRILLING METHOD	Hand-Auger/Airknife	TOP OF CASING ELEVATION	ON _	NA	
BORING DIAMETER	3.25 inches	SCREENED INTERVALS		5.25 to 5.75 fbg	
LOGGED BY	C. Benedict	DEPTH TO WATER (First E	ncountered) NA	Ž
REVIEWED BY	J. Kiernan, PE# C68498	DEPTH TO WATER (Static)		NA	
	·	` ,			_





Conestoga-Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900

Fax: 916-889-8999

CLIENT NAME Chevron Environmental Management Co. **BORING/WELL NAME** JOB/SITE NAME Former Signal Oil Bulk Plant (Chevron 20-6127) **DRILLING STARTED** 27-Sep-12 DRILLING COMPLETED 28-Sep-12 2301-2311 Blanding Avenue, Alameda, CA **LOCATION PROJECT NUMBER** 631916 WELL DEVELOPMENT DATE (YIELD) NA **DRILLER** Vapor Tech Services **GROUND SURFACE ELEVATION** 13.43 ft above msl DRILLING METHOD Hollow-stem auger TOP OF CASING ELEVATION 13.23 ft above msl BORING DIAMETER SCREENED INTERVAL 16.5 to 20 fbg W. Martinez DEPTH TO WATER (First Encountered) 17.0 fbg (28-Sep-12) LOGGED BY REVIEWED BY 7.6 fbg (02-Oct-12) Greg Barclay, P.G. 6260 **DEPTH TO WATER (Static) REMARKS** Cleared to 8 fbg with air knife, hollow stem auger to total depth, Perched groundwater encountered at 8fbg

CONTACT DEPTH (fbg) GRAPHIC LOG PID (ppm) BLOW U.S.C.S. EXTENT DEPTH (fbg) SAMPLE LITHOLOGIC DESCRIPTION WELL DIAGRAM Grass 0.5 FILL: concrete debris, trace mica; dusky red; moist. 5.0 SILT with sand: soft, fine sand, trace mica; greenish gray; moist; low plasticity. 47.9 MH Portland Type Ţ 1/11 @ 8 fbg dark greenish gray; wet (perched water); low 9.0 Sandy CLAY: stiff, fine sand, grades to more silt with WELL LOG (PID) 1:\PROJECT FILES\6-CHAR\63---\6319-\631916\631916-GINT\631916-GINT\631916-GINT\61 sand; dark greenish gray; moist; medium plasticity. CH 12.0 SILT with sand: stiff, fine sand; gray; moist; medium MH 13.0 plasticity. **<u>Silty SAND:</u>** medium dense, fine sand; pale green; moist; low plasticity. Bentonite Seal Monterey SM Sand #2/12 ∇ @ 17 fbg: loose; greenish gray; wet. 1"-diam., 0.020" Slotted Schedule 40 20.0 20 PVC Bottom of Boring @ 20 fbq PAGE 1 OF



REMARKS

Conestoga-Rovers & Associates 10969 Trade Center Drive, Suite 107 Rancho Cordova, CA Telephone: 916-889-8900

Fax: 916-889-8999

CLIENT NAME Chevron Environmental Management Co. **BORING/WELL NAME** JOB/SITE NAME Former Signal Oil Bulk Plant (Chevron 20-6127) **DRILLING STARTED** 2301-2311 Blanding Avenue, Alameda, CA LOCATION PROJECT NUMBER 631916 **DRILLER** Vapor Tech Services DRILLING METHOD Hollow-stem auger BORING DIAMETER _ SCREENED INTERVAL **LOGGED BY** W. Martinez REVIEWED BY Greg Barclay, P.G. 6260

BORING/WELL NAME P-2

DRILLING STARTED 27-Sep-12

DRILLING COMPLETED 28-Sep-12

WELL DEVELOPMENT DATE (YIELD) NA

GROUND SURFACE ELEVATION 13.82 ft above msl

TOP OF CASING ELEVATION 13.51 ft above msl

SCREENED INTERVAL 7 to 12 fbg

DEPTH TO WATER (First Encountered) 8.6 fbg (28-Sep-12)

Cleared to 8 fbg with air knife, hollow stem auger to total depth

DEPTH TO WATER (I list Encountered) 0.0 lbg (20 0cp 12)

■ 8.5 fbg (02-Oct-12)

■ 8.5 fbg (02-Oct-12)

PID (ppm) BLOW COUNTS SAMPLE ID EXTENT DEPTH (fbg) U.S.C.S. GRAPHIC LOG CONTACT DEPTH (fbg) MARCT DEPTH MARCT DEPTH MA	IAGRAM
	IAGRAW
Silty SAND: soft, fine sand with increasing clay; greenish gray; moist; medium plasticity. SM 13.0	Portland Type //II Bentonite Seal //onterey Sand #2/12 "-diam., 0.020" Slotted Schedule 40 PVC Bentonite Seal ottom of oring @ 13 g

Appendix B

Groundwater Monitoring and Sampling Data Tables



TABLE 1 Page 1 of 7

					н	YDROCARBO	VS		1	PRIMARY VOC	es	
Location	Date	тос	DTW	GWE	трн-дво	TPH-DRO w/ Si Gel	TPH-GRO	В	T	E	X	MTBE by SW8260
	Units	ft	ft	ft-amsl	μg/L	µg∕L	μg/L	μg/L	μg/L	µg∕L	μg/L	μ <i>g</i> /L
MW-1 MW-1	07/21/2010 10/22/2010 ¹	13.49 13.49	9.47	4.02	440	- -	65 J -	<0.5 -	<0.5 -	<0.5 -	<0.5 -	<0.5
MW-1RA	10/28/2010	13.02	9.23	3.79	-	4,000	6,400	830	22	65	20	-
MW-1RA	01/14/2011	13.02	7.20	5.82	-	1,500	790	160	2	1	1	-
MW-1RA	04/19/2011	13.02	7.42	5.60	-	3,000	3,800	600	9	18	9	-
MW-1RA	06/30/2011	13.02	7.51	5.51	-	3,700	6,800	780	13	36	13	-
MW-1RA	10/14/2011	13.02	7.96	5.06	6,900	360	6,800	1,300	19	51	14	-
MW-1RA	01/18/2012	13.02	7.34	5.68	4,300	1,400	6,400	1,300	17	38	12	-
MW-1RA	04/19/2012	13.02	5.23	7.79	3,700	400	3,100	120	<5	<5	<5	-
MW-1RA	07/23/2012	13.02	7.92	5.10	6,000	1,000	-	-	-	-	-	-
MW-1RA	07/27/20124	13.02	8.50	4.52	-	-	4,800	640	9	20	7	-
MW-1RA	01/19/2013	13.02	7.30	5.72	3,000	270	1,500	180	<5	<5	<5	-
MW-1RA	07/15/2013	13.02	8.09	4.93	4,200	630	3,700	430	8	5	2	-
MW-1RA	01/09/2014	13.02	7.05	5.97	3,300	150	910	130	2	3	4	-
MW-1RA	07/25/2014	13.02	8.04	4.98	2,500	390	1,100	17	<0.5	<0.5	<0.5	-
MW-1RB	10/28/2010	13.21	9.00	4.21	-	1,600	650	3	<0.5	0.8	<0.5	-
MW-1RB	01/14/2011	13.21	10.97	2.24	-	960	150	1	<0.5	<0.5	<0.5	-
MW-1RB	04/19/2011	13.21	12.11	1.10	-	1,200	190	6	<0.5	<0.5	<0.5	-
MW-1RB	06/30/2011	13.21	11.86	1.35	-	1,900	310	9	<0.5	<0.5	<0.5	-
MW-1RB	10/14/2011	13.21	12.14	1.07	4,000	57	300	15	<0.5	<0.5	<0.5	-
MW-1RB	01/18/2012	13.21	14.71	-1.50	2,400	260	340	11	<0.5	< 0.5	<0.5	-

TABLE 1 Page 2 of 7

					Н	YDROCARBO	NS		1	PRIMARY VOC	es .	
Location	Date	TOC	DTW	GWE	TPH-DRO	TPH-DRO w/ Si Gel	TPH-GRO	В	T	E	X	MTBE by SW8260
	Units	ft	ft	ft-amsl	µg∕L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L
MW-1RB MW-1RB	04/19/2012 07/23/2012	13.21 13.21	8.33 8.96	4.88 4.25	2,800 2,700	53 <50	180	1	<0.5	<0.5 -	<0.5 -	-
MW-1RB	07/27/20124	13.21	8.45	4.76	-	-	990	89	1	0.8	0.7	_
MW-1RB	01/19/2013	13.21	8.65	4.56	2,000	62	200	2	<0.5	<0.5	<0.5	_
MW-1RB	07/15/2013	13.21	8.18	5.03	2,000	<50	230	<0.5	<0.5	<0.5	<0.5	_
MW-1RB	01/09/2014	13.21	7.78	5.43	1,400	<50	150	<0.5	<0.5	<0.5	<0.5	_
MW-1RB	07/25/2014	13.21	9.96	3.25	2,300	57	270	1	<0.5	<0.5	<0.5	_
MW-2	07/21/2010	10.63	4.12	6.51	65 J	-	<50	<0.5	<0.5	<0.5	<0.5	-
MW-2	10/22/2010	10.63	4.31	6.32	-	58	<50	<0.5	<0.5	<0.5	<0.5	-
MW-2	$10/28/2010^2$	10.63	3.65	6.98	-	-	-	-	-	-	-	-
MW-2	01/14/2011	10.63	3.12	7.51	-	68	<50	<0.5	<0.5	<0.5	<0.5	-
MW-2	04/19/2011	10.63	3.51	7.12	-	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-2	06/30/2011	10.63	3.74	6.89	-	120	<50	<0.5	<0.5	<0.5	<0.5	-
MW-2	10/14/2011	10.63	3.52	7.11	160	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-2	01/18/2012	10.63	3.85	6.78	140	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-2	04/19/2012	10.63	3.16	7.47	<50	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-2	07/23/2012 ³	10.63	-	-	-	-	-	-	-	-	-	-
MW-2	07/27/2012	10.63	3.40	7.23	-	-	<50	<0.5	<0.5	<0.5	<0.5	-
MW-2	01/19/2013	10.63	3.45	7.18	<50	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-2	07/15/2013	10.63	3.75	6.88	150	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-2	$01/09/2014^3$	10.63	-	-	-	-	-	-	-	-	-	-
MW-2	07/25/2014	10.63	3.96	6.67	< 50	<50	<50	<0.5	<0.5	<0.5	<0.5	-

TABLE 1 Page 3 of 7

					Н	YDROCARBO	NS		1	PRIMARY VOC	es .	
Location	Date	тос	DTW	GWE	TPH-DRO	TPH-DRO w/ Si Gel	TPH-GRO	В	T	E	X	MTBE by SW8260
	Units	ft	ft	ft-amsl	µg∕L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L
MW-3	07/21/2010	10.72	5.09	5.63	640	-	65 J	0.6 J	<0.5	<0.5	<0.5	-
MW-3	10/22/2010	10.72	5.32	5.40	-	570	73	<0.5	<0.5	<0.5	<0.5	-
MW-3	$10/28/2010^2$	10.72	4.74	5.98	-	-	-	-	-	-	-	-
MW-3	01/14/2011	10.72	4.11	6.61	-	1,000	91	<0.5	<0.5	<0.5	<0.5	-
MW-3	04/19/2011	10.72	5.03	5.69	-	1,200	180	<0.5	<0.5	<0.5	<0.5	-
MW-3	06/30/2011	10.72	4.97	5.75	-	740	<50	<0.5	<0.5	<0.5	<0.5	-
MW-3	10/14/2011	10.72	4.52	6.20	1,800	<50	88	<0.5	<0.5	<0.5	<0.5	-
MW-3	01/18/2012	10.72	5.22	5.50	1,700	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-3	04/19/2012	10.72	4.63	6.09	3,000	50	260	<0.5	<0.5	<0.5	<0.5	-
MW-3	07/23/2012	10.72	4.89	5.83	1,200	<50	-	-	-	-	-	-
MW-3	07/27/2012 ⁴	10.72	4.58	6.14	-	-	<50	<0.5	<0.5	<0.5	< 0.5	-
MW-3	01/19/2013	10.72	4.52	6.20	1,600	<50	69	<0.5	<0.5	<0.5	<0.5	-
MW-3	07/15/2013 ⁵	10.72	4.54	6.18	1,500	<50	110	< 0.5	<0.5	<0.5	< 0.5	-
MW-3	01/09/2014	10.72	4.21	6.51	1,500	<50	<50	<0.5	<0.5	<0.5	< 0.5	-
MW-3	07/25/2014	10.72	4.95	5.77	1,700	<50	120	<0.5	<0.5	<0.5	<0.5	-
MW-4	07/21/2010	11.40	6.72	4.68	<50	-	<50	<0.5	<0.5	< 0.5	< 0.5	-
MW-4	10/22/2010	11.40	6.87	4.53	-	91	<50	< 0.5	<0.5	<0.5	<0.5	-
MW-4	$10/28/2010^2$	11.40	6.38	5.02	-	-	-	-	-	-	-	-
MW-4	01/14/2011	11.40	5.32	6.08	-	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-4	04/19/2011	11.40	7.65	3.75	-	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-4	06/30/2011	11.40	6.93	4.47		<50	<50	<0.5	<0.5	<0.5	<0.5	

TABLE 1 Page 4 of 7

					Н	YDROCARBO.	NS		1	PRIMARY VOC	es .	
Location	Date	тос	DTW	GWE	трн-рко	TPH-DRO w/ Si Gel	TPH-GRO	В	T	E	X	MTBE by SW8260
	Units	ft	ft	ft-amsl	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L
MW-4	10/14/2011	11.40	5.66	5.74	440	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-4	01/18/2012	11.40	8.36	3.04	330	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-4	04/19/2012	11.40	6.40	5.00	360	<50	<50	<0.5	0.5	<0.5	<0.5	-
MW-4	07/23/2012 ³	11.40	-	-	-	-	-	-	-	-	-	-
MW-4	07/27/2012	11.40	6.39	5.01	-	-	<50	<0.5	<0.5	<0.5	<0.5	-
MW-4	01/19/2013	11.40	6.78	4.62	380	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-4	07/15/2013	11.40	5.83	5.57	530	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-4	01/09/2014	11.40	5.19	6.21	240	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-4	07/25/2014	11.40	7.80	3.60	250	<50	<50	<0.5	<0.5	<0.5	<0.5	-
MW-5	07/21/2010	10.50	5.76	4.74	2,000	-	1,500	80	2	1	2	-
MW-5	10/22/2010	10.50	5.94	4.56	-	1,500	830	47	<0.5	1	<0.5	-
MW-5	$10/28/2010^2$	10.50	5.17	5.33	-	-	-	-	-	-	-	-
MW-5	01/14/2011	10.50	4.40	6.10	-	1,800	2,100	61	4	1	6	-
MW-5	04/19/2011	10.50	5.69	4.81	-	2,000	2,200	73	4	1	6	-
MW-5	06/30/2011	10.50	5.82	4.68	-	3,200	2,900	99	6	1	7	-
MW-5	10/14/2011	10.50	4.51	5.99	4,600	89	2,300	76	5	1	5	-
MW-5	01/18/2012	10.50	5.98	4.52	3,700	460	3,500	140	7	2	10	-
MW-5	04/19/2012	10.50	5.40	5.10	3,600	310	2,000	87	5	1	5	-
MW-5	07/23/2012	10.50	5.29	5.21	4,300	380	-	-	-	-	-	-
MW-5	07/27/20124	10.50	5.08	5.42	-	-	1,800	48	3	0.7	4	-
MW-5	01/19/2013	10.50	5.38	5.12	4,200	400	3,500	100	7	< 5	7	-
MW-5	07/15/2013	10.50	5.78	4.72	3,800	850	3,900	130	8	2	11	-

TABLE 1 Page 5 of 7

					Н	YDROCARBO	NS		1	PRIMARY VOC	es .	
Location	Date	тос	DTW	GWE	TPH-DRO	TPH-DRO w/ Si Gel	TPH-GRO	В	T	E	X	MTBE by SW8260
	Units	ft	ft	ft-amsl	µg∕L	µg∕L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L
MW-5 MW-5	01/09/2014 07/25/2014	10.50 10.50	4.20 6.20	6.30 4.30	4,000 3,200	670 720	3,600 3,400	130 130	9 9	2 2	13 14	- -
MW-6	10/28/2010	12.98	8.35	4.63	-	300	620	7	<0.5	1	2	-
MW-6	01/14/2011	12.98	7.58	5.40	-	560	120	3	<0.5	<0.5	<0.5	-
MW-6	04/19/2011	12.98	9.90	3.08	-	590	240	7	<0.5	<0.5	<0.5	-
MW-6	06/30/2011	12.98	9.97	3.01	-	640	200	3	< 0.5	< 0.5	<0.5	-
MW-6	10/14/2011	12.98	7.40	5.58	1,700	<50	510	10	< 0.5	< 0.5	<0.5	-
MW-6	01/18/2012	12.98	9.82	3.16	1,300	<50	300	7	<0.5	<0.5	<0.5	-
MW-6	04/19/2012	12.98	8.02	4.96	1,600	<50	290	7	0.6	<0.5	<0.5	-
MW-6	07/23/2012	12.98	9.69	3.29	1,600	73	-	-	-	-	-	-
MW-6	$07/27/2012^4$	12.98	8.39	4.59	-	-	450	9	<0.5	<0.5	0.6	-
MW-6	01/19/2013	12.98	8.92	4.06	830	<50	250	3	<0.5	<0.5	<0.5	-
MW-6	07/15/2013	12.98	7.70	5.28	2,400	<50	660	13	<0.5	<0.5	<0.5	-
MW-6	01/09/2014	12.98	6.85	6.13	1,400	<50	490	10	<0.5	<0.5	<0.5	-
MW-6	07/25/2014	12.98	9.85	3.13	1,500	<50	460	12	<0.5	<0.5	<0.5	-
QA	07/21/2010	-	-	-	-	-	<50	<0.5	<0.5	<0.5	<0.5	<0.5
QA	10/22/2010	-	-	-	-	-	<50	<0.5	<0.5	<0.5	<0.5	<0.5
QA	10/28/2010	-	-	-	-	-	<50	<0.5	<0.5	<0.5	<0.5	-
QA	01/14/2011	-	-	-	-	-	<50	<0.5	<0.5	<0.5	<0.5	-
QA	04/19/2011	-	-	-	-	-	<50	<0.5	<0.5	<0.5	<0.5	-
QA	06/30/2011	-	-	_	_	-	< 50	< 0.5	< 0.5	< 0.5	< 0.5	_

TABLE 1 Page 6 of 7

GROUNDWATER MONITORING AND SAMPLING DATA FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY CHEVRON BULK PLANT 206127 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA

Location Date TOC DTW GWE E E B T E X							YDROCARBO	NS		1	PRIMARY VOC	es	
QA 10/14/2011	Location	Date	тос	DTW	GWE	TPH-DRO	w/Si	TPH-GRO	В	T	E	X	MTBE by SW8260
QA 01/18/2012		Units	ft	ft	ft-amsl	µg∕L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L
QA 04/19/2012	QA	10/14/2011	-	-	-	-	-	<50	<0.5	<0.5	<0.5	<0.5	-
QA 07/23/2012	QA	01/18/2012	-	-	-	-	-	<50	<0.5	<0.5	<0.5	<0.5	-
QA 01/19/2013 <50 <0.5 <0.5 <0.5 <0.5 QA 07/15/2013 <50 <0.5 <0.5 <0.5 <0.5 QA 01/09/2014 <50 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	QA	04/19/2012	-	-	-	-	-	<50	<0.5	<0.5	< 0.5	< 0.5	-
QA 07/15/2013 <50 <0.5 <0.5 <0.5 <0.5 QA 01/09/2014 <50 <0.5 <0.5 <0.5 <0.5	QA	07/23/2012	-	-	-	-	-	<50	<0.5	<0.5	<0.5	<0.5	-
QA 01/09/2014 <50 <0.5 <0.5 <0.5	QA	01/19/2013	-	-	-	-	-	<50	<0.5	<0.5	<0.5	<0.5	-
	QA	07/15/2013	-	-	-	-	-	<50	<0.5	<0.5	<0.5	<0.5	-
	QA	01/09/2014	-	-	-	-	-	<50	<0.5	<0.5	<0.5	<0.5	-
QA 07/25/2014 <50 <0.5 <0.5 <0.5 <0.5	QA	07/25/2014	-	-	-	-	-	<50	<0.5	<0.5	<0.5	<0.5	-

Abbreviations and Notes:

TOC = Top of casing

DTW = Depth to water

GWE = Groundwater elevation

(ft-amsl) = Feet above mean sea level

ft = Feet

 μ g/L = Micrograms per liter

TPH-DRO = Total petroleum hydrocarbons - diesel range organics

TPH-GRO = Total petroleum hydrocarbons - gasoline range organics

B = Benzene

T = Toluene

E = Ethylbenzene

X = Xylenes (Total)

MTBE = Methyl tert butyl ether

TABLE 1 Page 7 of 7

GROUNDWATER MONITORING AND SAMPLING DATA FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY CHEVRON BULK PLANT 206127 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA

					Н	YDROCARBO	NS		I	PRIMARY VOC	S	
Location	Date	тос	DTW	GWE	TPH-DRO	TPH-DRO w/ Si Gel	TPH-GRO	В	T	E	X	MTBE by SW8260
	Units	ft	ft	ft-amsl	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L	µg∕L

^{-- =} Not available / not applicable

x = Not detected above laboratory method detection limit

J = Estimated concentration

- * TOC elevations for all wells were surveyed on July 30, 2009, by Morrow Surveying. Vertical Datum is NAVD 88 from GPS observations. TOC elevations were surveyed on January 25, 2001, by Virgil Chacez Land Surveying. The benchmark used for the survey was a City of Alameda benchmark being a cut square at the centerline return, south corner of Oak and Blanding, (Benchmark Elevation = 8.236 feet, NGVD 29).
- Destroyed and re-installed as MW-1RB.
- Monitored only for the 10/28/10 Special Event
- 3 Inaccessible.
- Due to laboratory error, a second set of samples had to be collected for TPHg and BTEX on 7/27/12 for wells MW1RA, MW1RB, MW-3, MW-5 and MW-6.
- No purge sample collected due to limited access.

Table 1 Groundwater Monitoring Data and Analytical Results

Chevron #206127 (Former Signal Oil Marine Terminal)
2301-2337 Blanding Avenue
Alameda, California

Experience and the second					Alameda, Camo					
WELL ID/	TQC*	DTW	GWE	TPH-DRO	TPH-GRO	В	T	E	X	MTBE
DATE	(fl.)	(ft.)	(msl)	(μg/L)	(pg/L)	(µg/L)	(µg/L)	(µg/L)	(µg/L)	(μg/L)
MW-1										
01/23/01		7.16		$1,100^{2,3}$	5,210 ⁴	868	<50.0	<50.0	<50.0	<250
04/09/01	10.62	8.12	2.50	1,200 ⁶	3,000 ⁵	920	<20	<20	<20	<100
07/30/01	10.62	9.15	1.47	550 ^{3,8}	2,000 ⁷	730	13	<5.0	<5.0	<25
10/08/01	10.62	7.86	2.76	2,200°	1,200	120	2.4	5.9	6.4	<2.5
01/13/02	10.62	7.02	3.60	$3,300^3$	930	320	0.78	0.87	3.8	<2.5
04/08/02	10.62	9.60	1.02	1,200 ³	960	50	1.4	2.6	9.0	<2.5
07/31/02	10.62	9.27	1.35	2,800 ³	930	64	1.4	1.9	H	<5.0
10/15/02	10.62	8.00	2.62	1,000 ³	620	25	0.78	1.4	4.3	<2.5
01/14/03	10.62	7.05	3.57	960³	1,600	20	1.3	1.3	<1.5	<2.5
04/15/03	10.62	8.02	2.60	920 ³	870	56	1	1.4	3.1	<2.5
07/16/03 ¹⁰	10.62	10.08	0.54	1,400 ³	780	85	1	0.8	0.7	<0.5
10/18/03 ¹⁰	10.62	8.51	2.11	1,200 ³	640	42	0.8	<0.5	0.5	<0.5
01/22/0410	10.62	8.95	1.67	1,500 ³	440	18	<0.5	<0.5	<0.5	<0.5
04/23/04 ¹⁰	10.62	8.95	1.67	2,200 ³	410	10	<0.5	<0.5	<0.5	<0.5
07/23/0410	10.62	9.21	1.41	1,800 ³	400	6	<0.5	<0.5	<0.5	<0.5
10/22/0410	10.62	8.36	2.26	$2,200^3$	150	2	<0.5	<0.5	<0.5	<0.5
01/28/05 ¹⁰	10.62	7.09	3.53	1,200 ³	55	8	<0.5	<0.5	<0.5	<0.5
04/26/0510	10.62	7.84	2.78	480^{3}	<50	5	<0.5	<0.5	<0.5	<0.5
07/15/05 ¹⁰	10.62	8.12	2.50	610 ^{3,11}	<50	< 0.5	<0.5	<0.5	<0.5	<0.5
10/14/0510	10.62	8.07	2.55	9203,12	<50	10	<0.5	<0.5	<0.5	<0.5
01/12/0610	10.62	6.98	3.64	960 ^{3,12}	<50	6	<0.5	<0.5	<0.5	<0.5
04/13/06 ¹⁰	10.62	7.04	3.58	1,200 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
07/13/06 ¹⁰	10.62	7.13	3.49	1,200 ³	92	14	<0.5	<0.5	<0.5	<0.5
10/17/06 ¹⁰	10.62	7.64	2.98	990 ³	<50	3	<0.5	<0.5	<0.5	<0.5
01/16/07 ¹⁰	10.62	7.09	3.53	840 ³	83	4	<0.5	<0.5	<0.5	<0.5
04/17/07 ¹⁰	10.62	7.11	3.51	1,200 ³	57	<0.5	<0.5	<0.5	<0.5	<0.5
07/17/07 ¹⁰	10.62	7.41	3.21	1,100 ³	120	8	<0.5	<0.5	<0.5	<0.5
10/16/07 ¹⁰	10.62	7.55	3.07	750 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
01/16/08 ¹⁰	10.62	6.98	3.64	1,700 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
04/16/08 ¹⁰	10.62	7.36	3.26	1,100 ³	62	<0.5	<0.5	<0.5	<0.5	<0.5
07/16/08 ¹⁰	10.62	7.89	2.73	580 ³	93	3	<0.5	<0.5	<0.5	<0.5
10/15/08 ¹⁰	10.62	7.46	3.16	740 ³	56	0.7	<0.5	<0.5	0.8	<0.5

Table 1
Groundwater Monitoring Data and Analytical Results
Chevron #206127 (Former Signal Oil Marine Terminal)

2301-2337 Blanding Avenue Alameda, California

WELL ID/					Liamou, camor					
555555555555555555	TQC*	DTW	GWE	TPH-DRO	TPH-GRO	В	T	E	X	MTBE
DATE	(ft.)	(ft.)	(msl)	(µg/L)	(µg/L)	(μg/L)	(µg/L)	(µg/L)	(µg/L)	(µg/L)
MW-1 (cont)										
01/21/0910	10.62	7.19	3.43	3903	<50	< 0.5	< 0.5	< 0.5	<0.5	< 0.5
04/15/0910	10.62	6.93	3.69	1,4003	80	0.7	< 0.5	<0.5	<0.5	< 0.5
07/03/0910	13.49	8.08	5.41	1,3003	51	< 0.5	<0.5	<0.5	<0.5	<0.5
10/01/0910	13.49	9.52	3.97	1,5003	86	< 0.5	<0.5	< 0.5	<0.5	< 0.5
01/19/1010	13.49	7.64	5.85	3403,15	<50	<0,5	< 0.5	< 0.5	<0.5	<0.5
04/26/1010	13.49	9.20	4.29	820 ³	66	<0.5	< 0.5	<0.5	<0.5	<0.5
										- 1-2
MW-2										
06/30/09 ¹	10.63	3.80	6.83	•=						-
07/03/0914	10.63	3.91	6.72	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	
10/01/09 ¹⁴	10.63	4.11	6.52	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	-
01/19/10 ¹⁴	10.63	3.90	6.73	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	
04/26/10 ¹⁴	10.63	4.08	6.55	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	12
MW-3										
06/30/09 ¹	10.72	4.61	6.11						where	
07/03/09 ¹⁴	10.72	4.57	6.15	170 ³	310	1	<0.5	2	<0.5	0
10/01/09 ¹⁴	10.72	5.22	5.50	1,000 ³	52	<0.5	<0.5	<0.5	<0.5	-
01/19/10 ¹⁴	10.72	4.84	5.88	1,800 ³	120	2	<0.5	<0.5	<0.5	2
D4/26/10 ¹⁴	10.72	4.86	5.86	1,700 ³	170	2	<0.5	<0.5	<0.5	- 4
MW-4										
06/30/091	11.40	6.02	5.38							97
07/03/09 ¹⁴	11.40	5.85	5.55	<50 ³	<50	< 0.5	< 0.5	< 0.5	< 0.5	iner I
10/01/09 ¹⁴	11.40	6.95	4.45	370 ³	<50	<0.5	< 0.5	< 0.5	<0.5	Sec
)1/19/10 ¹⁴	11.40	6.22	5.18	110 ³	<50	< 0.5	<0.5	< 0.5	<0.5	**
04/26/10 ¹⁴	11.40	6.61	4.79	210 ^{5,17}	<50	<0.5	<0.5	<0.5	<0.5	-

Table 1
Groundwater Monitoring Data and Analytical Results
Chevron #206127 (Former Signal Oil Marine Terminal)

2301-2337 Blanding Avenue Alameda, California

NAME OF TAXABLE PARTY OF TAXABLE PARTY.							574444444444444444			
WELL ID	TOC*	DTW	GWE	TPH-DRO	TPH-GRO	В	Ť	E		MTBE
DATE	(fi.)	(ft.)	(msl)	(μg/L)	(pg/L)	(µg/L)	(μg/L)	(µg/L)	(µg/L)	(μg/L)
MW-5										
06/30/091	10.50	5.20	5.30	20	**	Take		-	-	**
07/03/0914	10.50	5.17	5.33	1103	930	33	2	0.6	3	A
10/01/0914	10.50	5.66	4.84	2,5003	1,800	57	3	0.9	5	
01/19/1014	10.50	5.48	5.02	2,600 ³	2,200	74	4	1	5	-
04/26/1014	10.50	5.91	4.59	1,7003	2,200	94	4	2	5	
CS-2										
07/30/01	-	-	***	140 ^{3,5}	<50	< 0.50	< 0.50	< 0.50	< 0.50	<2.5
10/08/01	-	-		53°	<50	< 0.50	< 0.50	< 0.50	<1.5	<2.5
01/13/02	-	(94)	-	<50 ³	<50	< 0.50	< 0.50	< 0.50	<1.5	<2.5
04/08/02	~	-	**	77 ³	< 50	< 0.50	< 0.50	< 0.50	<1.5	<2.5
07/31/02	44	-		<50 ³	<50	< 0.50	< 0.50	< 0.50	<1.5	<2.5
10/15/02	-	(60)		<50 ³	<50	< 0.50	< 0.50	< 0.50	<1.5	<2.5
01/14/03	-	-		<50 ³	<50	< 0.50	< 0.50	< 0.50	<1.5	<2.5
04/15/03	**	-	-	<50 ³	<50	< 0.5	< 0.5	<0.5	<1.5	<2.5
07/16/03 ¹⁰	_	177		<50 ³	<50	< 0.5	0.7	< 0.5	0.6	< 0.5
10/18/03 ¹⁰	-	()	-	<50 ³	<50	< 0.5	< 0.5	< 0.5	<0.5	< 0.5
01/22/04 ¹⁰	-	-	+	<50 ³	<50	< 0.5	< 0.5	< 0.5	<0.5	<0.5
04/23/04 ¹⁰	14	-	77	<50 ³	<50	< 0.5	< 0.5	<0.5	<0.5	<0.5
07/23/04 ¹⁰	-	-	in the second	< 50 ³	<50	< 0.5	< 0.5	< 0.5	<0.5	<0.5
10/22/0410	-	-		<50 ³	<50	< 0.5	< 0.5	<0.5	<0.5	<0.5
01/28/05 ¹⁰		- 110	-	<50 ³	<50	< 0.5	< 0.5	<0.5	<0.5	< 0.5
04/26/05 ¹⁰	-		4.4	<50 ³	<50	<0.5	< 0.5	< 0.5	< 0.5	< 0.5
07/15/05 ¹⁰	-	***	-	<50 ³	<50	< 0.5	< 0.5	< 0.5	<0.5	<0.5
10/14/05 ¹⁰	40	-	-	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
01/12/06 ¹⁰	0	> 	24	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
04/13/06 ¹⁰	-	-	+	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
07/13/06 ¹⁰	⊕	-	-	140 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
10/17/06 ¹⁰	-	**	(+)	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
01/16/07 ¹⁰	-		44	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
04/17/07 ¹⁰	77	-	-4	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5

Table 1 Groundwater Monitoring Data and Analytical Results

Chevron #206127 (Former Signal Oil Marine Terminal)
2301-2337 Blanding Avenue
Alameda, California

					Alameda, Califor	IIIa				
WELL ID/	TOC*	DTW	GWE	TPH-DRO	TPH-GRO		T	E	X	MTBE
DATE	(fl.)	(fl.)	(nesl)	(µg/L)	(ng/L)	(µg/L)	(μg/L)	(µg/L)	(µg/L)	(µg/L)
CS-2 (cont)										
07/17/07 ¹⁰				<50 ³	<50	< 0.5	< 0.5	<0.5	< 0.5	< 0.5
10/16/07 ¹⁰		••		<50 ³	<50	< 0.5	<0.5	<0.5	<0.5	< 0.5
01/16/08 ¹⁰	••	••		85 ³	<50	< 0.5	<0.5	<0.5	<0.5	<0.5
04/16/08 ¹⁰				<50 ³	<50	< 0.5	<0.5	<0.5	<0.5	<0.5
07/16/08 ¹⁰				<50 ³	<50	< 0.5	< 0.5	<0.5	<0.5	<0.5
10/15/08 ¹⁰				<50 ³	<50	< 0.5	< 0.5	< 0.5	< 0.5	<0.5
01/21/09 ¹⁰				<50 ³	<50	<0.5	<0.5	< 0.5	<0.5	< 0.5
04/15/09 ¹⁰		••		86 ³	<50	< 0.5	<0.5	<0.5	<0.5	<0.5
07/03/09 ¹⁰		••		<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
10/01/09 ¹⁰		••	••	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
01/19/10 ¹⁰				2103,16	<50	<0.5	<0.5	<0.5	<0.5	<0.5
TRIP BLANK										
TB-LB										
01/23/01			-		<50.0	< 0.500	<0.500	< 0.500	< 0.500	<2.50
04/09/01		-		-	<50	<0.50	< 0.50	<0.50	<0.50	<2.5
07/30/01		-	-	4	<50	< 0.50	< 0.50	< 0.50	< 0.50	<2.5
QA										
10/08/01	-		-	-	<50	< 0.50	< 0.50	< 0.50	<1.5	<2.5
01/13/02	-		-	-	<50	< 0.50	< 0.50	< 0.50	<1.5	<2.5
04/08/02		**		-	<50	< 0.50	< 0.50	< 0.50	<1.5	<2.5
07/31/02	-	-	-		<50	< 0.50	< 0.50	<0.50	<1.5	<2.5
10/15/02	**		-	**	<50	< 0.50	< 0.50	<0.50	<1.5	<2.5
01/14/03	**	-		(44)	<50	< 0.50	< 0.50	<0.50	<1.5	<2.5
04/15/03	100		-	**	<50	< 0.5	< 0.5	< 0.5	<1.5	<2.5
)7/16/03 ¹⁰	-				<50	<0.5	< 0.5	<0.5	<0.5	<0.5
10/18/03 ¹⁰	-	-	-	-	<50	<0.5	<0.5	<0.5	< 0.5	< 0.5
01/22/04 ¹⁰	,***	-	-	-	<50	< 0.5	<0.5	<0.5	<0.5	<0.5
)4/23/04 ¹⁰			-		<50	<0.5	<0.5	<0.5	<0.5	<0.5
)7/23/04 ¹⁰	44	-		-	<50	< 0.5	< 0.5	<0.5	<0.5	<0.5
10/22/04 ¹⁰	**	-		-	<50	<0.5	<0.5	<0.5	<0.5	<0.5

Table 1 Groundwater Monitoring Data and Analytical Results Chevron #206127 (Former Signal Oil Marine Terminal)

2301-2337 Blanding Avenue Alameda, California

WELL ID/	TOC*	DTW	GWE	TPH-DRO	TPH-GRO	В	T	E	X	MTBE
ATE	(fl.)	(ft.)	(msl)	(μg/L)	(pg/L)	(µg/L)	(μg/L)	(µg/L)	(µg/L)	(μg/L)
A (cont)										
1/28/0510		•••			<50	<0.5	<0.5	<0.5	<0.5	<0.5
04/26/05 ¹⁰	••	**			<50	<0.5	<0.5	< 0.5	<0.5	< 0.5
7/15/0510		••		••	<50	< 0.5	<0.5	<0.5	<0.5	< 0.5
0/14/0510		**			<50	< 0.5	<0.5	<0.5	<0.5	< 0.5
1/12/06 ¹⁰					<50	< 0.5	<0.5	< 0.5	<0.5	< 0.5
4/13/06 ¹⁰					<50	<0.5	<0.5	<0.5	<0.5	<0.5
7/13/06 ¹⁰					<50	<0.5	<0.5	<0.5	<0.5	<0.5
0/17/06 ¹⁰					<50	< 0.5	<0.5	< 0.5	<0.5	<0.5
1/16/07 ¹⁰		**			<50	<0.5	<0.5	<0.5	<0.5	<0.5
4/17/07 ¹⁰					<50	< 0.5	<0.5	<0.5	<0.5	<0.5
7/17/07 ¹⁰			••	**	<50	<0.5	<0.5	<0.5	<0.5	<0.5
0/ 16/07 ¹⁰				••	<50	< 0.5	<0.5	<0.5	<0.5	<0.5
1/16/0810			**	**	<50	<0.5	<0.5	<0.5	<0.5	<0.5
4/16/08 ¹⁰				••	<50	< 0.5	<0.5	<0.5	<0.5	<0.5
7/16/08 ¹⁰				••	<50	<0.5	< 0.5	<0.5	<0.5	<0.5
0/15/08 ¹⁰	••			••	<50	< 0.5	< 0.5	<0.5	<0.5	<0.5
1/21/09 ¹⁰				••	<50 ¹³	< 0.5	< 0.5	<0.5	<0.5	<0.5
4/15/09 ¹⁰				••	<50	< 0.5	<0.5	< 0.5	<0.5	<0.5
7/03/09 ¹⁰					<50	< 0.5	< 0.5	<0.5	<0.5	<0.5
0/01/09 ¹⁰		-		**	<50	<0.5	<0.5	<0.5	<0.5	<0.5
I/19/10 ¹⁰				••	<50	< 0.5	< 0.5	<0.5	<0.5	<0.5
4/26/10 ¹⁰		••			<50	<0.5	<0.5	<0.5	<0.5	<0.5

Table 1

Groundwater Monitoring Data and Analytical Results

Chevron #206127 (Former Signal Oil Marine Terminal) 2301-2337 Blanding Avenue Alameda, California

EXPLANATIONS:

TOC = Top of Casing ORO = Diesel Range Organics ORO = DIESEL PORTO = DIESEL P

* TOC elevations for all wells were surveyed on July 30, 2009, by Morrow Surveying. Vertical Datum is NAVD 88 from GPS observations.

TOC elevations were surveyed on January 25, 2001, by Virgil Chavez Land Surveying. The benchmark used for the survey was a City of Alameda benchmark being a cut square at the centerline return, south corner of Oak and Blanding, (Benchmark Elevation = 8.236 feet, NGVD 29).

Well development performed.

TPH = Total Petroleum Hydrocarbons

- Laboratory report indicates unidentified hydrocarbons <C16.</p>
- Analyzed with silica gel cleanup.
- Laboratory report indicates weathered gasoline C6-C12.
- 5 Laboratory report indicates discrete peaks.
- Laboratory report indicates diesel C9-C24 + unidentified hydrocarbons <C16.</p>
- Laboratory report indicates gasoline C6-C12.
- 8 Laboratory report indicates unidentified hydrocarbons C9-C24.
- Analysis performed without silica gel cleanup although was requested on the Chain of Custody.
- 10 BTEX and MTBE by EPA Method 8260.
- Laboratory report indicates the observed sample pattern is not typical of #2 fuel/diesel. It elutes in the DRO range later than #2 fuel.
- Laboratory report indicates the observed sample pattern includes #2 fuel/diesel and an additional pattern which elutes later in the DRO range.

X = Xylenes

- Laboratory report indicates the original analysis was performed on an instrument where the ending calibration standard failed the method criteria. The sample was originally analyzed approximately 60 minutes after the LCS/LCSD. The LCS/LCSD showed good GRO recovery and the surrogate recovery for this sample was 85%. The sample was reanalyzed from a vial with headspace since only 1 vial was submitted. The results for the original and the reanalysis were similar. The reanalysis was reported.
- BTEX by EPA Method 8260.
- Laboratory report indicates DRO was detected in the method blank at a concentration of 38 μg/L. Results from the reextraction are within limits. The hold time had expired prior to the reextraction therefore, all results are reported from the original extract. Similar results were obtained in both extracts.
- Laboratory report indicates DRO was detected in the method blank at a concentration of 38 μg/L. Results from the reextraction are within limits. The hold time had expired prior to the reextraction therefore, all results are reported from the original extract. The DRO result for the reextract is 96 μg/L.
- Laboratory report indicates DRO was detected in the method blank at a concentration of 47 μg/L. Results from the reextraction are within limits. The hold time had expired prior to the reextraction therefore, all results are reported from the original extract. Similar results were obtained in both extracts.

Table 2

Groundwater Analytical Results - Metals

Chevron #206127 (Former Signal Oil Marine Terminal)

2301-2337 Blanding Avenue Alameda, California

WELL ID/ DATE	(1/gg)	(T/8#)	(Σ/gμ)	(7/80)	(1/gu)	(T/84)	Cobult	Copper	(Lygu)	(T/8/1) Molybdeaum	Nickel	Selenium (Ag/L)	Janus (ug/L)	(ng/L)	Miniperox (Aga)	Zinc	(µg/L)
MW-2						4.07	11.0.	170-2	(Fa) -2	4.97.	1178:17	Tra -1	(F8-2)	Vra -/	15-87	IPB P	(PS)
07/03/09	<9.7	<7.2	28.1	<1.4	<2.0	14.6	<2.1	<2.7	<6.9	<4.9	10.6	<8.9	<2.3	<14.0	12.6	11.6	<0.056
MW-3																	
07/03/09	<9.7	<7.2	143	<1.4	<2.0	8.5	<2.1	3.3	<6.9	<4.9	7.8	<8.9	<2.3	<14.0	13.8	18.8	<0.056
MW-4																	
07/03/09	<9.7	<7.2	83.5	<1.4	<2.0	10.0	<2.1	<2.7	<6.9	<4.9	4.5	<8.9	<2.3	<14.0	6.3	15.8	<0.056
MW-5																	
07/03/09	<9.7	32.7	148	<1.4	<2.0	<3.4	<2.1	3.1	<6.9	<4.9	3.6	<8.9	<2.3	<14.0	<2.5	19.2	<0.056

EXPLANATIONS

 $(\mu g/L)$ = Micrograms per liter

ANALYTICAL METHODS:


Metals analyzed by EPA Method SW-846 6010B Mercury analyzed by Method SW-7470A

Appendix C


Mass Flux

GRAPH A - TIDAL STUDY DATALOGGER REVIEW

FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY CHEVRON FACILITY 206127, 2301-2311 BLANDING AVENUE, ALAMEDA, CALIFORNIA





GRAPH B - TIDAL STUDY WELLS MW-1RA AND P-2 REVIEW FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY CHEVRON FACILITY 206127, 2301-2311 BLANDING AVENUE, ALAMEDA, CALIFORNIA





GRAPH C - TIDAL STUDY CONDUCTIVITY REVIEW

FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY CHEVRON FACILITY 206127, 2301-2311 BLANDING AVENUE, ALAMEDA, CALIFORNIA












TABLE 2 1 of 2

MANUAL DEPTH TO WATER MEASUREMENTS FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (FORMER CHEVRON 20-6127) 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA

WELL ID	DATE	TIME	Depth to Water
MW-1RA	10/02/12	13:01	7.60
	10/05/12	13:22	8.15
	10/08/12	12:07	8.07
	10/11/12	10:38	7.40
	10/15/12	9:42	7.80
MW-1RB	10/02/12	11:49	8.00
	10/05/12	13:12	7.61
	10/08/12	11:53	7.66
	10/11/12	10:30	7.41
	10/15/12	9:39	8.95
MW-2	10/02/12	12:48	3.53
	10/05/12	12:45	3.30
	10/08/12	11:30	3.35
	10/11/12	10:04	3.28
	10/15/12	11:12	3.58
MW-3	10/02/12	12:20	4.30
	10/05/12	13:00	4.33
	10/08/12	11:40	4.39
	10/11/12	10:22	4.19
	10/15/12	9:29	4.75
MW-4	10/02/12	12:30	6.15
	10/05/12		e- blocked by car
	10/08/12		e- blocked by car
	10/11/12	10:12	5.35
	10/15/12	10:17	5.90
MW-5	10/02/12	12:39	5.43
	10/05/12	13:17	4.61
	10/08/12	11:57	4.82
	10/11/12	10:33	4.18
	10/15/12	10:58	4.50
MW-6	10/02/12	11:30	8.00
	10/05/12	13:06	7.57
	10/08/12	11:48	7.98
	10/11/12	10:27	6.86
	10/15/12	9:19	8.10

TABLE 2 2 of 2

MANUAL DEPTH TO WATER MEASUREMENTS FORMER SIGNAL OIL MARINE STORAGE AND DISTRIBUTION FACILITY (FORMER CHEVRON 20-6127) 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA

WELL ID	DATE	TIME	Depth to Water
P-1	10/02/12	11:39	7.61
	10/05/12	13:30	7.69
	10/08/12	12:11	8.38
	10/11/12	10:43	7.14
	10/15/12	9:24	8.28
P-2	10/02/12	11:48	8.50
	10/05/12	13:35	8.25
	10/08/12	12:16	8.05
	10/11/12	10:46	7.95
	10/15/12	9:34	7.91
STILLING	10/02/12	14:42	5.28
	10/15/12	10:45	5.43

Appendix D

Degradation Calculations

Table A - Summary of Degradation Rate Calculations Former Signal Oil Bulk Plant (Chevron Facility 206127), 2301-2311 Blanding Avenue, Alameda, CA

Well	Analyte	Maximum Concentration (ug/L)	Current Concentration (ug/L)	Half-Life (years)	Date to Reach WQG
MW-1	TPHd	3,300	440	6.12	May 2027
101 0 0 - 1	TPHg	5,210	65	NA	Met
	Benzene	920	<0.5	NA NA	Met
MW-1RA	TPHd	4,000	3,700	NA	NA
	TPHg	6,800	6,800	NA	NA
	Benzene	830	780	NA	NA
MW-1RB	TPHd	1,900	1,900	NA	NA
	TPHg	650	310	NA	NA
	Benzene	9	9	NA	NA
MW-3	TPHd	1,800	50	NA	Met
	TPHg	310	<50	NA	Met
	Benzene	2	<0.5	NA	Met
MW-5	TPHd	3,200	720	3.80	Jan 2026
	TPHg	3,900	3,400	NA	Stable
	Benzene	140	130	NA	Stable
MW-6	TPHd	640	640	NA	NA
	TPHg	620	200	NA	NA
	Benzene	7	3	NA	NA

Predicted Time to Reach Environmental Screening Levels in Well MW-3

Former Signal Oil Bulk Plant (Chevron Facility 206127), 2301-2311 Blanding Avenue, Alameda, California

Calculate "Date to Reach Environmental Screening Level" given the first-order decay equation: $y = b e^{ax} \qquad ===> \qquad x = \ln(y/b) \ / \ a$ where: $y = \text{concentration in } \mu g / L \qquad a = \text{decay constant}$ $b = \text{concentration at time } (x) \qquad x = \text{time in days}$

Environmental Screening Level (ESL):

Constant:

Constant:

b

Constant:

a


Starting date for current trend:

Total Petroleum Hydrocarbons as Diesel (TPHd)	Total Petroleum Hydrocarbons as Gasoline (TPHg)	Benzene
100	100	1
NA	NA	NA
NA	NA	NA
NA	NA	NA

Calculate

Attenuation Half Life (years): $(-\ln(2)/a)/365.25$ NA NA NA NA

Estimated Date to Reach ESL: $(x = \ln(y/b)/a)$ NA NA NA



FORMER SIGNAL OIL BULK TERMINAL CHEVRON FACILITY 206127 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA MW-3: TPHd with SGC, TPHg BENZENE, AND DEPTH TO GROUNDWATER VERSUS TIME

Predicted Time to Reach Environmental Screening Levels in Well MW-5

Former Signal Oil Bulk Plant (Chevron Facility 206127), 2301-2311 Blanding Avenue, Alameda, California

Calculate "Date to Reach Environmental Screening Level" given the first-order decay equation: $y = b e^{ax}$ $x = \ln(y/b) / a$ where: $y = concentration in \mu g/L$ a = decay constant b = concentration at time (x)x = time in days


Constituent Environmental Screening Level (ESL): y Constant: b Constant: a Starting date for current trend:

Total Petroleum Hydrocarbons as Diesel (TPHd)	Total Petroleum Hydrocarbons as Gasoline (TPHg)	Benzene
100	100	1
1.00E+12	NA	NA
-5.00E-04	NA	NA
7/3/2009	NA	NA

Calculate

Attenuation Half Life (years): 3.80 NA NA $(-\ln(2)/a)/365.25$

Estimated Date to Reach ESL: $(x = \ln(y/b) / a)$ Ian 2026 NA NA



CHEVRON FACILITY 206127 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA

AND DEPTH TO GROUNDWATER VERSUS TIME

Appendix E

Sensitive Receptor Survey

SENSITIVE RECEPTOR AND WELL SURVEY FORMER SIGNAL OIL BULK PLANT (FORMER CHEVRON FACILITY 206127) 2301-2311 BLANDING AVENUE ALAMEDA, CALIFORNIA


ID on Map	Sensitive Receptor Type	DWR Well Drillers Report Number	Address	Owner	Well Type	Date Installed	Depth (fbg)	Screened (fbg)	Approximate Distance From Site
	Surface Water	NA	Alameda Canal		NA	NA	NA	NA	20 feet north
1	Well	32164	2307 Clement Avenue	Bob Tennant	Industrial	4/9/1977	80	20-80; 40-80	310 feet southwest
2	Well	32163	2307 Clement Avenue	Bob Tennant	Industrial	4/9/1977	71	20-71; 30-71	340 feet southwest
3	School	NA	2226 Pacific Avenue	Alameda Christian School	NA	NA	NA	NA	1775 feet southwest

Notes and Abbreviations

fbg = feet below grade

NA = not applicable

Well locations provided by the California Department of Water Resources (June 2011)



SENSITIVE RECEPTOR AND WELL SURVEY MAP FORMER SIGNAL OIL BULK PLANT (CHEVRON FACILITY 20-6127) 2301-2311 BLANDING AVENUE Alameda, California