Called of moore (Seacon)
recimed of updales of arco

April 13, 1992

92 APR 11 PM 8: 00

Ms. Susan Hugo Alameda County Department of Environmental Health 80 Swan Way Oakland, California 94621

ARCO Products Company Facilities in Alameda County

Dear Ms. Hugo:

Please find attached, Quarterly Summary Reports (QSRs) for ARCO Products Company Service Stations in Alameda County. The QSRs summarize activities conducted by ARCO at the respective sites during the first quarter of 1992; also included are projected site activities for the second quarter of 1992 and a bibliography of reports submitted for each location.

The QSRs are classified by city and address within Alameda County. We are submitting this document and attached QSRs as agreed. Please note that we are forwarding copies of the QSRs to the Regional Water Quality Control Board (RWQCB).

Please note that ARCO Products Company has reviewed the RWQCB's February 19, 1991 printout of ARCO fuel leak sites. We have evaluated each site with respect to ARCO's responsibility for investigation, monitoring, and/or remediation. Those locations for which ARCO is not responsible were listed and described in the QSR package delivered to you on July 15, 1991. The attached QSRs therefore represent only those locations for which ARCO is responsible.

ARCO is planning a subsequent comprehensive QSR submittal for ARCO sites on July 15, 1992. Please do not hesitate to contact us with any questions regarding this submittal.

Sincerely yours,

Kyle A. Christie

Environmental Engineer

Attachments:

ARCO Facility QSRs

A:\arcoqsrs\consmrg.ltr 50013-004-06

UST LEA		Date	nt April 6, 1992
SITE ID	ENTIFICATION		
Name	ARCO Service Station 276	Case	o Na.
Address	10609 MagArthur Bouleyard		
Andiese	Street Number Street		
	Oakland		94605
	City		ZIP Code
County	Alameda	Subst	ance Gasoline
Local Age	ncy Alameda County Health Care Services Agency (ACHCSA)		
_	Board Regional Water Quality Control Board - San Francisco Bay Area (CRWQCE	3)	
	Togonal Water County Control Board - Carl Trancisco Day Area (Crivico)	"	
LEAD S	TAFF PERSON ACHERA-Paul Smith		
CASE T	YPE		
37.13 .			na de la compansa de
	Undetermined Soil Only X Ground Water		Drinking Water
CTATIC	(Data indicates when area mound into actual)		
SIAIUS	(Date indicates when case moved into status)		
	No Action Taken	Data	4000
	Leak Being Confirmed Preliminary Site Assessment Workplan Submitted	Date _ Date	1988
	Preliminary Site Assessment Underway	Date .	3/89
	Pollution Characterization	Date _	8/89
X	Remediation Plan	Date _	7/91
<u>x</u>	Remedial Action Underway	Date	8/90
	Post Remedial Action Monitoring	Date	
	Case Referred to Regional Board	Date	
	Case Referred to Dept. of Health Services	Date	
	Case Closed	Date	
Vapor Ext replaced i 1991. Inst	NTS/MILESTONES: raction System installed offsite; startup date 8/90. Product removal by bailing for February 1990; approximately 100 cubic yards of soil removed from site. Perfor alled a Horner EZY floating product skimmer in MW-2 on 12/24/91. Received ACH tion of onsite VES.	med aquife	er pump test in November
RECENT	ACTIVITIES/FINDINGS:		
Installed a	ter Activities: Performed an aquifer pump test in November 1991. Submitted EBN Horner EZY floating product skimmer in MW-2 on 12/24/91. Received a verbal aqued two weeks prior to system startup.	•	
	uarter Activities: Submitted a remedial action plan to ACHCSA and RWQCB for in construction bids and selected a contractor for onsite VES installation.	iterim groud	ndwater remediation. Re-
ANTICIP	ATED ACTIVITIES:		
subsurfac	ter Activities: Continue groundwater monitoring; install onsite vapor extraction we investigation and pump test report; and prepare groundwater monitoring report; surface investigation.		
Reports da	ocumenting the site's history are listed on page 2		

REPORT Addendum Three to Work Plan for		<u>DATE</u> 3/18/92	CONSULTANT RECO.
Interim Groundwater Remediation 60026.08	n		
Letter Report on Fourth Quarter Groundwater Monitoring 60026.06	1991	3/9/92	RESNA
Letter Report on Third Quarter 1 Groundwater Monitoring 60026.06	1991	12/02/91	RESNA
Wastewater Discharge Permit App 60026.07	plication	11/26/91	RESNA
Addendum Two to Work Plan 60026.07		9/23/91	RESNA
Letter Report on Second Quarter Ground-Water Monitoring AGS 60026.02	1991	7/12/91	RESNA/Applied GeoSystems
Work Plan for Subsurface Environ Investigation and Remediation AGS 60026.03	nmental	7/01/91	RESNA/Applied GeoSystems
Addendum One to Work Plan AGS 60026.03		7/01/91	RESNA/Applied GeoSystems
Letter Report on First Quarter 19 Ground-Water Monitoring AGS 60026.02	991	4/16/91	RESNA/Applied GeoSystems
Report on Underground Gasoline Tank Removal and Replacement	: Storage	2/11/91	Applied GeoSystems
Letter Report on Quarterly Ground Monitoring for Fourth Quarter 19 AGS 60026-1		1/29/91	Applied GeoSystems
Report on Limited Offsite Subsurt Environmental Investigation AGS 19014-3	face	1/17/91	Applied GeoSystems
Letter Report on Quarterly Groun Water Monitoring for Fourth Qua First & Second Quarter 1990 at ARCO Station 276, Oakland, CA AGS 19014-4		8/6/90	Applied GeoSystems
Results of Soil Sampling in Propor Tank Pit Location	sed	2/13/90	Applied GeoSystems
Letter Report on Quarterly Ground Monitoring for Third Quarter 1999 AGS 60026-1		1/2/90	Applied GeoSystems

REPORT Report on Limited Subsurface Environmental Investigation AGS 19014-1	<u>DATE</u> 8/8/89	CONSULTANT Appel GeoSystems
Former Waste-Oil Tank Pit Analytical Results and Site Plan (Correspondence to Ms. Mary Meirs, ACEHD/HMD)	2/6/89	Pacific Environmental Group, Inc.
Preliminary Soil and Groundwater Quality Testing Program Foothill Square Job No. KE812-3A, 12302	10/7/88	Kaldveer Associates
Preliminary Environmental Assessment Proposed Foothill Square Job No. KE812-3, 12056	10/3/88	Kaldveer Associates
Soil Sampling and Monitoring Well Installation Foothill Square. Job No. 8-088.01	No date available	Western Geologic Resources, Inc.

.

.

.