AGENCY



DAVID J. KEARS, Agency Director

Ro#2638

September 15, 1997

Roger Gaither Law Office of Roger S. Gaither 238 Kittery Place San Ramon, CA - 94583

ENVIRONMENTAL, HEALTH SERVICES **ENVIRONMENTAL PROTECTION (LOP)** 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Redwood Christian Schools, 4200 James Street, Castro Valley, CA - 94546 RE:

Dear Mr. Gaither:

I am in receipt of the soil investigation report, dated August 14, 1997, prepared by Gettler-Ryan, Inc. for the above referenced site. This Department has conducted a review of all the pertinent documents and to move the site towards closure the following additional work needs to be completed:

At least a minimum of two samples needs to be collected at the depths of 2 feet in areas where the highest concentrations of TPH was identified. This is to confirm that the release is surficial and there is no significant threat due to contaminants leaching to groundwater.

Also, the fuel fingerprinting analysis done on few of the soil samples collected previously describes the contaminant to be an unidentified hydrocarbon having a extractable hydrocarbon range of C9-C40. Hence, please analyze a soil sample, (either a sample that was collected previously and is being held by the laboratory or a new soil sample) collected from an area of high TPH concentrations (based on previous laboratory analysis) for Poly Nuclear Aromatics (PNA's). This information is required since the cleanup level of 1000 ppm for the higher end hydrocarbons were established assuming the absence of any PNA's or BTEX.

The Environmental site assessment reports, one dated June 29, 1989 and the other dated October 24, 1989 mentions (on page 4) the presence of a steel storage tank designed for underground use that was observed in the northwestern part of the second parcel. Attached to the report is a copy of laboratory results for gasoline and BTEX analysis. Also, the more recent report prepared by Gettler Ryan (dated August 14, 1997) mentions the presence of an above ground storage tank in the west end of the referenced property. The reports do not provide any information on the location of the tanks, tank removal or disposal process followed, the materials stored in the tanks, the location of the samples for which the analysis was performed.

Please provide the information requested and a work plan for additional investigation within 30 days from the date of this letter. This is a formal request for technical information and any delays should in requested in writing. If you have any questions, you may reach me at (510) 567-6764.

Sincerely,

Madhulla Logan

Hazardous Material Specialist

C: Clyde Galantine

Gettler-Ryan, Inc.

6747 Sierra Court, Suite J Dublin, CA - 94568