ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

RO# 2646

March 2, 1998

ENVIRONMENTAL HEALTH SERVICES 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700

(510) 337-9335 (FAX)

Ms. Josefina Miller Express Electric Co. 1071 San Pablo Avenue Albany, California 94706

RE: Underground Storage Tank Removal at Express Electric Co.

(STID # 6363)

1071 San Pablo Avenue, Albany, CA 94706

Dear Ms. Miller:

This office has reviewed the case file regarding the removal of one 2,000 gallon gasoline underground storage tank (UST) at the above referenced site.

On May 6, 1992, the former UST was removed by Consolidated Technologies. Soil samples were collected following the removal of the tank. In addition, a grab water sample was collected from the bottom of the excavation pit. Analytical results of the soil and water samples showed no detectable level of Total Petroleum Hydrocarbon (TPH) as gasoline, benzene, toluene, ethyl benzene and xylene. Lead was detected in soil at very low concentration (6.6 ppm).

The tank has been removed in full compliance with the requirements of Title 23, California Code of Regulations. Therefore, based on the information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, no further investigation or cleanup action is required regarding the former underground storage tank.

If you have any questions concerning this letter, please contact me at (510) 567-6780.

Sincerely,

Susan L. Hugo

Hazardous Materials Specialist

Mee Ling Tung, Director, Environmental Health
 Dick Pantages, Chief, Environmental Protection Division
 Stephen Hill, San Francisco Bay RWQCB
 SH / files