

Plunkett, Steven, Env. Health

From: Brooke Disbrow [brooked@sanjoco.com]
Sent: Friday, May 22, 2009 10:38 AM
To: Plunkett, Steven, Env. Health
Cc: Dai SJC
Subject: RO2733 Oak Walk Remediation Results Summary
Attachments: RO2733 Remed Results Summary.pdf

Hi Mr. Plunkett,

Attached you will find all the requested remediation results, starting with a memo that will explain what each part is. The last 3 pages of the summary contain some groundwater results even though the post-remediation groundwater monitoring program has not yet begun. There are some pre and post GW results from non-monitoring well sources.

Because the summary is mostly numbers and drawings, the easiest way to get a handle on the site and on the neighboring sites is to first re-read Vol. I of the CAP. It's on your ftp site.

I have also uploaded this summary document to the ftp site.

Please call Dai Watkins at (510) 336-9118 if you have any questions.

Thank you,

Brooke

Brooke H. Disbrow
Project Manager
The San Joaquin Company Inc.
1120 Hollywood Ave., No. 3
Oakland, CA 94602
Voice: (510) 336-9118