November 05, 2008

Site Name & Address:

OAKLAND, CA 946124311

MOBIL #10-MHG

160 14TH ST

HEALTH CARE SERVICES

Certified Mail #: 7006 3450 0000 0503 3916







ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

(510) 567-6700

FAX (510) 337-9335

NOTICE OF RESPONSIBILITY

Local ID:

RO0002922

Related ID:

NA

RWQCB ID:

NA

Global ID:

T06019782296

Responsible Party:

TED W. DANG FOURTEENTH & MADISON ASSOCIATES 1305 FRANKLIN ST OAKLAND CA 94612-3213

Date First Reported: 4/27/2006

8006619 Gasoline-Automotive (motor gasoline

and additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified EXXONMOBIL as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5650.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker JAKUB, BARBARA, at this office at (510)639-1287 if you have questions regarding your site.

ARIU LEVI. Difector Contract Project Director

Date: 12/1-11

Action: Add

Reason: ADD RPs

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

November 05, 2008

Site Name & Address: MOBIL #10-MHG 160 14TH ST

OAKLAND, CA 946124311

Local ID:

RO0002922

Related ID: NA RWQCB ID: NA

Global ID:

T06019782296

- DE 1

All Responsible Parties

RP has been named a Primary RP - JENNIFER C SEDLACHEK EXXONMOBIL

4096 PIEDMONT AVE #194 | OAKLAND, CA 94611 | Phone (510) 547-8196

RP has been named a Primary RP - SUSAN FRIEDLAND MADISON STREET LOFTS LP

1250 ADDISON ST, STE G | BERKELEY, CA 94702-1713 | Phone No Phone Number Listed

RP has been named a Primary RP - LIANG C LEE UNK

388 MARKET ST, FL 5 | SAN FRANCISCO, CA 94111-5311 | Phone No Phone Number Listed

RP has been named a Primary RP - TED W DANG FOURTEENTH & MADISON ASSOCIATES

1305 FRANKLIN ST | OAKLAND, CA 94612-3213 | Phone No Phone Number Listed

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

November 05, 2008

Responsible Party Identification

RO 2922, 160 14th Street, Oakland, CA 94612

Existence of Unauthorized Release


The three underground storage tanks (USTs) were removed from operation in May 1986. Four soil samples collected at the time of removal were below the detection limits. However, no groundwater samples were collected at the time. A subsequent sampling event performed in 2001 revealed maximum concentrations of 87milligrams per kilogram (mg/kg) total petroleum hydrocarbons as gasoline (TPHg), 100 mg/kg total petroleum hydrocarbons as diesel (TPHd) and 1 mg/kg benzene in soil from boring S-2. Groundwater was not collected from this boring. TPHg was detected in water at a maximum concentration of 78 micrograms per liter (ug/L), TPHd at a maximum concentration of 340 ug/L and benzene at 5.7 ug/L. In 2006, further investigation detected 18,000 ug/L TPHg and 690 ug/l benzene in groundwater.


Responsible Party Identification

Mobil Oil Corporation Owned and operated underground storage tanks and the property at this location. Mobil meets the definition of a responsible party for the site because they had control over an underground storage tank at the time or following an unauthorized release of a hazardous substance (Definition 4) and they owned the property where an unauthorized release occurred, (Definition 3).

Fourteenth and Madison Associates purchased the property in June 1987 and was the property owner following an unauthorized petroleum hydrocarbon release(s). Fourteenth and Madison Associates meet the definition of a responsible party for the site because they owned the property where an unauthorized release occurred, (Definition 3).

Lee Liang purchased the property in March 2000 and was the property owner following an unauthorized petroleum hydrocarbon release(s). Lee Liang meets the definition of a responsible party for the site because he owned the property where an unauthorized release occurred, (Definition 3).





ν	
SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
 Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery Is desired. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits. Article Addressed to: TED W. DANG FOURTEEN & MADISON ASSOCIATES 1305 FRANKLIN STREET OAKLAND. CA 94612-3213 	A. Signature X
	3. Service Type Certified Mail Express Mail Registered Return Receipt for Merchandise Insured Mail C.O.D. 4. Restricted Delivery? (Extra Fee) Yes
2. Article Number (Transfer from service label) 7006 3450	0000 0503 391 L

HEALTH CARE SERVICES





DAVID J. KEARS, Agency Director

Certified Mail #: 7006 3450 0000 0503 3909

November 05, 2008

ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700

FAX (510) 337-9335

NOTICE OF RESPONSIBILITY

Site Name & Address:

MOBIL #10-MHG

160 14TH ST

OAKLAND, CA 946124311

Local ID:

RO0002922

Related ID:

NA

RWQCB ID: NA

Global ID:

T06019782296

Responsible Party:

LIANG C. LEE

UNK

388 MARKET ST, FL 5

SAN FRANCISCO CA 94111-5311

Date First Reported: 4/27/2006

Substance:

8006619 Gasoline-Automotive (motor gasoline

and additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified EXXONMOBIL as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5650.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker JAKUB, BARBARA, at this office at (510)639-1287 if you have questions regarding your site.

ARIU LEVIMDirector Contract Project Director Date: 1. 1-118

Action: Add

Reason: ADD RPs

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

November 05, 2008

Site Name & Address: MOBIL #10-MHG 160 14TH ST

OAKLAND, CA 946124311

Local ID: RO0002922

Related ID: NA RWQCB ID: NA

Global ID: T06019782296

All Responsible Parties

RP has been named a Primary RP - JENNIFER C SEDLACHEK

4096 PIEDMONT AVE #194 | OAKLAND, CA 94611 | Phone (510) 547-8196

RP has been named a Primary RP - SUSAN FRIEDLAND MADISON STREET LOFTS LP

1250 ADDISON ST, STE G | BERKELEY, CA 94702-1713 | Phone No Phone Number Listed

RP has been named a Primary RP - LIANG C LEE UNK

388 MARKET ST, FL 5 | SAN FRANCISCO, CA 94111-5311 | Phone No Phone Number Listed

RP has been named a Primary RP - TED W DANG FOURTEENTH & MADISON ASSOCIATES

1305 FRANKLIN ST | OAKLAND, CA 94612-3213 | Phone No Phone Number Listed

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

November 05, 2008

Responsible Party Identification

RO 2922, 160 14th Street, Oakland, CA 94612

Existence of Unauthorized Release

The three underground storage tanks (USTs) were removed from operation in May 1986. Four soil samples collected at the time of removal were below the detection limits. However, no groundwater samples were collected at the time. A subsequent sampling event performed in 2001 revealed maximum concentrations of 87milligrams per kilogram (mg/kg) total petroleum hydrocarbons as gasoline (TPHg), 100 mg/kg total petroleum hydrocarbons as diesel (TPHd) and 1 mg/kg benzene in soil from boring S-2. Groundwater was not collected from this boring. TPHg was detected in water at a maximum concentration of 78 micrograms per liter (ug/L), TPHd at a maximum concentration of 340 ug/L and benzene at 5.7 ug/L. In 2006, further investigation detected 18,000 ug/L TPHg and 690 ug/l benzene in groundwater.

Responsible Party Identification

Mobil Oil Corporation Owned and operated underground storage tanks and the property at this location. Mobil meets the definition of a responsible party for the site because they had control over an underground storage tank at the time or following an unauthorized release of a hazardous substance (Definition 4) and they owned the property where an unauthorized release occurred, (Definition 3).

Fourteenth and Madison Associates purchased the property in June 1987 and was the property owner following an unauthorized petroleum hydrocarbon release(s). Fourteenth and Madison Associates meet the definition of a responsible party for the site because they owned the property where an unauthorized release occurred, (Definition 3).

Lee Liang purchased the property in March 2000 and was the property owner following an unauthorized petroleum hydrocarbon release(s). Lee Liang meets the definition of a responsible party for the site because he owned the property where an unauthorized release occurred, (Definition 3).



HEALTH CARE SERVICES

Certified Mail #: 7006 3450 0000 0503 3886





DAVID J. KEARS, Agency Director

November 05, 2008

ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700

NOTICE OF RESPONSIBILITY FAX (510) 337-9335

Site Name & Address: MOBIL #10-MHG

160 14TH ST

OAKLAND, CA 946124311

Local ID:

RO0002922

Related ID:

NA

RWQCB ID:

NA

Global ID:

T06019782296

Responsible Party:

JENNIFER C. SEDLACHEK **EXXONMOBIL 4096 PIEDMONT AVE #194 OAKLAND CA 94611**

Date First Reported: 4/27/2006

Substance:

8006619 Gasoline-Automotive (motor gasoline

and additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified EXXONMOBIL as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5650.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker JAKUB, BARBARA, at this office at (510)639-1287 if you have questions

regarding your site/

Contract Project Director

ARIU LEVI, Director

Date: 1/1-/08

Action: Add

Reason: ADD RPs

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

November 05, 2008

Site Name & Address:

MOBIL #10-MHG

160 14TH ST

OAKLAND, CA 946124311

Local ID:

RO0002922

Related ID: NA

RWQCB ID: NA

Global ID:

T06019782296

All Responsible Parties

RP has been named a Primary RP - JENNIFER C SEDLACHEK

4096 PIEDMONT AVE #194 | OAKLAND, CA 94611 | Phone (510) 547-8196

RP has been named a Primary RP - SUSAN FRIEDLAND

MADISON STREET LOFTS LP

1250 ADDISON ST, STE G | BERKELEY, CA 94702-1713 | Phone No Phone Number Listed

RP has been named a Primary RP - LIANG C LEE

UNK

388 MARKET ST, FL 5 | SAN FRANCISCO, CA 94111-5311 | Phone No Phone Number Listed

RP has been named a Primary RP - TED W DANG

FOURTEENTH & MADISON ASSOCIATES

1305 FRANKLIN ST | OAKLAND, CA 94612-3213 | Phone No Phone Number Listed

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

November 05, 2008

Responsible Party Identification

RO 2922, 160 14th Street, Oakland, CA 94612

Existence of Unauthorized Release

The three underground storage tanks (USTs) were removed from operation in May 1986. Four soil samples collected at the time of removal were below the detection limits. However, no groundwater samples were collected at the time. A subsequent sampling event performed in 2001 revealed maximum concentrations of 87milligrams per kilogram (mg/kg) total petroleum hydrocarbons as gasoline (TPHg), 100 mg/kg total petroleum hydrocarbons as diesel (TPHd) and 1 mg/kg benzene in soil from boring S-2. Groundwater was not collected from this boring. TPHg was detected in water at a maximum concentration of 78 micrograms per liter (ug/L), TPHd at a maximum concentration of 340 ug/L and benzene at 5.7 ug/L. In 2006, further investigation detected 18,000 ug/L TPHg and 690 ug/l benzene in groundwater.

Responsible Party Identification

Mobil Oil Corporation Owned and operated underground storage tanks and the property at this location. Mobil meets the definition of a responsible party for the site because they had control over an underground storage tank at the time or following an unauthorized release of a hazardous substance (Definition 4) and they owned the property where an unauthorized release occurred, (Definition 3).

Fourteenth and Madison Associates purchased the property in June 1987 and was the property owner following an unauthorized petroleum hydrocarbon release(s). Fourteenth and Madison Associates meet the definition of a responsible party for the site because they owned the property where an unauthorized release occurred, (Definition 3).

Lee Liang purchased the property in March 2000 and was the property owner following an unauthorized petroleum hydrocarbon release(s). Lee Liang meets the definition of a responsible party for the site because he owned the property where an unauthorized release occurred, (Definition 3).



Sender: Please print your name, address, and ZIP+4 in this box

Environmental Health Services
Environmental Protection
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577
Attn: Fab Tag CP2923

NOV 1 2 ZIVI8

NOV 1 2 ZIVI8

ENVIRONMENTAL HEALTH SERVICES

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
 Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits. 1. Article Addressed to: JENNIFER C. SEDLACHEK EXXONMOBIL 4096 PIEDMONT AVE # 194 OAKLAND, CA 94611 	A. Signature X Agent Addressee B. Received by (Printed Name) C. Date of Delivery PATS D. Is delivery address different from item 1? Yes If YES, enter delivery address below:
	3. Service Type Certified Mail
2. Article Number (Transfer from service label) 7006 345	0 0000 0503 3886
PS Form 3811, February 2004 Domestic	Return Receipt 102595-02-M-1540

HEALTH CARE SERVICES



DAVID J. KEARS, Agency Director



Certified Mail #: 7006 3450 0000 0503 3893

November 05, 2008

ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700

NOTICE OF RESPONSIBILITY FAX (510) 337-9335

Site Name & Address:

MOBIL #10-MHG

160 14TH ST

OAKLAND, CA 946124311

Local ID:

RO0002922

Related ID:

NA

RWQCB ID:

NA

Global ID:

T06019782296

Responsible Party:

SUSAN FRIEDLAND MADISON STREET LOFTS LP 1250 ADDISON ST, STE G **BERKELEY CA 94702-1713**

Date First Reported: 4/27/2006

Substance:

8006619 Gasoline-Automotive (motor gasoline

and additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified EXXONMOBIL as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5650.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker JAKUB, BARBARA, at this office at (510)639-1287 if you have questions regarding your site.

ARIU LEVI. Director Contract Project Director Date: ///5/01

Action: Add Reason: ADD RPs

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

November 05, 2008

Site Name & Address: MOBIL #10-MHG

160 14TH ST

OAKLAND, CA 946124311

Local ID: RO0002922

Related ID: NA

RWQCB ID: NA

Global ID: T06019782296

All Responsible Parties

RP has been named a Primary RP - JENNIFER C SEDLACHEK

4096 PIEDMONT AVE #194 | OAKLAND, CA 94611 | Phone (510) 547-8196

RP has been named a Primary RP - SUSAN FRIEDLAND MADISON STREET LOFTS LP

1250 ADDISON ST, STE G | BERKELEY, CA 94702-1713 | Phone No Phone Number Listed

RP has been named a Primary RP - LIANG C LEE

UNK

388 MARKET ST, FL 5 | SAN FRANCISCO, CA 94111-5311 | Phone No Phone Number Listed

RP has been named a Primary RP - TED W DANG

FOURTEENTH & MADISON ASSOCIATES

1305 FRANKLIN ST | OAKLAND, CA 94612-3213 | Phone No Phone Number Listed

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

November 05, 2008

Responsible Party Identification

RO 2922, 160 14th Street, Oakland, CA 94612

Existence of Unauthorized Release

The three underground storage tanks (USTs) were removed from operation in May 1986. Four soil samples collected at the time of removal were below the detection limits. However, no groundwater samples were collected at the time. A subsequent sampling event performed in 2001 revealed maximum concentrations of 87milligrams per kilogram (mg/kg) total petroleum hydrocarbons as gasoline (TPHg), 100 mg/kg total petroleum hydrocarbons as diesel (TPHd) and 1 mg/kg benzene in soil from boring S-2. Groundwater was not collected from this boring. TPHg was detected in water at a maximum concentration of 78 micrograms per liter (ug/L), TPHd at a maximum concentration of 340 ug/L and benzene at 5.7 ug/L. In 2006, further investigation detected 18,000 ug/L TPHg and 690 ug/l benzene in groundwater.


Responsible Party Identification

Mobil Oil Corporation Owned and operated underground storage tanks and the property at this location. Mobil meets the definition of a responsible party for the site because they had control over an underground storage tank at the time or following an unauthorized release of a hazardous substance (Definition 4) and they owned the property where an unauthorized release occurred, (Definition 3).

Fourteenth and Madison Associates purchased the property in June 1987 and was the property owner following an unauthorized petroleum hydrocarbon release(s). Fourteenth and Madison Associates meet the definition of a responsible party for the site because they owned the property where an unauthorized release occurred, (Definition 3).

Lee Liang purchased the property in March 2000 and was the property owner following an unauthorized petroleum hydrocarbon release(s). Lee Liang meets the definition of a responsible party for the site because he owned the property where an unauthorized release occurred, (Definition 3).





• Sender: Please print your name, address, and ZIP+4 in this box •

Alameda County

Environmental Health Services
Environmental Protection NOV 1 0 2008

1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577 Environmental Health
Attn: Barbara, RO#2922

Daladaldalla addadalla addadalla addadla addadla addadla addadla addadla addadla addadla addadla addadla addad

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
 Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits. 1. Article Addressed to: SUSAN FRIEDLAND MADISON STREET LOFTS LP 1250 ADDISON STREET, STE G BERKELEY, CA 94702-1713 	A. Signature X. Addressee B. Received by (Printed Name) C. Date of Delivery Addressee D. Is delivery address different from item 1? Yes If YES, enter delivery address below: No
	3. Service Type Certified Mail Registered Return Receipt for Merchandise Insured Mail C.O.D. 4. Restricted Delivery? (Extra Fee)
2. Article Number 7006 345	50 0000 0503 3893