July 5, 2011

Ms. Barbara Jakub Alameda County Health Care Services Agency 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 **RECEIVED** 

11:03 am, Jul 18, 2011 Alameda County Environmental Health

Subject:

Site Investigation Report

Site:

76 Station No. 6277 15803 East 14<sup>th</sup> Street San Leandro, California

Fuel Leak Case No. RO0002969

Dear Ms. Jakub;

I declare under penalty of perjury that to the best of my knowledge the information and/or recommendations contained in the attached report is/are true and correct.

If you have any questions or need additional information, please call:

Brian Whalen Platinum Energy 30343 Canwood Street, Suite 200, Agoura Hills, Ca 91301

Tel: (818) 206-5704 Fax: (818) 206-5721

bwhalen@platinum-energy.net

Sincerely,

PLATINUM ENERGY

BRIAN WHALEN

Attachment



# Site Investigation Report

76 Service Station No. 6277 15803 East 14th Street San Leandro, CA Alameda County LOP Case No. RO0002969

GeoTracker Global ID No. T0619718179

Antea Group Project No. 140256277 July 5, 2011

Prepared for:

Ms. Barbara Jakub

Alameda County

Health Care Services Agency
1131 Harbor Bay Parkway,
Suite 250

Alameda, CA 94502-6577

Prepared by:
Antea™Group
11050 White Rock Road
Suite 110
Rancho Cordova, CA 95670
+1 800 477 7411





## **Table of Contents**

1.0	INTRODUCTION	3
1.1	Site Description	
1.2	Previous Assessment	
1.3	Sensitive Receptors	8
2.0	SITE GEOLOGY AND HYDROGEOLOGY	9
3.0	WELL INSTALLATION ACTIVITIES	10
3.1	Permitting, Utility Notification, and Borehole Clearance	10
3.2	Monitoring Well Installation	
3.3	Soil Sampling	11
3.4	Well Development, Monitoring, and Sampling	11
3.5	Wellhead Survey	12
3.6	Disposal of Drill Cuttings and Wastewater	12
4.0	GROUNDWATER MONITORING ACTIVITIES	12
4.1	Groundwater Monitoring	12
4.1	.1 Groundwater Flow Gradient and Direction	13
4.1	.2 Groundwater Quality Data	13
4.2	Waste Disposal Summary	14
4.3	Quality Assurance / Quality Control	14
5.0	RESULTS OF THE INVESTIGATION	15
5.1	Soil Analytical Results	15
5.2	Groundwater Analytical Results	15
6.0	CONCLUSIONS AND RECOMMENDATIONS	15
7.0	REMARKS	16

#### **Figures**

igure 1	Site Location Map
igure 2	Site Plan
igure 3	Cross Section A-A'
igure 4	Cross Section B-B'
igure 5	Groundwater Elevation Contour Map – April 18, 2011
igure 6	Dissolved Phase TPHg Isoconcentration Map – April 18, 2011
igure 7	Dissolved Phase Benzene Isoconcentration Map – April18, 2011
igure 8	Dissolved Phase MTBE Isoconcentration Map – April 18, 2011



#### **Tables**

Table 1 Historical Soil Analytical Results

Table 2 Current Groundwater Gauging and Analytical Data

Table 3 Historical Groundwater Analytical Data

**Case Closure Documents** 

### **Appendices**

Appendix H

Appendix A Well Installation Permit
 Appendix B Boring Logs and DWR Well Completion Reports
 Appendix C Certified Laboratory Analytical Reports and Data Validation Forms
 Appendix D Well Development Logs
 Appendix E Blaine Tech Services Groundwater Sampling Procedures
 Appendix F Blaine Tech Services Groundwater Sampling Field Data Sheets
 Appendix G Waste Manifest

ii www.anteagroup.com

### Site Investigation Report

76 Service Station No. 6277

#### 1.0 INTRODUCTION

Antea Group has prepared this report describing the installation, development, surveying, and sampling of four monitoring wells at the site located at 15803 East 14<sup>th</sup> Street in San Leandro, California. This work was performed as indicated in the work plan submitted by Delta Consultants, (currently Antea Group) on December 20, 2010.

#### 1.1 Site Description

The site is currently an operating 76 service station located at 15803 East 14<sup>th</sup> Street in San Leandro, California (**Figure 1**). Station facilities include two 12,000 gallon fuel underground storage tanks (USTs), a 520-gallon waste-oil UST, two dispenser islands and a service station building, containing three service bays (**Figure 2**).

#### 1.2 Previous Assessment

<u>1969</u> - Reported site history indicates the site was first developed as a gas station from an empty lot in 1969.

<u>March 1989</u> - Two 10,000-gallon gasoline USTs, one 550-gallon waste-oil UST, and the product piping were removed from the site during UST replacement activities. Kaprealian Engineering Inc. (KEI) advanced two exploratory borings designated as EB-1 and EB-2 at the site. The borings were advanced at the request of Alameda County to assess the possible presence of hydrocarbon impact to the soil in the vicinity of the proposed UST excavation.

The borings were advanced to depths of 10.5 feet below ground surface (bgs) and 13.5 feet bgs. Ground water was encountered in the borings at depths of 11 to 12 feet bgs. The analytical results of the soil samples were as follows:



- At a depth of 5 feet bgs soil samples analyzed for total petroleum hydrocarbons as gasoline (TPHg) ranged from below the laboratory's indicated reporting limit in boring EB-2 to 2.1 parts per million (ppm) in boring EB-1.
- At a depth of 10 feet bgs TPHg concentrations ranged from 200 ppm in boring EB-1 to 620 ppm in boring EB-2.

Based on results of this preliminary investigation, KEI recommended that the contractor excavate the existing UST excavation to a depth of approximately 13 feet bgs. Water was encountered in the fuel UST excavation at a depth of approximately 11 feet bgs, thus prohibiting the collection of any soil samples from immediately beneath the USTs.

Six soil samples, labeled SW1 through SW6, were collected from the sidewalls of the fuel UST pit at depths of approximately 1 foot above the water table; and one soil sample, labeled W0-1, was collected from beneath the waste-oil UST at a depth of about 10 feet bgs. Based on observations in the field, it was decided to excavate additional soil from three of the four excavation sidewalls.

<u>March 14, 1989</u>: Four trenches were installed to assess the limits of additional soil excavation needed. Four soil samples were then collected at depths of approximately 10 feet bgs. The soil analytical results were as follows:

- In the fuel UST excavation, TPHg concentrations ranged from 24 ppm to 150 ppm.
- A sample collected adjacent to the existing station building indicated that TPHg was present at a concentration of 3,500 ppm.
- The soil sample collected after excavating 2 feet of sidewall toward the station building indicated that TPHg was present at a concentration of 100 ppm.
- Soil sample (SW-2) contained TPHg at a concentration of 390 ppm.
- The soil sample collected from the waste-oil UST excavation (WO-1) contained total oil and grease (TOG) at a concentration of 280 ppm. A side wall sample, SW-7 collected after excavating 14 feet of sidewall contained TOG at a concentration of 41 ppm.

The analytical results of the water sample (W1) collected from the waste-oil/fuel UST excavation contained TPHg at a concentration of 19,000 parts per billion (ppb) and benzene at a concentration of 230 ppb.

<u>March 23, 1989</u>: KEI returned to the site for pipe trench soil sampling. Six soil samples, labeled P1 through P6, were collected from beneath the product lines at depths of approximately 3 to 3.5 feet below grade. The analytical results of the soil samples P1 through P6 collected from the pipe trenches indicated concentrations of TPHg ranging from 1.1 ppm to 6.8 ppm.



The fuel UST pit and the waste-oil UST pit were over-excavated in order to remove hydrocarbon-impacted soil. The majority of the hydrocarbon-impacted soil appeared to have been removed from the site, except for the capillary fringe in the vicinity of the former UST pit and the building.

<u>May 24, 1989</u>: Four two-inch diameter monitoring wells, MW-1 through MW-4 were installed at the site. The four wells were installed to depths ranging from 24.5 to 25 feet bgs. Ground water was encountered at depths ranging from 11 to 12 feet bgs during drilling.

July 1989: The monitoring and sampling program was initiated.

**February 1990:** Monitoring well MW-2 was destroyed on February 1 in preparation for additional soil excavation in the vicinity of this well. Soil was excavated to a depth of approximately 6 to 12 inches below the level of the groundwater, which was encountered at a depth of about 11.5 feet below grade. After additional excavation, four soil samples were collected from the sidewalls of the excavation, each approximately 6 to 12 inches above ground water. Soil excavation activities were terminated due to the close proximity of the former and new UST excavations and the site's property line.

The analytical results of three soil samples indicated that TPHg was present at concentrations ranging from 140 ppm to 1,100 ppm, while concentrations of total petroleum hydrocarbons as diesel (TPHd) ranged from below the laboratory's indicated reporting limits to 280 ppm. The analytical results also indicated Environmental Protection Agency (EPA) Method 8010 constituents and TOG from each of the four samples were below the laboratory's indicated reporting limits, except in sample SW11A which contained TOG at a concentration of 210 ppm.

Over-excavation in the vicinity of monitoring well MW-2 was completed in April of 1990. Monitoring well MW-2 was then replaced with a new monitoring well (MW-2A) in March 1991.

1991: Due to the regular occurrence of tetrachloroethene (PCE), trichloroethene (TCE) and 1,2-dichlorethane (1,2-DCA) in sampled groundwater, a review of records documenting historic site activities was performed in 1991 to assess whether there were any up-gradient sources contributing to the impacted groundwater at the site. The file review was conducted by KEI at the Regional Water Quality Control Board (RWQCB).

The review focused on three sites with monitoring wells located within a half mile of the station. The Okada property, located at 16109 Ashland Avenue, a former USA Petroleum station located at 15120



Hesperian Boulevard, and Kaufman and Broad, located at 1620 162<sup>nd</sup> Avenue, approximately 1,800 feet east-southeast of the site. The file review is outlined in Delta's *Addendum to Additional Site Assessment Work Plan*, dated April 3, 2009.

<u>December 1992</u>: A file review was conducted at the ACHCSA. Four sites with existing or former USTs were located in the vicinity of the site during the file review. These sites are as follows: 1.) Nayou Properties, 1500 Thrush Avenue; 2.) ABC Auto Repair, 15960 East 14<sup>th</sup> Street; 3. Petsas Property, 16035 East 14<sup>th</sup> Street, and; 4.) SpeeDee Oil Change, 15900 East 14<sup>th</sup> Street.

<u>1991-1993</u>: The California EPA, Department of Toxic Substances Control (DTSC), identified regional chlorinated solvent contamination of the upper aquifer in the San Leandro area.

1993: Based on the results of the site history research, site reconnaissance, and file review, and based upon the fact that no evidence of an on-site solvent source area in the vicinity of monitoring wells MW-3 and MW-4 was found, it was concluded that there was no likely on-site source of the halogenated volatile organic compound (HVOC) impact.

The potential of an off-site HVOC source is further supported by the fact that the highest HVOC concentrations have been reported in samples collected from monitoring wells MW-3 and MW-4, located on the up-gradient side of the site. HVOC concentrations reported in the groundwater samples collected from these monitoring wells are likely coming from a source (E.G. reaching sanitary sewer lines, etc.) up-gradient of the site.

March 1993: Monitoring wells MW-5 and MW-6 were installed on March 9, 1993. These wells were monitored monthly and sampled on a quarterly basis until 1996. Groundwater flow predominantly ranged from southwest to north during the course of the investigation. Chlorinated solvents have consistently been reported in up-gradient wells MW-3 and MW-4, and it appears that the chlorinated solvent impact at the site may be due to an unidentified source (or sources) located up-gradient of the site, or is part of a regional chlorinated solvent plume. The perimeter monitoring wells, MW-5 and MW-6, have historically shown a maximum concentration of 72 micrograms per liter (μg/L) of TPHg and below the laboratory's indicated reporting limits for benzene, toluene, ethylbenzene, and total xylenes (BTEX).

<u>March 1997</u>: An off-site investigation was conducted in March 1997 to assess any impacts in the downgradient direction from monitoring well MW-1. Monitoring well MW-1 is the most down-gradient of the



wells at the site and has historically contained the highest concentrations of petroleum hydrocarbons in groundwater throughout the duration of the site investigation.

Three direct push borings (EB-3, EB-4, and EB-5) were advanced through East 14th Street in a northerly transect from the site. The three borings were each advanced to total depths ranging from 11 to 15 feet below grade. Groundwater was encountered at depths ranging from 10.5 to 15 feet bgs during drilling. No reportable target compounds were identified in either soil or groundwater samples.

<u>1998</u> – A *Case Closure Summary* was prepared by the Alameda County Environmental Protection Department. This document concluded that drinking water wells are not affected. It also documented the maximum contaminant concentrations – before and after cleanup as follows:

Contaminant	Soil (ppm)		Water (ppb)	Water (ppb)				
	Before	After		Before	After			
TPHg	3,500	1,100		19,000	510			
TPHd	ND	6.2		NA	NA			
Benzene	40	8		230	72			
Toluene	280	43		79	ND			
Xylenes	600	230		1,300	17			
Ethyl-benzene	100	37		ND	ND			
Methyl tert-butyl								
ether (MTBE)	NA	NA		NA	390			
TOG	7,700	1,300		NA	NA			
Heavy Metals	NA	NA		NA	NA			
Other HVOC TCE	0.063	ND	TCE	4.4	ND			
			PCE	110	950			
			1,2-					
			DCA	2.8	ND			

The *Case Closure Summary* concluded that "there are no known municipal or residential water wells or surface water bodies within 750 feet down-gradient of the subject site that would be impacted by shallow groundwater from this site".



December 2000: The ACHCSA issued a Case Closure letter dated December 26, 2000.

**2003**: Six groundwater monitoring wells (MW-1, MW-2A, and MW-3 through MW-6) destroyed. Groundwater was at 6-11 feet bgs.

<u>September 2007</u>: Six soil borings (ATC-1 through ATC-6) were advanced in the vicinity of the existing fuel and waste-oil USTs and dispensers on September 25 and 26, 2007. The borings were advanced to total depths of approximately 20 feet bgs (ATC-2, ATC-3, ATC-4, and ATC-5) and 25 feet bgs (ATC-1 and ATC-6). Groundwater was initially encountered at depths ranging from 14 feet bgs to 24 feet bgs during drilling activities.

Groundwater samples were collected from each of the six borings. A duplicate groundwater sample designated as "Duplicate B-1" was collected from boring ATC-1. Photo ionization detector (PID) readings from the screened soil samples ranged from 1.4 ppm to 2,272 ppm. The analytical results from the ATC Investigation are outlined in Delta's *Addendum to Additional Site Assessment Work Plan* dated April 3, 2009.

<u>December 2009</u>: Delta advanced six soil borings (B-1 through B-5, and B-7) to assess the extent of petroleum hydrocarbon impact to the soil and groundwater. The borings were advanced to total depths ranging from 24 to 32 feet bgs. First groundwater was encountered at depths ranging from 21 to 28.5 feet bgs during drilling activities.

Soil and groundwater samples were collected from each of the six borings. PID readings from the screened soil samples ranged from 0.2 ppm to 197 ppm. The analytical results indicated that TPHg was present in the soil at a maximum concentration of 603 mg/kg (B-1 at 12 feet) and in the groundwater at a maximum concentration of 2,110  $\mu$ g/L (B-1). The analytical results from the December 2009 Investigation are outlined in Delta's *Subsurface Soil and Groundwater Investigation Report* dated March 23, 2010.

#### 1.3 Sensitive Receptors

<u>1991</u>: The well survey performed by KEI focused on the area within a one-half mile radius of the subject site, and was based upon data obtained from the Alameda County Flood Control and Water Conservation District. The information revealed the presence of 15 producing wells designated as irrigation wells and had depths ranging from 20 to 440 feet bgs.



The Alameda County Flood Control and Water Conservation District records suggested that the status of many of the irrigation wells is unknown. In the 1991 survey, it was stated that "no producing wells that could possibly influence the groundwater flow direction at the subject site were located". The closest irrigation well (148 feet deep) installed in 1949 was noted in the north corner of East 14<sup>th</sup> Street and 159<sup>th</sup> Avenue.

**2008**: This survey entailed a request to the California Department of Water Resources (DWR) office in Sacramento to provide well log records. DWR well log records were reviewed in order to assess the location of any water-supply wells in the vicinity of the subject site. Using the DWR well logs, a total of five wells had verifiable addresses within a half-mile radius of the site.

Stains and spills have been documented at the adjacent site to the east, SpeeDee Oil Change shop, located at 15900 East 14<sup>th</sup> Street, including staining from leaking automobiles, spills not cleaned up immediately, a spill migrating toward a storm drain inlet, a spill in the driveway not cleaned up, and a spill beneath the waste-oil UST was not appropriately addressed. Moreover, it is documented that solvents were used at this adjacent site in 1993 and based on that site history; it appears that solvents have been used at that site for decades.

#### 2.0 SITE GEOLOGY AND HYDROGEOLOGY

The site is located in the East Bay Plain Subbasin. The subbasin is an alluvial plain bounded by San Pablo bay to the north, the Franciscan Basement rock to the east, and the Niles Cone Groundwater Basin to the south. To the west the subbasin extends beneath the San Francisco Bay. Surface water collected in San Pablo Creek, Wildcat Creek, San Leandro Creek, and San Lorenzo Creek flow westward into the San Francisco and San Pablo bays. The San Francisco Bay is approximately 4 miles west of the site.

Based on soils observed during soil boring and monitoring well installation activities the site, the site is underlain by silty sand, gravelly sand, sandy gravel, gravelly clay, clay, silt, sandy silt, silt with sand, poorly graded sand, and sandy clay. Fine grain material such as clay and silt extend from just below ground surface to depths of 25 feet bgs. Discontinuous layers of sand and gravel appear at depths of approximately 15, 20, and 30 feet bgs. These layers range in thickness from inches to three feet. First encountered groundwater ranges in depth from 16 feet bgs to 28 feet bgs depending on lithology.



Static water levels in the wells are approximately nine to ten feet bgs. Based on depths to first encountered groundwater and static groundwater levels in on-site monitoring wells it appears that groundwater beneath the site is under confined conditions. Cross sections depicting the lithology beneath the site are presented on **Figure 3** and **Figure 4**.

#### 3.0 WELL INSTALLATION ACTIVITIES

#### 3.1 Permitting, Utility Notification, and Borehole Clearance

Before commencing field activities Antea Group prepared a Health and Safety Plan in accordance with state and federal requirements for use during investigation activities. Drilling permits were obtained for the well installation from the Alameda County Public Works Agency (**Appendix A**). Prior to drilling, Underground Service Alert (USA) was notified as required by law and a private utility locator was employed to clear the well boring locations for underground utilities. In addition, an air- knife was used to clear each well boring location to a depth of 5 feet bgs prior to borehole advancement.

#### 3.2 Monitoring Well Installation

On April 5, 2011, Antea Group supervised the installation of four (4) monitoring wells (MW-7 through MW-10). Gregg Drilling and Testing, Inc. (Gregg) under the supervision of an Antea Group geologist installed the monitoring wells using a limited access rig equipped with 8-inch outside diameter hollow-stem augers. Soil samples were collected continuously beginning at a depth of approximately 5 feet bgs and logged using the Unified Soil Classification System (USCS) for lithologic interpretation and field screened for the presence of volatile organic compounds by headspace analysis using a pre-calibrated photo ionization detector (PID). The soil samples were collected using direct push technologies before the installation of the monitoring wells. Three soil samples from each boring were retained for laboratory analysis. The samples were chosen based on PID readings, changes in lithology, groundwater elevation, and the total depth of the borings.

The groundwater monitoring well casing was installed in the well borings while the augers were in place. The monitoring wells consist of 2-inch diameter schedule 40 poly vinyl chloride (PVC) well casing with a screen interval that was determined in the field based on the encountered lithology, depth to first encountered groundwater (if observed), and depth to static groundwater. Monitoring well MW-7 has a 10 foot screen interval, from 9 feet bgs to 19 feet bgs, monitoring well MW-8 has an 11 foot screen interval, from 9 feet bgs, monitoring well MW-9 has a 15 foot screen interval, from 9 feet



bgs to 24 feet bgs, and monitoring well MW-10 has a 10 foot screen interval, from 10 feet bgs to 20 feet bgs. The perforation size in the screen interval is 0.020-inch. A sand pack consisting of RMC Lonestar #3 Sand was installed into the annular space and extends approximately one (1) foot above the top of the screen interval.

A one (1) foot thick bentonite seal was placed on top of the sand pack. The remainder of the annular space is filled with neat cement and the monitoring wells are fitted with a locking cap and encased in a traffic-rated protective vault placed at existing ground level.

Department of Water Resources (DWR) Well Completion Reports were prepared for each of the four (4) monitoring wells. Copies of the DWR Well Completion Reports are presented as **Appendix B**.

#### 3.3 Soil Sampling

Soil samples retained for analysis were analyzed for TPHg by the California LUFT Method, BTEX, MTBE, tertiary amyl methyl ether (TAME), di-isopropyl ether (DIPE), ethyl tertiary-butyl ether (ETBE), tertiary butyl alcohol (TBA), 1,2-DCA, ethylene dibromide (EDB), and ethanol by EPA Method 8260; residual range organics (RRO) by EPA Method 8015B; and total lead by EPA Method 6010. Additionally, the soil samples collected from the monitoring well MW-10 boring were also analyzed for diesel range organics (DRO) by EPA Method 8015B. The soil analytical results are presented in **Table 1**.

#### 3.4 Well Development, Monitoring, and Sampling

The monitoring wells were developed a minimum of 72 hours after construction. A minimum of 10 casing volumes of groundwater were removed from each monitoring well during the development process. Copies of the well development logs are presented as **Appendix D**.

The monitoring wells were sampled on April 18, 2011 and the results of that sampling event are described in Section 4.0.

Groundwater samples collected for analysis from each monitoring well was analyzed for TPHg by the California LUFT Method, BTEX, MTBE, TAME, DIPE, ETBE, TBA, 1,2-DCA, EDB, and ethanol by EPA Method 8260.



#### 3.5 Wellhead Survey

Following the completion of the new monitoring wells, a California licensed surveyor surveyed the northing and easting of the monitoring wells using Datum NAD 83. The monitoring well elevation was surveyed relative to mean sea level, with an accuracy of +/- 0.01 foot. A global positioning system (GPS) was also used to survey the latitude and longitude of each monitoring well to be uploaded into California's Geo Tracker database system. The survey of the monitoring well locations is to sub-meter accuracy.

#### 3.6 Disposal of Drill Cuttings and Wastewater

Drill cuttings and well purge water generated during monitoring well installation and development activities was placed into properly labeled 55-gallon Department of Transportation (DOT) approved steel drums and are being temporarily stored on the station property. Samples of the drill cuttings and well purge water were collected, properly labeled, placed on ice, and submitted to a California-certified laboratory for analysis of TPHg by the CA LUFT Method, BTEX and MTBE by EPA Method 8260, and total lead by EPA Method 6010. Chain-of-custody documentation accompanied the samples during transportation to the laboratory. Subsequent to receiving the laboratory analytical results, the drummed drill cuttings and well purge water will be profiled, transported, and disposed of at an approved facility.

#### 4.0 GROUNDWATER MONITORING ACTIVITIES

#### 4.1 Groundwater Monitoring

For the April 2011 groundwater monitoring and sampling event, four wells were gauged, purged, and sampled by Blaine Tech per standard sampling protocol (**Appendix E**). Copies of Blaine Tech's field data sheets are presented as **Appendix F**. The recent gauging and sampling data are summarized below and in **Table 2**.

Well gauging and sampling date:	April 18, 2011
Wells gauged:	MW-7 through MW-10
Wells sampled:	MW-7 through MW-10
Purge method:	3 well casing volumes via electric, submersible pump
Sample collection method:	Disposable bailers



Groundwater parameters measured (Attachment C):	Temperature, pH, Conductivity, Oxidation-reduction potential (ORP), Turbidity, Dissolved Oxygen (DO)
Wells with measurable LNAPL:	None
Current depth to water range (ft below top of casing (BTOC)):	Min: 9.40 (MW-7 and MW-8) Max: 10.55 (MW-10)
Current groundwater elevation range (ft):	Min: 25.20 (MW-7) Max: 25.54 (MW-9)
Change in water depths from previous event (average change for all gauged wells):	Not Applicable
Groundwater flow direction and gradient in foot per foot (ft/ft):	North-Northwest at 0.003 ft/ft

#### 4.1.1 Groundwater Flow Gradient and Direction

With the recent installation of four wells, this site now has four on-site monitoring wells. Monitoring wells MW-7 through MW-10 will be sampled on a quarterly basis. The second quarter 2011 groundwater monitoring and sampling event was performed by Blaine Tech on April 18, 2011. The average groundwater elevation was 25.41 feet above mean sea level. Depth to groundwater in the site monitoring wells ranged from 9.40 feet (MW-7 and MW-8) to 10.55 feet (MW-10) BTOC during the current event. The groundwater flow direction and gradient were interpreted to be to the north-northwest at 0.003 ft/ft during the current event. A groundwater contour map is presented on **Figure 5**.

#### 4.1.2 Groundwater Quality Data

Groundwater samples collected during the second quarter 2011 were submitted with chain-of-custody documentation to Pace Analytical Services, Inc. (Pace), a state of California Environmental Laboratory Accreditation Program (ELAP) certified laboratory (Certification No. 01153CA). The complete analytical report and Antea Group's laboratory data validation checklist is presented as **Appendix C**. Groundwater samples were analyzed for one or more of the following:

- Total petroleum hydrocarbons as gasoline by CA LUFT Method;
- BTEX, MTBE, TBA, DIPE, ETBE, TAME, EDB, 1,2-DCA, and ethanol by EPA Method 8260;

Groundwater analytical results are presented in **Tables 2** (current) and **Tables 3** (historical grab samples). The following ranges of contaminant concentrations were reported in the specified site wells groundwater samples collected on April 18, 2011. Only the reported contaminants are listed in the table below.



Constituents	Number of Reported Samples Above LRL of the Samples Collected	Minimum Reported Concentration, in μg/L (Sample ID)	Maximum Reported Concentration, in μg/L (Sample ID)
TPHg	4 of 4	208 (MW-9)	2,420 (MW-7)
Benzene	2 of 4	1.4 (MW-8)	22.4 (MW-7)
Toluene	2 of 4	0.75 (MW-8)	12.4 (MW-7)
Ethylbenzene	3 of 4	2.8 (MW-8)	11.3 (MW-7)
Total Xylenes	3 of 4	14.2 (MW-8)	449 (MW-7)
MTBE	4 of 4	1.6 (MW-9)	152 (MW-7)
TBA	1 of 4	5.7 (MW-7)	5.7 (MW-7)

**Explanations:** 

μg/L = Micrograms per liter

LRL = Laboratory reporting limit

#### 4.2 Waste Disposal Summary

Approximately 26 gallons of waste water were generated during well purging/sampling and equipment cleaning during the second quarter event. The waste water was transported to Blaine Tech's bulk facility in San Jose, California. After the batching process, the wastewater was transported to Seaport Environmental in Redwood City, California for disposal. A copy of the waste manifest is presented as **Appendix G.** 

#### 4.3 Quality Assurance / Quality Control

Antea Group's QA/QC measures included a detailed QA/QC data validation check on the Pace Laboratory analytical results for the April 2011 sampling event. Antea Group's laboratory data validation checklist and the Pace laboratory report are presented as **Appendix C**.

Laboratory QA/QC Performed:	Yes (validated by Antea Group)
Laboratory Data Qualifiers:	Yes – two qualifiers*
Are the data valid for their intended purpose?	Yes, the data are valid

<sup>\*1</sup>n – The TPHg result for this sample did not match the laboratory standard for gasoline. This is likely due to the presence of tetrachoroethene in the sample.

Based on a review of the laboratory's analytical report, including their QA/QC procedures and those implemented by Antea Group, we conclude that the laboratory data obtained during this groundwater sampling event are valid for their intended purpose.

<sup>\*</sup>D6 –The relative percent difference between the sample and sample duplicate exceeded laboratory control limits.



#### 5.0 RESULTS OF THE INVESTIGATION

#### 5.1 Soil Analytical Results

Analytical results of soil samples collected during the monitoring well installation reported TPHg concentrations ranging from 0.68 milligrams per kilogram (mg/kg) (MW-8d13) to 289 mg/kg (MW-7d9), benzene concentrations ranging from 0.016 mg/kg (MW-8d13) to 0.061 mg/kg (MW-7d9), toluene concentrations ranging from 0.034 mg/kg (MW-7d9) to 0.037 mg/kg (MW-7d16), ethylbenzene concentrations ranging from 0.0039 mg/kg (MW-10d15) to 4.3 mg/kg (MW-7d9), total xylenes concentrations ranging from 0.012 mg/kg (MW-10d15) to 8.4 mg/kg (MW-7d9), MTBE concentrations ranging from 0.013 mg/kg (MW-7d16) to 0.086 mg/kg (MW-8d9), TBA concentrations ranging from 0.018 mg/kg (MW-7d9) to 0.023 mg/kg (MW-8d9), RRO concentrations ranging from 20.7 mg/kg (MW-7d9) to 852 mg/kg (MW-8d13), and lead concentrations ranging from 5.3 mg/kg (MW-9d2) to 15.7 mg/kg (MW-8d13). The soil analytical results are presented in **Table 1**. A copy of the laboratory report, chain-of-custody documentation, and a laboratory validation sheet are presented as **Appendix C**.

#### **5.2** Groundwater Analytical Results

Analytical results of groundwater samples collected during the second quarter 2011 groundwater monitoring event reported TPHg concentrations ranging from 208  $\mu$ g/L (MW-9) to 2,420  $\mu$ g/L (MW-7), benzene concentrations ranging from 1.4  $\mu$ g/L (MW-8) to 22.4  $\mu$ g/L (MW-7), toluene concentrations ranging from 0.75  $\mu$ g/L (MW-8) to 12.4  $\mu$ g/L (MW-7), ethylbenzene concentrations from 2.8  $\mu$ g/L (MW-8) to 11.3  $\mu$ g/L (MW-7), total xylenes concentrations ranging from 14.2  $\mu$ g/L (MW-8) to 449  $\mu$ g/L (MW-7), MTBE concentrations ranging from 1.6  $\mu$ g/L (MW-9) to 152  $\mu$ g/L (MW-10), and a TBA concentration of 5.7  $\mu$ g/L in monitoring well MW-7. The groundwater analytical results are presented in **Table 2** and **Table 3**. A copy of the laboratory report, chain-of-custody documentation, and a laboratory validation check lists are presented as **Appendix C**. Isonconcentration maps for TPHg, benzene, and MTBE are presented on **Figure 6**, **Figure 7**, and **Figure 8**, respectively.

#### 6.0 CONCLUSIONS AND RECOMMENDATIONS

Based on the results of soil samples taken during the monitoring well installation activities and the groundwater samples collected on April 18, 2011 it appears that site conditions have remained consistent with conditions present when the site was granted closure in 2000. This appears to indicate that there has not been a new release since the site was granted closure. The case closure documents from 2000 are presented as **Appendix H**. It is Antea Group's recommendation to conduct groundwater



monitoring and sampling activities at the site for no less than two quarters to better assess if there has been a new release at the site.

#### 7.0 REMARKS

The recommendations contained in this report represent Antea USA, Inc.'s professional opinions based upon the currently available information and are arrived at in accordance with currently accepted professional standards. This report is based upon a specific scope of work requested by the client. The contract between Antea USA, Inc. and its client outlines the scope of work, and only those tasks specifically authorized by that contract or outlined in this report were performed. This report is intended only for the use of Antea USA, Inc.'s client and anyone else specifically identified in writing by Antea USA, Inc. as a user of this report. Antea USA, Inc. will not and cannot be liable for unauthorized reliance by any other third party. Other than as contained in this paragraph, Antea USA, Inc. makes no express or implied warranty as to the contents of this report.

Prepared by:

Edward T. Weyrens, G.I.T.

Staff Geologist

Information, conclusions, and recommendations provided by Antea Group in this document regarding the site have been prepared under the supervision of and reviewed by the licensed professional whose signature appears below.

Licensed Approver:

DENNIS SHANNON DETTLOFF

DETTLOFF No. 7480

OF CALLED

Date: 7-5-11

Dennis S. Dettloff, P.G.

Project Manager

California Registered Professional Geologist No. 7480




### **Figures**

igure 1	Site Location Map
igure 2	Site Plan
igure 3	Cross Section A-A'
igure 4	Cross Section B-B'
igure 5	Groundwater Elevation Contour Map – April 18, 2011
igure 6	Dissolved Phase TPHg Isoconcentration Map – April 18, 2011
igure 7	Dissolved Phase Benzene Isoconcentration Map – April18, 2011
igure 8	Dissolved Phase MTBE Isoconcentration Map – April 18, 2011









### FIGURE 1 SITE LOCATION MAP


76 SERVICE STATION NO. 6277 15803 EAST 14TH STREET SAN LEANDRO, CALIFORNIA


PROJECT NO. 14256277	DRAWN BY JH 05/13/11	
FILE NO. 6277-SiteLocator	PREPARED BY EW	
REVISION NO.	REVIEWED BY	$\neg$






















### **Tables**

Table 1	Historical Soil Analytical Results
Table 2	Current Groundwater Gauging and Analytical Data
Table 3	Historical Groundwater Analytical Data

#### HISTORICAL SOIL ANALYTICAL RESULTS 76 Service Station No. 6277 15803 East 14th Street, San Leandro, CA

Sample ID	Date	Sample	TPHg	Benzene	Toluene	Ethyl-	Total Xylenes	MTBE	TBA	TAME	DIPE	ETBE	Ethanol	1,2-DCA	EDB	DRO	RRO	Lead
		Depth (feet)	(mg/kg)	(mg/kg)	(mg/kg)	benzene (mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)
ATC 2007		(1001)	(6/6/	(6/6/	(6/6/	(6/6/	\6/6/	(6/6/	(6/6/	(6/6/	(6/6/	(6/6/	(8787	(8787	(8)	(8787	(6/6/	(8)
ATC-1d12.0	9/25/2007	12	100	<0.005	<0.005	0.016	0.029	0.024	0.19	<0.001	<0.001	<0.001	<0.10			57		8.15
ATC-1d20.0	9/25/2007	20	<1.0	<0.005	<0.005	<0.005	<0.005	<0.0005	<0.10	<0.001	<0.001	<0.001	<0.10			<12		4.57
ATC-2d12.0	9/25/2007	12	560	<0.62	<0.62	8.8	48	0.83	<0.10	<0.001	< 0.001	<0.001	<0.10		-	51		7.62
ATC-2d20.0	9/25/2007	20	<1.0	<0.005	<0.005	< 0.005	< 0.005	0.011	<0.10	<0.001	< 0.001	<0.001	<0.10			<12		3.57
ATC-3d12.0	9/25/2007	12	27	< 0.63	< 0.63	0.82	2.93	<0.0005	<0.10	< 0.001	< 0.001	< 0.001	<0.10			310		7.71
ATC-3d18.0	9/25/2007	18	<1.0	<0.005	<0.005	<0.005	< 0.005	<0.0005	<0.10	<0.001	<0.001	<0.001	<0.10			18	-	8.21
ATC-4d5.0	9/26/2007	5	1,000	<0.63	<0.63	11	43	<0.0005	<0.10	<0.001	<0.001	<0.001	<0.10			170		6.48
ATC-4d20.0	9/26/2007	20	<1.0	<0.005	<0.005	<0.005	<0.005	0.015	<0.10	<0.001	<0.001	<0.001	<0.10			<12		2.85
ATC-5d5.0	9/26/2007	5	220	<0.62	1.2	6.2	25.2	<0.0005	<0.10	<0.001	<0.001	<0.001	<0.10			<12		6.27
ATC-5d20.0	9/26/2007	20	<1.0	<0.005	<0.005	<0.005	<0.005	<0.0005	<0.10	<0.001	<0.001	<0.001	<0.10			<14		2.59
ATC-6d12.0	9/25/2007	12	59	<0.005	<0.005	<0.005	<0.005	<0.0005	<0.10	<0.001	<0.001	<0.001	<0.10			<12		9.37
ATC-6d15.0	9/25/2007	15	<1.0	<0.005	<0.005	<0.005	<0.005	<0.0005	<0.10	<0.001	<0.001	<0.001	<0.10			<12		5.27
Delta 2009																		
B-1@12	12/29/2009	12	603	0.71	12.3	19	103	0.013	0.021	<0.0029	<0.0029	<0.0029		<0.0029	-	16.3	55.2	7
B-1@15	12/29/2009	15	0.94	<0.0028	0.023	0.027	0.16	0.017	<0.014	<0.0028	<0.0028	<0.0028		<0.0028	-	<2.0	<9.9	6.2
B-1@20	12/29/2009	20	<0.25	<0.0030	<0.0030	<0.0030	<0.0059	0.021	<0.015	<0.0030	<0.0030	<0.0030		<0.0030	-	2.2	<10	<4.7
B-1@24	12/29/2009	24	<0.23	<0.0027	<0.0027	<0.0027	<0.0054	0.0087	<0.014	<0.0027	<0.0027	<0.0027		<0.0027	-	<2.0	<10	<4.8
B-1@30	12/29/2009	30	<0.25	<0.0030	<0.0030	<0.0030	<0.0060	<0.0030	<0.015	<0.0030	<0.0030	<0.0030		<0.0030	-	<2.0 9.2	<9.8 <10	<4.3 <b>10.1</b>
B-2@5 B-2@10	12/29/2009	5 10	2.8	0.1	<0.0027 <0.0030	0.488	0.22	0.058	0.034	<0.0027 <0.0030	<0.0027	<0.0027 <0.0030		<0.0027 <0.0030		9.2	<9.9	6.3
B-2@10	12/29/2009 12/29/2009	20	1.5 <0.24	<b>0.073</b> <0.0028	<0.0030	<0.0028	<0.0060 <0.0057	<b>0.13</b> <0.0028	<0.014	<0.0030	<0.0030 <0.0028	<0.0030		<0.0030	-	<2.0	<10	5.5
B-2@24	12/29/2009	24	42.2	0.0028	<0.0028	0.0028	2.3	0.0028	0.014	<0.0028	<0.0028	<0.0028		<0.0028		27.2	79.8	7
B-2@28	12/29/2009	28	<0.23	<0.0027	<0.0028	<0.0028	<0.0056	<0.0028	<0.017	<0.0028	<0.0028	<0.0028		<0.0028		<2.0	<9.8	4.1
B-3@5	12/29/2009	5	<0.24	<0.0028	<0.0028	<0.0028	<0.0057	0.043	0.042	<0.0028	<0.0028	<0.0028		<0.0028		2.2	<9.9	19.7
B-3@10	12/29/2009	10	<0.24	<0.0023	<0.0023	<0.0023	<0.0057	0.043	0.042	<0.0023	<0.0023	<0.0023		<0.0023		2	<10	7.6
B-3@15	12/29/2009	15	<0.22	<0.0026	<0.0026	<0.0026	<0.0052	<0.0026	<0.013	<0.0026	<0.0026	<0.0026		<0.0026		<2.0	<9.9	5.7
B-3@20.5	12/29/2009	20.5	<0.25	<0.0030	<0.0030	<0.0030	<0.0060	0.0081	<0.015	<0.0030	<0.0030	<0.0030		<0.0030		2.2	18.7	5.8
B-3@24.5	12/29/2009	24.5	<0.25	<0.0030	<0.0030	<0.0030	<0.0059	0.0071	<0.015	<0.0030	< 0.0030	<0.0030		<0.0030		11.1	174	8.2
B-3@28	12/29/2009	28	<0.23	<0.0027	<0.0027	<0.0027	< 0.0055	<0.0027	< 0.014	<0.0027	<0.0027	<0.0027		<0.0027		<2.0	<9.8	4.9
B-4@5	12/30/2009	5	<0.25	<0.0030	< 0.0030	<0.0030	<0.0060	<0.0030	< 0.015	<0.0030	< 0.0030	<0.0030		<0.0030		22.5	379	37.9
B-4@10	12/30/2009	10	<0.25	< 0.0030	<0.0030	< 0.0030	< 0.0059	<0.0030	< 0.015	< 0.0030	< 0.0030	<0.0030		< 0.0030		4	51.2	14.3
B-4@20	12/30/2009	20	<0.25	<0.0029	<0.0029	<0.0029	< 0.0059	<0.0029	< 0.015	<0.0029	<0.0029	<0.0029		<0.0029		<2.0	<9.9	4.9
B-4@28	12/30/2009	28	<0.24	< 0.0029	<0.0029	< 0.0029	<0.0058	< 0.0029	< 0.015	< 0.0029	< 0.0029	< 0.0029		< 0.0029		<2.0	<9.9	5.5
B-5@5	12/30/2009	5	<0.25	<0.0030	<0.0030	<0.0030	< 0.0059	<0.0030	< 0.015	<0.0030	< 0.0030	<0.0030		<0.0030		3.6	40.1	15.4
B-5@12	12/30/2009	12	<0.24	< 0.0029	0.0037	<0.0029	<0.0058	<0.0029	< 0.014	<0.0029	< 0.0029	<0.0029		<0.0029		11.6	247	8.4
B-5@15	12/30/2009	15	<0.25	<0.0029	<0.0029	<0.0029	< 0.0059	<0.0029	<0.015	<0.0029	<0.0029	<0.0029		<0.0029		<2.0	<9.9	6.1
B-5@20	12/30/2009	20	<0.23	<0.0028	<0.0028	<0.0028	<0.0056	<0.0028	<0.014	<0.0028	<0.0028	<0.0028		<0.0028		<2.0	<10	6.5
B-5@25	12/30/2009	25	<0.25	<0.0030	<0.0030	<0.0030	<0.0059	<0.0030	<0.015	<0.0030	<0.0030	<0.0030		<0.0030	-	<2.0	<10	5.2
B-5@28	12/30/2009	28	<0.24	<0.0029	<0.0029	<0.0029	<0.0058	<0.0029	<0.015	<0.0029	<0.0029	<0.0029		<0.0029		2.5	23.5	6.3
B-7@5	12/30/2009	5	<0.25	<0.0029	<0.0029	<0.0029	<0.0059	<0.0029	<0.015	<0.0029	<0.0029	<0.0029		<0.0029	-	63.7	582	22.1
B-7@10	12/30/2009	10	1.3	0.018	<0.0030	0.0035	<0.0060	0.21	0.093	<0.0030	<0.0030	<0.0030		<0.0030	-	5.7	<9.8	7.3
B-7@20	12/30/2009	20	<0.25	<0.0030	<0.0030	<0.0030	<0.0059	0.014	<0.015	<0.0030	<0.0030	<0.0030		<0.0030		<2.0	<9.9	5.8
B-7@24	12/30/2009	24	<0.22	<0.0027	<0.0027	<0.0027	<0.0053	<0.0027	<0.013	<0.0027	<0.0027	<0.0027		<0.0027		<2.0	<10	<4.5
Antea Group 201			1 200	2.054	2.224			2 2 2 2	2 242	0.0024	-0.0024	-0.0024	-0.22	-0.0024	-0.0024			
MW-7d9	4/5/2011	9	289	0.061	0.034	4.3	8.4	0.042	0.018	<0.0024	<0.0024 <0.0024	<0.0024 <0.0024	<0.32 <0.32	<0.0024 <0.0024	<0.0024 <0.0024		20.7 788	8.9
MW-7d16	4/5/2011	16	0.9 M1	0.017	0.037	0.054	0.24	0.013	<0.012	<0.0024	<0.0024	<0.0024	<0.32	<0.0024	<0.0024		<b>788</b> <9.9	13.9 6.3
MW-7d20 MW-8d9	4/5/2011 4/5/2011	20 9	<0.24 <b>0.75</b>	<0.0029 <b>0.02</b>	<0.0029 <0.003	<0.0029 <0.003	<0.0087 <0.0089	0.019 0.086	<0.015 <b>0.023</b>	<0.0029 <0.003	<0.0029	<0.0029	<0.39	<0.0029	<0.0029		<9.9	9.9
MW-8d13	4/5/2011	13	0.75	0.02	<0.003	<0.003 <b>0.024</b>	0.06	0.086	<0.014	<0.003	<0.003	<0.003	<0.37	<0.003	<0.003		852	15.7
MW-8d20	4/5/2011	20	<0.23	<0.0023	<0.0028	<0.0023	<0.007	<0.0023	<0.014	<0.0028	<0.0028	<0.0028	<0.31	<0.0028	<0.0028		<10	<4.1
MW-9d8	4/5/2011	8	<0.23	<0.0023	<0.0023	<0.0025	<0.007	<0.0023	<0.012	<0.0023	<0.0023	<0.0023	<0.35	<0.0023	<0.0023		<9.7	8.9
MW-9d20	4/5/2011	20	<0.24	<0.0028	<0.0028	<0.0028	<0.0078	<0.0028	<0.013	<0.0028	<0.0028	<0.0028	<0.38	<0.0028	<0.0028		<9.8	5.3
MW-9d24	4/5/2011	24	<0.24	<0.0028	<0.0028	<0.0028	<0.0083	<0.0028	<0.014	<0.0028	<0.0027	<0.0027	<0.36	<0.0027	<0.0027		<9.9	6.4
MW-10d10	4/5/2011	10	<0.21	<0.0027	<0.0027	<0.0027	<0.0032	0.028	<0.014	<0.0027	<0.0027	<0.0027	<0.33	<0.0027	<0.0027	<2.0	<10	8.5
MW-10d15	4/5/2011	15	<0.21	<0.0023	<0.0025	0.0023	0.012	<0.0026	<0.012	<0.0023	<0.0025	<0.0025	<0.34	<0.0025	<0.0023	<1.9	<9.7	6.1
MW-10d13	4/5/2011	20	<0.22	<0.0026	<0.0026	<0.0035	<0.0077	<0.0026	<0.013	<0.0026	<0.0026	<0.0026	<0.34	<0.0026	<0.0026	<2.0	<9.9	5.8
Notes:	., 5, 2011	0		-0.3020	-0.5020	-0.3020	.0.0077	.0.3020		.0.3020							2.0	

total petroleum hydrocarbons as gasoline by CA LUFT

benzene, toluene, ethyl-benzene, total xylenes by EPA Method 8260 methyl tertiary butyl ether by EPA Method 8260

Notes: TPHg= BTEX = MTBE = TBA = tert butyl alcohol by EPA Method 8260 TAME = tert amyl methyl ether by EPA Method 8260 DIPE = ETBE = Diisopropyl ether by EPA Method 8260 Ethyl-tert-butyl-ether by EPA Method 8260 1,2-DCA = 1,2-Dichloroethane by EPA Method 8260 EDB = DRO = RRO = M1 = mg/kg = 1,2-Dibromoethane by EPA Method 8260 Diesel range organics by EPA Method 8015

Residual range organics by EPA Method 8015 Matrix Spike recovery exceeded QC limits. Batch accepted based on laboratory control sample recovery.

milligrams per kilogram

Below the laboratory's indicated reporting limit Above the laboratory's indicated reporting limit

Not analyzed

US Environmental Protection Agency

#### Table 2

#### CURRENT GROUNDWATER GAUGING AND ANALYTICAL DATA

#### 76 Service Station No. 6277 15803 EAST 14TH ST SAN LEANDRO, CALIFORNIA

Well I.D.	Date	GROUNDWATER GAUGING DATA					GROUNDWATER ANALYTICAL DATA											
		TOC Elevation (ft)	Depth to Water (ft)		Water Elevation* (ft)	TPHg (ug/L)	Benzene (ug/L)	Toluene (ug/L)	Ethylbenzene (ug/L)	Total Xylenes (ug/L)	MTBE (ug/L)	TBA (ug/L)	Ethanol (ug/L)	DIPE (ug/L)	ETBE (ug/L)	TAME (ug/L)	1,2- Dibromoethane (EDB) (ug/L)	1,2- Dichloroethane (ug/L)
MW-7	4/18/2011	34.60	9.40	NP	25.20	2420	22.4	12.4	11.3	449	152	5.7	<250	<0.50	< 0.50	<0.50	<1.0	<1.0
MW-8	4/18/2011	34.85	9.40	NP	25.45	439	1.4	0.75	2.8	14.2	28.3	<5.0	<250	<0.50	<0.50	<0.50	<1.0	<1.0
MW-9	4/18/2011	35.09	9.55	NP	25.54	208 1n	<0.50	<0.50	<0.50	<1.5	1.6	<5.0	<250	<0.50	<0.50	<0.50	<1.0	<1.0
MW-10	4/18/2011	36.00	10.55	NP	25.45	513	<0.50	<0.50	6.9	40.0	14.9	<5.0	<250	<0.50	<0.50	<0.50	<1.0	<1.0

Gauging Notes:

TOC - Top of Casing

ft - Feet

NP - LNAPL not present

LNAPL - Light non-aqueous phase liquid

\* - Corrected for LNAPL if present (assumes LNAPL specific gravity = 0.75)

-- - No information available

Analytical Notes:

**Bold** - Above laboratory's indicated reporting limit < - Below laboratory's indicated reporting limit

ug/L - micrograms/liter

TPHg- Total petroleum hydrocarbons as gasoline

MTBE- Methyl tertiary-butyl ether

TBA- Tertiary-butyl alcohol

DIPE- Di-isopropyl ether

ETBE- Ethyl tertiary-butyl ether

TAME- Tertiary-amyl methyl ether

1n - The TPHg result for this sample did not match the laboratory standard for gasoline. This is likely due to the presence of tetrachloroethene in the sample

Table 3

#### HISTORICAL GROUNDWATER ANALYTICAL DATA

#### 76 Service Station No. 6277 15803 East 14th Street, San Leandro, California

Sample ID	Date	TPHg	DRO	Benzene	Toluene	Ethyl-benzene	<b>Total Xylenes</b>	MTBE	TBA	TAME	DIPE	ETBE	Ethanol	1,2-DCA	EDB
		(μg/L)	(μg/L)	(μg/L)	(µg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)
ATC 2007															
ATC-1	9/25/2007	140	15,000	<5.0	<5.0	<5.0	7	7	<10	<0.8	<0.8	<0.8	<50	<1.0	
ATC-2	9/25/2007	860	5,200	39	<5.0	27	117	210	<10	<0.8	<0.8	<0.8	<50	<1.0	
ATC-3	9/25/2007	3,700	8,100	<5.0	<5.0	160	630	<0.5	<10	<0.8	<0.8	<0.8	<50	<1.0	
ATC-4	9/26/2007	6,400	1,900	60	120	300	1,040	37	<10	<0.8	<0.8	<0.8	<50	<1.0	
ATC-5	9/26/2007	2,500	810	33	64	110	400	6	<10	<0.8	<0.8	<0.8	<50	<1.0	
ATC-6	9/26/2007	93	910	<5.0	<5.0	<5.0	<5.0	<0.5	<10	<0.8	<0.8	<0.8	<50	<1.0	
Delta 2009															
B-1	12/29/2009	2,110	494	86.9	56	114	357	80.2	<5.0	<1.0	<1.0	<1.0			
B-2	12/29/2009	858	372	25	<1.0	26.9	47.7	7.3	<5.0	<1.0	<1.0	<1.0			
B-3	12/29/2009	254	311	<1.0	<1.0	1.2	3.2	5.8	<5.0	<1.0	<1.0	<1.0			
B-4	12/30/2009	158	411	<1.0	<1.0	<1.0	<3.0	2	<5.0	<1.0	<1.0	<1.0			
B-5	12/30/2009	104	188	<1.0	<1.0	<1.0	<3.0	<1.0	<5.0	<1.0	<1.0	<1.0			
B-7	12/30/2009	1,340	479	4.7	6.9	61.1	284	59.5	<5.0	<1.0	<1.0	<1.0			
Antea Group 2011															
MW-7	4/18/2011	2,420		22.4	12.4	11.3	449	152	5.7	<0.50	<0.50	<0.50	<250	<1.0	<1.0
MW-8	4/18/2011	439		1.4	0.75	2.8	14.2	28.3	<5.0	<0.50	<0.50	<0.50	<250	<10	<1.0
MW-9	4/18/2011	208		<0.50	<0.50	<0.50	<1.5	1.6	<5.0	<0.50	<0.50	<0.50	<250	<1.0	<1.0
MW-10	4/18/2011	513		< 0.50	< 0.50	6.9	40	14.9	<5.0	< 0.50	< 0.50	< 0.50	<250	<1.0	<1.0

#### Notes:

TPHg = total petroleum hydrocarbons as gasoline by CA LUFT

DRO = Diesel range organics by EPA Method 8015B

BTEX = benzene, toluene, ethyl-benzene, total xylenes by EPA Method 8260

MTBE = Methyl t-butyl Ether by EPA Method 8260 TBA = tert butyl alcohol by EPA Method 8260 TAME = Tert-amylmethyl ether by EPA Method 8260 DIPE = Diisopropyl ether by EPA Method 8260 ETBE = Ethyl-tert-butyl-ether by EPA Method 8260 1,2-DCA = 1,2-Dichloroethane by EPA Method 8260 EDB = 1,2-Dibromoethane by EPA Method 8260 μg/L = micrograms per liter

< = Below the laboratory's indicated reporting limit Bold = Above the laboratory's indicated reporting limit

EPA = US Environmental Protection Agency

- = Not analyzed



### Appendix A

Well Installation Permit

#### Alameda County Public Works Agency - Water Resources Well Permit



399 Elmhurst Street Hayward, CA 94544-1395 Telephone: (510)670-6633 Fax:(510)782-1939

Application Approved on: 03/16/2011 By jamesy

Permit Numbers: W2011-0153 to W2011-0156

Permits Valid from 04/04/2011 to 04/06/2011

City of Project Site:San Leandro

Application Id: Site Location:

15803 E 14th St. San Leandro, CA

Project Start Date:

03/28/2011

Completion Date:03/30/2011

Assigned Inspector:

Contact Vicky Hamlin at (510) 670-5443 or vickyh@acpwa.org

1299779690663

Extension End Date: 04/06/2011

Extension Count:

Extension Start Date: 04/04/2011

Extended By: vickyh1

Applicant:

Antea Group - Ed Weyrens

Phone: 916-288-0154

Property Owner:

11050 White Rock Rd, Ste 110, Rancho Cordova, CA 95670

Platinum Energy

Phone: 818-206-5704

Client:

30343 Canwood St, Ste 200, Agoura Hills, CA 91301 \*\* same as Property Owner \*\*

Total Due:

\$1588.00

Receipt Number: WR2011-0072

**Total Amount Paid:** 

\$1588.00

Payer Name : Antea Group

Paid By: CHECK

PAID IN FULL

#### Works Requesting Permits:

Well Construction-Monitoring-Monitoring - 4 Wells

Driller: Gregg Drilling - Lic #: 485165 - Method: hstem

Work Total: \$1588.00

#### Specifications

Permit #	Issued Date	Expire Date	Owner Well	Hole Diam.	Casing Diam.	Seal Depth	Max. Depth
W2011- 0153	03/16/2011	06/26/2011	MW10	8.00 in.	2.00 in,	13.00 ft	25.00 ft
W2011- 0154	03/16/2011	06/26/2011	MW7	8.00 in.	2.00 in.	13.00 ft	25.00 ft
W2011- 0155	03/16/2011	06/26/2011	MW8	8.00 in.	2.00 in.	13.00 ft	25.00 ft
W2011- 0156	03/16/2011	06/26/2011	MW9	8.00 in.	2.00 in	13.00 ft	25.00 ft

#### Specific Work Permit Conditions

- Permittee shall assume entire responsibility for all activities and uses under this permit and shall indemnify, defend and save the Alameda County Public Works Agency, its officers, agents, and employees free and harmless from any and all expense, cost, liability in connection with or resulting from the exercise of this Permit Including, but not limited to, properly damage, personal injury and wrongful death.
- Permittee, permittee's contractors, consultants or agents shall be responsible to assure that all material or waters generated during drilling, boring destruction, and/or other activities associated with this Permit will be safely handled, properly managed, and disposed of according to all applicable federal, state, and local statutes regulating such. In no case shall these materials and/or waters be allowed to enter, or potentially enter, on or off-site storm sewers, dry wells, or waterways or be allowed to move off the property where work is being completed.
- Prior to any drilling activities, it shall be the applicant's responsibility to contact and coordinate an Underground Service Alert (USA), obtain encroachment permit(s), excavation permit(s) or any other permits or agreements required for that Federal, State, County or City, and follow all City or County Ordinances. No work shall begin until all the permits and requirements have been approved or obtained. It shall also be the applicants responsibilities to provide to the Cities or to Alameda County an Traffic Safety Plan for any lane closures or detours planned. No work shall begin until all the

#### Alameda County Public Works Agency - Water Resources Well Permit

permits and requirements have been approved or obtained.

- 4. Compliance with the well-sealing specifications shall not exempt the well-sealing contractor from complying with appropriate State reporting-requirements related to well construction or destruction (Sections 13750 through 13755 (Division 7, Chapter 10, Article 3) of the California Water Code). Contractor must complete State DWR Form 188 and mail original to the Alameda County Public Works Agency, Water Resources Section, within 60 days. Including permit number and site map.
- 5. Applicant shall submit the copies of the approved encroachment permit to this office within 60 days.
- 6. Applicant shall contact Vicky Hamlin for an inspection time at 510-670-5443 or email to vickyh@acpwa.org at least five (5) working days prior to starting, once the permit has been approved. Confirm the scheduled date(s) at least 24 hours prior to drilling.
- 7. Wells shall have a Christy box or similar structure with a locking cap or cover. Well(s) shall be kept locked at all times. Well(s) that become damaged by traffic or construction shall be repaired in a timely manner or destroyed immediately (through permit process). No well(s) shall be left in a manner to act as a conduit at any time.
- 8. Minimum surface seal thickness is two inches of cement grout placed by tremie
- 9. Minimum seal (Neat Cement seal) depth for monitoring wells is 5 feet below ground surface(BGS) or the maximum depth practicable or 20 feet.
- 10. Copy of approved drilling permit must be on site at all times. Failure to present or show proof of the approved permit application on site shall result in a fine of \$500.00.



### Appendix B

Boring Logs and DWR Well Completion Reports

# CONFIDENTIAL

STATE OF CALIFORNIA DWR WELL COMPLETION REPORT (WELL LOGS)

**REMOVED** 

		0	Project Logged		140256277 ETW	7		Clien		COP-ELT Boring/Well No: MW-7 15803 East 14th Street Page 1 of 1
nte	ag	roup	Driller: Drilling	Method: g Method Type: e:	Gregg HSA	Direct I		Date Hole Hole Well Well First	Drilled Dlame Depth Diame Depth Water	1: 4/5/2011 Location Hap iter: 8" 1: 20' iter: 2"
			Elevatio	n:		Northin	g:			Easting:
Secrific Casing Casing	tion	Water Level	Moisture Content	PID Reading (ppm)	Sample Identification	Depth (feet)	Recovery gs	Interval	Soll Type	LITHOLOGY / DESCRIPTION
100	1	-								Asphalt (4 inches thick) Class II AB
M)		h	dry			1-	+		SM	Silty Sand: 65% sand, 30% sllt, 5% gravel (large),
			OI y			2-			200	light brown to dark brown, dry, sand is fine to
1	ļ	(%) []]	V 1				+	Н		coarse grain
						3-				
	-	1				4-	+	-		
						5-				
41	-						X			155
		1 1				6-	X			
	1		des	1.4		7-	X	-	ML	Silt; 95% silt, 5% fine sand, olive green, dry
			dry	1.4		8	X			
	1					٠.	X	H		
	-		dry	7.4	MW-7d9	9-	X	0	CL	Clay, 95% clay, 5% fine sand, olive green, dry
	"	区				10-	X	H		
		Į.	1			11-	X			
	1					11.	X	_		
						12-	X			
			1			13-	X			
							- x			2:
						14-	X			e e
	İ					15	X			
		▼	O O	w .:	28/30/20/20/20	16-	X	0	SW	Well graded sand w/ gravel; 80% sand, 15% grav
		1	wet	5.1	MW-7d16		X	0	Describ.	5% silt, dark brown, wet, sand is fine to coarse grain,
			wet		1	17-	X		CL	gravel is small Clay; 95% clay, 5% sand, dark brown, wet
						18-	X			Stuy, said stuy, or it seems, seems,
						19-	X		ML	Sandy silt; 65% silt, 35% fine sand, pale grey, wet
			wet	0.6	MW-7d20		X	0	1904	
9116	- N	8				20-	F			TD = 20 feet bgs
		. 0			1	21-	+			
						22-			1	



Bentonite Grout

Bentonite Chip Seal


Two Inch diameter 0.02-Inch Slotted PVC Screen Two Inch diameter PVC well casing grouted in place

RMC Lonestar Sand #3 Filter Pack

Project Name and Location:

76 Service Station No. 6277

Site Address: 15803 East 14th Street City, State: San Leandro, California



# CONFIDENTIAL

STATE OF CALIFORNIA DWR WELL COMPLETION REPORT (WELL LOGS)

**REMOVED** 

	9	0	Project I		140256277 ETW		_		tion	COP-ELT 15803 East 14th Street : 4/5/2011 Location	Boring/Well No: MW-8 Page 1 of 1			
anteagroup si		Casing Type: PVC Slot Size: 0.02 Gravel Pack: #3			Well Diamete Well Depth: First Water D Static Water		ter: 8" 20' ter: 2" 20'	rap						
W	ell		Elevatio		1 -	15.5	1	25	-	Edsking:				
Combletion Nater Level		Water Level	Moisture Content PID Reading (ppm)		Sample Identification	Depth (feet)	Recovery	Interval	Soil Type	LITHOLOGY / DESCRIPTION				
TIE.	1					-				Asphalt (4 inches thick) Class II AB				
19.	+		dry			1-			ML	Sandy silt; 65% silt, 30	% fine sand, 5% gravel (large)			
Sq.			- 21		1	2-	-			olive green to black, dry				
1						3-				E THE STATE OF STATE				
505	-		] ]			- E	+				* 1 *			
57						4-				at V	н эт			
54						5-	X							
88						6-	X							
	1		1 1			7-	X				4 7			
	100		dry				X				÷ 8			
	-		1 1	8.1		8-	X				2.00			
			moist	5.6	MW-8d9	9-	X	0	CL	Clay, 95% clay, 5% fine	sand, olive green, moist			
		V	, iii		107.850	10-	X		2.5	A 881				
						-	X							
	II		. 4			11-	X	_						
						12-	X							
			moist	2.2	MW-8d13	13-	X	0	SW	Well graded sand w/	gravel; 80% sand, 15% grave			
					1,41-0013	14-	X	Ľ		5% clay, brown, moist,	sand is medium to coarse,			
			moist	1.2		-	X		CL	gravel is small Clay; 95% clay, 5% fine	e sand, light brown, moist			
						15-	X			A STATE OF THE STA				
						16-	X							
			1			17-	X	-		Į,				
			1			18-	X							
						-	X				ATT PARTY OF THE P			
			moist			19-	X		ML		, 15% fine sand, pale brown,			
	U		1	0.3	MW-Bd20	20-	X	0_		moist TD = 20 feet bgs				
						21-								
								-						
						22-								



Project Name and Location:

76 Service Station No. 6277

Site Address: 15803 East 14th Street City, State: San Leandro, California

DEPTH (ft bgs)			MW-8 CONSTRUCTION DETAILS
	GROUND		Flush Mounted Well Box
0	SURFACE	KV	Locking Well Cap
1			Concrete = 0 ft. to 1 ft.
Į.	1	2000	Concrete - O to to x to
ĺ		100000 1000000	Bentonite Grout = 1 ft. to 7 ft.
		10000 100000 100000 10000 10000 10000 10000 10000 10000 10000 10000 10000 1000	2" Sch. 40 blank PVC casing
		······	set from 0 ft. to 9 ft.
1		10000 100000 100000 10000 10000 10000 10000 10000 10000 10000 10000 10000 1000	
	J. v	minoral panetari panetari panetari panetari panetari panetari panetari	Bentonite Seal = 7 ft. to 8 ft.
		00000 00000 00000	
7	1		
8			
9	J		
- 1			
- 1			
	4.3		
- 1			A Company of the Comp
- 1	Į.		
			RMC Lonestar Sand #3 Filter Pack
			set from 8 ft. to 20 ft.
			,
		1	2" Sch. 40, 0.02-Inch slotted PVC screen
1			set from 9 ft. to 20 ft.
	J 1		Mark To a language of the control of
			Threaded PVC End Cap
	1	(4 th)	

Total Depth of boring at 20 feet below ground surface (bgs)



Concrete

Bentanite Grout

Two inch diameter 0.02-inch Slotted PVC Screen

Two inch diameter PVC well casing grouted in place

RMC Lonestar Sand #3 Filter Pack

Bentonite Chip Seal

# CONFIDENTIAL

STATE OF CALIFORNIA DWR WELL COMPLETION REPORT (WELL LOGS)

**REMOVED** 

		2	Project I		140256277 ETW				tion:	COP-ELT 15803 East 14th Street	Location Map	Boring/Well No: MW-9 Page 1 of 2		
ante	ag	roup	Driller: Drilling I Samplin Casing T Slot Size Gravel P	g Method Type: tack:	d: PVC 0.02 #3	Direct P	rush ▼ ▽	Hole Hole Well Well First		ter: 8° : 24 ter: 2" : 24' Depth: 22' r Depth: 10.40'				
Wel			Elevation		_	Northin	9:	-	23.5	Easting:				
Comple	ompletion E		Moisture Content	PID Reading (ppm)	Sample	Depth (feet)	Recovery 5	Interval al	Soil Type	*53.00		Y / DESCRIPTION		
150	Г					- 2				Asphalt (4 inches Class II AB	thick)			
	1		dry		1	1-			SW	Well graded sand	d w/ gra	vel; 75% sand, 25% gravel		
165			u.y			2-				brown, dry, sand is fine to coarse grain, gravel is small				
			1		1	100	-	Н		to large				
	=					3								
6	-					4-					-			
	1					5					=			
			1		1	-	X							
			dry	0.3		6	X		ML	Silt w/ sand; 80°	% silt, 20	% fine sand, grey, dry		
					1	7-	X							
	-					8	Х				Of Fire an	ad dark brown moist		
	1		moist	0.8	MW-968	-	X	0	CL	Clay; 95% clay, 5	% fine sa	nd, dark brown, moist		
						9	X							
	١.	V				10-	X	-				*		
		777				11-	X			v =	- 2			
						72	X	-						
						12-	X			2923				
						13	X	-		Change color to br	own			
		1			1	14-	X			Change Color to a	4,745.41			
						-	X							
					Į.	15	x							
						16-	X		0					
					1	17	X							
	1					17	X							
					1	18-	X							
						19-	X		CL	Sandy lean clay:	70% cla	y, 30% fine sand,		
			moist	0.7	MW-9d20	20-	X	0	GL	Sandy lean clay; 70% clay, 30% fine sand, pale brown, moist				
				1215	12.0	20	X							
						21-	X			(6)				
		•	200200			22	X		CC	Clavey cand: 509	% fine sa	nd, 40% clay, brown, wet		
	1	-5000 L	wet			125/00	X		SC	ciayey saitu, so	.5 50			


6	5	Project Logged		I40256277 ETW				t: tion: Drille	COP-ELT 15803 East 14th Street i: 4/5/2011	Boring/Well No: MW-9 Page 2 of 2			
anteagr	oup		e: Pack:		Direct Push Hole Depth Well Dlame 02 Well Depth Y First Water V Static Water Northing:				Diameter: 2" Depth: 24' Water Depth: 22' C Water Depth: 10.40' Easting:				
Well	-			5	-	_	mole	20					
Casing Ca	Water Level	Moisture	PID Reading (ppm)	Sample Identification	Depth (feet)	Recovery 5	1000	Soll Type		LOGY / DESCRIPTION			
					23-	X			Clayey sand; 60%	fine sand, 40% clay, brown,			
		wet	0.7	MW-9d24	-	X	0	N					
HARRIE U_			1,751.0	Mercaren and	24-	T			TD = 24 feet bgs				
25					25-	-							
220					26-								
						+	-						
		1			27-								
1					28-	+							
					29-		10						
204		1			-	+							
					30 —	$\perp$							
100					31 —	+				20 50 TO			
33.0		1		1 8	32-					E .			
					-	+							
					33					25			
					34-	+			200				
					35-					55.0			
					14	+							
					36-								
					37-	+							
					38-								
					T. 14	-							
					39	1							
					40-	+	-						
					41-	1							
					42-								
					43-	+							
					44				V.				



Project Name and Location:

76 Service Station No. 6277

Site Address: 15803 East 14th Street City, State: San Leandro, California



Total Depth of boring at 24 feet below ground surface (bgs)

Concrete

Bentonite Grout

Two Inch diameter 0.02-inch Slotted PVC Screen

Two inch diameter PVC well casing grouted in place

RMC Lonestar Sand #3 Fifter Pack

Bentonite Chip Seal

# CONFIDENTIAL

STATE OF CALIFORNIA DWR WELL COMPLETION REPORT (WELL LOGS)

**REMOVED** 

anteagr	oup	Project No. Logged & Driller; Drilling No. Sempling Total State Gravel P.	Method: g Method ype: :: ack:	PVC 0.02 #3	Direct Po	<b>▼</b>	Hole Hole Well Well First	Drilled Dinme Depth Diame Depth: Water Water	ter: U" 20' ter: 2"		
Seckfill Consister Level Mater Level Mosture Content Content (ppm)		Sample entification	Depth (Sett)		Interval R		LITHOLOGY / DESCRIPTION				
8 0	W	dry	d	22	1— 2— 3— 4—	8	A	Fill	Asphalt (4 inches thick) Class II AB Well graded gravel w/ sand; 55% gravel, 45% sand, brown, dry, sand is fine to coarse grain, gravel is large, material is fill		
		dry	5.7		5	X X X X X		CL	Clay w/ sand; 85% clay, 15% fine sand, black, dry		
	又	moist	1	MW-10d10	10-11	X X X X	0	CL	Olive green  Clay; 95% clay, 5% fine sand, black, moist, strong oder  Dark brown		
		moist	1.1	MW-10/(15	14-	X X X X X	0	SC	Clayey sand; 75% fine sand, 25% clay, light brown, moist		
		moist	0.9	MW-10d20	17	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Ö	CL	Clay; 90% clay, 10% fine sand, brown, moist  Dark brown  TD = 20 feet bgs		




Project Name and Location:

76 Service Station No. 6277

Site Address: 15803 East 14th Street

City, State: 5an Leandro, California



Total Depth of boring at 20 feet below ground surface (bgs)

Concrete

Bentonite Grout

Two Inch diameter 0.02-inch Slotted PVC Screen

Two Inch diameter PVC well casing grouted in place

RMC Lonestar Sand #3 Filter Pack

Bentonite Chip Seal

Site InvestigationReport 76 Service Station No. 6277 Antea Group Project No. 140256277



## Appendix C

Certified Laboratory Analytical Reports and Data Validation Forms

### Is the Data Set Valid?

(circle) Yes / No

### **Preservation Temperature**


(if Known): \_\_\_\_\_3,2\_\_\_\_oc

### Antea<sup>™</sup>Group Laboratory Data Validation Sheet

Project/Client: 76 Service Station # 6277 / COR-ELT  Project #: 140256277  Date of Validation: 426-11 Date of Analysis: 4/12/11 to 4/18/11  Sample Date: 4-5-11 Completed By: ETW	Circle or Highlight  Yes No (below)
Analytical Lab Used and Report # (if any): 257254	
1. Were the analyses the ones requested?	Yes / No
2. Do the sample number(s) on the chain-of-custody (COC) match the one(s) that appear on the laboratory data sheet?	Yes / No
3. Were samples prepared (extracted, filtered, etc.) within EPA holding times?	Yes / No
4. Once prepared/extracted, were the samples analyzed within the EPA holding times?	Yes / No
5. Were Laboratory blanks performed, if so, were they non-detect?	Yes / No
<ol> <li>Are the units correct? (i.e., soil samples in mg/kg or ug/g, water samples mg/L, ug/L, and air samples in volume mg/m³,etc.)</li> </ol>	Yes / No
7. Were appropriate Matrix Spike (MS) and Matrix Spike Duplicate (MSD) samples included in the laboratory batch sample?	Yes / No
8. In lieu of MS/ MSD, were surrogate spike (SS) or surrogate spike duplicate (SSD) samples included in the laboratory batch samples?	Yes / No
<ol><li>Were MS/ MSD (or SS/SSD) within the acceptable range of % recovery (i.e., approximately 80-120%, depending on the analyte)?</li></ol>	Yes / No
10. Were MS/MSD (or SS/SSD) values used to calculate Relative Percent Difference (RPD)?	Yes / No
11. Were Relative Percent Difference values within the acceptable range (i.e. $\pm 25\%$ )?	Yes / No

## If any answer is no, explain why and what corrective action was taken (use additional sheet(s), as necessary:

6 Qualifiers reported: D6 => RPD exceeded control limits. MID Matrix spik recover exceeded QC limits. M6=> M5 + M5D not evaluated against control limits has to sample dilution. S0=> sample recovery outside LCL. S2=> sample recovery outside LCL. S2=> sample recovery outside LCL. S2=> sample limits.	II.





April 22, 2011

Dennis Dettloff Antea USA 11050 White Rock Rd. #110 Rancho Cordova, CA 95670

RE: Project: 256277

Pace Project No.: 257254

#### Dear Dennis Dettloff:

Enclosed are the analytical results for sample(s) received by the laboratory on April 08, 2011. The results relate only to the samples included in this report. Results reported herein conform to the most current NELAC standards, where applicable, unless otherwise narrated in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Regina SteMarie

Regina Ste. Marie

regina.stemarie@pacelabs.com Project Manager

Enclosures

cc: Tara Bosch, Antea USA
Jonathon Fillingame, Antea USA
Josh Mahoney, Antea USA
Tony Perini, Antea USA
Don Pinkerton, Antea USA
Doug Umland, Antea USA
Ed Weyrens, Antea USA



Pace Analytical Services, Inc. 940 South Harney Seattle, WA 98108 (206)767-5060

#### **CERTIFICATIONS**

Project:

256277

Pace Project No.: 257254

Washington Certification IDs 940 South Harney Street, Seattle, WA 98108 Alaska CS Certification #: UST-025 Alaska Drinking Water VOC Certification #: WA01230 Alaska Drinking Water Micro Certification #: WA01230

California Certification #: 01153CA Florida/NELAP Certification #: E87617 Oregon Certification #: WA200007 Washington Certification #: C1229







#### SAMPLE ANALYTE COUNT

Project:

256277

Pace Project No.: 257254

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory
257254001	MW-7d9	EPA 8015B	AY1	3	PASI-S
		EPA 6010	BGA	1	PASI-S
		EPA 8260	LPM	6	PASI-S
		EPA 8260	LPM	14	PASI-S
		CA LUFT	LPM	2	PASI-S
257254002	MW-7d16	EPA 8015B	AY1	3	PASI-S
		EPA 6010	BGA	1	PASI-S
		EPA 8260	LPM	16	PASI-S
		CALUFT	LPM	2	PASI-S
257254003	MW-7d20	EPA 8015B	AY1	3	PASI-S
		EPA 6010	BGA	1	PASI-S
		EPA 8260	LPM	16	PASI-S
		CA LUFT	LPM	2	PASI-S
257254004	MW-8d9	EPA 8015B	AY1	3	PASI-S
		EPA 6010	BGA	1	PASI-S
		EPA 8260	LPM	16	PASI-S
		CA LUFT	LPM	2	PASI-S
257254005	MW-8d13	EPA 8015B	AY1	3	PASI-S
		EPA 6010	BGA	1	PASI-S
		EPA 8260	LPM	16	PASI-S
		CALUFT	LPM	2	PASI-S
257 254006	MW-8d20	EPA 8015B	AY1	3	PASI-S
		EPA 6010	BGA	1	PASI-S
		EPA 8260	LPM	16	PASI-S
		CALUFT	LPM	2	PASI-S
257254007	MW-9d8	EPA 8015B	AY1	3	PASI-S
		EPA 6010	BGA	1	PASI-S
		EPA 8260	LPM	16	PASI-S
		CALUFT	LPM	2	PASI-S
57254008	MW-9d20	EPA 8015B	AY1	3	PASI-S
		EPA 6010	BGA	1	PASI-S
		EPA 8260	LPM	16	PASI-S
		CA LUFT	LPM	2	PASI-S
57254009	MW-9d24	EPA 8015B	AY1	3	PASI-S
		EPA6010	BGA	1	PASI-S
		EPA 8260	LPM	16	PASI-S
		CALUFT	LPM	2	PASI-S

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc..



Page 3 of 31





#### SAMPLE ANALYTE COUNT

Project:

256277

Pace Project No.: 257254

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory
257254010	MW-10d10	EPA 8015B	AY1	4	PASI-S
		EPA 6010	BGA	1	PASI-S
		EPA 8260	LPM	16	PASI-S
		CALUFT	LPM	2	PASI-S
257254011	MW-10d15	EPA 8015B	AY1	4	PASI-S
		EPA 6010	BGA	1	PASI-S
		EPA 8260	LPM	16	PASI-S
		CALUFT	LPM	2	PASI-S
257254012	MW-10d20	EPA 8015B	AY1	4	PASI-S
		EPA 6010	BGA	1	PASI-S
		EPA 8260	LPM	16	PASI-S
		CALUFT	LPM	2	PASI-S







#### **HITS ONLY**

Project:

256277

257254

Pace Project No.:

Client	Sample	ID

Lab Sample ID	Client Sample ID					
Melhod	Parameters	Result	Units	Report Limit	Analyzed	Qualifiers
 257254001	MW-7d9					
EPA 8015B	TPH-RRO (C24-C40) SG	20.7	mg/kg	9.8	04/16/11 02:16	
EPA 6010	Lead	8.9	mg/kg	0.92	04/18/11 16:00	
EPA 8260	Ethylbenzene	4.3	mg/kg	0.045	04/18/11 11:34	
EPA 8260	Xylene (Tolal)	8.4	mg/kg	0.13	04/18/11 11:34	
EPA 8260	Benzene	0.061	mg/kg	0.0024	04/12/11 18:51	
EPA 8260	tert-Butyl Alcohol	0.018	mg/kg	0.012	04/12/11 18:51	
EPA 8260	Methyl-tert-butyl ether	0.042	mg/kg	0.0024	04/12/11 18:51	
EPA 8260	Toluene	0.034	mg/kg	0.0024	04/12/11 18:51	
CALUFT	TPH-Gasoline (C05-C12)	289	mg/kg	2.2	04/18/11 11:34	
257254002	MW-7d16					
EPA 8015B	TPH-RRO (C24-C40) SG	788	mg/kg		04/16/11 00:19	
EPA 6010	Lead	13.9	mg/kg	0.85	04/18/11 16:04	
EPA 8260	Benzene	0.017	mg/kg	0.0024	04/12/11 19:10	
EPA 8260	Ethylbenzene	0.054	mg/kg	0.0024	04/12/11 19:10	
EPA 8260	Methyl-terl-butyl ether	0.013	mg/kg	0.0024	04/12/11 19:10	
EPA 8260	Toluene	0.037	mg/kg	0.0024	04/12/11 19:10	
EPA 8260	Xylene (Total)	0.24	mg/kg	0.0073	04/12/11 19:10	
CA LUFT	TPH-Gasoline (C05-C12)	0.90	mg/kg	0.20	04/12/11 19:10	M1
57254003	MW-7d20					
EPA 6010	Lead	6.3	mg/kg	4,5	04/18/11 17:15	
EPA 8260	Methyl-tert-butyl ether	0.019	mg/kg	0.0029	04/12/11 19:30	
57254004	MW-8d9					
EPA 6010	Lead	9.9	mg/kg	1.4	04/18/11 17:18	
EPA 8260	Benzene	0.020	mg/kg	0.0030	04/12/11 19:50	
EPA 8260	tert-Butyl Alcohol	0.023	mg/kg	0.015	04/12/11 19:50	
EPA 8260	Methyl-tert-butyl ether	0.086	mg/kg	0.0030	04/12/11 19:50	
CALUFT	TPH-Gasoline (C05-C12)	0.75	mg/kg	0.25	04/12/11 19:50	
57254005	MW-8d13					
EPA 8015B	TPH-RRO (C24-C40) SG	852	mg/kg	99.5	04/16/11 01:30	
EPA 6010	Lead	15.7	mg/kg	1.8	04/18/11 17:21	
EPA 8260	Benzene	0.016	mg/kg	0.0028	04/12/11 20:09	
EPA 8260	Ethylbenzene	0.024	mg/kg	0.0028	04/12/11 20:09	
EPA 8260	Methyl-tert-butyl ether	0.023	mg/kg	0.0028	04/12/11 20:09	
EPA 8260	Xylene (Total)	0.060	mg/kg	0.0083	04/12/11 20:09	
CALUFT	TPH-Gasoline (C05-C12)	88.0	mg/kg	0.23	04/12/11 20:09	
57254007	8be-WM					
EPA 6010	Lead	8.9	mg/kg	0.92	04/18/11 16:27	
57254008	MW-9d20					
EPA 6010	Lead	5.3	mg/kg	0.96	04/18/11 16:30	
57254009	MW-9d24					
PA 6010	Lead	6.4	mg/kg	0.92	04/18/11 16:33	

REPORT OF LABORATORY ANALYSIS

Page 5 of 31





#### HITS ONLY

Project:

256277

Pace Project No.:

257254

Lab	Sample	ID

Client Sample ID

Lab Gample ID	Olient Gample ID					
Method	Parameters	Result	Units	Report Limit	Analyzed	Qualifiers
257254010	MW-10d10					
EPA 6010	Lead	8.5 mg	/kg	0.99	04/18/11 16:37	
EPA 8260	Methyl-tert-butyl ether	0.028 mg	/kg	0.0025	04/18/11 17:10	
257254011	MW-10d15					
EPA 6010	Lead	6.1 mg	/kg	0.76	04/18/11 16:40	
EPA 8260	Ethylbenzene	0.0039 mg	/kg	0.0026	04/13/11 16:57	
EPA 8260	Xylene (Tolal)	0.012 mg	/kg	0.0077	04/13/11 16:57	
257254012	MW-10d20					
EPA 6010	Lead	5.8 mg.	/kg	0.69	04/18/11 16:44	






Project: 256277 Pace Project No.: 257254

Date: 04/22/2011 03:06 PM

Sample: MW-7d9 Lab (D: 257254001 Collected: 04/05/11 08:52 Received: 04/08/11 08:15 Matrix: Solid Results reported on a "wet-weight" basis Parameters Results Units Report Limit DF CAS No. Qual Prepared Analyzed 8015B CA Diesel Range Org SG Analytical Method: EPA 8015B Preparation Method: EPA 3546 TPH-RRO (C24-C40) SG 20.7 mg/kg 9.8 1 04/12/11 10:55 04/16/11 02:16 o-Terphenyl (S) SG 95 % 50-150 04/12/11 10:55 04/16/11 02:16 84-15-1 1 n-Octacosane (S) SG 108 % 50-150 04/12/11 10:55 04/16/11 02:16 630-02-4 6010 MET ICP Analytical Method: EPA 6010 Preparation Method: EPA 3050 04/14/11 14:09 04/18/11 16:00 7439-92-1 Lead 8.9 mg/kg 0.92 1 8260 MSV 5030 Med Level VOA Analytical Method: EPA 8260 Preparation Method: EPA 5030 Ethylbenzene 4.3 mg/kg 0.045 1 04/18/11 07:00 04/18/11 11:34 100-41-4 04/18/11 07:00 04/18/11 11:34 Xylene (Total) 1330-20-7 8.4 mg/kg 0.13 1 Dibromofluoromethane (S) 97 % 81-114 04/18/11 07:00 04/18/11 11:34 1868-53-7 Toluene-d8 (S) 97 % 84-121 04/18/11 07:00 04/18/11 11:34 2037-26-5 4-Bromofluorobenzene (S) 95 % 78-127 1 04/18/11 07:00 04/18/11 11:34 460-00-4 1,2-Dichloroelhane-d4 (S) 96 % 76-115 1 04/18/11 07:00 04/18/11 11:34 17060-07-0 8260 MSV 5030 Analytical Method: EPA 8260 ND mg/kg tert-Amylmethyl ether 0.0024 1 04/12/11 18:51 994-05-8 Веплепе 0.061 mg/kg 0.0024 04/12/11 18:51 71-43-2 1 tert-Butyl Alcohol 0.018 mg/kg 0.012 04/12/11 18:51 75-65-0 1 1,2-Dibromoethane (EDB) ND mg/kg 0.0024 04/12/11 18:51 106-93-4 1 1,2-Dichloroethane 04/12/11 18:51 107-06-2 ND ma/ka 0.0024 1 Diisopropyl ether ND mg/kg 0.0024 04/12/11 18:51 108-20-3 Ethanol ND mg/kg 04/12/11 18:51 64-17-5 0.32 Ethyl-tert-bulyl ether ND mg/kg 0.0024 04/12/11 18:51 637-92-3 Methyl-tert-butyl ether 0.042 mg/kg 0.0024 04/12/11 18:51 1634-04-4 Toluene 0.034 mg/kg 0.0024 04/12/11 18:51 108-88-3 Dibromofluoromethane (S) 04/12/11 18:51 1868-53-7 96 % 80-136 1 Toluene-d8 (S) 109 % 80-120 04/12/11 18:51 2037-26-5 1 4-Bromofluorobenzene (S) 94 % 72-122 1 04/12/11 18:51 460-00-4 108 % 04/12/11 18:51 17060-07-0 1,2-Dichloroethane-d4 (S) 80-143 CA LUFT MSV GRO Medium Soil Analytical Method: CALUFT Preparation Method: CALUFT TPH-Gasoline (C05-C12) 289 mg/kg 2.2 04/18/11 07:00 04/18/11 11:34 04/18/11 07:00 04/18/11 11:34 460-00-4 4-Bromofluorobenzene (S) 95 % 72-122 Sample: MW-7d16 Lab (D: 257254002 Collected: 04/05/11 09:05 Received: 04/08/11 08:15 Matrix: Solid Results reported on a "wet-weight" basis **Parameters** Results Units Report Limit DE Prepared Analyzed CAS No. Qual 8015B CA Diesel Range Org SG Analytical Method: EPA 8015B Preparation Method: EPA 3546 TPH-RRO (C24-C40) SG 788 mg/kg 99.2 10 04/12/11 10:55 04/16/11 00:19 o-Terphenyl (S) SG 0 % 50-150 10 04/12/11 10:55 04/16/11 00:19 84-15-1 S4 n-Octacosane (S) SG 0 % 50-150 04/12/11 10:55 04/16/11 00:19 630-02-4 S4

**REPORT OF LABORATORY ANALYSIS** 

Page 7 of 31







Project:

256277


Pace Project No.: 257254

Sample: MW-7d16 Lab ID: 257254002 Collected: 04/05/11 09:05 Received: 04/08/11 08:15 Matrix: Solid Results reported on a "wet-weight" basis Units DF CAS No. **Parameters** Results Report Limit Prepared Analyzed Qual **5010 MET ICP** Analytical Method: EPA 6010 Preparation Method: EPA 3050 Lead 04/14/11 14:09 04/18/11 16:04 7439-92-1 13.9 mg/kg 0.85 8260 MSV 5030 Analytical Method: EPA 8260 tert-Amylmethyl ether ND mg/kg 0,0024 1 04/12/11 19:10 994-05-8 Benzene 0.017 mg/kg 0,0024 04/12/11 19:10 71-43-2 1 tert-Bulyl Alcohol ND mg/kg 0.012 04/12/11 19:10 75-65-0 1 1,2-Dibromoethane (EDB) ND mg/kg 0.0024 04/12/11 19:10 106-93-4 1,2-Dichloroethane ND mg/kg 0.0024 04/12/11 19:10 107-06-2 Diisopropyl ether ND mg/kg 0.0024 04/12/11 19:10 108-20-3 Ethanol ND mg/kg 0.32 1 04/12/11 19:10 64-17-5 Ethylbenzene 0.054 mg/kg 0.0024 1 04/12/11 19:10 100-41-4 Ethyl-tert-butyl ether ND mg/kg 0.0024 1 04/12/11 19:10 637-92-3 Methyl-tert-butyl ether 0.013 mg/kg 0.0024 1 04/12/11 19:10 1634-04-4 04/12/11 19:10 108-88-3 Toluene 0.037 mg/kg 0.0024 1 0.24 mg/kg 04/12/11 19:10 1330-20-7 Xvlene (Total) 0.0073 1 Dibromofluoromethane (S) 94 % 80-136 04/12/11 19:10 1868-53-7 1 Toluene-d8 (S) 100 % 80-120 1 04/12/11 19:10 2037-26-5 4-Bromofluorobenzene (S) 110 % 72-122 04/12/11 19:10 460-00-4 1 1,2-Dichloroethane-d4 (S) 93 % 80-143 04/12/11 19:10 17060-07-0 **CALUFT MSV GRO** Analytical Method: CA LUFT TPH-Gasoline (C05-C12) 0.90 mg/kg 04/12/11 19:10 0.20 1 M1 4-Bromofluorobenzene (S) 72-122 04/12/11 19:10 460-00-4 110 % 1 Sample: MW-7d20 Lab ID: 257254003 Collected: 04/05/11 08:58 Received: 04/08/11 08:15 Results reported on a "wet-weight" basis **Parameters** Results CAS No. Units Report Limit DF Prepared Analyzed Qual 8015B CA Diesel Range Org SG Analytical Method; EPA 8015B Preparation Method; EPA 3546 TPH-RRO (C24-C40) SG ND mg/kg 9.9 1 04/12/11 10:55 04/15/11 20:01 o-Terphenyl (S) SG 93 % 50-150 04/12/11 10:55 04/15/11 20:01 84-15-1 1 n-Octacosane (S) SG 105 % 50-150 04/12/11 10:55 04/15/11 20:01 630-02-4 1 6010 MET ICP Analytical Method: EPA 6010 Preparation Method: EPA 3050 Lead 6.3 mg/kg 4.5 04/14/11 14:09 04/18/11 17:15 7439-92-1 8260 MSV 5030 Analytical Method: EPA 8260 tert-Amylmethyl ether 0.0029 04/12/11 19:30 994-05-8 ND mg/kg 1 Велгеле ND mg/kg 0.0029 04/12/11 19:30 71-43-2 tert-Bulyl Alcohol ND mg/kg 0.015 04/12/11 19:30 75-65-0 1,2-Dibromoethane (EDB) ND mg/kg 0.0029 1 04/12/11 19:30 106-93-4 1,2-Dichloroethane ND mg/kg 0.0029 04/12/11 19:30 107-06-2 Diisopropyl ether ND mg/kg 0.0029 04/12/11 19:30 108-20-3

Date: 04/22/2011 03:06 PM

#### REPORT OF LABORATORY ANALYSIS

Page 8 of 31







Project: 256277 Pace Project No.: 257254

Sample: MW-7d20 Lab ID: 257254003 Collected: 04/05/11 08:58 Received: 04/08/11 08:15 Matrix: Solid

Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
Analytical Met	hod: EPA 820	60					
ND m	g/kg	0.39	1		04/12/11 19:30	64-17-5	
ND m	g/kg	0.0029	1		04/12/11 19:30	100-41-4	
		0.0029	1		04/12/11 19:30	637-92-3	
0.019 mg	g/kg	0.0029	1				
		0.0029	1				
•		0.0087	1		04/12/11 19:30	1330-20-7	
92 %	, ,	80-136	1		04/12/11 19:30	1868-53-7	
			1		04/12/11 19:30	2037-26-5	
104 %			1				
94 %		80-143	1				
Analytical Meth	nod: CA LUF	Т					
<b>N</b> D mo	ı/kg	0.24	1		04/12/11 19:30		
104 %	,	72-122	1			460-00-4	
Lab ID: 257	254004	Collected: 04/05/1	1 10:27	Received: 04	I/08/11 08:15 M	latrix: Solid	
" basis							
Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
Analytical Meth	nod: EPA 801	I5B Preparation Me	thod: El	PA 3546			
. ND mg	ı/kg	10	1	04/12/11 10:55	04/15/11 20:25		
95 %	-	50-150	1	04/12/11 10:55	04/15/11 20:25	84-15-1	
107 %		50-150	1	04/12/11 10:55	04/15/11 20:25	630-02-4	
Analytical Meth	od: EPA 601	0 Preparation Meth	od: EP/	A 3050			
<b>9.9</b> mg	ı/kg	1.4	2	04/14/11 14:09	04/18/11 17:18	7439-92-1	
Analytical Meth	od: EPA 826	0					
ND mg	/kg	0.0030	1		04/12/11 19:50	994-05-8	
		0.0030	1		04/12/11 19:50	71-43-2	
-							
-	_						
-	_						
•	U						
-	-						
_	-						
_	_						
_	_						
•	•						
_	/ng						
96 % 104 %		80-136 80-120	1 1				
	Analytical Methodology of the second of the	Analytical Method: EPA 826  ND mg/kg 92 % 104 % 104 % 94 %  Analytical Method: CA LUF ND mg/kg 104 %  Lab ID: 257254004  ' basis Results Units  Analytical Method: EPA 803  ND mg/kg 95 % 107 %  Analytical Method: EPA 601 9.9 mg/kg ND mg/kg	Analytical Method: EPA 8260  ND mg/kg 0.39 ND mg/kg 0.0029 ND mg/kg 0.0029 ND mg/kg 0.0029 ND mg/kg 0.0029 ND mg/kg 0.0087 92 % 80-136 104 % 80-120 104 % 72-122 94 % 80-143  Analytical Method: CA LUFT ND mg/kg 0.24 104 % 72-122  Lab ID: 257254004 Collected: 04/05/1 'basis  Results Units Report Limit  Analytical Method: EPA 8015B Preparation Methors with the second method of the second	Analytical Method: EPA 8260   ND mg/kg	Analytical Method: EPA 8260   ND mg/kg	Analytical Method: EPA 8260  ND mg/kg	Analytical Method: EPA 8260  ND mg/kg

Date: 04/22/2011 03:06 PM

4-Bromofluorobenzene (S)


#### **REPORT OF LABORATORY ANALYSIS**

72-122

100 %

Page 9 of 31

04/12/11 19:50 460-00-4







Project:	25
Pace Project No.:	25

256277 257254

Results reported on a "wet-weight" basis

Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
Analytical Me	thod: EPA 8260						
100 %	<b>S</b>	80-143	1		04/12/11 19:50	17060-07-0	
Analytical Me	thod: CA LUFT						
0.75 m	ıg/kg	0.25	1		04/12/11 19:50		
100 %	j	72-122	1		04/12/11 19:50	460-00-4	
	Analytical Me 100 % Analytical Me 0.75 m	Analytical Method: EPA 8260 100 % Analytical Method: CA LUFT 0.75 mg/kg 100 %	Analytical Method: EPA 8260 100 % 80-143 Analytical Method: CA LUFT 0.75 mg/kg 0.25	Analytical Method: EPA 8260  100 % 80-143 1  Analytical Method: CA LUFT  0.75 mg/kg 0.25 1	Analytical Method: EPA 8260  100 % 80-143 1  Analytical Method: CA LUFT  0.75 mg/kg 0.25 1	Analytical Method: EPA 8260  100 % 80-143 1 04/12/11 19:50  Analytical Method: CA LUFT  0.75 mg/kg 0.25 1 04/12/11 19:50	Analytical Method: EPA 8260  100 % 80-143 1 04/12/11 19:50 17060-07-0  Analytical Method: CA LUFT  0.75 mg/kg 0.25 1 04/12/11 19:50

Sample: MW-8d13	Lab ID: 257254005	Collected: 04/05/11 10:32	Received: 04/08/11 08:15	Matrix: Solid
-----------------	-------------------	---------------------------	--------------------------	---------------


Results reported on a "wet-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
8015B CA Diesel Range Org SG	Analytical Mell	od: EPA 8015B	Preparation Me	ethod: E	EPA 3546			
TPH-RRO (C24-C40) SG	8 <b>52</b> mg	g/kg	99.5	10	04/12/11 10:55	04/16/11 01:30		
o-Terphenyl (S) SG	0 %		50-150	10	04/12/11 10:55	04/16/11 01:30	84-15-1	S4
n-Octacosane (S) SG	0 %		50-150	10	04/12/11 10:55	04/16/11 01:30	630-02-4	S4
6010 MET ICP	Analytical Meth	nod: EPA 6010	Preparation Meth	nod: EF	PA 3050			
Lead	<b>15.</b> 7 mg	J/kg	1.8	2	04/14/11 14:09	04/18/11 17:21	7439-92-1	
8260 MSV 5030	Analytical Meth	nod: EPA 8260						
tert-Amylmethyl ether	ND mg	ı/kg	0.0028	1		04/12/11 20:09	994-05-8	
Benzene	<b>0.016</b> mg	ı/kg	0.0028	1		04/12/11 20:09	71-43-2	
ert-Bulyl Alcohol	ND mg	ı/kg	0.014	1		04/12/11 20:09	75-65-0	
1,2-Dibromoethane (EDB)	ND mg	ı/kg	0.0028	1		04/12/11 20:09	106-93-4	
1,2-Dichloroethane	ND mg	ı/kg	0.0028	1		04/12/11 20:09	107-06-2	
Diisopropyl ether	ND mg	ı/kg	0.0028	1		04/12/11 20:09	108-20-3	
E <b>1</b> hanol	ND mg	ı/kg	0.37	1		04/12/11 20:09	64-17-5	
Ethylbenzene	<b>0.024</b> mg	/k <b>g</b>	0.0028	1		04/12/11 20:09	100-41-4	
Ethyl-lert-bulyl ether	ND mg	/kg	0.0028	1		04/12/11 20:09	637-92-3	
Methyl-tert-butyl ether	<b>0.023</b> mg	/kg	0.0028	1		04/12/11 20:09	1634-04-4	
l'oluene	ND mg	/kg	0.0028	1		04/12/11 20:09	108-88-3	
(ylene (Total)	<b>0.060</b> mg	/kg	0.0083	1		04/12/11 20:09	1330-20-7	
Dibromofluoromethane (S)	96 %		80-136	1		04/12/11 20:09	1868-53-7	
ſoluene-d8 (S)	106 %		80-120	1		04/12/11 20:09	2037-26-5	
I-Bromofluorobenzene (S)	1 <b>1</b> 8 %		72-122	1		04/12/11 20:09	460-00-4	
1,2-Dichloroelhane-d4 (S)	102 %		80-143	1		04/12/11 20:09	17060-07-0	
CA LUFT MSV GRO	Analytical Meth	od: CA LUFT						
ГРН-Gasoline (C05-C12)	<b>0.6</b> 8 mg	/kg	0.23	1		04/12/11 20:09		
I-Bromofluorobenzene (S)	118 %	-	72-122	1		04/12/11 20:09	460-00-4	

Date: 04/22/2011 03:06 PM

**REPORT OF LABORATORY ANALYSIS** 

Page 10 of 31







 Project:
 256277

 Pace Project No.:
 257254

Sample: MW-8d20 Lab ID: 257254006 Collected: 04/05/11 10:36 Received: 04/08/11 08:15 Matrix: Solid

Results reported on a "wet-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8015B CA Diesel Range Org SG	Analytical Me	thod: EPA 8015B	Preparation Me	elhod: E	EPA 3546			
TPH-RRO (C24-C40) SG	ND m	ng/kg	10	1	04/12/11 10:55	04/15/11 20:48		
o-Terphenyl (S) SG	94 %	, D	50-150	1	04/12/11 10:55	04/15/11 20:48	84-15-1	
n-Octacosane (S) SG	106 %	,	50-150	1	04/12/11 10:55	04/15/11 20:48	630-02-4	
6010 MET ICP	Analytical Met	lhod: EPA 6010	Preparation Met	hod: EF	PA 3050			
Lead	ND m	ng/kg	4.1	5	04/14/11 14:09	04/18/11 17:25	7439-92-1	
8260 MSV 5030	Analytic <i>a</i> l <b>M</b> el	thod; EPA 8260						
tert-Amylmethyl ether	ND m	ıg/kg	0.0023	1		04/12/11 20:29	994-05-8	
Benzene	ND m	ıg/kg	0.0023	1		04/12/11 20:29	71-43-2	
tert-Butyl Alcohol	ND m	ıg/kg	0.012	1		04/12/11 20:29	75-65-0	
1,2-Dibromoethane (EDB)	ND m	ıg/kg	0.0023	1		04/12/11 20:29	106-93-4	
1,2-Dichloroethane	ND m	ıg/kg	0.0023	1		04/12/11 20:29	107-06-2	
Diisopropyl ether	ND m		0.0023	1		04/12/11 20:29	108-20-3	
Ethanol	ND m	ıg/kg	0.31	1		04/12/11 20:29	64-17-5	
Ethylbenzene	ND m	g/kg	0.0023	1		04/12/11 20:29		
Elhyl-tert-bulyl ether	ND m	a/ka	0.0023	1		04/12/11 20:29		
Methyl-tert-butyl ether	ND m		0.0023	1		04/12/11 20:29		
Toluene	ND m		0.0023	1		04/12/11 20:29	108-88-3	
Xylene (Total)	ND m		0.0070	1		04/12/11 20:29		
Dibromofluoromethane (S)	90 %		80-136	1		04/12/11 20:29		
Toluene-d8 (S)	106 %		80-120	1		04/12/11 20:29		
4-Bromofluorobenzene (S)	106 %		72-122	1		04/12/11 20:29		
1,2-Dichloroethane-d4 (S)	95 %		80-143	1		04/12/11 20:29		
CA LUFT MSV GRO	Analytical Met	hod: CA LUFT						
TPH-Gasoline (C05-C12)	ND m	a/ka	0.23	1		04/12/11 20:29		
4-Bromofluorobenzene (S)	106 %		72-122	1		04/12/11 20:29	460-00-4	
Sample: MW-9d8	Lab ID: 257	<b>254007</b> Col	lected: 04/05/1	1 12:58	Received: 04	/08/11 08:15 M	latrix: Solid	
Results reported on a "wet-weight"	basis							
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8015B CA Diesel Range Org SG	Analytical Met	hod: EPA 8015B	Preparation Me	thod: El	PA 3546			
TPH-RRO (C24-C40) SG	ND mg	g/kg	9.7	1	04/12/11 10:55	04/15/11 21:12		
o-Terphenyl (S) SG	90 %	<del>-</del>	50-150	1	04/12/11 10:55	04/15/11 21:12	84-15-1	
n-Octacosane (S) SG	102 %		50-150	1	04/12/11 10:55	04/15/11 21:12	630-02-4	
6010 MET ICP	Analytical Meti	hod: EPA 6010 F	reparation Meth	od: EP/	A 3050			
Lead	<b>8.9</b> mg	g/kg	0.92	1	04/14/11 14:09	04/18/11 16:27	7439-92-1	
8260 MSV 5030	Analytical Meth	nod: EPA 8260						
	•							

tert-Amylmethyl ether

Date: 04/22/2011 03:06 PM

#### REPORT OF LABORATORY ANALYSIS

0.0026

Page 11 of 31

04/12/11 20:49 994-05-8

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc..

ND mg/kg



Matrix: Solid



#### **ANALYTICAL RESULTS**

Collected: 04/05/11 12:58

Received: 04/08/11 08:15

Lab ID: 257254007

Project: 256277 Pace Project No.: 257254

Results reported on a "wet-weight" basis

Sample: MW-9d8


Parameters Results Units Report Limit DF Prepared Analyzed CAS No. Qual 8260 MSV 5030 Analytical Method: EPA 8260 Benzene ND mg/kg 0.0026 04/12/11 20:49 71-43-2 1 tert-Butyl Alcohol ND mg/kg 0.013 04/12/11 20:49 75-65-0 1,2-Dibromoethane (EDB) ND mg/kg 0.0026 04/12/11 20:49 106-93-4 1,2-Dichloroethane ND mg/kg 0.0026 04/12/11 20:49 107-06-2 Diisopropyl ether 0.0026 ND mg/kg 04/12/11 20:49 108-20-3 Ethanol ND mg/kg 0.35 04/12/11 20:49 64-17-5 Ethylbenzene ND mg/kg 0.0026 04/12/11 20:49 100-41-4 1 Ethyl-tert-butyl ether ND mg/kg 0.0026 1 04/12/11 20:49 637-92-3 Methyl-tert-bulyl ether ND mg/kg 0.0026 04/12/11 20:49 1634-04-4 Toluene ND mg/kg 0.0026 04/12/11 20:49 108-88-3 Xylene (Total) 0.0078 04/12/11 20:49 1330-20-7 ND mg/kg 93 % Dibromofluoromethane (S) 80-136 04/12/11 20:49 1868-53-7 1 Toluene-d8 (S) 107 % 80-120 04/12/11 20:49 2037-26-5 1 4-Bromofluorobenzene (S) 106 % 72-122 1 04/12/11 20:49 460-00-4 1,2-Dichloroethane-d4 (S) 95 % 80-143 04/12/11 20:49 17060-07-0 1 CA LUFT MSV GRO Analytical Method: CA LUFT TPH-Gasoline (C05-C12) ND mg/kg 0.22 1 04/12/11 20:49 4-Bromofluorobenzene (S) 106 % 04/12/11 20:49 460-00-4 72-122 1 Sample: MW-9d20 Lab ID: 257254008 Collected: 04/05/11 13:05 Received: 04/08/11 08:15 Matrix: Solid Results reported on a "wet-weight" basis **Parameters** Results Units Report Limit DF Prepared Analyzed CAS No. Qual

8015B CA Diesel Range Org SG	Analytical Method: EPA 8015B Pt	reparation Me	thod: I	EPA 3546		
ТРН-RRO (C24-C40) SG	ND mg/kg	9.8	1	04/12/11 10:55	04/15/11 21:35	
o-Terphenyl (S) SG	93 %	50-150	1	04/12/11 10:55	04/15/11 21:35	84-15-1
n-Oclacosane (S) SG	105 %	50-150	1	04/12/11 10:55	04/15/11 21:35	630-02-4
6010 MET ICP	Analytical Method: EPA 6010 Pre	paration Meth	od: El	PA 3050		
Lead	<b>5.3</b> mg/kg	0.96	1	04/14/11 14:09	04/18/11 16:30	<b>7</b> 439-92-1
8260 MSV 5030	Analytical Method: EPA 8260					
tert-Amylmethyl ether	ND mg/kg	0.0028	1		04/12/11 21:08	994-05-8
Benzene	ND mg/kg	0.0028	1		04/12/11 21:08	71-43-2
tert-Bulyl Alcohol	ND mg/kg	0.014	1		04/12/11 21:08	75-65-0
1,2-Dibromoethane (EDB)	ND mg/kg	0.0028	1		04/12/11 21:08	106-93-4
1,2-Dichloroethane	ND mg/kg	0.0028	1		04/12/11 21:08	107-06-2
Diisopropyl ether	ND mg/kg	0.0028	1		04/12/11 21:08	108-20-3
Elhanol	ND mg/kg	0.38	1		04/12/11 21:08	64-17-5
Ethylbenzene	ND mg/kg	0.0028	1		04/12/11 21:08	100-41-4
Ethyl-tert-butyl ether	ND mg/kg	0.0028	1		04/12/11 21:08	637-92-3
Methyl-tert-butyl ether	ND mg/kg	0.0028	1		04/12/11 21:08	1634-04-4

Date: 04/22/2011 03:06 PM

REPORT OF LABORATORY ANALYSIS

Page 12 of 31








Project: 256277 257254

Pace Project No.: Sample: MW-9d20 Lab ID: 257254008 Collected: 04/05/11 13:05 Received: 04/08/11 08:15 Matrix: Solid Results reported on a "wet-weight" basis **Parameters** Results Units Report Limit DF Prepared Analyzed CAS No. Qual 8260 MSV 5030 Analytical Method: EPA 8260 Toluene ND mg/kg 0.0028 1 04/12/11 21:08 108-88-3 Xylene (Total) ND mg/kg 0,0085 04/12/11 21:08 1330-20-7 Dibromofluoromethane (S) 94 % 80-136 1 04/12/11 21:08 1868-53-7 Toluene-d8 (S) 101 % 80-120 1 04/12/11 21:08 2037-26-5 4-Bromofluorobenzene (S) 04/12/11 21:08 460-00-4 101 % 72-122 1 04/12/11 21:08 17060-07-0 1,2-Dichloroethane-d4 (S) 94 % 80-143 1 CA LUFT MSV GRO Analytical Method: CALUFT TPH-Gasoline (C05-C12) ND mg/kg 0.24 1 04/12/11 21:08 4-Bromofluorobenzene (S) 101 % 72-122 04/12/11 21:08 460-00-4 Sample: MW-9d24 Lab ID: 257254009 Collected: 04/05/11 13:19 Received: 04/08/11 08:15 Results reported on a "wet-weight" basis Parameters Results Units Report Limit DF Prepared Analyzed CAS No. Qual 8015B CA Diesel Range Org SG Analytical Method: EPA 8015B Preparation Method: EPA 3546 TPH-RRO (C24-C40) SG ND mg/kg 9.9 04/12/11 10:55 04/15/11 21:58 103 % 50-150 04/12/11 10:55 04/15/11 21:58 84-15-1 o-Terphenyl (S) SG 1 115 % 50-150 04/12/11 10:55 04/15/11 21:58 630-02-4 n-Octacosane (S) SG 6010 MET ICP Analytical Method: EPA 6010 Preparation Method: EPA 3050 0.92 04/14/11 14:09 04/18/11 16:33 7439-92-1 Lead 6.4 mg/kg 8260 MSV 5030 Analytical Method; EPA 8260 ND mg/kg tert-Amylmethyl ether 0.0027 1 04/12/11 21:28 994-05-8 ND mg/kg 04/12/11 21:28 71-43-2 Benzene 0.0027 1 tert-Butyl Alcohol 04/12/11 21:28 75-65-0 ND mg/kg 0.014 1 1,2-Dibromoethane (EDB) 04/12/11 21:28 106-93-4 ND mg/kg 0.0027 1 1.2-Dichloroethane ND mg/kg 0.0027 04/12/11 21:28 107-06-2 1 Diisopropyl ether ND mg/kg 0.0027 04/12/11 21:28 108-20-3 1 Ethanol ND mg/kg 0.36 04/12/11 21:28 64-17-5 1 04/12/11 21:28 100-41-4 Ethylbenzene ND mg/kg 0.0027 1 Ethyl-tert-butyl ether 0.0027 04/12/11 21:28 637-92-3 ND mg/kg Methyl-tert-butyl ether ND mg/kg 0.0027 04/12/11 21:28 1634-04-4 Toluene ND mg/kg 0.0027 04/12/11 21:28 108-88-3 Xvlene (Total) ND mg/kg 0.0082 04/12/11 21:28 1330-20-7 Dibromofluoromethane (S) 91 % 80-136 1 04/12/11 21:28 1868-53-7 Toluene-d8 (S) 95 % 80-120 1 04/12/11 21:28 2037-26-5 4-Bromofluorobenzene (S) 105 % 1 04/12/11 21:28 460-00-4 72-122 04/12/11 21:28 17060-07-0 1,2-Dichloroethane-d4 (S) 99 % 80-143 1 **CALUFT MSV GRO** Analytical Method; CA LUFT TPH-Gasoline (C05-C12) ND mg/kg 0.21 04/13/11 15:58

Date: 04/22/2011 03:06 PM

#### REPORT OF LABORATORY ANALYSIS

Page 13 of 31







Project:

256277

Pace Project No.:

257254

Sample: MW-9d24

**CA LUFT MSV GRO** 

Lab ID: 257254009

Collected: 04/05/11 13:19

Report Limit

Received: 04/08/11 08:15

Qual

Qual

CAS No.

Results reported on a "wet-weight" basis

Results Units

Analytical Method: CA LUFT

4-Bromofluorobenzene (S)

103 %

ND mg/kg

103 %

72-122

DF

1

04/13/11 15:58 460-00-4

Analyzed

04/18/11 17:10

04/18/11 17:10 460-00-4

Sample: MW-10d10

Lab ID: 257254010

Collected: 04/05/11 15:13

Received: 04/08/11 08:15

Prepared

Matrix: Solid

CAS No.

Results reported on a "wel-weight" basis sults Units DF Report Limit Prepared Analyzed

Parameters	F	₹e

**Parameters** 

ND mg/kg ND mg/kg 96 % 107 % ytical Method: EPA 6010 P 8.5 mg/kg ytical Method: EPA 8260	2.0 10 50-150 50-150 reparation Meth 0.99	1 1 1 1 od: EF	04/12/11 10:55 04/12/11 10:55 04/12/11 10:55	04/15/11 22:22 04/15/11 22:22 04/15/11 22:22 04/15/11 22:22	
96 % 107 % ytical Method: EPA 6010 P 8.5 mg/kg ytical Method: EPA 8260	50-150 50-150 reparation Meth	1 1 od: EF	04/12/11 10:55 04/12/11 10:55 PA 3050	04/15/11 22:22 04/15/11 22:22	
107 % ytical Method: EPA 6010 P 8.5 mg/kg ytical Method: EPA 8260	50-150 reparation Meth	1 od: EF	04/12/11 10:55 PA 3050	04/15/11 22:22	
ytical Method: EPA 6010 P 8.5 mg/kg ytical Method: EPA 8260	reparation Meth	od: EF	PA 3050		630-02-4
8.5 mg/kg y(ical Method: EPA 8260	•			0.44044.40.07	
y(ical Method; EPA 8260	0.99	1	04/14/11 14:09	0440444007	
			5	04/18/11 16:37	7439-92-1
ND ma/ka					
ND IIIg/kg	0.0025	1		04/18/11 17:10	994-05-8
ND mg/kg	0.0025	1		04/18/11 17:10	71-43-2
ND mg/kg	0.012	1		04/18/11 17:10	75-65-0
ND mg/kg	0.0025	1		04/18/11 17:10	106-93-4
ND mg/kg	0.0025	1		04/18/11 17:10	107-06-2
ND mg/kg	0.0025	1		04/18/11 17:10	108-20-3
ND mg/kg	0.33	1		04/18/11 17:10	64-17-5
ND mg/kg	0.0025	1		04/18/11 17:10	100-41-4
ND mg/kg	0.0025	1		04/18/11 17:10	637-92-3
0.028 mg/kg	0.0025	1		04/18/11 17:10	1634-04-4
ND mg/kg	0.0025	1		04/18/11 17:10	108-88-3
ND mg/kg	0.0075	1		04/18/11 17:10	1330-20-7
103 %	80-136	1		04/18/11 17:10	1868-53-7
94 %	80-120	1		04/18/11 17:10	2037-26-5
103 %	72-122	1		04/18/11 17:10	460-00-4
108 %	80-143	1		04/18/11 17:10	17060-07-0
tical Method: CA LUFT					
	ND mg/kg O.028 mg/kg ND mg/kg ND mg/kg 103 % 94 % 103 % 108 %	ND mg/kg 0.0025 ND mg/kg 0.012 ND mg/kg 0.0025 ND mg/kg 0.0075 103 % 80-136 94 % 80-120 103 % 72-122 108 % 80-143	ND mg/kg 0.0025 1 ND mg/kg 0.012 1 ND mg/kg 0.0025 1 ND mg/kg 0.0075 1 103 % 80-136 1 94 % 80-120 1 103 % 72-122 1 108 % 80-143 1	ND mg/kg	ND mg/kg

Date: 04/22/2011 03:06 PM

TPH-Gasoline (C05-C12)

4-Bromofluorobenzene (S)

REPORT OF LABORATORY ANALYSIS

0.21

72-122

Page 14 of 31





Project: 256277
Pace Project No.: 257254

Sample: MW-10d15 Lab ID: 257254011 Collected: 04/05/11 15:17 Received: 04/08/11 08:15 Matrix: Solid

Results reported on a "wet-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qu
8015B CA Diesel Range Org SG	Analytical Meth	nod: EPA 801	5B Preparation Me	thod: E	PA 3546			
TPH-DRO (C10-C24) SG	ND mg	ı/kg	1.9	1	04/12/11 10:55	04/15/11 23:32		
TPH-RRO (C24-C40) SG	ND mg	_	9.7	1	04/12/11 10:55	04/15/11 23:32		
o-Terphenyl (S) SG	97 %		50-150	1	04/12/11 10:55	04/15/11 23:32	84-15- <b>1</b>	
n-Octacosane (S) SG	106 %		50-150	1	04/12/11 10:55	04/15/11 23:32	630-02-4	
6010 MET (CP	Analytical Meth	od: EPA 601	0 Preparation Meth	nod: EP	A 3050			
Lead	<b>6.1</b> mg	/kg	0.76	1	04/14/11 14:09	04/18/11 16:40	7439-92-1	
8260 MSV 5030	Analytical Meth	od: EPA 826	0					
ert-Amylmethyl ether	ND mg	/kg	0.0026	1		04/13/11 16:57	994-05-8	
Benzene	ND mg	/kg	0.0026	1		04/13/11 16:57	71-43-2	
ert-Butyl Alcohol	ND mg	/kg	0.013	1		04/13/11 16:57	75-65-0	
1,2-Dibromoethane (EDB)	ND mg	/kg	0.0026	1		04/13/11 16:57	106-93-4	
1,2-Dichloroethane	ND mg	/kg	0.0026	1		04/13/11 16:57	107-06-2	
Diisopropyl ether	ND mg	/kg	0.0026	1		04/13/11 16:57	108-20-3	
Elhanol	ND mg		0.34	1		04/13/11 16:57	64-17-5	
Elhylbenzene	0.0039 mg	-	0.0026	1		04/13/11 16:57	100-41-4	
Ethyl-tert-butyl ether	ND mg	-	0.0026	1		04/13/11 16:57	637-92-3	
Methyl-tert-butyl ether	ND mg	-	0.0026	1		04/13/11 16:57		
Toluene	ND mg	-	0.0026	1		04/13/11 16:57		
(Ylene (Total)	0.012 mg	~	0,0077	1		04/13/11 16:57		
Dibromofluoromethane (S)	90 %		80-136	1		04/13/11 16:57		
Toluene-d8 (S)	103 %		80-120	1		04/13/11 16:57		
4-Bromofluorobenzene (S)	104 %		72-122	1		04/13/11 16:57		
I,2-Dichloroethane-d4 (S)	94 %		80-143	1		04/13/11 16:57		
CA LUFT MSV GRO	Analytical Meth-	od: CA LUFT						
TPH-Gasoline (C05-C12)	ND mg/	/ka	0.25	1		04/18/11 18:09		
1-Bromofluorobenzene (S)	103 %		72-122	1		04/18/11 18:09	460-00-4	
Control of Maria 10 100	1 - L ID - 0570	F4040	2-11-1- L 0.10-14	1.45.00		10044 00 45 - 1	Lucio de Bal	
Sample: MW-10d20	Lab ID: 2572	54012	Collected: 04/05/11	15:23	Received: 04	/U8/11 U8:15 M	latrix: Solid	
Results reported on a "wet-weight"								
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
1015B CA Diesel Range Org SG	Analytical Metho	od: EPA 8015	B Preparation Met	hod: El	PA 3546			
PH-DRO (C10-C24) SG	ND mg/	'kg	2.0	1	04/12/11 10:55	04/15/11 23:56		
TPH-RRO (C24-C40) SG	ND mg/		9.9	1	04/12/11 10:55	04/15/11 23:56		
o-Terphenyl (S) SG	96 %		50-150	1	04/12/11 10:55	04/15/11 23:56	84-15- <b>1</b>	
1-Octacosane (S) SG	107 %		50-150	1	0.4/4.9/44.40-55	04/15/11 23:56	600.00.4	

Date: 04/22/2011 03:06 PM

6010 MET ICP

Lead

#### **REPORT OF LABORATORY ANALYSIS**


0.69

Analytical Method: EPA 6010 Preparation Method: EPA 3050

5.8 mg/kg

Page 15 of 31

04/14/11 14:09 04/18/11 16:44 7439-92-1







Project:

256277

Pace Project No.: 257254

Sample: MW-10d20

Lab ID: 257254012

Collected: 04/05/11 15:23 Received: 04/08/11 08:15 Matrix: Solid

Parameters	Results Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8260 MSV 5030	Analytical Method: EPA 82	60					
tert-Amylmethyl ether	ND mg/kg	0.0026	1		04/13/11 17:17	994-05-8	
Benzene	ND mg/kg	0.0026	1		04/13/11 17:17	71-43-2	
lert-Butyl Alcohol	ND mg/kg	0.013	1		04/13/11 17:17	75-65-0	
1,2-Dibromoethane (EDB)	ND mg/kg	0.0026	1		04/13/11 17:17	106-93-4	
1,2-Dichloroethane	ND mg/kg	0.0026	1		04/13/11 17:17	107-06-2	
Diisopropyl ether	ND mg/kg	0.0026	1		04/13/11 17:17	108-20-3	
Ethanol	ND mg/kg	0.34	1		04/13/11 17:17	64-17-5	
Ethylbenzene	ND mg/kg	0.0026	1		04/13/11 17:17	100-41-4	
Ethyl-lert-butyl ether	ND mg/kg	0.0026	1		04/13/11 17:17	637-92-3	
Melhyl-tert-butyl ether	ND mg/kg	0.0026	1		04/13/11 17:17	1634-04-4	
Toluene	ND mg/kg	0.0026	1		04/13/11 17:17	108-88-3	
Xylene (Total)	ND mg/kg	0.0077	1		04/13/11 17:17	1330-20-7	
Dibromofluoromethane (S)	90 %	80-136	1		04/13/11 17:17	1868-53-7	
Toluene-d8 (S)	102 %	80-120	1		04/13/11 17:17	2037-26-5	
4-Bromofluorobenzene (S)	103 %	72-122	1		04/13/11 17:17	460-00-4	
1,2-Dichloroethane-d4 (S)	101 %	80-143	1		04/13/11 17:17	17060-07-0	
CA LUFT MSV GRO	Analytical Method: CA LUF	T					
TPH-Gasoline (C05-C12)	ND mg/kg	0.22	1		04/13/11 17:17		
4-Bromofluorobenzene (S)	103 %	72-122	1		04/13/11 17:17	460-00-4	





Project:

256277

Pace Project No.:

257254

QC Batch:

OEXT/3558

Analysis Method:

EPA 8015B

QC Batch Method: I

EPA 3546

Analysis Description:

EPA 8015B CA TPH Silca Gel

140

50-150

Associated Lab Samples:

257254001, 257254002, 257254003, 257254004, 257254005, 257254006, 257254007, 257254008, 257254009, 257254010, 257254011, 257254012

METHOD BLANK: 66591

Matrix: Solid

Associated Lab Samples:

o-Terphenyl (S) SG

257254001, 257254002, 257254003, 257254004, 257254005, 257254006, 257254007, 257254008, 257254009,

257254010, 257254011, 257254012

Reporting Blank Parameter Units Result Limit Analyzed Qualifiers TPH-DRO (C10-C24) SG ND 2.0 04/15/11 19:14 mg/kg TPH-RRO (C24-C40) SG ND 10.0 04/15/11 19:14 mg/kg n-Octacosane (S) SG 108 04/15/11 19:14 % 50-150 o-Terphenyl (S) SG 04/15/11 19:14 % 94 50-150

LABORATORY CONTROL SAMPLE: 66592

Parameter	Units	Spike Conc.	LCS Result	LCS % Rec	% Rec Limits	Qualifiers
TPH-DRO (C10-C24) SG	mg/kg	83.3	80.4	97	56-124	
TPH-RRO (C24-C40) SG	mg/kg	83.3	85.1	102	50-150	
n-Octacosane (S) SG	%			112	50-150	

MATRIX SPIKE & MATRIX SI	PIKE DUPLICA	TE: 66593			66594						
Parameter	Units	257254002 Result	MS Spike Conc.	MSD Spike Conc.	MS Result	MSD Result	MS % Rec	MSD % Rec	% Rec Limits	RPD	Qual
TPH-DRO (C10-C24) SG	mg/kg	68.1	83.2	83.1	157	147	107	95	56-124	7	
TPH-RRO (C24-C40) SG	mg/kg	788	83.2	83.1	973	821	223	40	50-150	17 M6	
n-Octacosane (S) SG	%						0	0	50-150	S4	
o-Terphenyl (S) SG	%						0	0	50-150	S4	





Project:

256277

Pace Project No.:

257254

QC Batch:

MPRP/2157

Analysis Method:

EPA 6010

QC Batch Method:

EPA 3050

Analysis Description:

6010 MET

Associated Lab Samples:

257254001, 257254002, 257254003, 257254004, 257254005, 257254006, 257254007, 257254008, 257254009,

257254010, 257254011, 257254012

METHOD BLANK: 66918

Matrix: Solid

Associated Lab Samples:

257254001, 257254002, 257254003, 257254004, 257254005, 257254006, 257254007, 257254008, 257254009,

257254010, 257254011, 257254012

Blank

Reporting

Parameter

Units

Limit

Analyzed Qualifiers

Lead

mg/kg

Result ND

25

1.0 04/18/11 14:34

105

LABORATORY CONTROL SAMPLE:

Parameter

Parameter

66919

mg/kg

Spike Conc.

LCS Result

LCS % Rec % Rec Limits

80-120

Qualifiers

MATRIX SPIKE & MATRIX SPIKE DUPLICATE:

Result

66920

15.9

Units

MSD

23.2

26.2

66921

MSD

MS

MSD

% Rec

Qual

Lead

Lead

257220001

Units

mg/kg

MS Spike Conc.

22.7

Spike Conc.

MS Result

37.8

Result 35.7 % Rec % Rec Limits

RPD

75-125





Project:

256277

Pace Project No.:

257254

QC Batch:

MSV/4278

QC Batch Method;

EPA 5030

Analysis Method:

EPA 8260

Analysis Description:

8260 MSV 5030 Medium Soil

Associated Lab Samples:

METHOD BLANK: 67066

Matrix: Solid

Associated Lab Samples:

257254001

257254001

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
Ethylbenzene	mg/kg		0.050	04/18/11 10:54	
Xylene (Total)	mg/kg	ND	0.15	04/18/11 10:54	
1,2-Dichloroethane-d4 (S)	%	96	76-115	04/18/11 10:54	
4-Bromofluorobenzene (S)	%	95	78-127	04/18/11 10:54	
Dibromofluoromethane (S)	%	96	81-114	04/18/11 10:54	
Toluene-d8 (S)	%	97	84-121	04/18/11 10:54	

LABORATORY CONTROL SAMPLE: 67067

Parameter	Units	Spike Conc.	LCS Result	LCS % Rec	% Rec Limits	Qualifiers
Ethylbenzene	mg/kg		1.1	108	74-120	
Xylene (Total)	mg/kg	3	3.2	106	76-120	
1,2-Dichloroethane-d4 (S)	%			96	76-115	
4-Bromofluorobenzene (S)	%			100	78-127	
Dibromofluoromethane (S)	%			99	81-114	
Toluene-d8 (S)	%			99	84-121	

MATRIX SPIKE & MATRIX SP	IKE DUPLICA	TE: 67117			671 <b>18</b>						
Parameter	Units	257254001 Resull	MS Spike Coric.	MSD Spike Conc.	MS Result	MSD Result	MS % Rec	MSD % Rec	% Rec Limits	RPD	Qual
Ethylbenzene	mg/kg	4.3	.9	.9	5.1	5.1	89	83	77-126		
Xylene (Total)	mg/kg	8.4	2.7	2.7	11.0	10.9	94	91	77-127	.7	
1,2-Dichloroethane-d4 (S)	%						93	98	76-115		
4-Bromoffuorobenzene (S)	%						99	97	78-127		
Dibromofluoromethane (S)	%						98	99	81-114		
Toluene-d8 (S)	%						100	98	84-121		





Project: Pace Project No.: 256277

257254

QC Batch:

MSV/4244

Analysis Method:

EPA 8260

QC Batch Method:

EPA 8260

Analysis Description:

8260 MSV 5030 Volatile Organics

Associated Lab Samples:

257254001, 257254002, 257254003, 257254004, 257254005, 257254006, 257254007, 257254008, 257254009

METHOD BLANK: 66690

Matrix: Solid

Associated Lab Samples:

257254001, 257254002, 257254003, 257254004, 257254005, 257254006, 257254007, 257254008, 257254009

		Blank	Reporting		
Parameter Parameter	Units	Result	Limit	Analyzed	Qualifiers
1,2-Dibromoethane (EDB)	mg/kg	ND	0.0030	04/12/11 15:13	<u> </u>
1,2-Dichloroethane	mg/kg	ND	0.0030	04/12/11 15:13	
Benzene	mg/kg	ND	0.0030	04/12/11 15:13	
Diisopropyl ether	mg/kg	ND	0.0030	04/12/11 15:13	
Ethanol	mg/kg	ND	0.40	04/12/11 15:13	
Ethyl-tert-butyl ether	mg/kg	ND	0.0030	04/12/11 15:13	
Ethylbenzene	mg/kg	ND	0.0030	04/12/11 15:13	
Methyl-tert-butyl ether	mg/kg	ND	0.0030	04/12/11 15:13	
tert-Amylmethyl ether	mg/kg	ND	0.0030	04/12/11 15:13	
tert-Butyl Alcohol	mg/kg	ND	0.015	04/12/11 15:13	
Toluene	mg/kg	ND	0.0030	04/12/11 15:13	
Xylene (Total)	mg/kg	ND	0.0090	04/12/11 15:13	
1,2-Dichloroethane-d4 (S)	%	96	80-143	04/12/11 15:13	
4-Bromofluorobenzene (S)	%	101	72-122	04/12/11 15:13	
Dibromofluoromethane (S)	%	94	80-136	04/12/11 15:13	
Toluene-d8 (S)	%	100	80-120	04/12/11 15:13	

LABORATORY CONTROL SAMPLE: 66691

		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
1,2-Dibromoethane (EDB)	mg/kg	.05	0.057	115	71-123	
1,2-Dichloroethane	mg/kg	.05	0.056	112	70-124	
Benzene	mg/kg	.05	0.052	105	75-133	
Diisopropyl ether	mg/kg	.05	0.052	104	63-139	
Ethanol	mg/kg	1	1.0	103	53-134	
Elhyl-tert-bulyl ether	mg/kg	.05	0.050	99	63-135	
Elhylbenzene	mg/kg	.05	8.050	100	68-13 <b>1</b>	
Methyl-tert-butyl ether	mg/kg	.05	0.052	103	52-143	
tert-Amylmethyl ether	mg/kg	.05	0.053	105	62-138	
tert-Bulyl Alcohol	mg/kg	.25	0.27	109	35-151	
Toluene	mg/kg	.05	0.053	107	73-124	
Xylene (Totat)	mg/kg	.15	0.16	104	68-130	
1,2-Dichloroethane-d4 (S)	%			99	80-143	
4-Bromofluorobenzene (S)	%			98	72-122	
Dibromofluoromethane (S)	%			98	80-136	
Toluene-d8 (S)	%			<b>1</b> 01	80-120	

Date: 04/22/2011 03:06 PM REPORT OF LABORATORY ANALYSIS Page 20 of 31







Project: 256277 Pace Project No.: 257254

MATRIX SPIKE & MATRIX SP	PIKE DUPLICA	ATE: 66777			66778						
			MS	MSD							
		257305001	Spike	Spike.	MS	MSD	MS	MSD	% Rec	-	
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limils	RPD	Qual
1,2-Dibromoethane (EDB)	mg/kg	ND ND	.05	.05	0.042	0.033	85	66	71-123	26 N	 11
1,2-Dichloroethane	mg/kg	ND	.05	.05	0.037	0.032	74	64	71-124	15 N	<b>1</b> 1
Benzene	mg/kg	ND	.05	.05	0.042	0.038	84	77	68-124	9	
Diisopropyl ether	mg/kg	ND	.05	.05	0.041	0.035	83	71	20-160	15	
Ethanol	rng/kg	ND	1	1	0.58	0.78	58	78	60-140	30 N	11
Ethyl-tert-butyl ether	mg/kg	ND	.05	.05	0.039	0.037	78	74	70-140	5	
Ethylbenzene	mg/kg	ND	.05	.05	0.044	0.047	87	94	63-131	8	
Methyl-terl-bulyl ether	mg/kg	ND	.05	.05	0.038	0.043	75	85	68-139	13	
ert-Amylmethyl ether	mg/kg	ND	.05	.05	0.038	0.034	75	69	74-125	9 N	11
ert-Butyl Alcohol	mg/kg	ND	.25	.25	0.12	0.14	47	54	49-122	14 N	11
Toluene	mg/kg	ND	.05	.05	0.055	0.049	106	94	61-126	11	
(ylene (Total)	mg/kg	ND	.15	.15	0.13	0.13	80	86	68-129	6	
,2-Dichloroethane-d4 (S)	%						90	74	80-143	S	2
-Bromofluorobenzene (S)	%						145	135	72-122	S	2
ibromofluoromethane (S)	%						90	71	80-136	S	2
oluene-d8 (S)	%						126	118	80-120	S	2

Date: 04/22/2011 03:06 PM

REPORT OF LABORATORY ANALYSIS

Page 21 of 31





Project:

256277

Pace Project No.:

257254

QC Batch:

MSV/4247

Analysis Method:

EPA 8260

QC Batch Method:

EPA 8260

Analysis Description:

8260 MSV 5030 Volatile Organics

Associated Lab Samples:

257254011, 257254012

METHOD BLANK: 66720

Matrix: Solid

Associated Lab Samples:

257254011, 257254012

20.	201011, 20, 201012	Dlopk	Reporting		
Parameter	Units	Blank Result	Limit	Analyzed	Qualifiers
1,2-Dibromoelhane (EDB)	mg/kg	ND	0.0030	04/13/11 10:21	
1,2-Dichloroethane	mg/kg	ND	0.0030	04/13/11 10:21	
Benzene	mg/kg	ND	0.0030	04/13/11 10:21	
Diisopropyl ether	mg/kg	ND	0.0030	04/13/11 10:21	
Ethanol	mg/kg	ND	0.40	04/13/11 10:21	
Ethyl-tert-butyl ether	mg/kg	ND	0.0030	04/13/11 10:21	
Ethylbenzene	mg/kg	ND	0.0030	04/13/11 10:21	
Methyl-tert-butyl ether	mg/kg	ND	0.0030	04/13/11 10:21	
tert-Amylmethyl ether	mg/kg	ND	0.0030	04/13/11 10:21	
tert-Bulyl Alcohol	mg/kg	ND	0.015	04/13/11 10:21	
Toluene	mg/kg	ND	0.0030	04/13/11 10:21	
Xylene (Total)	mg/kg	ND	0.0090	04/13/11 10:21	
1,2-Dichloroethane-d4 (S)	%	99	80-143	04/13/11 10:21	
4-Bromofluorobenzene (S)	%	105	72-122	04/13/11 10:21	
Dibromofluoromethane (S)	%	99	80-136	04/13/11 10:21	
Toluene-d8 (S)	%	103	80-120	04/13/11 10:21	
roluene-us (S)	%	103	80-120	04/13/11 10:21	


LABORATORY	CONTROL	SAMPLE:	66721

Parameter	Units	Spike Conc.	LCS Result	LCS % Rec	% Rec Limils	Qualifiers
1,2-Dibromoethane (EDB)	mg/kg	.05	0.053	105	71-123	
1,2-Dichloroethane	mg/kg	.05	0.053	105	70-124	
Benzene	mg/kg	.05	0.056	112	75-133	
Diisopropyl elher	mg/kg	.05	0.060	120	63-139	
Ethanol	mg/kg	1	1.1	113	53-134	
Ethyl-tert-butyl ether	mg/kg	.05	0.056	111	63-135	
Ethylbenzene	mg/kg	.05	0.054	107	68-131	
Methyl-tert-butyl ether	mg/kg	.05	0.059	117	52-143	
tert-Amylmethyl ether	mg/kg	.05	0.057	113	62-138	
tert-Butyl Alcohol	mg/kg	.25	0.27	107	35-151	
Toluene	mg/kg	.05	0.060	121	73-124	
Xylene (Total)	mg/kg	.15	0.17	111	68-130	
1,2-Dichloroethane-d4 (S)	, %			96	80-143	
4-Bromofluorobenzene (S)	%			94	72-122	
Dibromofluoromethane (S)	%			104	80-136	
Toluene-d8 (S)	%			101	80-120	

Date: 04/22/2011 03:06 PM

**REPORT OF LABORATORY ANALYSIS** 

Page 22 of 31







Project: 256277
Pace Project No.: 257254

MATRIX SPIKE & MATRIX SF	PIKE DUPLICA	TE: 67144	•	•	67145	•					
			MS	MSD							
Dozonalas	l Indian	257267001	Spike	Spike	MS	MSD	MS % Date	MSD	% Rec	DDD	Ound
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limils	RPD _	Qual
1,2-Dibromoelhane (EDB)	mg/kg	ND	.063	.063	0.063	0.064	100	102	71-123	2	
1,2-Dichloroethane	mg/kg	ND	.063	.063	0.064	0.060	101	95	71-124	6	
Benzene	mg/kg	ND	.063	.063	0.062	0.061	99	97	68-124	2	
Diisopropyl ether	mg/kg	ND	.063	.063	0.065	0.065	104	104	20-160	.1	
∃thanol	mg/kg	ND	1.3	1.3	1.3	1.1	101	87	60-140	15	
Ethyl-tert-butyl ether	mg/kg	ND	.063	.063	0.062	0.063	98	100	70-140	2	
Ethylbenzene	mg/kg	ND	.063	.063	0.060	0.060	95	95	63-131	.5	
Methyl-terl-bulyl ether	mg/kg	ND	.063	.063	0.064	0.066	102	104	68-139	2	
ert-Amylmethyl ether	mg/kg	ND	.063	.063	0.063	0.064	99	102	74-125	2	
ert-Butyl Alcohol	mg/kg	ND	.32	.32	0.30	0.30	95	96	<del>49</del> -122	1	
foluene	mg/kg	ND	.063	.063	0.064	0.065	101	102	61-126	1	
(ylene (Total)	mg/kg	ND	.19	.19	0.18	0.18	98	96	68-129	1	
,2-Dichloroethane-d4 (S)	%						99	96	80-143		
-Bromofluorobenzene (S)	%						101	101	72-122		
Dibromofluoromethane (S)	%						100	96	80-136		
foluene-d8 (S)	%						102	104	80-120		

Date: 04/22/2011 03:06 PM

REPORT OF LABORATORY ANALYSIS





Project:

256277

Pace Project No.:

QC Batch Method:

257254

QC Batch:

MSV/4291

EPA 8260

Analysis Method:

EPA 8260

Analysis Description:

8260 MSV 5030 Volatile Organics

Associated Lab Samples:

METHOD BLANK: 67204

Matrix: Solid

Associated Lab Samples:

257254010

257254010

Participant of the properties			Blank	Reporting		
P-Dichloroethane mg/kg ND 0.0030 04/18/11 09:33 mzene mg/kg ND 0.0030 04/18/11 09:33 mzene mg/kg ND 0.0030 04/18/11 09:33 manol mg/kg ND 0.0030 04/18/11 09:33 manol mg/kg ND 0.0030 04/18/11 09:33 myl-tert-butyl ether mg/kg ND	Parameter	Units	Result	Limit	Analyzed	Qualifiers
mg/kg ND 0.0030 04/18/11 09:33 sopropyl ether mg/kg ND 0.0030 04/18/11 09:33 manol mg/kg ND 0.40 04/18/11 09:33 myl-tert-butyl ether mg/kg ND 0.0030 04/18/11 09:33 myl-tert-butyl ether mg/kg ND 0.015 04/18/11 09:33 myl-tert-butyl ether mg/kg ND 0.0030 04/18/11 09:33 myl-tert-bu	1,2-Dibromoethane (EDB)	mg/kg	ND	0.0030	04/18/11 09:33	
sopropyl ether mg/kg ND 0.0030 04/18/11 09:33 manol mg/kg ND 0.40 04/18/11 09:33 manol mg/kg ND 0.0030 04/18/11 09:33 myl-tert-butyl ether mg/kg ND 0.0030 04/18/11 09:33 mg/kg ND 0.0030 04/18/11 09:33 mg/kg ND 0.015 04/18/11 09:33 mg/kg ND 0.0030 04/18/11 09:33 mg/kg ND 0.0030 04/18/11 09:33 mg/kg ND 0.0030 04/18/11 09:33 mg/kg ND 0.0090 04/18/11 09:33 mg/kg MD 0.0090	1,2-Dichloroethane	mg/kg	ND	0.0030	04/18/11 09:33	
manol mg/kg ND 0.40 04/18/11 09:33 mg/kg ND 0.0030 04/18/11 09:33 myl-tert-butyl ether mg/kg ND 0.0030 04/18/11 09:33 mylbenzene mg/kg ND 0.0030 04/18/11 09:33 mg/kg ND 0.015 04/18/11 09:33 mg/kg ND 0.0030 04/18/11 09:33 mg/kg ND 0.0030 04/18/11 09:33 mg/kg ND 0.0030 04/18/11 09:33 mg/kg ND 0.0090 04/18/11 09	Benzene	mg/kg	ND	0.0030	04/18/11 09:33	
nyl-tert-butyl ether mg/kg ND 0.0030 04/18/11 09:33 mg/kg ND 0.015 04/18/11 09:33 mg/kg ND 0.015 04/18/11 09:33 mg/kg ND 0.0030 04/18/11 09:33 mg/kg ND 0.0030 04/18/11 09:33 mg/kg ND 0.0090 04/18/11 09:33 mg/kg ND 0.0	Diisopropyl ether	mg/kg	ND	0.0030	04/18/11 09:33	
nylbenzene         mg/kg         ND         0.0030         04/18/11 09:33           sthyl-tert-butyl ether         mg/kg         ND         0.0030         04/18/11 09:33           t-Amylmethyl ether         mg/kg         ND         0.0030         04/18/11 09:33           t-Butyl Alcohol         mg/kg         ND         0.015         04/18/11 09:33           tuene         mg/kg         ND         0.0030         04/18/11 09:33           tene (Total)         mg/kg         ND         0.0090         04/18/11 09:33           t-Dichloroethane-d4 (S)         %         95         80-143         04/18/11 09:33           bromofluorobenzene (S)         %         103         72-122         04/18/11 09:33           bromofluoromethane (S)         %         100         80-136         04/18/11 09:33	Ethanol	mg/kg	ND	0.40	04/18/11 09:33	
thyl-tert-butyl ether mg/kg ND 0.0030 04/18/11 09:33 t-Amylmethyl ether mg/kg ND 0.0030 04/18/11 09:33 t-Amylmethyl ether mg/kg ND 0.0030 04/18/11 09:33 t-Butyl Alcohol mg/kg ND 0.015 04/18/11 09:33 tuene mg/kg ND 0.0030 04/18/11 09:33 tuene (Total) mg/kg ND 0.0090 04/18/11 09:33 tene (Total) % 95 80-143 04/18/11 09:33 tene (Total) % 103 72-122 04/18/11 09:33 tene (Total) % 103 72-122 04/18/11 09:33 tenenofluoromethane (S) % 100 80-136 04/18/11 09:33	Ethyl-tert-butyl ether	mg/kg	ND	0.0030	04/18/11 09:33	
t-Amylmethyl ether mg/kg ND 0.0030 04/18/11 09:33 t-Butyl Alcohol mg/kg ND 0.015 04/18/11 09:33 tuene mg/kg ND 0.0030 04/18/11 09:33 tuene (Total) mg/kg ND 0.0090 04/18/11 09:33 tene (Total) % 95 80-143 04/18/11 09:33 tene (Total) % 95 80-143 04/18/11 09:33 tene (Total) % 103 72-122 04/18/11 09:33 tene (Total) % 100 80-136	Ethylbenzene	mg/kg	ND	0.0030	04/18/11 09:33	
t-Butyl Alcohol mg/kg ND 0.015 04/18/11 09:33 tuene mg/kg ND 0.0030 04/18/11 09:33 tene (Total) mg/kg ND 0.0090 04/18/11 09:33 t-Dichloroethane-d4 (S) % 95 80-143 04/18/11 09:33 tromofluorobenzene (S) % 103 72-122 04/18/11 09:33 tromofluoromethane (S) % 100 80-136 04/18/11 09:33	Methyl-tert-butyl ether	mg/kg	ND	0.0030	04/18/11 09:33	
duene         mg/kg         ND         0.0030         04/18/11 09:33           elene (Total)         mg/kg         ND         0.0090         04/18/11 09:33           d-Dichloroethane-d4 (S)         %         95         80-143         04/18/11 09:33           dromofluorobenzene (S)         %         103         72-122         04/18/11 09:33           poromofluoromethane (S)         %         100         80-136         04/18/11 09:33	tert-Amylmethyl ether	mg/kg	ND	0.0030	04/18/11 09:33	
lene (Total) mg/kg ND 0.0090 04/18/11 09:33 2-Dichloroethane-d4 (S) % 95 80-143 04/18/11 09:33 3-Cromofluorobenzene (S) % 103 72-122 04/18/11 09:33 3-Cromofluoromethane (S) % 100 80-136 04/18/11 09:33	tert-Butyl Alcohol	mg/kg	ND	0.015	04/18/11 09:33	
P-Dichloroethane-d4 (S) % 95 80-143 04/18/11 09:33 95 970 970 970 970 970 970 970 970 970 970	Toluene	mg/kg	ND	0.0030	04/18/11 09:33	
Bromofluorobenzene (S)     %     103     72-122     04/18/11 09:33       bromofluoromethane (S)     %     100     80-136     04/18/11 09:33	Xylene (Total)	mg/kg	ND	0.0090	04/18/11 09:33	
oromofluoromethane (S) % 100 80-136 04/18/11 09;33	1,2-Dichloroethane-d4 (S)	%	95	80-143	04/18/11 09:33	
	4-Bromofluorobenzene (S)	%	103	72-122	04/18/11 09:33	
uene-d8 (S) % 94 80-120 04/18/11 09:33	Dibromofluoromethane (S)	%	100	80-136	04/18/11 09;33	
70 00 120 0 11 10 11 00 00	Toluene-d8 (S)	%	94	80-120	04/18/11 09:33	

LABORATORY CONTROL SAMI	PLE & LCSD: 67205		67	'206	_					
		Spike	LCS	LCSD	LCS	LCSD	% Rec		Max	
Parameter	Units	Conc.	Result	Result	% Rec	% Rec	Limils	RPD	RPD	Qualifiers
1,2-Dibromoethane (EDB)	mg/kg	.05	0.052	0.053	104	105	71-123	1	30	
1,2-Dichloroethane	mg/kg	.05	0.059	0.059	118	118	70-124	.4	30	
Benzene	mg/kg	.05	0.058	0.058	117	115	75-133	2	30	
Diisopropyl ether	mg/kg	.05	0.054	0.054	109	108	63-139	.1	30	
Ethanol	mg/kg	1	0.89	1.0	89	102	53-134	13	30	
Elhyl-tert-butyl ether	mg/kg	.05	0.054	0.054	108	108	63-135	.2	30	
Elhylbenzene	mg/kg	.05	0.049	0.049	98	98	68-131	.3	30	
Methyl-tert-butyl ether	mg/kg	.05	0.057	0.056	113	113	52-143	.6	30	
tert-Amylmethyl ether	mg/kg	.05	0.057	0.056	113	113	62-138	.8	30	
tert-Butyl Alcohol	mg/kg	.25	0.26	0.26	105	104	35-151	2	30	
Toluene	mg/kg	.05	0.055	0.055	110	109	73-124	.7	30	
Xylene (Total)	mg/kg	.15	0.16	0.16	104	103	68-130	1	30	
1,2-Dichloroethane-d4 (S)	%				99	99	80-143			
4-Bromofluorobenzene (S)	%				97	100	72-122			
Dibromofluoromethane (S)	%				103	104	80-136			
Toluene-d8 (S)	%				91	93	80-120			





Project:

256277

Pace Project No.:

257254

QC Batch:

MSV/4277

QC Batch Method:

CA LUFT

Analysis Method:

CALUFT

Analysis Description:

CALUFT MSV GRO

Associated Lab Samples:

METHOD BLANK: 67064

Parameter

Parameter

257254001

Malrix: Solid

Associated Lab Samples:

257254001

Units

Blank Result Reporting Limit

Analyzed

Qualifiers

TPH-Gasoline (C05-C12) 4-Bromofluorobenzene (S)

mg/kg

ND 95

2.5 04/18/11 10:54 72-122 04/18/11 10:54

LABORATORY CONTROL SAMPLE & LCSD:

67065

67202 Spike LCS Conc. Result

LCSD LCS 25.5

LCSD % Rec % Rec

% Rec Limits 60-140

Max RPD

RPD Qualifiers

TPH-Gasoline (C05-C12) 4-Bromofluorobenzene (S)

%

mg/kg

Units

25

26.9

Result

108 95

102 94 72-122

5

30





Project:

256277

Pace Project No.:

257254

QC Batch:

MSV/4252

Analysis Method:

CALUFT

QC Batch Method:

**CALUFT** 

Analysis Description:

CALUFT MSV GRO

Associated Lab Samples:

257254002, 257254003, 257254004, 257254005, 257254006, 257254007, 257254008

METHOD BLANK: 66792 Associated Lab Samples:

257254002, 257254003, 257254004, 257254005, 257254006, 257254007, 257254008

Matrix: Solid

Blank

Reporting

Parameter	
TPH-Gasoline (C05-C12)	

Units

Units

Result

Limit Analyzed Qualifiers

4-Bromofluorobenzene (S)

mg/kg %

ND 101

0.25 04/12/11 15:13 72-122 04/12/11 15:13

LABORATORY CONTROL SAMPLE:

Parameter

66793

mg/kg

%

mg/kg

	Spike Conc.
_	

LCS Result 0.48

LCS % Rec 97

100

% Rec Limits

60-140 72-122

MATRIX SPIKE & MATRIX SPIKE DUPLICATE:

67150

Parameter TPH-Gasoline (C05-C12) 4-Bromofluorobenzene (S)

TPH-Gasoline (C05-C12)

4-Bromofluorobenzene (S)

MS 257254002 Spike Units Result Conc. 0.90

MSD Spike Conc. .42 .36

MS MSD Result Result 1.4 0.97

MS % Rec 121 125

% Rec Limits 19 116

% Rec

MSD

Qualifiers

60-140 72-122

RPD

37 D6,M1 S0

Qual







Project:

256277

Pace Project No.:

257254

QC Batch:

MSV/4253

Analysis Method:

CALUFT

QC Batch Method: Associated Lab Samples:

**CALUFT** 

Analysis Description:

Matrix: Solid

CALUFT MSV GRO

METHOD BLANK: 66794

Units

257254009, 257254012

257254009, 257254012

Blank Result

Reporting Limit

Analyzed

Parameter TPH-Gasoline (C05-C12) 4-Bromofluorobenzene (S)

Associated Lab Samples:

mg/kg

%

ND 105

0.25 04/13/11 10:21 72-122 04/13/11 10:21 Qualifiers

LABORATORY CONTROL SAMPLE:

Parameter

MATRIX SPIKE & MATRIX SPIKE DUPLICATE:

66795

Spike Conc.

LCS Result

LCS % Rec % Rec Limits

Qualifiers

TPH-Gasoline (C05-C12) 4-Bromofluorobenzene (S)

%

Units

Units mg/kg

.5

0.52

66982

MS

103 104

60-140 72-122

66981

Result

MSD

MSD

MS % Rec MSD

% Rec

RPD Qual

TPH-Gasoline (C05-C12)

257350001 Spike

MS

Spike

Result

Result

% Rec 1

Limits

4-Bromofluorobenzene (S)

Parameter

%

0.41 mg/kg

Conc. Conc. .39

.4 0.41

0.60

49 103

60-140

38 D6,M1

117 72-122





Project:

256277

Pace Project No.:

257254

QC Batch:

MSV/4289

Analysis Method:

**CALUFT** 

QC Batch Method:

**CALUFT** 

Analysis Description:

CALUFT MSV GRO

Associated Lab Samples:

257254010, 257254011

METHOD BLANK: 67196

Matrix: Solid

Associated Lab Samples:

257254010, 257254011

%

%

Blank

Reporting

Parameter

Parameter

Units

Result

Limit

Analyzed Qualifiers

TPH-Gasoline (C05-C12) 4-Bromofluorobenzene (S) mg/kg

ND 99

0.25 04/18/11 16:31 72-122 04/18/11 16:31

LABORATORY CONTROL SAMPLE & LCSD:

Spike

67198 LCSD LCS LCSD

% Rec

Max RPD Qualifiers

TPH-Gasoline (C05-C12) 4-Bromofluorobenzene (S)

Date: 04/22/2011 03:06 PM

mg/kg

Units

Conc. .5

LCS Result Result 0.49 0.48

% Rec % Rec 98 102

96 99 2

RPD 30

72-122

60-140

Limits

This report shall not be reproduced, except in full,



#### **QUALIFIERS**

Project: 256277 Pace Project No.: 257254

#### **DEFINITIONS**

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to changes in sample preparation, dilution of the sample aliquot, or moisture content.

ND - Not Detected at or above adjusted reporting limit.

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

S - Surrogate

1,2-Diphenylhydrazine (8270 listed analyte) decomposes to Azobenzene.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

DUP - Sample Duplicate

RPD - Relative Percent Difference

NC - Not Calculable.

SG - Silica Gel Clean-Up

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Pace Analytical is NELAP accredited. Contact your Pace PM for the current list of accredited analytes.

#### **LABORATORIES**

PASI-S Pace Analytical Services - Seattle

#### **BATCH QUALIFIERS**

Batch: MSV/4277

[M5] A matrix spike/matrix spike duplicate was not performed for this batch due to insufficient sample volume.

Batch: MSV/4289

[M5] A matrix spike/matrix spike duplicate was not performed for this batch due to insufficient sample volume.

Batch: MSV/4290

[M5] A matrix spike/matrix spike duplicate was not performed for this batch due to insufficient sample volume.

Balch: MSV/4291

[M5] A matrix spike/matrix spike duplicate was not performed for this batch due to insufficient sample volume.

#### **ANALYTE QUALIFIERS**

Date: 04/22/2011 03:06 PM

D6	The relative percent difference (RPD) between the sample and sample duplicate exceeded laboratory control limits.
M1	Matrix spike recovery exceeded QC limits. Batch accepted based on laboratory control sample (LCS) recovery.
M6	Matrix spike and Matrix spike duplicate recovery not evaluated against control limits due to sample dilution.

S0 Surrogate recovery outside laboratory control limits.


S2 Surrogate recovery outside laboratory control limits due to matrix interferences (confirmed by similar results from sample

re-analysis).

S4 Surrogate recovery not evaluated against control limits due to sample dilution.

REPORT OF LABORATORY ANALYSIS

Page 29 of 31







#### QUALITY CONTROL DATA CROSS REFERENCE TABLE

Project: 256277
Pace Project No.: 257254

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
257254001	MW-7d9	EPA 3546	OEXT/3558	EPA 8015B	GCSV/2418
257254002	MW-7d16	EPA 35 <b>4</b> 6	OEXT/3558	EPA 8015B	GCSV/2418
257254003	MW-7d20	EPA 3546	OEXT/3558	EPA 8015B	GCSV/2418
257254004	MW-8d9	EPA 3546	OEXT/3558	EPA 8015B	GCSV/2418
257254005	MW-8d13	EPA 3546	OEXT/3558	EPA 8015B	GCSV/2418
257254006	MW-8d20	EPA 3546	OEXT/3558	EPA 8015B	GCSV/2418
257254007	MW-9d8	EPA 3546	OEXT/3558	EPA 8015B	GCSV/2418
257254008	MW-9d20	EPA 3546	OEXT/3558	EPA 8015B	GCSV/2418
257254009	MW-9d24	EPA 3546	OEXT/3558	EPA 8015B	GCSV/2418
257254010	MW-10d10	EPA 3546	OEXT/3558	EPA 8015B	GCSV/2418
257254011	MW-10d15	EPA 3546	OEXT/3558	EPA 8015B	GCSV/2418
257254012	MW-10d20	EPA 3546	OEXT/3558	EPA 8015B	GCSV/2418
257254001	MW-7d9	EPA 3050	MPRP/2157	EPA 6010	ICP/2064
257254002	MW-7d16	EPA 3050	MPRP/2157	EPA 6010	(CP/2064
257254003	MW-7d20	EPA 3050	MPRP/215 <b>7</b>	EPA 6010	ICP/2064
257254004	MW-8d9	EPA 3050	MPRP/2157	EPA 6010	ICP/2064
257254005	MW-8d13	EPA 3050	MPRP/2157	EPA 6010	ICP/2064
257254006	MW-8d20	EPA 3050	MPRP/2157	EPA 6010	ICP/2064
257254007	MW-9d8	EPA 3050	MPRP/2157	EPA 6010	ICP/2064
257254008	MW-9d20	EPA 3050	MPRP/2157	EPA 6010	ICP/2064
257254009	MW-9d24	EPA 3050	MPRP/2157	EPA 6010	ICP/2064
257254010	MW-10d10	EPA 3050	MPRP/2157	EPA 6010	ICP/2064
257254011	MW-10d15	EPA 3050	MPRP/2157	EPA 6010	ICP/2064
257254012	MW-10d20	EPA 3050	MPRP/2157	EPA 6010	ICP/2064
257254001	MW-7d9	EPA 5030	MSV/4278	EPA 8260	MSV/4281
257254001	MW-7d9	EPA 8260	MSV/4244		
257254002	MW-7d16	EPA 8260	MSV/4244		
257254003	MW-7d20	EPA <b>82</b> 60	MSV/ <b>42</b> 44		
257254004	MW-8d9	EPA 8260	MSV/4244		
257254005	MW-8d13	EPA 8260	MSV/4244		
257254006	MW-8d20	EPA 8260	MSV/4244		
257254007	MW-9d8	EPA 8260	MSV/4244		
257254008	MW-9d20	EPA 8260	MSV/4244		
257254009	MW-9d24	EPA 8260	MSV/4244		
257254010	MW-10d10	EPA 8260	MSV/4291		
257254011	MW-10d15	EPA 8260	MSV/4247		
257254012	MW-10d20	EPA 8 <b>2</b> 60	MSV/4247		
257254001	MW-7d9	CALUFT	MSV/4277	CALUFT	MSV/4290
257254002	MW-7d16	CALUFT	MSV/4252		
257254003	MW-7d 20	CALUFT	MSV/4 <b>2</b> 52		
257254004	MW-8d9	CA LUFT	MSV/4252		
257254005	MW-8d13	CALUFT	MSV/4252		
257254006	MW-8d20	CALUFT	MSV/4252		
257254007	MW-9d8	CALUFT	MSV/4252		
257254008	MW-9d20	CALUFT	MSV/425 <b>2</b>		

Date: 04/22/2011 03:06 PM

#### **REPORT OF LABORATORY ANALYSIS**

Page 30 of 31

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc..





#### QUALITY CONTROL DATA CROSS REFERENCE TABLE

Project: 256277
Pace Project No.: 257254

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
257254009	MW-9d24	CALUFT	MSV/4253		
257254010 257254011	MW-10d10 MW-10d15	CA LUFT CA LUFT	MSV/4289 MSV/4289		
257254012	MW-10d20	CA LUFT	MSV/4253		



## CHAIN-OF-CUSTODY / Analytical Request Document The Chain-of-Custody is a LEGAL DOCUMENT. All relevant fields must be completed accurately.

257254

	lection B		Interes	nation					rction C	Man												Page	e:	1	8	1 8	5
Componer A 1 /	leport Ye:	-	enn		e4110	CC	-		and the same	Deni		T	10 F	+lof	C			1				ı			-	241	673
	юру То	U	en-	1.	17710		_	G	mpany Na	_	1-1	_	_	-	_			REC	SULA	TORY	AGE	NCY		-			
		-	_		_		_	Ac	IIOS O	whi	_	_		Bro RJ.		14 1	in	F	NPD	-	-	NAME AND ADDRESS OF	-	ATER	F	DRINKING	WATED
Transfer of Coradon City	unchase O	rider f	Vip.:	_	_			100	IN CHOCK	Whi	- 1	100	_	KJ.	5-	Le I	IU	-	UST			CRA	100 110	MILEN.		OTHER .	THE LOCAL CONTRACT OF
hone Fire	roject Nan	rie:					_	Ru	derenae.		-			-		_		,	_	. 1		-	_	_	-	OTHER .	-
716-503-1261 716-638-9385	reject Nun		14	02562	77			M	co Profile III	750				1.	_	_		510	e Loca			CA					
7	1463-114					_			m(China	210	14.	2/	L1	31	_				_	17E:			T				
Territoria.		_	_					_	-		_		_	-	R	edne	sted	Anal	lysis I	Filter	ed (Y/	N)					
Section D Matrix Co. Required Clarit Information MATRIX + C.		Ŧ	(40)		COLL	ECTED				Pros	ervəfi	ives		WIN				Ш									
Denking Water Water	DIV	Card record to half)	C=COMP)					5		TT	Т	П	П		-7,	T		П	_		_			$\neg$			
Waste Veater Product	WW	87.	No C	001/20 \$144		ENEVOIR				П		Н			8		- CA					П	1	Ē			
Sot'Solu	51	4	IG=CRAD				į	§	9					-	8/	. 5	TPH				s l		2	=			
SAMPLE ID ON Wine	OL WP AR TS	10.30	1000						CONTAINERS		Ш	L1	Ш	98	MEX	TPH	1-T	0		11			. 3	NII O			
Sample IDs MOST BE UNIQUE Those Other	TS	000	YPE						V PO			Ш	_ T	=	8	+	7 5	PRO		Ш	1		1	5			
	0.	HIX	AE.				1	9 1	8 8		1	o,	ano.	alys	0	è.	3	1		Ш			1	99			
		MATRIX CODE	SAMPLE TYPE	OATE	TRAE	DATE	TIME	divise.	Unpreserved	1	NaOH	Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub>	Methe	Analysis Test	-0928	8018	CA LUFT-	-5108		Ш			1	Rasidual Calenno (Y/N)	Pace I	Project No	./ Lab I.D.
1 MW-729		SL		GITTI II	1800	4-5-11		+	1 1	T	+		-	1	X	_	CX	-			9	Ť	ď		Luce	10/10/14	rir tamo no.
2 MW-7 2 16		SL				4-5-11		1	1 X	11					X		(x	П									
1 MU-7 120		SL				4-5-11		1	1 1	Ħ					x		XX	П					П				
4 MW-829		SL	6			4-5-11	10:27		1 1	П				10	x	XY	X	П									
5 MW-82 13		SL	61			4-5-11		T	i X	H					X	X	KX										
6 MW-87 20		SL	G			4-5-11	10:36	1	1 1					7	X	X	X										
7 MW-938		SL	6			4-5-11	12:58	T	1 X	$\Box$	T				X	X	XX										
s MW-7220			6			4-2-11			1  x						1		ďχ										
= MW-924		SL				4-5-11			1 X				-		X	X >	X					1					
10 MW-180 10		SL				4-5-11		1	1  x	П							( x										
11 MW-100 15		SL				4-5-11			1 X	$\perp$	1				_		X	_	1								
12 MW-102 20		SL	G			4-5-11	15:23		1 1	Ш					X	X	C X	X									
ADDITIONAL COMMENTS		REL	INQU	ISHED BY	ASFILIAT	TON	DATE	1	TIME			ACI	CEPT	ED BY	LAF	FILIAT	MON		DA	TE	715	ZE.			SAMPL	E CONDITIO	ONS.
8 Oxy's - MIDE/TAME/	1	4	TA	~/	Anten	Grap	4-7-1	1	14:00									_[i]									
DIPE/ETBE/TBA/1,2-DCA/	TE	D	E)	1		-1-	040811	_	0815	Ca	det	41	110	alu	E	PA	Œ		0408	11	081	5	3.2	1	1	Y	Y
EDB/Ethanol							atterior Germania	ľ								-											
								1																T			
	PSHIP	Tibr	B)		SAMPLE	ER NAME A	ND SIGNATI	RE															9	3	5.5	date	intact
	OHIO	210	rst.			THE STATE OF	TE of SAMPLE		6)	9	لها	ley	-	22			igned	U	/7	/			Temp in		to (V/II)	Custoty eated Coats (V/11)	emples Intact (V211)
Impertant hope for women my turn you are economic	ng Phone's 162	ET 38	Say 5-	munt torres	and appears			ولو	or site three	16	***	ne 30	CINT	_	1 15	MOD	HITE	-	1	11	-	_	F.A	-		7, 15-May	2007

### Sample Container Count

CLIENT:	ŀ	Inter										,			Fa	) ce Analyi	tical *		
COC PAGE	124167	5										int.		;		2 5	5 7 2	5 4	
Sample Line item	VG9H	AG1H	AG1U	BG1H	BP1U	BP2U	BP3U	BP2N	BP2S	WGFU	WGKU	Pister		5	rubsan	mplecon	nment (	1900, 1x	
1												1		1	+09	em,	250	199W, 1x	wer
2												1			1		- 1	0+21B	Tely 1
3												1		1				1	
4																			
5																			
6																			
7												1							
8																	h 15= 1		
9																			
10	100																		
11				1				Ú				1		T					$\neg \vdash$
12												8		Tr	iodlank	? No		V	V
																			Č
AG1H	1 liter HC	L amber	plass				BP2S	500mL	H2SO4 p	olastic			JG	FU  4	oz unpre	served a	mber wi	de	
	1liter unp			ass			BP2U	500mL	unpreser	ved plast	ic				erra core		Morale eco.		
	500mL H						BP2Z	500mL	NaOH, Z	n Ac				US	umma C	an			
AG2U	500mL u	noreserve	d amber	alass			BP3C	250mL	NaOH pla	astic			VG	9H 4	OmL HC	L clear vi	ial		
AG3S	250mL H	2SO4 am	ber glass				BP3N	250mL	HNO3 p	lastic			VG	9T 4	OmL Na	Thio. cle	ar vial		==/
BG1H	1 liter HC	L clear of	255		-		BP3S	250mL	H2SO4	plastic			VG	9U 4	OmL unp	reserved	i clear v	ial	
BG1U	1 liter ung	preserved	glass				BP3U	250mL	unprese	rved plas	tio		VGS	W 4	OmL gla	ss vial pre	eweighte	ed (EPA 5	035
BP1N	1 Fter HN	O3 plasti	c				DG9B	40mL N	la Bisulfa	te amber	vial		V:	SG H	leadspar	e septa	vial & H	CL	
	1 Rer H25						DG9H	40mL H	HCL amb	er voa via	al l				oz clear				- 1
BP1U	1 liter unp	reserved	plastic		1		DG9M	40mL N	NeOH cie	ar vial						ar w/hex	ane wip	e	
	1 liter Nat						DG9T	40mL N	la Thio a	mber vial					iploc Ba				
	500mL H				1		DG9U	40mL u	npreserv	ed ambe	rvial					,			
	500mL N				1		- 4	Wipe/S	wab					1					

The state of the s	Sample Condition Upon Re	celpt
Pace Analytical Client Nam	e: Antra	Project # 2 5 7 2 5
Courier: MFed Ex UPS USPS CI Tracking #: 8704 9477 9315 Custody Seal on Gooler/Box Present: Will		
A CONTRACTOR OF THE PERSON NAMED IN CONT	ole Bags   None   Other OVALC	
	1099 Type of Ice: Wel Blue None	Samplus on ice, cooling process has begun
Cooler Temperature 3.24 Temp should be above freezing s 6°C		Date and initials of person examining contents: 1)4081 CW
Chain of Custody Present	Bres Dies Dran 1	
Chain of Custody Filled Out:	EYes Dies DNA 2	
Chain of Custody Relinquished:	Elves Dito Dies 3	
Sampler Name & Signature on COC:	Wes DNo DNA 4.	
Samples Arrived within Hold Time:	Dires DNO DNA 5.	
Short Hold Time Analysis (<72hr):	Dyes Miles Class 6.	
Rush Turn Around Time Requested:	Dives May DNA 7.	
Follow Up / Hold Analysis Requested:	Dives Mio DNA B.	
Sufficient Voturne:	Elyes ONn ONA 9.	
Correct Containers Used:	BYES SHE DINA 10. RICVIL LA	plastic sleeves
-Pace Containers Used.	DVes Mins DNA	
Containers Intact	Elves Drin China 11.	
Filtered volume received for Dissolved tests	Dives Date Effet 12	
Sample Lubels match COC: Includes date/time/ID/Analysis Matrix	IV/OS EINO ENVA 13.	253-4
All containers needing preservation have been checked.	Dives Divo Shea 14,	
All centainers needing preservation are found to be in compliance with EPA recommendation	Dres Che (Wes	×

lient Notification/ Resolution:		Field Data Required?	Y / N
Person Contacted:	Date/Time		
Comments/ Resolution:	111-11		
	_	10.3	_
Project Manager Review	alm	Date: 74/	11.74

100 17.

Indian when

completed

Lot # of added

preservative

Note: Whenever there is a discrepancy affecting North Carolina compliance samples, a copy of this form will be sent to the North Carolina DEHNR Certification Office (i.e. out of hold, incorroct preservative, out of tump, incorroct containers)

Dres Che Linu

DYES DIES BINA

Dives DNo

Dies DNo 10km 16

Exceptions: VOA, colitoim, TOC, OSG

Trip Blanks Present

Samples checked for dechlorination:

Headspace in VOA Vials ( >6mm):

Trip Blank Custody Seals Present Pace Trip Blank Lot # (if purchased):

### Is the Data Set Valid?

(circle)

## **Preservation Temperature**

(if Known): 4.3 \_\_\_\_oc

## Antea<sup>™</sup>Group Laboratory Data Validation Sheet

Artica Group Laboratory Data Validation Sheet	
Project/Client: 76 Service Station No. 6277 / COP-ELT Project #: 240256277	Circle
Date of Validation: 6-16-11 Date of Analysis: 4/21/11 Sample Date: 4/18/11 Completed By: ETW	or Highlight
Signature:	(below)
Analytical Lab Used and Report # (if any): PACE #: 257356	
1. Were the analyses the ones requested?	Yes / No
<ol><li>Do the sample number(s) on the chain-of-custody (COC) match the one(s) that appear on the laboratory data sheet?</li></ol>	Yes / No
3. Were samples prepared (extracted, filtered, etc.) within EPA holding times?	Ves / No
4. Once prepared/extracted, were the samples analyzed within the EPA holding times?	Yes / No
5. Were Laboratory blanks performed, if so, were they non-detect?	Yes / No
<ol> <li>Are the units correct? (i.e., soil samples in mg/kg or ug/g, water samples mg/L, ug/L, and air samples in volume mg/m³,etc.)</li> </ol>	Yes / No
<ol><li>Were appropriate Matrix Spike (MS) and Matrix Spike Duplicate (MSD) samples included in the laboratory batch sample?</li></ol>	Ves / No
8. In lieu of MS/ MSD, were surrogate spike (SS) or surrogate spike duplicate (SSD) samples included in the laboratory batch samples?	Yes / No
<ol><li>Were MS/ MSD (or SS/SSD) within the acceptable range of % recovery (i.e., approximately 80-120%, depending on the analyte)?</li></ol>	Wes / No
10. Were MS/MSD (or SS/SSD) values used to calculate Relative Percent Difference (RPD)?	Yes / No
11. Were Relative Percent Difference values within the acceptable range (i.e. ±25%)?	Yes / No

## If any answer is no, explain why and what corrective action was taken (use additional sheet(s), as necessary:

圳		RPD	for D6	Ethanol	MAI	ontside	the	laboratory	control	1:-:+s
Que for jos	lifier the oline.	In sample this is	notice like	on TI	they the	pothm press	from	MU-9: The Internal	the TPH3 tong stands	result and for me in





April 26, 2011

Dennis Dettloff Antea USA 11050 White Rock Rd. #110 Rancho Cordova, CA 95670

RE: Project: 256277

Pace Project No.: 257356

#### Dear Dennis Dettloff:

Enclosed are the analytical results for sample(s) received by the laboratory on April 19, 2011. The results relate only to the samples included in this report. Results reported herein conform to the most current NELAC standards, where applicable, unless otherwise narrated in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Regina SteMarie

Regina Ste. Marie

regina.stemarie@pacelabs.com Project Manager

#### Enclosures

cc: Tara Bosch, Antea USA
Jonathon Fillingame, Antea USA
Lia Holden, Antea USA
Dan Keltner, Antea USA
Josh Mahoney, Antea USA
Tony Perini, Antea USA
Nicole Persaud, Antea USA
Don Pinkerton, Antea USA
Doug Umland, Antea USA
Ed Weyrens, Antea USA



Pace Analytical Services, Inc. 940 South Harney Seattle, WA 98108 (206)767-5060

#### **CERTIFICATIONS**

Project: 256277 Pace Project No.: 257356

Washington Certification IDs

940 South Harney Street, Seattle, WA 98108
Alaska CS Certification #: UST-025
Alaska Drinking Water VOC Certification #: WA01230
Alaska Drinking Water Micro Certification #: WA01230

California Certification #: 01153CA Florida/NELAP Certification #: E87617 Oregon Certification #: WA200007 Washington Certification #: C1229







#### **SAMPLE ANALYTE COUNT**

Project:

256277

Pace Project No.: 257356

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory	
257356001	MW-10_20110430	EPA 5030B/8260	СС	16	PASI-S	
		CALUFT	CC	2	PASI-S	
257356002	MW-7_20110430	EPA 5030B/8260	cc	16	PASI-S	
		CALUFT	cc	2	PASI-S	
257356003	MW-8_20110430	EPA 5030B/8260	cc	16	PASI-S	
		CALUFT	cc	2	PASI-S	
257356004	MW-9_20110430	EPA 5030B/8260	cc	16	PASI-S	
		CALUFT	cc	2	PASI-S	





#### HITS ONLY

Project: 256277
Pace Project No.: 257356

Lab Sample ID	Client Sample ID					
Method	Parameters	Result	Units	Report Limit	Analyzed	Qualifiers
257356001	MW-10_20110430					
EPA 5030B/8260	Ethylbenzene	6.9 ug/L		0.50	04/21/11 16:44	
EPA 5030B/8260	Methyl-tert-butyl ether	14.9 ug/L		0.50	04/21/11 16:44	
EPA 5030B/8260	Xylene (Total)	40.0 ug/L		1.5	04/21/11 16:44	
CALUFT	TPH-Gasoline (C05-C12)	513 ug/L		50.0	04/21/11 16:44	
257356002	MW-7_20110430					
EPA 5030B/8260	Benzene	22.4 ug/L		0.50	04/21/11 17:04	
EPA 5030B/8260	tert-Butyl Alcohol	5.7 ug/L		5.0	04/21/11 17:04	
EPA 5030B/8260	Ethylbenzene	11.3 ug/L		0.50	04/21/11 17:04	
EPA 5030B/8260	Methyl-lert-bulyl ether	152 ug/L		0.50	04/21/11 17:04	
EPA 5030B/8260	Toluene	12.4 ug/L		0.50	04/21/11 17:04	
EPA 5030B/8260	Xylene (Total)	449 ug/L		1.5	04/21/11 17:04	
CALUFT	TPH-Gasoline (C05-C12)	2420 ug/L		50.0	04/21/11 17:04	
257356003	MW-8_20110430					
EPA 5030B/8260	Benzene	1.4 ug/L		0.50	04/21/11 17:24	
EPA 5030B/8260	Ethylbenzene	2.8 ug/L		0.50	04/21/11 17:24	
EPA 5030B/8260	Methyl-tert-butyl ether	28.3 ug/L		0.50	04/21/11 17:24	
EPA 5030B/8260	Toluene	0. <b>7</b> 5 ug/L		0.50	04/21/11 17:24	
EPA 5030B/8260	Xylene (Total)	14.2 ug/L		1.5	04/21/11 17:24	
CALUFT	TPH-Gasoline (C05-C12)	439 ug/L		50.0	04/21/11 17:24	
257356004	MW-9_20110430					
EPA 5030B/8260	Methyl-tert-butyl ether	1.6 ug/L		0.50	04/21/11 17:44	
CALUFT	TPH-Gasoline (C05-C12)	208 ug/L		50.0	04/21/11 17:44	1n





#### **ANALYTICAL RESULTS**


Project: 256277 Pace Project No.: 257356

Sample: MW-10_20110430	Lab ID: 25735	6001	Collected: 04/18/1	11 14:10	Received: 04	4/19/11 08:50 M	//alrix: Water	
Parameters	Results	Units	Report Limit	DF	Prepared	Anaíyzed	CAS No.	Qual
8260 MSV	Analytical Metho	d: EPA 50	30B/8260					
tert-Amylmethyl ether	ND ug/L		0.50	1		04/21/11 16:44	994-05-8	
Benzene	ND ug/L		0.50	1		04/21/11 16:44	71-43-2	
tert-Butyl Alcohol	ND ug/L		5.0	1		04/21/11 16:44	75-65-0	
1,2-Dibromoethane (EDB)	ND ug/L		1.0	1		04/21/11 16:44	106-93-4	
1,2-Dichloroethane	ND ug/L		1.0	1		04/21/11 16:44	107-06-2	
Diisopropyl ether	ND ug/L		0.50	1		04/21/11 16:44	108-20-3	
Ethanol	ND ug/L		250	1		04/21/11 16:44	64-17-5	
Ethylbenzene	6.9 ug/L		0.50	1		04/21/11 16:44	100-41-4	
Elhyl-tert-butyl elher	ND ug/L		0.50	1		04/21/11 16:44	637-92-3	
Methyl-tert-butyl ether	14.9 ug/L		0.50	1		04/21/11 16:44	1634-04-4	
Toluene	ND ug/L		0.50	1		04/21/11 16:44	108-88-3	
Xylene (Total)	<b>40.0</b> ug/L		1.5	1		04/21/11 16:44	1330-20-7	
4-Bromofluorobenzene (S)	97 %		80-120	1		04/21/11 16:44	460-00-4	
Dibromofluoromethane (S)	97 %		80-122	1		04/21/11 16:44	1868-53-7	
1,2-Dichloroethane-d4 (S)	93 %		80-124	1		04/21/11 16:44	17060-07-0	
Toluene-d8 (S)	95 %		80-123	1		04/21/11 16:44	2037-26-5	
CA LUFT MSV GRO	Analytical Method	: CA LUF	ĒT.					
TPH-Gasoline (C05-C12)	513 ug/L		50.0	1		04/21/11 16:44		
4-Bromofluorobenzene (S)	97 %		82-116	1		04/21/11 16:44	460-00-4	
Sample: MW-7_20110430	Lab ID: 25735	6002	Collected: 04/18/1	1 12:35	Received: 04	/19/11 08:50 M	latrix: Water	
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8260 MSV	Analytical Method	I: EPA 50	30B/8260					
tert-Amylmethyl ether	ND ug/L							
Benzene			0.50	1		04/21/11 17:04	994-05-8	
	<b>22.</b> 4 ug/L		0.50 0.50	1 1		04/21/11 17:04 04/21/11 17:04		
tert-Butyl Alcohol	<b>22.</b> 4 ug/L <b>5.</b> 7 ug/L						71-43-2	
•	•		0.50	1		04/21/11 17:04	7 <b>1</b> -43-2 75-65-0	
1,2-Dibromoethane (EDB)	<b>5.7</b> ug/L		0.50 5.0	1 1		04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4	
1,2-Dibromoethane (EDB) 1,2-Dichloroethane	5.7 ug/L ND ug/L		0.50 5.0 1.0	1 1 1		04/21/11 17:04 04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4 107-06-2	
1,2-Dibromoethane (EDB) 1,2-Dichloroethane Diisopropyl ether	5.7 ug/L ND ug/L ND ug/L		0.50 5.0 1.0 1.0	1 1 1 1		04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4 107-06-2 108-20-3	
1,2-Dibromoethane (EDB) 1,2-Dichloroethane Diisopropyl ether Ethanol	5.7 ug/L ND ug/L ND ug/L ND ug/L		0.50 5.0 1.0 1.0 0.50	1 1 1 1		04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4 107-06-2 108-20-3 64-17-5	
1,2-Dibromoethane (EDB) 1,2-Dichloroethane Diisopropyl ether Ethanol Ethylbenzene	5.7 ug/L ND ug/L ND ug/L ND ug/L ND ug/L		0.50 5.0 1.0 1.0 0.50 250	1 1 1 1 1		04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4 107-06-2 108-20-3 64-17-5 100-41-4	
1,2-Dibromoethane (EDB) 1,2-Dichloroethane Diisopropyl ether Ethanol Ethylbenzene Ethyl-tert-butyl ether	5.7 ug/L ND ug/L ND ug/L ND ug/L ND ug/L 11.3 ug/L		0.50 5.0 1.0 1.0 0.50 250 0.50	1 1 1 1 1 1		04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4 107-06-2 108-20-3 64-17-5 100-41-4 637-92-3	
1,2-Dibromoethane (EDB) 1,2-Dichloroethane Diisopropyl ether Ethanol Ethylbenzene Ethyl-tert-butyl ether Methyl-tert-butyl ether	5.7 ug/L ND ug/L ND ug/L ND ug/L ND ug/L 11.3 ug/L ND ug/L 152 ug/L		0.50 5.0 1.0 1.0 0.50 250 0.50	1 1 1 1 1 1 1		04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4 107-06-2 108-20-3 64-17-5 100-41-4 637-92-3 1634-04-4	
1,2-Dibromoethane (EDB) 1,2-Dichloroethane Diisopropyl ether Ethanol Ethylbenzene Ethyl-tert-butyl ether Methyl-tert-butyl ether Toluene	5.7 ug/L ND ug/L ND ug/L ND ug/L ND ug/L 11.3 ug/L ND ug/L		0.50 5.0 1.0 1.0 0.50 250 0.50 0.50	1 1 1 1 1 1 1 1		04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4 107-06-2 108-20-3 64-17-5 100-41-4 637-92-3 1634-04-4 108-88-3	
1,2-Dibromoethane (EDB) 1,2-Dichloroethane Diisopropyl ether Ethanol Ethylbenzene Ethyl-tert-butyl ether Voluene Kylene (Total)	5.7 ug/L ND ug/L ND ug/L ND ug/L ND ug/L 11.3 ug/L ND ug/L 152 ug/L		0.50 5.0 1.0 1.0 0.50 250 0.50 0.50 0.50	1 1 1 1 1 1 1 1 1		04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4 107-06-2 108-20-3 64-17-5 100-41-4 637-92-3 1634-04-4 108-88-3 1330-20-7	
1,2-Dibromoethane (EDB) 1,2-Dichloroethane Diisopropyl ether Ethanol Ethylbenzene Ethyl-tert-butyl ether Methyl-tert-butyl ether Toluene Kylene (Tolal) 1-Bromofluorobenzene (S)	5.7 ug/L ND ug/L ND ug/L ND ug/L ND ug/L 11.3 ug/L ND ug/L 152 ug/L 12.4 ug/L		0.50 5.0 1.0 1.0 0.50 250 0.50 0.50 0.50 0.50	1 1 1 1 1 1 1 1 1		04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4 107-06-2 108-20-3 64-17-5 100-41-4 637-92-3 1634-04-4 108-88-3 1330-20-7 460-00-4	
1,2-Dibromoethane (EDB) 1,2-Dichloroethane Diisopropyl ether Ethanol Ethylbenzene Ethyl-tert-butyl ether Methyl-tert-butyl ether Toluene Kylene (Tolal) 1-Bromofluorobenzene (S) Dibromofluoromethane (S)	5.7 ug/L ND ug/L ND ug/L ND ug/L ND ug/L 11.3 ug/L ND ug/L 152 ug/L 12.4 ug/L 449 ug/L 94 %		0.50 5.0 1.0 1.0 0.50 250 0.50 0.50 0.50 0.50 1.5 80-120	1 1 1 1 1 1 1 1 1 1 1 1		04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4 107-06-2 108-20-3 64-17-5 100-41-4 637-92-3 1634-04-4 108-88-3 1330-20-7 460-00-4 1868-53-7	
1,2-Dibromoethane (EDB) 1,2-Dichloroethane Diisopropyl ether Ethanol Ethylbenzene Ethyl-tert-butyl ether Methyl-tert-butyl ether Toluene Xylene (Tolal) 4-Bromofluorobenzene (S) Dibromofluoroethane (S) 1,2-Dichloroethane-d4 (S)	5.7 ug/L ND ug/L ND ug/L ND ug/L ND ug/L 11.3 ug/L ND ug/L 152 ug/L 12.4 ug/L 449 ug/L 94 % 96 %		0.50 5.0 1.0 1.0 0.50 250 0.50 0.50 0.50 0.50 1.5 80-120 80-122	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4 107-06-2 108-20-3 64-17-5 100-41-4 637-92-3 1634-04-4 108-88-3 1330-20-7 460-00-4 1868-53-7 17060-07-0	
terl-Butyl Alcohol  1,2-Dibromoethane (EDB)  1,2-Dichloroethane  Diisopropyl ether  Ethanol  Ethylbenzene  Ethyl-tert-butyl ether  Methyl-tert-butyl ether  Toluene  Xylene (Tolal)  4-Bromofluorobenzene (S)  Dibromofluoroethane (S)  1,2-Dichloroethane-d4 (S)  Toluene-d8 (S)	5.7 ug/L ND ug/L ND ug/L ND ug/L 11.3 ug/L ND ug/L 152 ug/L 12.4 ug/L 449 ug/L 94 % 96 % 90 %	: CA LUF	0.50 5.0 1.0 1.0 0.50 250 0.50 0.50 0.50 0.50 1.5 80-120 80-122 80-123	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		04/21/11 17:04 04/21/11 17:04	71-43-2 75-65-0 106-93-4 107-06-2 108-20-3 64-17-5 100-41-4 637-92-3 1634-04-4 108-88-3 1330-20-7 460-00-4 1868-53-7 17060-07-0	

Date: 04/26/2011 01:59 PM

#### **REPORT OF LABORATORY ANALYSIS**

Page 5 of 12







#### **ANALYTICAL RESULTS**

Project:         256277           Pace Project No.:         257356								
Sample: MW-7_20110430	Lab ID: 25	7356002	Collected: 04/18/	11 12:35	Received: 04	/19/11 08:50	Malrix: Water	_
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
CA LUFT MSV GRO	Analytical Me	thod: CA LU	FT					
4-Bromofluorobenzene (S)	94 %	,	82-116	1		04/21/11 17:04	460-00-4	
Sample: MW-8_20110430	Lab ID: 257	7356003	Collected: 04/18/	11 13:10	Received: 04	/19/11 08:50	Matrix: Water	
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8260 MSV	Analytical Met	lhod: EPA 5	030B/8260					
tert-Amylmethyl ether	ND uş	g/L	0.50	1		04/21/11 17:24	994-05-8	
Benzene	1.4 uç		0.50	1		04/21/11 17:24	71-43-2	
tert-Butyl Alcohol	ND uç	g/L	5.0	1		04/21/11 17:24	75-65-0	
1,2-Dibromoethane (EDB)	ND uç	g/L	1.0	1		04/21/11 17:24	106-93-4	
1,2-Dichloroelhane	ND uç	-	1.0	1		04/21/11 17:24	107-06-2	
Diisopropyl ether	ND uç	•	0.50	1		04/21/11 17:24	108-20-3	
Ethanol	ND uç		250	1		04/21/11 17:24		
Ethylbenzene	<b>2.8</b> ug		0.50	1		04/21/11 17:24		
Ethyl-tert-butyl ether	ND uç		0.50	1		04/21/11 17:24	637-92-3	
Methyl-tert-bulyl ether	<b>28.3</b> ug	•	0.50	1		04/21/11 17:24		
Toluene	<b>0.75</b> ug	•	0.50	1		04/21/11 17:24		
Xylene (Total)	14.2 uç	•	1.5	1		04/21/11 17:24	-	
4-Bromofluorobenzene (S)	94 %		80-120	1		04/21/11 17:24		
Dibromofluoromethane (S)	95 %		80-122	1		04/21/11 17:24		
1,2-Dichloroethane-d4 (S)	92 %		80-124	1		04/21/11 17:24		
Toluene-d8 (S)	96 %		80-123	1		04/21/11 17:24	2037-26-5	
CA LUFT MSV GRO	Analytical Met	hod: CA LU	FT					
TPH-Gasoline (C05-C12)	439 ug	J/L	50.0	1		04/21/11 17:24		
4-Bromofluorobenzene (S)	94 %		82-116	1		04/21/11 17:24	460-00-4	
Sample: MW-9_20110430	Lab ID: 257	356004	Collected: 04/18/1	1 13:45	Received: 04/	19/11 08:50 N	/atrix: Water	
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8260 MSV	Analytical Meti	hod: EPA 50	30B/ <b>82</b> 60					
tert-Amylmethyl ether	ND ug	ı/L	0.50	1		04/21/11 17:44	994-05-8	
Benzene	<b>N</b> D ug	/L	0.50	1		04/21/11 17:44		
tert-Bulyl Alcohol	<b>N</b> D ug		5.0	1		04/21/11 17:44		
1,2-Dibromoethane (EDB)	ND ug		1.0	1		04/21/11 17:44		
1,2-Dichloroethane	ND ug		1.0	1		04/21/11 17:44		
Diisopropyl ether	ND ug		0.50	1		04/21/11 17:44		
Ethanol	ND ug		250	1		04/21/11 17:44		
Ethylbenzene	ND ug		0.50	1		04/21/11 17:44		
Ethyl-tert-bulyl ether	ND ug		0.50	1		04/21/11 17:44		
Methyl-tert-butyl ether	1.6 ug		0.50	1		04/21/11 17:44		
Toluene	ND ug	/L	0.50	1		04/21/11 17:44	108-88-3	

Date: 04/26/2011 01:59 PM REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc..





#### **ANALYTICAL RESULTS**

Project: 256277
Pace Project No.: 257356

Sample: MW-9_20110430	Lab ID: 25735600	O4 Collected: 04/18/1	1 13:45	Received: 04	1/19/11 08:50 I	Matrix: Water	
Parameters	Results U	Inits Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8260 MSV	Analylical Method: E	PA 5030B/8260					
Xylene (Total)	ND ug/L	1.5	1		04/21/11 17:44	1330-20-7	
4-Bromofluorobenzene (S)	93 %	80-120	1		04/21/11 17:44	460-00-4	
Dibromofluoromethane (S)	93 %	80-122	1		04/21/11 17:44	1868-53-7	
1,2-Dichloroethane-d4 (S)	90 %	80-124	1		04/21/11 17:44	17060-07-0	
Toluene-d8 (S)	95 %	80-123	1		04/21/11 17:44	2037-26-5	
CA LUFT MSV GRO	Analytical Method: C	A LUFT					
TPH-Gasoline (C05-C12)	<b>208</b> ug/L	50.0	1		04/21/11 17:44		1n
4-Bromofluorobenzene (S)	93 %	82-116	1		04/21/11 17:44	460-00-4	

Dale: 04/26/2011 01:59 PM

REPORT OF LABORATORY ANALYSIS

Page 7 of 12





Project:
Pace Project No.:

256277 257356

QC Batch:

MSV/4301

Analysis Method:

EPA 5030B/8260

QC Batch Method:

EPA 5030B/8260

Analysis Description:

8260 MSV Water 10 mL Purge

Associated Lab Samples:

257356001, 257356002, 257356003, 257356004

METHOD BLANK: 67314

Matrix: Water

Associated Lab Samples:

257356001, 257356002, 257356003, 257356004

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
1,2-Dibromoethane (EDB)	ug/L		1.0	04/21/11 10:41	
1,2-Dichloroelhane	ug/L	ND	1.0	04/21/11 10:41	
Benzene	ug/L	ND	0.50	04/21/11 10:41	
Diisopropyl ether	ug/L	ND	0.50	04/21/11 10:41	
Ethanol	ug/L	ND	250	04/21/11 10:41	
Ethyl-tert-butyl ether	ug/L	ND	0.50	04/21/11 10:41	
Ethylbenzene	ug/L	ND	0.50	04/21/11 10:41	
Methyl-tert-butyl ether	ug/L	ND	0.50	04/21/11 10:41	
lert-Amylmethyl ether	ug/L	ND	0.50	04/21/11 10:41	
tert-Butyl Alcohol	ug/L	ND	5.0	04/21/11 10:41	
Toluene	ug/L	ND	0.50	04/21/11 10:41	
Xylene (Total)	ug/L	ND	1.5	04/21/11 10:41	
1,2-Dichloroethane-d4 (S)	%	93	80-124	04/21/11 10:41	
4-Bromofluorobenzene (S)	%	93	80-120	04/21/11 10:41	
Dibromofluoromethane (S)	%	101	80-122	04/21/11 10:41	
Toluene-d8 (S)	%	93	80-123	04/21/11 10:41	

LABORATORY CONTROL SAMPLE:	67315					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
1,2-Dibromoethane (EDB)	ug/L	20	16.7	83	73-124	
1,2-Dichloroethane	ug/L	20	18.1	90	78-125	
Benzene	ug/L	20	19.1	96	76-127	
Diisopropyl ether	ug/L	20	20.5	103	70-137	
Ethanol	ug/L	400	361	90	31-182	
Ethyl-tert-butyl ether	ug/L	20	19.5	97	70-137	
Ethylbenzene	ug/L	20	17.3	86	72-125	
Methyl-tert-butyl ether	ug/L	20	19.8	99	58-145	
tert-Amylmethyl ether	ug/L	20	20.5	103	71- <b>1</b> 33	
tert-Butyl Alcohol	ug/L	100	87.3	87	31-166	
Toluene	ug/L	20	15.9	79	69-125	
Xylene (Tolal)	ug/L	60	52.2	87	74-124	
1,2-Dichloroethane-d4 (S)	%			93	80-124	
4-Bromofluorobenzene (S)	%			94	80-120	
Dibromofluoromethane (S)	%			99	80-122	
Toluene-d8 (S)	%			96	80-123	

Date: 04/26/2011 01:59 PM

REPORT OF LABORATORY ANALYSIS

Page 8 of 12






Project: 256277 Pace Project No.: 257356

MATRIX SPIKE & MATRIX SF	PIKE DUPLICA	TE: 67362			67363						
			MS	MSD							
		257356001	Spike	Spike	MS	MSD	MS	MSD	% Rec		
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	Qua
1,2-Dibromoethane (EDB)	ug/L	 	20	20	19.6	18.9	98	95	78-117	4	
1,2-Dichloroethane	ug/L	ND	20	20	21.8	21.2	109	106	73-127	3	
Benzene	ug/L	ND	20	20	24.8	23.9	122	117	75-124	4	
Diisopropyl ether	ug/L	ND	20	20	25.2	24.5	126	123	69-130	3	
∃thanol	ug/L	ND	400	400	344	524	86	131	36-177	41 D6	
Ethyl-tert-butyl ether	ug/L	ND	20	20	23.5	23.4	117	<b>1</b> 17	67-131	.3	
Ethylbenzene	ug/L	6.9	20	20	27.7	27.6	104	104	76-124	.4	
Methyf-fert-butyl ether	ug/L	14.9	20	20	39.9	40.4	125	128	72-130	1	
ert-Amylmethyl ether	ug/L	ND	20	20	24.5	23.9	122	120	67-132	2	
ert-Butyl Alcohol	ug/L	ND	100	100	104	107	102	105	36-164	3	
Toluene	ug/L	ND	20	20	20.4	19.6	101	96	75-124	4	
(ylene (Total)	ug/L	40.0	60	60	104	103	107	105	76-123	.7	
,2-Dichloroethane-d4 (S)	%						94	93	80-124		
-Bromofluorobenzene (S)	%						94	96	80-120		
Dibromofluoromethane (S)	%						103	103	80-122		
foluene-d8 (S)	%						94	93	80-123		

Date: 04/26/2011 01:59 PM REPORT OF LABORATORY ANALYSIS

Page 9 of 12







Project:

256277

Pace Project No.:

257356

QC Batch:

MSV/4302

Analysis Method:

**CALUFT** 

QC Batch Method:

**CALUFT** 

Analysis Description:

CALUFT MSV GRO

Analyzed

Associated Lab Samples:

257356001, 257356002, 257356003, 257356004

METHOD BLANK: 67316

Malrix: Water

Associated Lab Samples:

257356001, 257356002, 257356003, 257356004

Blank Result

Reporting

Parameter

Units

Limit

Qualifiers

TPH-Gasoline (C05-C12) 4-Bromofluorobenzene (S)

ug/L %

ND 93

04/21/11 10:41 50.0 82-116 04/21/11 10:41

LABORATORY CONTROL SAMPLE:

Parameter

Parameter

TPH-Gasoline (C05-C12)

4-Bromofluorobenzene (S)

67317

Unils

Spike Conc.

LCS

LCS % Rec % Rec Limits

Qualifiers

TPH-Gasoline (C05-C12) 4-Bromofluorobenzene (S)

ug/L %

Units

ug/L

%

500

Result 504

101 96 60-140

82-116

MATRIX SPIKE & MATRIX SPIKE DUPLICATE:

67522

257356002

Result

2420

67523

MS Spike

MS

MS

MSD % Rec

94

% Rec Limits

RPD

Qual

60-140

Conc. 500

Spike Conc.

500

MSD

MSD Result Result 2900 2810

% Rec 97

77

82-116

92

Date: 04/26/2011 01:59 PM





#### **QUALIFIERS**

Project: 256277 Pace Project No.: 257356

#### **DEFINITIONS**

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to changes in sample preparation, dilution of the sample aliquot, or moisture content.

ND - Not Detected at or above adjusted reporting limit.

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

S - Surrogate

1,2-Diphenylhydrazine (8270 listed analyle) decomposes to Azobenzene.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

DUP - Sample Duplicate

RPD - Relative Percent Difference

NC - Not Calculable.

SG - Silica Gel Clean-Up

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Pace Analytical is NELAP accredited. Contact your Pace PM for the current list of accredited analytes.

#### **LABORATORIES**

PASI-S Pace Analytical Services - Seattle

#### ANALYTE QUALIFIERS

Date: 04/26/2011 01:59 PM

1n The GRO result for this sample did not match the pattern of the laboratory standard for gasoline. This is likely due to the presence of tetrachloroethene in the sample.

D6 The relative percent difference (RPD) between the sample and sample duplicate exceeded laboratory control limits,

REPORT OF LABORATORY ANALYSIS







#### QUALITY CONTROL DATA CROSS REFERENCE TABLE

Project: 256277
Pace Project No.: 257356

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
257356001	MW-10_20110430	EPA 5030B/8260	MSV/4301		
257356002	MW-7_20110430	EPA 5030B/8260	MSV/4301		
257356003	MW-8_20110430	EPA 5030B/8260	MSV/4301		
257356004	MW-9_20110430	EPA 5030B/8260	MSV/4301		
257356001	MW-10_20110430	CALUFT	MSV/4302		
257356002	MW-7_20110430	CALUFT	MSV/4302		
257356003	MW-8_20110430	CALUFT	MSV/4302		
257356004	MW-9_20110430	CA LUFT	MSV/4302		

Date: 04/26/2011 01:59 PM

REPORT OF LABORATORY ANALYSIS

Page 12 of 12



## COP ELT CHAIN-OF-CUSTODY / Analytical Request Document The Chain-of-Custody is a LEGAL DOCUMENT. AD relevant fields must be completed and accurate.

Page:	1 of	
Cooler#	of	

anteagroup

2Q 2011 GW Event

Required Lab Information:	Required Project Information:		Required Invoice is	nformation:			AA 7 11.			
Lab Name: Pace-Seattle	Site ID a 256277 Task:	WG_BM_201104	Send Invoice to:	Tara Bosch			22423/4			
Address:	AnteaGrp proj# 140256277		Address: 11050 V	Vinte Rock Road Su	te 110		Turn around time (days) 10			
940 S. Harriey Street Seattle WA 98108	Site Address 15803 East 14th	Street	City/State	Rancho Cordova C	A 95670 Phone #:	916-503-1267	QC level Required: Standard	Special Mark one		
Lab PM: Regina Ste. Mane	City Son Leandro St	ate CA	Reimbursement pro	79Ct7	Non-reimbursement pr	oject? Mark one	NJ Reduced Deliverable Pac	ckage?		
Phone/Fax: P: 206-957-2433 F: 206-767-5063	AG PM Name: Dennis	Dettioff	Send EDD to	copeltdate@intellig	entehs.com		MA MCP Cert? CT F	RCP Cert? Mark One		
Lab PM email Regina, SteMarie@pacelabs.com	Phone/Fax: P: 916-503-126		CC Hardcopy r		<u> </u>		Lab Project ID (lab use)	<u> </u>		
Applicable Lab Quote s.	AG PM Email: Dennis,Det	noti@anteagroup com	CC Hard∞py r	eport to			Requested ////			
SAMPLE ID  One Character per box. (A-Z, 0-9 /,-)  Samples IDs MUST BE UNIQUE	Valid Matte Codes  MATRIX  CHARACTER AND	MATRIX CODE SAMPLE TYPE G-GRAG C-COMP	SAMPLE DATE	SAMPLE TIME	FOF CONTAINERS FIELD FILTERED? (YAI)	Hro, Hro, Hro, Hro, Hro, Hro, Hro, Hro,	Analyses	Comments/Lab Sample i.D.		
MW-10_20110430		WG	4-19-11	1410	6 N	X	xx	7 Oxy's = MTBE, DIPE,		
MW-7_20110430		wg	4-18-11	1235	6 N	X	x x	ETBE, TAME, TBA, Ethanol, 1,2DCA, and		
3 MW-8_20110430		wg	4-18-6	1310	10 N	ו או	x x	EDB		
MW-9_20110430		wg	4-18-11	1345	6 N		x x			
5										
6 :										
7	_									
8										
9								1		
10										
11										
12										
Additional Commental Special Instructions:		RELINQUISHED BY	/ AFFILIATION	DATE	TIME ACCEPTE	D BY / AFFILIATION	DATE TIME	Sample Receipt Conditions		
		Mottestini	BlasneTe	4.18.1	1530			Y/N Y/N Y/N		
			1			,		Y/N Y/N Y/N		
		Po	dex	40	1080 2	40thi Swam	ACE 4/19/11 0852	43 (V) N (V) N		
Global ID: T0619718179							. 1	YIN YIN YING		
		SHIPPING METHO			ER NAME AND SIGN	NATURE		S S S S S S S S S S S S S S S S S S S		
	UPS COURIER	FEDE PROIT N		Ma 131	تحي رُ		Sampies on lee? Sample intact? Trip Blank?			
		US MAIL	BIGNATU	IRE of SAMPLER	there	DATE Somed	Time: 530	Sar		

#### **Sample Container Count**

CLIENT:	Ant	ea-	CA					•						Pace.	Analyti	ical ~	
COC PAGE														į.			
Sample Line Item	VG9H	AG1H	AG1U	BG1H	BP1U	BP2U	BP3U	BP2N	BP2\$	WGFU	WGKU				Com	ments	
1	6																
2	6																
3	60																
4	6																
5																	
6																	
7																	
8																(	
9																	
10																	
11															ر ،		
12														Trip Blank?	70,	<b>၁</b>	
AG1H	1 liter HC	Lamber	glass				BP2S	500mL	H2SO4 p	lastic			JGFU	4oz unprese	rved ar	nber wide	

AG1H	1 liter HCL amber glass	BP2S	500mL H2SO4 plastic	JGFU	4oz unpreserved amber wide
	1liter unpreserved amber glass		500mL unpreserved plastic	R	terra core kit
	500mL H2SO4 amber glass		500mL NaOH, Zn Ac	U	Summa Can
	500mL unpreserved amber glass		250mL NaOH plastic	VG9H	40mL HCL clear vial
	250mL H2SO4 amber glass		250mL HNO3 plastic	VG9T	40mL Na Thio. clear vial
	1 liter HCL clear glass	_	250mL H2SO4 plastic	VG9U	40mL unpreserved clear vial
BG1U	1 liter unpreserved glass	BP3U	250mL unpreserved plastic	VG9W	40mL glass vial preweighted (EPA 5035)
BP1N	1 liter HNO3 plastic		40ml. Na Bisulfate amber vial	VSG	Headspace septa vial & HCL
BP1S	1 liter H2SO4 plastic	DG9H	40mL HCL amber voa vial	WGFU	4oz clear soil jar
BP1U	1 liter unpreserved plastic	DG9M	40mL MeOH clear vial	WGFX	4oz wide jar w/hexane wipe
BP1Z	1 liter NaOH, Zn, Ac	DG9T	40mL Na Thio amber vial		Ziploc Bag
BP2N	500mL HNO3 plastic	DG9U	40mL unpreserved amber vial		
BP2O	500mL NaOH plastic	1	Wipe/Swab		

~		Sam	bie .	Jone	mon upon kei	ceiht ·	
Pace Analytical (	Client Name:	<u>A.</u>	nte	a	·	Project #	25735
Courler: Fed Ex UPS [		t 🗆	Comm	erciat	Pace Other		
Custody Seal on Cooler/Box P			No	Seals	intact: 🗕 7es	□ No	~0
Packing Material: Bubble V	Vrap []Bubble	Bags		None	Other	Temp. Blank	No
Thermometer Used 132013	or 101731982 or 226099	Туре	of Ice	: We	Blue None		cooling process has begun
Cooler Temperature	F.30C	Biolo	glcat	Tissuc	is Frozen: Yes No	Date and init	tials of person examining
Temp should be above freezing ≤ 6°C	3				Comments:		77
Chain of Custody Present:		_ []¥es	□No	□ NVA	1.		
Chain of Custody Filled Out:				□ N#A	2.		
Chain of Custody Relinquished:		-EYes					
Sampler Name & Signature on C	:OC:				-		
Samples Arrived within Hold Tim	ie:			□N/A	<del></del>		
Short Hold Time Analysis (<72	hr):			QwA	6.		
Rush Turn Around Time Requi	esled:		₽¥0	□N/A	7.		
Follow Up / Hold Analysis Req	uested:	[]Yes	ДN°	□N/A	8.		
Sufficient Volume:		□Yes	□No	□N/A	9.		
Correct Containers Used:		₽√es	□No	□ NVA	10.		
-Pace Containers Used:		12 Fest	<b>⊠</b> ‰	□nva		0	
Containers Intact:		□Yes	- <b>D</b> 7%	□nva	11.2/10 Vial	s to MW-8 r	ecerced broken.
Fillered volume received for Diss	olved tests	□Yes	□No	DNA	12.		
Sample Labels match COC:		⊠Yes	□No	□n⁄a	13.		
-Includes date/time/ID/Analysi		Wood	e/				
All containers needing preservation have	re been checked.	□Чов	□No	<b>,⊡</b> #4/A	14.		
All containers needing preservation as		□Yes	□No	₽N/A			
compliance with EPA recommendation	n.				Initial when	Lot # of added	-
Exceptions VDA coliform, TOC, O&G					completed	preservative	
Samples checked for dechlorinat	ion:	□Y€5	DNo	□MAV	15.		
Headspace in VOA Vials ( >6mm	ı):	□Yes	<b>⊅</b> 400	□N/A	16.		
Trip Blanks Present:		□Yes	CNE	<b>□</b> N/A	17.		
Trip Blank Custody Seals Presen	1	□Yes	□No	<b>₽</b> N/A			
Pace Trip Blank Lot # (if purchase	ed):						
Client Notification/ Resolution: Person Contacted: Comments/ Resolution:			_	Date/	Fime:	Field Oata Require	ed? Y / N
		_					
					_		
	ARm =						
Project Manager Review:	NOWY)					Date: 🗸	H119/11

Note: Whenever there is e discrepancy affecting North Carolina compliance samples, a copy of this form will be sent to the North Carolina DEHNR Certification Office (i.e. out of hold, incorrect preservative, out of temp, incorrect containers)

Site InvestigationReport 76 Service Station No. 6277 Antea Group Project No. 140256277



## Appendix D

Well Development Logs

G	REGG

#### MONITODING WELL DEVELOPMENT LOC

Page	of	7
------	----	---

Well Numb Date Time Start: Client Project Job Numb Installation	All measurement er/^	1 - 7 -11 End: 1'- Enoup	10	Borehole Diar Screen Lengti Measured De Measured De Static Water L Standing Wat One Well Volu	rotective Casin meter	opment)	19.70	Sa Q Q M D D D D D D D D D D D D D D D D D	Page of			
	Amount			Field Pa	rameters Me	asured		GPM /	Comments	Field		
Time	Purged (gal.)	pH	EC	Turbidity	D.O.	D.O. Temp.	SAL.	W.L.	Continents	Tech.		
12 40	- 4	TART	SULGI	NG 2	WELL			~	HARD BOTTON	2		
2:55	- 57	00 30	CLUC	1 500	P.Du	24-						
1:00	- 570	13.41	LING	BAK	4 60	Iloa S			Suggest light for 15 p	1st		
1:02	- 1	TANT	Qu,	00106	AT	2	Gollon	Spar	MINUTES			
1.04	4/4	7.60	1,94	949		20.1		200	M/DW-10.50			
1.06	4/8	7.50	1.84	999	-	20.1	*	3 601	1/ STU- 10.60			
1.08	4/12	7.23	183	209	-	20.0	-	200	A DTUS 10.60			
1.10	4/16	7.25	1.82	622	_	19.9		2 900	2/ DWE 10-60			
1:12	4/20	7.23	1.81	442	حيد	20.0		5-00	N STIME 10.60			
- The Control of the	1/	100		0, 0 1	E PEN		- N-	N				

#### FINAL FIELD PARAMETER MEASUREMENTS

G	REGG	1
른		

#### MONITORING WELL DEVELOPMENT LOG

Page \_\_\_\_\_\_ of \_\_\_\_\_

V									PageOi	
All measurements taken from:									div. of Drilling Fluid Lost	
	100			Field Pa	arameters Me	asured				
Time	Amount Purged	6004.8	EC	Turbidity	D.O.	DO Temp	CAL	GPM /	Comments	Field
	(gal.)	pН	EC	luroidity	D.O.	D.O. Temp.	SAL	W.L.		Tech.
11:40	(gal.)	TAGET	SILG		21 WE		SAL	W.L.	HARD BOTTON	lech.
11:40	(gal.)						SAL	W.L.	HARD BOTTON	102000
11:40	- 5		SULG	سان		10 -		W.L.	Walter and the second second	102000
11:40	- 5		SULG	سان		LC -		W.L.	Walter and the second second	102000
	- 5	TAFT OF SU	SULG	26 5/ 57 - 12	2" WE 200 130 AIL 5	LC -		1 gp /2	Walter and the second second	102000
2:05	- 5	TAFT OF SU	SULG	26 5/ 57 12 12 10/186	2" WE 200 130 AIL 5	LC -		1 gp 1	SURGED LIEU FOL 15	102000
2:05	- 5	7 ACT 20 B 7 ACT 7.53	SURG PILING PILING 1.79	26 ST 5/ ST 12 12 10/NG	2" WE 2007 120 AIL S	16 - Gallo 1 6 71.2		مرويد	SURGED LIEU FOR 15	102000
2:05	- 5	7 ACT 20 B 7 ACT 7.53	SURG 12512/1 11-146 11-149 11-167	26 5/ 57 12 12 12 12 19 19 9 9 9	2" WE 200 120 AIL 5	16 - 6 allo 2 6 21.2 71.4	200	مرويد	SURGED LIEU FOL 15  1 DTW- 10:35  1 DTW- 10:35	102000
2:05	- 57 - 57 - 57 - 57 2/2 2/4 2/6	7 APT P SU P PS P PS	SUF-G PGING PUN 1.79 1.67 1.68	26 5/ 57 12 12 12 12 12 13 13 13 13 13 13 13 13 13 13 13 13 13	2" WE 200 120 AIL 5	16 - 2151NG 210 21.2 21.4 21.4	200	1 5pm 1 5pm 1 5pm	SURGED LIEU FOL 15  1 DTW- 10:35  1 DTW- 10:35	102000

FINAL FIELD PARAMETER MEASUREMENTS

2:24 4/19 6.89 1.67 999 - 21.4 - 29pm/ DTW= 10.80



#### MONITORING WELL DEVELOPMENT LOG

Done	of	
Page	OI	

Sample ID

Well Number Date Time Start: Client Project Job Number	er	nd: 31	3-0 14-1111-2	Borehole Diar Screen Lengti Measured De Measured De Static Water L Standing Wat One Well Volu	meter  pth (pre-deveront (post-deveront (ft.)  er Column (ft.)  ume (gal.)	y#	Oty: of Drilling Fluid Lost			
	150 10			Field Pa	rameters Me	easured				
Time	Amount Purged (gal.)	рН	EC	Turbidity	D.O.	D.O. Temp.	SAL.	GPM W.L.	Comments	Field Tech.
- 122	7.4	AT 5	SEA D						HATTI Burrateta	
3104	10	6.70	1.75	#9 TY	F	76.1	0718	Im line	EUS SOUR 2145	
3:06	PY	1.90	1,72	>50	-	70 3	0.08	70 A-15	Ras 2 ani	
304	18	6 36	1692	7997	V	7144	0.60	35/026	the terms whom	
3-10	11 -	6,20	1.60=	>997	-	20.3	0.27	11/11.65	EUD 11.1 9.76	
3013	20	6.88	167	> 977	*	70.3	0.07	For 1125		
	The second second		1							
7										
				FINAL	FIELD PARA	METER MEAS	UREMENTS			
							50			

G	REGG	

#### MONITORING WELL DEVELOPMENT LOG

Dane	us vi
Page	of

V===									Page of/	-
			7/			-	. i	S	ample ID	
Well Number					91/ lopment)	19.50 19.50 2 90 -51	M	Alinimum Gal. to be Purged	144 144 144 144 144 144 144 144	
Tren Diame				One Artifages	voi: (gai-)					
	Amount			Field Parameters Measured				GPM /		Field
									1021100 - 20100	HIDIO
Time	Purged (gal.)	pH	EC	Turbidity	D.O.	D.O. Temp.	SAL	W.L	Comments	Tech.
Time 1:30	(gal.)	PH ART C		Turbidity					HART BOTTONS	
	(gal.)	ART C	EC WAGING	Turbidity  JG —		D.O. Temp.				
	(gal.)	ART C	UEGU	16, -	13				HARD BOTTOM	
1:30	(gal.)	ART S OP SUC BAIN	UEGU	JG - STAIL	13	ALLING	- 1	W.L	HARD BOTTOM	
1:30	(gal.)	ART S OP SUC BAIN	WEGING ,	JG - STAIL	17 5 6 4 6	allow	- 1	W.L TW =	HARD BOTTOM	
1:30	(gal.)	PRT S	WEGING .	JG - SAIL NG	13 14 6 14 6	9141NC	- 1	W.L TW =	HARD BOTTONS	
1:30	(gal.) - ST - STOP - STOP - ST	9RT 5 0P 500 13A14 1915 8 7.45	WEGING WG.	STAS BAIL NG GAG	13 14 6 14 6	91600) 91600) 19.4	7	WIL =	HARD BOTTONS  11.19  11.19  11.19  11.10	
1:30	(gal.) - ST - STOP - STOP - ST	9RT 5 0P 500 13A14 1915 8 7.45	WEGING WAGING WAGING 2.14	16 - 15 - 13 AIL 14 G 19 G 19 G	13 4 6 8 7	2 GP 19.4	7	WIL TW = 2 ggm 2 ggm 2 ggm	HARD BOTTONS  11.19  11.19  11.19  11.10	
1:30	(gal.) - ST - STOP - STOP - ST	9RT S 100 SAIN 17.45 17.25 1.02	WEGING	16 - 15 - 13 AIL 14 G 19 G 19 G	13 4 6 8 7	91000) 2 GP 19.4 19.5	- 1 - 1 	WIL TW = 2 ggm 2 ggm 2 ggm	HARD BOTTONS  11.16  / NTW= 12.110  n/ STW=12.40  n/ DTW=12.60  n/ DTW=12.70	

FINAL FIELD PARAMETER MEASUREMENTS

Site InvestigationReport 76 Service Station No. 6277 Antea Group Project No. 140256277



## Appendix E

Blaine Tech Services Groundwater Sampling Procedures

# BLAINE TECH SERVICES, INC. METHODS AND PROCEDURES FOR THE ROUTINE MONITORING OF GROUNDWATER WELLS

#### SAMPLING PROCEDURES OVERVIEW

#### SAFETY

All groundwater monitoring assignments performed for DELTA comply with safety guidelines, 29 CFR 1910.120 and SB-198 Injury and Illness Prevention Program (IIPP). All Field Technicians receive the full 40 hour 29CFR 1910.120 OSHA SARA HAZWOPER course, medical clearance and on-the-job training prior to commencing any work on any DELTA COP/ELT site.

#### INSPECTION AND GAUGING

Wells are inspected prior to evacuation and sampling. The condition of the wellhead is checked and noted according to a wellhead inspection checklist.

Standard measurements include the depth to water (DTW) and the total well depth (TD) obtained with industry standard electronic sounders which are graduated in increments of hundredths of a foot.

The water in each well is inspected for the presence of Immiscibles or sheen and when free product is suspected, it is confirmed using an electronic interface probe (e.g. MMC). No samples are collected from a well containing free product.

#### **EVACUATION**

Depth to water measurements are collected by our personnel prior to purging and minimum purge volumes are calculated anew for each well based on the height of the water column and the diameter of the well. Expected purge volumes are never less than three case volumes and are set at no less than four case volumes in some jurisdictions.

Well purging devices are selected on the basis of the well diameter and the total volume to be evacuated. In most cases the well will be purged using an electric submersible pump (i.e. Grundfos) suspended near (but not touching) the bottom of the well. Small volumes of purgewater are often removed by hand bailing with a disposable bailer.

#### PARAMETER STABILIZATION

Well purging completion standards include minimum purge volumes, but additionally require stabilization of specific groundwater parameters prior to sample collection. Typical groundwater parameters used to measure stability are electrical conductivity, pH, and temperature. Instrument readings are obtained at regular intervals during the evacuation process (no less

than once per case volume).

Stabilization standards for routine quarterly monitoring of fuel sites include the following: Temperature is considered to have stabilized when successive readings do not fluctuate more than +/- 1 degree Celsius. Electrical conductivity is considered stable when successive readings are within 10%. pH is considered to be stable when successive readings remain constant or vary no more than 0.2 of a pH unit.

#### **DEWATERED WELLS**

Normal evacuation removes no less than three case volumes of water from the well. However, less water may be removed in cases where the well dewaters and does not recharge.

Wells known to dewater are evacuated as early as possible during each site visit in order to allow for the greatest amount of recovering. Any well that does not recharge to 80% of its original volume will be sampled prior to the departure of our personnel from the site in order to eliminate the need of a return visit.

In jurisdictions where a certain percentage of recovery is included in the local completion standard, our personnel follow the regulatory expectation.

#### **PURGEWATER CONTAINMENT**

All non-hazardous purgewater evacuated from each groundwater monitoring well is captured and contained in on-board storage tanks on the Sampling Vehicle and/or special water hauling trailers. Effluent from the decontamination of reusable apparatus (sounders, electric pumps and hoses etc.), consisting of groundwater combined with deionized water and non-phosphate soap, is also captured and pumped into effluent tanks.

Non hazardous purgewater is transported under standard Bill of Lading or Non-Hazardous manifest to a Blaine Tech Services, Inc. facility before being transported to an approved disposal facility.

#### SAMPLE COLLECTION DEVICES

All samples are collected using disposable bailers.

#### SAMPLE CONTAINERS

Sample material is decanted directly from the sampling bailer into sample containers provided by the laboratory which will analyze the samples. The type of sample container, material of construction, method of closure and filling requirements are specific to the intended analysis. Chemicals needed to preserve the sample material are commonly placed inside the sample containers by the laboratory or glassware vendor prior to delivery of the bottle to our personnel. The laboratory sets the number of replicate containers.

#### TRIP BLANKS

Upon request, a Trip Blank is carried to each site and is kept inside the cooler for the duration of the sampling event. It is turned over to the laboratory for analysis with the samples from that site.

#### **DUPLICATES**

Upon request, one Duplicate sample is collected at each site. It is up to the Field Technician to choose the well at which the Duplicate is collected. Typically, a duplicate is collected from one of the most contaminated wells. The Duplicate sample is labeled DUP thus rendering the sample blind.

#### SAMPLE STORAGE

All sample containers are promptly placed in food grade ice chests for storage in the field and transport (direct or via our facility) to the analytical laboratory that will perform the intended analytical procedures. These ice chests contain quantities of restaurant grade ice as a refrigerant material. The samples are maintained in either an ice chest or a refrigerator until relinquished into the custody of the laboratory or laboratory courier.

#### DOCUMENTATION CONVENTIONS

Each and every sample container has a label affixed to it. In most cases these labels are generated by our office personnel and are partially preprinted. Labels can also be hand written by our field personnel. The site is identified with the store number and site address, as is the particular groundwater well from which the sample is drawn (e.g. MW-1, MW-2, S-1 etc.). The time at which the sample was collected and the initials of the person collecting the sample are handwritten onto the label.

Chain of Custody records are created using client specific preprinted forms following USEPA specifications.

Bill of Lading records are contemporaneous records created in the field at the site where the non-hazardous purgewater is generated. Field Technicians use preprinted Bill of Lading forms.

#### DECONTAMINATION

All equipment is brought to the site in clean and serviceable condition and is cleaned after use in each well and before subsequent use in any other well. Equipment is decontaminated before leaving the site.

The primary decontamination device is a commercial steam cleaner. The steam cleaner is detuned to function as a hot pressure washer which is then operated with high quality deionized water which is produced at our facility and stored onboard our sampling vehicle. Cleaning is facilitated by the use of proprietary fixtures and devices included in the patented workstation that is incorporated in each sampling vehicle. The steam cleaner is used to decon reels, pumps

and bailers.

Any sensitive equipment or parts (i.e. Dissolved Oxygen sensor membrane, sounder etc.) that cannot be washed using the hot high pressure water, will be sprayed with a non-phosphate soap and deionized water solution and rinsed with deionized water.

EXAMPLE: The sounder is cleaned between wells using the non-phosphate soap and deionized water solution followed by deionized water rinses. The sounder is then washed with the steam cleaner between sites or as necessitated by use in a particularly contaminated well.

#### DISSOLVED OXYGEN READINGS

All Dissolved Oxygen readings are taken using YSI meters (e.g. YSI Model 550 meter). These meters are equipped with membrane probe that enables them to collect accurate in-situ readings.

The probe and reel is decontaminated between wells as described above. The meter is calibrated as per the instructions in the operating manual. The probe is lowered into the water column allowed to stabilize before use.

#### **OXYIDATON REDUCTION POTENTIAL READINGS**

All readings are obtained with either Corning or Myron-L meters (e.g. Corning ORP-65 or a Myron-L Ultrameter GP). The meter is cleaned between wells as described above. The meter is calibrated at the start of each day according to the instruction manual. In use the probe is placed in a cup of freshly obtained monitoring well water and allowed to stabilize.

Site InvestigationReport 76 Service Station No. 6277 Antea Group Project No. 140256277



### Appendix F

Blaine Tech Services Groundwater Sampling Field Data Sheets

Site Address:	COP-ELT Well-Head Inspection & Well Gauging Form								
Field Point	and the second s								
Field Point	cool								
MW-7 G G G G W Q 1140 9.40 18.90  MW-8 G G G G W Q 114G 9.40 19.65  MW-9 G G G G W Q 115G 9.55 23.95  MW-10 G G G G W Q 1201 10.55 19.70  MW-10 G G G G W Q 1201 10.55 19.70  Notes:  **All well caps opene minutes or longer before wells:									
Notes:    Mu-9	iments								
Notes:    MU-9   G   G   G   G   W   Z   120   10.55   19.70	1 Can								
Notes:  *** All well caps opene minutes or longer bef wells:	Cap.								
Notes:  *** All well caps opene minutes or longer bef wells:	Corp.								
Notes:  *** All well caps opene minutes or longer bef wells:	Cap.								
Notes:  ** All well caps opene minutes or fonger bef wells:									
Notes:  *** All well caps opene minutes or longer bef wells:									
Notes:  *** All well caps opene minutes or longer bef wells:									
Notes:  ** All well caps opene minutes or longer bef wells:									
Notes:  ** All well caps opene minutes or longer bef wells:									
Notes:  ** All well caps opene minutes or longer bef wells:									
Notes:  ** All well caps opene minutes or longer bef wells:									
Notes:  ** All well caps opene minutes or longer bef wells:									
Notes:  ** All well caps opene minutes or longer bef wells:									
Notes:  ** All well caps opene minutes or longer bef wells:									
** All well caps opene minutes or longer bef wells:									
minutes or longer bef	opened at least 15								
	er before gauging								
	ells: E: YES or NO**								
anteagroup Note: Use G=good and P=poor for well condition Page	of								

			1754 VAU				(			
	€0	P-E		直接指数形式の	ater S	amp	ling Fo	rm		
Site Address	15803	E	14/74	57	Sun B	enne	tro a	4		
Project No.	N- 40				Field Tech	nician:	M. Pes			
Fleid Point	MIN					Date:	4 - 18	<u>11                                  </u>		
Depth to Water (DTW) (ft bgs)				We	eli Diamet	er (ln):	O	9 4 6 4	3	
Depth to LNAPL (ft bgs)	:			Thickne	ss of LNA	PL (ft):				
Total Depth of Well (ft bgs):	18,90	)		Water Col	umn Heig	ht (ft):	9.5	0		
			Pur	ging Info a	nd Calcul	ations				
Purge Method:		F		uipment:				Sample Col	lection Metho	12 E.D.
Low-Flow		` E		ole Bailer Mersible				Dispo: Extra	save Baller W	B
3 casing valumes Other:		-	Peristalt	ic Pump				Dedica	ated Tubing	
		Othe		r Pump			c	ther:	able Tubing	
Water Column Height (ft):	7.50	Y- C^-	nversion	Factor-/231/f	41	17	مرحولشتر	ing-Volume-/	nal): 1.7	
_	,7		eclfied Vo		· 3			l Purge (gal)		
Conversion Factors		= 0.1			"= 1.5	8" = 2		= radius <sup>2</sup> *		_
	rime: //					date to the second second second	top Time:		1227	
Time	Temp (°C)		рН	Conductivity (µS/cm)	ORP (	mV)	Turbidity (NTU)	D.O. (mg/L)	Volume Purged (gal)	Water Level
Pre-Purge	(0)			(p3/ciii)			(110)	(mg/L)	Turged (gar)	
1222	19.6	6.	0	823	-65.	1	937	2.68	1.0	
1223	19.7	7.		1447	-70.		410	2.41	2.0	
1224	19.8	7.	<del></del>	1395	-68.		232	2.34	3.0	
1225	10 9	7		1380	-61.		000 158	2.30	4.0	
· _	10 0	/(	,					2.28	5.0	
1226	171	7:		372	-59. C		146	2.24		
100	19.9			1369	7816	9 1	37	a, a I	6.0	
	***									
Post-Purge										
Did Well dewater?	Yes /	1 <u>7</u>		Total	l Purge vo	olume (c	pal): <i>C.O</i>	) )		
DIO NOI GENERA	100			SI	2% =-	11. 3	0			
Other Comments:	Strong	7	oder	- 0-	-	110	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~			
		A CENTRAL		<u> </u>	アルニ	9, 5	> /			
ample Info:	7	0- 11	W17		Sample	o Date :	and Time	21 18-11	1235	
Sample ID:								710111	····· ··/ & > 5	
Selected Analysis:	GRO, IS	EX,	MTISE	104	(15				and the second s	
gnature:	les lon			<u> </u>	D	ate:		18-4		
tea <sup>TM</sup> Group, 1-800-477-7411			light non-a elow ground	queous phase l I surface	liquids	_	ol = gailon/s rop = temperat	ure		
			oxidation-Reissolved ex	eduction Potent /gen	tlal		ľU ≈ Nephelom V = millivotts	etric Turbidity U	'nits	
13 a.O.			- '''	. = .						
						• • • • • • • • • • • • • • • • • • • •				
									· · · · · · · · · · · · · · · ·	

	CO	P-ELT Gr	oundwa	ater Sam	pling Fo	rm		
Site Address	15803	3 E 1	Ph 51	Sun Le	andro			
Project No			1	ield Technician		sioni		
Field Point		<u> </u>		Date		8-11		
Depth to Water (DTW (ft bgs)	)		We	II Diameter (in)		4 6 8		
Depth to LNAPL (ft bgs)			Thicknes	s of LNAPL (ft)	:			
Total Depth of Well (ft bgs)	19.0	35	Water Colu	ımn Height (ft)	10.2	5		
			ging Info an	d Calculation				
Purge Method:	,	Purge Ed	quipment:			•	ection Method	
Low-Flow 3 casing Volumes Other:		Elect <b>ric S</b> Peristal	ble Baller Ubmersible tlc Pump er Pump	_	0	Extrac Dedicat	able Bailer W/ tion Port red Tubing ble Tubing	B.E.V.
Water-Golumn-Height-(ft):	10.25						/ 72	J
Water-Column-Height-(ft): Casing Volume (gal):	. 10	X Conversion X Specified V			= Casi _ = Calculated			5000
Conversion Factors Purge: Start		= 0.17   4"		" = 1.5 8" =	Stop Time:	= radius $^2 * 0$		
And the state of t	Temp	and the second s	Conductivity	The second secon	Turbidity	D.O.	Volume	Water Level (for
Time	(°C)	pН	(µS/cm)	OKP (mv)	(NTU)	(mg/L)	Purged (gal)	Law-Flow anly)
Pre-Purge	10.0	9,	i	4 21	<b>5</b> /	O mld	10	
1254	19.2	7.1	1356	-17,4	>1000	2.84	1.0	
1255	20.	7.3	1403	-14.2	170	2.01	2.0	
1256	20.9	7.2	1380	-18.0	149	1.59	3.0	ne mananily se .
1257	21.0	7.2	1350	-18,5	132	1.48	4.0	
1258	21.1	7.2	1342	- 19.1	129	1.41	5.0	
1259	21.	7.2	1339	-19.6	126	1,39	6.0	
Post-Purge			100.00					
Did Well dewater?	Yes 🕏	9	Total	Purge Volume	(gal):	6.0		
	&v% =	11.45						
Other Comments:	DTW.	9.60		MS/MSD	(ExTa	4 Iha's	)	
Sample Info				7:37	(5)//2	7 7000	23	
Sample ID:	MW-8	2011043	50	Sample Date	and Time:	4.1811	1310	
Selected Analysis:	GRO	BETEX	MTBE	70K	5/G	<u> </u>		
Signature:	Mag			Date:	4.1	8.11		
5/g/ldtds-C	1.00 1		· · · · · · · · · · · · · · · · · · ·	Dutci_				
Antea <sup>74</sup> Group, 1-800-477-7411		LNAPL= light non- bgs = below groui ORP = Oxldation-l D,O.= dissolved o	nd surface Reduction Potent	ial	gal = gallon/s temp = temperat NTU = Nephelom rnV = millivolts		bits	. ·
	· · ·							
anteagroup	)					Page	of	
. <del></del>								

	· Calle San All San Miles		的程式是自然的企业上的经验	ater Sam	国际人们的企业 医脑膜			
Site Address		803 E			Son Les		_	
Project No:	V-7 . 9	····	<u> </u>	Field Technician	/V!" [C,			
Field Point	7000	<b>/</b>		Date	: 4.1	18.11		
Depth to Water (DTW) (ft bgs)			We	elf Diameter (in)	· 0	4 6 8		
Depth to LNAPL (ft bgs):			Thickne	ss of LNAPL (ft)				
Total Depth of Well (ft bgs):	23.9	5	Water Col	umn Helght (ft)	: /	4.40		
			rging Info a	nd Calculation	<b>S</b> ;			
Purge Method:		Purge E	quipment;			•	lection Method	
Low-Flow 3 casing volumes Other:		Electric S Perista	able Bailer Submersible Iltic Pump er Pump		o	Dedlca	antobailer ction Port ted Tubing able Tubing	BE, 0
Water. Column Height:(ft):	12/2/			, 7			2-5	
Water. Column Height:(ft): Casing Volume (gal):								<u>ig as a silo sis pes</u>
Casing Volume (gal):							· ·	
Conversion Factors			" = 0.66 6	" = 1.5 8" =	printed from the Links Strangers and Strangers Court of Co.	= radius² * (	.163	
Purge: Start 1	Temp		Conductivity	,	Stop Time:	D.O.	Volume	Waler Level
Time	(°C)	рH	(µS/cm)	ORP (mV)	(NTU)	(mg/L)	Purged (gal)	Low-Flow o
Pre-Purge								
1326	19.1	7.2	1215	-9.4	21000	2.95	1.5	
1327	19.0	7.3	1440	-0.7	>1000	2.85	2.5	
1328	19.2	7.3	1265	-42	847	1.69	2/.0	
1329	19.3	7-3	1251	-6.4	760	1.30	5.5	
1330	19.3	7.3	1246	-7.1	743	1.19	7.0	
33	19.3	7.3	1242	-8.3	731	1.16	8.5	
Post-Purge								
Did Well dewater?	Yes /	io)	Tota	l Purge volume	(gaf);	8.5		
	80 6	12:4	3					
Other Comments:		•	_					
ample Info:	<u> </u>	10.0	<b>ラ</b> ン			SM-Shranistash Make		SAGNAL FALANCA
	16.0	0- 11-11		Sample Date	and Times	2/		·)  /-
Sample ID:	HW9-	401104	0.0	Sample Date	and time;	7-/8-	<u> </u>	)
Selected Analysis:			<u> </u>	· · · · · · · · · · · · · · · · · · ·				
Ignature:Man A	Stoni			Date: _	4.18-	1/	<del></del>	<del></del>
								~
ntea <sup>™</sup> Group, 1-800-477-7411	;	bgs = below grou	Reduction Potent		gal = gallon/s temp = temperat NTO = Nephelom mV = millivolts		nits	
anteagroup						Page		

	CO	P-ELT G	roundw	ater San	npling Fo	rm		
Site Address	1580	3 E /	y7h S	T Sun	Lean	dro		
Project No:				Field Technicia	in: M. 0	18-11		
Field Point	MU-	10		Dat	.e: 4-	18-11		
Depth to Water (DTW) (ft bgs)			We	ell Diameter (Ir	I 65	L.		
Depth to LNAPL (ft bgs):	1		Thickne	ss of LNAPL (fi	t):			
Total Depth of Well (ft bgs):	19,70	2	Water Col	umn Height (fi	t): 9,1	5		
Purge Method:			irging Info a Equipment:	nd Calculatio	Contract Court Cou	Sample Col	ection Method	•
Low-Flow 3 castro volumes Other:		Dispos Electrica Perist	sable Bailer Submersible altic Pump der Pump			Dispog Extra Dedica	oble Pailer Cition Port ted Tubing able Tubing	^
Water Calument 12-by (6)	7.15	V 6		17			<sub>jal):</sub>	6
Water Column Height (ft):  Casing Volume (gal):	1.56	X Specified	n::Factor:(gal/i Volumes:	3	= Calculated	ng <u>=volume=(c</u> l Purge (gal):	<u>4.7</u>	
Conversion Factors	(gal/ft): 2"	= 0.17 4	" = 0.66 6	" = 1.5 8"	= 2.6 Other	· = radius² * 0	.163	
urge: Start.	Time:	135G	o television		Stop Time:	Control of the Contro		\$130 P. OT 17
Time	Temp (°C)	рН	Conductivity (µS/cm)	ORP (mV)	Turbidity (NTU)	D.O. (mg/L)	Volume Purged (gal)	Water Level (fo Low-Flow only)
Pre-Purge			(po/cm/		(WIO)	(mg/c)	, arges (gar)	
1351	19.6	7.3	1612	12.8	>1000	3.34	1.0	
1352	19.2	7.3	1639	10.1	>1000	1.77	1.5	
1353	19.1	7.8	1610	6.3	231	1.35	2.0	
1354	19.1	7.1	1580	4.8	143	1.28	2.5	
1355	19-1	7.1	1550	2.3	130	1.20	3.0	
135 6	19-1	7.1	1546	1.5	121	1.18	3.5	en e
135 7	19.1	7.0	1542	1.2	116	1.14	4.0	
1358	19,1	7.0	1540	1.0	112	1.11	5.0	
Post-Purge						* * * * * * * * * * * * * * * * * * * *		
Did Well dewater?	Yes 🙋	D	Tota	:ı I Purge volum∈	e (gal): <b>5.</b> (	>	Vanication of progression and	
Other Comments:	80% =	44.10						
	DTW	11.2	5					
mple Info:								
Sample ID:	MW-10-	20110	430	Sample Da	te and Time:	4.18-11	14:1	0
Selected Analysis:	GRO	BETE	K, MTBL	- <u>- 70</u>	<u> </u>			1. 1. 10 - 10 - 10 - 10 - 10
nature:	au ( 651	oní_		Date:	1.18.	<u> [[                                  </u>		
ea <sup>TM</sup> Group, 1-800-477-7411		bgs = below gro	ı-Reduction Poten		gal = gallon/s temp = temperat NTU = Nephelom mV = millivolts		nits	
<u>9</u>								······································
<b>antea</b> group						Page	of	
		, -						

## anteagroup

### COP ELT CHAIN-OF-CUSTODY / Analytical Request Document The Chain-of-Custody is a LEGAL DOCUMENT: All relevant fields must be completed and accurate.

Page: 1 of Cooler# of

2Q 2011 GW Event

Required Lab Information:	Required Project Information:		Required Invoice I	nformation:					
Lab Name: Pace-Seattle	Site ID #: 256277 Task:	WG_BM_201104	Send Invoice to:	Tara Bosch					
Address:	AnteaGrp proj# 140256277		Address: 11050 V	Vhite Rock Road Suite	110		Turn around time (days)	10	
940 S. Harney Street Seattle WA 98108	Site Address 15803 East 14th	Street	City/State	Rancho Cordova C/	95670 Phone #: 916-503-1267		QC level Required: Standard	Special	Mark one
Lab PM: Regina Ste. Marie	City San Leandro Sta	te CA	Reimbursement pro	oject?	lon-reimbursement project?	Mark one	NJ Reduced Deliverable Pad	kage?	
Phone/Fax: P: 206-957-2433 F: 206-767-5063	AG PM Name: Dennis D	ettlo#	Send EDD to	copeltdata@intellige	intehs.com		MA MCP Cert? CT F	RCP Cert?	Mark One
Lab PM email Regina.SteMarie@pacetabs.com	Phone/Fax: P: 916-503-1261	F: 916-638-8385	CC Hardcopy r	eport to			Lab Project ID (lab use)		
Applicable Lab Quote #:	AG PM Email: Dennis Dettion	ff@anteagroup.com	CC Hardcopy r	eport to			Requested ///	//////	<b>一</b> ~ 一
SAMPLE ID  Que Character per box. (A-Z, 0-91,-) Samples IDS MUST BE UNIQUE	Valid Matur Codes  MATRIX  WATRIX  WATRIX  WATRIX  WATRIX  WATRIC WATRI   MATRIX CODE SAMPLE TYPE G=GRAB G=COMP	SAMPLE DATE	SAMPLE TIME	# OF CONTAINERS FIELD FILTERED? (VIN) Linguisserved # HSO, HSO, HSO, HSO, HSO,	O <sub>3</sub>	Analyses	, , ,	ments/Lab ple I.D.	
MW-10_20110430		WG	4-18-11	1410	GNX		x x		TBE, DIPE,
2 MW-7 20110430		wg	4-18-11	1235	6 W X		x x	ETBE, TAN Ethanol, 1,3	
MW-8_20110430		WG	4.18 0	1310	10 N X		x x	EDB	
MW-9_20110430		wg	4-18-11	1345	6 N K	12.45	x x		
5, 1, 1	<u> </u>								
6				-					
7	<u> </u>								
8			1 1						
91 :	<u> </u>								:
10				:					_
<u> </u>									
12		Mean of the California		The state of the state of					
Additional Comments/Special Instructions:	: 1	RELINQUISHED BY	the discontinuous in a humanited	etitione in the resident fraction rate.	TIME ACCEPTED BY JAFFILIA	TION	DATE TIME	Sample Receipt C	onditions
	: !	Mattesten	· Blasnet	Zet 4.18.11	1530	1		Y/N Y	/N Y/N
								Y/N Y	/N Y/N
								Y/N Y	/N Y/N
Global ID: T0619718179	! .								IN Y/N
		1 Part of the Control	OD: (mark as epprop REDEX PART SIGNAT		MELL VESTON ?	DAITE Signed	Time: 530	Samples on Ice?	intact? Trip Blank?



# TEST EQUIPMENT CALIBRATION LOG

PROJECT NAM	ME 15803	E 14 m.	ST Saulande	PROJECT NUI	MBER 110418 M		
EQUIPMENT NAME	EQUIPMENT NUMBER	DATE/TIME (	OF STANDARDS USED	EQUIPMENT READING	CALIBRATED TO: OR WITHIN 10%:		
6/tomotone	<del>6214213</del>	4-18-4 @	PH CO	The state of the s		TEMP.	INITIALS
Tur Bidometr	21009	1133	800	796	yes	1500	
ysI 55 6	06 F1362AT	1135	P4 4.7.10,	4.7.10.	The second secon		87
			DO 100%	101.7	1		3
					Secretary of the secret		
			1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
	. :						
	-						
			And the second s				
	1 :		And the second of the second o				

Site InvestigationReport 76 Service Station No. 6277 Antea Group Project No. 140256277



### Appendix G

Waste Manifest

### NON-HAZARDOUS WASTE MANIFEST ase print or type (Form dealgned for use on elite (12 pitch) typowriter)

	Plea	se print or type (Form designed for use on elite (1	2 pitch) typewriler)		*** <u></u>	********************			
		NON-HAZARDOUS WASTE MANIFEST	1. Generator's US EPA I	D No.			Manifest Document No	244-05//A	2. Page 1 of
		3. Generator's Name and Mailing Address	RAR	TON ST	Eneraly.		CT	4 20071	1
ı			303	143 Cov.	undoor st	: 200	15803	C. 14-42 57	reet
		4. Generator's Phone (B) B) BOUT - E	5+05 Hg	OVICE H	Ils, CAY	1301,	Sanle	andro CA	94577
		5. Transporter 1 Company Norm	enices i		A ID Number		A. State Trans		- 111 pargen
		7. Transporter 2 Company Name	(12)	L US EF	PA ID Number	<del>, , , , , , , , , , , , , , , , , , , </del>	B. Transporter C. State Trans		Transfer 25
		The bright open moved if and many below to the property of the second	1	. تعدني	- The state of the		D. Transporter		- Veitar areas
		9. Designated Facility Name and Site Address	ertz 1	IO. USE	PA ID Number		E. State Faeili	ly's ID	
		9. Designated Facility Name and Site Addross Separate Environment Separate	id.	0000	01357	2	F. Facility's Ph	under a service and a service	
		INDUSTRIAL CONTRACTOR	9401031	250 CM 230 A			10	<u>50 304-</u>	1024
		11. WASTE DESCRIPTION U				12. Co No.	nlainers Type	13. Total Quanlity	14. Unit Wt./Vol.
		a,					.,,,,,,		
		Non hurardors wa	ile ligad			1	TT	26	6
	G E	b.							
	N E								
	Ř A	C.							
	<b>T</b>								
	O R	d.	\$\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\						
F- (0)									
MASTE		G. Additional Descriptions for Materials Listed Above		·	·····		H. Handling Co	odes for Wastes Listed Above	***************************************
Ž									
ON-HAZARDOUS									
4				**************************************	renews y warms you you never have no constituted and the state of the	-T+5411-2			
42		15. Special Handling Instructions and Additional Infor	mation L. L. T. L	f.,	And	reva	1 No.	520 - 1049	7
ナ		Went postative equipment weights and volumes are	GROWKING	her.3	Derect	be	1 Blan	SID - 1049 ne Teach Stere	rees
ğ	46	7. (bir coveragency plane	No (30) 88	re-4455m				PATHOSUN	
4				y <i>nama ma</i>		i assi			
		16. GENERATOR'S CERTIFICATION: I hereby certi- In proper condition for transport. The materials de	ly that the contents of this received on this manifest ar	shipment are fully ar e not subject to tode	nd accurately described a gral hazordous waste rec	and ere in : julations.	all respects		
86.90		( proton Gran)						<del> </del>	Daie
£300		Prinlet/Typed Name	thorsed no	Signature	TEME	fi	Λ.	Month	
246	<u>-</u>	Jernyn Hendes	Plad-Ene	1914 /	XXXXX	<u> </u>		V 4	15411
	R A	17. Transporter 1 Acknowledgement of Receipt of Ma	RIOTRIS	Signature			The state of the s	MgnJh	Date /
	S P	Murit Restani	The state of the s	alice (	terset,	J. Janes		4	1811
	잁.	18. Transporter 2 Acknowledgement of Receipt of Ma	derials	Clenatura		·	وبالمهادة والمراجعة		Dale Day Year
	T E R	Printed/Typed Name		Signalure				Month	Day Year
	F	19. Discrepancy Indication Space				<del></del>		g yn hyfryd gyngyd glawr ach a glae gan y de gan de gan y gan y gan	مسادر در مود جوزارد
	A								
[	ĭ	20. Facility Owner or Operator; Certification of mocipi	of the waste materials cov	rered by this manifes	st, except as noted in ite	m 19.	# 475124 1954W PEYRLAND	n, mary hynyggyyd, miny shyd ym y Glindyr y theiddiolod 1884 ff abrunia'd a'n turur heid a Maurein.	
	<u>.</u>	The state of the s	AND THE SECOND S		maranas de la composición del composición de la composición del composición de la co	- Constitution	عدالا فالمتلفظ تسترك فلينوي والفراس ويبادرانها	en e	Dale
	Υ	Printed/Typed Name	Country	Signature		Section of the second section of the section of the second section of the section of the second section of the section of	Manage of	Month (*)	Day Year



Site InvestigationReport 76 Service Station No. 6277 Antea Group Project No. 140256277



### Appendix H

**Case Closure Documents** 

#### ALAMEDA COUNTY

#### **HEALTH CARE SERVICES**





DAVID J. KEARS, Agency Director

December 26, 2000

STID 2422

Mr. David De Witt Tosco Marketing Company 2000 Crow canyon Place, Ste. 400 San Ramon, CA 94583 ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

RE:

Unocal Service Station #6277, 15803 East 14th Street, San Leandro

Dear Mr. De Witt:

This letter transmits the enclosed underground storage tank (UST) case closure letter in accordance with Chapter 6.75 (Article 4, Section 25299.37[h]) of the California Health and Safety Code. The State Water Resources Control Board (SWRCB) has required since March 1, 1997 that this agency use this case closure letter for all UST leak sites. We are also transmitting to you the enclosed case closure summary. These documents confirm the completion of the Investigation and cleanup of the reported release at this site.

#### SITE INVESTIGATION AND CLEANUP SUMMARY

Please be advised that the following conditions exist at the site:

- Up to 510 micrograms per liter (ug/l) Total Petroleum Hydrocarbons as Gasoline (TPH-G), 72 ug/l
  Benzene, and 390 ug/l MtBE are present in groundwater beneath the site.
- Up to 1100 milligrams per kilogram (mg/kg) TPH-G, 8 mg/kg Benzene, and 1300 mg/kg Oil & Grease are present in soil at depths between 5 and 15' below grade.

If you have any questions, please contact the undersigned at (510) 567-6783.

Sincerely,

Scott/O. Seen/, CHMM

Hazardous Materials Specialist

#### Enclosures:

- 1. Case Closure Letter
- 2. Case Closure Summary

cc: Ariu Levi, Chief, Environmental Protection

Matthew Coelho, 18616 Hwy 33 East, Dos Palos, CA 93620-9620 (w/attachment)





DAVID J. KEARS, Agency Director

December 26, 2000

**STID 2422** 

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PHOTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

#### **REMEDIAL ACTION COMPLETION CERTIFICATION**

Mr. David De Witt Tosco Marketing Company. 2000 Crow Canyon Place, Ste. 400 San Ramon, CA 94583

RE:

Unocal Service Station #6277, 15803 E. 14th Street, San Leandro

Dear Mr. De Witt:

This letter confirms the completion of a site investigation and remedial action for the underground storage tanks formerly located at the above-described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tanks are greatly appreciated.

Based on information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, no further action related to the underground tank release is required.

This notice is issued pursuant to a regulation contained in Section 2721(e) of Title 23 of the California Code of Regulations.

Please contact our office if you have any questions regarding this matter.

Sincerely,

Mee Ling Tung

Director, Environmental Health Services

c: Chuck Headlee, RWQCB

Michaell Partons

Allan Patton, SWRCB (w/attachment)

Matthew Coelho, 18616 Hwy 33 East, Dos Palos, CA 93620-9620 (w/attachment)

SOS/files



505

STW

2422

EMPROTECTION

00 JUN 19 AM 9: 00

2000 Crow Canyon Place Sulte 400 San Ramon, CA 94583 925.277.2305 fax: 925.277.2361

Environmental Compliance Department

June 15, 2000

Mr. Thomas Peacock
Manager - LOP
Alameda County - Environmental Health Services
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577

Re: No Further Action

Tosco/76 Products Service Station # 6277

15803 East 14<sup>th</sup> Street San Leandro, CA

Dear Mr. Peacock:

As requested in your June 12, 2000 letter, I certify that I have notified the fee title holder of the subject property of the proposed action by Alameda County. I have included a copy of the letter I sent to Matthew and Ellamae Coelho with regards to the proposed "No Further Action".

If you have any additional questions or concerns, please feel free to contact me at 925-277-2384.

Sincerely,

David B. De Witt

Environmental Project Manager





2000 Crow Canyon Place Sulte 400 San Ramon, CA 94583 925.277.2305 fax: 925.277.2361

Environmental Compliance Department

June 15, 2000

Matthew and Ellamae Coelho 18616 Hwy 33 Dos Palos, CA 93620-9620

Re: No Further Action

Toseo/76 Products Service Station # 6277

15803 East 14th Street San Leandro, CA

Dear Matthew and Ellamae Coelho:

Alameda County Health Care Services – LOP has determined that Tosco Corporation has completed the necessary environmental work at this site and that a finding of "No Further Action" is being considered. I have attached a copy of this notification for your records. As required by the Health and Safety Code (Ch. 6.7 – section 25297.15), I am notifying you, as the fee title holder, of this proposed action.

If you have questions or concerns on this subject, please feel free to call me at 925-277-2384.

Sincerely,

David B. De Witt

Environmental Project Manager



#### ALAMEDA COUNTY

#### **HEALTH CARE SERVICES**

**AGENCY** 



June 12, 2000

**STID 2422** 

Mr. David De Witt Tosco Marketing Company 2000 Crow Canyon Place, Ste. 400 San Ramon, CA 94583

DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Sulte 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

RE: Unocal Service Station #6277, 15803 E. 14th Street, San Leandro

INTENT TO MAKE A DETERMINATION THAT NO FURTHER ACTION IS REQUIRED

Dear Mr. De Witt:

This letter is to inform you that Alameda County Euvironmental Health Department, Local Oversight Program (LOP), intends to make a determination that no further action is required at the above site, as concurrence from the Regional Water Quality Control Board (RWQCB) has been received. Please notify this agency of any input and recommendations you may have on these proposed actions within 20 days of the date of this letter.

In accordance with section 25297.15 of Ch. 6.7 of the Health & Safety Code, you must provide certification to the local agency that <u>all</u> of the current record fee title owners have been informed of the proposed action. Please provide this certification to this office within 20 days of the date of this letter.

If you have any questions about these proposed actions, please contact Scott Seery at (510) 567-6783.

Sincerely,

Thomas Peacock

Manager, LOP

cc;

Chuck Headlee, RWQCB Scott Seery, ACDEH LOP

Date: 04/29/98



### 00 JUN -9 PM 4: 19 Leaking Underground Fuel Storage Tank Program

#### J. AGENCY INFORMATION

Agency name: Alameda County-EPD Address: 1131 Harbor Bay Pkwy #250

City/State/Zip: Alameda, CA 94502 Phone: (510) 567-6700 Phone: Title: Haz. Materials Spec.

#### II. CASE INFORMATION

Site facility name: Unocal Station #6277

Site facility address: 15803 E.14th Street, San Leandro 94578

RB LUSTIS Case No: N/A Local Case No./LOP Case No.: 2422

URF filing date: 03/16/89 SWEEPS No: N/A

Responsible Parties: Addresses: Phone Numbers:

Tosco Marketing Co. P.O. Box 5155 (925) 277-2384

Attn: David deWitt San Ramon, CA 94583

Mathew & Ella Coelho 18616 Hwy 33 East

Dos Palos, CA 93620-9620

<u>Tank</u>	Size in	Contents:	Closed in-place	Date:
No:	gal,:		or removed?:	
1	10,000	gasoline	removed	03/13/89
2	10,000	D	11	41
3	550	waste oil	1)	II .

#### III. RELEASE AND SITE CHARACTERIZATION INFORMATION

Cause and type of release: UNK (failed integrity test lead to UST removals)

Site characterization complete? YES

Date approved by oversight agency:

Monitoring Wells installed? YES Number: 7

Proper screened interval? YES

Highest GW depth below ground surface: 5.85' Lowest depth: 11.34' (stabilized)

Flow direction: predominately NW - N

Most sensitive current use: commercial (adjoined by apts.)

Are drinking water wells affected? NO Aquifer name: San Leandro cone

#### Page 2 of 7

#### Leaking Underground Fuel Storage Tank Program

#### III. RELEASE AND SITE CHARACTERIZATION INFORMATION (Continued)

Is surface water affected? NO Nearest affected SW name: NA

Off-site beneficial use impacts (addresses/locations): NONE

Report(s) on file? YES Where is report filed? Alameda County

1131 Harbor Bay Pkwy Alameda CA 94502

Treatment and Disposal of Affected Material:

	Disposar of Africator materials	a 45 450 4	<b>.</b>
<u>Material</u>	<u>Amount</u>	Action (Treatment	<u>Date</u>
	<u>(include units)</u>	or Disposal w/destination)	
Tank	(2 x 10K; 1x 550 gal)	Disposal – UNK (but presumed	3/89
	,	to have gone to Erickson, Richmor	nd,
		CA)	•
Piping	Unk	as above	,
Free Product	NA		•
Soil	162 tons	Disposal - Casmalia LF	4/14/89
	1000	Casmalia, CA	
	1000 yds <sup>3</sup>	Disposal - Redwood LF	4/4/89 -
	,	Novato, CA	4/18/89
	218 tons	Disposal – Petroleum Waste	5/18/89
		Buttonwillow, CA	
	1060 yds <sup>3</sup>	Disposal - Mt. View dump	9/5/89
	·	Mt. View, CA	9/11/89
	2.4 tons	Disposal - GSX Services	11/1/89
		Buttonwillow, CA	
	673 tons	Disposal - GSX Services	4/13/90
		Buttonwillow, CA	4/16/90
		•	
Groundwater	19,400 gal	Disposal - H& H Ship Svc.	3/21/89 &
		So. S.F., CA	4/2/90 4/5/90
		· · · · · · · · · · · · · · · · · ·	

#### Maximum Documented Contaminant Concentrations - - Before and After Cleanup

Contaminant	Soil¹ (p	pm)	Water <sup>2,3</sup> (ppb)	
	Before	After	Before A	fter
TPH (Gas)	3500	1100	19,000 5	10
TPH (Diesel)	ND	6.2	NA N	ĮΑ
Benzene	40	8	230 7	2
T <b>ol</b> uene	280	43	79 N	<b>I</b> D
Xylene	600	230	1300 1	7

#### Page 3 of 7

#### **Leaking Underground Fuel Storage Tank Program**

#### III. RELEASE AND SITE CHARACTERIZATION INFORMATION (Continued)

#### Maximum Documented Contaminant Concentrations - - Before and After Cleanup

Contaminant	Soil¹ (p	Soil <sup>1</sup> (ppm)			Water <sup>2,3</sup> (ppb)	
	Before	<u>After</u>		Before	After	
Ethylbenzene MtBE	100 NA	37 NA		ND NA	ND 390	
Oil & Grease Heavy metals	7700 NA	1300 NA		NA "	NA "	
Other HVOC TCE	0.063	ND	TCE PCE DCA	4.4 110 2.8	ND 950 ND	

#### Note:

- 1) All "before" soil results compiled from initial sidewall samples collected during March 1989 fuel UST closures, except for Q&G, TCE and TPH-D results. O&G and TCE results from the 5' sample collected during advancement of well/boring MW-2 in May 1989. TPH-D result derived from a sample collected from the base of the waste oil UST pit following tank removal. All "after" soil results from sidewall samples collected after the 1990 over-excavation of the general area of former well MW-2, except for O&G. O&G result from the 5' soil sample collected from well/boring MW-2A in 1991.
- 2) "Before" water results from sample collected from the fuel UST excavation during 1989 closures, except as otherwise indicated. All "after" water results reflect samples collected from well MW-1 in November 1996, except as otherwise indicated.
- 3) "Before" HVOC water results from initial sample collected from well MW-2 in June 1989. "After" water results from sample collected from well MW-3 in January 1996.

#### Comments (Depth of Remediation, etc.):

During March 1989 three (3) single wall steel USTs were removed from this site. Two 10,000 gasoline and one 550 gallon waste oil USTs were closed during this effort. The original USTs were replaced by double-wall tanks emplaced elsewhere at the site. Tank replacement appears to have been prompted by a series of failed integrity tests in the years and months preceding this effort.

Ground water was encountered in the fuel tank pit at a depth of ~11 feet BG. Consequently, sidewall samples, six in all, were initially collected from the excavation a foot above stabilized water level. A single soil sample was collected from the base of the shallower waste oil tank pit. In addition, soil samples were also collected from the product piping trenches.

Initial subjective evidence prompted the contractor to expand the fuel tank excavation laterally in two rounds, at which point additional sidewall samples were collected. This expanded excavation encroached on and engulfed the former waste oil UST location as well. Following the initial over-excavation effort, a reported ~5000 gallons of water was pumped from the excavation, and ~14,500 gallons during the second. A water sample was collected from ground water that collected in the expanded tank pit.

#### Page 4 of 7

#### Leaking Underground Fuel Storage Tank Program

Initial soil samples from the fuel UST pit revealed up to 3500 ppm TPH-G and 40 ppm benzene, among other detected fuel compounds. Over-excavation samples demonstrated a marked reduction in contaminant concentrations, with a TPH-G high of 100 ppm and benzene high of 3.1 ppm. Although the initial waste oil UST pit sample Identified the presence of TOG (280 ppm), no 8240 compounds were identified above laboratory detection limits. The water sample, however, revealed up to 19,000 ug/l TPH-G and 230 ug/l benzene, among other detected fuel components.

Significant soil was removed from the enlarged UST excavation and stockpiled on-site during the 1989 (and subsequent 1990) activities. All soil was eventually disposed of at various California waste facilities between April 1989 and April 1990. (See: Section III. Release and Site Characterization Information)

#### IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan?
Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan?
Does corrective action protect public health for current land use? YES Site management requirements: NA
Should corrective action be reviewed if land use changes? YES
Monitoring wells Decommissioned: YES (1)
Number Decommissioned: 1 Number Retained: 6 (pending case closure)
List enforcement actions taken: NONE
List enforcement actions rescinded: NONE
V. LOCAL AGENCY REPRESENTATIVE DATA
Name: Scott Seery Title: Haz Mat Specialist Signature: Date: 4-2/-00
Name: Eva Chu Signature:  Name: Eva Chu Sign

#### Page 5 of 7

#### Leaking Underground Fuel Storage Tank Program

#### VI. RWQCB NOTIFICATION

4-21-00 Date Submitted to RB:

RWQCB Staff Name: Chuck Headlee

RB Response: Concur Cluel Headlel
Title: Eng. Assoc. Date: 4/28/00

#### VII. ADDITIONAL COMMENTS, DATA, ETC.

In preparation for the 1989 tank replacement project, exploratory borings were advanced in the area of the site chosen for the new USTs. Borings EB-1 and -2 were advanced up to 13.5' BG. Ground water was encountered between 11 and 12' BG. Soil samples collected at the 5 and 10' depths revealed some degree of impact by fuel compounds, most evident in the 10' samples, a depth consistent with that of ground water at the site.

Following UST closures, four (4) monitoring wells were installed at the site during May 1989. Total well depths ranged from 24.5 to 25' BG, with 19.5' well screens. Encountered sediments were primarily fine-grained to depths explored. Ground water stabilized between approximately 10 and 11' BG.

Elevated concentrations TOG (7700 ppm), benzene (13 ppm), as well as detectable concentrations of TCE (0.063 ppm) and other fuel components, were identified in the 5' soil sample collected from well boring MW-2.

Detectable fuel components were also identified in shallow soil samples collected from the other well borings, but were present at unremarkable concentrations.

Initial water samples identified detectable TPH-G in samples collected from each well; all BTEX components were "ND". However, detectable concentrations of PCE (110 ug/l), 1,2-DCA (2.8 ug/l), and TCE (4.4 ug/l) were noted in water sampled from MW-2.

As a consequence of soil contamination noted during advancement of well boring MW-2, this well was eventually destroyed and the area around it excavated in early 1990 to a depth of approximately 12' BG. Soll samples were collected from the sidewalls of the resultant excavation. Up to 1100 ppm TPH-G, 8 ppm benzene, and 210 ppm TOG, among other constituents, were identified in these samples, collected at the 10.5' depth. HVOC compounds were "ND".

Well MW-2 was eventually replaced by well MW-2A in a location 30' northwest of its original location. Up to 1300 ppm TOG was identified in the 5' sample collected during boring advancement.

Due to the regular occurrence of PCE. TCE and 1.2-DCA in sampled ground water, a review of records documenting historic site activities was performed in 1993. Reported site history indicates the site was first developed as a gas station from an empty lot in 1969. No likely on-site source of the HVOC impact was identified. The potential for an off-site HVOC source is further supported by the fact that the highest HVOC concentrations have been found in samples collected from wells MW-3 and -4, located on the upgradient side of the subject site, close to property margins. Hence, HVOCs detected in these wells are likely coming from a source (e.g., leaching sanitary sewer lines, etc.) upgradient of the site.

#### Page 6 of 7

#### Leaking Underground Fuel Storage Tank Program

#### VIJ. ADDITIONAL COMMENTS, DATA, ETC. (Continued)

Following several quarters of ground water and sampling, two additional wells (MW-5 and -6) were installed in the adjoining apartment complex to assess potential off-site impacts from the UST release at this site. Some impact, albeit minor, was identified.

Well sampling continued through November 1996. Groundwater flow has predominantly ranged from SW to N during the course of the investigation.

Water sampled from well MW-1 continued to show the highest concentrations of fuel hydrocarbons throughout the duration of this investigation. As well MW-1 is the most downgradient of the wells at the site, an off-site study was conducted in March 1997 to assess any impacts in the downgradient direction. Three Geoprobe boreholes (EB-3, -4, and -5) were advanced through E. 14th Street in a northerly transect from the site. No detectable target compounds were identified in either soil or ground water samples.

This case appears be a "Low Risk Groundwater Case", as described in the January 5, 1996 San Francisco Bay Regional Water Quality Control memorandum entitled "Regional Board Supplemental Instructions to State water Board December 8, 1995, Interim Guidance on Required Cleanup at Low-Risk Fuel Sites," as follows:

1) The leak has been stopped and ongoing sources, including free product, have been removed or remediated.

The subject tanks were removed in 1989. Free product has not been known to occur at the site.

#### 2) The site has been adequately characterized.

A 6-well network of wells was installed, monitored, and sampled over the course of several years. Additional sampling points were installed downgradient of the site. These points have allowed an adequate confirmation of underlying geology, groundwater flow, and contaminant extent.

#### 3) The dissolved hydrocarbon plume is not migrating.

The plume appears stable. Hydrocarbon concentrations have attenuated over time, and appear limited in extent.

4) No water wells, deeper drinking water aquifers, surface water, or other sensitive receptors are likely to be impacted.

There are no known municipal or residential water wells or surface water bodies within 750' downgradient of the subject site that would be impacted by shallow groundwater from this site.

#### Page 7 of 7


#### Leaking Underground Fuel Storage Tank Program

#### 5) The site presents no significant risk to human health.

Comparison of ASTM E 1739-95 *Risk Based Screening Levels (RBSL)* with site-specific concentration and occurrence of risk-driving target compounds (e.g., benzene) in groundwater demonstrate that RBSL values are not exceeded for plausible exposure pathways at the 1E-05 risk level for a commercial/industrial site. Residual benzene soil concentrations (based on 1990 soil data) exceed RBSL values for the soil-vapor-intrusion-to-buildings exposure pathway at the 1E-04 risk level. However, default criteria used to calculate the published RBSLs use exceedingly conservative input parameters (e.g., sandy soil texture). Site-specific geology (clay) and asphalt cap are much less conducive to vertical vapor transport to potential receptor locations at the site.

#### 6) The site presents no significant risk to the environment.

No environmental receptors are known or expected to be proximal to the site.




Base modified from 7.5 minute U.S.G.S. Hayward and San Leandro Quadrangles (both photorevised 1980)

O 2000 4000
Approx. scale feet



UNOCAL SERVICE STATION #6277 15803 E, 14TH STREET SAN LEANDRO, CALIFORNIA


LOCATION MAP





#### KAPREALIAN ENGINEERING, INC.

Consulting Engineers
P. Q. BOX 913
BENICIA, CA 94510
(415) 676 - 9100 (707) 746 - 6915




15803 East 14th Street San Leandro, California



#### KAPREALIAN ENGINEERING, INC.

#### Consulting Engineers

P.O. BOX 996 • BENICIA, CA 94510 (707) 746-6915 • (707) 746-6916 • FAX: (707) 746-5581



Unocal Service Station #6277 15803 East 14th Street San Leandro, California

Table /A
Summary of Laboratory Analyses
Water

			· · · · · · · · · · · · · · · · · · ·				1868 NESTER 1868
Well #	Date	TPH as Gasoline	Benzene	Toluene	Ethyl- Beitzene	Xylenes.	MTBE
Well Williams	ing properties	THE MAY PROPERTY.				4.55.55	-200
MW1	11/25/96	510♦	72	ND	ND	17	390 √
	7/1/96	ND	ND	ND	ND	ND	230
	4/8/96	2,100	43	27	7.4	21	480
	1/10/96	220	35	ND	2.0	7.6	†
	7/14/95	410	77	ND	7.4	30	
	4/4/95	410♦	19	ND	ND	ND	
	1/5/95	780	30	ND	ND	9.1	-4
	10/6/94	970	19	ND	ND	13	77,
	7/7/94	2,100 + +	250	ND	57	200	
	4/4/94	1,100	15	ND	ND	7.4	
	1/6/94	260	21	ND	2.5	14	
	10/6/93	1,200+	36	ND	ND	23	
	7/1/93	510	100	0.79	5.7	52	
	4/2/93	690	94	0.73	5.3	39	
	1/29/93	740♦♦	69	ND	3.8	43	
	10/20/92	720	110	1.4	18	110	
	7/20/92	630	100	2.8	6.3	52	
	4/23/92	530	100	7.9	4.6	60	
	1/13/92	450	240	4.6	8.6	73	
	9/10/91	280	38	3.1	4.1	22	
	6/10/91	310	1.5	. ND	ND	0.31	
	3/15/91	110	21	ND	ND	8.4	
	12/14/90	450	150	6.8	0.28	49	
	9/19/90	140	ND	ND	ND	3,5	
	6/25/90	310	10	0.89	0.37	2.1	
	3/29/90	320	12	1.6	0.31	3.5	
	12/12/89	340	100	13	3.4	44	
	9/13/89	550	32	17	3.4	52	
	6/6/89	590	ND	ND	ND	ND	
Λ₩2A	11/25/96	86♦	0.82	ND	ND	ND	ND
11211	7/1/96	170	2.4	ND	0.65	2.0	ND
	4/8/96	ND	ND	ND	ND	ND	ND
	1/10/96	89	1.2	ND	ND	0.58	***
	7/14/95	60	3.0	ND	1.3	2.4	
	4/4/95	67♦	1.0	ND	ND	ND	
	1/5/95	140♦	1.4	ND	ND	ND	
	10/6/94	71	6.4	ND	2.1	2.4	
	7/7/94	90	5.2	ND	1.5	2.2	
	4/4/94	80	8.0	ND	1.4	1.5	_=
	1/6/94	110	2.6	ND	1.6	1.7	
	10/6/93	110♦	12	ND	7.4	1.4	
	7/1/93	74♦	0.75	ND	ND	ND	
	//1/73	/→ ▼	7.2	ND	5.8	1.2	

**Table**Summary of Laboratory Analyses
Water

Well #	. Date	TPH as Gasoline	Benzene	Taluenc	Ethyl- Benzene	Xylenes	MTBE
MW2A (Cont)	10/20/92	96	2.8	ND	1.8	1.6	
211 (2011)	7/20/92	99	8.6	ND	2.4	0.95	
	4/23/92	190	15	ND	15	2.0	~~
	1/13/92	160	11	2.0	10	5.9	
	9/10/91	180	8.7	0.93	15	13	
	6/10/91	54	1.2	ND	ND	0.69	
	3/15/91	160	2.5	ND	ND	51	
∕IW2	12/12/89	660	220	6.6	13	36	
	9/13/89	170	2.0	0.38	ND	9.5	
	6/6/89	77	ND	ND	ND	ND	₩#
1W3	11/25/96	120♦	ND	ND	ND	ND	ND
	7/1/96	ND	ND	ND	ND	МD	ND
	4/8/96	ND	ND	ND	ND	ND	ND
	1/10/96	100 ♦	ND	ND	ND	ND	μ <b>-</b>
	7/14/95	130 ♦	ND	ND	1.3	4.2	
	4/4/95	100 ♦	0.62	ND	ND	ND	
	1/5/95	140 ♦	ND	ND	ND	ND	
	10/6/94	93♦	ND	ND	ND	ND	~-
	7/7/94	190♦	ND	ND	ND	ND	F-
	4/4/94	170♦	ND	ND	ND	ND	
	1/6/94	140♦	ND	ND	ND	ND	
	10/6/93	140♦	ND	ND	ND	ND	
	7/1/93	120 ♦	ND	ND	ND	ND	
	4/2/93	130◆	ND	ND	ND	ND	
	1/29/93	130 ♦	0.84	ND	ND	ND	
	10/20/92	180 ♦	ND	ND	ND	ND	
	7/20/92	120♦	ND	ND	ND	ND	
	4/23/92	150♦	1.6	ND	ND	ND	
	1/13/92	120♦	ND	ND	ND	ND	
	9/10/91	170	ND	ND	ND	ND	
	6/10/91	160	0.65	ND	ND	ND	
	3/15/91	150	ND	ND	ND	0.45	
	12/14/90	150	ND	ND	ND	ND	
	9/19/90	74	0.74	ND	ND	ND	
	6/25/90	190	1.5	0.68	ND ·	5.3	
	3/29/90	85	ND	ND	ND	ND	
	12/12/89	120	6.7	0,64	0.46	1.5	
	9/13/89	76	ND	ND	ND	ND	
	6/6/89	32	ND	ND	ND	ND	

**Table /A**Summary of Laboratory Analyses
Water

			water				
		TPHas			Ethyl-		
Well #	Date	Gasoline	Benzene	Toluene	Benzene	Xylenes	MTBE
	<u>. 17 </u>	<u> </u>		· · · · · · · · · · · · · · · · · · ·			
MW4	11/25/96	120♦	ND	ND	ND	ND	ND
	7/1/96	ND	ND	ND	ND.	ND	ND
	4/8/96	ND	ND	ND	ND	ND	ND
	1/10/96	100♦	ND	ND	ND	1.8	~~
	7/14/95	89♦	ND	ND	0.97	0.52	**
	4/4/95	82♦	ND	ND	ND	ND	
	1/5/95	150♦	ND	ND	ND	ND	en 19
•	10/6/94	78♦	ND	ND	ND	ND	w.m
	7/7/94	150♦	ND	ND	ИD	ND	~=
	4/4/94	120	0.76	0.76	ND	0.98	
	1/6/94	100♦	ND	ND	ИD	ND	
	10/6/93	130♦	ND	ND	ND	ND	
	7/1/93	91 ♦	ND	ND	ND	ND	
	4/2/93	110♦	ND	ND	ND	ND	***
	1/29/93	130♦	0.95	ND	ND	ND	
	10/20/92	110◆	ND	ND	ND	ND	
	7/20/92	80 ♦	ND	ND	ND	ND	
	4/23/92	120◆	ND	ИD	ND	ND	
	1/13/92	58♦	ND	ND	ND	ND	
	9/10/91	56	ND	ND	ND	ND	
	6/10/91	64	ND	ND	ND	ND	
	3/15/91	. 53	ND	ND	ND	ND	
	12/14/90	54	ND	ND	ND	ND	p. m.
	9/19/90	61	ИD	ND	ND	ND	
	6/25/90	66	ND	ND	ND	ND	
	3/29/90	120	0.39	ND	ND	ND	
	12/12/89	97	4.6	ND	ND	ND	
	9/13/89	77	ND	ND	ИD	ND	
	6/6/89	37	ND	ND	ND	ND	
MW5	11/25/96	120◆	ND	ND	ND	ND	ND
	7/1/96	ND	ND	ND	ND	ND	ND
	4/8/96	ND	ND	ND	ND	ND	ND
	1/10/96	50♦	ND	ND	ND	ND	
•	7/14/95	ND	ND	0.91	ND	1.1	
·	4/4/95	ND	ND	ND	ND .	-	
	1/5/9 <b>5</b>	ND	ND	ND	ND	ND	₩.
	10/6/94	ND	ND	ND	ND	ND	
	7/7/94	72♦	ND	ND	ND	ND	
	4/4/94	65♦	ND	ND	ND	ND	
	1/6/94	62◆	ND	ND	ND	ND	=-
	10/6/93	60♦	ND	ND	ND	ND	
	7/1/93	54♦	ND	ND	ND	ND	
	4/2/93	65♦	ND	ND	ND	ND	

Table IA
Summary of Laboratory Analyses
Water

Well #	Date	TPH as Gasoline	Benzene"	Toluëne	Ethyl- Benzene	Xylones	MTBE
MW6	11/25/96	120◆	ND	ND	ND	ND	ND
	7/1/96	ND	ND	ND	ND	ND	ND
	4/8/96	ND	ND	ND	ND	ND	ND
	1/10/96	53 ♦	ND	ND	ND	ND	
	7/14/95	ND	ND	ND	ND	ND .	-
	4/4/95	ND	ND	ND	ND	ND	
	1/5/95	ND	ND	ND	ND	ND	
	10/6/94	ND '	ND	ND	ND	ND	
	7/7/94	ND	ND	ND	ND	ND	
	4/4/94	57♦	ND	ND	ND	ND	
	1/6/94	53♦	ND	ND	ND	ND	
	10/6/93	ND	ND	ND	ND	ND	
	7/1/93	ND	ND	ND	ND	ND	
	4/2/93	ND	ND	ND	ND	ND	,

- † Sequoia Analytical Laboratory has identified the presence of MTBE at a level above or equal to the taste and odor threshold of 40 μg/L in the sample collected from this well.
- Sequoia Analytical Laboratory reported that the hydrocarbons detected did not appear to be gasoline.
- • Sequoia Analytical Laboratory reported that the hydrocarbons detected appeared to be a gasoline and non-gasoline mixture.

MTBE = methyl tert butyl ether.

ND = Non-detectable.

Results are in micrograms per liter (µg/L), unless otherwise indicated.

- Note: The detection limit for results reported as ND by Sequoia Analytical Laboratory is equal to the stated detection limit times the dilution factor indicated on the laboratory analytical sheets.
  - Prior to August 1, 1995, the total purgeable petroleum hydrocarbon (TPH as gasoline) quantification range used by Sequoia Analytical Laboratory was C4 C12. Since August 1, 1995, the quantification range used by Sequoia Analytical Laboratory is C6 C12.
  - Laboratory analyses data prior to January 6, 1994, were provided by Kaprealian Engineering, Inc.

**Table 1B**Summary of Laboratory Analyses
Water

Well#	Date	TPH as Diesel		Trichloro ethene	1.2 Dichloro ethane	Cis-1,2- dichloro- ethene	Total Oil & Grease (mg/L)
MW1	4/04/94*		390	38	ND	17	8745
	4/2/93	ND					
	1/29/93	ND	300	ND	ND	ND	
	10/20/92	ND	230	22	ND	16	
	7/20/ <del>9</del> 2	62♦	200	7.4	ND	ND	<b>*</b> -
MW2	4/2/93	ND					
	12/12/89	1,700	30	9.0	ND	ND	1.2
	9/13/89	ND	18	6.1	4.2	1.2	ND
	6/6/89	ND	110	4.4	2.8	ND	ND
MW2A	9/10/93	65		***			
	1/29/93	ND	140	10	ND	ND	N-
	10/20/92	ND	64	11	ND	NÐ	
	7/20/92	ND	35	7.2	ND	4.8	ND
,	4/23/92	ND	17	5.6	ND	1.9	ND
	1/13/92**	ND	33	ND	ND	2.1	ND
	6/10/91	100	150	10	ND	ND	ND
	3/15/91	ND	67	8.2	ND	2.6	ND
MW3	1/10/96	<b>#</b> =	950	ND	ND	ND	
	1/5/95		1,100	18	ND	6.2	
	1/6/94		960	ND	ND	ND	
	4/2/93	ND					
	1/29/93	ND	980	ND	ND	ND	
	10/20/92	ND	1,100	20	ND	ND	<b>~-</b>
	7/20/92	ND	1,400	25	ND	ND	<del>-</del> -
MW4	1/29/93	ND	950	ND	ND	ND	
	7/20/92	ND	440	11	ND	ND	
	4/2/93	ND					
	10/20/92	ND	360	17 '	ND	ND	
MW5	4/2/93	ND	190	ND	ND	ND	
MW6	4/2/93	ND	71	ND	ND	ND	

### Table 18 Summary of Laboratory Analyses Water

- \* All EPA method 8240 constituents were non-detectable, except for concentrations of benzene at 29 µg/L, ethylbenzene at 3.4 µg/L, total xylenes at 19 µg/L, and trans-1,2-dichloroethene at 2.4 µg/L.
- \*\* 1,1,2-trichloroethane was detected at a concentration of 9.9 μg/L.
- Sequoia Analytical Laboratory reported that the hydrocarbons detected did not appear be diesel.

ND = Non-detectable.

-- Indicates analysis was not performed.

mg/L = milligrams per liter.

Results are in micrograms per liter (µg/L), unless otherwise indicated.

Note:

All EPA method 8010 constituents were non-detectable in all of the ground water samples, except as indicated.

Laboratory analyses data prior to January 6, 1994, were provided by Kaprealian Engineering, Inc.

KEI-P89-0301.R1 March 13, 1989

TABLE 1 C

### SUMMARY OF LABORATORY ANALYSES SOIL

(Results in ppm) (Collected on March 6, 1989)

Sample <u>Number</u>	TPH as <u>Gasoline</u>	Benzene	<u>Toluene</u>	Xylenes	<u>Ethylbenzene</u>
EB1(5)	2.1	ND	0.11	ND	0.14
EB1(10)	200	2.3	7.7	5.7	33
EB2(5)	ND	ND	ND	ND	ND
EB2(10)	620	2.2	20	13	78

ND = Non-detected

KEI-P89-0301.R12 April 11, 1997

TABLE 1/.D

SUMMARY OF LABORATORY ANALYSES
SOIL

Date	Sample Number	TPH as <u>Gasoline</u>	Benzene	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylenes	MTBE
3/18/97	EB3 (5)	ND	ND	ND	ND	ND	ND
	EB3 (10)	ND	ND	ND	ND	ND	ND
	EB3 (14.5)	ND	ND	ND	ND	ND	ND
	EB4(4.5)	ND	ND	ND	ND	ND	ND
	EB4 (10)	ND	ND	ND ·	ND	ND	ND
	EB4 (13)	ND	ND	ND	ND	ND	ND
	EB5(5)	ND	ND	ND	ND	ND	ND
	EB5 (10)	ND	ND	. ND	ND	ND	ND

NOTE: The soil samples were collected at the depths below grade indicated in the ( ) of the respective sample number.

ND = Non-detectable.

Results are in milligrams per kilogram (mg/kg), unless otherwise indicated.

KEI-P89-0301.R12 April 11, 1997

TABLE 1 &
SUMMARY OF LABORATORY ANALYSES
WATER

<u>Date</u>	Sample <u>Number</u>	TPH as <u>Gasoline</u>	Benzene	Toluene	Ethyl- <u>benzene</u>	Xvlenes	MTBE
3/18/97	EB3	ND	ND	ИD	ИD	ND	ND
	EB4	ИО	ND	ND	ND	ND	ND
	EB5	ND	ND	ИD	ND	ИД	ND

NOTE: Water samples were collected during drilling. The results of the analyses may not be representative of formation water, and should be used for comparative informational purposes only.

Results are in micrograms per liter ( $\mu g/L$ ), unless otherwise indicated.

KEI-P89-0301.R3 March 27, 1989

#### TABLE 2

SUMMARY OF LABORATORY ANALYSES \* WATER

(Results in ppb)

The state of

(Samples collected on March 19, 1989)

Sample # Gasoline Benzene Toluene Xylenes Ethylbenzene
W-1 19,000 230 79 1,300 ND

Detection
Limits 50 0.5 0.5 0.5

ND = Non-detectable

\* sample collected from UST pit during 1989 closures

KEI-P89-0301.R8 April 16, 1991

#### TABLE 3

# SUMMARY OF LABORATORY ANALYSES SOIL

KANS TEAL.

(Collected on March 12, 1991)

Depth TPH as TPH as Ethyl-Sample (feet) Diesel Gasoline Benzene Toluene Xylenes benzene TOG Number MW2A(5)\* 5 4.8 ND ND ND ND ND 1,300 MW2A(10)\* 10 2.4 10 0.12 0.17 1.6 0.14 260 MW2A(14.5)\* 14.5 ND ND ND 0.0080 0.036 ND 57 Detection 0.0050 0.0050 Limits 1.0 1,0 0.0050 0.0050 30

ND = Non-detectable.

Results in parts per million (ppm), unless otherwise indicated.

•

<sup>\*</sup> All EPA method 8010 constituents were non-detectable, except for 0.110 ppm of 1,2-dichlorobenzene, and 0.120 ppm of tetrachloroethene detected in sample MW2A(10).

KEI-P89-0301.R8

April 16, 1991

TABLE 4
SUMMARY OF LABORATORY ANALYSES
SOIL

(Samples collected on April 3, 1990)

Sample	Depth (feet)	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Xylenes	Ethyl- benzene
sw8A*	10.5	62	260	1.4	8.0	40	7.0
sw9A*	10.5	ND	ND	0.017	0.041	0.033	0.0092
SW10A*	10.5	ИD	140	0.085	0.12	5.0	1.4
SW11A**	10.5	280	1,100	8.0	43	230	37
Detection Limits	on	1.0	1.0	0.0050	0.0050	0.0050	0.0050

<sup>\*</sup> TOG and all EPA method 8010 constituents were non-detectable for these samples.

ND = Non-detectable.

Results in parts per million (ppm), unless otherwise indicated.

<sup>\*\*</sup> TOG showed 210 ppm, while all EPA method 8010 constituents were non-detectable.

KEI-P89-0301.R8 . April 16, 1991

TABLE 5
SUMMARY OF LABORATORY ANALYSES
SOIL

Sample <u>Number</u>	Depth (feet)	TPH as <u>Gasoline</u>	Benzene	<u>Toluene</u>	<u>Xylenes</u>	Ethylbenzene
		(Col)	lected on	March 6,	1989)	The man was
EB1(5) EB1(10)	5 10	2.1 200	ND 2.3	0.11 7.7	ND 5.7	0.14 33
EB2(5) EB2(10)	5 10	ND 620	ND 2.2	ND 20	ND 13	ND 78
		(Collected	on March	13, 14 8	17, 1989	9)
SW1 SW1(2) SW2 SW3(15) SW4/5(6) SW6(12) SW7(14)*	10	3,500 100 390 60 24 150 ND	1.3 40 1.6 2.6 3.1 0.3	280 6.6 4.3 2.9 1.7 6.2 ND	600 16 71 7.8 2.7 5.6 ND	100 2.9 10 1.5 0.56 3.6 ND
P1 P2 P3 P4 P5 P6	3 3 3 3 3,5	2.3 1.5 1.1 5.6 6.8 5.5	ND ND ND ND 0.15 0.06	0.15 0.31 0.1 0.15 0.58 0.18	ND ND ND 0.39 0.55 0.15	ND ND ND ND 0.12 ND
WO1**	10	15	ND	ИD	0.21	88.0
		(Col)	ected on	May 24,	1989)	•
MW1(5) MW1(10)	5 10	2.3 290	0.08 1.0	ND 11	0.62 48	ND 8.8
MW2(5)** MW2(10)+		230 31	13 1.2	1.7 1.0	3.2 5.5	1.5 1.1
MW3(5) MW3(10)	5 <b>10</b>	3.2 4.6	0.29 ND	O.1 ND	0.7 0.44	ND 0.3
MW4 (5) MW4 (10)	5 10	3.1 ND	ND ND	0.11 ND	ND ND	ND ND

KEI-P89-0301.R8 April 16, 1991

#### TABLE 5 (Continued)

# SUMMARY OF LABORATORY ANALYSES SOIL

A ....

- \* TPH as diesel was 6.2 ppm; TOG was at 41 ppm; all 8240 constituents are non-detectable, except as noted above.
- \*\* TPH as diesel was non-detectable; TOG was at 280 ppm; all 8240 constituents are non-detectable, except as noted above.
- \*\*\* TPH as diesel was non-detectable, TOG was 7,700 ppm, and trichloroethene at 0.063 ppm.
- + TPH as diesel was non-detectable, TOG was 38 ppm, and trichloroethene at 0.065 ppm.

ND = Non-detectable.

Results in parts per million (ppm), unless otherwise indicated.

				во	RII	1 G	L O G	
Project No KEI-P89-0		. <del>- =</del> -		ring a	& Cas	sing D	iameter	Logged By Doug Lee
	oject Name Unocal Wel Leandro, E. 14th					evati	on	Date Drilled 5/24/89
Boring No.	Boring No. MW1				3	Holl Auge:	ow-stem r	Drilling Company EGI
Penetra- tion blows/6"	tion level Sa			(ft)		ati- phy s		Description
10/15/17			5 10 15 20	ples (1)			clay, himoist, himois	gh plasticity, stiff, black, with gravel to ove 4'.  above.
			30				т	OTAL DEPTH 24.5

Page 1 of 1

				во	RII	N G	LOG	
Project N KEI-P89-0				ring (	& Cas	sing D	iameter	Logged By Doug Lee
Project No.			We]	ll Hea	ad El	levati	on	Date Drilled 5/24/89
Boring No MW2	Boring No.				3	Holle Auge	ow-stem	Drilling Company EGI
Penetra- tion blows/6"	n level Samples					ati- phy S	ı	Description
22/24/28 9/11/26			5 10 15 20 25		CH CH		Sandy graslightly Clay, hig moist, b Color chat grayish Silty clay fine sand blocky, ly cements clay clay	nge below 12' to dark
							TO	OTAL DEPTH 24.5'

Page 1 of 1

:/				во	RI	NG LOG	the state of the s
Project No			Вс	ring 9"	& Ca	sing Diameter 2"	Logged By W.W.
Project Nas 15803 E. 1			We	:11 C	over :	Elevation	Date Drilled 3/12/91
Boring No. MW2A	**					Hollow-stem Auger	Drilling Company EGI
Penetration blows/6"	enetration G. W. Dept lows/6" level (fee Samp			str graj USC:		Desc	eription
11/9/8 7/9/13 5/8/15		5		GC CH		Clayey gravel w 5" in diameter brown, traces  Clayey gravel f above, yellowi  Base Clay, trace sil lar gravel to very stiff, ve rootlets.  Clay, high plas very stiff, ve	
	•	<del></del>		СН	AMERICAN ACCESS  AMERIC	Clay, moist, ver ish gray.	ry stiff, light brown-
5/7/8		- 15 - - - - - - - - - - - - - - - - - - -				light brownish  Clay with silt, ed, stiff, trac	very moist to saturat- ce caliche, trace

		<del>-</del>		BORI	NG LOG	
Project No KEI-P89-03			В	oring & Ca	sing Diameter 2"	Logged By W.W.
Project Na 15803 E. 1	me Uno 4th S	cal an L	W	ell Cover	Elevation	Date Drilled 3/12/91
Boring No.				rilling ethod	Hollow-stem Auger	Drilling Company EGI
Penetration G. W. Depth blows/6" level (feet Samp)			=)	strati- graphy USCS	Des	cription
/8				CL/	Clay, with sil	t, as above.
		_			silty clay, tra saturated, st brown to light	ace fine-grained sand, iff, light yellowish colive brown.
3/5/6		— — 25 —				
	Ī					
	-  -  -	30 · 30 ·				
	-	 				
Į.	-  -  -	<del></del>				
		 35 -  			-	
	_  -  -	 				
	-  -  -	<del>-</del> 				
	-	- - 40 -			TOT	AL DEPTH: 25.5'

# BORING LOG

Project No			Bo	rina	& Cas	sing D	iameter	Logged By
KEI-P89-0				9"		2		Doug Lee
Project Na San Leand		We:	ll Hea	ad El	levati	on	Date Drilled 5/24/89	
Boring No.			illing chod	3	Holl Auge	ow-stem r	Drilling Company EGI	
Penetra- tion blows/6"	tion level Sa			(ft)		rati- iphy S		Description
			0				A.C. Pav Silt, sa	ement nd and gravel: fill.
9/14/18			5				Clay, hi moist,	gh plasticity, stiff, black.
12/17/19	<u>-</u>		10		СН		Color cha	ange below 12' to dark brown.
		——————————————————————————————————————	15					
			20		CL		stiff, o	ay, 10% fine sand, cemented, blocky, wet, "hard pan".
		<del>-</del>	25		СН		Silty cla olive by	ay, firm, wet, dark cown.
			30					
	-  -  -							
	-						<b>T</b>	COTAL DEPTH 24.5'

# BORING LOG

Project No KEI-P89-0			Boring 9"	& Cas	sing D		Logged By Doug Lee
Project Na San Leand			Well He	ad E] N/A	Levati	on	Date Drilled 5/24/89
Boring No. MW4	Boring No. MW4				Holld Auger	ow-stem r	Drilling Company EGI
Penetra- tion blows/6"	G. W. level		oth (ft)		cati- ophy cs		Description
9/14/19 10/15/17 25/25/26 12/14/18			10	СН		concrete Gravelly plastic: dark gravelly plastic: dark gravelly clay, hid moist, with below 9 Color chat grayish Color chat grayish Color chat grayish Clay, as Silty cla ticity, cementat "hard pa Sandy cla fine, fi brown. Silty cla very moi blocky, cemented	avel, silt: fill, with e blocks. clay with silt, high ity, firm, moist, very ay. gh plasticity, stiff, with weak cementation ', black. ange at 9' to very dark brown. ange at 11' to dark brown. above.  ay with sand, low plas- hard, wet, strong cion, blocky, white, an'. ay, sand - medium to irm, wet, light olive ay, 10% fine sand, firm, st, light olive brown, blocks moderately

				ВОІ	RIN	I G	rog	
Project No KEI-J89-03		_		ing	& Cas	ing D	iameter	Logged By Doug Lee
Project Na E. 14th, S		Wel	l Hea	ad El	evati	on	Date Drilled 3/6/89	
Boring No. EB-1	Boring No. EB-1			lling hod	J	Holld Auger	ow-stem	Dril@ing Company EGI
Penetra- tion blows/6"	G. W. level		Depth (ft) Samples			ati- phy S	]	Description
4/6/8 4/6/8 3/6/9			5 10 15 20 25		он ОН		gravel leading of the color of	& concrete pavement and base andy gravel, reddish very stiff to hard, gravel to 2" sandy clay, very dark tiff, moist, high plasme silt and sand, black, moist, high plasticity the silt, grayish brown, ary moist
				•			Т	OTAL DEPTH 13.5'

Page 1 of 1

			1	вог	RIN	<b>G</b> ]	. o c	
Project No	D.		Bori 9'	ing &	Cas	ing Di	Logged By Doug Lee	
Project Na E. 14th, S	ame Uno San Lean	cal,	Well		d El	evatio	on	Date Drilled 3/6/89
Boring No.	•		Drilling Method			Hollo Auger	ow-stem	Drilking Company EGI
Penetra- tion blows/6"	G. W. level		oth (inples	ft)	stra graj USC			Description
4/9/8 4/8/9			0 = 5 10 15 20		GC OH		gravel Clayey s brown, Gravelly very st ticity Clay. so	& concrete pavement and base andy gravel, reddish very stiff, moist clay, very dark gray, iff, moist, high plas-  me sand and silt, black, moist, high plasticity
			30			·		TOTAL DEPTH 10.5'

Page 1 of 1

			ь		BORIN	GLOG		
Project KEI-P89		.P6			Diameter Diameter	1.375"	Logged By D.L.	
1			l S/S #6277 San Leandro	ſ	over Elevation N/A	1	Date Drilled 3/18/97	
Boring No.			Drilling Method		Probe	Drilling Company Gregg Drilling		
Pene- tration blows/6"	n level (ppm) (feet) Samples			Stratigraph USCS	у	Description		
N/o			0		A.C. pay	ement over sand a	nd gravel base.	
No Data						el with sand, very ompacted roadbase	dense to hard, dry to slightly moist, brown e).	
				ML	Clayey si mottled.	lt, very stiff, moist	t, dark grayish brown and very dark brown,	
		0.0	10	CL ML	Silty clay,	, trace sand, stiff, i , stiff, moist, dark low 10 feet. t, stiff, moist, olive	gray, with abundant caliche, grades to olive	
		0.0		CL ML EEE		stiff, moist, very o	dark gray, with root holes and caliche.	
ſ	<u>-</u>	-	_15		- Caryey sin		AL DEPTH:15'	

					BORING LO	)G	, , , , , , , , , , , , , , , , , , ,
Project		77.	100000000000000000000000000000000000000	Boring Di		375"	Logged By
KEI-P89				Casing Di		/A	D.L.
_			l S/S #6277 San Leandro		r Elevation N/A		Date Drilled 3/18/97
Boring l EB4	No.			Drilling Method	GeoProbe		<b>Drilling Company</b> Gregg Drilling
Pene- tration blows/6"	G.W. level	O.V.M. (ppm)	(feet) Samples	Stratigraphy USCS	Description **		
			0		A.C. pavement	over sand and gra	avel base.
No Data					asphalt and deb	ris (fill). silt and sand, stiff	e, moist, dark yellowish brown, with
		No Data	5 -	ML	(Very poor reco	very at 4.5 feet) f, moist, dark gray	yish brown.
		0.0	10-	CL		moist, olive gray brown below 10 fi	to dark olive gray, with caliche eet.
	<u> </u>	0.0		ML TOTAL	Clayey silt, firm	, moist, olive bro	very moist, olive brown, locally
ĺ	-				grades to silt est	imated at 20-30%	clay.
		ŀ	15			TOTAL DI	EPTH:14.5°
İ							•
		}					
		-					
			-20				
		-					

						BORING	LOG	
Project		. D.C		В	oring Di	ameter	1.375"	Logged By
KEI-P89					asing Di		N/A	D,L,
1			l S/S #6277 San Leandi	[	Vell Cove	er Elevation N/A		<b>Date Drilled</b> 3/18/97
Boring I	No.				rilling lethod	GeoP	robe	Drilling Company Gregg Drilling
Pene- tration blows/6"	G.W level	O.V.M. (ppm)	Depth (feet) Samples	Strat U	igraphy SCS		-	Description 💆 😽
			0 =			A.C. paven	nent over sand	and gravel base.
						very dark g	rayish brown (:	debris, firm to stiff, very moist, black and fill).
	0.0		ML		(Poor recovery at 4.5 feet)  Sandy silt, trace clay, sand is fine to medium-grained, stiff, moist, dark olive gray.			
				CL		Silty clay, s	tiff, moist, oliv	e brown.
	-	0.0	10	ML		Sandy silt, t		is very fine to fine-grained, stiff, moist,
			15			OUAS DEOMO		'AL DEPTH: 11'

#### ALAMEDA COUNTY

# **HEALTH CARE SERVICES**





DAVID J. KEARS, Agency Director

December 26, 2000

**STID 2422** 

Mr. David De Witt Tosco Marketing Company 2000 Crow canyon Place, Ste. 400 San Ramon, CA 94583 ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkwa, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

RE:

Unocal Service Station #6277, 15803 East 14th Street, San Leandro

Dear Mr. De Witt:

This letter transmits the enclosed underground storage tank (UST) case closure letter in accordance with Chapter 6.75 (Article 4, Section 25299.37[h]) of the California Health and Safety Code. The State Water Resources Control Board (SWRCB) has required since March 1, 1997 that this agency use this case closure letter for all UST leak sites. We are also transmitting to you the enclosed case closure summary. These documents confirm the completion of the investigation and cleanup of the reported release at this site.

#### SITE INVESTIGATION AND CLEANUP SUMMARY

Please be advised that the following conditions exist at the site:

- Up to 510 micrograms per liter (ug/l) Total Petroleum Hydrocarbons as Gasoline (TPH-G), 72 ug/l Benzene, and 390 ug/l MtBE are present in groundwater beneath the site.
- Up to 1100 milligrams per kilogram (mg/kg) TPH-G, 8 mg/kg Benzene, and 1300 mg/kg Oil & Grease are present in soil at depths between 5 and 15' below grade.

If you have any questions, please contact the undersigned at (510) 567-6783.

Sincerely,

Scott/O. Seen/, CHMM

Hazardous Materials Specialist

# Enclosures:

- Case Closure Letter
- Case Closure Summary

cc: Ariu Levi, Chief, Environmental Protection

Matthew Coelho, 18616 Hwy 33 East, Dos Palos, CA 93620-9620 (w/attachment)

# ALAMEDA COUNTY

# **HEALTH CARE SERVICES**





DAVID J. KEARS. Agency Director

December 26, 2000

**STID 2422** 

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

#### REMEDIAL ACTION COMPLETION CERTIFICATION

Mr. David De Witt Tosco Marketing Company. 2000 Crow Canyon Place, Ste. 400 San Ramon, CA 94583

RE:

Unocal Service Station #6277, 15803 E. 14th Street, San Leandro

Dear Mr. De Witt:

This letter confirms the completion of a site investigation and remedial action for the underground storage tanks formerly located at the above-described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tanks are greatly appreciated.

Based on information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, no further action related to the underground tank release is required.

This notice is issued pursuant to a regulation contained in Section 2721(e) of Title 23 of the California Code of Regulations.

Please contact our office if you have any questions regarding this matter.

Sincerely,

Mee Ling Tung

Director, Environmental Health Services

c: Chuck Headlee, RWQCB

Michaell Gudos

Allan Patton, SWRCB (w/attachment)

Matthew Coelho, 18616 Hwy 33 East, Dos Palos, CA 93620-9620 (w/attachment)

SOS/files



505

5TW

ノイタン

PROTECTION

00 JUN 19 AM 9: 00

2000 Crow Canyon Place Suite 400 San Ramon, CA 94583 925.277.2305 fax: 925.277.2361

Environmental Compliance Department

June 15, 2000

Mr. Thomas Peacock
Manager - LOP
Alameda County - Environmental Health Services
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577

Re: No Further Action

Tosco/76 Products Service Station # 6277

15803 East 14<sup>th</sup> Street San Leandro, CA

Dear Mr. Peacock:

As requested in your June 12, 2000 letter, I certify that I have notified the fee title holder of the subject property of the proposed action by Alameda County. I have included a copy of the letter I sent to Matthew and Ellamae Coelho with regards to the proposed "No Further Action".

If you have any additional questions or concerns, please feel free to contact me at 925-277-2384.

Sincerely,

David B. De Witt

Environmental Project Manager





2000 Crow Canyon Place Sulte 400 San Ramon, CA 94583 925.277.2305 fax: 925.277.2361

Environmental Compliance Department

June 15, 2000

Matthew and Ellamae Coelho 18616 Hwy 33 Dos Palos, CA 93620-9620

Re: No Further Action

Tosco/76 Products Service Station # 6277

15803 East 14<sup>th</sup> Street San Leandro, CA

Dear Matthew and Ellamae Coelho:

Alameda County Health Care Services – LOP has determined that Tosco Corporation has completed the necessary environmental work at this site and that a finding of "No Further Action" is being considered. I have attached a copy of this notification for your records. As required by the Health and Safety Code (Ch. 6.7 – section 25297.15), I am notifying you, as the fee title holder, of this proposed action.

If you have questions or concerns on this subject, please feel free to call me at 925-277-2384.

Sincerely,

David B. De Witt

Environmental Project Manager



#### ALAMEDA COUNTY

# **HEALTH CARE SERVICES**

AGENCY



DAVID J. KEARS, Agency Director

June 12, 2000

**STID 2422** 

Mr. David De Witt Tosco Marketing Company 2000 Crow Canyon Place, Ste. 400 San Ramon, CA 94583 ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

RE: Unocal Service Station #6277, 15803 E. 14th Street, San Leandro

INTENT TO MAKE A DETERMINATION THAT NO FURTHER ACTION IS REQUIRED

Dear Mr. De Witt:

This letter is to inform you that Alameda County Environmental Health Department, Local Oversight Program (LOP), intends to make a determination that no further action is required at the above site, as concurrence from the Regional Water Quality Control Board (RWQCB) has been received. Please notify this agency of any input and recommendations you may have on these proposed actions within 20 days of the date of this letter.

In accordance with section 25297.15 of Ch. 6.7 of the Health & Safety Code, you must provide certification to the local agency that <u>all</u> of the current record fee title owners have been informed of the proposed action. Please provide this certification to this office within 20 days of the date of this letter.

If you have any questions about these proposed actions, please contact Scott Seery at (510) 567-6783.

Sincerely,

Thomas Peacock Manager, LOP

cc: Chuck Headlee, RWQCB

Scott Seery, ACDEH LOP



# 00 JUN -9 PM 4: 19 Leaking Underground Fuel Storage Tank Program

#### I. AGENCY INFORMATION

Agency name: Alameda County-EPD

Address: 1131 Harbor Bay Pkwy #250

Date: 04/29/98

City/State/Zip: Alameda, CA 94502 Responsible staff person: Scott Seery Phone: (510) 567-6700 Title: Haz. Materials Spec.

#### II. CASE INFORMATION

Site facility name: Unocal Station #6277

Site facility address: 16803 E.14th Street, San Leandro 94578

RB LUSTIS Case No. N/A Local Case No./LOP Case No.: 2422

URF filing date: 03/16/89 SWEEPS No: N/A

Responsible Parties: Addresses: Phone Numbers:

Tosco Marketing Co. P.O. Box 5155 (925) 277-2384

Attn: David deWitt San Ramon, CA 94583

Mathew & Ella Coelho 18616 Hwy 33 East

Dos Palos, CA 93620-9620

<u>Tank</u>	<u>Size in</u>	<u>Contents:</u>	<u>Closed in-place</u>	Date:
No:	gal.:		or removed?:	
1	10,000	gasoline	removed	03/13/89
2	10,000	11	u	н
3	550	waste oil	O.	11

# III. RELEASE AND SITE CHARACTERIZATION INFORMATION

Cause and type of release: UNK (failed integrity test lead to UST removals)

Site characterization complete? YES

Date approved by oversight agency:

Monitoring Wells installed? YES Number: 7

Proper screened interval? YES

Highest GW depth below ground surface: 5.85' Lowest depth: 11.34' (stabilized)

Flow direction: predominately NW - N

Most sensitive current use: commercial (adjoined by apts.)

Are drinking water wells affected? NO Aquifer name: San Leandro cone

# Page 2 of 7

# Leaking Underground Fuel Storage Tank Program

# III. RELEASE AND SITE CHARACTERIZATION INFORMATION (Continued)

Is surface water affected? NO Nearest affected SW name: NA

Off-site beneficial use impacts (addresses/locations): NONE

Report(s) on file? YES Where is report filed? Alameda County

1131 Harbor Bay Pkwy Alameda CA 94502

Treatment and Disposal of Affected Material:

riçabilelit allu	Dishosal of Vitected materi	a).	
<u>Material</u>	<u>Amount</u>	Action (Treatment	<u>Date</u>
	(include units)	or Disposal w/destination)	
Tank	(2 x 10K; 1x 550 gal)	Disposal – UNK (but presumed	3/89
	•	to have gone to Erickson, Richm	ond,
		CA)	
Piping	Unk	as above	,
Free Product	NA		ı
Soil	162 tons	<u>Disposal</u> – Casmalia LF	4/14/89
		Casmalia, CA	
	1000 yds³	<u>Disposal</u> – Redwood LF	4/4/89 -
		Novato, CA	4/18/89
	218 tons	<u>Disposal</u> – Petroleum Waste	5/18/89
		Buttonwillow, CA	
	1060 yds³	<u>Disposal</u> – Mt. View dump	9/5/89
		Mt. View, CA	9/11/89
	2.4 tons	Disposal – GSX Services	11/1 <b>/</b> 89
		Buttonwillow, CA	
	673 tons	<u>Disposai</u> – GSX Services	4/13/90
		Buttonwillow, CA	4/16/90
Groundwater	19,400 gal	<u>Disposal</u> – H& H Ship Svc.	3/21/89 &
	· –	So. S.F., CA	4/2/90 4/5/90

# Maximum Documented Contaminant Concentrations - - Before and After Cleanup

Contaminant	Soil¹ (į	opm)	Water <sup>2,3</sup> (ppb)		
	<u>Before</u>	After	Before	After	
TPH (Gas)	3500	1100	19,000	510	
TPH (Diesel)	ND	6.2	NA	NA	
Benzene	40	8	230	72	
Toluene	280	43	79	ND	
Xylene	600	230	1300	17	

# Page 3 of 7

# Leaking Underground Fuel Storage Tank Program

#### III. RELEASE AND SITE CHARACTERIZATION INFORMATION (Continued)

#### Maximum Documented Contaminant Concentrations - - Before and After Cleanup

Contaminant	Soil1 (p	pm)	Water <sup>2,3</sup> (ppb)		
	Before	After		Before	After
Ethylbenzene	100	37		ND	ND
MtBE	NA	NA		NA	390
Oil & Grease	7700	1300		NA	NA
Heavy metals	NA	NA		II	II
Other <b>HVOC</b> TCE	0,063	ND	TCE	4.4	ND
			PCE	110	950
			DCA	2.8	ND

Note:

- 1) All "before" soil results compiled from initial sidewall samples collected during March 1989 fuel UST closures, except for O&G, TCE and TPH-D results. O&G and TCE results from the 5' sample collected during advancement of well/boring MW-2 in May 1989. TPH-D result derived from a sample collected from the base of the waste oil UST pit following tank removal. All "after" soil results from sidewall samples collected after the 1990 over-excavation of the general area of former well MW-2, except for O&G. O&G result from the 5' soil sample collected from well/boring MW-2A in 1991.
- 2) "Before" water results from sample collected from the fuel UST excavation during 1989 closures, except as otherwise indicated. All "after" water results reflect samples collected from well MW-1 in November 1996, except as otherwise indicated.
- 3) "Before" HVOC water results from initial sample collected from well MW-2 in June 1989. "After" water results from sample collected from well MW-3 in January 1996.

#### Comments (Depth of Remediation, etc.):

During March 1989 three (3) single wall steel USTs were removed from this site. Two 10,000 gasoline and one 550 gallon waste oil USTs were closed during this effort. The original USTs were replaced by double-wall tanks emplaced elsewhere at the site. Tank replacement appears to have been prompted by a series of failed integrity tests in the years and months preceding this effort.

Ground water was encountered in the fuel tank pit at a depth of ~11 feet BG. Consequently, sidewall samples, six in all, were initially collected from the excavation a foot above stabilized water level. A single soil sample was collected from the base of the shallower waste oil tank pit. In addition, soil samples were also collected from the product piping trenches.

Initial subjective evidence prompted the contractor to expand the fuel tank excavation laterally in two rounds, at which point additional sidewall samples were collected. This expanded excavation encroached on and engulfed the former waste oil UST location as well. Following the initial over-excavation effort, a reported ~5000 gallons of water was pumped from the excavation, and ~14,500 gallons during the second. A water sample was collected from ground water that collected in the expanded tank pit.

## Page 4 of 7

# Leaking Underground Fuel Storage Tank Program

Initial soil samples from the fuel UST pit revealed up to 3500 ppm TPH-G and 40 ppm benzene, among other detected fuel compounds. Over-excavation samples demonstrated a marked reduction in contaminant concentrations, with a TPH-G high of 100 ppm and benzene high of 3.1 ppm. Although the initial waste oil UST pit sample Identified the presence of TOG (280 ppm), no 8240 compounds were identified above laboratory detection limits. The water sample, however, revealed up to 19,000 ug/l TPH-G and 230 ug/l benzene, among other detected fuel components.

Significant soil was removed from the enlarged UST excavation and stockpiled on-site during the 1989 (and subsequent 1990) activities. All soil was eventually disposed of at various California waste facilities between April 1989 and April 1990. (See: Section III. Release and Site Characterization Information)

#### IV. CLOSURE

Regional Board Basin Plan?
Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan?
Does corrective action protect public health for current land use? YES Site management requirements; NA
Should corrective action be reviewed if land use changes? YES
Monitoring wells Decommissioned: YES (1)
Number Decommissioned: 1 Number Retained: 6 (pending case closure)
List enforcement actions taken: NONE
List enforcement actions rescinded: NONE
,
V. LOCAL AGENCY REPRESENTATIVE DATA
Name: Scott Seery Title: Haz Mat Specialist Signature: Date: 4-2/-00
Reviewed by Name: Tom Peacook Signature:  Name: Eva Chu Signature:  Date:  Title: Supervising Haz Mat Specialist  Date:  Title: Haz Mat Specialist  Date:  4 20/00

Does completed corrective action protect existing beneficial uses per the

#### Page 5 of 7

## **Leaking Underground Fuel Storage Tank Program**

#### VI. RWQCB NOTIFICATION

4-21-00 Date Submitted to RB:

RWQCB Staff Name: Chuck Headlee

RB Response: Concur Cluck Headlel Title: Eng. Assoc. Date: 4/28/00

# VII. ADDITIONAL COMMENTS, DATA, ETC.

In preparation for the 1989 tank replacement project, exploratory borings were advanced in the area of the site chosen for the new USTs. Borings EB-1 and -2 were advanced up to 13.5' BG. Ground water was encountered between 11 and 12' BG. Soil samples collected at the 5 and 10' depths revealed some degree of impact by fuel compounds, most evident in the 10' samples, a depth consistent with that of ground water at the site.

Following UST closures, four (4) monitoring wells were installed at the site during May 1989. Total well depths ranged from 24.5 to 25' BG, with 19.5' well screens. Encountered sediments were primarily fine-grained to depths explored. Ground water stabilized between approximately 10 and 11' BG.

Elevated concentrations TOG (7700 ppm), benzene (13 ppm), as well as detectable concentrations of TCE (0.063 ppm) and other fuel components, were identified in the 5' soil sample collected from well boring MW-2.

Detectable fuel components were also identified in shallow soil samples collected from the other well borings. but were present at unremarkable concentrations.

Initial water samples identified detectable TPH-G in samples collected from each well; all BTEX components were "ND". However, detectable concentrations of PCE (110 ug/l), 1,2-DCA (2.8 ug/l), and TCE (4.4 ug/l) were noted in water sampled from MW-2.

As a consequence of soil contamination noted during advancement of well boring MW-2, this well was eventually destroyed and the area around it excavated in early 1990 to a depth of approximately 12' BG. Soil samples were collected from the sidewalls of the resultant excavation. Up to 1100 ppm TPH-G, 8 ppm benzene, and 210 ppm TOG, among other constituents, were identified in these samples, collected at the 10.5' depth. HVOC compounds were "ND".

Well MW-2 was eventually replaced by well MW-2A in a location 30' northwest of its original location. Up to 1300 ppm TOG was identified in the 5' sample collected during boring advancement.

Due to the regular occurrence of PCE, TCE and 1,2-DCA in sampled ground water, a review of records documenting historic site activities was performed in 1993. Reported site history indicates the site was first developed as a gas station from an empty lot in 1969. No likely on-site source of the HVOC impact was identified. The potential for an off-site HVOC source is further supported by the fact that the highest HVOC concentrations have been found in samples collected from wells MW-3 and -4, located on the upgradient side of the subject site, close to property margins. Hence, HVOCs detected in these wells are likely coming from a source (e.g., leaching sanitary sewer lines, etc.) upgradient of the site.

#### Page 6 of 7

# Leaking Underground Fuel Storage Tank Program

#### VII. ADDITIONAL COMMENTS, DATA, ETC. (Continued)

Following several quarters of ground water and sampling, two additional wells (MW-5 and -6) were installed in the adjoining apartment complex to assess potential off-site impacts from the UST release at this site. Some impact, albeit minor, was identified.

Well sampling continued through November 1996. Groundwater flow has predominantly ranged from SW to N during the course of the investigation.

Water sampled from well MW-1 continued to show the highest concentrations of fuel hydrocarbons throughout the duration of this investigation. As well MW-1 is the most downgradient of the wells at the site, an off-site study was conducted in March 1997 to assess any impacts in the downgradient direction. Three Geoprobe boreholes (EB-3, -4, and -5) were advanced through E. 14th Street in a northerly transect from the site. No detectable target compounds were identified in either soil or ground water samples.

This case appears be a "Low Risk Groundwater Case", as described in the January 5, 1996 San Francisco Bay Regional Water Quality Control memorandum entitled "Regional Board Supplemental Instructions to State water Board December 8, 1995, Interim Guidance on Required Cleanup at Low-Risk Fuel Sites," as follows:

1) The leak has been stopped and ongoing sources, including free product, have been removed or remediated.

The subject tanks were removed in 1989. Free product has not been known to occur at the site.

2) The site has been adequately characterized.

A 6-well network of wells was installed, monitored, and sampled over the course of several years. Additional sampling points were installed downgradient of the site. These points have allowed an adequate confirmation of underlying geology, groundwater flow, and contaminant extent.

3) The dissolved hydrocarbon plume is not migrating.

The plume appears stable. Hydrocarbon concentrations have attenuated over time, and appear limited in extent.

4) No water wells, deeper drinking water aquifers, surface water, or other sensitive receptors are likely to be impacted.

There are no known municipal or residential water wells or surface water bodies within 750' downgradient of the subject site that would be impacted by shallow groundwater from this site.

#### Page 7 of 7

# Leaking Underground Fuel Storage Tank Program


#### 5) The site presents no significant risk to human health.

Comparison of ASTM E 1739-95 *Risk Based Screening Levels (RBSL)* with site-specific concentration and occurrence of risk-driving target compounds (e.g., benzene) in groundwater demonstrate that RBSL values are not exceeded for plausible exposure pathways at the 1E-05 risk level for a commercial/industrial site. Residual benzene soil concentrations (based on 1990 soil data) exceed RBSL values for the soil-vapor-intrusion-to-buildings exposure pathway at the 1E-04 risk level. However, default criteria used to calculate the published RBSLs use exceedingly conservative input parameters (e.g., sandy soil texture). Site-specific geology (clay) and asphalt cap are much less conducive to vertical vapor transport to potential receptor locations at the site.

# 6) The site presents no significant risk to the environment.

No environmental receptors are known or expected to be proximal to the site.






Base modified from 7.5 minute U.S.G.S. Hayward and San Leandro Quadrangles (both photorevised 1980) O 2000 4000
Approx. scale feet



UNOCAL SERVICE STATION #6277 15803 E. 14TH STREET SAN LEANDRO, CALIFORNIA


LOCATION MAP





# KAPREALIAN ENGINEERING, INC.

Consulting Engineers
P. Q. BOX 913
BENICIA, CA 94510
(415) 676 - 9100 (707) 746 - 6915



SITE PLAN Figure 1


Unocal Service Station #6277 15803 East 14th Street San Leandro, California



# KAPREALIAN ENGINEERING, INC.

# Consulting Engineers

P.O. BOX 996 • BENICIA, CA 94510 (707) 746-6915 • (707) 746-6916 • FAX: (707) 746-5581



San Leandro, California

**Table /A**Summary of Laboratory Analyses
Water

Well#	Date	TPH as Gasoline	Benzene	Toluene	Ethyl- Bertzene	Xylones	MTBE
MW1	11/25/96	510♦	72	ND	ND	17	390 🕡
	7/1/96	ND	ND	ND	ND	ND	230
	4/8/96	2,100	43	27	7.4	21	480
	1/10/96	220	35	ND	2.0	7.6	†
	7/14/95	410	77	ND	7.4	30	
	4/4/95	410♦	19	ND	ND	ND	
	1/5/95	780	30	ND	ND	9.1	
	10/6/94	970	19	ND	ND	13	,
	7/7/94	2,100 ♦ ♦	250	ND	57	200	
	4/4/94	1,100	15	ND	ND	7.4	
	1/6/94	260	21	ND	2.5	14	
	10/6/93	1,200♦	36	ND	ND	23	
	7/1/93	510	100	0.79	5.7	52	
	4/2/93	690	94	0.73	5.3	39	
	1/29/93	740 ♦ ♦	69	ND	3.8	43	
	10/20/92	720	110	1.4	18	110	
	7/20/92	630	100	2.8	6.3	52	
	4/23/92	530	100	7.9	4.6	60	
	1/13/92	450	240	4.6	8.6	73	
	9/10/91	280	38	3.1	4.1	22	
	6/10/91	310	1.5	ND	ND	0.31	
	3/15/91	110	21	ND	ND	8.4	
	12/14/90	450	150	6.8	0.28	49	
	9/19/90	140	ND	ND	ND	3,5	
	6/25/90	310	10	0.89	0.37	2.1	
	3/29/90	320	12	1.6	0.31	3.5	
	12/12/89	340	100	13	3.4	44	
	9/13/89	550	32	17	3.4	52	
	6/6/89	590	ND	ND	ND	ND	
/W2A	11/25/96	86♦	0.82	ND	ND	ИD	ND
	7/1/96	170	2.4	ND	0.65	2.0	ND
	4/8/96	ND	ND	ND	ND	ND	ND
	1/10/96	89	1.2	ND	ND	0.58	
	7/14/95	60	3.0	ND	1.3	2.4	
	4/4/95	67♦	1.0	ND	ND	ND	
	1/5/95	140 ♦	1.4	ND	ND	ND	
	10/6/94	71	6.4	ND	2.1	2.4	
	7/7/94	90	5.2	ND	1.5	2.2	
	4/4/94	80	8.0	ND ND	1.4	1.5	
	1/6/94	110	2.6	ND	1.6	1.7	
	10/6/93	110+	12	ND	7.4	1.4	
	7/1/93	74+	0.75	ND	ND	ND	**
	4/2/93	120	7.2	ND	5.8	1.2	

**Table**Summary of Laboratory Analyses
Water

Well #	Dale	TPH as Gasoline	Benzene	Toluene	Ethyl- Benzene	Xylenes	MTBE
MW2A (Cont)	10/20/92	96	2.8	ND	1.8	1.6	
, ,	7/20/92	99	8.6	ND	2.4	0.95	
	4/23/92	190	15	ND	15	2.0	
	1/13/92	160	11	2.0	10	5,9	
	9/10/91	180	8.7	0.93	15	13	
	6/10/91	54	1.2	ND	ND	0.69	
	3/15/91	160	2.5	ND	ND	51	
∕IW2	12/12/89	660	220	6.6	13	36	
	9/13/89	170	2.0	0.38	ND	9.5	
	6/6/89	77	ND	ND	ND	ND	-+
MW3	11/25/96	120♦	ND	ND	ND	ND	ND
	7/1/96	ND	ND	ND	ND	ND	ND
	4/8/96	ND	ND	ND	ND	ND	ND
	1/10/96	100 ◆	ND	ND	ND	ND	
	7/14/95	130♦	ND	ND	1.3	4.2	
	4/4/95	100 ♦	0.62	ND	ND	ND	
	1/5/95	140◆	ND	ND	ND	ND	
	10/6/94	93 ♦	ND	ND	ND	ND	
	7/7/94	190 ♦	ND	ND	ND	ND	e-
	4/4/94	170 ♦	ND	ND	ND	ND	
	1/6/94	140 ◆	ND	ND	ND	ND	
	10/6/93	140 ♦	ND	ND	ND	ND	
	7/1/93	120 ♦	ND	ND	ND	ND	
	4/2/93	130 ♦	ND	ND	ND	ND	
	1/29/93	130♦	0.84	ND	ND	ND	~-
	10/20/92	180♦	ND	ND	ND	ND	
	7/20/92	120◆	ND	ND	ND	ND	
	4/23/92	150♦	1.6	ND	ND	ND	
	1/13/92	120◆	ND	ND	ND	ND	
	9/10/91	170	ND	ND	ND	ND	
	6/10/91	160	0.65	ND	ND	ND	
	3/15/9 <b>1</b>	150	ND	ND	ND	0.45	
	12/14/90	150	ND	ND	ND	ND	
	9/19/90	74	0.74	ND	ND	ND	_==
	6/25/90	190	1.5	0,68	ND ·	5.3	
	3/29/90	85	ND	ND	ND	ND	
	12/12/89	120	6.7	0.64	0.46	1.5	
	9/13/89	76	ND	ND	ND	ND	
	6/6/89	32	ND	ND	ND	ND	

**Table /A**Summary of Laboratory Analyses
Water

	184.222.233.2	re unice re-	<del></del>				
Vell#	Date	TPH as Gasoline	Benzene	Toluene	Ethyl Benzene	Xylenes	MTBE
#337.4	11/05/07	100.	) III)	) III)		)II)	NID
AW4	11/25/96 7/1/96	120 <b>♦</b> ND	ND ND	ND ND	ND ND .	ND ND	ND ND
	4/8/96	ND	ND ND	ND	ND	ND	ND ND
		100♦	ND	ND ND	ND ND	1.8	
	1/10/96		ND	ND	0.97	0.52	
	7/14/95	89♦		ND ND	ND	0.52 ND	~~
	4/4/95	82 ♦	ND		ND ND	ND ND	
	1/5/95	150 ♦	ND	ND			-w
	10/6/94	78♦	ND	ND	ND	ND	
	7/7/94	150♦	ND	ND	ND	ND	
	4/4/94	120	0.76	0.76	ND	0.98	
	1/6/94	100◆	ND	ND	ND	ND	
	10/6/93	130 ♦	ND	ND	ND	ND	
	7/1/93	91 ♦	ND	ND	ND	ND	
	4/2/93	110 ♦	ИD	ND	ND	ND	H#
	1/29/93	130♦	0.95	ND	ND	ND	
	10/20/92	110+	ND	ND	ND	ND	
	7/20/92	80♦	ND	ND	ND	ND	
	4/23/92	120♦	ND	ND	ND	ND	
	1/13/92	58♦	ND	ND	ND	ND	
	9/10/91	56	ND	ND	ND	ND	
	6/10/91	64	ND	ND	ND	ND	
	3/15/91	. 53	ND	ND	ND	ND	
	12/14/90	54	ND	ND	ND	ND	
	9/19/90	61	ND	ND	ND	ND	
	6/25/90	66	ND	ND	ND	ND	
	3/29/90	120	0.39	ND	ND	ND	
	12/12/89	97	4.6	ND	ND	ND	
	9/13/89	77	ND	ND	ND	ND	
	6/6/89	37	ND	ND	ND	ND	
W5	11/25/96	120♦	ND	ND	ND	ND	ND
	7/1/96	ND	ND	ND	ND	ND	ND
	4/8/96	ND	'nD	ND	ND	ND	ND
	1/10/96	50 ♦	ND	ND	ND	ND	
	7/14/95	ND	ND	0.91	ND	1.1	
•	4/4/95	ND	ND	ND	ND .	ND	
	1/5/95	ND	ND	ND	ND	ND	
	10/6/94	ND	ND	ND	ND	ND	
	7/7/94	72 ♦	ND	ND	ND	ND	
	4/4/94	65♦	ND	ND	ND	ND	
	1/6/94	62 <b>♦</b>	ND	ND	ND	ND	
	10/6/93	60♦	ND	ND	ND	ND	
	7/1/93	54♦	ND	ND	ND	ND	
	011173	<i>J</i> 1 ₹	1 1 L	~ +##			

MPDS-UN6277-11 December 13, 1996 Page 6 of 8

Well#	Date	TPH as Gasoline	Bengene	Toluenc	Ethyl- Benzene	Xylenes	M3'BE
MW6	11/25/96	120♦	ND	ND	ND	ND	ND
	7/1/96	ND	ND	ND	ND	ND	ND
	4/8/96	ND	ND	ND	ND	ND	ND
	1/10/96	53♦	ND	ND	ND	ND	
	7/14/95	ND	ND	ND	ND	ND.	
	4/4/95	ND	ND	ND	ND	ND	
	1/5/95	ND	ND	ND	ND	ND	
	10/6/94	ND '	ND	ND	ND	ND	
	7/7/94	ND	ND	ND	ND	ND	
	4/4/94	57♦	ND	ND	ND	ND	
	1/6/94	53♦	ND	ND	ND	ND	
	10/6/93	ND	ND	ND	ND	ND	
	7/1/93	ND	ND	ND	ND	ND	
	4/2/93	ND	ND	ND	ND	ND	,

- † Sequoia Analytical Laboratory has identified the presence of MTBE at a level above or equal to the taste and odor threshold of  $40 \mu g/L$  in the sample collected from this well.
- Sequoia Analytical Laboratory reported that the hydrocarbons detected did not appear to be gasoline.
- Sequoia Analytical Laboratory reported that the hydrocarbons detected appeared to be a gasoline and non-gasoline mixture.

MTBE = methyl tert butyl ether.

ND = Non-detectable.

Results are in micrograms per liter (µg/L), unless otherwise indicated.

- Note: The detection limit for results reported as ND by Sequoia Analytical Laboratory is equal to the stated detection limit times the dilution factor indicated on the laboratory analytical sheets.
  - Prior to August 1, 1995, the total purgeable petroleum hydrocarbon (TPH as gasoline) quantification range used by Sequoia Analytical Laboratory was C4 C12. Since August 1, 1995, the quantification range used by Sequoia Analytical Laboratory is C6 C12.
  - Laboratory analyses data prior to January 6, 1994, were provided by Kaprealian Engineering, Inc.

**Table /B**Summary of Laboratory Analyses
Water

		TPHas	Tetra-	Trichloro	1.2- Dichloro	Cis-1,2- dichloro-	Total Oil & Grease
Well#	Date	Diesel	chlordethene	ethene	ethane	ethene	(mg/L)
MW1	4/04/94*		390	38	ND	17	=-
272 11 1	4/2/93	ND					
	1/29/93	ND	300	ND	ND	ND	
	10/20/92	ND	230	22	ND	16	
	7/20/92	62♦	200	7.4	ND	ND	<u>-</u>
MW2	4/2/93	ND		_			
	12/12/89	1,700	30	9.0	ND	ND	1.2
	9/13/89	ND	18	6.1	4.2	1.2	ND
	6/6/89	ND	110	4.4	2.8	ND	ND
MW2A	9/10/93	65					
	1/29/93	ND	140	10	ND	ND	
	10/20/92	ND	64	11	ND	ND	
	7/20/92	ИD	35	7.2	ND	4.8	ND
	4/23/92	ND	17	5.6	ND	1.9	ND
	1/13/92**	ND	33	ND	ND	2.1	ND
	6/10/91	100	150	10	ND	ND	ND
	3/15/91	ND	67	8.2	ND	2.6	ND
MW3	1/10/96		950	ND	ND	ND	
	1/5/95		1,100	18	ND	6.2	n=
	1/6/94		960	ND	ND	ND	
	4/2/93	ND					
	1/29/93	ND	980	ND	ND	ND	
	10/20/92	ND	1,100	20	ND	ND	n=
	7/20/92	ND	1,400	25	ND	ND	
MW4	1/29/93	ND	950	ND	ND	ND	
	7/20/92	ND	440	11	ND	ND	<del></del> -
	4/2/93	ND			<del></del>		
	10/20/92	ND	360	17 ′	ND	ND	<b>~</b> -
MW5	4/2/93	ND	190	ND	ND	ND	
MW6	4/2/93	ND	71	ND	ND	ND	

### Table (8 Summary of Laboratory Analyses Water

- \* All EPA method 8240 constituents were non-detectable, except for concentrations of benzene at 29 µg/L, ethylbenzene at 3.4 µg/L, total xylenes at 19 µg/L, and trans-1,2-dichloroethene at 2.4 µg/L.
- \*\* 1,1,2-trichloroethane was detected at a concentration of 9.9 μg/L.
- Sequoia Analytical Laboratory reported that the hydrocarbons detected did not appear be diesel.

ND = Non-detectable.

-- Indicates analysis was not performed.

mg/L = milligrams per liter.

Results are in micrograms per liter (µg/L), unless otherwise indicated.

Note:

All EPA method 8010 constituents were non-detectable in all of the ground water samples, except as indicated.

Laboratory analyses data prior to January 6, 1994, were provided by Kaprealian Engineering, Inc.

KEI-P89-0301.R1 March 13, 1989

TABLE 1 C

SUMMARY OF LABORATORY ANALYSES
SOIL

(Results in ppm) (Collected on March 6, 1989)

Sample <u>Number</u>	TPH as <u>Gasoline</u>	Benzene	<u>Toluene</u>	Xylenes	<u>Ethylbenzene</u>
EB1(5)	2.1	ND	0.11	ND	0.14
EB1(10)	200	2.3	7.7	5.7	33
EB2(5)	ND	ND	ND	ND	ND
EB2(10)	620	2.2	20	13	78

ND = Non-detected

KEI-P89-0301.R12 April 11, 1997

TABLE 1/.D
SUMMARY OF LABORATORY ANALYSES
SOIL

<u>Date</u>	Sample Number	TPH as <u>Gasoline</u>	Benzene	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylenes	MTBE
3/18/97	EB3 (5) EB3 (10) EB3 (14.5)	ND ND ND	ND ND	ND ND ND	ND ND	ND ND ND	ND ND ND
	EB4 (4.5) EB4 (10) EB4 (13)	ND ND ND	ND ND	ND ND	ND ND	ND ND ND	ND ND ND
	EB5(5) EB5(10)	ND ND	ND ND	ND . ND	ND ND	ND ND	ND ND

NOTE: The soil samples were collected at the depths below grade indicated in the ( ) of the respective sample number.

ND = Non-detectable.

Results are in milligrams per kilogram (mg/kg), unless otherwise indicated.

KEI-P89-0301.R12 April 11, 1997

TABLE 1 &
SUMMARY OF LABORATORY ANALYSES
WATER

Date	Sample <u>Number</u>	TPH as <u>Gasoline</u>	Benzene	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylenes	<u>mtbe</u>
3/18/97	EB3	ND	ND	ND	ИД	ND	ND
	EB4	ND	ND	ND	ND	ND	ND
	EB5	ND	ND	ND	ND	ND	ND

NOTE: Water samples were collected during drilling. The results of the analyses may not be representative of formation water, and should be used for comparative informational purposes only.

Results are in micrograms per liter ( $\mu g/L$ ), unless otherwise indicated.

KEI-P89-0301.R3 March 27, 1989

#### TABLE 2

SUMMARY OF LABORATORY ANALYSES \*\*
WATER
(Results in ppb)

(Samples collected on March 19, 1989)

Sample #	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	<u>Xylenes</u>	Ethylbenzene
W-1	19,000	230	79	1,300	ND
Detection Limits	50	0.5	0.5	0.5	0.5

ND = Non-detectable

\* sample collected from UST pit during 1989 closures

KEI-P89-0301.R8 April 16, 1991

#### TABLE 3

# SUMMARY OF LABORATORY ANALYSES SOIL

1000

· 50-4"

(Collected on March 12, 1991)

Sample Depth TPH as TPH as Ethyl-Number (feet) Diesel Gasoline Benzene Toluene Xylenes benzene TOG MW2A(5)\* 5 4.8 ND ND ND ND ИD 1,300 MW2A(10) \* 10 2.4 0.12 0.17 0.14 260 10 1.6 0.0080 14.5 ИD ND ND 0.036 ИD 57 MW2A(14.5)\* Detection Limits 1.0 1.0 0.0050 0.0050 0.0050 0.0050 30

ND = Non-detectable.

Results in parts per million (ppm), unless otherwise indicated.

<sup>\*</sup> All EPA method 8010 constituents were non-detectable, except for 0.110 ppm of 1,2-dichlorobenzene, and 0.120 ppm of tetrachloroethene detected in sample MW2A(10).

KEI-P89-0301.R8 April 16, 1991

TABLE 4
SUMMARY OF LABORATORY ANALYSES
SOIL

(Samples collected on April 3, 1990)

Sample	Depth (feet)	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	Toluene	Xylenes	Ethyl- <u>benzene</u>
sw8A*	10.5	62	260	1.4	8.0	40	7.0
*Aewa	10.5	ND	ND	0.017	0.041	0.033	0.0092
sw10A*	10.5	ИD	140	0.085	0.12	5.0	1.4
SW11A**	10.5	280	1,100	8.0	43	230	37
Detection Limits	on	1.0	1.0	0.0050	0.0050	0.0050	0.0050

<sup>\*</sup> TOG and all EPA method 8010 constituents were non-detectable for these samples.

ND = Non-detectable.

Results in parts per million (ppm), unless otherwise indicated.

<sup>\*\*</sup> TOG showed 210 ppm, while all EPA method 8010 constituents were non-detectable.

KEI-P89-0301.R8 , April 16, 1991

TABLE 5
SUMMARY OF LABORATORY ANALYSES
SOIL

Sample	Depth	TPH as				
<u>Number</u>	(feet)	<u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	<u>Xylenes</u>	<u>Ethylbenzene</u>
		(001)	ra bataa	Varob 6	1000)	
		(001)	lected on	March 6,	1989)	Age va.
EB1(5)	5	2.1	ND	0.11	ND	0.14
EB1 (10)	10	200	2.3	7.7	5.7	33
EB2 (5)	5	ND	ND	ND	ND	ND
EB2 (10)	10	620	2.2	20	13	78
, ,						
		(Collected	l on March	13, 14	£ 17, 1989	9)
SW1	10	3,500	22	280	600	100
SW1(2)	10	100	1.3	6.6	16	2.9
SW2	10	390	40	4.3	71	10
SW3 (15)	10	60	1.6	2.9	7.8	1.5
SW4/5(6)	10	24	2.6	1.7	2.7	0.56
SW6(12)	10	150	3.1	6.2	5.6	3.6
SW7(14)*	10	ND	0.3	ND	ND	ND
P1	3	2.3	ND	0.15	ND	ND
P2	3	1.5	ND	0.31	ND	ND
P3	3	1.1	ND	0.1	ND	ND
P4	3	5.6	ND	0.15	0.39	ND
P5	3	6.8	0.15	0.58	0.55	0.12
P6	3.5	5.5	0.06	0.18	0.15	ND
W01**	10	15	ND	ND	0.21	0.88
		10-31				
		(COT.	lected on	may 24,	1989)	•
MW1(5)	5	2.3	0.08	ND	0.62	ND
MW1(10)	10	290	1.0	11	48	8.8
MW2(5)**	* 5	230	13	1.7	3.2	1.5
MW2(10)+		31	1.2	1.0	5.5	1.1
Mag (E)	-	2 2	0.20	0.1	٥. ٦	ND.
MW3 (5)	5	3.2	0.29	0.1	0.7	ND
MW3(10)	10	4.6	ND	ND	0.44	0.3
MW4 (5)	5	3.1	ND	0.11	ND	ND
MW4(10)	10	ND	ND	ND	ИD	ND

KEI-P89-0301.R8 April 16, 1991

#### TABLE 5 (Continued)

# SUMMARY OF LABORATORY ANALYSES SOIL

- \* TPH as diesel was 6.2 ppm; TOG was at 41 ppm; all 8240 constituents are non-detectable, except as noted above.
- \*\* TPH as diesel was non-detectable; TOG was at 280 ppm; all 8240 constituents are non-detectable, except as noted above.
- \*\*\* TPH as diesel was non-detectable, TOG was 7,700 ppm, and trichloroethene at 0.063 ppm.
- + TPH as diesel was non-detectable, TOG was 38 ppm, and trichloroethene at 0.065 ppm.

ND = Non-detectable.

Results in parts per million (ppm), unless otherwise indicated.

			-	вок	ı N	G I	C O G	
Project No KEI-P89-03			Boring & Casing Diameter					Logged By Doug Lee
Project Na San Leandr	Project Name Unocal San Leandro, E. 14th				d Eld N/A	evatio	on	Date Drilled 5/24/89
Boring No.	Boring No. MW1			lling hod	f 	Hollo Auge	ow-stem	Drilling Company EGI
Penetra- tion blows/6"	G. W. level		oth (		Stra graj USC	5		Description
10/15/17			5 10 15 20 25		CH		Clay, hi moist, 3/4" ab Clay, as Color ch grayish Silty cl plastic fine, f	gh plasticity, stiff, black, with gravel to ove 4'.  above.  ange at 12' to dark
								TOTAL DEPTH 24.5

Page 1 of 1

			В	0 R	RIN	<b>G</b> 1	LOG	
Project No XEI-P89-03			Boring & Casing Diameter					Logged By Doug Lee
Project Na San Leandr			Well		d El N/A	evatio	on	Date Drilled 5/24/89
Boring No. MW2			Dril Meth		J	Holla Auger	ow-stem	Drilling Company EGI
Penetra- tion blows/6"	G. W. level		oth (f	t)		ati- phy s		Description
22/24/28 9/11/26	<b>▼</b>		5 10 15 20 25		CH CH		Sandy graphilical solutions of the sandy graphilical solutions of the sandy solutions of th	ange below 12' to dark brown.  lay, low plasticity, 10% and, hard, cemented, blocks are very strongented, wet, white.  lay, high plasticity, yet, dark olive brown.
			<u>.                                    </u>				- Adam	TOTAL DEPTH 24.5'

Page 1 of 1

.f.——				во	RI	NG LOG	
Project No			В	oring 9"	& Ca	sing Diameter 2"	Logged By W.W.
Project Nau 15803 E. 14			W	ell C	over	Elevation	Date Drilled 3/12/91
Boring No. MW2A				rilli ethod		Hollow-stem Auger	Drilling Company EGI
Penetration blows/6"	G. W. level	Depti (feet Samp)	=)	gra	ati- phy s	Desc	eription
7/9/13		5 - 10 -		GC		Clayey gravel w 5" in diameter brown, traces  Clayey gravel f above, yellowi  Base Clay, trace sil lar gravel to very stiff, verotlets.	of Fill  t and sand, trace angu- 1/2" diameter, moist, ery dark gray, trace  sticity, porous, moist, ery dark gray.
5/8/15				CL/ CH	THE STATE OF THE S	Clay, moist, ve ish gray.	ry stiff, light brown-
5/7/8		15				light brownish  Clay with silt, ed, stiff, tra	very moist to saturat- ce caliche, trace
5/7/		 20 ·	$\prod$			gray.	and, light brownish

		<u> </u>		во	RII	NG LOG					
Project No.	-	Вс	ring 9"	& Cas	sing Diameter	Logged By W.W.					
Project Nam 15803 E. 14		We	ell Co	over 1	Elevation	Date Drilled 3/12/91					
Boring No.	_		Drilling Method			Hollow-stem Auger	Drilling Company EGI				
Penetration blows/6"	G. W. level	Depti (feet Samp)	t)	gra		Description					
/8			CT/			silty clay, tr saturated, st	Clay, with silt, as above.  Silty clay, trace fine-grained sand, saturated, stiff, light yellowish				
3/5/6		30				brown to ligh	t olive brown.				
		_ 40				то	TAL DEPTH: 25.5				

### BORING LOG

Project No KEI-P89-03		Bori 9"		Cas	ing Di	Logged By Doug Lee	
Project Na San Leand		Well		d El N/A	evatio	n	Date Drilled 5/24/89
Boring No.	•	Dril Meth	ling od	i	Hollo Auge	ow-stem	Drilling Company EGI
Penetra- tion blows/6"	oth (1 nples	t)	str gra USC		Description		
9/14/18	<u></u>	5 10 15 20 25		CH		Color ch grayish Silty cl stiff, white, Silty cl olive b	and and gravel: fill.  gh plasticity, stiff, black.  ange below 12' to dark brown.  ay, 10% fine sand, cemented, blocky, wet, "hard pan".  ay, firm, wet, dark

#### BORING LOG Project No. Boring & Casing Diameter Logged By KEI-P89-0301 Doug Lee Date Drilled Project Name Unocal Well Head Elevation San Leandro, E. 14th N/A 5/24/89 Drilling Hollow-stem Boring No. Drilling Company MW4 Method Auger EGI G. W. Penetra-Depth (ft) Strati-Description tion level Samples graphy "3\awold USCS A.C. Pavement Sand, gravel, silt: fill, with concrete blocks. Gravelly clay with silt, high 9/14/19 plasticity, firm, moist, very dark gray. Clay, high plasticity, stiff, CH moist, with weak cementation below 9', black. 10/15/17 10 Color change at 9' to very dark gravish brown. Color change at 11' to dark grayish brown. 15 Clay, as above. Silty clay with sand, low plas-CLticity, hard, wet, strong 25/25/26 20 cementation, blocky, white, "hard pan". Sandy clay, sand - medium to CH fine, firm, wet, light olive brown. Silty clay, 10% fine sand, firm, 12/14/18 25

30

TOTAL DEPTH 25 \*

very moist, light olive brown,

blocky, blocks moderately

cemented.

				ВОІ	RIN	I G	LOG	
Project No KEI-J89-03	Bor 9		cas	ing D	iameter	Logged By Doug Lee		
	Project Name Unocal, E. 14th, San Leandro					evati	on	Date Drilled 3/6/89
Boring No. EB-1	•		Dri Met	lling hod	j	Hollo Auger	ow-stem	Drilling Company EGI
Penetra- tion blows/6"	G. W. level		oth (			ati- phy S		Description
4/6/8 4/6/8 3/6/9	<b>—</b>		5 10 15 20 25		GC ОН СН		gravel Clayey some brown, moist, Gravelly gray, sticity Clay, some stiff, 1	& concrete pavement and base andy gravel, reddish very stiff to hard, gravel to 2" sandy clay, very dark tiff, moist, high plasme silt and sand, black, moist, high plasticity th silt, grayish brown, ery moist
							<u></u>	TOTAL DEPTH 13.5'

Page 1 of 1

BORING LOG									
Project No KEI-		ing (	& Cas	ing D	iameter	Logged By Doug Lee			
Project No. 14th, S			Wel	l Hea	ad·El N/A	evatio	on	Date Drilled 3/6/89	
Boring No. EB-2	•			lling hod	3	Hollo Auge	ow-stem	Drilming Company EGI	
Penetra- tion blows/6"	G. W. level		oth (		ı	ati- phy S		Description	
4/9/8		<b>5</b>		ОН		Asphalt & concrete pavement and gravel base Clayey sandy gravel, reddish brown, very stiff, moist Gravelly clay, very dark gray, very stiff, moist, high plasticity			
4/8/9			10		OH			me sand and silt, black, moist, high plasticity	
			20 25 30						
	-	OR OW			index V V V		ŋ	TOTAL DEPTH 10.5'	

Page 1 of 1

	,		_		BORING LOG				
Project KEI-P89		.P6		Boring Dia		Logged By D.L.			
			S/S #6277 San Leandro	<del> </del>	ameter N/A r Elevation N/A	Date Drilled 3/18/97			
Boring I EB3	No.	<del>-</del>	,	Drilling Method	GeoProbe	<b>Drilling Company</b> Gregg Drilling			
Penc- tration blows/6"	G.W. level	O.V.M. (ppm)	(feet) Samples	Stratigraphy USCS	Description ***				
			0=		A.C. pavement over s	and and gravel base.			
No Data					Silty gravel with sand (highly compacted roa	, very dense to hard, dry to slightly moist, brown adbase).			
				ML FEET	Clayey silt, very stiff, mottled.	moist, dark grayish brown and very dark brown,			
	0.0			CL	Silty clay, trace sand,				
		0.0	10-		brown below 10 feet.	Silty clay, stiff, moist, dark gray, with abundant caliche, grades to olive prown below 10 feet.			
				ML ====	Clayey silt, stiff, mois	t, olive brown.			
		0.0		CL	Silty clay, stiff, moist, very dark gray, with root holes and caliche.				
	_	0.0	15- I	ML EEEE	Clayey silt, stiff, mois				
	74					TOTAL DEPTH:15'			

	<u> </u>	<del></del>			BORIN	G LOG		
Project No. KEI-P89-0301.	P6			ring Dia sing Dia		1.375" N/A	Logged By D,L.	
Project Name 15803 East 14th		<u> </u>	il Cover	Elevation		Date Drilled 3/18/97		
Boring No. EB4	_		illing thod	Geo	GeoProbe Drilling Company Gregg Drilling			
Pene- tration blows/6"	tration level (ppm) (feet)				Description 👺 🐳			
No Data	No Data	5 - 10 - 15	ML CL		Silty gra asphalt a  Pocketed dark gray (Very poclayey s  Silty clay grades to Clayey si	nd debris (fill).  clay, silt and sand is brown.  or recovery at 4.5 ilt, stiff, moist, dans olive brown below it, stiff, moist, olive brown below.  It, firm to stiff, moist, olive it, stiff, moist, olive brown below it, stiff, moist, olive brown below it, stiff, moist, olive brown below it, stiff, moist, olive brown below it.	y dense, moist, dark yellowish brown, with  d, stiff, moist to wet, predominantly very  feet)  rk grayish brown.  e gray to dark olive gray, with caliche ow 10 feet.  ive brown.	

						BORING	GLOG			
Project	No.			Вс	oring Dia	ameter	1.375"	Logged By		
KEI-P89	0-0301	.Р6		Ca	asing Di	ameter	N/A	D,L.		
Project	Name	Unocal	l S/S #6277	W	cll Cove	r Elevation	i	Date Drilled		
15803 E	ast 140	h Street,	San Leandr	0		N/A		3/18/97		
Boring I EB5	Boring No					Geo	GeoProbe Drilling Company Gregg Drilling			
Pene- tration blows/6"	G.W. level	O.V.M. (ppm)	Depth (feet) Samples	Strati US	graphy SCS		Description Description			
	1					A.C. pav	ement over sand	and gravel base.		
						very dark	grayish brown			
		0.0	3			(Poor recovery at 4.5 feet)				
				ML		Sandy silt, trace clay, sand is fine to medium-grained, stiff, moist, dark olive gray.				
				CL		Silty elay, stiff, moist, olive brown.				
	<u>-</u>	0.0	10	ML		Sandy silt, trace clay, sand is very fine to fine-grained, stiff, moist, olive brown.				
						olive bro		OFAL DEPTH: 11'		