Activities Report

GEOTRACKER HOME | MANAGE PROJECTS | REPORTS | SEARCH | LOGOUT

ABF FREIGHT SYSTEMS (T0600100018) - MAP THIS SITE

OPEN - SITE ASSESSMENT

4575 TIDEWATER AVE OAKLAND, CA 94601

ACTIVITIES REPORT
PUBLIC WEBPAGE

CLEANUP OVERSIGHT AGENCIES

ALAMEDA COUNTY LOP (LEAD) - CASE #: 01-0022

ALAMEDA COUNTY

VIEW PRINTABLE CASE SUMMARY FOR THIS SITE

SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-0022

THIS PROJECT WAS LAST MODIFIED BY PARESH KHATRI ON 4/22/2010 4:08:30 PM - HISTORY

ACTIVITIES RE	PORT ACTIVITY TY	PE FILTER: Show All Activ	vities	* INDICATES A REVISED DUE DATE	
SCHEDULE NEW REGULATORY ACTION		N SCHEDULE	SCHEDULE NEW COMPLIANCE RESPONSE / SCHEDULE RECURRING		
ACTION TYPE	<u>ACTION</u>	ACTION DATE	RECEIVED / ISSUE DATE	ACTION DESCRIPTION	
LEAK ACTION	Leak Discovery	7/3/1986			
LEAK ACTION	Leak Reported	7/3/1986			
LEAK ACTION	Leak Stopped	7/3/1986			

LOGGED IN AS TEENALEKHAN

CONTACT GEOTRACKER HELP

Closure Review

GEOTRACKER HOME | MANAGE PROJECTS | REPORTS | SEARCH | LOGOUT

ABF FREIGHT SYSTEMS (T0600100018) - MAP THIS SITE

OPEN - SITE ASSESSMENT CLEANUP OVERSIGHT AGENCIES

4575 TIDEWATER AVE OAKLAND, CA 94601 ALAMEDA COUNTY

ACTIVITIES REPORT PUBLIC WEBPAGE

YES

ALAMEDA COUNTY LOP (LEAD) - CASE #: 01-0022 SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-0022

VIEW PRINTABLE CASE SUMMARY FOR THIS SITE

THIS PROJECT WAS LAST MODIFIED BY PARESH KHATRI ON 4/22/2010 4:08:30 PM - HISTORY

CLOSURE REVIEW

THIS VERSION IS IN PROGRESS AS OF 4/22/2010

CLOSURE REVIEW HISTORY

IS THIS CASE READY FOR CLOSURE?

NO

VIEW MAXIMUM CONCENTRATIONS REPORT

IMPEDIMENTS TO CLOSURE

Site Assessment Incomplete

Incomplete Conceptual Site Model (CSM)

Pollutant Sources Have Not Been Adequately Identified or Evaluated

Extent of Contamination Has Not Been Determined

Potential Risks, Threats, And Other Environmental Concerns Have Not Been Adequately Identified And Assessed

Sensitive Receptor Survey Has Not Been Completed

Other

Inadequate Source Control

Feasible Source Control Not Performed

Remaining Source Poses Threat to Groundwater

Plume Instability

Groundwater Contamination Plume Not Stable or Decreasing

Significant Rebound In Concentrations After Remediation

Verification Monitoring Not Complete

Other

Groundwater Impacts

Groundwater Impacted Above Background

Groundwater Impacted Above Other Cleanup Goal

Groundwater Will Not Meet Relevant WQOs Before the Beneficial Use of the Groundwater is Needed

Other

Well Impacts

Municipal Wells Impacted

Municipal Wells Potentially Impacted

Domestic Wells Impacted

Domestic Wells Potentially Impacted

Irrigation / Industrial Wells Impacted

Irrigation / Industrial Wells Potentially Impacted

De-Watering Well / Sump Impacted

De-Watering Well / Sump Potentially Impacted

BENEFITS OF ADDITIONAL WORK Fill-in RI Data Gaps

Transport of Contaminants

Complete CSM and Our Understanding of Hydrogeologic Regime and Fate and

Verify Remedial Action Effectiveness

Remove / Reduce Source Mass

Protect Designated Beneficial Uses

Restore Beneficial Uses

Protect Existing Water Supply Wells

Protect Human Health

Protect Ecological Receptors

Restore Blighted Property to Productive Use

Other

Unacceptable Risk

Unacceptable Risks to Human Health from Soil

Unacceptable Risks to Human Health from Vapor Intrusion

Unacceptable Risk from Soil Contaminants Entering Surface Runoff

Unacceptable Risk from Contaminated Groundwater Day Lighting to Surface

Water

Other

Land Use Impediments

Proposed Change In Land Use (Need Additional RI and/or Cleanup)

Risk Management Measures Need Agency Oversight (eg. Cap Maintenance)

Other

Procedural Impediments

Non-Responsive and / or Recalcitrant Responsible Party

RP Says They Do Not Have Adequate Funds to Initiate or Continue Work at

the Site

Site Data And Reports Not Uploaded to Geotracker

Monitoring Wells Not Yet Abandoned

Landowner Objects to Case Closure

Regional Water Board Objects to Closure Local Agency Objects to Case Closure

Community Objects to Case Closure

LOC Suspended

Reimbursements Delayed

Other

Other Impediments

SENSITIVE RECEPTORS LIKELY TO BE IMPACTED AND TIME FRAME FOR IMPACT

Municipal Well

Domestic Wells

Groundwater

Surface Water (Bay, Estuary, Stream, Lake)

Storm drain (Runoff of contaminated soil)

Indoor Air (Residential or Commercial)

Irrigation / Industrial Well

Other

	NOTES / COMMENTS
	SPELL CHECK
ļ	

LOGGED IN AS TEENALEKHAN

CONTACT GEOTRACKER HELP

Facility / Site Address

GEOTRACKER HOME | MANAGE PROJECTS | REPORTS | SEARCH | LOGOUT

ABF FREIGHT SYSTEMS (T0600100018) - MAP THIS SITE

OPEN - SITE ASSESSMENT

4575 TIDEWATER AVE OAKLAND , CA 94601 ALAMEDA COUNTY

ACTIVITIES REPORT
PUBLIC WEBPAGE

CLEANUP OVERSIGHT AGENCIES

ALAMEDA COUNTY LOP (LEAD) - CASE #: 01-0022 SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-0022

VIEW PRINTABLE CASE SUMMARY FOR THIS SITE

THIS PROJECT WAS LAST MODIFIED BY PARESH KHATRI ON 4/22/2010 4:08:30 PM - HISTORY

FACILITY / SITE ADDRESS

Save Changes

THIS IS A "TEST PROJECT" (WILL BE EXCLUDED FROM <u>PUBLIC</u> SEARCH / REPORTS AND REGULATOR REPORTS)

PROJECT NAME

THIS PROJECT IS A RESIDENCE

STREET # STREET NAME / LOCATION

BUILDING #

<u>CITY</u> <u>STATE</u> <u>ZIP</u> <u>COUNTY</u>

Alameda

CROSS STREET NAME

FIELDS CALCULATED BASED ON LATITUDE / LONGITUDE

 GW BASIN NAME
 WATERSHED NAME
 COUNTY

 Santa Clara Valley - East Bay Plain (2-9.04)
 South Bay - East Bay Cities (20420)
 Alameda

SPELL CHECK

LOGGED IN AS TEENALEKHAN

CONTACT GEOTRACKER HELP

Project Information

GEOTRACKER HOME | MANAGE PROJECTS | REPORTS | SEARCH | LOGOUT

ABF FREIGHT SYSTEMS (T0600100018) - MAP THIS SITE

OPEN - SITE ASSESSMENT

DATE

4575 TIDEWATER AVE OAKLAND , CA 94601 ALAMEDA COUNTY

CONTROLLED?

ACTIVITIES REPORT
PUBLIC WEBPAGE

GROUNDWATER MIGRATION - INFO

CONTROLLED?

DATE

CLEANUP OVERSIGHT AGENCIES

ALAMEDA COUNTY LOP (LEAD) - CASE #: 01-0022 SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-0022

FINAL REMEDY FOR CLEANUP

DATE

IMPLEMENTED?

VIEW PRINTABLE CASE SUMMARY FOR THIS SITE

HUMAN HEALTH EXPOSURE - **INFO**

THIS PROJECT WAS LAST MODIFIED BY *PARESH KHATRI* ON 4/22/2010 4:08:30 PM - HISTORY

PROJECT INFORMATION

PROJECT STATUS HISTORY

SITE TYPE

LUST Cleanup Site

Open - Site Assessment

FUNDING FOR CLEANUP

FILE LOCATION

RP IDENTIFICATION

RP ID DATE

SELECTED?

DATE

SITE HISTORY (PUBLIC)

STAFF NOTES (INTERNAL)

LEANUP OVERSIGHT AGENCIES

CASE NUMBER CLEANUP OVERSIGHT AGENCY LEAD LEAD DATE END DATE

ALAMEDA COUNTY LOP

SAN FRANCISCO BAY RWQCB (REGION 2)

LATITUDE/LONGITUDE INFORMATION MUST BE IN THE GEOGRAPHIC NAD83 COORDINATE SYSTEM:

LATITUDE LONGITUDE BUFFER (IN FEET) LAT / LONG SOURCE

* Historical Geocode - Exact Address Match

CLICK HERE TO RE-POSITION THIS PROJECT ON THE MAP

SPELL CHECK

LOGGED IN AS TEENALEKHAN CONTACT GEOTRACKER HELP

Activities Report

GEOTRACKER HOME | MANAGE PROJECTS | REPORTS | SEARCH | LOGOUT

ABF FREIGHT SYSTEMS (T0600100018) - MAP THIS SITE

OPEN - SITE ASSESSMENT

4575 TIDEWATER AVE OAKLAND , CA 94601 ALAMEDA COUNTY

<u>ACTIVITIES REPORT</u>

CLEANUP OVERSIGHT AGENCIES

PUBLIC WEBPAGE

ALAMEDA COUNTY LOP (LEAD) - CASE #: 01-0022 SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-0022

VIEW PRINTABLE CASE SUMMARY FOR THIS SITE

THIS PROJECT WAS LAST MODIFIED BY PARESH KHATRI ON 4/22/2010 4:08:30 PM - HISTORY

PROJECT STATUS HISTORY					
PROJECT STATUS	STATUS DATE	DATE UPDATED			
Open - Site Assessment	9/12/1986	9/12/1986			
Open - Case Begin Date	7/3/1986	7/3/1986			

LOGGED IN AS TEENALEKHAN

CONTACT GEOTRACKER HELP

Project Summary

GEOTRACKER HOME | MANAGE PROJECTS | REPORTS | SEARCH | LOGOUT

ABF FREIGHT SYSTEMS (T0600100018) - MAP THIS SITE

OPEN - SITE ASSESSMENT

4575 TIDEWATER AVE OAKLAND, CA 94601

ALAMEDA COUNTY

ACTIVITIES REPORT

PUBLIC WEBPAGE

CLEANUP OVERSIGHT AGENCIES

ALAMEDA COUNTY LOP (LEAD) - CASE #: 01-0022

SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-0022

VIEW PRINTABLE CASE SUMMARY FOR THIS SITE

THIS PROJECT WAS LAST MODIFIED BY PARESH KHATRI ON 4/22/2010 4:08:30 PM - HISTORY

PROJECT INFO

SITE TYPE **STATUS STATUS DATE**

LUST CLEANUP SITE OPEN - SITE ASSESSMENT 9/12/1986

CONTACTS

THERE ARE CURRENTLY NO CONTACTS ASSOCIATED WITH THIS PROJECT

LOGGED IN AS TEENALEKHAN

CONTACT GEOTRACKER HELP

Risk Information

GEOTRACKER HOME | MANAGE PROJECTS | REPORTS | SEARCH | LOGOUT

ABF FREIGHT SYSTEMS (T0600100018) - MAP THIS SITE

CLEANUP OVERSIGHT AGENCIES ACTIVITIES REPORT

ALAMEDA COUNTY LOP (LEAD) - CASE #: 01-0022 SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-0022

VIEW PRINTABLE CASE SUMMARY FOR THIS SITE

THIS PROJECT WAS LAST MODIFIED BY PARESH KHATRI ON 4/22/2010 4:08:30 PM - HISTORY

PUBLIC WEBPAGE

RISK INFORMATION

4575 TIDEWATER AVE

OAKLAND, CA 94601

ALAMEDA COUNTY

CONTAMINANT(S) OF CONCERN

DIESEL

INTERNAL PRIORITY (OPTIONAL)

OPEN - SITE ASSESSMENT

Save Changes

REDEVELOPMENT PLANNED - INFO

YES NO **CURRENT LAND USE** NONE SPECIFIED

BENEFICIAL USE

RELEASE TYPE

NONE SPECIFIED

MEDIA OF CONCERN

NONE SPECIFIED **VULNERABILITY BASIS**

IMPACTED DRINKING WATER WELLS

ADDITIONAL RISK DESCRIPTION (IF NEEDED)

DRINKING WATER SUPPLY SHUT DOWN

YES NO THERE ARE 0 DHS SUPPLY WELLS WITHIN 1/2 MILE OF THIS SITE (INCLUDING SITE BUFFER)

WELL IMPACT DESCRIPTION

REPORT DATE

DISCHARGE DATE

RELEASE DESCRIPTION

STOP DATE STOP METHOD

> DISCHARGE CAUSE **DISCHARGE SOURCE**

STRUCTURAL FAILURE TANK **DISCHARGE DESCRIPTION**

STOP DESCRIPTION

DISCOVERED DATE HOW DISCOVERED


TANK CLOSURE

HOW DISCOVERED DESCRIPTION

QUANTITY (GALLONS) HAZMAT INCIDENT FILED WITH OES? LEAK CONFIRMED AS A VAPOR RELEASE?

SPELL CHECK

LOGGED IN AS TEENALEKHAN **CONTACT GEOTRACKER HELP**



MAP AN ADDRESS: