UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT								
EMERGENCY HAS STATE OFFICE OF EMERGENCY SERVICES ☐ Yes ☑ No REPORT BEEN FILED? ☐ Yes ☑ No				FOR LOCAL AGENCY USE ONLY THEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE				
	☐ Yes ☑ No REPORT BEEN FILED? ☐ Yes ☑ No REPORT DATE CASE #			REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF				
				Par	ex MClu		-8-10	
	NAME OF INDIVIDUAL FILING REPORT		PHONE	SIGNED	SIGNATURE	:: 2/10 g 20.2 a wheelstoo	PATE VALUE	
REPORTED BY	Markus Niebanck (510) 596-4356							
					COMPANY OR AGENCY NAME City of Emeryville			
	1333 Park Avenue			Emeryville		CA STATE	94608 zip	
RESPONSIBLE PARTY	NAME Pellegrini Refridge & Rest Equip Co □ Unknown			CONTACT PERSON Pennie Barger		(510) 653-9850		
				Emeryville		CA STATE	94608 zip	
	FACILITY NAME (IF APPLICABLE)			OPERATOR		PHONE		
SITE LOCATION	Same as above							
	Same as above STREET CITY COUNTY ZIP							
	CROSS STREET							
IMPLEMENTING AGENCIES	LOCAL AGENCY AGENCY NAME					PHONE		
	Alameda County Environmental Health - Barney Chan					(510) 50	(510) 567-6765	
	REGIONAL BOARD					PHONE		
SUBSTANCES INVOLVED	(1) NAME QUANTITY LOST (GALLONS)							
	Heating Oil Unknown						∠ Unknown	
	Unknown							
DISCOVERY/ABATEMENT	DATE DISCOVERED 2/8/2010	HOW DISCOVERED	Tank T		Tank Removal	=	sance Conditions	
	DATE DISCHARGE BEGAN		Invento	ory Control METHOD USED T	Subsurface Monitoring TO STOP DISCHARGE (CHECK	Oth		
		Remove Contents Close Tank						
	HAS DISCHARGE BEEN STOPPED?			Repair Tank Change Procedure Replace Tank Other				
	YES NO IF YES, DATE Repair Piping							
SOURCE/ CAUSE	SOURCE OF DISCHARGE CAUSE(S)							
S S	☐ Tank Leak ☐ Piping Leak ☒ t	Jnknown 🔲 Other	Overfil	rfill ☐ Corrosion ☐ Rupture/Failure ☒ Unknown ☐ Spill ☐ Other				
CASE	CHECK ONE ONLY ☐ Undetermined ☐ Soit Only ☐ Groundwater ☐ Drinking Water – (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED							
CURRENT	CHECK ONE ONLY							
	☒ No Action Taken ☐ Case Closed (Cleanup Completed or Unnecessary) ☐ Leak Being Confirmed ☐ Pollution Characterization							
	☐ Remediation Plan ☐ Post Cleanup Monitoring in Progress ☐ Respiratory Site Assessment Worksler Submitted							
	☐ Preliminary Site Assessment Workplan Submitted ☐ Cleanup Underway ☐ Preliminary Site Assessment Underway							
REMEDIAL ACTION	CHECK APPROPRIATE ACTION(S) Cap Site (CD)	Excavate & Treat (E	Τ)	☐ Treatmer	nt At Hookup (HU)	☐ Other		
	☐ Contamination Barrier (CB) ☐ No Action Required (NA) ☐ Enhanced Bio Degradation (IT) ☐ Vacuum Extract (VE) ☐ Remove Free Product (FP) ☐ Replace Supply (RS)					_		
	Vacuum Extract (VE)						 	
ΣT								
COMMENTS								
[§								