UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK)/ CONTAMINATION SITE REPORT						
EMERGENCY HAS STATE OFFICE OF EMERGENCY SERVICES REPORT 95EN FILEO? ☐ Yes ☐ No				FOR LOCAL AGENCY USE ONLY THEREBY CERTIFY THAT LAM A DESIGNATED COVERNMENT ENGLOYER AND THAT THAT THE		
		REPORTED THIS INFORMATION TO LOCAL OFFICIALS PERSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.				
4/22/10			Jan >	The As	08/31/10	
	NAME OF INDIVIDUAL FILING REPORT	,	PHONE	SIGNED	SIGNATURE	DATE
REFCRIED BY	Annette Chen	_	(415) 512-1555	1 /li-	
	REPRESENTING LOCAL AGENCY REGIONAL BOARD			COMPANY OR AGENCY NAME Golden Gate Tank Removal, Inc.		
Ä	OWNER/OPERATOR × OTHER Contractor ADDRESS			Golden Gate Tank Removal, Inc.		
	3730 Mission Street	ET.		San Francisco	CA	94110
RESPONSIBLE PARTY	Leslie Mulholland		☐ Unknown			PHONE 510-681-6976
	132 Guilford Rd.		—	Piedmont	CA	94611
SITE LOCATION	FACILITY NAME (IF APPLICABLE)	<u>,,,</u>		OPERATOR CHY		PHONE 7/P
	ADDRESS					
	132 Guilford Rd.	FT		Piedmont		meda 94611
	Highland Ave.					
(APLEMENTING AZENICIES	AGENCY AGENCY NAME Alameda County Department of Environmental Health -Robert			Weston (510)567 67		1
	Alameda County Department of Environmental Health -Robert Weston (510)567-67					
						PHONE
SUBSTANCES PAGLYED	Diesel		NAME			QUANTITY LOST (GALLONS) X Unknown
	Uńknown					
DISCOVERY/ABATEVENT	DATE DISCOVERED 4/21/10 HOW DISCOVERED Tank Test Inventory Cor			☑ Tank Removal ☐ Nuisance Conditions ontrol ☐ Subsurface Monitoring ☐ Other		
	DATE DISCHARGE BEGAN	METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) ☑ Remove Contents ☑ Close Tank & Removed ☐ Repair Tank ☐ Change Procedure				
	MAS DISCHARGE BEEN STOPPED?					
				Repair Piping		
SOURCE	SQUIRCE OF DISCHARGE CAUSE(S) Tank Leak Plping Leak Unknown Other Overfill Corrosion Rupture/Feiture Unknown Spill Other					
CASE	☑ Undetermined ☑ Soil Only ☐ Groundwater ☐ Drinking Water - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY REEN AFFECTED) CHECK ONE ONLY					
CURRENT STATUS	ET NIO Anti Tallian					
	☐ Remediation Plan ☐ Post Cleanup Monitoring in Progress ☐ Preliminary Site Assessment Workplan Submitted ☐ Cleanup Underway ☐ Preliminary Site Assessment Underway					
7.	CHECK APPROPRIATE ACTION(S)					
REVEDIAL ACTION	☐ Cap Site (CD) ☐ Excavate & Treat (ET) ☐ Treatment at Hookup (HU) ☐ Other ☐ Contamination Barrier (CB) ☐ No Action Required (NA) ☐ Enhanced Bio Degradation (IT) ☐ Vacuum Extract (VE) ☐ Remove Free Product (FP) ☐ Replace Supply (RS) ☐ Excavate & Dispose (ED) ☐ Pump & Treat Groundwater (GT) ☐ Vent Soil (VS)					
COMMENTS	Holes found in the tank.					
Ü						