

PHOTOGRAPHS



Photo 1: View of garbage container on northwest corner of the Subject Property.



Photo 2: View of historical boring location.

Project: Phase I ESA
1625 Chestnut St.
Livermore, California

Project Number:
6988-003.01

Date of Photos:
March 12, 2015





Photo 3: View of historical boring location.



Photo 4: View of Subject Property front.

Project: Phase I ESA
1625 Chestnut St.
Livermore, California

Project Number:
6988-003.01

Date of Photos:
March 12, 2015





Photo 5: View of historical boring location.



Photo 6: View of Unit 1635A, which is used as a storage area for a theatre company.

Project: Phase I ESA
1625 Chestnut St.
Livermore, California

Project Number:
6988-003.01

Date of Photos:
March 12, 2015





Photo 7: View of typical ceiling in the Subject Property.



Photo 8: View of Unit 1635A.

Project: Phase I ESA
1625 Chestnut St.
Livermore, California

Project Number:
6988-003.01

Date of Photos:
March 12, 2015

