



Photo 17: View of staining on cement in the western storage container.



Photo 18: View of front entrance of the Subject Property.

Project: Phase I ESA  
1625 Chestnut St.  
Livermore, California

Project Number:  
6988-003.01

Date of Photos:  
March 12, 2015





Photo 19: View of donation storage area.



Photo 20: View of typical floor tile.

Project: Phase I ESA  
1625 Chestnut St.  
Livermore, California

Project Number:  
6988-003.01

Date of Photos:  
March 12, 2015







Photo 21: View of Unit 1635N Shepard's Gate Outlet.



Photo 22: View of southern exterior wall.

Project: Phase I ESA  
1625 Chestnut St.  
Livermore, California

Project Number:  
6988-003.01

Date of Photos:  
March 12, 2015







Photo 23: View of recycling container on southern portion of the Subject Property.



Photo 24: View of garbage container on southern portion of the Subject Property.

Project: Phase I ESA  
1625 Chestnut St.  
Livermore, California

Project Number:  
6988-003.01

Date of Photos:  
March 12, 2015







Photo 25: View of eastern loading dock.



Photo 26: View of water pooling.

Project: Phase I ESA  
1625 Chestnut St.  
Livermore, California

Project Number:  
6988-003.01

Date of Photos:  
March 12, 2015

**A·C·C**  
ENVIRONMENTAL  
CONSULTANTS  
An Employee Owned Company