



Photo 27: View of train tracks behind southern portion of the Subject Property.



Photo 28: View of vacant parcel.

Project: Phase I ESA
1625 Chestnut St.
Livermore, California

Project Number:
6988-003.01

Date of Photos:
March 12, 2015





Photo 29: View of storm drain on southeastern portion of the Subject Property.



Photo 30: View of vacant parcel.

Project: Phase I ESA
1625 Chestnut St.
Livermore, California

Project Number:
6988-003.01

Date of Photos:
March 12, 2015





Photo 31: View of eastern portion of the Subject Property.



Photo 32: View of north parking lot.


Project: Phase I ESA
1625 Chestnut St.
Livermore, California

Project Number:
6988-003.01



Date of Photos:
March 12, 2015

A·C·C
ENVIRONMENTAL
CONSULTANTS
An Employee Owned Company

FIGURES 1-4



Source: Google Earth, 2015

Title <i>Location Map 1625 Chestnut St., Livermore, California</i>	
Figure Number: 1	Scale: None
Project Number: 6988-003.01	Drawn By: JNL
 An Employee Owned Company	Date: 3/13/15
	 N