UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK)/ CONTAMINATION SITE REPORT						
MERGENCY HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED?			FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE			
Yes No			REPORTED THIS INFORMATION TO LOCAL OFFICIALS PERSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.			
REPORT DATE CASE #			Bola Oak Intible			
04/15/16				SIGNED	91	/DATE*
	NAME OF INDIVIDUAL FILING REPORT		PHONE	\ 540.4555	SIGNATURE	4 Λ
REPORTED BY	Gina Wee		(415	) 512-1555		ll_
	REPRESENTING  LOCAL AGENCY REGIONAL BOARD  OWNER/OPERATOR XOTHER contractor		Golden Gate Tank Removal, Inc.			
	1480 Carroll Avenue			San Francisco	CA	94124 ZIP
SITE LOCATION RESTONSIBLE PARTY	11J Family Housing, LP					PHONE 510-287-5353
	ADDRESS 1825 San Pablo Avenue			Oakland	CA	94612 TATE ZIP
	,			OPERATOR		PHONE
	ADDRESS 1110 Jackson St Oakland Alameda 94607					
	STREET CITY COUNTY ZIP CROSS STREET					
	38th-Avenue /Z Th ST,					
AGENCIES	LOCAL AGENCY	AGENCY NAME				PHONE
	Alameda County Environmental Health -Barbara Jakub 510-567-6737					
	REGIONAL BOARD					PHONE
_	(1)		NAME		(	QUANTITY LOST (GALLONS)
INVOLVED	Gasoline					☐ Unknown
	(2)					☐ Unknown
F	DATE DISCOVERED HOW DISCOVERED Tank Test Tank Removal Nuisance Conditions					
DISCOVERY/ABATEMENT	04/15/16					
	DATE DISCHARGE BEGAN			METHOD USED TO STOP DISCHA	RGE (CHECK ALL THAT APPLY)	
	□ Remove Contents    □ Close Tank & Removed					
	HAS DISCHARGE BEEN STOPPED?	☐ Repair Tank ☐ Change Procedure ☐ Replace Tank ☐ Other				
	☐ Yes ☐ No 04/15/16  IF YES, DATE					
) iii	SOURCE OF DISCHARGE CAUSE(S)					
CAUSE	☐ Tank Leak ☐ Piping Leak 📆 Unknown ☐ Other ☐ Overfill ☐ Corrosion ☐ Rupture/Failure ☐ Unknown ☐ Spill ☐ Other					
CAUSE TYPE	CHECK ONE ONLY  Undetermined X Soil Only Groundwater Drinking Water - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)					
STATUS	CHECK ONE ONLY					
	□ No Action Taken □ Case Closed (Cleanup Completed or Unnecessary) □ Leak Being Confirmed □ Pollution Characterization □ Remediation Plan □ Post Cleanup Monitoring in Progress □ Preliminary Site Assessment Workplan Submitted □ Cleanup Underway □ Preliminary Site Assessment Underway					
ACTION	CHECK APPROPRIATE ACTION(S)  Cap Site (CD)					
COMMENTS	Holes found in the tanks Contaminated Soil					